

Brocade v7.0.0d1 Internal Content Notes

The Brocade CCE process has been used to provide stable code fixes to various Brocade customer sites. This CCE has been created especially for FICON Emulation customers that require at a minimum the IBM FICON qualified FOS V7.0.0d code base with important fixes. The base of the CCE is the IBM FICON Qualified FOS release of V7.0.0d plus confirmed changes.

The current CCE label is: v7.0.0d1.

The following sections define the defects and improvements that have been added in various builds of the CCE. CCE Builds are available to customer sites through an SR Request to Brocade Support.

CCEs are packaged exactly the same way as a normal Brocade FOS Release. The normal Firmware Download process is used to upgrade a switch to the CCE. As of 10/09/2014, the following TRs fixes are in the following releases:

This document can be shared with customers and partners as required. The following sections include the list of Defects that have been incorporated into the CCE branch and a description of the issue that was addressed.

Common Questions and Answers Related to the Bash Shell Security Vulnerability Fix (Defect 529761)

- Q How is FOS exposed to the Bash Shell security vulnerability?
- A FOS is only exposed when an authenticated user login to a Brocade switch and gain access to the CLI interface. This includes login through Console, Telnet, SSH connections. An authenticated user account could exploit this vulnerability to gain privileges beyond the permission granted to the account, such as executing commands with root privilege.

FOS is not exposed to the Bash Shell vulnerability through remote attacks, specifically through any of the following protocols.

- SNMP not exposed. FOS does not support executing shell script.
- SMI-S not exposed. FOS does not support executing shell script.
- HTTP not exposed. FOS does not allow arbitrary code / scripts (CGI) to run.
- DHCP client not exposed. FOS does not support DHCP script capabilities. FOS DHCP client does not support option 114.
- Q How can I mitigate the Bash Shell vulnerability in FOS?
- A Following is a list of mitigation procedures to strengthen Brocade switch account management and hence remove the exposure to the Bash Shell vulnerability.



- Place your Brocade SAN switch and other data center critical infrastructure behind firewall to disallow access from the Internet.
- If you have not done so in the past, change all Brocade default account passwords, including the root passwords, from the factory default passwords.
- Examine the list of accounts, including the ones on the switch and ones on remote
 authentication servers, such as RADIUS, LDAP, and TACAS+, to ensure only the necessary
 personnel are granted access to Brocade FOS switch. Delete guest accounts and temporary
 accounts created for one-time usage.
- Utilize FOS password policy management to strengthen the complexity, age, and history requirements of switch account passwords.
- Q Do I have to install this CCE patch to mitigate the Bash Shell vulnerability in FOS?
- A If you have followed the mitigation procedures documented above to protect your switch accounts, it is not necessary to install this CCE patch. You can wait for the next scheduled upgrade to a supported patch version that contains the fix to the Bash Shell vulnerability, ideally to a FOS Target Path release.

Please note, once upgraded, if you want to download to a release without the Bash fix again, you may see some Bash error during firmware cleanup as part of the firmware download process. These can be ignored and will be cleaned up again in future upgrades to a release with the Bash fix.

###################################

```
Removing unneeded files, please wait ...

There was a problem cleaning /bin, retrying

There was a problem cleaning /bin, retrying

There was a problem cleaning /bin, retrying

There was a problem cleaning /sbin, retrying

There was a problem cleaning /sbin, retrying

There was a problem cleaning /sbin, retrying
```

FOS v7.0.0d1 is equivalent to FOS CVR 419235 Build 9 – Completed on 10/9/2014

Defect ID: DEFECT000529761		
Technical Se	everity: High	Probability: Medium
Product: F	OS	Technology: Security
Reported In	Release: FOS6.3.0	Technology Area: Security Vulnerability
Closed In Release(s): FOS6.2.2f9, FOS6.4.2a1, FOS6.4.3f3, FOS7.0.0d1, FOS7.0.2e1, FOS7.1.0cb,FOS7.1.1c1,		
	FOS7.1.2b1, FOS7.2.0d6, FOS7.2	.1c1, FOS7.3.0b
Symptom: Bash shell security vulnerabilities (CVE-2014-6271, CVE-2014-7169, CVE-2014-7186, CVE-2014-		
7187). These vulnerabilities allow certain malformed function definition to bypass privilege		
boundaries and execute unauthorized commands.		



Condition:	To exploit these vulnerabilities in FOS requires access to the CLI interface after user authentication	
	through console, Telnet, and SSH connections. An authenticated user account could exploit this bug to	
	gain privileges beyond the permission granted to this account, such as executing commands with root	
	privilege	

Workaround: Place switch and other data center critical infrastructure behind firewall to disallow access from the Internet; Change all default account passwords; Delete guest accounts and temporary accounts created for one-time usage needs; Utilize FOS password policy management to strengthen the complexity, age, and history requirements of switch account passwords.

Defect ID: DEFECT000513920		
Technical S		Probability: Low
Product:	FOS	Technology: Security
Reported In	Release: FOS7.1.0a	Technology Area: Fabric Authentication
Closed In R	elease(s): FOS6.4.3f2, FOS7.0.0d1, FOS7.0 FOS7.2.0d2, FOS7.2.1b, FOS7.3.	.2d6, FOS7.0.2e1, FOS7.1.0cb, FOS7.1.1c1, FOS7.1.2b,
Symptom:	tom: CVE-2014-0224: OpenSSL before 0.9.8za, 1.0.0 before 1.0.0m, and 1.0.1 before 1.0.1h does not properly restrict processing of ChangeCipherSpec messages, which allows man-in-the-middle attackers to trigger use of a zero-length master key in certain OpenSSL-to-OpenSSL communications, and consequently hijack sessions or obtain sensitive information, via a crafted TLS handshake, aka the "CCS Injection" vulnerability.	
Condition:		
Workaroun		th PEAP-MSCHAPv2 for authentication, upgrading the that does not contain this vulnerability will prevent

Defect ID: DEFECT00505359	Technical Severity: Medium
Summary: Switch panics intermittently after SS command is started	
Symptom: Switch panic during supportsave.	
Workaround: Contact support to remove RTE section data gathering from supportsave	



Defect ID: **DEFECT00383558** Technical Severity: Medium

Summary: Director with FX8-24 occasionally panics when performing a supportsave when

switch is configured in FMS mode

Symptom: Switch panic during supportsave.

Workaround: Contact support to remove RTE section data gathering from supportsave

Defect ID: **DEFECT00389303** Technical Severity: High

Summary: Switch finds inconsistency in domain count and E-port count during HAfailover

Symptom: After FOS upgrade, multiple ports report "Not ready for F or L ports"

Workaround: Manual fabric rebuilds by bouncing a downstream/upstream ISL port/trunk. No

impact to F port if domain ID does not change during bounce.

Defect ID: **DEFECT00419235** Technical Severity: Medium

Summary: Devices attached to failing FC10-6 port may report errors.

Symptom: FOS does not report physical port errors detected on FC10-6 10 Gpbs ports

Defect ID: **DEFECT00470487** Technical Severity: Medium

Summary: Fabric Watch does not calculating VEX port packet loss correctly.

Symptom: Erroneous FW-1190 error messages seen on different VEX tunnels:

Event: , VEXport#3/16, Packet Loss, is above high boundary (High=100, Low=0). Current value

is 1176 Percentage (%). Severity: Warning.

Defect ID: **DEFECT00460296** Technical Severity: Medium

Summary: Unit check during tape repositioning resulted in FICN-1056 FICON Emulation Error

code 100

Symptom: Unit check during tape repositioning resulted in FICN-1056 FICON Emulation Error

code 100 and ficon abort.

Workaround: Disable FICON Tape Read Pipelining on the FCIP Tunnel



Defect ID: **DEFECT00454312** Technical Severity: Medium

Summary: CP panic during taken over as active CP due to access media on a disabled blade

Symptom: Switch cold boot when there is connection problem between FX8-18 port blade

and chassis backend.

Workaround: None

Defect ID: DEFECT00376595

Summary: Replication of FABRIC WATCH through BNA fails in Brocade switches in VF

Symptom: User cannot replicate fabric watch only data through BNA. CLI works if fabic.name is added to configure file; However both CLI and BNA removed bottleneck

detection configure data.

Workaround: Use CLI

Defect ID: **DEFECT00419235** Technical Severity: Medium

Summary: FOS software does not expose 10 Gpbs user port physical errors on a FC10-6

blade

Symptom: Need to monitor 10G ASIC internal errors and report to user via raslog EGR-1000

and EGR-1001

Workaround: None

Defect ID: **DEFECT00431920** Technical Severity: High

Summary: Support the documented BRCD-FCIP-Ext MIB in MIB reference

Symptom: User will always see 0 for the below measures

1. fcipExtendedLinkTcpDroppedPackets

2. fcipExtendedLinkTcpSmoothedRTT

3. fcipExtendedLinkRtxRtxT0

4. fcipExtendedLinkRtxDupAck

5. fcipExtendedLinkDupAck

Workaround: None

Defect ID: **DEFECT00373218** Technical Severity: High

Summary: Memory leaks on standby CP during execution of supportsave

Symptom: CP panics after multiple interactions of supportsave. Memory block used for

"buffer_head" increased significantly

Workaround: Reboot standby CP when memory is low



Defect ID: DEFECT00358156	Technical Severity: High	
Summary: FCIP Tunnel bounce caused by chip reset. PCIe errors throughout errdumpall		
Symptom: Chip reset due to PCle errors with raslog BLS-5023. The chip reset can cause tunnel bounce and IO halt		
Work around: Issue is seen less when ipsec is disabled.		
Defect ID: DEFECT00358156	Technical Severity: High	
Summary: FCIP Tunnel bounce caused by chip reset. PCIe errors throughout errdumpall		
Symptom: Chip reset due to PCIe errors with raslog BLS-5023. The chip reset can cause tunnel bounce and IO halt		
Work around: Issue is seen less when ipsec is disabled.		

Defect ID: DEFECT00358156	Technical Severity: High
Summary: FCIP Tunnel bounce caused by chip reset. PCIe errors throughout errdumpall	
Symptom: Chip reset due to PCIe errors with raslog BLS-5023. The chip reset can cause tunnel bounce and IO halt	
Work around: Issue is seen less when ipsec is disabled.	

Defect ID: DEFECT00419620	Technical Severity: Meidum
Summary: An hafailover, hareboot or firmwaredownload may cause offline ports with a ASIC register being zeroed out	
Symptom: If frames are queued to the offline ports, credit is permanently lost and observe busy buffer condition on the port	
Work around: None	

Defect ID: DEFECT00403592	Technical Severity: Meidum	
Summary: Frame discards after enabling new TI zone		
Symptom: After enabling a new TI zone with failover enabled and all member ports disabled, discards due to un-routable were observed in another TI zone		
Work around: None		



Defect ID: **DEFECT00415795** Technical Severity: High

Summary: DCX with FC10 blade continuous reboots after fwdl; blades stuck in POST2 before

chassis reboots

Symptom: When FC10 blades run POST, DCX went into a continuous reboot loop until POST

was disabled

Work around: Disable diagnostic POST.

Defect ID: DEFECT00 423389 Technical Severity: High

Summary: Switch panic while running suppotsave with 4G blades.

Symptom: In FOS v7.0.x, When RTE (route module) portion of supportsave is run on 4G

blade, it triggered switch panic. This was only reported by one customer site but

multiple times.

Work around: Avoid running supportsave during route change

Defect ID: **DEFECT00386010** Technical Severity: Medium

Summary: Device does re-FLOGI with a different WWN cause stale entry in Flogin DataBase

Symptom: switch reports duplicate WWN and panic.

Work around: None

Defect ID: **DEFECT00 409878** Technical Severity: Medium

Summary: HTTPD (Apache server 1.3.31-10) goes to defunct state

Symptom: Customer loses manageability via BNA

Work around: Restart httpd or HAfailover (hareboot)