

# Brocade Fabric OS v7.3.2a

## Release Notes v1.0

June 13, 2016

### Document History

Document Title	Summary of Changes	Publication Date
Brocade Fabric OS v7.3.2a Release Notes v1.0	Initial Release	June 13, 2016

© 2016 Brocade Communications Systems, Inc. All Rights Reserved.

ADX, AnyIO, Brocade, Brocade Assurance, the B-wing symbol, DCX, Fabric OS, ICX, MLX, MyBrocade, OpenScript, VCS, VDX, and Vyatta are registered trademarks, and HyperEdge, The Effortless Network, and The On-Demand Data Center are trademarks of Brocade Communications Systems, Inc., in the United States and/or in other countries. Other brands, products, or service names mentioned may be trademarks of their respective owners.

Notice: This document is for informational purposes only and does not set forth any warranty, expressed or implied, concerning any equipment, equipment feature, or service offered or to be offered by Brocade. Brocade reserves the right to make changes to this document at any time, without notice, and assumes no responsibility for its use. This informational document describes features that may not be currently available. Contact a Brocade sales office for information on feature and product availability. Export of technical data contained in this document may require an export license from the United States government.

## Contents

Overview .....	5
Resolution of Important Defects.....	5
New Features & Support .....	5
Planned Deprecation of Legacy FOS Features.....	6
<b>FOS v7.3.0 Feature Descriptions.....</b>	<b>6</b>
New Hardware Support .....	6
New FCIP Features on Brocade 7840 .....	6
Monitoring and Alerting Policy Suite (MAPS) Enhancements.....	8
Flow Vision Enhancements .....	9
ClearLink Diagnostic (D_Port) Enhancements .....	10
Read Diagnostics Parameters .....	10
Link Cable Beacon (Port Peer Beacon).....	10
E_Port Balance Priority Routing.....	11
FCR enhancements .....	11
Security Enhancements .....	11
Access Gateway Enhancements .....	11
Zoning Enhancements.....	12
High Integrity Fabric.....	12
RAS Enhancements .....	12
Brocade 8510 ICL Scalability Enhancement .....	13
Miscellaneous Enhancements.....	13
<b>Optionally Licensed Software.....</b>	<b>15</b>
<b>Temporary License Support .....</b>	<b>19</b>
<b>Supported Switches.....</b>	<b>20</b>
<b>Standards Compliance .....</b>	<b>20</b>
<b>Technical Support.....</b>	<b>20</b>
<b>FOS Migration Considerations .....</b>	<b>22</b>
FOS Upgrade and Downgrade Special Considerations.....	22
Recommended Migration Paths to FOS v7.3.2a .....	22
<b>Important Notes.....</b>	<b>23</b>
Brocade Network Advisor Compatibility .....	23
WebTools Compatibility .....	23
SMI Compatibility.....	24
Fabric OS Compatibility .....	24
SNMP Support .....	26
<b>Blade Support.....</b>	<b>35</b>
<b>Scalability.....</b>	<b>40</b>
<b>Other Important Notes and Recommendations .....</b>	<b>40</b>

Adaptive Networking/Flow-Based QoS Prioritization .....	40
Access Gateway .....	41
D_Port.....	41
Encryption Behavior for the Brocade Encryption Switch (BES) and FS8-18 .....	42
FCIP (Brocade 7800 and FX8-24).....	43
FCIP (Brocade 7840).....	43
FCoE/DCB/CEE (FCOE10-24) .....	44
FCR and Integrated Routing.....	46
Forward Error Correction (FEC) .....	46
FICON.....	46
FL_Port (Loop) Support.....	46
Flow Vision .....	47
ICLs on DCX/DCX-4S .....	47
Native Connectivity (M-EOS interoperability).....	47
Port Initialization .....	47
Port Mirroring .....	47
Virtual Fabrics .....	47
WebTools.....	48
Zoning.....	48
Read Diagnostics Parameters .....	48
Link Cable Beaconsing.....	48
16G 2km ICL QSFP .....	48
Brocade Analytics Monitoring Platform .....	49
Miscellaneous .....	49
<b>Defects .....</b>	<b>52</b>
Closed with Code Change in Fabric OS v7.3.2a.....	52
Closed with Code Change in Fabric OS v7.3.2.....	63
Closed with Code Change in Fabric OS v7.3.1d.....	114
Closed with Code Change in Fabric OS v7.3.1c.....	115
Closed with Code Change in Fabric OS v7.3.1b.....	119
Closed with Code Change in Fabric OS v7.3.1a.....	131
Open in Fabric OS v7.3.1 .....	138
Closed with Code Change in Fabric OS v7.3.1.....	140
Closed without Code Change in Fabric OS v7.3.1 .....	153

## Overview

FOS v7.3.2a is a patch release based on FOS v7.3.2. All hardware platforms and features supported in FOS v7.3.2 are also supported in FOS v7.3.2a. This release contains fixes for defects documented in the closed defect table at the end of this document.

## Resolution of Important Defects

- DEFECT000577166 - F\_Ports went into an In\_sync state or route error was triggered on E\_port trunk causing frame drop during a firmware upgrade.
- DEFECT000583695 - If a blade or switch is disabled while the D-Port test is running, the switch/blade might move to disabled state permanently which requires a reboot of the blade/switch to recover.
- DEFECT000590745 - Flow Vision daemon (npd) may crash on a switch during firmwaredownload.
- DEFECT000600016 - Kernel Panic may be encountered, triggered by "Detected termination of MAPs mdd process"

## New Features & Support

In addition to fixes for defects, FOS v7.3.2 also includes new features and support.

FOS v7.3.2 includes the following features introduced in FOS v7.4.0b that enable Brocade Gen 5 fabric switches as source switches to be monitored by the Brocade Analytics Monitoring Platform:

- Support for virtual tap (vTap)
  - vTap is a Brocade Gen 5 Flow Vision capability enabled on a fabric switch to mirror selected frames to Analytics Monitoring Platform for analysis. A new pre-defined flow named "sys\_analytics\_vtap" supports vTap.
  - vTap supports automatic discovery of Analytic F\_Port (AF\_Port) when a Brocade Analytics Monitoring Platform is attached to the fabric. An AF\_Port is a mirror port on the Analytics Monitoring Platform designated as the destination of information sent from vTap-enabled ports on a fabric switch.
  - Support Low QoS zone configuration or in-flight encryption and compression to co-exist with vTap on fabric switches monitored by the Brocade Analytics Monitoring Platform.
- Support for Analytics E\_Port (AE\_Port) connectivity between fabric switches and the Brocade Analytics Monitoring Platform through Analytics Switch Link (ASL)
  - ASLs are Gen 5 Fibre Channel links dedicated for carrying information from vTap-enabled ports on fabric switches to Brocade Analytics Monitoring Platform.
  - ASLs do not carry normal data traffic unless they are the only paths from hosts to targets.
- Enhancement to MAPS for monitoring AE\_Port and vTap
  - Add Fabric Performance Impact (FPI) monitoring for latency and congestion monitoring on AE\_Port
  - Add FPI monitoring for back-end ports with active vTap on a fabric switch
  - Add Switch Resource monitoring for vTap traffic IOPS with active vTap on a fabric switch

FOS v7.3.2 has the following enhancements.

- SNMP enhancement to MIB object ifOperStatus to report port online/offline state independently from the value of ifAdminStatus.
- Support certificate signing request (CSR) generated with SHA-256 signature through secCertUtil CLI command with "-hash sha256" option.
- Support QSFP Part Number: 57-1000294-02 to be used on Brocade FC16-64 port blade and on Brocade DCX8510 core blades for Inter Chassis Link (ICL).
- Support following new optics part numbers:
  - Finisar 16G DWDM 40km SFP+ (FTLX3670SCCxxB16)
  - Finisar 8G DWDM 40km SFP+ (FTLX3670SCC\*\*B08)
  - Finisar 8G CWDM 70km SFP+ (FTLX2870SCC\*\*B08)

- Finisar 8G CWDM 40km SFP+ (FTLX2670SCC\*\*B08)
  - Finisar 4G DWDM 80km SFP+ (FWLF1634RL\*\*B04)
  - Finisar 4G CWDM 80km SFP (FWLF1625P2L\*\*B04)
  - Finisar 4G ELWL 50km SFP (FWLF1524P2L55B03)
  - Finisar 4G ELWL 100km SFP (FWLF1625P2L55B03)
- Support Low QoS zone configuration to co-exist with vTap on fabric switches monitored by the Brocade Analytics Monitoring Platform.

## Planned Deprecation of Legacy FOS Features

Following legacy FOS features will be deprecated beginning with the FOS v7.4.0 release.

- Fabric Watch
- Advanced Performance Monitoring (APM)

For switches that do not have the Brocade Fabric Vision license or the combination of Brocade Fabric Watch license and Brocade APM license that enables the Fabric Vision features, the individual Fabric Watch license and APM license will continue to be available to facilitate the upgrade to Fabric Vision features. Users do not plan to migrate from Fabric Watch or APM to the improved capabilities in MAPS and Flow Vision will continue to be supported at the FOS v7.3.x and earlier firmware levels.

## FOS v7.3.0 Feature Descriptions

### New Hardware Support

FOS v7.3.1 introduces support for long distance 16G optical cable QSFP that extends the ICL connectivity up to two kilometers (km).

FOS v7.3 introduces support for the following **new** 16G FC hardware platform:

- Brocade 7840 Gen 5 FC extension switch platform that offers the following capabilities:
  - Support 24 16G FC ports, 16 10GE/1GE FCIP ports, and 2 40GE FCIP ports
  - Support maximum 40G WAN throughput with two WAN Rate upgrade licenses.
  - Support maximum 20G bandwidth on a VE port.
  - Support existing FCIP features on Brocade 7800 and FX8-24 blade.
  - Support non-disruptive firmware download.
  - Support Fabric Vision features.
  - Support increased compression performance.
  - Support stream based flow control.
  - Support out of order TCP delivery.
  - Support WAN link test tool.
- Brocade FC16-64 port blade for Brocade 8510 that offers the following capabilities:
  - 16 QSFP ports per blade provide total 64 FC ports supporting 16G, 8G, and 4G speeds.
  - 512 16G FC ports in a fully populated Brocade 8510-8 chassis.

FOS v7.3 introduces the support of the **existing** FCOE10-24 blade in a Brocade **8510-8** chassis.

FOS v7.3 supports all hardware platforms supported by FOS v7.2.x.

### New FCIP Features on Brocade 7840

In addition to the existing FCIP features supported on Brocade 7800 and FX8-24, FOS v7.3 supports the following new FCIP features on Brocade 7840.

- Support maximum 40G WAN throughput.
- Support maximum 20G bandwidth on a VE port.
- Non-disruptive firmware download.
- Fabric Vision for Extension.
  - ClearLink Diagnostic Port (D\_Port) on all FC ports.
  - Monitoring and Alerting Policy Suites (MAPS) for FCIP QoS, tunnels, and circuits.
  - Full Flow Vision capabilities on all FC ports.

- Ethernet Jumbo Frame
- IPSec enhancement
- Adaptive Rate Limiting (ARL) enhancements
- Increased compression performance
- Path MTU Discovery
- Stream based flow control
- Out of order TCP delivery
- WAN test tool

### **Support maximum 40G WAN throughput**

FOS v7.3 supports maximum 40G WAN throughput on Brocade 7840. The maximum throughput is supported with two WAN Rate Upgrade licenses. The base configuration without either WAN upgrade license supports maximum 5G WAN throughput.

### **Support maximum 20G bandwidth on a VE port**

FOS v7.3 supports on Brocade 7840 10 VE mode with maximum 20G bandwidth on a VE port and 20 VE mode with maximum 10G bandwidth on a VE port. End users can create single FCIP circuit with 20G bandwidth or create multiple circuits to load balance with different bandwidths that sum to 20G.

### **Non-disruptive Firmware Download**

FOS v7.3 supports firmware download on Brocade 7840 without disruption to FCIP links. During a non-disruptive firmware download, throughput of individual FCIP tunnels are maintained, while the total bandwidth is limited to half of the maximum bandwidth supported on the platform.

### **Fabric Vision for Extension**

FOS v7.3 supports and expands Fabric Vision features for Brocade 7840 Extension platform. These include:

- ClearLink Diagnostic Port (D\_Port) on all FC ports to diagnose FC link optics and cable problems.
- Monitoring and Alerting Policy Suites (MAPS) enhancements to provide pre-defined threshold and alerting rules for FCIP statistics at QoS level, tunnel level, and circuit level and capture FCIP specific violations in MAPS dashboard.
- Full Flow Vision feature support on all FC ports to provide broad visibility, deep insight, and pre-production validation for traffic between data centers across FCIP links.

### **Ethernet Jumbo Frame**

FOS v7.3 supports a Jumbo IP frame with MTU up to 9216 bytes on Brocade 7840.

### **IPSec Enhancements**

FOS v7.3 increase IPSec performance on Brocade 7840 with near line-rate throughput. FOS v7.3 implements IPSec configuration through a policy applied to a FCIP tunnel. IPSec supports both IPv4 and IPv6 and jumbo frames.

### **Adaptive Rate Limiting (ARL) Enhancements**

FOS v7.3 implements two new ARL algorithms, Modified Multiplicative Decrease and Time-based Decrease, to provide additional performance tailored to network conditions. In addition, ARL ramp up time has been decreased from 10s to 1s comparing to Brocade 7800.

### **Increased Compression Performance**

FOS v7.3 supports increased compression performance on FC data frames on Brocade 7840 before they are sent through FCIP channels. End users can choose None, Aggressive Deflate, Deflate, and Fast Deflate compression algorithm to choose from the highest compression ratio but lowest pre-compression throughput at 10G to lowest compression ratio but highest pre-compression throughput at 40G.

### **Path MTU Discovery**

FOS v7.3 supports path MTU discovery on Brocade 7840 to automatically discover IP MTU settings over the WANs.

### **Stream Based Flow Control**

FOS v7.3 supports stream based flow control on Brocade 7840 to isolate slow devices from affecting performance of other devices for emulated devices sharing the same VE\_Port.

### **Out of Order TCP Delivery**

FOS v7.3 supports out of order TCP delivery on Brocade 7840 over WAN connections to minimize retransmission of FC frames in a scenario of TCP packet loss.

### **WAN Test Tool**

FOS v7.3 supports a WAN test tool on Brocade 7840 to generate test traffic over a pair of IP addresses to test a WAN path for any network issue.

## **Monitoring and Alerting Policy Suite (MAPS) Enhancements**

FOS v7.3 has a number of important MAPS feature enhancements. These include:

- Monitor Fabric Performance Impact
- Monitor new FCIP statistics on Brocade 7840
- Monitor fabric scalability limits
- Monitor ClearLink Diagnostic ports
- Monitor Ethernet management ports
- Monitor Flow Vision learning flows
- Support Port Decommissioning as an action
- Support dynamic groups
- Support port group augmentation
- Usability enhancements

### **Monitor Fabric Performance Impact**

FOS v7.3 supports automatic monitoring and alerting of latency bottleneck conditions through pre-defined thresholds and alerts in all pre-defined policies in MAPS. The advanced monitoring capabilities identify ports in two latency severity levels and provide intuitive reporting in MAPS dashboard under a new Fabric Performance Impact category.

### **Monitor FCIP statistics**

FOS v7.3 supports new monitoring elements (RTT, Jitter) in the FCIP circuit group, adds a FCIP tunnel group to monitor tunnel state change and throughput, adds 4 FCIP tunnel QoS groups to monitor throughput and packet loss for each QoS priority. These new monitoring elements and groups are included in MAPS pre-defined policies and supported only on Brocade 7840.

### **Monitor fabric scalability limit**

FOS v7.3 supports new monitoring elements in the switch group to monitor them against the fabric scalability limits supported by Brocade. These elements include number of device connections in a layer2 fabric, number



of imported devices in a metaSAN, number of FCRs in a backbone fabric, and zoning database size. These new monitoring elements are included in MAPS pre-defined policies.

### **Monitor ClearLink Diagnostic (D\_Port) ports**

FOS v7.3 supports new monitoring elements for port error statistics (CRC, ITW, PE, LF, and LOSS\_SYNC) in a new D\_Port logical group to monitor D\_Port tests so that the test results can be determined by thresholds in the MAPS rules. These new monitoring elements and groups are included in MAPS pre-defined policies.

### **Monitor Ethernet management port**

FOS v7.3 supports monitoring Ethernet management port state in a new Ethernet port group to generate alerts if states for Ethernet management ports are changed. These new monitoring elements and group are included in MAPS pre-defined policies.

### **Monitor Flow Vision learning flows**

FOS v7.3 supports importing and monitoring of learning flows created through Flow Vision in MAPS. Administrators can use this capability to configure thresholds and alerts for application flows without knowing the source or destination device identities in advance.

### **Support Port Decommissioning as an action**

FOS v7.3 supports port decommissioning as an action that can be triggered by MAPS rules. With port decommissioning, ports can be gracefully shutdown in the event of violations without I/O interruption. FOS v7.3 supports port decommissioning on E\_Port natively through MAPS. For port decommissioning on F\_Port, Brocade Network Advisor 12.3 is required.

### **Support dynamic group based on user defined pattern**

FOS v7.3 introduces dynamic group to enhance logic group definition for port objects. Administrators can create custom groups whose membership dynamically changes based on user defined port identity traits.

### **Support port group augmentation**

FOS v7.3 implements port group augmentation to pre-defined groups and dynamic groups so that administrators can make small adjustments to group memberships without having to create a new group.

### **Usability enhancements**

FOS v7.3 has a number of usability enhancements to MAPS. These include:

- Change *mapssam* CLI to display system CPU, memory, and flash usage.
- Change *mapsrule* and *logicalgroup* CLIs to make deletion of rules and groups easier.
- Add a new option to *mapsConfig* CLI to send test emails to validate email configuration.

## **Flow Vision Enhancements**

FOS v7.3 has a number of important Flow Vision enhancements to the Flow Monitor, Flow Generator, and Flow Mirror functionalities.

### **Flow Monitor enhancements**

FOS v7.3 extends the learning capability to Flow Monitor on E\_Port and Ex\_Port. FOS v7.3 also supports Flow Monitor for static and learning flows on XISL ports and backbone E\_Port. These enhancements allow administrators to apply Flow Monitor function at all point of interests in most supported SAN topologies.

### **Flow Mirror enhancements**

FOS v7.3 introduces Local Flow Mirror to mirror application flows to a mirror port on the same local switch where the flows are defined. This feature enables administrators to attach external analyzers to the mirror port to capture all frames belonging to the flows for deep analysis. FOS v7.3 enhance Flow Mirror to mirror flows originated from switch CPU and egress on a port, to mirror flows on either ingress or egress on F\_Port and F\_Port trunks. FOS v7.3 adds the support of combination of *-frametype* and *-ingrport* keywords and combination of *-frametype* and *-bidir* keywords in flow definition for Flow Mirror.

## Flow Generator enhancements

FOS v7.3 introduces a system pre-defined flow *sys\_gen\_all\_simports* for Flow Generator to generate test traffic from every SIM port in a switch to all the other SIM ports. This allows administrators to fully stress test a switch before deployment.

## Miscellaneous Flow Vision enhancements

FOS v7.3 supports duplicated flow definition to be created but not activated in a switch. Administrators can create flows with the same parameters but for different Flow Vision functions. FOS v7.3 increases the maximum number of flows on fixed port switches to 128 user-defined flows and 128 sub flows and on backbone switches to 512 user-defined flows and 512 sub flows.

## ClearLink Diagnostic (D\_Port) Enhancements

FOS v7.3 implements following important D\_Port feature enhancements.

### D\_Port and MAPS Integration

FOS v7.3 integrate D\_Port test with MAPS threshold based monitoring. Administrators can use this ability to automatically monitor D\_Port tests and determine D\_Port test success or failure base on threshold settings within MAPS.

### Dynamic D\_Port and On-demand D\_Port

FOS v7.3 implements dynamic D\_Port and on-demand D\_Port modes on ISLs. With these modes, administrators can configure D\_Port test to be run automatically on ISLs after switch enable, slot enable, or port persistent enable.

### D\_Port Provision

FOS v7.3 implements D\_Port provision list to be configured by CLI command *portcfgdport* (via *--provision* option). Ports on the pre-provisioned list do not need to be disabled before being configured as D\_Port.

### portCfgDport Show Result

FOS v7.3 enhances the D\_Port test result displayed by *portCfgDport* command (via *--show* option) to clearly identify loopback connection type or remote port index.

### Port LED Display D\_Port Result

FOS v7.3 implements visually display D\_Port test failure by flashing yellow on the port LED.

### D\_Port on FC16-64 Blade QSFPs

FOS v7.3 implements D\_Port test on the FC compliant QSFPs for FC16-64 blade. Electrical loopback and optical loopback tests are not supported on these QSFPs. Only link saturation test and link distance and latency measurements are performed.

## Read Diagnostics Parameters

FOS v7.3 introduces the Read Diagnostics Parameters feature to support reporting diagnostics parameters associated with optics and media for any link between Nx\_port and Fx\_port from any point within a fabric. Administrators can use this ability to discover and diagnose link related errors or degrading conditions from a single point anywhere within a fabric.

## Link Cable Beacon (Port Peer Beacon)

FOS v7.3 introduces the support of Link Cable Beacon feature, with which administrators can run the *portpeerbeacon* command to turn on port LED beacon on both end of a link cable connection. Administrators can use this feature to quickly identify peer ports of a connection without physically tracing the cables in a data center.

## **E\_Port Balance Priority Routing**

FOS v7.3 enhances routing policy with the E\_Port Balance Priority option. With this enhancement, when multiple paths to a domain exist, routing policy would assign routes so that the bandwidth demands from source ports are evenly distributed among all E\_Ports.

## **FCR enhancements**

FOS v7.3 adds a number of enhancements to FCR.

### **IsanZoneShow Change**

FOS v7.3 enhances CLI IsanZoneShow (via -d option) to display the fabric IDs for devices exist in a fabric and devices imported to a fabric.

### **IsCfg Change**

FOS v7.3 enhances CLI IsCfg (via --show -n option) to display additional information for a logical switch.

### **Fabric Alias Name**

FOS v7.3 supports assigning alias names to each edge fabric IDs. Administrator can use the fabric alias name to represent each edge fabric.

## **Security Enhancements**

FOS v7.3 has a number of important security enhancements.

### **FCAP and DH-CHAP Enhancements**

FOS v7.3 supports SHA-256 hashing algorithm for FCAP and DH-CHAP in both FIPS mode and non-FIPS mode to provide stronger security.

### **In-flight Encryption Enhancements**

FOS v7.3 supports in-flight encryption with session keys derived from FCAP. With this enhancement, administrators can use FCAP and in-flight encryption features at the same time.

### **Fabric-wide Consistency Policy Enhancements**

FOS v7.3 supports FCRs to be present in a fabric with strict fabric-wide consistency policy configuration. Administrators can turn on strict fabric-wide consistency policy even when an FCR is connected to the fabric via an Ex\_Port.

### **Open Source Software Packages**

FOS v7.3 upgrades a number of important open source software packages (openSSH, openssl, Apache) to provide stronger security.

## **Access Gateway Enhancements**

FOS v7.3 implements following Access Gateway (AG) enhancements.

### **ClearLink Diagnostics (D\_Port) Support on AG**

FOS v7.3 supports dynamic D\_Port on connections between an AG and an HBA to allow automatically start D\_Port test requested by an HBA.

### **User Account and Password Distribution to AG**

FOS v7.3 supports user account and password database distribution from a native switch to an AG so that user accounts and passwords can be managed the same way as native switches in a fabric.

## **Fabric Device Management Interface (FDMI) Data Access on AG**

FOS v7.3 adds the support of accessing device information for devices that are registered with FDMI and connected through AGs.

## **Zoning Enhancements**

FOS v7.3 enhances zoning to disallow two fabrics with empty zoning configuration to merge if one fabric has All Access as default zone access mode and the other has No Access as default zone access mode. This enhancement prevents the fabric with All Access default zone access mode from losing all device connections due to converting to No Access default zone access mode after fabrics merging.

## **High Integrity Fabric**

FOS v7.3 introduces support of High Integrity Fabric mode to ensure strict and consistent fabric configurations required by a FICON fabric, which include Insistent Domain ID and strict fabric-wide Switch Connection Control policy. Administrators can use the High Integrity Fabric mode to enforce these configurations for a FICON fabric.

## **RAS Enhancements**

FOS v7.3 implements the following RAS enhancements.

### **Frame Viewer (Class 3 Discard Log) Enhancements**

FOS v7.3 enhances Frame Viewer to capture two new types of class 3 discard frames. The new discard types captured include destination unreachable frames and unroutable frames.

### **Audit Log for Class 3 Discard Frames**

FOS v7.3 adds to audit log message for each class 3 discard frame. This ability to allow administrator to configure audit log to send class 3 discard frame messages to a centralized syslog server, which does not have size limitation of a switch Frame Viewer log.

### **Forward Error Correction (FEC) Enhancements**

FOS v7.3 adds the ability to allow FEC capability negotiation during speed negotiation in Transmitter Training Signal. This ability can be configured by existing CLI command portCfgFec.

### **Firmware Download Enhancement**

FOS v7.3 introduces firmware sync ability for the firmware on an active CP to be automatically synced to a standby CP after the standby CP is hot-plugged into a backbone switch chassis. Administrator can configure this ability on their chassis to enable quick operational replacement of a standby CP.

### **Rolling Reboot Detection Enhancements**

FOS v7.3 enhances the rolling reboot detection feature to detect and stop a rolling reboot in disabled FOS switch state as a first attempt. This would enable an administrator to capture more diagnostic information.

### **New external RASLOG for Link Reset**

FOS v7.3 adds a new external RASLOG (Cx-1014) for Link Reset due to credit loss for both front-end and back-end ports.

### **supportInfoClear Command**

FOS v7.3 introduces a new CLI command supportInfoClear to clear a number of statistics counters and logs. This command can help administrators to quickly reset the counters and logs on behalf of switch vendors in support scenarios.

## **Brocade 8510 ICL Scalability Enhancement**

FOS v7.3 increases the supported number 8510 chassis connected via ICL in a core-edge topology to twelve switches.

## **Miscellaneous Enhancements**

### **trunkShow CLI Enhancement**

FOS v7.3 adds to CLI trunkShow (via -swname option) to display the switch name of the neighboring switch connected on the other end of trunked ports.

### **fabricShow CLI Enhancement**

FOS v7.3 adds to CLI fabricShow (via -version option) to display the firmware version of each switch listed in the fabricShow output.

### **portShow and portName CLI Enhancement**

FOS v7.3 enhances the CLI portShow and portName to display as port name the host name registered with FDMI for the host system attached to that port. Administrators must enable the “Display FDMI Host Name” configuration via the configure CLI.

### **fspfShow and lsdbShow CLI Enhancement**

FOS v7.3 changes fspfShow and lsdbShow CLI output to omit all zero value to be listed in port bitmap values.

### **Device Probing and Update on ALPA 0xC0 and 0x40**

FOS v7.3 enhances FCP probing for devices connected to a port with ALPA 0xC0 and 0x40 to obtain the device information for NS entry.

For base devices that logged in with ALPA 0xC0 and 0x40, FOS v7.3 provides the ability to update NS entries when these base devices perform logout. Administrators can turn on this update mode to ensure NS and login database consistency with “F-port Device Update Mode” option under the “Fabric parameters” section of the configure CLI. This option can only be changed when a switch is disabled.

### **NPIV Base Device Logout Enhancements**

FOS v7.3 enhances NPIV by allowing NPIV devices remain logged in on a port to a fabric when the base device on the same port performs a logout. Administrator can configure this feature via the portCfgFlogiLogout CLI.

### **fosExec Remote Execution**

FOS v7.3 adds the ability to execute a FOS CLI command via fosExec CLI on a remote domain in the fabric. Administrators can enable this capability to execute CLI commands on multiple switches from a single switch in a fabric.

### **CS\_CTL QoS Enhancements**

FOS v7.3 enhances CS\_CTL based QoS feature by reporting the CS\_CTL auto mode in responses to device FLOGI, FDISC, and PLOGI requests.

### **bottleneckMon CLI Change**

FOS v7.3 deprecates the back-end credit recovery options in the bottleneckMon CLI. These options are supported via the existing creditRecovMode CLI.

### **Maximum Auto Speed Negotiation**

FOS v7.3 allows configuring a maximum speed for port auto speed negotiation with CLI portcfgspeed (via -m option). Administrators can use this to control the maximum speed a device is allowed to join a fabric but still allow port speed to be auto negotiated.

### **Back-end credit recovery on FX8-24 blade**

FOS v7.3 enhances back-end credit loss detection and recovery to back-end links on FX8-24 with the existing CLI command `creditRecovMode`.

### **aptPolicy change**

FOS v7.3 deprecates AP policy related configuration from the CLI command `aptPolicy`. AP policy is used only by FR4-18i blade, which is not supported since FOS 7.1.

### **slotPowerOn and slotPowerOff enhancement**

FOS v7.3 supports `slotPowerOn` and `slotPowerOff` command on core blades in a DCX/DCX-4 or DCX 8510/DCX 8510-4 chassis. Administrators can use this command to power on or off a core blade without physical presence.

### **Port Transition from Persistent Disabled to Disabled**

FOS v7.3 supports directly transition a persistently disabled port to the disabled state without having to persistently enable the port first. Administrator can configure this option via the new `portCfgPersistence` command

### **portBeacon Change**

FOS v7.3 enhances the `portBeacon` command to list all beaconing ports in a switch (via `-all` option).

### **ethif Command**

FOS v7.3 introduces a new CLI command `ethif` to manage the switch Ethernet management interfaces. With this command, administrator can configure and show the state Ethernet management interfaces.

### **haRedundancy Command**

FOS v7.3 introduces a new CLI command `haRedundancy` to display switch uptime and HA redundancy settings for a backbone switch.

## Optionally Licensed Software

Fabric OS v7.3 includes all basic switch and fabric support software, as well as optionally licensed software that is enabled via license keys.

Optionally licensed features include:

**Brocade Ports on Demand**—Allows customers to instantly scale the fabric by provisioning additional ports via license key upgrade. (Applies to select models of switches).

**Brocade Extended Fabrics**—Provides greater than 10km of switched fabric connectivity at full bandwidth over long distances (depending on platform this can be up to 3000km).

**Note:**

If a port on 16G FC blades or a 16G switch is configured to operate at 10G speed, Extended fabrics license is not needed to enable long distance connectivity on that port.

**Brocade ISL Trunking**— Provides the ability to aggregate multiple physical links into one logical link for enhanced network performance and fault tolerance. Also includes Access Gateway ISL Trunking on those products that support Access Gateway deployment.

**Brocade Advanced Performance Monitoring**—Enables performance monitoring of networked storage resources. This license includes the Top Talkers feature.

**Brocade Fabric Watch** — Monitors mission-critical switch operations. Fabric Watch includes Port Fencing capabilities.

**Brocade Fabric Vision** – Enables MAPS (Monitoring and Alerting Policy Suite), Flow Vision, and ClearLink (D\_Port) to non-Brocade devices. MAPS enables rules based monitoring and alerting capabilities, provides comprehensive dashboards to quickly troubleshoot problems in Brocade SAN environments. Flow Vision enables host to LUN flow monitoring, application flow mirroring for non-disruptive capture and deeper analysis, and test traffic flow generation function for SAN infrastructure validation. D\_Port to non-Brocade devices allows extensive diagnostic testing of links to devices other than Brocade switches and adapters. (Functionality requires support by attached device, availability TBD).

Fabric Vision license also enables Fabric Watch and Advanced Performance Monitoring functionalities without requiring Brocade Fabric Watch or Brocade Advanced Performance Monitoring license (with FOS v7.2 and later only).

**Note:**

If installed on a switch operating with FOS v7.1.x, the Fabric Vision license will be displayed as “Fabric Insight”. If installed on a switch operating with FOS v7.0.x or earlier, the Fabric Vision license will be displayed as “Unknown”. Fabric Vision features are not supported under FOS v7.1.x or earlier.

**FICON Management Server**— Also known as “CUP” (Control Unit Port), enables host-control of switches in Mainframe environments.

**Enhanced Group Management** — This license enables full management of devices in a data center fabric with deeper element management functionality and greater management task aggregation throughout the environment. This license is used in conjunction with Brocade Network Advisor application software and is applicable to all FC platforms supported by FOS v7.0 or later.

**Note:** This capability is enabled by default on all Gen 5 65XX model switches and DCX 8510 platforms, and on DCX and DCX-4S platforms that are running Fabric OS v7.0.0 or later. Gen 5 embedded switches receive this capability by default with FOS v7.2.1 and later. Individual upgrade is required when upgrading directly to FOS v7.2.1 on Gen 5 embedded switches. Subsequent group operations on Gen 5 embedded switches including group upgrade are supported..

**Adaptive Networking with QoS**—Adaptive Networking provides a rich framework of capability allowing a user to ensure high priority connections obtain the bandwidth necessary for optimum performance, even in congested environments. The QoS SID/DID Prioritization and Ingress Rate Limiting features are the first components of this license option, and are fully available on all 8Gb and 16Gb platforms.

**Note :**

With FOS v7.2, the Adaptive Networking license has become part of the base FOS firmware, and features under this license no longer require the license to be installed. Customers that wish to have these capabilities without purchasing the license are required to upgrade to FOS v7.2 or later.

Brocade 6520 does not require the Adaptive Networking with QoS license to enable the capabilities associated with this license. These capabilities are included by default on the Brocade 6520.

**Server Application Optimization** — When deployed with Brocade Server Adapters, this license optimizes overall application performance for physical servers and virtual machines by extending virtual channels to the server infrastructure. Application specific traffic flows can be configured, prioritized, and optimized throughout the entire data center infrastructure. This license is not supported on the Brocade 8000.

**Note :**

With FOS v7.2, Server Application Optimization license has become part of the base FOS firmware, and features under this license no longer require the license to be installed. Customers that wish to have these capabilities without purchasing the license are required to upgrade to FOS v7.2 or later.

Brocade 6520 does not require the SAO license to enable the capabilities associated with this license. These capabilities are included by default on the Brocade 6520.

**Integrated Routing**— This license allows any port in a DCX 8510-8, DCX 8510-4, Brocade 6510, Brocade 6520, DCX-4S, DCX, 5300, 5100, 7800, 7840, or Brocade Encryption Switch to be configured as an Ex\_port or VEx\_port (on some platforms) supporting Fibre Channel Routing.

**Encryption Performance Upgrade** — This license provides additional encryption processing power. For the Brocade Encryption Switch or a DCX/DCX-4S/DCX 8510-8/DCX 8510-4, the Encryption Performance License can be installed to enable full encryption processing power on the BES or on all FS8-18 blades installed in a DCX/DCX-4S/DCX 8510-8/DCX 8510-4 chassis.

**DataFort Compatibility** — This license is required on the Brocade Encryption Switch or DCX/DCX-4S/DCX 8510-8/DCX 8510-4 with FS8-18 blade(s) to read and decrypt NetApp DataFort-encrypted disk and tape LUNs. DataFort Compatibility License is also required on the Brocade Encryption Switch or DCX/DCX-4S/DCX 8510-8/DCX 8510-4 Backbone with FS8-18 Encryption Blade(s) installed to write and encrypt the disk and tape LUNs in NetApp DataFort Mode (Metadata and Encryption Algorithm) so that DataFort can read and decrypt these LUNs. DataFort Mode tape encryption and compression is supported beginning with the FOS v6.2.0 release on DCX platforms. Availability of the DataFort Compatibility license is limited; contact your vendor for details.

**Advanced Extension** – This license enables two advanced extension features: FCIP Trunking and Adaptive Rate Limiting. The FCIP Trunking feature allows multiple IP source and destination address pairs (defined as FCIP Circuits) via multiple 1GbE or 10GbE interfaces to provide a high bandwidth FCIP tunnel and failover resiliency. In addition, each FCIP circuit supports four QoS classes (Class-F, High, Medium and Low Priority), each as a TCP connection. The Adaptive Rate Limiting feature provides a minimum bandwidth guarantee for each tunnel with full utilization of the available network bandwidth without impacting throughput performance under high traffic load. This license is available on the 7800, 7840, and the DCX/DCX-4S/DCX 8510-8/DCX 8510-4 for the FX8-24 on an individual slot basis.



**10GbE FCIP/10G Fibre Channel** – This license enables the two 10GbE ports on the FX8-24 and/or the 10G FC capability on FC16-xx blade ports supported on DCX 8510 platforms except for the FC16-64 blade. On the Brocade 6510, Brocade 6520 this license enables 10G FC ports. This license is not applicable to Brocade 7840 or Brocade 6505.

**On FX8-24:**

With this license installed and assigned to a slot with an FX8-24 blade, two additional operating modes (in addition to 10 1GbE ports mode) can be selected:

- 10 1GbE ports and 1 10GbE port, or
- 2 10GbE ports

**On FC16-xx:**

- Enables 10G FC capability on an FC16-xx blade in a slot that has this license

**On Brocade 6510, Brocade 6520:**

- Enables 10G FC capability on Brocade 6510 and Brocade 6520.

This license is available on the DCX/DCX-4S/DCX 8510-8/DCX 8510-4 on an individual slot basis.

**Advanced FICON Acceleration** – This licensed feature uses specialized data management techniques and automated intelligence to accelerate FICON tape read and write and IBM Global Mirror data replication operations over distance, while maintaining the integrity of command and acknowledgement sequences. This license is available on the 7800, 7840, and the DCX/DCX-4S/DCX 8510-8/DCX 8510-4 for the FX8-24 on an individual slot basis.

**7800 Port Upgrade** – This license allows a Brocade 7800 to enable 16 FC ports (instead of the base four ports) and six GbE ports (instead of the base two ports). This license is also required to enable additional FCIP tunnels and also for advanced capabilities like tape read/write pipelining.

**ICL 16-link, or Inter Chassis Links** – This license provides dedicated high-bandwidth links between two Brocade DCX chassis, without consuming valuable front-end 8Gb ports. Each chassis must have the 16-link ICL license installed in order to enable the full 16-link ICL connections. (Available on the DCX only.)

**ICL 8-Link** – This license activates all eight links on ICL ports on a DCX-4S chassis or half of the ICL bandwidth for each ICL port on the DCX platform by enabling only eight links out of the sixteen links available. This allows users to purchase half the bandwidth of DCX ICL ports initially and upgrade with an additional 8-link license to utilize the full ICL bandwidth at a later time. This license is also useful for environments that wish to create ICL connections between a DCX and a DCX-4S, the latter of which cannot support more than 8 links on an ICL port. Available on the DCX-4S and DCX platforms only.

**ICL POD License** – This license activates ICL ports on core blades of DCX 8510 platforms. An ICL 1st POD license only enables half of the ICL ports on CR16-8 core blades of DCX 8510-8 or all of the ICL ports on CR16-4 core blades on DCX 8510-4. An ICL 2nd POD license enables all ICL ports on CR16-8 core blades on a DCX 8510-8 platform. (The ICL 2<sup>nd</sup> POD license does not apply to the DCX 8510-4.)

**Enterprise ICL (EICL) License** – The EICL license is required on a Brocade DCX 8510 chassis when that chassis is connected to four or more Brocade DCX 8510 chassis via ICLs either as ISLs or IFLs.

Note that this license requirement does not depend upon the total number of DCX 8510 chassis that exist in a fabric, but only on the number of other chassis connected to a DCX 8510 via ICLs. This license is recognized/displayed when operating with FOS v7.0.1 but enforced with FOS v7.1.0 or later.

**Note:** The EICL license supports a maximum of nine DCX 8510 chassis connected in a full mesh topology or up to twelve DCX 8510 chassis connected in a core-edge topology. Refer to the Brocade SAN Scalability Guidelines document for additional information.

**WAN Rate Upgrade 1 License** – The WAN Rate Upgrade 1 license provides the additional WAN throughput up to 10 Gbps on Brocade 7840. The base configuration of Brocade 7840 without the WAN Rate Upgrade 1 license provides WAN throughput up to 5 Gbps.

**WAN Rate Upgrade 2 License** – The WAN Rate Upgrade 2 license provides unlimited WAN throughput (other than the hardware limit) on Brocade 7840. The WAN Rate Upgrade 2 licenses also enable the use of two 40GbE ports on Brocade 7840. The 40GbE ports cannot be configured without the WAN Rate Upgrade 2 license. A WAN Rate Upgrade 1 license must be installed on a Brocade 7840 before a WAN Rate Upgrade 2 license is installed. A WAN Rate Upgrade 1 license cannot be removed before the WAN Rate Upgrade 2 license has been removed.

**Note:** The WAN Rate Upgrade 1 and WAN Rate Upgrade 2 licenses apply only to Brocade 7840. They control the aggregate bandwidth for all tunnels on a Brocade 7840. The entire capacity controlled by the licenses can be assigned to a single tunnel subject to hardware limitation, or a portion of the capacity can be assigned to multiple tunnels. The total bandwidth aggregated for all tunnels should not exceed the limits established by the licenses.

## Temporary License Support

The following licenses are available in FOS v7.3 as Universal Temporary or regular temporary licenses:

- Fabric (E\_Port) license
- Extended Fabric license
- Trunking license
- High Performance Extension license
- Advanced Performance Monitoring license
- Fabric Watch license
- Integrated Routing license
- Advanced Extension license
- Advanced FICON Acceleration license
- 10GbE FCIP/10GFibre Channel license
- FICON Management Server (CUP)
- Enterprise ICL license
- Fabric Vision license
- WAN Rate Upgrade 1 license
- WAN Rate Upgrade 2 license

**Note:** Temporary Licenses for features available on a per slot basis enable the feature for any and all slots in the chassis.

Temporary and Universal Temporary licenses have durations and expiration dates established in the licenses themselves. FOS will accept up to two temporary licenses and a single Universal license on a unit. Universal Temporary license keys can only be installed once on a particular switch, but can be applied to as many switches as desired. Temporary use duration (the length of time the feature will be enabled on a switch) is provided with the license key. All Universal Temporary license keys have an expiration date upon which the license can no longer be installed on any unit.

## Supported Switches

FOS v7.3.1 supports the following platforms:

- 300, 5100, 5300, 7800, VA-40FC, Brocade Encryption Switch, DCX, DCX-4S
- 6510, 6505, 6520, 7840, DCX 8510-8, DCX 8510-4
- FC8-16, FC8-32, FC8-48, FC8-64, FX8-24, FS8-18, FCOE10-24
- FC16-32, FC16-48, FC16-64, FC8-32E, FC8-48E
- 5410, M5424, 5430, 5431, 5432, 5450, 5460, 5470, 5480, NC-5480
- 6545, 6546, 6547, 6548, M6505

Access Gateway mode is also supported by Fabric OS v7.3, and is supported on the following switches: the Brocade 300, 5100, VA-40FC, 5410, 5430, 5431, 5432, 5450, 5460, 5470, 5480, NC-5480, M5424, 6545, 6546, 6547, 6548, M6505, 6510, 6505.

The Brocade 8000 is not supported with FOS v7.2.0 and later.

## Standards Compliance

This software conforms to the Fibre Channel Standards in a manner consistent with accepted engineering practices and procedures. In certain cases, Brocade might add proprietary supplemental functions to those specified in the standards. For a list of FC standards conformance, visit the following Brocade Web site: <http://www.brocade.com/sanstandards>

The FCOE10-24 blade conforms to the following Ethernet standards:

- IEEE 802.1D      Spanning Tree Protocol
- IEEE 802.1s      Multiple Spanning Tree
- IEEE 802.1w      Rapid reconfiguration of Spanning Tree Protocol
- IEEE 802.3ad      Link Aggregation with LACP
- IEEE 802.3ae      10G Ethernet
- IEEE 802.1Q      VLAN Tagging
- IEEE 802.1p      Class of Service Prioritization and Tagging
- IEEE 802.1v      VLAN Classification by Protocol and Port
- IEEE 802.1AB      Link Layer Discovery Protocol (LLDP)
- IEEE 802.3x      Flow Control (Pause Frames)

The following draft versions of the Converged Enhanced Ethernet (CEE) and Fibre Channel over Ethernet (FCoE) Standards are also supported on the FCOE10-24 blade:

- IEEE 802.1Qbb      Priority-based Flow Control
- IEEE 802.1Qaz      Enhanced Transmission Selection
- IEEE 802.1      DCB Capability Exchange Protocol (Proposed under the DCB Task Group of IEEE 802.1 Working Group)
- FC-BB-5      FCoE (Rev 2.0)

## Technical Support

Contact your switch supplier for hardware, firmware, and software support, including product repairs and part ordering. To expedite your call, have the following information immediately available:

### 1. General Information

- Technical Support contract number, if applicable
- Switch model
- Switch operating system version

- Error numbers and messages received
- **supportSave** command output and associated files
  - For dual CP platforms running FOS v6.2 and above, the supportsave command gathers information from both CPs and any AP blades installed in the chassis
- Detailed description of the problem, including the switch or fabric behavior immediately following the problem, and specific questions
- Description of any troubleshooting steps already performed and the results
- Serial console and Telnet session logs
- Syslog message logs

## 2. Switch Serial Number

The switch serial number is provided on the serial number label, examples of which are shown here:



The serial number label is located as follows:

- Brocade Encryption Switch, VA-40FC, 300, 5100, 5300, 6510, 6505, 6520 – On the switch ID pull-out tab located on the bottom of the port side of the switch
- Brocade 7800, 7840 – On the pull-out tab on the front left side of the chassis underneath the serial console and Ethernet connection and on the bottom of the switch in a well on the left side underneath (looking from front)
- Brocade DCX, DCX 8510-8 – Bottom right of the port side
- Brocade DCX-4S, DCX 8510-4 – Back, upper left under the power supply

## 3. World Wide Name (WWN)

When the Virtual Fabric feature is enabled on a switch, each logical switch has a unique switch WWN. Use the **wwn** command to display the switch WWN.

If you cannot use the **wwn** command because the switch is inoperable, you can get the primary WWN from the same place as the serial number, except for the Brocade DCX/DCX-4S and DCX 8510-8/DCX 8510-4. For the Brocade DCX/DCX-4S and DCX 8510-8/DCX 8510-4 access the numbers on the WWN cards by removing the Brocade logo plate at the top of the non-port side. The WWN is printed on the LED side of both cards.

### 1. License Identifier (License ID)

There is only one License Identifier associated with a physical switch or director/backbone chassis. This License Identifier is required as part of the ordering process for new FOS licenses.

Use the **licenseIdShow** command to display the License Identifier.

## FOS Migration Considerations

This section contains important details to consider before migrating to or from this FOS release.

### FOS Upgrade and Downgrade Special Considerations

DCX/DCX-4S units with FCOE10-24 blades running any FOS v7.2.x can be non-disruptively upgraded to FOS v7.3.2a. This upgrade is non-disruptive to both FC and FCoE traffic (when using FCOE10-24 blades). In FOS versions prior to v7.1.0, firmware upgrade is disruptive to FCoE traffic.

Any firmware activation on Brocade 7800, or DCX, DCX-4S, DCX 8510-8, DCX 8510-4 with FX8-24 will disrupt I/O traffic on the [FCIP links](#).

For FCIP, the best practice is to always operate the switch or blade at both ends of the tunnel with the same level of Fabric OS, down to the maintenance release. Fabric OS upgrades should be done on both ends of the FCIP tunnel concurrently.

In rare conditions, upgrade to FOS v7.3.x may fail if the firmware have been upgraded from FOS v6.4.x to FOS v7.1.x using the optional “-s” parameter with the *firmwaredownload* command. Downgrade from FOS v7.4.x may also fail. Please contact your technical support provider for workaround in these rare cases.

**Disruptive** upgrades to Fabric OS v7.3.2a are allowed and supported from FOS v7.1.x (up to a two-level migration) using the optional “-s” parameter with the *firmwaredownload* command.

If there are multiple node EGs (encryption groups) in a fabric, please complete *firmwaredownload* on one node at a time before downloading on another node.

### Recommended Migration Paths to FOS v7.3.2a

#### Migrating from FOS v7.2

Any 8G or 16G platform running any FOS v7.2.x firmware can be non-disruptively upgraded to FOS v7.3.2a.

#### Migrating from FOS v7.1

Any 8G or 16G platform operating at FOS v7.1.x must be upgraded to FOS v7.2.x before non-disruptively upgrading to FOS v7.3.2a.

Disruptive upgrade to FOS v7.3.2a from FOS v7.1 is supported.

## Important Notes

This section contains information that you should consider before you use this Fabric OS release.

### Brocade Network Advisor Compatibility

Brocade Network Advisor greatly simplifies the steps involved in daily operations while improving the performance and reliability of the overall SAN and IP networking environment. Brocade Network Advisor unifies, under a single platform, network management for SAN, LAN and converged networks. Brocade Network Advisor provides a consistent user experience, across the entire Brocade portfolio of switches, routers and adapters.

Brocade Network Advisor provides health and performance dashboards, with an easy-to-use graphical user interface and comprehensive features that automate repetitive tasks. With Brocade Network Advisor, storage and network administrators can proactively manage their SAN environments to support non-stop networking, address issues before they impact operations, and minimize manual tasks.

Brocade Network Advisor is available with flexible packaging and licensing options for a wide range of network deployments and for future network expansion. Brocade Network Advisor 12.3.0 is available in

- SAN-only edition
- IP-only edition
- SAN+IP edition.

For SAN Management, Network Advisor 12.3.0 is available in three editions:

- **Network Advisor Professional:** a fabric management application that is ideally suited for small-size businesses that need a lightweight management product to manage their smaller fabrics. It manages one FOS fabric at a time and up to 1,000 switch ports. It provides support for Brocade FC switches, Brocade HBAs / CNAs, and Fibre Channel over Ethernet (FCoE) switches.
- **Network Advisor Professional Plus:** a SAN management application designed for medium-size businesses or departmental SANs for managing up to thirty-six physical or virtual fabrics (FOS) and up to 2,560 switch ports. It supports Brocade backbone and director products (DCX 8510-4/DCX-4S, 48Ks, etc.), FC switches, Fibre Channel Over IP (FCIP) switches, Fibre Channel Routing (FCR) switches/ Integrated Routing (IR) capabilities, Fibre Channel over Ethernet (FCoE) / DCB switches, and Brocade HBAs / CNAs.
- **Network Advisor Enterprise:** a management application designed for enterprise-class SANs for managing up to thirty-six physical or virtual fabrics and up to 9,000 switch ports. Network Advisor SAN Enterprise supports all the hardware platforms and features that Network Advisor Professional Plus supports, and adds support for the Brocade DCX Backbone (DCX 8510-8/DCX) and Fiber Connectivity (FICON) capabilities.

More details about Network Advisor's new enhancements can be found in the Network Advisor 12.3.0 Release Notes, Network Advisor 12.3.0 User Guide, and Network Advisor 12.3.0 Installation, Migration, & Transition Guides.

#### Note:

Brocade Network Advisor 12.3.0 or later is required to manage switches running FOS 7.3.0 or later.

The Brocade Network Advisor seed switch should always have the highest FOS version used in the fabric.

### WebTools Compatibility

FOS v7.3.2a is qualified and supported with Oracle Java version 7 update 80 and Java version 8 update 66. Please refer to Other Important Notes and Recommendations section for more details.

## SMI Compatibility

- It is important to note that host SMI-S agents cannot be used to manage switches running FOS v7.3. If users want to manage a switch running FOS v7.3 using SMI-S interface, they must use Brocade Network Advisor's integrated SMI agent.

## Fabric OS Compatibility

The following table lists the earliest versions of Brocade software supported in this release, that is, the *earliest* supported software versions that interoperate. Brocade recommends using the *latest* software versions to get the greatest benefit from the SAN.

To ensure that a configuration is fully supported, always check the appropriate SAN, storage or blade server product support page to verify support of specific code levels on specific switch platforms prior to installing on your switch. Use only FOS versions that are supported by the provider.

For a list of the effective end-of-life dates for all versions of Fabric OS, visit the following Brocade Web site:

<http://www.brocade.com/en/support/product-end-of-life.html>

Supported Products and FOS Interoperability	
4900, 7500, 7500e, 5000, 200E, 48K Brocade 4012, 4016, 4018, 4020, 4024, 4424	v6.2.2 or later <sup>5</sup>
Brocade 5410, 5480, 5424, 5450, 5460, 5470, NC-5480	v6.2.0 or later <sup>5</sup>
Brocade DCX, 300, 5100, 5300	v6.1.0e and later <sup>1 5 7</sup>
VA-40FC	v6.2.1_vfc <sup>5</sup> , v6.2.2 or later <sup>5</sup>
Brocade DCX-4S	v6.2.0 or later <sup>5 7</sup>
Brocade DCX with FS8-18 blade(s), Brocade Encryption Switch	v6.1.1_enc or later <sup>5</sup>
Brocade 7800, DCX and DCX-4S with FCOE10-24 or FX8-24 blades	V6.3.0 or later
Brocade 8000 <sup>9</sup>	V6.1.2_CEE1 or later
Brocade DCX/DCX-4S with FA4-18 blade(s)	DCX requires v6.0.x or later <sup>5</sup> , DCX-4S requires 6.2.x or later <sup>4 7</sup>
Brocade DCX 8510-8/DCX 8510-4	FOS v7.0 or later
Brocade DCX 8510-8/DCX 8510-4 with FC16-64 blade	FOS v7.3.0 or later
Brocade DCX 8510-8 with FCOE10-24 blade	FOS v7.3.0 or later
Brocade 6510	FOS v7.0 or later
Brocade 6505	FOS v7.0.1 or later
Brocade 6520	FOS v7.1 or later
Brocade 7840	FOS v7.3.0 or later
5430	FOS v7.1 or later <sup>9</sup>
5431, 6547, M6505	FOS v7.2 or later <sup>9</sup>
6548, 5432	v7.2.1 or later <sup>9</sup>
6545, 6546	v7.3.1 or later <sup>9</sup>
48000 with FA4-18 blade(s), Brocade 7600	V6.2.2 or later <sup>5</sup>



Supported Products and FOS Interoperability	
Mi10k, M6140 (McDATA Fabric Mode and Open Fabric Mode)	Not Supported

Multi-Protocol Router Interoperability	
Brocade 7500 and FR4-18i blade	V6.2.2 and higher <sup>3 5 7</sup>
McDATA SANRouters 1620 and 2640	Not Supported

NOS (VDX Platform) Interoperability	
Brocade VDX6710, VDX6720, VDX6730	NOS v2.1.1 or later <sup>6</sup>
Brocade VDX8770	NOS 3.0 or later

#### Table Notes:

- <sup>1</sup> When directly attached to a Host or Target that is part of an encryption flow.
- <sup>2</sup> These platforms may not be directly attached to hosts or targets for encryption flows.
- <sup>3</sup> McDATA 1620 and 2640 SANRouters should not be used with FOS-based routing (FCR) for connections to the same edge fabric.
- <sup>4</sup> FA4-18 is not supported in a DCX/DCX-4S that is running FOS v7.0 or later
- <sup>5</sup> If operating with **FOS v6.2.2e or earlier**, Adaptive Networking QoS must be disabled when connecting to 16G FC platform. Otherwise, ISL will segment.
- <sup>6</sup> Connectivity to FC SAN is established via VDX6730 connected to FCR running FOS v7.0.1 or later. FCR platforms supported include 5100, VA-40FC, 5300, 7800, DCX, DCX-4S, DCX 8510-8, DCX 8510-4, 6510, 6520 (requires FOS v7.1 or later). For higher FCR backbone scalability (refer to separate "Brocade SAN Scalability Guidelines" documentation for details), please use 5300, 6520, DCX, DCX-4S, DCX 8510-8, and DCX 8510-4.
- <sup>7</sup> FR4-18i and FC10-6 are not supported on DCX/DCX-4S on FOS v7.1 or later.
- <sup>8</sup> Brocade 8000 is not supported with FOS v7.2 or later.
- <sup>9</sup> Represents the earliest major FOS version. These embedded platforms running respective dedicated FOS versions can also interoperate with FOS v7.3.

#### Zoning Compatibility Note:

Users are recommended to upgrade to the following versions of firmware when interoperating with a switch running FOS v7.0 or later in the same layer 2 fabric to overcome some of the zoning operations restrictions that otherwise exist:

Main code level	Patch code levels with full zoning compatibility
FOS v6.2	FOS v6.2.2d or later
FOS v6.3	FOS v6.3.2a or later
FOS v6.4	FOS v6.4.1 or later

If there are switches running FOS versions lower than the above listed patch levels in the same fabric as a switch with FOS v7.0 or later, then cfsave and cfsenable operations **initiated** from these switches will fail if the zoning database is greater than 128KB. In such scenarios zoning operations such as cfsave/cfsenable can still be performed successfully if initiated from a switch running FOS v7.0 or later.

## SNMP Support

Starting with FOS v7.2.0, the *Fabric OS MIB Reference* document is not updated. You can obtain the latest MIBs from the downloads area of MyBrocade site after logging in.

For information about SNMP support in Fabric Operating System (FOS) and how to use MIBs, see the *Fabric OS Administrator's Guide*.

### Obtaining the MIBs

You can download the MIB files required for this release from the downloads area of the MyBrocade site.

To download the Brocade-specific MIBs from the Brocade Technical Support website, you must have a user name and password.

1. On your web browser, go to <http://my.brocade.com>.
2. Login with your user name and password.
3. Click the downloads tab.
4. On the downloads tab, under Product Downloads, select All Operating Systems from the Download by list.
5. Select Fabric Operating System (FOS), and then navigate to the release.
6. Navigate to the link for the MIBs package and either open the file or save it to disk.

**NOTE:** Distribution of standard MIBs has been stopped. Download the required standard MIBs from the <http://www.oidview.com/> or <http://www.mibdepot.com/> website.

### FOS v7.3.0a Changes in SNMP MIBs and Objects

This release introduces the following changes in MIBs and objects.

#### New MIBs

There are no new MIBs introduced in this patch release.

#### Modified MIBs

The "swIODState" MIB object is newly added to the **SW.mib** to display the In-Order delivery (IOD) state.

MIB Object and OID	Description
swIODState 1.3.6.1.4.1.1588.2.1.1.1.38	The MIB object represents the IOD feature state. Possible values are: <ul style="list-style-type: none"><li>• 1 – enabled</li><li>• 2 – disabled</li><li>• 3 – unknown</li></ul>

### FOS v7.3.0 Changes in SNMP MIBs and Objects

This release introduces the following changes in MIBs and objects:

### New MIBs

There are no new MIBs introduced in this release.

### Updated MIBs

The following existing MIBs are supported for Brocade 7840 platform.

- **BRCD-FCIP-EXT-MIB**

Table Name	Is Supported	Description
fcipExtendedLinkTable	Yes	This table contains statistical information about FCIP tunnel compression, retransmission, packet loss, and latency details. The information stored in this table is returned in response to <b>portshow fcip tunnel</b> commands.
fcipConnStatsTable	Yes	The table contains statistical information about FCIP tunnel compression, retransmission, packet loss, and latency details. <b>Note:</b> This table shows circuits and TCP connections stats. However, for Brocade 7840 platform this table shows only circuit stats.

- **IF-MIB**

Table Name	Is Supported	Description
ifTable	Yes	This table contains the statistics of switch interfaces including FCIP tunnels.
ifXTable	Yes	This table is enhanced version of ifTable.
ifTestTable	No	Not supported.
ifStackTable	No	Not supported.
ifRcvAddressTable	No	Not supported.

- **FCIP-MGMT-MIB**

Table Name	Is Supported	Description
fcipEntityInstanceTable	Yes	This table contains the information related to FCIP entities.
fcipLinkErrorsTable	No	Not supported.
fcipLinkTable	Yes	This table contains the information about link of FCIP entities.
fcipTcpConnTable	No	Not supported.
ifRcvAddressTable	No	Not supported.

## MIB Objects

### *fcipExtendedLinkTable*

This table contains statistical information about FCIP tunnel compression, retransmission, packet loss, and latency details.

MIB Object and OID	Description
fcipExtendedLinkIfIndex 1.3.6.1.4.1.1588.4.1.1.1	The ifIndex value of the virtual interface corresponding to the FCIP tunnels running over TCP/IP.
fcipExtendedLinkTcpRetransmits 1.3.6.1.4.1.1588.4.1.1.2	The number of retransmitted packets.
fcipExtendedLinkTcpDroppedPackets 1.3.6.1.4.1.1588.4.1.1.3	The number of dropped packets.
fcipExtendedLinkTcpSmoothedRTT 1.3.6.1.4.1.1588.4.1.1.4	The round trip time (latency) in milliseconds for a transfer over an FCIP tunnel.
fcipExtendedLinkCompressionRatio 1.3.6.1.4.1.1588.4.1.1.5	The ratio between compressed bytes and raw bytes over an FCIP tunnel.
fcipExtendedLinkRawBytes 1.3.6.1.4.1.1588.4.1.1.6	The total number of raw bytes sent or received.
fcipExtendedLinkCompressedBytes 1.3.6.1.4.1.1588.4.1.1.7	The total number of compressed bytes received over an FCIP tunnel.
fcipExtendedLinkConnectedCount 1.3.6.1.4.1.1588.4.1.1.8	The total number of TCP session connections.
fcipExtendedLinkRtxRtxTO 1.3.6.1.4.1.1588.4.1.1.9	A counter containing retransmit packets due to timeout.
fcipExtendedLinkRtxDupAck 1.3.6.1.4.1.1588.4.1.1.10	A counter containing retransmit packets due to duplicate acknowledgement.
fcipExtendedLinkDupAck 1.3.6.1.4.1.1588.4.1.1.11	A counter containing duplicate acknowledgement packets.
fcipExtendedLinkRtt 1.3.6.1.4.1.1588.4.1.1.12	The round trip time in milliseconds.
fcipExtendedLinkOoo 1.3.6.1.4.1.1588.4.1.1.13	A counter containing TCP out-of-order.
fcipExtendedLinkSlowStarts 1.3.6.1.4.1.1588.4.1.1.14	A counter containing slow starts.

### *fcipConnStatsTable*

This table contains statistical information about FCIP circuit and connection compression, retransmission, packet loss, and latency details. For Brocade 7840 platform this table shows only circuit stats.

MIB Object and OID	Description
xfcipEntityId 1.3.6.1.4.1.1588.4.2.1.1	The FCIP entity identifier.
xfcipLinkIfIndex 1.3.6.1.4.1.1588.4.2.1.2	The ifIndex value of the virtual interface corresponding to the FCIP Link running over TCP/IP.
xfcipLinkIndex 1.3.6.1.4.1.1588.4.2.1.3	An arbitrary integer that uniquely identifies one FCIP link within an FCIP entity.
xfcipExtendedLinkTcpRetransmits 1.3.6.1.4.1.1588.4.2.1.4	The number of retransmitted packets.
xfcipExtendedLinkTcpDroppedPackets 1.3.6.1.4.1.1588.4.2.1.5	The number of dropped packets.
xfcipExtendedLinkTcpSmoothedRTT 1.3.6.1.4.1.1588.4.2.1.7	The round trip time (latency) in milliseconds.
xfcipExtendedLinkCompressionRatio 1.3.6.1.4.1.1588.4.2.1.6	The compression ratio of the link.
xfcipExtendedLinkRawBytes 1.3.6.1.4.1.1588.4.2.1.8	The total number of raw bytes sent or received.
xfcipExtendedLinkCompressedBytes 1.3.6.1.4.1.1588.4.2.1.9	The total number of compressed bytes sent or received.

#### **ifTable**

This table contains the statistics of switch interfaces including FCIP tunnels.

MIB Object and OID	Description
ifIndex .1.3.6.1.2.1.2.2.1.1	The interface index.
ifDesc .1.3.6.1.2.1.2.2.1.2	The description of the interface.
ifType .1.3.6.1.2.1.2.2.1.3	The media type.
ifMtu .1.3.6.1.2.1.2.2.1.4	The largest size packet that can be transmitted.
ifSpeed .1.3.6.1.2.1.2.2.1.5	The interface speed in Mbps.
ifPhysAddress .1.3.6.1.2.1.2.2.1.6	The physical address of the interface.

MIB Object and OID	Description
ifAdminStatus .1.3.6.1.2.1.2.2.1.7	The admin status of the interface
ifOperStatus .1.3.6.1.2.1.2.2.1.8	The operational status of the interface.
ifLastChange .1.3.6.1.2.1.2.2.1.9	The operational state time.
ifInOctets .1.3.6.1.2.1.2.2.1.10	The number of received bytes.
ifInUcastPkts .1.3.6.1.2.1.2.2.1.11	The number of received unicast packets.
ifInNUcastPkts .1.3.6.1.2.1.2.2.1.12	This object is deprecated in favour of ifInMulticastPkts and ifInBroadcastPkts.
ifInDiscards .1.3.6.1.2.1.2.2.1.13	The number of discarded packets.
ifInErrors .1.3.6.1.2.1.2.2.1.14	The number of received packets having errors.
ifInUnknownProtos .1.3.6.1.2.1.2.2.1.15	The number of received packets having unknown or unsupported protocols.
ifOutOctets .1.3.6.1.2.1.2.2.1.16	The number of transmitted bytes.
ifOutUcastPkts .1.3.6.1.2.1.2.2.1.17	The number of transmitted unicast packets.
ifOutNUcastPkts .1.3.6.1.2.1.2.2.1.18	This object is deprecated in favour of ifOutMulticastPkts and ifOutBroadcastPkts.
ifOutDiscards .1.3.6.1.2.1.2.2.1.19	The number of discarded outgoing packets.
ifOutErrors .1.3.6.1.2.1.2.2.1.20	The number of outgoing packets not transmitted because packet has error.
ifOutQLen .1.3.6.1.2.1.2.2.1.21	The length of outgoing packets.
ifSpecific .1.3.6.1.2.1.2.2.1.22	This object is deprecated.

#### **ifXTable**

This table is enhance version of ifTable.

<b>MIB Object and OID</b>	<b>Description</b>
ifName .1.3.6.1.2.1.31.1.1.1.1	The interface name.
ifInMulticastPkts .1.3.6.1.2.1.31.1.1.1.2	The number of received multicast packets.
ifInBroadcastPkts .1.3.6.1.2.1.31.1.1.1.3	The number of received broadcast packets.
ifOutMulticastPkts .1.3.6.1.2.1.31.1.1.1.4	The number of transmitted multicast packets.
fOutBroadcastPkts .1.3.6.1.2.1.31.1.1.1.5	The number of transmitted broadcast packets.
ifHCInOctets .1.3.6.1.2.1.31.1.1.1.6	The number of received bytes in 64 bits format.
ifHCInUcastPkts .1.3.6.1.2.1.31.1.1.1.7	The number of received unicast packets in 64 bits format.
ifHCInMulticastPkts .1.3.6.1.2.1.31.1.1.1.8	The number of received multicast packets in 64 bits format.
fHCInBroadcastPkts .1.3.6.1.2.1.31.1.1.1.9	The number of received broadcast packets in 64 bits format.
ifHCOctets .1.3.6.1.2.1.31.1.1.1.10	The number of transmitted bytes in 64 bits format.
ifHCOUcastPkts .1.3.6.1.2.1.31.1.1.1.11	The number of transmitted unicast packets in 64 bits format.
ifHCOMulticastPkts .1.3.6.1.2.1.31.1.1.1.12	The number of transmitted multicast packets in 64 bits format.
ifHCOBroadcastPkts .1.3.6.1.2.1.31.1.1.1.13	The number of transmitted broadcast packets in 64 bits format.
ifLinkUpDownTrapEnable .1.3.6.1.2.1.31.1.1.1.14	Indicates if linkUp/linkDown traps must be generated for this interface.
ifHighSpeed .1.3.6.1.2.1.31.1.1.1.15	The interface speed in Mbps.
ifPromiscuousMode .1.3.6.1.2.1.31.1.1.1.16	Indicates if it accepts all the packets on the media. Value must be 2.
ifConnectorPresent .1.3.6.1.2.1.31.1.1.1.17	This object has the value 'true(1)' if the interface sublayer has a physical connector and the value false(2)' otherwise.

***fcipEntityInstanceTable***

This table contains information related to FCIP entities.

<b>MIB Object and OID</b>	<b>Description</b>
fcipEntityId 1.3.6.1.2.1.224.1.1.4.1.1	The entity identifier.
fcipEntityName 1.3.6.1.2.1.224.1.1.4.1.2	The entity name.
fcipEntityAddressType 1.3.6.1.2.1.224.1.1.4.1.3	The address type and it can be ipv4, ipv6, etc.,
fcipEntityAddress 1.3.6.1.2.1.224.1.1.4.1.4	The address of the entity.
fcipEntityTcpConnPort 1.3.6.1.2.1.224.1.1.4.1.5	The connection port number.
fcipEntitySeqNumWrap 1.3.6.1.2.1.224.1.1.4.1.6	The sequence number.
fcipEntityPHBSupport 1.3.6.1.2.1.224.1.1.4.1.7	Not supported.
fcipEntityStatus 1.3.6.1.2.1.224.1.1.4.1.8	The entity status and it is always active.

***fcipLinkTable***

This table contains information about link of FCIP entities.

<b>MIB Object and OID</b>	<b>Description</b>
fcipLinkIndex 1.3.6.1.2.1.224.1.1.5.1.1	The ifIndex of ifTable.
fcipLinkIfIndex 1.3.6.1.2.1.224.1.1.5.1.2	The ifIndex value of the virtual interface corresponding to the FCIP Link running over TCP/IP.
fcipLinkCost 1.3.6.1.2.1.224.1.1.5.1.3	The link cost.
fcipLinkLocalFcipEntityMode 1.3.6.1.2.1.224.1.1.5.1.4	The entity mode and it is always eport.
fcipLinkLocalFcipEntityAddressType 1.3.6.1.2.1.224.1.1.5.1.5	The address type.
fcipLinkLocalFcipEntityAddress 1.3.6.1.2.1.224.1.1.5.1.6	The entity address.



MIB Object and OID	Description
fcipLinkRemFcipEntityId 1.3.6.1.2.1.224.1.1.5.1.7	The remote entity identifier.
fcipLinkRemFcipEntityAddressType 1.3.6.1.2.1.224.1.1.5.1.8	The remote entity address type.
fcipLinkRemFcipEntityAddress 1.3.6.1.2.1.224.1.1.5.1.9	The remote entity address.
fcipLinkStatus 1.3.6.1.2.1.224.1.1.5.1.10	The link status and it is always active.
fcipLinkCreateTime 1.3.6.1.2.1.224.1.1.5.1.11	Not supported.

### ***fcipTcpConnTable***

This table contains TCP connection information about the link.

MIB Object and OID	Description
fcipTcpConnLocalPort 1.3.6.1.2.1.224.1.1.6.1.1	The TCP connection local port.
fcipTcpConnRemPort 1.3.6.1.2.1.224.1.1.6.1.2	The TCP connection remote port.
fcipTcpConnRWSIZE 1.3.6.1.2.1.224.1.1.6.1.3	The windows size.
fcipTcpConnMSS 1.3.6.1.2.1.224.1.1.6.1.4	The segment size.

### **Modified MIBs**

The following changes have been made to the **SW.mib**:

- The “swBrcdBitObjVal” MIB object is newly added.

MIB Object and OID	Description
swBrcdBitObjVal 1.3.6.1.4.1.1588.2.1.1.1.1.37	The MIB object will have object value for each change mentioned in swBrcdGenericTrap. It will be empty for the events which do not have any values.

- The “swFCPortPrevType” MIB object is updated to include D\_Port option.

### **Updated Traps**

The following BD traps are updated to include a new variable “slotPort” to display port number in slot/port format:

- bdTrap
- bdClearTrap

#### **Deprecated/Obsoleted MIBs**

The following MIB objects/traps in **SW.mib** are deprecated:

- swTrackChangesInfo
- swTelnetShellAdmStatus
- swTrackChangesTrap

## Blade Support

Fabric OS v7.3 software is fully qualified and supports the blades for the DCX/DCX-4S noted in the following table:

DCX/DCX-4S Blade Support Matrix	
16-, 32-, 48- and 64-port 8Gbit port blades (FC8-16, FC8-32, FC8-48, FC8-64)	Supported with FOS v6.0 and above (FC8-64 requires FOS v6.4) with any mix and up to 8/4 of each. No restrictions around intermix.
FC10-6	Not supported on FOS v7.1 or later
Intelligent blade	Up to a total of 8/4 intelligent blades. See below for maximum supported limits of each blade.
Virtualization/Application Blade (FA4-18)	Not supported on FOS v7.0 or later
FCIP/FC Router blade (FR4-18i)	Not supported on FOS v7.1 or later
Encryption Blade (FS8-18)	Up to a maximum of 4 blades of this type.
Extension Blade (FX8-24)	Up to a max of 4 blades of this type.
FCoE/L2 CEE blade FCOE10-24	Up to a max of 4 blades of this type. <b>Not supported in the same chassis with other intelligent blades or the FC8-64 port blade.</b>
FC16-32, FC16-48, FC16-64, FC8-32E, FC8-48E	Not supported

**Table 1 Blade Support Matrix for DCX and DCX-4S with FOS v7.3**

Note: The iSCSI FC4-16IP blade is not qualified for the DCX/DCX-4S.

Fabric OS v7.3 software is fully qualified and supports the blades for the DCX 8510-8 and DCX 8510-4 noted in the table below.

DCX 8510-8/DCX 8510-4 Blade Support Matrix	
FC16-32, FC16-48 16G FC blades	FOS v7.0 or later.
FC16-64 blade <sup>2,3</sup>	FOS v7.3 or later.
FC8-64 64 port 8Gbit port blade	With any mix and up to 8/4 of each. No restrictions around intermix. <b>Note:</b> FC8-16, FC8-32, FC8-48 blades are <b>not</b> supported on DCX 8510 platforms.
FC8-32E, FC8-48E <sup>1</sup>	FOS v7.0.1 or later.
Intelligent blade	Up to a total of 8/4 intelligent blades. See below for maximum supported limits of each blade.
FCIP/FC Router blade (FR4-18i)	Not supported.
Virtualization/Application Blade (FA4-18)	Not Supported
Encryption Blade (FS8-18)	Up to a maximum of 4 blades of this type.
Extension Blade (FX8-24)	Up to a max of 4 blades of this type.
FCoE/L2 CEE blade FCOE10-24	<b>Supported at slot 1 position only on DCX 8510-8 with FOS v7.3.0. Supported in the same chassis with FC16-32 and FC8-32E blades only. Not supported with any other port blades or intelligent blades in the same chassis. Not supported in DCX 8510-4 chassis.</b>

**Table 2 Blade Support Matrix for DCX 8510-8 and DCX 8510-4 with FOS v7.3**

Note: The iSCSI FC4-16IP blade is not qualified for the DCX 8510-8/DCX 8510-4.

1. Note that 16G SFP+ is not supported in FC8-32E and FC8-48E blades
2. 8510 core blade QSFPs, part numbers 57-1000267-01 and 57-0000090-01, are not supported in FC16-64. The QSFPs supported in FC16-64, part number 57-1000294-01, are not supported on 8510 core blades either.
3. E-port connections on FC16-64 blade have the following restrictions:
  - E-port connections between two FC16-64 blades are not supported.
  - Connecting a QSFP port between a FC16-64 blade and an ICL QSFP port on a core blade is not supported.
  - E-port connections between a FC16-64 and other port blades (via break-out) are supported.

Power Supply Requirements for Blades in DCX/DCX-4S				
Blades	Type of Blade	DCX/DCX-4S @110 VAC (Redundant configurations)	DCX/DCX-4S @200-240 VAC (Redundant configurations)	Comments
FC10-6 <sup>1</sup> , FC8-16, FC8-32, FC 8-48, FC8-64	Port Blade	2 Power Supplies	2 Power Supplies	<ul style="list-style-type: none"> <li>Distribute the Power Supplies evenly to 2 different AC connections for redundancy.</li> </ul>
FR4-18i <sup>1</sup>	Intelligent Blade	Not Supported	2 Power Supplies	
FS8-18, FX8-24, FCOE10-24	Intelligent Blade	Not Supported	DCX: 2 or 4 Power Supplies  DCX-4S: 2 Power Supplies	<ul style="list-style-type: none"> <li>For DCX with three or more FS8-18 Blades, (2+2) 220VAC Power Supplies are required for redundancy.</li> <li>For DCX with one or two FS8-18 Blades, (2) 220VAC Power Supplies are required for redundancy.</li> <li>For DCX-4S, (2) 220VAC Power Supplies provide redundant configuration with any supported number of FS8-18 Blades.</li> <li>For both DCX and DCX-4S with FX8-24 blades, (1+1) 220VAC Power Supplies are required for redundancy.</li> </ul>

**Table 3 Power Supply Requirements for DCX and DCX-4S**

1. Note that FC10-6 and FR4-18i are not supported with FOS v7.1 or later

<b>Typical Power Supply Requirements Guidelines for Blades in DCX 8510-8</b> (For specific calculation of power draw with different blade combinations, please refer to Appendix A: Power Specifications in the 8510-8 Backbone Hardware Reference Manual)					
Configured Number of Ports	Blades	Type of Blade	DCX 8510-8 @110 VAC (Redundant configurations)	DCX 8510-8 @200-240 VAC (Redundant configurations)	Comments
Any combination of 8Gb or 16Gb ports with QSFP ICLs	FC8-64, FC16-32, FC16-64, FC8-32E	Port Blade	4 Power Supplies	2 Power Supplies	200-240VAC: 1+1 Power Supplies 110VAC: 2+2 <sup>1</sup> Power Supplies
256 16Gb ports + QSFP ICLs	FC16-32, FC16-48 (Maximum of fully populated FC16-32 blades), FC16-64	Port Blade	4 Power Supplies	2 Power Supplies	200-240VAC: 1+1 Power Supplies 110VAC: 2+2 <sup>1</sup> Power Supplies Max 8 FC16-32 port blades
256 8Gb ports + QSFP ICLs	FC8-32E, FC8-48E (Maximum of fully populated FC8-32E blades)	Port Blade	4 Power Supplies	2 Power Supplies	200-240VAC: 1+1 Power Supplies 110VAC: 2+2 <sup>1</sup> Power Supplies Max 8 FC8-32E port blades
192 16Gb Ports & max 2 intelligent blades (FX8-24 /FS8-18/combination) with QSFP ICLs	FC16-32, FC16-48, FC16-64, FX8-24, FS8-18	Port / Intelligent Blade	4 Power Supplies	2 Power Supplies	200-240VAC: 1+1 Power Supplies 110VAC: 2+2 <sup>1</sup> Power Supplies Max four FC16-48 port blades and max 2 Intelligent blades
192 8Gb Ports & max 2 intelligent blades (FX8-24 /FS8-18/combination) with QSFP ICLs	FC8-32E, FC8-48E, FX8-24, FS8-18	Port / Intelligent Blade	4 Power Supplies	2 Power Supplies	200-240VAC: 1+1 Power Supplies 110VAC: 2+2 <sup>1</sup> Power Supplies Max four FC8-48E port blades and max 2 Intelligent blades
336 16Gb ports + QSFP ICLs	FC16-48 (Maximum of seven FC16-48 blades, with one empty port blade slot)	Port Blade	4 Power Supplies	2 Power Supplies	200-240VAC: 1+1 Power Supplies 110VAC: 2+2 <sup>1</sup> Power Supplies Max 7 FC16-48 port blades

<b>Typical Power Supply Requirements Guidelines for Blades in DCX 8510-8</b> (For specific calculation of power draw with different blade combinations, please refer to Appendix A: Power Specifications in the 8510-8 Backbone Hardware Reference Manual)					
Configured Number of Ports	Blades	Type of Blade	DCX 8510-8 @110 VAC (Redundant configurations)	DCX 8510-8 @200-240 VAC (Redundant configurations)	Comments
336 8Gb ports + QSFP ICLs	FC8-48E (Maximum of seven FC8-48E blades, with one empty port blade slot)	Port Blade	4 Power Supplies	2 Power Supplies	200-240VAC: 1+1 Power Supplies 110VAC: 2+2 <sup>1</sup> Power Supplies Max 7 FC8-48E port blades
384 16Gb ports + QSFP ICLs	FC16-48	Port Blade	Not Supported	4 Power Supplies	200-240VAC: For DCX 8510-8, four (2+2) <sup>1</sup> 220V AC Power Supplies are required
384 16Gb ports + QSFP ICLs	FC16-64	Port Blade	4 Power Supplies	2 Power Supplies	200-240VAC: 1+1 Power Supplies 110VAC: 2+2 <sup>1</sup> Power Supplies
384 8Gb ports + QSFP ICLs	FC8-48E	Port Blade	4 Power Supplies	4 Power Supplies	200-240VAC: For DCX 8510-8, four (2+2) <sup>1</sup> 220V AC Power Supplies are required
Any combination of 8Gb or 16Gb ports and intelligent blades with QSFP ICLs	FC16-32, FC16-48, FC8-64, FC8-32E, FC8-48E, FS8-18, FX8-24	Intelligent Blade /Combination	Dependent on configuration. Requires power calculation for specific configuration	2 or 4 Power Supplies, depending on configuration	For DCX 8510-8, four (2+2) <sup>1</sup> 220V AC Power Supplies are required when any special purpose blade are installed
512 16Gb ports	FC16-64	Port Blade	4 Power Supplies	2 Power Supplies	200-240VAC: 1+1 Power Supplies 110VAC: 2+2 <sup>1</sup> Power Supplies
512 16Gb ports + QSFP ICLs	FC16-64	Port Blade	4 Power Supplies	2 Power Supplies	200-240VAC: 1+1 Power Supplies 110VAC: 2+2 <sup>1</sup> Power Supplies

**Table 4 Power Supply Requirements for DCX 8510-8**

Notes:

1. When 2+2 power supply combination is used, the users are advised to configure the Fabric Watch setting for switch marginal state to be two power supplies. Users can use the CLI `switchstatuspolicyset` to configure this value if the current value is set to zero. In FOS v7.0.x, the default setting for the marginal state due to missing

power supplies is incorrectly set to zero, which will prevent Fabric Watch from generating notifications when the switch enters the marginal state due to missing power supplies

<b>Typical Power Supply Requirements Guidelines for Blades in DCX 8510-4</b> <b>(For specific calculation of power draw with different blade combinations, please refer to Appendix A: Power Specifications</b> <b>in the 8510-4 Backbone Hardware Reference Manual)</b>					
Configured Number of Ports	Blades	Type of Blade	DCX 8510-4 @110 VAC (Redundant configurations)	DCX 8510-4 @200-240 VAC (Redundant configurations)	Comments
96 ports max with QSFP ICLs	FC16-32, FC8-32E	Port Blade	2 Power Supplies	2 Power Supplies	1+1 redundancy with 110 or 200-240 VAC power supplies
Any combination of 8Gb or 16 Gb ports and intelligent blades with QSFP ICLs	FC16-32, FC16-48, FC16-64, FC8-32E, FC8-48E, FC8-64, FS8-18, FX8-24	Intelligent Blade /Combination	Not Supported	2 Power Supplies	200-240VAC: 1+1 Power Supplies

**Table 5 Power Supply Requirements for DCX 8510-4**

## Scalability

All scalability limits are subject to change. Limits may be increased once further testing has been completed, even after the release of Fabric OS. For current scalability limits for Fabric OS, refer to the *Brocade Scalability Guidelines* document, available under the *Technology and Architecture Resources* section at <http://www.brocade.com/compatibility>

## Other Important Notes and Recommendations

### Adaptive Networking/Flow-Based QoS Prioritization

- Any 8G or 4G FC platform running FOS v6.2.2e or lower version of firmware cannot form an E-port with a 16G FC platform when Adaptive Networking QoS is enabled at both ends of the ISL. Users must disable QoS at either end of the ISL in order to successfully form an E-port under this condition.  
Users can disable QoS via portcfgQos –disable command. Please consult Fabric OS Command Reference manual for details related to portcfgQos command.
- When using QoS in a fabric with 4G ports or switches, FOS v6.2.2 or later must be installed on all 4G products in order to pass QoS info. E\_Ports from the DCX to other switches must come up AFTER 6.2.2 is running on those switches.
- When FOS is upgraded from v7.1.x to v7.2.0 or later:
  - If the Adaptive Networking license was NOT installed in v7.1.x, all ports will have QOS disabled following the firmware upgrade and links will come up in normal mode.



- If the Adaptive Networking license was installed in v7.1.x, there will be no change in port QOS mode following the upgrade.
  - If the remote port supports QOS and QOS is not explicitly disabled on the local or remote port, the link will come up in QOS mode.
  - Otherwise, the link will come up in normal mode.
- If FOS v7.2 or later is factory installed (or net installed), Adaptive Networking features are always available. This matches the behavior of the Brocade 6520 and all products shipping with prior versions of FOS and with the Adaptive Networking license factory installed.
  - Ports will come up in AE mode by default
  - If the remote port supports QOS and is not explicitly disabled, the link will come up in QOS mode. Otherwise, the link will come up in normal mode.

## Access Gateway

- Users who want to utilize Access Gateway's Device-based mapping feature in the ESX environments are encouraged to refer to the SAN TechNote GA-TN-276-00 for best implementation practices. Please follow these instructions to access this technote:
  - Log in to <http://my.brocade.com>
  - Go to Documentation > Tech Notes.
  - Look for the Tech Note on Access Gateway Device-Based Mapping in VMware ESX Server.

## D\_Port

- The 16Gb QSFP optics used in FC16-64 blade do not support electrical loopback and optical loopback tests. Support is limited to:
  - Link traffic tests across the 16Gb QSFPs
  - Roundtrip link latency measurements
  - Link distance measurements for links that are longer than 100 meter
- D\_Port support with HBA/Adapter from Qlogic and Emulex begins with FOS v7.3.0a. Please refer to Qlogic and Emulex documentation for specific adapter models and firmware levels required,

## Edge Hold Time

- Edge Hold Time (EHT) default settings for FOS v7.x have changed from those in some FOS v6.4.x releases. The following table shows the Default EHT value based on different FOS release levels originally installed at the factory:

Factory Installed Version of FOS	Default EHT Value
FOS v7.X	220 ms
FOS v6.4.3x	500 ms
FOS v6.4.2x	500 ms
FOS v6.4.1x	220 ms
FOS v6.4.0x	500 ms

Any version prior to FOS v6.4.0	500 ms
---------------------------------	--------

Gen 5 platforms and blades are capable of setting an EHT value on an individual port basis. On 8G platforms EHT is set on an ASIC-wide basis, meaning all ports on a common ASIC will have the same EHT setting. Extra care should be given when configuring EHT on 8G platforms or Gen 5 platforms with 8G blades to ensure E\_Ports are configured with an appropriate Hold Time setting.

When using Virtual Fabrics and creating a new Logical Switch when running FOS v7.1.0 or later, the default EHT setting for the new Logical Switch will be the FOS default value of 220ms. However, with FOS v7.1.0 and later, each Logical Switch can be configured with a unique EHT setting that is independent of other Logical Switches and the Default Switch. Any Gen 5 ports (Condor3 based) assigned to that Logical Switch will be configured with that Logical Switch's EHT setting. Any 8G ports (Condor2 based) will continue to share the EHT value configured for the Default Switch.

For more information on EHT behaviors and recommendations, refer to the Brocade SAN Fabric Resiliency Best Practices v2.0 document available on [www.brocade.com](http://www.brocade.com).

## Encryption Behavior for the Brocade Encryption Switch (BES) and FS8-18

- SafeNet's KeySecure hosting NetApp's LKM (SSKM) is supported for data encryption operations with SSKM operating in PVM mode. Please see SSKM documentation for operating in PVM mode for details. Operation in HVM mode is not supported
  - RASlog SPC-3005 with error 34 may be seen if the link key used by a BES/FS8-18 is re-established. Please refer to the LKM/SSKM Encryption Admin Guide for the workaround. Also, please ensure that two (2) SSKM's are present in the deployment for workaround to be performed.
- For crypto tape operations, please ensure to use Emulex FC HBA firmware/drivers 2.82A4/7.2.50.007 or higher. Use of lower level firmware/drivers may result in hosts not being able to access their tape LUNs through a crypto target container.
- Adding of 3PAR Session/Enclosure LUNs to CTCs is now supported. Session/Enclosure LUNs (LUN 0xFE) used by 3PAR InServ arrays must be added to CryptoTarget (CTC) containers with LUN state set to "cleartext", encryption policy set to "cleartext". BES/FS8-18 will not perform any explicit enforcement of this requirement.
- The Brocade Encryption switch and FS8-18 blade do not support QoS. When using encryption or Frame Redirection, participating flows should not be included in QoS Zones.
- The RSA DPM Appliance SW v3.2 is supported. The procedure for setting up the DPM Appliance with BES or a DCX/DCX-4S/DCX 8510 with FS8-18 blades is located in the Encryption Admin Guide.
- Support for registering a 2nd DPM Appliance on BES/FS8-18 is blocked. If the DPM Appliances are clustered, then the virtual IP address hosted by a 3rd party IP load balancer for the DPM Cluster must be registered on BES/FS8-18 in the primary slot for Key Vault IP.
- With Windows and Veritas Volume Manager/Veritas Dynamic Multipathing, when LUN sizes less than 400MB are presented to BES for encryption, a host panic may occur and this configuration is not supported in the FOS v6.3.1 or later release.
- Hot Code Load from FOS v7.2.x to FOS v7.3 is supported. Cryptographic operations and I/O will be disrupted but other layer 2 FC traffic will not be disrupted.
- When disk and tape CTCs are hosted on the same encryption engine, re-keying cannot be done while tape backup or restore operations are running. Re-keying operations must be scheduled at a time that does not conflict with normal tape I/O operations. The LUNs should not be configured with auto rekey option when single EE has disk and tape CTCs.

- Gatekeeper LUNs used by SYMAPI on the host for configuring SRDF/TF using in-band management must be added to their containers with LUN state as “cleartext”, encryption policy as “cleartext” and without “-newLUN” option.
- FOS7.2 and later supports KMIP key vault type for Thales e-Security Key Authority SW v4.0.0 KMIP servers. Please refer to the KMIP Encryption Admin Guide for more details.
  - Replication feature from Thales e-Security Key Authority KMIP server is not supported with BES/FS8-18.
- In FOS 7.1.0 or later the encryption FPGA has been upgraded to include parity protection of lookup memory (ROM) within the AES engine. This change enhances parity error detection capability of the FPGA.
- BES/FS8-18 will reject the SCSI commands WRITE SAME, ATS(Compare and Write/Vendor Specific opcode 0xF1) and EXTENDED COPY, which are related to VAAI (vStorage APIs for Array Integration) hardware acceleration in vSphere 4.1/5.x. This will result in non-VAAI methods of data transfer for the underlying arrays, and may affect the performance of VM related operations.
- VMware VMFS5 uses ATS commands with arrays that support ATS. BES/FS8-18 does not support this command set. Use of a workaround procedure is required in order to configure encryption in a VMFS 5 environment. Please refer to Brocade Tech Note “Deployment Options for VMware VMFS-5 with Brocade Encryption” for details.
- XIV storage arrays that have been upgraded to firmware 11.2x or later required to support encryption on thin provisioned LUNs will report all XIV data LUNs as TP=Yes.

## **FCIP (Brocade 7800 and FX8-24)**

- Any firmware activation will disrupt I/O traffic on FCIP links.
- Latency measurements supported on FCIP Tunnels:
  - 1GbE & 10GbE - 200ms round trip time and 1% loss.
- After inserting a 4G SFP in GE ports of an FX8-24 blade or 7800 switch, sometimes “sfpshow” output might display “Cannot read serial data!”. Removing and re-inserting the SFP should resolve this issue. It is recommended that users perform sfpshow immediately after inserting the SFP and ensure SFP is seated properly before connecting the cables.
- When running FOS v7.2.0 or later, if the new FCIP Circuit Group feature is configured on any FCIP Circuits, a downgrade operation to pre-FOS v7.2.0 will be blocked until the feature is removed from the FCIP configuration(s).

## **FCIP (Brocade 7840)**

- Brocade 7840 does not support FCIP connection to Brocade 7800 or FX8-24.
- FOS v7.3- does not support concurrent non-disruptive firmware download.
- FOS v7.3- does not support 10G speed on the 24 16G FC ports on Brocade 7840.
- FOS v7.3- does not support VEX port on Brocade 7840.
- FOS v7.3- does not support base switch on Brocade 7840.
- FOS v7.3- does not support credit recovery on BI ports on Brocade 7840.
- Running offline diagnostic tests results in FCIP tunnels down. Reboot the switch after offline diagnostic tests to recover the tunnels.
- Brocade 7840 supports Brocade 10 Gbps Tunable DWDM 80KM SFP+ optical transceiver. Following CLI command can be used to configure the transceiver usage in Brocade 7840.

```
portcfgge ge_num --set -channel <channel_num>
```

The channel number can have a value of 1 through 102. The detailed explanation of the values are provided in the product data sheet at the following link:

[http://www.brocade.com/downloads/documents/data\\_sheets/product\\_data\\_sheets/10gbe-tunable-dwdm-80km-sfp-ds.pdf](http://www.brocade.com/downloads/documents/data_sheets/product_data_sheets/10gbe-tunable-dwdm-80km-sfp-ds.pdf)

- FCIP non-disruptive firmware download can fail in configurations with large FCIP object counts. This can occur in FICON or FCP emulation enabled configurations. FCIP non-disruptive firmware download may fail if there are greater than 20,000 FCP or FICON device objects. This problem can be avoided by performing a disruptive firmware download. (This issue is also noted as defect 528010.)
- When Brocade Network Advisor (BNA) v12.3.2 is used to download firmware on Brocade 7840, BNA reports success of firmware download prematurely when 7840 has not reached High Availability state. Customers for 7840 using BNA to download firmware should wait for extra fifteen minutes after BNA reports success to resume a work load.

### **FCoE/DCB/CEE (FCOE10-24)**

- When upgrading a DCX/DCX-4S with one or more FCOE10-24 blades from FOS v6.x to FOS v7.0.0 or later, the user should carefully review Chapter 5 of the FOS v7.0.0 Converged Enhanced Ethernet Administrator's Guide.
- Ethernet L2 traffic with xSTP Hello timer set to less than or equal to 3 seconds may experience momentary traffic disruption during HA failover.
- Hot plugging a CP with firmware level less than FOS v6.3.0 into a DCX or DCX-4S with an active FCOE10-24 blade will result in the new standby CP not coming up.
- When operating in Converged Mode, tagged traffic on the native VLAN of the switch interface is processed normally. The host should be configured not to send VLAN tagged traffic on the switch's native VLAN.
- When operating in Converged Mode, tagged frames coming with a VLAN tag equal to the configured native VLAN are dropped.
- The Converged Network Adapter (CNA) may lose connectivity to the FCOE10-24 if the CNA interface is toggled repeatedly over time. This issue is related to the CNA and rebooting the CNA restores connectivity.
- The FCOE10-24 support only one CEE map on all interfaces connected to CNAs. Additionally, CEE map is not recommended for use with non-FCoE traffic. QoS commands are recommended for interfaces carrying non-FCoE traffic.
- Before upgrading to FOS v6.4.1\_fcoe/v6.4.1\_fcoe1/v7.0.0 or later, if the CEE map "default" value already exists, the same "default" value is preserved after upgrading to FOS v6.4.1\_fcoe/v6.4.1\_fcoe1/v7.0.0 or later. However, if the CEE map "default" is not configured before upgrading to FOS v6.4.1\_fcoe/v6.4.1\_fcoe1/v7.0.0 or later, then after upgrading to FOS v6.4.1\_fcoe/v6.4.1\_fcoe1/v7.0.0 or later, the following CEE map "default" will be created automatically:

```
cee-map default
priority-group-table 1 weight 40 pfc
priority-group-table 2 weight 60
priority-table 2 2 2 1 2 2 2 2
```

- When upgrading from FOS v6.3.x or v6.4.x to FOS v6.4.1\_fcoe/v6.4.1\_fcoe1/v7.0.0 or later, the CEE start up configuration dcf.conf file will be incompatible with the FCoE provisioning changes implemented in v6.4.1\_fcoe and later releases. Users can save the dcf.conf file as a backup and

apply it once the firmware upgrade is completed to get the DCX/DCX-4S to the same startup configuration as in the older release.

- It is recommended that Spanning Tree Protocol and its variants be disabled on CEE interfaces that are connected to an FCoE device.
- The Fabric Provided MAC Address (FPMA) and the Fibre Channel Identifier (FCID) assigned to a VN\_Port cannot be associated with any single front-end CEE port on which the FLOGI was received.
- LLDP neighbor information may be released before the timer expires when DCBX is enabled on a CEE interface. This occurs only when the CEE interface state changes from active to any other state. When the DCBX is not enabled, the neighbor information is not released until the timer expires, irrespective of the interface state.
- The FCoE login group name should be unique in a fabric-wide FCoE login management configuration. If there is a login group name conflict, the merge logic would rename the login group by including the last three bytes of the switch WWN in the login group name. As long as the OUI of the switch WWNs are identical this merge logic guarantees uniqueness in any modified login group name (switches with the same OUI will have unique last 3 bytes in WWN). However, if the participating switches have different OUIs but identical last three bytes in the switch WWNs, then the merge logic will fail to guarantee uniqueness of login group names. This will result in one of the login groups being dropped from the configuration. This means, no device can login to the login group that is dropped as a result of this name conflict. Users must create a new login group with a non-conflicting name to allow device logins.
- Ethernet switch services must be explicitly enabled using the command “*fosconfig -enable ethsw*” before powering on an FCOE10-24 blade. Failure to do so will cause the blade to be faulted (fault 9). Users can enable ethsw after upgrading firmware without FC traffic interruption.
- Upgrading firmware on a DCX or DCX-4S with one or more FCOE10-24 blades from FOS v6.4.1\_fcoe1 to FOS v7.0 or later will be non-disruptive to FCoE traffic through FCOE10-24 blades and FC traffic.
- Upgrading firmware on a DCX or DCX-4S with one or more FCOE10-24 blades from FOS v6.3.x, v6.4.x, and v6.4.1\_fcoe to FOS v7.0 or later will be disruptive to any traffic through the FCOE10-24 blades.
- When rebooting a DCX or DCX-4S with an FCOE10-24 blade, Qlogic CNA and LSan zoning, the switch will become very unresponsive for a period of time. This is due to the CNA sending excessive MS queries to the switch.
- The FCOE10-24 can handle 169 small FCoE frames in bursts. If you are using the FCOE10-24, and you delete a large number of v-ports with HCM, some of the v-ports may not appear to be deleted. To correct this, disable and re-enable FCoE with the following CLI commands:

```
switch:admin>fcoe -disable slot/port
```

```
switch:admin>fcoe -enable slot/port
```

- When a FCOE10-24 blade is powered off during configuration replay, the interface specific configuration won't get applied. Later when FCOE10-24 blade is powered on, all physical interfaces will come up with default configurations. User can execute “copy startup-config running-config” command to apply the new configuration after powering on the FCOE10-24 blade.
- When IGMP Snooping is disabled on a VLAN, all configured IGMP groups are removed from that VLAN. User has to reconfigure the IGMP groups after enabling the IGMP snooping on that VLAN.
- FOS v7.3 adds the support of FCOE10-24 blade in DCX 8510-8 chassis with following limitations:
  - Only one FCOE10-24 blade is supported at the fixed slot 1 position. Inserting the blade into other slot positions, however, will not fault the blade.
  - An FCOE10-24 blade can co-exist with FC16-32 and FC8-32E blades only in a DCX 8510-8 chassis.

- Only supports FCoE direct attach.
- Layer2 Ethernet traffic is not supported.
- If an FCoE10-24 blade is inserted into a DCX 8510-8 chassis, it is required to reboot the chassis or slot poweroff/poweron core blades. A chassis reboot or slot poweroff/poweron core blades must also be performed if the FCoE10-24 blade is removed and replaced with another blade type.

## FCR and Integrated Routing

- With routing and dual backbone fabrics, the backbone fabric ID must be changed to keep the IDs unique.
- VEX edge to VEX edge device sharing will not be supported.
- The man page and help display of `fcrlsanmatrix --display` and `fcrlsan --show` command syntax should be corrected as below:

```
fcrlsanmatrix --display -lsan | -fcr | -all
fcrlsan --show -enforce | -speed | -all
```

•

## Forward Error Correction (FEC)

- Though FEC capability is generally supported on Condor3 (16G capable FC) ports when operating at either 10G or 16G speed, it is not supported with all DWDM links. Hence FEC may need to be disabled on Condor3 ports when using DWDM links with some vendors by using `portCfgFec` command. Failure to disable FEC on these DWDM links may result in link failure during port bring up. Refer to the Brocade Fabric OS 7.x Compatibility Matrix for supported DWDM equipment and restrictions on FEC use.
- To connect between a switch and an HBA at 16 Gbps, both sides must be in the same mode (fixed speed, and FEC on or off) for them to communicate at that rate. If only one port has FEC enabled, neither port will be able to see the other. If the ports are in dynamic mode, then they may connect, but not at 16 Gbps.

## FICON

- For FICON qualified releases, please refer to the *Appendix: Additional Considerations for FICON Environments* section for details and notes on deployment in FICON environments. (This appendix is only included for releases that have completed FICON qualification).

## FL\_Port (Loop) Support

- FL\_Port is not supported on FC16-32, FC16-48, FC16-64, FC8-32E, FC8-48E, Brocade 6510, Brocade 6505, Brocade 6520, or Brocade 7840.
- The FC8-48 and FC8-64 blade support attachment of loop devices.
  - Virtual Fabrics must be enabled on the chassis and loop devices may only be attached to ports on a 48-port or 64-port blade assigned to a non-Default Logical Switch operating with the default 10-bit addressing mode (they may not be in the default Logical Switch).
- A maximum of 144 ports may be used for connectivity to loop devices in a single Logical Switch within a chassis in 10-bit dynamic area mode on DCX-4S.
- A maximum of 112 ports may be used for connectivity to loop devices in a single Logical Switch within a chassis in 10-bit dynamic area mode on DCX.
- Loop devices continue to be supported when attached to ports on the FC8-16, FC8-32 with no new restrictions.

## Flow Vision

- Users must not specify well known FC addresses, domain controller addresses or CUP Port ID (in FMS mode) for either the source or the destination device field while defining flows.
- Flow Vision does not support port swap. Users must not create flows on ports that are already swapped and users must not swap the ports on which the flows are currently defined.
- After a HA reboot, a flow generator flow can be created if the source or the destination port is F-Port. But traffic will not be initiated. Toggling the port will enforce the restriction again to simulated ports.
- Flow Monitor does not support flows with defined LUN parameters on ingress ports on 8G platforms.

## ICLs on DCX/DCX-4S

- If a DCX with an 8-link ICL license is connected to a DCX with a 16-link license, the DCX with the 16-link license will report enc\_out errors. The errors are harmless, but will continue to increment. These errors will not be reported if a DCX with a 16-link license is connected to a DCX-4S with only 8-link ICL ports.
- If ICL ports are disabled on only one side of an ICL link, the enabled side may see enc\_out errors.

## Native Connectivity (M-EOS interoperability)

- A switch running FOS v7.0 or later cannot form E-port connectivity with any M-EOS platform.
- Platform running FOS v7.1 or later does not support EX port configuration in Interopmode 2 or Interopmode 3.
- Device sharing between a switch running FOS v7.1 or later and McDATA fabrics is allowed via Integrated Routing platforms using FOS v7.0.x (or earlier) firmware.

## Port Initialization

Users may observe that a port is in “Port Throttled” state when an F\_Port is being initialized. This is mostly an informational message that is shown in switchshow output indicating systematic initialization of F\_Ports.

However, a port may remain in “Port Throttled” state for an extended period of time and may never come online if it fails to negotiate speed successfully with the neighboring port. Users are advised to check the speed setting of the neighboring switch port to determine the cause of the speed negotiation failure.

Example Output:

```
74      9      10      36ed40      id      N8      In_Sync      FC      Disabled (Port
Throttled)
```

## Port Mirroring

- Port Mirroring is not supported on the Brocade 7800.

## Virtual Fabrics

- When creating Logical Fabrics that include switches that are not Virtual Fabrics capable, it is possible to have two Logical Switches with different FIDs in the same fabric connected via a VF incapable switch. Extra caution should be used to verify the FIDs match for all switches in the same Logical Fabric.
- A switch with Virtual Fabrics enabled may not participate in a fabric that is using Password Database distribution or Administrative Domains. The Virtual Fabrics feature must be disabled prior to deploying in a fabric using these features.

- ISL R\_RDY mode is not supported in a base switch with FOS version 7.0 or higher.

## WebTools

- WebTools since FOS v7.1.0 has a “SupportSave” interface. It only collects, however, information specifics to WebTools. It does not contain the same information as collected by supportSave initiated through CLI or Brocade Network Advisor.
- When launching WebTools on a computer without Internet access, it could take up to 5 minutes to complete because the certificate revocation check performed for the WebTools application takes time to timeout. Users can turn off the certification revocation check on the Java control panel as a workaround.
- FOS v7.3.2a is qualified and supported with Oracle Java version 7 update 80 and Java version 8 update 66. Oracle enforces the latest JRE update to be used to launch WebTools. After JRE expiration date users will see the message “Your Java version is out of date” when launching WebTools. Users can either ignore the message by selecting the later option to proceed with launching WebTools, or install the latest JRE release and then launch WebTools.
- Due to Java signing certificate expiration, launching WebTools from Network Advisor 12.3.2 remote client will not work with JRE 8 starting from 2/13/2015. An attempt to launch the WebTools will be blocked and “Failed to validate certificate. The application will not be executed” message will be shown. Network Advisor 12.3.4 resolves this issue. To work around this issue in Network Advisor 12.3.2, please uninstall JRE 8, install JRE 1.7U80 and set the security level to Medium.

## Zoning

- There are limitations to zoning operations that can be performed from a FOS v6.x switch that is in the same fabric as a FOS v7.0 or later switch if the FOS v6.x switch is not running the recommended firmware version. Please see Fabric OS Interoperability section for details.

## Read Diagnostics Parameters

- FOS v7.3 only supports the Read Diagnostics Parameters (RDP) feature between Brocade switches both running FOS v7.3. RDP is not supported with any other vendor devices nor supported with switches running other FOS versions.

## Link Cable Beaconsing

- The Link Cable Beaconsing (LCB) feature on FOS v7.3 is only supported on ISLs between two Brocade switches both running FOS v7.3.0 – FOS v7.3.1a. Support with third party vendor devices is only available with FOS v7.3.1b or above with fix for defect 540720.

## 16G 2km ICL QSFP

- For existing DCX8510 switches with 16G 2km ICL QSFP installed to fix defect 539584, in addition to upgrade to FOS v7.3.1b, it is required to port decommission or disable the affected ICLs, pull out and insert the 2km QSFP, followed by persistently disable then persistently enable the ICL ports.
- The maximum number of ICL ports with the 2km ICL QSFP can be supported in an 8510 backbone switch with the two kilometer distance is 10, which requires 16 credits configured per Virtual Channel.
- Before the ICL ports with the 2km ICL QSFP come online, switchShow CLI command may display the port states as in-sync or shifting in and out of port fault.
- The sfpShow CLI command displays the 16G 2km ICL QSFP incorrectly as “Length Cu: 3 (units m)” instead of the correct value 0.
- Firmware downgrade from FOS v7.3.1 to a prior version is blocked if ICL ports with 2km ICL QSFP optics are present in the switch.



## Brocade Analytics Monitoring Platform

- vTap is only supported on Brocade Gen5 SAN products including: 6510, 6505, 6520, , DCX 8510-8, DCX 8510-4, 6545, 6546, 6547, 6548, M6505
- vTap flows do not need to be deactivated when monitored switches are upgraded from FOS v7.4.0b to FOS v7.4.1.
- When a D\_Port mode configuration mismatch between a fabric source switch and Analytics Monitoring Platform leads to a segmented analytic switch link, the source switch will display the segmented AE\_Port as a segmented E\_Port. This is tracked as defect 563489.
- vTap and auto-discovered AF\_Port do not support high availability. In the event that a AF\_port is re-discovered by a fabric switch after a domain change on the attached Analytics Mointoring Platform and followed by an hafailover or hareboot of the fabric switch, the remote AF\_port information would be stale and vTap flows cannot be activated. In this case, use one of the following workarounds:
  - Manually configure the AF\_Port after hafailover or hareboot
  - Disable and then enable the AF\_Port on the Analytics Monitoring Platform
  - Deactivate vTap flow before firmware download, hafailover, or hareboot and activate vTap flow again.
- vTap and CS\_CTL are mutually exclusive on a fabric switch. If CS\_CTL is enabled on one port, the entire switch cannot enable vTap. An F\_Port trunk supporting CS\_CTL must have all ports in the trunk group enabling CS\_CTL. Similary, in order to to enable vTap, all ports in an F\_Port trunk must have CS\_CTL disabled. In addition, the master port of a trunk should remain the same between CS\_CTL enable and disable. If this sequence is not followed, vTap may remain active even after CS\_CTL is enabled on an F\_Port, or the error message “Disable QoS zones error” may be observed when enabling vTap. A suggested method is to use the following sequence:
  - When enabling CS\_CTL mode, enable on all slave ports, followed by enabling on the master port, noted as port M.
  - When disabling CS\_CTL mode, disable all active ports in the trunk, except the master port M. Disable CS\_CTL mode on port M. Enable all ports in the trunk followed by disabling CS\_CTL mode on the remaining ports.
- When CS\_CTL is enabled on a port without any connection, after reboot and disabling CS\_CTL, vTap cannot be enabled. The workaround is to enable the port as a SIM port after disabling CS\_CTL, then toggle the port and remove the SIM port configuration.
- vTap and High QoS zone configuration is mutually exclusive on a fabric switch. vTap and Low QoS zone configuration co-existence on a fabric switch is supported.
- vTap and in-flight encryption or compression compatibility is supported only on the following platforms: Brocade DCX8510-8/DCX8510-4 and 6520. On these supported platforms, the ports with vTap enabled and ports with in-flight encryption or compression enabled must belong to different ASICs. Please refer to the hardware installation guides of these platforms for port to ASIC mapping boundary.

## Miscellaneous

- Users must also keep the RADIUS accounting port (Authentication Port+1) open in the firewall to ensure proper working of the RADIUS authentication.
- Using a Windows anonymous FTP server for supportsave collection:

When using anonymous ftp, to avoid long delays or failure of simultaneous supportsave collections when AP blades are present in a director chassis, the number of unlimited anonymous users for a Windows FTP server should be configured as follows:

$$\text{Number of anonymous FTP connections} = (\text{Number of director chassis}) + (\text{Number of installed Application Blades} \times 3)$$
- RASlog message AN-1010 may be seen occasionally indicating “Severe latency bottleneck detected”. Even though it is a “Warning” message, it is likely to be a false alarm and can be ignored.

- It is important to note that the outputs of slotshow -p and chassisShow commands also display the maximum allowed power consumption per slot. These are absolute maximum values and should not be confused with the real-time power consumption on 16G blades. The chassisshow command has a "Power Usage (Watts):" field that shows the actual power consumed in real-time on 16G blades.
- Class 3 frames that have been trapped to CPU will be discarded in the following scenarios on DCX/DCX-4S/DCX 8510 during the following conditions:
  - HA failover on DCX/DCX-4S/DCX 8510 platforms while running FOS v7.0 or later firmware
  - Firmware upgrade from v7.0 to a later release on Brocade 300, 5100, VA-40FC, 5300, 6510
  - Firmware upgrade from v7.0.1 to a later release on Brocade 6505
  - Firmware upgrade from v7.1.0 to a later release on Brocade 6520
- The QSFP information in the sfpshow output will indicate the ID field as all zeros. This is as designed.
 

```

ras080:FID128:root> sfpshow 5/32
QSFP No: 8 Channel No:0
Identifier: 13 QSFP+
Connector: 12 MPO Parallel Optic
Transceiver: 0000000000000000 16_Gbps id

```
- It is recommended that for directors with more than 300 E\_Ports, the switch be disabled prior to executing the "switchCfgTrunk" command (used to disable or enable trunking on the switch).
- During non-disruptive firmware upgrades, E\_Ports in R-RDY mode may cause some frame drops on the E-port links.
- The Brocade Network Advisor seed switch should always have the highest FOS version used in the fabric.
- For login authentication through RADIUS, Brocade switch should be able to reach RADIUS servers through TCP authentication port (default 1812) and accounting port (default 1813). Both of these ports must be kept open in any firewall settings.
- When a firmware upgrade on a Brocade 6510 switch initiated through Brocade Network Advisor results with "failed to enforce new iptable rules" error message, the switch could be inaccessible via SSH and/or Telnet. Activating (from console) a new policy with rules of default active policy will restore access to the switch.
- Firmware downgrade from FOS v7.3.0 with one or more ports enabled with the Flow Generator feature as a SIM port will be blocked. The SIM ports configuration must first be disabled.
- Firmware upgrade to FOS v7.3.0 with one or more ports enabled with the Flow Generator feature as a SIM port will be blocked. The SIM ports configuration must first be disabled.
- FOS v7.3.0 includes a fix for defect 492340 where users may see frame drops on the back-end edge and core ports with FS8-18 and FX8-24 blades in DCX 8510 chassis. This fix will only take effect after the affected blades are powered off and on. After the fix takes effect, a new credit allocation model leads to fewer credits available for long distance ports. If there are long distance port configurations that have used up all the credits prior to applying this fix, some long distance ports may experience degraded performance.
- Firmware downgrade from FOS v7.3.0 will be blocked when any logical switch is configured with in-flight encryption with FCAP protocol or SHA-256 hashing algorithm is used with FCAP or

DH-CHAP protocol. These configurations must be removed from all logical switches for downgrade.

- The Location ID parameter under the *configure* CLI affects routing calculations, and should remain set to the default value of 0 for normal use. Do not change the value unless explicitly instructed to do so by a Brocade Support engineer.
- Fabric OS Command Reference contains an error for the command *creditRecovMode*. The *creditRecovMode -fe\_crdloss* configures time-out based credit loss detection of Condor-2 front-end ISL links. However, this feature is NOT enabled by default.

## Defects

### Closed with Code Change in Fabric OS v7.3.2a

This section lists the defects with Critical, High and Medium Technical Severity closed with a code change as of June 13, 2016 in Fabric OS v7.3.2a.

<b>Defect ID:</b> DEFECT000506068	
<b>Technical Severity:</b> Low	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.1.2	<b>Technology:</b> Configuration Fundamentals
<b>Symptom:</b> CLI chassiscfgperrthreshold parameter settings are not saved to configuration, for parameters such as: system.perrFaultFlg and system.perrThreshold. Though the setting is in effect and persists through cold boot, but CLI, such as configshow or configdownlaod, show the value as 0.	
<b>Condition:</b> This issue is seen when enabling parity threshold using CLI chassiscfgperrthreshold.	

<b>Defect ID:</b> DEFECT000510618	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> RAS - Reliability, Availability, and Serviceability
<b>Symptom:</b> When supportsave is invoked from BNA the following raslog is seen on the switch.  [SS-1001], 525, SLOT 7   CHASSIS, WARNING, DCX_155, supportSave's upload operation to host IP address 10.38.162.10 aborted.  This indicates that a specific support module file transfer was not complete and failed.	
<b>Condition:</b> This is encountered only when there is a network issue while transferring support files from the switch to the remote host. SupportSave will continue to transfer the remaining support files to the remote host.	
<b>Workaround:</b> Verify all parameters / arguments provided to supportsave. This may also be due to an intermittent network issue. Rerun Supportsave to collect the data that was not transferred.	
<b>Recovery:</b> Verify all arguments passed to supportsave, check network connectivity to the remote host and rerun supportsave.	

<b>Defect ID:</b> DEFECT000533101	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> MAPS - Monitoring and Alerting Policy Suite
<b>Symptom:</b> MAPS does not give the SFP_IN notification when an sfp is added to switch.	
<b>Condition:</b> All platforms with MAPS enabled will see this problem.	

<b>Defect ID:</b> DEFECT000542065	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> Management GUI
<b>Symptom:</b> BNA displays incorrect serial number in FOS 7.3.0.	
<b>Condition:</b> All platforms running FOS 7.3.0 exhibit this behavior where switch properties show "Chassis Factory Serial Num:" instead of "WWN Unit: 1 Factory Serial Num:". FOS v7.4 and later versions are not impacted.	

<b>Defect ID:</b> DEFECT000547319	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Software Installation & Upgrade
<b>Symptom:</b> No user warning message is shown to the BNA User while attempting firmware downgrade to v7.3.0 where the MAPS rule with 'quiet time' is no longer monitored.	
<b>Condition:</b> This is encountered when User defined MAPS rule with quiet time is present in the switch running v7.4. and firmware downgrade to v7.3 is initiated from BNA.	

<b>Defect ID:</b> DEFECT000549964	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> CLI - Command Line Interface
<b>Symptom:</b> 'lsanzoneshow -s' reports device state as "Invalid state type".	
<b>Condition:</b> Seen when CLI command 'lsanzoneshow -s' is executed. This is only a display problem. Device state itself is correct.	

<b>Defect ID:</b> DEFECT000561045	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Fabric Watch
<b>Symptom:</b> The FW-1430 messages not only list sensors which are out of range but also the sensors which are absent.	
<b>Condition:</b> This behavior will be observed on all the platforms when the number of temperature sensors that are out of range exceeds the configured threshold.	

<b>Defect ID:</b> DEFECT000561871	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Fibre Channel Services
<b>Symptom:</b> If the portEportCredits and portFportBuffers are set on ports using these respective CLI commands, then performing a configdownload that does not include these 'keys' results in the ports being set back to the default setting.	
<b>Condition:</b> This occurs upon configdownload of a configuration file with portEportCredits and portFportBuffers keys absent.	
<b>Workaround:</b> Do not remove port eportcredits and fportbuffers configuration from the configdownload configuration file.	
<b>Recovery:</b> reconfigure the impacted ports by invoking portEportCredits and portFportBuffers CLI commands.	

## Closed with Code Change in Fabric OS v7.3.2a

<b>Defect ID:</b> DEFECT000563629	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Extension
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> FCIP - Fibre Channel over IP
<b>Symptom:</b> One or more IPSec enabled FCIP circuits may continuously bounce or go down and not recover. The affected DP will report Authentication Tag Mismatch errors continually.	
<b>Condition:</b> This may be encountered when IPSec is enabled on an FCIP tunnel between a pair of FX8-24 blades.	
<b>Recovery:</b> Reboot the affected FX8-24 blade.	

<b>Defect ID:</b> DEFECT000564187	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS6.4.2	<b>Technology:</b> RAS - Reliability, Availability, and Serviceability
<b>Symptom:</b> User can still configure FA-TRAP/ISCSI-TRAP on upgraded version, though FA-MIB/ISCSI-MIB was set to 'NO' in the previous version with snmpconfig --set mibcapability.	
<b>Condition:</b> This may occur if system underwent an upgrade from FOS v6.3.x to FOS v6.4.x with FA-MIB/ISCSI-MIB set to 'NO'.	

<b>Defect ID:</b> DEFECT000564450	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Management GUI
<b>Symptom:</b> After using "seccertutil import -config cacert" to import an SSL CA cert in .cer (binary) format, HTTPD fails to start and hareboot fails with a message "system is not ready yet or other LS/HA config is in progress, rc = -1".	
<b>Condition:</b> This may be encountered when using Windows Active Directory (AD) Server Certificate Authority (CA) to sign the CSRs and import the Windows AD Sever CA cert into the switch.	
<b>Workaround:</b> CA certificate is allowed only with the base64 encoded certificate along with .pem extension.	

<b>Defect ID:</b> DEFECT000564909	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> CLI - Command Line Interface
<b>Symptom:</b> Switches upgraded to FOSv7.x firmware from FOSv6.4.x with long distance ISLs configured will see "Desired Buffers = 0" in portshow output instead of the configured distance.	
<b>Condition:</b> This issue is seen in the output of the CLI command portshow, on all platforms upgraded from FOSv6.4.x with Long distance ISLs configured. However, the ISL itself is correct and functional.	
<b>Workaround:</b> Use portbuffershow CLI to view the correct distance/buffer as configured.	

<b>Defect ID:</b> DEFECT000567237	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> MAPS - Monitoring and Alerting Policy Suite
<b>Symptom:</b> After converting from fabric watch to Maps, temperature is missing in the rule list of converted maps policies.	
<b>Condition:</b> This is applicable to all the FOSv7.3 supported platforms during fabric watch to maps conversion.	

<b>Defect ID:</b> DEFECT000573714	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Fibre Channel Services
<b>Symptom:</b> Response to Management Server queries for Get Port List may be incomplete.	
<b>Condition:</b> This maybe encountered while trying to get the port list by using the switch wwn	

<b>Defect ID:</b> DEFECT000574862	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> RAS - Reliability, Availability, and Serviceability
<b>Symptom:</b> Raslog message severity is not synced between active and standby.	
<b>Condition:</b> This issue is seen when user changes the severity of raslog message using rasadmin command.	

<b>Defect ID:</b> DEFECT000575899	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> SNMP - Simple Network Management Protocol
<b>Symptom:</b> SNMP requests from BNA are sent to the chassis ip address but the switch responds back with the active CP IP. This may lead to BNA discovery issues.	
<b>Condition:</b> This issue will be seen on director class products only.	

<b>Defect ID:</b> DEFECT000577166	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.4.1	<b>Technology:</b> Port Bring-up
<b>Symptom:</b> F_Ports went into an In_sync state or route error was triggered on Eport trunk causing frame drop during a firmware upgrade.	
<b>Condition:</b> This may be seen if media validation check failed on ports during HA. SFP media validation failure may be triggered by the insertion of an SFP while the port was disabled and the switch had been upgraded to FOS v7.4.1, 7.4.1a or 7.4.1b from FOS v7.0.x or earlier through non-disruptive firmware upgrade path. Also effects FOS v7.3.1c, v7.3.1d, v7.2.1f and v7.2.1g.	
<b>Workaround:</b> Run sfpshow -f before upgrade from FOS v7.0.x releases up to FOS v7.4.1,7.4.1a and 7.4.1b or directly upgrade to FOS v7.4.1c with the fix. Also effects FOS v7.3.1c, v7.3.1d, v7.2.1f and v7.2.1g.	
<b>Recovery:</b> For F-port, bounce the port to recover. For trunk ports, disable ports in the trunk one at a time and then enable all ports.	

<b>Defect ID:</b> DEFECT000577234	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Management GUI
<b>Symptom:</b> User cannot login via web tool	
<b>Condition:</b> This issue is encountered when FID is swapped between default and other logical switch and login to default switch via webtool using user whose home LF is 128.	

<b>Defect ID:</b> DEFECT000578895	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS6.3.2	<b>Technology:</b> NTP - Network Time Protocol
<b>Symptom:</b> NTP server details may not be propagated when an edge switch is attached	
<b>Condition:</b> This may be encountered while doing portdisable and portenable frequently.	

<b>Defect ID:</b> DEFECT000583695	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.2	<b>Technology:</b> D-Port - Diagnostic Port
<b>Symptom:</b> If a blade or switch is disabled while the D-Port test is running, the switch/blade might move to disabled state permanently which requires a reboot of the blade/switch to recover.	
<b>Condition:</b> This may be encountered on all platforms, if a blade or switch is disabled while D-Port test is in progress.	
<b>Workaround:</b> Avoid disabling blade/switch when D-Port test is running.	
<b>Recovery:</b> Reboot the blade/switch.	

<b>Defect ID:</b> DEFECT000587033	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS8.0.1	<b>Technology:</b> Configuration Fundamentals
<b>Symptom:</b> A switch panic may be seen when spinfab is disrupted while in progress.	
<b>Condition:</b> The panic is seen only when all ports or the switch are manually disabled while D-Port or spinfab (online tests) are running. Note that such manual disabling of ports/switch is not recommended while these tests are in progress.	

<b>Defect ID:</b> DEFECT000588485	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> Port Bring-up
<b>Symptom:</b> Switch in AG mode reboots.	
<b>Condition:</b> This may occur when host is rebooted and switch did not discard the ABTS frame for the FLOGI while N-port is undefined.	

<b>Defect ID:</b> DEFECT000589472	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Security
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Security Policies
<b>Symptom:</b> CLI ipfilter disallows configuring a port value greater than 1024.	
<b>Condition:</b> This occurs when creating an ipfilter policy rule with port value greater than 1024. This is not permitted and results in an error message: Invalid port number(range) for IP filter policy rule.	



<b>Defect ID:</b> DEFECT000590383	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Security
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Fabric Authentication
<b>Symptom:</b> Certain devices are denied access to login to the switch when they have a DCC policy configured with proper WWNs.	
<b>Condition:</b> This may occur when either of the WWN words have the most significant bit set. For example WWNs like c0:xx:xx:xx:xx:xx:xx:xx or xx:xx:xx:xx:c0:xx:xx:xx might see this problem when DCC is configured.	

<b>Defect ID:</b> DEFECT000590415	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> Access Gateway
<b>Symptom:</b> Discrepancy is seen between the outputs of CLI commands "ag --show" and "ag --mapshow" on AG switch.	
<b>Condition:</b> This may occur on AG switches in no policy mode. When the F- port comes online, the mapped N- port is not updated as the current N-port for the F-ports.	

<b>Defect ID:</b> DEFECT000590689	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Security
<b>Reported In Release:</b> FOS7.3.2	<b>Technology:</b> Security Policies
<b>Symptom:</b> When "seccertutil gencsr" is executed to generate CSR file, unneeded integer number is displayed between "Generating CSR, file name is:" and "Done." messages.	
<b>Condition:</b> This issue is seen on all platforms running FOSv7.3.2 but there is no functional impact.	

<b>Defect ID:</b> DEFECT000590745	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS8.0.1	<b>Technology:</b> Flow Vision
<b>Symptom:</b> Flow Vision daemon (npd) may crash on a switch during firmwaredownload.	
<b>Condition:</b> User may encounter this behavior only on an Analytics Monitoring Platform enabled fabric during a switch disable/enable or reboot or hafailover operations.	
<b>Recovery:</b> Deactivate sys_analytics_vtap flow and restart npd daemon.	

<b>Defect ID:</b> DEFECT000591205	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.2	<b>Technology:</b> RAS - Reliability, Availability, and Serviceability
<b>Symptom:</b> RASLOG SS-1000 is logged to indicate success even when Supportsave operation fails.	
<b>Condition:</b> This happens in all the platforms running FOSv7.3.2 when Supportsave operation fails.	

<b>Defect ID:</b> DEFECT000591718	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.2	<b>Technology:</b> SNMP - Simple Network Management Protocol
<b>Symptom:</b> auditcfg config key is not getting updated properly if the VF is enabled and switch has Logical Switches created.	
<b>Condition:</b> This will happen in system with logical switches setup.	
<b>Recovery:</b> Use hareboot/hafailover to create the keys properly.	

<b>Defect ID:</b> DEFECT000591754	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Configuration Fundamentals
<b>Symptom:</b> Attempts to change IP address on embedded switch fails intermittently.	
<b>Condition:</b> This may be seen with Brocade M5424 switch, when IP address change is performed through CMC management module.	
<b>Workaround:</b> Log into serial console and use "ipaddrset" to change IP address.	

<b>Defect ID:</b> DEFECT000591977	
<b>Technical Severity:</b> Low	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.2	<b>Technology:</b> APM - Advanced Performance Monitoring
<b>Symptom:</b> Error message "RBAC permission denied" is observed while executing fmmonitor --clear command.	
<b>Condition:</b> This issue is seen on clearing the counters corresponding to frame monitor using the command "fmmonitor --clear".	

<b>Defect ID:</b> DEFECT000592041	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.2	<b>Technology:</b> Configuration Fundamentals
<b>Symptom:</b> Supportffdc configuration is not persistent across firmwaredownload.	
<b>Condition:</b> This behavior is seen in all platforms with FOS Versions v7.3.2 and prior	

<b>Defect ID:</b> DEFECT000592080	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.2	<b>Technology:</b> Flow Vision
<b>Symptom:</b> User is not able to modify the VTAP port to wildcard when the port id mode is set to slot port.	
<b>Condition:</b> This is encountered when AMP is used for monitoring the fabric	
<b>Workaround:</b> Update the mode to domain, index and modify the ingress port.	
<b>Recovery:</b> Update the mode to domain, index and modify the ingress port.	

<b>Defect ID:</b> DEFECT000593202	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.2	<b>Technology:</b> Fabric Watch
<b>Symptom:</b> Continuous FW-1430 and FW-1447 raslogs are recorded.	
<b>Condition:</b> This issue is seen when temperature sensor(s) exceeds the active temperature threshold value.	

## Closed with Code Change in Fabric OS v7.3.2a

<b>Defect ID:</b> DEFECT000593653	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.2.0	<b>Technology:</b> CLI - Command Line Interface
<b>Symptom:</b> The portcfgportcredits CLI command does not appear to set the credits specified in the command input.	
<b>Condition:</b> This issue may be observed with various platforms running FOS7.2.1f, 7.3.1c, 7.4.1 or later releases.	
<b>Recovery:</b> Bounce the affected port after running portcfgportcredits.	

<b>Defect ID:</b> DEFECT000593781	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> MAPS - Monitoring and Alerting Policy Suite
<b>Symptom:</b> CLI "mapsdb --show" gives the sum of all the violations related to the category rather than the number of violated rules per each category as the "Rule Count" counter.	
<b>Condition:</b> This is encountered on Switch using MAPS with the specified CLI.	

<b>Defect ID:</b> DEFECT000593988	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> ISL - Inter-Switch Linking
<b>Symptom:</b> Switch panic may occur, resulting from secd termination.	
<b>Condition:</b> This may be encountered when a remote switch is rebooted or a new remote switch is connected to fabric.	

<b>Defect ID:</b> DEFECT000595186	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.4.1	<b>Technology:</b> Flow Vision
<b>Symptom:</b> With Maps logical group as ingress port for vTap flow, portdisable/enable of Fport belonging to MAPS group may result in halting of vTap-mirroring.	
<b>Condition:</b> 1. Maps logical group as ingress port for vTAP flow. 2. Repetitive portdisable/enable of Fports belonging to MAPS group.	
<b>Recovery:</b> hareboot to failover to the standby CP	

<b>Defect ID:</b> DEFECT000595573	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.2	<b>Technology:</b> Flow Vision
<b>Symptom:</b> Customer observes a "/" following the * in the ingressport display of sys_analytics_vtap.	
<b>Condition:</b> This is seen when AMP is used for monitoring the fabric performance.	
<b>Workaround:</b> This is a cosmetic issue and functionality is not impacted.	
<b>Recovery:</b> This is a cosmetic issue and functionality is not impacted.	

<b>Defect ID:</b> DEFECT000595812	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> Buffer Credit Management
<b>Symptom:</b> Hosts may experience aborts and frame loss without visible errors on switch.	
<b>Condition:</b> This is a rare occurrence that may be triggered by a bit corruption on BE port leading to frame loss	

<b>Defect ID:</b> DEFECT000596066	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.2.0_hit	<b>Technology:</b> CLI - Command Line Interface
<b>Symptom:</b> Brocade 6546 units may occasionally signal to the chassis management module that a power supply voltage has reached a “fatal” level, leading to switch to be powered off.	
<b>Condition:</b> This is encountered only while performing AC power on/off cycling with Full POST enabled during outgoing inspection.	

<b>Defect ID:</b> DEFECT000596508	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.2	<b>Technology:</b> SNMP - Simple Network Management Protocol
<b>Symptom:</b> SNMP swDeviceStatusTrap trap is not generated in FOS v7.3.2 when device status is changed from offline to online or vice versa.	
<b>Condition:</b> Switches running FOS v7.3.2 are affected. FOS v7.3.1x does not have this problem.	

<b>Defect ID:</b> DEFECT000596616	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.0.2	<b>Technology:</b> High Availability
<b>Symptom:</b> Termination of weblinker is observed.	
<b>Condition:</b> This issue is seen rarely during configupload operation from management application.	

<b>Defect ID:</b> DEFECT000597291	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.2	<b>Technology:</b> RAS - Reliability, Availability, and Serviceability
<b>Symptom:</b> trackchangeset is deprecated in 7.3. However the following need to be addressed. 1. the configuration parameter in configshow/configupload needs to be cleared. 2. TRCK raslog messages appearing on errdump in 7.3.2 need to be stopped. 3. swTrackChangesTrap that is sent to SNMP Manager also needs to be stopped. 4. swTrackChangesInfo OID should be blocked when SNMP manager tries to SNMP-GET.	
<b>Condition:</b> This applies only to trackchangeset related cli commands, traps and query supported in pre 7.3 versions in all platforms and deprecated from 7.3 onward.	

<b>Defect ID:</b> DEFECT000597483	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.2	<b>Technology:</b> Fabric Watch
<b>Symptom:</b> Some difference are seen in the severity of filter class between Event traps and Fabric Watch traps.	
<b>Condition:</b> This is applicable to all the platforms.	

<b>Defect ID:</b> DEFECT000598549	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.2	<b>Technology:</b> Management GUI
<b>Symptom:</b> https with FQDN will not work if switch csr is generated from Non- default switch FID.	
<b>Condition:</b> VF enabled switch might exhibit this issue.	
<b>Workaround:</b> switch CSR needs to be generated only on default switch.	
<b>Recovery:</b> Please delete swtich csr and recreate the csr from default switch ID.	

<b>Defect ID:</b> DEFECT000599105	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.0.2	<b>Technology:</b> Software Installation & Upgrade
<b>Symptom:</b> DCX Power Supply may encounter "unknown header" after performing a reboot via firmwaredownload or hafailover that may result in a faulty power supply unit, where Chassisshow command shows PS as follows:: POWER SUPPLY Unit: <n>                      Unknown	
<b>Condition:</b> This is a very rare occurrence that may lead to FRU header corruption in the power supply internal EEPROM.	

<b>Defect ID:</b> DEFECT000599182	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.2	<b>Technology:</b> Flow Vision
<b>Symptom:</b> VTAP is active in a fabric with QOS high zones enabled.	
<b>Condition:</b> This is encountered when AMP is used to monitor the fabric performance.	
<b>Workaround:</b> Deactivate sys_analytics_vtap flow.	
<b>Recovery:</b> Deactivate sys_analytics_vtap flow.	

<b>Defect ID:</b> DEFECT000599416	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.4.1	<b>Technology:</b> Syslog
<b>Symptom:</b> Changing MIB capability in SNMP does not report proper old and new values in RAS log.	
<b>Condition:</b> This is applicable to all platforms.	

<b>Defect ID:</b> DEFECT000599746	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.3.2	<b>Technology:</b> ISL - Inter-Switch Linking
<b>Symptom:</b> The switch.login.perSwitchMax parameter of 'F-port login setting' is removed after user issued configure setting or configdefault.	
<b>Condition:</b> Configkey "switch.login.perSwitchMax" gets removed only when the default value is configured. This is applicable to all platforms.	

<b>Defect ID:</b> DEFECT000599939	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.2	<b>Technology:</b> RAS - Reliability, Availability, and Serviceability
<b>Symptom:</b> The integer value after the string INTEGER in SNMP trap does not match with ifindex.	
<b>Condition:</b> This issue is applicable for all platforms.	

<b>Defect ID:</b> DEFECT000599955	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.2	<b>Technology:</b> Flow Vision
<b>Symptom:</b> Customer uses VTAP with port based csctl configuration on a chassis.	
<b>Condition:</b> This is encountered when AMP is used for monitoring fabric performance.	
<b>Workaround:</b> Deactivate sys_analytics_vtap flow	
<b>Recovery:</b> Deactivate sys_analytics_vtap flow	

<b>Defect ID:</b> DEFECT000600016	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> MAPS - Monitoring and Alerting Policy Suite
<b>Symptom:</b> Kernel Panic may be encountered, triggered by "Detected termination of MAPS mdd process".	
<b>Condition:</b> This may occur when executing the CLI command "mapsdb --show" to get the MAPS dashboard.	

<b>Defect ID:</b> DEFECT000600111	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.2	<b>Technology:</b> APM - Advanced Performance Monitoring
<b>Symptom:</b> Installation for frame monitor via webtool may fail	
<b>Condition:</b> This issue is seen when there's any stale monitor present on the port and user is trying to install any frame monitor via webtool on the same port.	

<b>Defect ID:</b> DEFECT000602221	
<b>Technical Severity:</b> Low	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.2	<b>Technology:</b> CLI - Command Line Interface
<b>Symptom:</b> The output of the CLI command fwPortDetailShow does not update immediately after a state change.	
<b>Condition:</b> This may be encountered for all SFP types, when using the CLI command fwportdetailshow after the relevant area (RXP/TXP) changes state from above high threshold, back to between high and low thresholds. Here the 'x' indication of SRX and STX in CLI command fwportdetailshow does not change back to a dash '-'.	

## Closed with Code Change in Fabric OS v7.3.2

This section lists the defects with Critical, High and Medium Technical Severity closed with a code change as of February 16, 2016 in Fabric OS v7.3.2.

<b>Defect ID:</b> DEFECT000431369	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.0.2	<b>Technology:</b> SNMP - Simple Network Management Protocol
<b>Symptom:</b> Mib browser displays ascii-hex of populated fcpportflag value. For example it displays "30" for 0, "31" for 1, where expected display is "0", "1".	
<b>Condition:</b> This is seen only for the MIB display of fcpportflag.	

<b>Defect ID:</b> DEFECT000471996	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.0.2	<b>Technology:</b> Hardware Monitoring
<b>Symptom:</b> During systemverification, while running portloopbacktest command, or during POST following a reboot, the portloopback test may occasionally fail with errors of "MEM init failed", "Timeout waiting for packet", or it may trigger a silent reboot or panic due to "machine check, sig: 7".	
<b>Condition:</b> This issue is seen only on 16G switches. Director switches do not have this problem.	
<b>Workaround:</b> To avoid loopback test failures, use small values such as 100 for -nframes option with more iterations.	

<b>Defect ID:</b> DEFECT000472607	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Other
<b>Reported In Release:</b> FOS7.2.0	<b>Technology:</b> Other
<b>Symptom:</b> Brocade 6510 switch may become inaccessible via SSH and/or Telnet when a firmware upgrade of the switch initiated through Brocade Network Advisor results with "failed to enforce new iptable rules" error message.	
<b>Condition:</b> It's a race condition caused by an existing ineffective file locking mechanism.	
<b>Workaround:</b> Activating (from console) a new policy with rules of default active policy will restore access to the switch. such as: Ipfilter -clone new_rules -from default_ipv4 Ipfilter -activate new_rules	

<b>Defect ID:</b> DEFECT000479904	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS6.4.3	<b>Technology:</b> Software Installation & Upgrade
<b>Symptom:</b> Firmware Migration might result in a switch panic due to a weblinker termination.	
<b>Condition:</b> In rare cases, a firmware download might cause a weblinker termination followed by a panic.	
<b>Recovery:</b> In a chassis based system, reboot the standby CP. In a pizza box, reboot the switch.	

<b>Defect ID:</b> DEFECT000484766	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Distance
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> FCIP - Fibre Channel over IP
<b>Symptom:</b> Port persistent disable feature doesnt work for GE ports on FX8-24 across any reboot or hareboot operations.	
<b>Condition:</b> GE ports on FX8-24 are not persistently disabled across a reboot, hareboot, or firware download operations.	
<b>Recovery:</b> Use FOS CLI to manually disable GE ports.	

<b>Defect ID:</b> DEFECT000486385	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.1.1	<b>Technology:</b> Configuration Fundamentals
<b>Symptom:</b> Rasadmin config keys/values are not replicated after configdownload.	
<b>Condition:</b> This is seen when the user configures these keys via the rasadmin cli before configupload.	

<b>Defect ID:</b> DEFECT000492786	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.0.2	<b>Technology:</b> Fabric Watch
<b>Symptom:</b> Customer can change the "thresh.env" and "thresh.res" (chassis settings) from the Logical Switch even if the user does not have chassis wide permissions.	
<b>Condition:</b> An account(admin/root) on a specific logical switch with chassis role user are allowed to change the chassis wide parameters when fwsettocustom and fwsetto default are used.	

<b>Defect ID:</b> DEFECT000494952	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.2.0_fuj	<b>Technology:</b> Management GUI
<b>Symptom:</b> In Webtools fabric watch explorer, F/FL copper Port class is missing.	
<b>Condition:</b> On embedded switch where internal ports 1 - 16 are copper ports.	

<b>Defect ID:</b> DEFECT000495229	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.2.1_HIL	<b>Technology:</b> Software Installation & Upgrade
<b>Symptom:</b> After a non-disruptive firmware download, portstatsshow may display increased instances of fec_uncor_detected errors on front end port.	
<b>Condition:</b> This may be encountered only on embedded platforms.	

<b>Defect ID:</b> DEFECT000497810	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.1.1	<b>Technology:</b> D-Port - Diagnostic Port
<b>Symptom:</b> Core blade faults when dport tests are being run on ICL ports and ports are disabled.	
<b>Condition:</b> Disable port under test.	
<b>Workaround:</b> Don't disable ports when dport tests are in progress.	



<b>Defect ID:</b> DEFECT000498132	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.1.1	<b>Technology:</b> Fabric Watch
<b>Symptom:</b> Configured actions for SFP monitoring will not be taken for a port if 8G and 16G SFPs are interchanged for that port.	
<b>Condition:</b> It happens only when 8G SFP is replaced by 16G or vice versa.	

<b>Defect ID:</b> DEFECT000499559	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> Configuration Fundamentals
<b>Symptom:</b> Current diag reset sequence for Brocade 6510 does not work well on all units. It results in switch going faulty when diags are enabled.	
<b>Condition:</b> This does not happen under normal circumstances. This is seen on some of the Brocade 6510 units where continuous reboot is encountered with diagpost enabled.	

<b>Defect ID:</b> DEFECT000500423	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> Fibre Channel Routing
<b>Symptom:</b> Routing Queries issued through MVS may not return the correct set fabric paths for the identified SID/DID pair when DBR is used.  Port metrics for all E-Port PDB's returned for a Diagnostic Query may exhibit information that is unrelated to the specified SID/DID pair.	
<b>Condition:</b> 1. FMS enabled 2. FICON . MVS environment, with switch managed by host 3. DBR Routing Policy configured in the fabric.	

<b>Defect ID:</b> DEFECT000504187	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS6.3.2	<b>Technology:</b> QoS - Quality of Service
<b>Symptom:</b> Some ports on Brocade 5480 switch may exhibit CRC errors.	
<b>Condition:</b> This stems from the serdes tuning on this switch not being set to optimum setting.	

<b>Defect ID:</b> DEFECT000512293	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> Configuration Fundamentals
<b>Symptom:</b> For 7840 platform, the management link doesn't come up when eth0 (Management interface) speed and duplex is forced to 100Mbps/Half-duplex and rolling error message seen on console.	
<b>Condition:</b> When the 7840 platform eth0 is configured to 100Mbps half duplex.	
<b>Workaround:</b> Use speed of 100Mbps/Full-duplex instead of 100Mbps/Half-duplex.	

<b>Defect ID:</b> DEFECT000513544	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.1.1	<b>Technology:</b> Fibre Channel Services
<b>Symptom:</b> During code upgrade, standby CP may run into repeated msd panics and may not come online to standby ready mode.	
<b>Condition:</b> This occurs when AG node name is missing on active CP during execution of the FC-GS-3 Register Platform (RPL) command.	

<b>Defect ID:</b> DEFECT000513914	
<b>Technical Severity:</b> Low	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> Fabric Watch
<b>Symptom:</b> When a blade inserted, SFP insertion messages are reported in raslog.	
<b>Condition:</b> This happens for ports that are parts of a logical switch. It does not happen if all ports are in default switch.	

<b>Defect ID:</b> DEFECT000514903	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.1.1	<b>Technology:</b> Fabric Watch
<b>Symptom:</b> FW-1403 raslog message is logged on all logical switches other than default switch.	
<b>Condition:</b> This issue is seen when flash usage goes beyond 90 percent.	

<b>Defect ID:</b> DEFECT000516645	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Extension
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> FCIP - Fibre Channel over IP
<b>Symptom:</b> FX8-24 blade experienced a watchdog exception panic.	
<b>Condition:</b> The signature of the kernel crash indicates there is an interrupt storm, and should be very rare.	
<b>Workaround:</b> Powercycle should help recover from the issue.	

<b>Defect ID:</b> DEFECT000520333	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.2.0	<b>Technology:</b> FICON
<b>Symptom:</b> CUP remained quiescent after firmware upgrade.	
<b>Condition:</b> It happens in a timing condition when the firmware download completion notification is missed by CUP.	

<b>Defect ID:</b> DEFECT000521204	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS6.4.3	<b>Technology:</b> Configuration Fundamentals
<b>Symptom:</b> During hafailover, customer encountered a switch panic.	
<b>Condition:</b> This was encountered during a rare PCI write failure to an ASIC chip. An invalid DMA descriptor was accessed without validation check.	
<b>Recovery:</b> Replace the faulty port blade.	

<b>Defect ID:</b> DEFECT000521344	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.1.2	<b>Technology:</b> Fabric Watch
<b>Symptom:</b> Configuring portthconfig with area ST posts continuous alerts even after being in the same state.	
<b>Condition:</b> Configure ST area for portclasses(port/eport/fport/fcpuport classes)	

<b>Defect ID:</b> DEFECT000522361	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.1.0	<b>Technology:</b> MAPS - Monitoring and Alerting Policy Suite
<b>Symptom:</b> 16Gbs Core blades experiencing heavy frame loss are not being faulted and impacted fabric traffic.	
<b>Condition:</b> When 16G blades experience excessive bad_os, enc_out etc link errors.	
<b>Recovery:</b> Replace excessive link error blade. After upgrade to a release with fix, the blade will be faulted if link error reaches an internal monitoring threshold.	

<b>Defect ID:</b> DEFECT000522386	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> FEC - Forward Error Correction
<b>Symptom:</b> Forward Error Correction counters will not be displayed in the portstatssh command for offline ports.	
<b>Condition:</b> With port fencing feature enabled, when the ports go offline, the Forward Error Counters will not be displayed in the portstatssh command for these offline ports.	

<b>Defect ID:</b> DEFECT000523383	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> Bottleneck Detection (legacy)
<b>Symptom:</b> When there is real latency device in fabric and triggers frame timeout, latency warning AN-1003 reports affected delay, slowdown and pct secs as 0. For example:  [AN-1003], 2/2, FID 128, WARNING, , Latency bottleneck on F-Port 9 0.00 pct. of 30 secs affected Avg. delay 0 us. Avg. slowdown 0., traf.c, line: 4457, comp:trafd,	
<b>Condition:</b> In a frame timeout situation, a race condition may lead Bottleneck monitor to read counters before lower layer driver has populated the data.	
<b>Recovery:</b> It will recover by next data read cycle. Ignore the occasional 0 counters.	

<b>Defect ID:</b> DEFECT000523845	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS6.3.2	<b>Technology:</b> Access Gateway
<b>Symptom:</b> Appearance of the configuration parameter "ag.fporttrunking" differs depending on reboot/hareboot	
<b>Condition:</b> After non-disruptive firmware upgrade from FOS v6.2 to FOS v6.3, configuration key ag.fporttrunking(introduced in FOS v6.3) created at boot stage is getting removed. And the issue persists when user performs non-disruptive firmware upgrade to higher firmware versions without reboot.	
<b>Recovery:</b> No other functional impact	

<b>Defect ID:</b> DEFECT000523863	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.2.0	<b>Technology:</b> FICON
<b>Symptom:</b> Channel Detected Errors, may see an error indicating a protocol timeout, the CUP continues to run.	
<b>Condition:</b> System Reset Received by CUP.	
<b>Recovery:</b> If the CUP stops communicating, vary CUP Path back online (vary offline/online).	

<b>Defect ID:</b> DEFECT000524532	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> Bottleneck Detection (legacy)
<b>Symptom:</b> Unwarranted Bottleneck Detection alerts may be encountered on a switch.	
<b>Condition:</b> This issue stems from a failing API leading to incorrect computations. When applying consistent latency into the switch, the AN-1003 messages for the specific F_Port show very low affected percentages with a slowdown value of 0.	

<b>Defect ID:</b> DEFECT000525413	
<b>Technical Severity:</b> Low	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Distance
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> FCIP - Fibre Channel over IP
<b>Symptom:</b> The 'portcfgge <port> --show' command and 'portshow autoneg <port>' command do not show the valid output for 7800/FX8-24. It will report 'No GE configuration entries found' instead of reporting the actual data.	
<b>Condition:</b> This will occur every time the 'portcfgge <port> --show' and 'portshow autoneg <port>' commands are issued.	

<b>Defect ID:</b> DEFECT000526298	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.1.2	<b>Technology:</b> Fabric Watch
<b>Symptom:</b> Event values that occur when porthconfig --pause is used are displayed after porthconfig --continue is executed.	
<b>Condition:</b> When a port is paused for certain class and area and enabled later it still has the previous values which it had during pause.	

<b>Defect ID:</b> DEFECT000526963	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> MAPS - Monitoring and Alerting Policy Suite
<b>Symptom:</b> EM-5029 and MAPS-1003 raslog messages are logged indicating a temperature out of range.	
<b>Condition:</b> Occurs during a transient internal error in reading the temperature sensor status.	

<b>Defect ID:</b> DEFECT000527025	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> APM - Advanced Performance Monitoring
<b>Symptom:</b> CLI command fmmonitor --delmonitor <fmttype> -port 2/2 returns with "Specified Frame type doesn't exist on the specified port" even though a new fm-type was created and added to port 2/2.	
<b>Condition:</b> This may be seen when user moves the frame monitor installed port from one logical switch to another and then moves back the same port to the original logical switch.	

<b>Defect ID:</b> DEFECT000527506	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.1.0	<b>Technology:</b> Configuration Fundamentals
<b>Symptom:</b> I2C access failures leading to various symptoms such as: <ol style="list-style-type: none"> <li>1. slotshow command output may flag some components with an "*", indicating no i2c access to that component.</li> <li>2. switchshow command output may indicate "Speed Mismatch / Incompatible SFP"</li> <li>3. tempshow command output may display "unknown"</li> <li>4. Console log (dmesg) may include: pcf954x_select_mux: Failed to select the I2C mux (addr=76, val=08, err=-1 id=0)!</li> </ol>	
<b>Condition:</b> Brocade 6520 with the current version of software fails to properly reset or clear transient i2c faults. Consequently, Temporary or Transient errors on the I2C bus can result in what appears to be a permanent HW failure on a Brocade 6520.	
<b>Recovery:</b> Cold boot switch	

<b>Defect ID:</b> DEFECT000527862	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> Management GUI
<b>Symptom:</b> Name server table column position is not persistent across re-launch.	
<b>Condition:</b> This name server table column display issue is seen when the switch is in non AG mode.	

<b>Defect ID:</b> DEFECT000528010	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Distance
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> FCIP - Fibre Channel over IP
<b>Symptom:</b> FCIP HCL failure encountered due to a large number of FCIP objects in the configuration	
<b>Condition:</b> This is encountered when a large number of FCIP Objects (>> 20K FICON or FCP objects) are present.	
<b>Workaround:</b> Schedule a maintenance window for a disruptive FOS code load.	
<b>Recovery:</b> Recover environment after disruptive code load completes.	

<b>Defect ID:</b> DEFECT000528142	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> Management GUI
<b>Symptom:</b> When using Network Advisor Real Time performance graphing and specifying latency on the FCIP tunnel graph, the latency being reported is 645ms. Whereas the Round Trip Time value reported by the CLI command "portshow fcip tunnel <tunnel id> -p" for the specific FCIP tunnel 12/22 is 10 ms.	
<b>Condition:</b> This was not specific to a given scenario. For a given FCIP tunnel the aggregated RTT value of all the TCP connections is displayed in the Network Advisor latency output of Real Time Performance graph.	

<b>Defect ID:</b> DEFECT000528396	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS6.4.3	<b>Technology:</b> Fabric Watch
<b>Symptom:</b> Switch status changes to MARGINAL and back to HEALTHY with no contributing factor reported.	
<b>Condition:</b> Transient condition with no impact to traffic, switch, or fabric.	

<b>Defect ID:</b> DEFECT000528657	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Security
<b>Reported In Release:</b> FOS7.2.0	<b>Technology:</b> Zoning
<b>Symptom:</b> FCPD termination encountered when device sends malformed response with incorrect R_CTL information during FCP probing.	
<b>Condition:</b> This occurs only when the device responds with malformed frames during FCP probing.	

<b>Defect ID:</b> DEFECT000528891	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> Fibre Channel Routing
<b>Symptom:</b> Observed "queue iswitch: queue full" or iswitchd termination during stress test.	
<b>Condition:</b> This may be encountered in a FCR environment, during an overnight test run with FCR zone change, device change, and Fabric-ID change test cases.	

<b>Defect ID:</b> DEFECT000530212	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Fibre Channel Services
<b>Symptom:</b> CLI command "ipaddrshow" may exit with segment fault when IPV6 is enabled on management interface.	
<b>Condition:</b> This is seen when bond0 is enabled with ipv6 enabled.	

<b>Defect ID:</b> DEFECT000530663	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> Access Gateway
<b>Symptom:</b> A device connected through Access Gateway cannot login into the switch.	
<b>Condition:</b> This issue will be seen only when the device sends a class 2 FLOGI and the edge switch does not support the class 2 frames.	

<b>Defect ID:</b> DEFECT000532726	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Management GUI
<b>Symptom:</b> WebTools will not launch with Java 8 update 40.	
<b>Condition:</b> When Admin Domain is enabled in the switch.	
<b>Workaround:</b> If supported, enable virtual fabric.	

<b>Defect ID:</b> DEFECT000532780	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Software Installation & Upgrade
<b>Symptom:</b> DCX kernel panic on standby CP during hafailover without any functional impact.	
<b>Condition:</b> A timing issue during hafailover stress test.	

<b>Defect ID:</b> DEFECT000532799	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> Management GUI
<b>Symptom:</b> Webtools fails to launch from browser if HTTPS & fully qualified domain name (FQDN) are used.	
<b>Condition:</b> FQDN names may not work after upgrading to FOS 7.2.x and above.	
<b>Workaround:</b> Use switch IP address instead of fully qualified domain name.	

<b>Defect ID:</b> DEFECT000533717	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> CLI - Command Line Interface
<b>Symptom:</b> Unexpected log message "CONF-1042: Fabric Configuration Parameter Edge hold time changed to 220" even when "Edge Hold Time" value is not changed.	
<b>Condition:</b> Raslog CONF-1042 is posted even when there is no change in edge hold time value through "configure" CLI.	

<b>Defect ID:</b> DEFECT000533844	
<b>Technical Severity:</b> Low	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> SNMP - Simple Network Management Protocol
<b>Symptom:</b> swTrackChangesTrap MIB object is obsolete but the customer is able to configure and get TRCK-100X RAS messages. Firmware migration retained the trackchangeset configuration causing the user unable to remove it as the new firmware doesn't support this configuration.	
<b>Condition:</b> trackchangeset configuration and migration to unsupported version.	

<b>Defect ID:</b> DEFECT000533925	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.1.0	<b>Technology:</b> FICON
<b>Symptom:</b> FCIP FICON Emulated Tape device failures with FICN-1062 in RASLOG and LastStates=0x0000423F443F.	
<b>Condition:</b> When attempting to complete read processing and the device presents Device Busy then Device End, FICON emulation logic incorrectly generated a No-Op command with chaining instead of accepting the Device End Status.	
<b>Workaround:</b> Disable FICON Read Pipelining.	

<b>Defect ID:</b> DEFECT000534141	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.3.0_HUR	<b>Technology:</b> Port Bring-up
<b>Symptom:</b> BR6543 switch takes very long time for the internal link to come online.	
<b>Condition:</b> This problem can be observed by disabling/enabling the port using portdisable/portenable CLI.	

<b>Defect ID:</b> DEFECT000534151	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Other
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Other
<b>Symptom:</b> Configdownload -vf fails with message "VF config file version is not compatible with the switch firmware version. Invalid header in config file."	
<b>Condition:</b> This is encountered when running the CLI command configdownload -vf.	
<b>Recovery:</b> Rebuild VF config on switch.	

<b>Defect ID:</b> DEFECT000534413	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> MAPS - Monitoring and Alerting Policy Suite
<b>Symptom:</b> "logicalgroup --show" command will show more ports than switch has under "ALL_PORTS" group. MAP-1003 RASLOG messages seen on non-existent ports.	
<b>Condition:</b> This issue happens if the customer has MAPS enabled and performs hafailover or migrates firmware to MAPS supported versions with online F_Port trunk.	
<b>Workaround:</b> Bring up the F_port trunk ports after hafailover.	

<b>Defect ID:</b> DEFECT000534507	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Distance
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> FCIP - Fibre Channel over IP
<b>Symptom:</b> Severe FICON workload disruption occurs during 7840 hot code load.	
<b>Condition:</b> This is encountered when FCIP HCL is attempted on a single 7840 switch in a 7840 pair with HA and active FICON data flow.	
<b>Workaround:</b> Plan a disruptive firmware download.	

<b>Defect ID:</b> DEFECT000534748	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Other
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Other
<b>Symptom:</b> The switch names longer than 15 characters will be truncated to 15 characters in the switch name field of "islshow" output.	
<b>Condition:</b> When user executes "islshow" CLI command, user will notice that only up to 15 characters of switchname get displayed.	

<b>Defect ID:</b> DEFECT000535483	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Security
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Fabric Authentication
<b>Symptom:</b> Observed error message "Hash type as Invalid" when authentication has set to FCAP.	
<b>Condition:</b> It happens when authentication is set to FCAP and after a hareboot.	



<b>Defect ID:</b> DEFECT000535808	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> MAPS - Monitoring and Alerting Policy Suite
<b>Symptom:</b> After firmwaredownload to FOS v7.3.0c, taking Supportsave causes mdd termination. The issue persists even after reboot of the switch.	
<b>Condition:</b> Race condition during BNA polling of switch status policy.	
<b>Workaround:</b> Avoid BNA polling.	

<b>Defect ID:</b> DEFECT000536235	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.1.2	<b>Technology:</b> Fabric Watch
<b>Symptom:</b> Fabric watch traps are not generated for the voltage area for both 8Gsfp and 16Gsfp.	
<b>Condition:</b> Occurs on all platforms that run FOS7.1.2b, FOS7.2.0, FOS7.3.0 and higher versions.	

<b>Defect ID:</b> DEFECT000536455	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> Fibre Channel Services
<b>Symptom:</b> Both Active and Standby CPs panic in a director while processing Read Diagnostic Parameters (RDP) Extended Link Service (ELS) request from local device.	
<b>Condition:</b> This is triggered by a race condition when a local device repeatedly sends unsolicited RDP ELS request and the switch is running FOS7.3.0 or above.	
<b>Workaround:</b> Disable device port capable of RDP.	

<b>Defect ID:</b> DEFECT000536632	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Hardware Monitoring
<b>Symptom:</b> Diagnostic test "systemverification" fails with "NON_DIAG errors detected during run".	
<b>Condition:</b> This is encountered when running systemverification test on BR7840.	

<b>Defect ID:</b> DEFECT000536832	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> ISL - Inter-Switch Linking
<b>Symptom:</b> Port does not come online and raslog is flooded with the following message: "Brocade6520, S0,P51(114): Port is offline due to Encryption Compression Block error."	
<b>Condition:</b> This is seen when Inflight Encryption is enabled on an Ex-Port.	

<b>Defect ID:</b> DEFECT000537093	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Extension
<b>Reported In Release:</b> FOS7.1.1	<b>Technology:</b> FCIP - Fibre Channel over IP
<b>Symptom:</b> When Fastwrite and Tape-pipelining are enabled on an FCIP tunnel, timeouts occur after Reservation Conflict Status is reported from tape devices.	
<b>Condition:</b> This occurs when multiple servers attempt to reserve the same tape device over OSTP enabled tunnel.	
<b>Workaround:</b> Disable OSTP on the FCIP Tunnel.	

<b>Defect ID:</b> DEFECT000537108	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS6.4.3	<b>Technology:</b> Buffer Credit Management
<b>Symptom:</b> Standby CP reboots due to software assert during a hafailover.	
<b>Condition:</b> If back-end credit recovery is enabled with Link Reset only option via CLI, creditrecovmode and credit recovery algorithms kick in. During that window if either core or edge blade goes offline, this can sometimes cause the standby CP to panic during a subsequent hafailover.	

<b>Defect ID:</b> DEFECT000537311	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Distance
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> FCIP - Fibre Channel over IP
<b>Symptom:</b> Switchshow shows no ports found in the system.	
<b>Condition:</b> Run switchshow command.	

<b>Defect ID:</b> DEFECT000537571	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.2.0	<b>Technology:</b> Hardware Monitoring
<b>Symptom:</b> CRC errors with good EOF at 4G speed may be encountered when with some SFPs.	
<b>Condition:</b> This may be seen when using 4G LW SFP part number 57-1000027-02.	

<b>Defect ID:</b> DEFECT000537848	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Fibre Channel Routing
<b>Symptom:</b> Host is unable to discover target devices in an Edge-to-Edge FCR topology.	
<b>Condition:</b> When some of the edge fabric switches having trunked IFLs are rebooted, resulting in Fabric ID conflicts in any of the backbone fabric FCRs, a few hosts may not be able to discover targets.	
<b>Recovery:</b> Enable any EX_ports that have been disabled as a result of fabric ID conflict and disable / enable the edge switch FC ports of affected hosts.	

<b>Defect ID:</b> DEFECT000538046	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.1.1	<b>Technology:</b> Configuration Fundamentals
<b>Symptom:</b> Fabric Watch terminates in a busy system causing switch reboot.	
<b>Condition:</b> This is a very rare occurrence that may be encountered on systems that are very busy.	

<b>Defect ID:</b> DEFECT000538051	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> FICON
<b>Symptom:</b> BR7840 FICON Emulation OXID usage overlap causes Interface Control Check error messages on the mainframe console.	
<b>Condition:</b> The issue can occur anytime when two or more devices are active in FICON emulation over an FCIP tunnel.	
<b>Workaround:</b> Disable FICON emulation features on the FCIP Tunnel.	

<b>Defect ID:</b> DEFECT000538092	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> Access Gateway
<b>Symptom:</b> Following a FOS firmware upgrade or hareboot, traffic to and from the Access Gateway stops after the N-Port trunk master is disabled.	
<b>Condition:</b> This issue will occur when the following conditions occur: - hareboot for any reason, including firmwaredownload. - N-port trunk with at least two trunk members. - Trunk master of the N-port trunk is disabled.	
<b>Workaround:</b> Never disable the N-port trunk master when other trunk members are online. Instead, always disable all trunk members. Trunk slaves can be disabled with no issue.	
<b>Recovery:</b> To recover, do one of two things: 1. Bounce a host F_port on the Access Gateway. Or, 2. Disable all trunk members and then enable all trunk members.	

<b>Defect ID:</b> DEFECT000538492	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Extension
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> FCIP - Fibre Channel over IP
<b>Symptom:</b> Error recovery issue when the last write in a small write block is dropped.	
<b>Condition:</b> Data Integrity Error can be exposed when the Last Write Data Frame in a small write (8k) Across 7840 FCIP Tunnel when TP is on.	

<b>Defect ID:</b> DEFECT000538917	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Fibre Channel Services
<b>Symptom:</b> The Fibre Channel specification (FC-FS-3) pertaining to Read Diagnostic Parameters (RDP) has been updated with new descriptor codes and descriptor flags. This renders current implementation incompatible. Device will not get properly formatted RDP response.	
<b>Condition:</b> This happens in a fabric with device capable of RDP and running FOS v7.3.0 or above.	
<b>Workaround:</b> Disable device port capable of RDP.	

<b>Defect ID:</b> DEFECT000539167	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.1.1	<b>Technology:</b> Management GUI
<b>Symptom:</b> Weblinker termination is seen when the TACACS+ server is unreachable.	
<b>Condition:</b> Happens only when user tries to login to switch which has unreachable TACACS+ server for authentication.	
<b>Workaround:</b> Use local or other remote authentication(LDAP/RADIUS) for login.	

<b>Defect ID:</b> DEFECT000539290	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> Buffer Credit Management
<b>Symptom:</b> On internal back end (BE) link with 16G core blade to 8G edge blade, credit is not automatically recovered.	
<b>Condition:</b> For the 16G core blade to 8G edge blade direction, if there is credit loss on VC and the "creditrecovmod --cfg onLROnly" command is not enabled in an early release, then once the 16G credit leak interrupt is triggered, the credit leak interrupt enabled bits will not be enabled again.	
<b>Workaround:</b> Run creditrecovmod --cfg onLROnly before credit is depleted.	
<b>Recovery:</b> Slotpoweroff /on core blade to recover the BE link.	

<b>Defect ID:</b> DEFECT000539342	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> MAPS - Monitoring and Alerting Policy Suite
<b>Symptom:</b> System may encounter mdd process killed by Software Watchdog and show console message "Detected termination of process mdd0".	
<b>Condition:</b> These may be seen after a reboot, when MAPS is up and polls for the FC routing statistics from the FOS services, and encounters slow response.	
<b>Recovery:</b> When the problem occurs, MAPS will restart and the system should come up normally.	

<b>Defect ID:</b> DEFECT000539473	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> MAPS - Monitoring and Alerting Policy Suite
<b>Symptom:</b> MAPS generate CPU load alert during Supportsave.	
<b>Condition:</b> While running cpu intensive operation during supportSave gathering.	

<b>Defect ID:</b> DEFECT000539576	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> RAS - Reliability, Availability, and Serviceability
<b>Symptom:</b> TRCE-1005 will be triggerd when autoftp feature is enabled with SCP protocol.	
<b>Condition:</b> Happens only on systems configured with SCP protocol.	
<b>Workaround:</b> Use FTP or SFTP instead of SCP.	

<b>Defect ID:</b> DEFECT000539584	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Hardware Monitoring
<b>Symptom:</b> 2KM QSFP ICL ports may see link errors such as CRC and FEC errors. The link errors may result in credit or frame loss and trigger link reset.	
<b>Condition:</b> Errors may be seen after any conditions that causes the port to be toggled, such as a portdisable or switchdisable.	
<b>Recovery:</b> Clear the stats. Toggle the port and check for link errors.	

<b>Defect ID:</b> DEFECT000539641	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Virtual Fabrics
<b>Symptom:</b> If blade ports 48-63 on FC16-64 are moved to a logical switch from a base switch, they cannot be moved back to base switch on 8510-4.	
<b>Condition:</b> Issue will only be seen on 8510-4 with FC16-64 blade.	

<b>Defect ID:</b> DEFECT000539670	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Fibre Channel Services
<b>Symptom:</b> BR7840 becomes unusable after Firmware download from FOS7.4.0 to FOS7.3.x. Switch may show faulty rc=20015 status.	
<b>Condition:</b> Failure may occur during the switch downgrade of FOS from FOS 7.4.0 to FOS7.3.0x on a BR7840.	
<b>Recovery:</b> Power cycle the failed BR7840.	

<b>Defect ID:</b> DEFECT000540027	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.0.2	<b>Technology:</b> MAPS - Monitoring and Alerting Policy Suite
<b>Symptom:</b> Supportffdc configuration is set to default(enable) after firmwaredownload/hareboot/reboot.	
<b>Condition:</b> Caused by non-default supportffdc configuration and firmwaredownload/hareboot/reboot.	
<b>Recovery:</b> Reconfigure supportffdc option as needed after reboot (/hareboot/firmwaredownload).	

<b>Defect ID:</b> DEFECT000540035	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Licensing
<b>Symptom:</b> There is a new business requirement to offer a 20 port version of the Brocade 5432 switch plus 4 “port on demand” licensed ports.	
<b>Condition:</b> POD was not supported before.	
<b>Recovery:</b> Upgrade to the new FOS version to limit the switch to 20 licensed ports. To enable the additional 4 ports, the customer would need to purchase and install the POD license.	

<b>Defect ID:</b> DEFECT000540245	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Distance
<b>Reported In Release:</b> FOS7.1.0	<b>Technology:</b> FCIP - Fibre Channel over IP
<b>Symptom:</b> Tunnels bounce caused FFDC event.	
<b>Condition:</b> This may occur if a FICON frame sequence is received with FC type of 0x1B or 0x1C, with one SOFi3 frame followed by more than 13 SOFn3 frames in sequence on an FCIP Tunnel. Such condition may occur with a failed FICON adapter in a connected device.	

<b>Defect ID:</b> DEFECT000540469	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.1.0	<b>Technology:</b> FICON
<b>Symptom:</b> Channel Detected Error message after a tape job failure.	
<b>Condition:</b> When running a tape write job that experiences a timeout (due to FC CRC errors occurring during the IO), the job will normally detect an MIH failure and go through error recovery and the error recovery could encounter the invalid token CDE.	
<b>Workaround:</b> Disable FICON Tape Pipelining or correct the cause of the FC CRC errors.	

<b>Defect ID:</b> DEFECT000540585	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> RAS - Reliability, Availability, and Serviceability
<b>Symptom:</b> Support Save output does not include VE or GE port information.	
<b>Condition:</b> This is seen after multiple logical switches have been created and one or more of the logical switches have been deleted and the VE ports reside in a logical switch that was created after one that was deleted.	
<b>Workaround:</b> Recreate empty logical switches up to the limit of logical switches in that chassis.	

<b>Defect ID:</b> DEFECT000540694	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> APM - Advanced Performance Monitoring
<b>Symptom:</b> Switch repeatedly logs the following raslog message: "[PS-1009], 16386, SLOT 7   FID 128, WARNING, , Failed to add the device updates in condb database." This can mislead the customer on the number of devices supported by name server, zoning and device connectivity.	
<b>Condition:</b> This happens when there are large number of devices zoned together and with "Performance Monitor license". There is no impact to device connectivity, but Top talkers may not be able to display the top talking flows.	

<b>Defect ID:</b> DEFECT000540720	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Hardware Monitoring
<b>Symptom:</b> Even though the portpeerbeacon CLI does succeed and correctly lights up the LED on both end ports, a trace shows the 'Beacon on' sub-command is in the wrong format.	
<b>Condition:</b> When user executes portpeerbeacon CLI.	

<b>Defect ID:</b> DEFECT000541101	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> TIZ - Traffic Isolation Zoning
<b>Symptom:</b> An unexpected reload occurred after all non-dedicated ISL ports have been disabled which triggers non-TI zone traffic to take dedicated TI path.	
<b>Condition:</b> All of the following conditions need to be met to hit the issue. 1. There are mix of dedicated TI zone ISLs and non-dedicated TI zone ISLs reachable to at least one domain. 2. HA operations (hafailover, non-disruptive downgrade or upgrade) have issued in the switch after TI zone is successfully established. 3. portdisable is issued on all non-dedicated ISLs, which triggered non-TI zone traffic to take dedicated TI path.	

<b>Defect ID:</b> DEFECT000541322	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> FICON
<b>Symptom:</b> IOS050I CHANNEL DETECTED ERROR message on mainframe console after 0x70 Status from XRC primary controller.	
<b>Condition:</b> This is seen during FCIP FICON XRC emulated tunnel processing of 0x70 Status from the connected DASD controller.	
<b>Workaround:</b> Disable FICON XRC Emulation on the FCIP Tunnel.	

<b>Defect ID:</b> DEFECT000541427	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.0.1	<b>Technology:</b> Hardware Monitoring
<b>Symptom:</b> Switch will panic when the user runs portloopback tests within one hour after hafailover.	
<b>Condition:</b> This would happen only on C3 platforms.	
<b>Workaround:</b> Wait to run portloopback/diag tests until at least 1 hour after hafailover is completed.	

<b>Defect ID:</b> DEFECT000541653	
<b>Technical Severity:</b> Low	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.0.0	<b>Technology:</b> Management GUI
<b>Symptom:</b> Unsupported thconfig security areas showed up in Webtools.	
<b>Condition:</b> When using Webtools to configure thconfig security areas.	
<b>Workaround:</b> Use the CLI.	

<b>Defect ID:</b> DEFECT000541661	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> Virtual Fabrics
<b>Symptom:</b> Active CP Panic may occur while running Brocade SAN Health report.	
<b>Condition:</b> This may be encountered in a large virtual fabric environment when running back to back CLI commands "lfcfg --showall -xxxx"	

<b>Defect ID:</b> DEFECT000542334	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Configuration Fundamentals
<b>Symptom:</b> BR7840 switch runs out of Control Processor file system disk space.	
<b>Condition:</b> This is seen when there are old trace files and corefiles left in /var/log or /mnt/var/log directory.	
<b>Workaround:</b> Use CLI "rm" to remove /var/log/core.* /mnt/var/log/core.*	

<b>Defect ID:</b> DEFECT000542388	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.1.1	<b>Technology:</b> Access Gateway
<b>Symptom:</b> Even though there are no mappings being shown in ag -mapshow for some ports, available F-ports cannot be mapped to existing N-ports. All F-ports are reported to be mapped to a non-existent N-port, and do not show up in ag -mapshow.	
<b>Condition:</b> Inconsistent config file is downloaded to the switch with configdownload. The inconsistency entails one of the following: - F-to-N-port mapping for F-Ports, or - No port config, but F-to-N-port mapping exists.	
<b>Recovery:</b> Configure all non-used ports (ports that are not N-port and not F-port) as N-port and then remove that configuration. In rare cases, even the F-ports may need to be temporarily configured as N-ports and then remove the configuration.	

<b>Defect ID:</b> DEFECT000542559	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Distance
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> FCIP - Fibre Channel over IP
<b>Symptom:</b> Tunnel bounce with an associated BLS-5024 FFDC event.	
<b>Condition:</b> This issue can occur after FCIP tunnel bounces due to WAN outage or other network issue.	

<b>Defect ID:</b> DEFECT000542630	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Access Gateway
<b>Symptom:</b> In AG setup, fdmid daemon has memory leak after overnight I/O run.	
<b>Condition:</b> This is encountered in an AG setup following overnight I/O stress, resulting from memory allocated for nportInfo in fdmi query not being freed.	
<b>Recovery:</b> Invoke hafailover/hareboot to free up the memory.	

<b>Defect ID:</b> DEFECT000542770	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Port Bring-up
<b>Symptom:</b> Port 60 on BR6520 cannot come online.	
<b>Condition:</b> This seems to happen with FOSv7.3.1 and later code.	
<b>Workaround:</b> Use a different port.	



<b>Defect ID:</b> DEFECT000542995	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> Access Gateway
<b>Symptom:</b> Customer encounters a panic when enabling access gateway through Web Tools and then running commands through the CLI subsequently.	
<b>Condition:</b> Enable AG mode in the switch through Web Tools.	
<b>Recovery:</b> Auto-recovery after panic dump.	

<b>Defect ID:</b> DEFECT000543727	
<b>Technical Severity:</b> Low	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> RAS - Reliability, Availability, and Serviceability
<b>Symptom:</b> The CP flash drive can run low on space due to the /var/log/esmd_lib.log file growing too large.	
<b>Condition:</b> The problem may occur on any switch other than the Brocade 7840 switch, when running with FOS7.3.0x and FOS7.3.1. The problem will not occur on the Brocade 7840 switch.	
<b>Recovery:</b> Manually delete the /var/log/esmd_lib.log file.	

<b>Defect ID:</b> DEFECT000543734	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> Fibre Channel Services
<b>Symptom:</b> DCX CP reboots after a port blade going to faulty state.	
<b>Condition:</b> This happened when NPIV devices falsely detected duplicate PWWN as a result of path failover upon detect faulty blade. It could also happen if a device connected to a port blade which goes faulty and moving the device to other port blades in chassis without powering down the faulty blade.	

<b>Defect ID:</b> DEFECT000543921	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Security
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Security Vulnerability
<b>Symptom:</b> CVE-2014-3570: Bignum squaring (BN_sqr) may produce incorrect results.	
<b>Condition:</b> This bug occurs at random with a very low probability, and is not known to be exploitable in any way, though its exact impact is difficult to determine. Straightforward bug attacks fail - either the attacker cannot control when the bug triggers, or no private key material is involved.	

<b>Defect ID:</b> DEFECT000544160	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Security
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> Encryption
<b>Symptom:</b> After FS8-18 or BES was powered up, several LUNs were inaccessible. The LUN state was "LUN setup".	
<b>Condition:</b> After firmware download or power event, BES tried to re-establish nexus for each Container-Host pair. As part of nexus establishment, Internal login commands to Fabric got dropped on core blades. This resulted in improper cleanup and retry timed-out internal request.	
<b>Recovery:</b> Bounce affected port.	

<b>Defect ID:</b> DEFECT000544649	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Other
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> Other
<b>Symptom:</b> Switch/CP panic with fabricd process terminated.	
<b>Condition:</b> When a lots of "fabriclog -s" commands are executed simultaneously.	
<b>Workaround:</b> Allow the CLI to finish before start another one.	

<b>Defect ID:</b> DEFECT000544788	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> APM - Advanced Performance Monitoring
<b>Symptom:</b> CP reboots after perfmon -del <port> and then running perfmon --show <port> in fabricmode top talkers.	
<b>Condition:</b> Happens only when TT monitor is configured for fabricmode and show CLI is executed with port number that is already deleted.	

<b>Defect ID:</b> DEFECT000544986	
<b>Technical Severity:</b> Low	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Hardware Monitoring
<b>Symptom:</b> The CLI command "sfps show <slot/port>" always returns a zero in "Length 50u (OM3)" field.	
<b>Condition:</b> This is seen only for OM3 50um QSFPs.	

<b>Defect ID:</b> DEFECT000545217	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> Management GUI
<b>Symptom:</b> End to End (EE) monitor is not supported in base switch, yet, when configuring it, improper message pops up such as: 1). "The SID is not associated with any devices. Do you still want to use this SID?" 2). "The DID is not associated with any devices. Do you still want to use this DID?" Rather than just error out with : "EE monitor not supported on base switch".	
<b>Condition:</b> It occurs when configuring EE monitor(SID/DID performance graph) through WebTools in base switch.	
<b>Workaround:</b> Use CLI.	

<b>Defect ID:</b> DEFECT000545619	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.1.1	<b>Technology:</b> Fabric Watch
<b>Symptom:</b> When user tries to add the filter monitors using 'fmmonitor' command , CLI displays "Performance License is required to execute this command"	
<b>Condition:</b> This issue is seen when we try to add the predefined frame monitor filters(like scsi) to a port and its corresponding filter area is not available in FabricWatch	
<b>Workaround:</b> Remove/delete the fabric watch license from license db	

<b>Defect ID:</b> DEFECT000545930	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Access Gateway
<b>Symptom:</b> Failover policy on AG gets disabled after fastboot action.	
<b>Condition:</b> This is seen on AG switch when failover policy has an unused port defined.	
<b>Workaround:</b> Configure all unused ports as N-ports (portcfgnport <port> 1) and then remove the N-port configuration from those ports (portcfgnport <port> 0).	

<b>Defect ID:</b> DEFECT000546095	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.2.0	<b>Technology:</b> Virtual Fabrics
<b>Symptom:</b> Switch reboot occurred during simultaneous invocation of lfcfg command.	
<b>Condition:</b> Occurs when lfcfg is invoked simultaneously by different users.	
<b>Workaround:</b> Refrain from invoking lfcfg command simultaneously.	

<b>Defect ID:</b> DEFECT000546296	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Fibre Channel Services
<b>Symptom:</b> 1. [MAPS-1003] raslog is posted frequently. 2. CLI commands on the switch depict sluggishness.	
<b>Condition:</b> This is encountered while managing the switch from Brocade Network Advisor.	
<b>Recovery:</b> Snmpconfig –default snmpv3 will reset the snmp configuration to default which will rectify this issue. After this command is executed users have to reconfigure the SNMP configuration and rediscover the switch from Brocade Network Advisor.	

<b>Defect ID:</b> DEFECT000546417	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> SNMP - Simple Network Management Protocol
<b>Symptom:</b> After upgrade to FOS 7.3.1, SNMP traps would not be seen in BNA master log.	
<b>Condition:</b> If switch is configured with IPFC address and if we change IP address of a switch, the traps are sent using IPFC address instead of chassis/switch IP address.	
<b>Recovery:</b> CP failover after both CPs migrated to new firmware or after IP address change.	

<b>Defect ID:</b> DEFECT000546941	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Extension
<b>Reported In Release:</b> FOS7.2.0	<b>Technology:</b> Fastwrite
<b>Symptom:</b> XTUN-1001 and XTUN-1008 RASLOG messages generated and failed FCIP Fast Write or Tape Pipelined I/O operations.	
<b>Condition:</b> When there are multiple logical switches each with an emulation feature enabled FCIP Tunnel (Fast Write and/or OSTP). If one of the Fast Write or OSTP configurations include a large number of discovered FCIP objects (ITNs and ITLs), the FCIP emulation memory manager may incorrectly allocate and cache too many I/O structures leading to out of memory conditions in any one of the different FCIP Tunnel logical switch configurations.	

<b>Defect ID:</b> DEFECT000546994	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Other
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Other
<b>Symptom:</b> Supportsave initiated from BNA fails. Using same credentials from CLI, supportsave works	
<b>Condition:</b> This happens only when special character (\$) is used.	
<b>Workaround:</b> Configuring BNA FTP password with no special character.	

<b>Defect ID:</b> DEFECT000547042	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Software Installation & Upgrade
<b>Symptom:</b> When BufOpMode is enabled for core blades, Firmware upgrade/downgrade to FOS versions not supporting BufOpMode on core blades is not being blocked (as should be the case).	
<b>Condition:</b> This is encountered when BufOpMode is enabled and firmware upgrade/downgrade to FOS version not supporting this feature is being attempted.	
<b>Workaround:</b> Check to see if BufOpMode is enabled and clear/reset it before attempting a firmwaredownload of FOS versions that do not support this feature.	

<b>Defect ID:</b> DEFECT000547722	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Other
<b>Reported In Release:</b> FOS7.1.2	<b>Technology:</b> Other
<b>Symptom:</b> Configuration keys corresponds to credit recovery feature may not be consistently reflected in configshow.	
<b>Condition:</b> This issue is seen when user changes credit recovery feature configuration.	
<b>Recovery:</b> Only display issue, the feature works as expected.	

<b>Defect ID:</b> DEFECT000547759	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Security
<b>Reported In Release:</b> FOS7.1.0	<b>Technology:</b> Security Vulnerability
<b>Symptom:</b> Customer was unable login with RADIUS user to switch after changed password expiration period by "passwdcfg --set -maxpasswordage 90".	
<b>Condition:</b> When admin (local) is expired , remote users(radius) with admin privileges are not allowed to login as switch will try to authenticate the remote users based on the credentials available in local database.	

<b>Defect ID:</b> DEFECT000547765	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.0.2	<b>Technology:</b> Buffer Credit Management
<b>Symptom:</b> Link reset events encountered on internal back-end (BE) port trunks with no link errors or credits lost. This is also a rare occurrence that a link reset is missed on front end E port while there is complete credit loss.	
<b>Condition:</b> This may be encountered when frames are dropped continuously at internal Back-End ports as well as at Front-End E-ports at the same time due to heavy congestion or credit loss on front end ports. This defect only affects 8G Platforms.	
<b>Workaround:</b> Disable credit recovery on Front-End E-ports if BE link resets continuously.	
<b>Recovery:</b> Remove the source of congestion or credit loss issue that is causing frame drops.	

<b>Defect ID:</b> DEFECT000547921	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Access Gateway
<b>Symptom:</b> In an AG fabric or NPIV environment, device is not found or HBA detects SCSI command timeout and fabric switch stops routing AG switch/NPIV device traffic.	
<b>Condition:</b> This may occur when fabric switch is configured for session based zoning and a device connected to AG switch or an NPIV device that is not in any zone database, is enabled. This causes all traffic going through the same fabric switch F-port to be disrupted. This issue only impacts 16G fabric switch running FOSv7.4.0, FOSv7.3.1 and FOSv7.2.1d.	
<b>Workaround:</b> Use hard zoning on fabric switch, or add the device into zoning database first before bringing it online.	
<b>Recovery:</b> Upon hitting this issue, the user may bring up ANY zoned member on AG switch or NPIV, that is using the fabric switch F-Port, to recover.	

<b>Defect ID:</b> DEFECT000548463	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.1.1	<b>Technology:</b> Port Bring-up
<b>Symptom:</b> Kernel panic encountered on a CP while taking over the Active Role, due to heartbeat loss, causing a cold recovery of the system.	
<b>Condition:</b> This may be encountered only when processing FDISC with duplicate PWWNs.	

<b>Defect ID:</b> DEFECT000548512	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.0_HUR	<b>Technology:</b> Fibre Channel Services
<b>Symptom:</b> Switch experienced panic during system verification test and disabling switch during D-port test.	
<b>Condition:</b> This is seen in a race condition when diag test reset ASIC while ASIC is being accessed in parallel.	

<b>Defect ID:</b> DEFECT000548713	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Distance
<b>Reported In Release:</b> FOS7.2.0	<b>Technology:</b> FCIP - Fibre Channel over IP
<b>Symptom:</b> Disk to disk mirroring application failures with associated XTUN-1001 RASLOG messages.	
<b>Condition:</b> When a specific Disk to Disk mirroring application encounters IO errors over a 7800 or FX8-24 FCIP Tunnel, it will issue an odd sequence of Extended Link Services commands (concurrent LOGO/LOGO and PLOGI sequences). The problem can be encountered if the FCIP Tunnel has OSTP and/or Fast Write enabled and there are still active FCP commands flowing when the ELS sequences are processed.	
<b>Recovery:</b> Reboot 7800 platform or slotpoweroff/slotpoweron the FX8-24 blade.	

<b>Defect ID:</b> DEFECT000548721	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS6.4.3	<b>Technology:</b> Fabric Watch
<b>Symptom:</b> E-port is fenced even after port fencing has been disabled.	
<b>Condition:</b> This issue would only happen if E-port and port classes are configured with the same thresholds for ST area. Disabling port fencing does not handle properly E-ports that have been fenced earlier under this condition.	
<b>Workaround:</b> Use the E-Port only threshold to monitor the State change of ISLs, or to monitor all the ports in general, choose different threshold values for E-port thresholds and port class thresholds (probably E-Port threshold + 5 ).	
<b>Recovery:</b> Bounce the port.	

<b>Defect ID:</b> DEFECT000549322	
<b>Technical Severity:</b> Low	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.3.2	<b>Technology:</b> Fibre Channel Routing
<b>Symptom:</b> Switch hit "Verify - Failed expression" after a FWDL, paths were lost after running portloopbacktest.	
<b>Condition:</b> This happens in versions earlier than v7.3.2. Both systemverification and portloopbacktest leave routing tables in an incomplete state on a 8G/16G switch with D-port and D-port comes on line first before other ports. When the switch is enabled again after running these commands, routes are incorrect or nonexistent.	
<b>Workaround:</b> Don't run systemverification or portloopbacktest.	
<b>Recovery:</b> Power cycle the affected blades.	

<b>Defect ID:</b> DEFECT000549477	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> MAPS - Monitoring and Alerting Policy Suite
<b>Symptom:</b> MAPS might generate a transient MAPS-1021 RASLOG message to indicate switch in Critical state due to faulty port rule/thresholds has violated during CEC testing. Effect of this RASLOG does not stay very long (less than few minutes) and MAPS generates a healthy message.	
<b>Condition:</b> This happens during CEC IML test.	

<b>Defect ID:</b> DEFECT000549913	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> CLI - Command Line Interface
<b>Symptom:</b> Loading unsupported firmware is not blocked on Brocade 5432.	
<b>Condition:</b> User CLI "Firmwaredownload" to load unsupported code onto Brocade 5432.	

<b>Defect ID:</b> DEFECT000550167	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Fabric Watch
<b>Symptom:</b> porthconfg --show CLI does not show ST area configuration (either default or custom) for port class.	
<b>Condition:</b> All platforms exhibit this behavior with FOS version 7.3.1 and above.	

<b>Defect ID:</b> DEFECT000550377	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> MAPS - Monitoring and Alerting Policy Suite
<b>Symptom:</b> If MAPS daemon is terminated multiple times in a short period of time, the switch may lose HA synchronization.	
<b>Condition:</b> The problem can happen when configdownload or mapspolicy command is run, or when a switch is polled for MAPS data before MAPS daemon has finished initialization.	
<b>Recovery:</b> When MAPS gets restarted, the system should work fine. If daemon restart fails and causes switch to get out of HA synchronization, a cold boot is needed to recover HA.	

<b>Defect ID:</b> DEFECT000550418	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Hardware Monitoring
<b>Symptom:</b> Duration field, Dur(H:M), in fwPortDetailShow does not show correct value for Inter Chassis Link(ICL) and Logical Inter Switch Link (LISL) ports on director platform.	
<b>Condition:</b> Happens on chassis with ICL links.	
<b>Recovery:</b> A display issue without functional impact, no recovery needed.	

<b>Defect ID:</b> DEFECT000550514	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Other
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> Other
<b>Symptom:</b> Creditrecovmode --check fails between core blade and FX8-24 blade creditrecovmode --check 5/108,30 Error: Not Supported on this link.	
<b>Condition:</b> Error: Not Supported on this link is seen if an AP blade has ever had a VE port enabled without a reboot, manual credit recovery CLI "creditrecovmode" occurring. This is seen even if the VE port is currently disabled.	
<b>Recovery:</b> After rebooting the switch, the "creditrecovmode --check" will work on non-VE port AP blade.	

<b>Defect ID:</b> DEFECT000550684	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Fibre Channel Services
<b>Symptom:</b> When an embedded switch configured in Access Gateway mode is connected to a 3rd party fibre channel switch, the Brocade embedded switch has a software assert error and reboots. [KSWD-1002], 18/14, FFDC   CHASSIS, WARNING, 5, Detected termination of process fdmid0:1226., hasm_swd.c.	
<b>Condition:</b> Error occurs during FDMI request response process with following embedded platforms: BR6547, 6548, M5424, M6505 running FOSv7.3.0 and higher. The error does not occur with v7.2.x.	

<b>Defect ID:</b> DEFECT000550874	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Fibre Channel Services
<b>Symptom:</b> With 16Gbps FC cards from a specific vendor connected to Brocade 6546, OS Boot failures occur at a high probability and the attached port on BR6546 becomes a G-Port.	
<b>Condition:</b> This may be encountered with HBAs from a specific vendor on a BR6546 platform.	

<b>Defect ID:</b> DEFECT000550923	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Other
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> Other
<b>Symptom:</b> 3rd party application queries with an alias name that doesn't require padding often fail with an error code 0x9.	
<b>Condition:</b> This occurs when a user application tries to get zoning alias name information from a switch.	
<b>Workaround:</b> Add a 4 byte pad to the word-align alias name query in user application.	

<b>Defect ID:</b> DEFECT000551318	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Other
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Other
<b>Symptom:</b> BNA is not able to discover the DCX and DCX-4s platforms.	
<b>Condition:</b> This is encountered when two or more application blades are present in the chassis based platforms DCX/DCX-4s.	

<b>Defect ID:</b> DEFECT000551420	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Fabric Watch
<b>Symptom:</b> Incorrect comparison operator is seen in the MAPS rules that are obtained as the result of converting fabric watch setting corresponds to resource class, flash area.	
<b>Condition:</b> This issue is seen when user executes "mapsconfig --fwconvert" command.	

<b>Defect ID:</b> DEFECT000551520	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Extension
<b>Reported In Release:</b> FOS7.2.0	<b>Technology:</b> WAN Performance Analysis Tools
<b>Symptom:</b> Brocade NMS monitoring services are unable to do snmpwalk of fcipExtendedLinkTable to collect statistical data.	
<b>Condition:</b> During an snmpwalk "FcipExtendedLinkTable" fails when a 7800 or FX8-24 blade has GE ports in the default switch and VE ports in a separate Virtual Fabric configuration. If the GE ports and VE port are in the same VF the snmpwalk will work without problems.	

<b>Defect ID:</b> DEFECT000551531	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Security
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Security Vulnerability
<b>Symptom:</b> OpenSSL Security Advisory [19 Mar 2015]: CVE-2015-0286, CVE-2015-0288, CVE-2015-0289, CVE-2015-0292. These vulnerabilities could allow various maliciously crafted data to trigger segment fault, memory corruption or DOS attack.	
<b>Condition:</b> To exploit these vulnerabilities in FOS requires access to switch after user authentication through console, Telnet, and SSH connections.	
<b>Workaround:</b> Place switch and other data center critical infrastructure behind firewalls to disallow access from the Internet; Change all default account passwords; Delete guest accounts and temporary accounts created for one-time usage needs; Utilize FOS password policy management to strengthen the complexity, age, and history requirements of switch account passwords. Upgrading to a FOS version including this fix prevents exposures to the four CVEs noted in the defect Symptom.	



<b>Defect ID:</b> DEFECT000551676	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.1.1	<b>Technology:</b> Hardware Monitoring
<b>Symptom:</b> I2c errors may be encountered during the early init phase of the system such as - VPD write seeprom (fru) 0x75 (bus addr 0x54, mem addr 0x90) len 14, i2c return -1.	
<b>Condition:</b> This may be seen under rare i2 access contention situations on switches only. Directors are not subject to this access contention.	

<b>Defect ID:</b> DEFECT000551787	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Fibre Channel Routing
<b>Symptom:</b> FCR devices not imported for up to 10 minutes following hafailover, resulting in IO disruption.	
<b>Condition:</b> This may be encountered in an FCR setup, when ports (E/ExVex/Fport) are bounced in edge fabric during hafailover. This only impacts FOS7.3.x and FOS7.4.0 with staged port matching feature.	
<b>Workaround:</b> If there is VEx port in a FCR fabric, upgrade to a FOS version with this fix. If already running a version of FOS without this fix, contact tech support to disable staged port matching feature on backbone fabric to reduce future risk until able to upgrade to a version with fix.	
<b>Recovery:</b> Wait approximately 10 minutes for FCR to re-import the devices after an HaFailover or toggle end device to recover.	

<b>Defect ID:</b> DEFECT000552474	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> FICON
<b>Symptom:</b> Unable to run Teradata with Teradata FICON emulation enabled on the FCIP tunnel.	
<b>Condition:</b> When Teradata emulation is enabled on an FCIP tunnel and a read operation presents early ending status for a short read. This leads to an error in the FICON Teradata emulation logic and subsequent IOs fail.	
<b>Workaround:</b> Disable Teradata emulation on the FCIP Tunnel.	

<b>Defect ID:</b> DEFECT000552552	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Port Bring-up
<b>Symptom:</b> Speed will show higher (in switchshow) than actual SFP speed. For instance, 8G SFP will negotiate to 16G speed though SFP is not capable of 16G speed.	
<b>Condition:</b> This occurs when remote 16G capable port generates Loss of Signal (light cut-off and on) by cable plug-out/in after switch performed HA-failover.	
<b>Workaround:</b> Use 16G SFP on 16G port blade.	
<b>Recovery:</b> Use CLI portdisable/portenable to recover the affected port. But the problem can reoccur if there is a subsequent hafailover on the switch and the remote 16G port cuts light again.	

<b>Defect ID:</b> DEFECT000553129	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Other
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Other
<b>Symptom:</b> Observed fcippathtest failure executing lb_mode 5 with -nframes options in Brocade 7800 with: BTR ETH ASIC port 0 Link Status FAILED 0x168 fcippathtest: Blaster port 50, bad lli status	
<b>Condition:</b> This may occur when fcippathtest is ran for a high number of iterations.	

<b>Defect ID:</b> DEFECT000553134	
<b>Technical Severity:</b> Low	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> CLI - Command Line Interface
<b>Symptom:</b> Diagnostic run may fail with raslog "[BLZ-5040], 0, CHASSIS, ERROR, Brocade 7840, S0,P8(105) [OID 0x43028829]: Sending ipp port fault for reason 1".	
<b>Condition:</b> When running diagnostics on BR7840.	

<b>Defect ID:</b> DEFECT000553197	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Extension
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> FCIP - Fibre Channel over IP
<b>Symptom:</b> I/O errors to BR7840 FCIP Open Systems Tape Pipelining connected FCP SID/DID pairs and XTUN-1000 Missed data frame RASLOG.	
<b>Condition:</b> This may occur when OSTP is currently in read pipelining when a FCP Inquiry command is received using the same OXID that is currently active for an OSTP read-ahead read command sequence.	
<b>Workaround:</b> Disable OSTP Read Pipelining on the BR7840 FCIP Tunnel.	

<b>Defect ID:</b> DEFECT000553786	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.2.0	<b>Technology:</b> Fibre Channel Services
<b>Symptom:</b> HA State Synchronization failed when switch detected there is duplicated WWN.	
<b>Condition:</b> HA Sync is stopped when the delete operation on AG duplicated device entry on standby fails.	
<b>Recovery:</b> Reboot standby CP to recover.	

<b>Defect ID:</b> DEFECT000553920	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> Virtual Fabrics
<b>Symptom:</b> Ports in logical switch may bounce following firmwaredownload or hareboot.	
<b>Condition:</b> In a VF environment with XISL on and base switch not defined, FMS is enabled on one logical switch, other logical switches without FMS mode enabled, will have FICON filters installed on ports by mistake and cause traffic disruption.	

<b>Defect ID:</b> DEFECT000554238	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Software Installation & Upgrade
<b>Symptom:</b> After swapping QSFP with 2km SFP on core blade ICL ports, downgrade to FOS v7.3.x is blocked.	
<b>Condition:</b> This is seen when QSFP is replaced by 2km SFP, and a firmware code downgrade is attempted.	
<b>Recovery:</b> Remove all 2km optics, find old standard QSFP optics and insert them into the empty ports previously occupied by the 2km optics, then perform firmware downgrade.	

<b>Defect ID:</b> DEFECT000554414	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> Configuration Fundamentals
<b>Symptom:</b> Link issues are seen when fcippathtest runs for a longer duration on BR7800.	
<b>Condition:</b> Running systemverification test in a loop of about 10+ iterations results in this issue.	

<b>Defect ID:</b> DEFECT000554530	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Security
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> Zoning
<b>Symptom:</b> Zone enforcement may not be properly enforced on an NPIV port which can lead to timeouts or frame loss at any of the NPIV devices on the same switch port.	
<b>Condition:</b> This may be seen when a device on an NPIV port that has no zoning members (un-zoned device) existing on the same NPIV port as other devices with zoning members defined. Zoning configuration change (cfgsave or cfgenable) can lead to incorrect zoning enforcement on this port. Any non-NPIV ports that also have no zoning definition (no members defined) will also be left in a state where these un-zoned ports would be able to communicate with each other. No impact to ports that have zoning defined. This can be seen in FOS v7.2.1d, v7.2.1e, v7.3.1, v7.3.1a, v7.4.0, v7.4.0a	
<b>Workaround:</b> NS queries will properly block access to viewing any other devices, but physical access could still be allowed. To prevent any physical access, create a "dummy zone" for all ports that are currently un-zoned (no zoning members defined).	

<b>Defect ID:</b> DEFECT000554744	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Management GUI
<b>Symptom:</b> The alias member revert back to an old offline WWPN as one switched from the "Alias" tab to the "Config" tab in Web Tools.	
<b>Condition:</b> Name server dialog is opened with "Auto refresh" on, such that name server info, zoning info and switch details will be polled from switch and refreshed in Web Tools. As the zone information is refreshed, user changed zone alias will be overwritten.	
<b>Workaround:</b> Disable the auto refresh before doing any zoning changes in Web Tools	

<b>Defect ID:</b> DEFECT000554772	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Distance
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> FCIP - Fibre Channel over IP
<b>Symptom:</b> BR7840 FCIP Hot Code Load failure (firmware download is disruptive of FCIP traffic over the FCIP Tunnel).	
<b>Condition:</b> This is encountered when attempting to perform FCIP HCL on a BR7840 FICON Emulation enabled tunnel.	
<b>Workaround:</b> As a work around, schedule a maintenance window to perform disruptive firmware download.	

<b>Defect ID:</b> DEFECT000555034	
<b>Technical Severity:</b> Low	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> RAS - Reliability, Availability, and Serviceability
<b>Symptom:</b> Customer may see an alert on intrusion detection system due to switch sending a frame to 127.1.10.1 out management interface.	
<b>Condition:</b> This may be encountered only on non-chassis systems with no Application Processor Blade.	

<b>Defect ID:</b> DEFECT000555286	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Extension
<b>Reported In Release:</b> FOS7.1.1	<b>Technology:</b> FCIP - Fibre Channel over IP
<b>Symptom:</b> FCIP OSTP (Open Systems Tape Pipelining) Read I/O Job failures (block count mismatch or other errors).	
<b>Condition:</b> After tape server or tape server HBA code upgrade, SSC-2/3 (T10 standard) commands can be issued to an FCIP OSTP enabled tunnel to a tape device. FCIP currently does not have the SSC-2 command set implemented and therefore unknown errors can occur.	
<b>Workaround:</b> Disable OSTP Read Pipelining on the FCIP Tunnel between the server and the tape device.	

<b>Defect ID:</b> DEFECT000555363	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> MAPS - Monitoring and Alerting Policy Suite
<b>Symptom:</b> Power on Hours of thconfig did not convert to MAPS properly after mapsconfig --fwconvert.	
<b>Condition:</b> Configure power on hours for 16G SFP in fabric watch and convert them to MAPS using mapsconfig --fwconvert.	

<b>Defect ID:</b> DEFECT000555831	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Other
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> Other
<b>Symptom:</b> Memory leak caused weblinker to crash and restart.	
<b>Condition:</b> Various operations such as configupload operation from BNA and LDAP authentication caused memory issue with weblinker.	
<b>Workaround:</b> Perform configupload via CLI. Avoid frequent configupload/stats from BNA.	

<b>Defect ID:</b> DEFECT000556108	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Management GUI
<b>Symptom:</b> Zone Administration display is completely blank and fails to display the buttons.	
<b>Condition:</b> When trying to fetch the vendor name using the OUI which doesn't exist in WebTools repository.	

<b>Defect ID:</b> DEFECT000556188	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Buffer Credit Management
<b>Symptom:</b> On 16G director, while credit recovery feature is not turned on, if there is unstable back-end link, blade could be faulted.	
<b>Condition:</b> A blade could be faulted on 16G director when following conditions are meet: 1. Credit recovery feature is off 2. There is credit loss caused by link level error on back-end ports. 3. The link cannot be recovery by an automatic Link Reset. This can happen with FOS7.2.1e and 7.3.1a and FOS7.4.0; With earlier releases, the credit loss will result no further action until user manually link reset if credit recovery feature is off.	
<b>Workaround:</b> Turn on credit recovery "creditrecovmode --cfg onLrOnly" to limit the fault to a back-end port only under error condition.	
<b>Recovery:</b> Turn on credit recovery "creditrecovmode --cfg onLrOnly" to limit the fault to a back-end port only under error condition.	

<b>Defect ID:</b> DEFECT000556419	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> SNMP - Simple Network Management Protocol
<b>Symptom:</b> MIB browser displays octet string instead of decimal for both SNMP traps and queries.	
<b>Condition:</b> All the traps/queries with fcportflag would see this problem.	

<b>Defect ID:</b> DEFECT000556479	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Security
<b>Reported In Release:</b> FOS7.1.1	<b>Technology:</b> Zoning
<b>Symptom:</b> Zoned terminated and caused switch to panic.	
<b>Condition:</b> Zone contains alias name as member and zone is renamed such that both zone and member contains same name and user executes zone --validate <zone_name>.	

<b>Defect ID:</b> DEFECT000556926	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Distance
<b>Reported In Release:</b> FOS8.0.0	<b>Technology:</b> FCIP - Fibre Channel over IP
<b>Symptom:</b> DP Panics on BR7840 due to memory corruption.	
<b>Condition:</b> This is a rare occurrence from a race condition where TCP Header access occurs after the wire buffer has been freed in IPV6 configuration.	

<b>Defect ID:</b> DEFECT000557254	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> FICON
<b>Symptom:</b> CUP goes offline when CSCTL priority is enabled on CUP port.	
<b>Condition:</b> Plogi response frame has priority bit set and CSCTL priority to the CUP is not supported.	

<b>Defect ID:</b> DEFECT000557582	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> Fabric Watch
<b>Symptom:</b> Though LISL isn't included in the "Number of ports:" of switchstatuspolicy, when the LISL port state changes, switch status is still changed to MARGINAL with Fabric watch FW-1436 logged.	
<b>Condition:</b> Occurs when LISL state changes via switchdisable/enable on Logical Switch or Base switch.	

<b>Defect ID:</b> DEFECT000557651	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> Configuration Fundamentals
<b>Symptom:</b> Director panics while port blade reports power failure.	
<b>Condition:</b> It happens when a port blade suddenly lost power, and CP continues to access the blade without valid blade information.	
<b>Recovery:</b> Remove problem blade.	

<b>Defect ID:</b> DEFECT000558108	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.4.1	<b>Technology:</b> RAS - Reliability, Availability, and Serviceability
<b>Symptom:</b> RAS-1004 raslog messages are seen logged as WARNING messages.	
<b>Condition:</b> This was the default setting for this message. This has since been changed to INFO setting so as to avoid any undue alarm.	

<b>Defect ID:</b> DEFECT000558281	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Security
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Encryption
<b>Symptom:</b> Encryption blades were faulted resulting in loss of paths to encrypted LUNs.	
<b>Condition:</b> It happens during a Read Cap on access check LUNs which caused memory to be freed twice.	

<b>Defect ID:</b> DEFECT000558395	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Management GUI
<b>Symptom:</b> Sorting on Port ID doesn't work properly on Port Admin and Name server "Accessible devices".	
<b>Condition:</b> From the Port Admin tab, the issue is seen when the switch is configured with logical ports. The sorting support was not provided for the Accessible devices in Name server.	

<b>Defect ID:</b> DEFECT000558507	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Distance
<b>Reported In Release:</b> FOS7.2.0	<b>Technology:</b> FCIP - Fibre Channel over IP
<b>Symptom:</b> FX8-24 DP Soft Faults due to SE Core Panic after [FICN-1056] FICON Emulation Error Code=7	
<b>Condition:</b> Error case when XRC update traffic is running over FCIP XRC Emulation enabled tunnel.	
<b>Workaround:</b> Disable FICON XRC emulation on the FCIP Tunnel.	

<b>Defect ID:</b> DEFECT000558511	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Configuration Fundamentals
<b>Symptom:</b> Loss of CUP connectivity in a cascaded FICON environment, following the disruption of all ISL paths to a given CUP.	
<b>Condition:</b> Following disruption of all ISL paths to a given cascaded CUP, subsequent exchanges destined to the cascaded CUP cannot be delivered until a new PLOGI session is established.	
<b>Recovery:</b> Vary channel online to recover.	

<b>Defect ID:</b> DEFECT000558610	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.2.0	<b>Technology:</b> SNMP - Simple Network Management Protocol
<b>Symptom:</b> User does not see the swFCPortDisableReason as part of the SNMP trap.	
<b>Condition:</b> This issue is seen in all platforms , when the user receives swFCPortScn SNMP trap for port disable event.	

<b>Defect ID:</b> DEFECT000558820	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Other
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Other
<b>Symptom:</b> Response time out happens with higher nframes value specified for fcippathtest.	
<b>Condition:</b> Issue happens when nframes value as high as 70 is specified for fcippathtest.	

<b>Defect ID:</b> DEFECT000558864	
<b>Technical Severity:</b> Low	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Management GUI
<b>Symptom:</b> Switch View -> Switch Events Tab "Last Updated" time may lag behind the true last update time.	
<b>Condition:</b> Using GUI interface on switch event view.	

<b>Defect ID:</b> DEFECT000558936	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Other
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Other
<b>Symptom:</b> HIF mode value is not always being displayed in switchshow output .	
<b>Condition:</b> This is encountered when HIF mode is disabled. HIF mode value is displayed only when HIF mode is enabled.	

<b>Defect ID:</b> DEFECT000559178	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Fabric Watch
<b>Symptom:</b> Message corresponding to an unsupported feature shows as: Only "root" can turn ON certain zoning features.	
<b>Condition:</b> This is observed when user tries to change zoning operation parameters "Disable NodeName Zone Checking" through configure command.	

<b>Defect ID:</b> DEFECT000559228	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Configuration Fundamentals
<b>Symptom:</b> Switch has failed the POST tests. FRU is being faulted.” during firmwarecleaninstall in BR7840.	
<b>Condition:</b> This happens when a firmwaredownload is done between two versions if there is a u-boot update happening. Firmwaredownload of same versions will not see this issue. POST will fail due to timeout only when the uboot update is happening.	
<b>Recovery:</b> Subsequent reboots won't see the problem.	

<b>Defect ID:</b> DEFECT000559352	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.2.0	<b>Technology:</b> SNMP - Simple Network Management Protocol
<b>Symptom:</b> Unlike the display for other SNMP test traps, swDeviceStatus test Trap displays only varbind "swTestString".	
<b>Condition:</b> This behavior is seen on all platforms for swDeviceStatus test trap.	

<b>Defect ID:</b> DEFECT000559528	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> MAPS - Monitoring and Alerting Policy Suite
<b>Symptom:</b> MAPS traps are not sent as part of snmpTraps --send(test traps) command.	
<b>Condition:</b> All FOS platforms with MAPS enabled are affected. FOS 7.4 and above has no Fabric Watch as well as MAPS traps support in snmptraps command.	

<b>Defect ID:</b> DEFECT000559551	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Fabric Watch
<b>Symptom:</b> Severities of Event trap and Fabric Watch trap might be different for the same event.	
<b>Condition:</b> Any platform that runs versions less than FOS7.4 will see this.	

<b>Defect ID:</b> DEFECT000559709	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Management GUI
<b>Symptom:</b> Switch Health Report does not reflect accurate state of the ports: Web Tools shows the Error Ports Monitor as DOWN - but displays "All ports are healthy".	
<b>Condition:</b> Error Ports Monitor does not correctly reflect the status through Web Tools when there are ports with errors.	
<b>Workaround:</b> CLI command works properly and can be used as a workaround.	



<b>Defect ID:</b> DEFECT000559947	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> APM - Advanced Performance Monitoring
<b>Symptom:</b> Switch goes into rolling reboot following the execution of these sequence of commands: fmmonitor, configdefault, configupload/download.	
<b>Condition:</b> This may be encountered if configuration download and upload is performed when there are user defined frame monitors.	
<b>Workaround:</b> Avoid downloading configuration file with user defined frame monitors.	

<b>Defect ID:</b> DEFECT000560326	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Security
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Zoning
<b>Symptom:</b> Target Peer Zoning configuration parameter is shown in prior release configuration where the feature is not implemented.	
<b>Condition:</b> Target Peer Zoning configuration parameter is seen in the output for the configure command.	
<b>Workaround:</b> This is just a benign display issue with no functional impact.	

<b>Defect ID:</b> DEFECT000560344	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Other
<b>Reported In Release:</b> FOS7.1.1	<b>Technology:</b> Other
<b>Symptom:</b> Kernel panic while running fcping.	
<b>Condition:</b> This issue is observed rarely when user runs fcping with large frame numbers from different sessions.	

<b>Defect ID:</b> DEFECT000560375	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> Configuration Fundamentals
<b>Symptom:</b> Faulty power supply may lead to Raslog HIL-1611 (MISMATCH in PSU-FAN Air Flow direction.) resulting in system shutdown in 2 minutes.	
<b>Condition:</b> This is triggered by a faulty power supply causing read failures in power supply fan sensors.	
<b>Recovery:</b> Replace the faulty power supply to recover.	

<b>Defect ID:</b> DEFECT000560593	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Fibre Channel Services
<b>Symptom:</b> The parameter "switch.login.perSwitchMax" is not shown in configshow output.	
<b>Condition:</b> By design, when a key is not defined (i.e not yet configured by the user), system will display the default value for it. But this key is different in that it does not have a fixed default value. The default value is computed dynamically as a function of the platform. As such this behavior anomaly is per design.	

<b>Defect ID:</b> DEFECT000560645	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Configuration Fundamentals
<b>Symptom:</b> Management access (via assigned IP address of logical switch) is lost and changing IP addresses is not possible.	
<b>Condition:</b> This may happen when multiple logical switches have been created and assigned individual IP addresses for management purpose.	
<b>Workaround:</b> Create an extra logical switch, then make the appropriate IP address changes.	

<b>Defect ID:</b> DEFECT000560757	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> RAS - Reliability, Availability, and Serviceability
<b>Symptom:</b> When the user changes SNMP configuration attribute, switch outputs SNMP-1005 with previous value instead of current value.	
<b>Condition:</b> This behavior is seen in all platforms from FOS 7.3.1 onwards when there is a change in SNMP configuration attribute.	

<b>Defect ID:</b> DEFECT000560880	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> MAPS - Monitoring and Alerting Policy Suite
<b>Symptom:</b> SNMP traps are received even when the action for the maps rule is "none".	
<b>Condition:</b> This behavior is seen in all platforms with MAPS enabled ,when the action specified for maps rule is "NONE".	

<b>Defect ID:</b> DEFECT000560946	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Extension
<b>Reported In Release:</b> FOS7.1.0	<b>Technology:</b> Extended Fabrics
<b>Symptom:</b> When attempting to form an ISL over an extended fabric link through a third party DWDM, the link does not form.	
<b>Condition:</b> This may be encountered on an E-port connected to a third party DWDM.	
<b>Workaround:</b> Physically unplug the cable between the two DWDMs and plug it back in. The link should have fewer errors and come up after that.	

<b>Defect ID:</b> DEFECT000560963	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> FICON
<b>Symptom:</b> IFCCs reported on mainframe console when shutting down Teradata connections.	
<b>Condition:</b> When shutting down the Teradata processes on the mainframe when the Teradata subsystem is accessed via a 7840 FICON Teradata Emulation FCIP tunnel.	
<b>Workaround:</b> Disable FICON Teradata Emulation on the 7840 FCIP Tunnel.	

<b>Defect ID:</b> DEFECT000561049	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Security
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> Security Vulnerability
<b>Symptom:</b> Configuration key corresponds to crypto key length may have invalid value 40 or 56.	
<b>Condition:</b> Crypto key length 40 and 56 are invalid and the same has been removed in v7.2.1. This issue is observed when switch is running firmware lower to v7.2.1, user sets the crypto key length to invalid value 40 or 56 and upgrades the switch to firmware version v7.2.1 or above.	
<b>Workaround:</b> Set the crypto key length to valid value 128 prior to upgrade to firmware version v7.2.1 or above.	

<b>Defect ID:</b> DEFECT000561100	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> SNMP - Simple Network Management Protocol
<b>Symptom:</b> SNMP mibwalk of fcipExtendedLinkTable fails on BR7840.	
<b>Condition:</b> It occurs when a BR7840 is configured with Virtual Fabrics and have the GE ports in the default switch and the VE port in a separate VF.	

<b>Defect ID:</b> DEFECT000561174	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> APM - Advanced Performance Monitoring
<b>Symptom:</b> portperfshow display all zeros for some ports even when traffic is flowing.	
<b>Condition:</b> The issue happens when an internal 32bit counter wraps.	
<b>Recovery:</b> portdisable/portenable port to recover from the problem.	

<b>Defect ID:</b> DEFECT000561332	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Configuration Fundamentals
<b>Symptom:</b> FDMI Host Name parameter is added by reboot, then this parameter is removed by changing other parameters -- e.g. Domain ID.	
<b>Condition:</b> Run the 'configure' command to change another switch parameter, like Domain ID.	

<b>Defect ID:</b> DEFECT000561871	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Fibre Channel Services
<b>Symptom:</b> If the portEportCredits and portFportBuffers are set on a port, then doing a configdownload that does not include these 'keys' causes the ports to be set back to the default.	
<b>Condition:</b> It happens when download a configuration file with portEportCredits and portFportBuffers keys absent.	
<b>Workaround:</b> Don't remove port eportcredits and fportbuffers configuration from the configuration file.	
<b>Recovery:</b> Port can be reconfigured by using portEportCredits and portFportBuffers CLI.	

<b>Defect ID:</b> DEFECT000562107	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Configuration Fundamentals
<b>Symptom:</b> Iswitch queue full seen in one of the Backbone switches.	
<b>Condition:</b> This is seen when adding zones in a large edge fabric. It leads to iswitch queue full in one of the Backbone switches to which the large edge fabric connects to.	

<b>Defect ID:</b> DEFECT000562136	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> Fabric Watch
<b>Symptom:</b> fwportdetailshow shows incorrect values for SFP transmit(STX) and Receive power(SRX). When the threshold is crossed for SRX, the fwportdetailshow shows STX marked as "x"(threshold crossed) instead of SRX and vice versa	
<b>Condition:</b> This issue is observed whenever threshold for STX or SRX is crossed for any of the ports.	

<b>Defect ID:</b> DEFECT000562160	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Software Installation & Upgrade
<b>Symptom:</b> Unable to run support-save on embedded Brocade switch after a series of upgrade/downgrade/upgrade because there is not enough compact flash memory.	
<b>Condition:</b> This may be seen on 256MB or smaller flash capacity platforms, after performing upgrades / downgrades testing to various FOS versions.	
<b>Workaround:</b> Work with Brocade Support (with root permission) to remove stale files.	

<b>Defect ID:</b> DEFECT000562252	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Distance
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> FCIP - Fibre Channel over IP
<b>Symptom:</b> XTUN-1008 indicating that the FCP DP complex is almost 100% out of DRAM2 memory followed by an FFDC event (BLS-5024)	
<b>Condition:</b> When running a specific FICON Tape Read Job that primarily uses only data chained reads. FICON emulation never acquires a model for this type of chain but rather consumes a large amount of DRAM2 attempting to define the read channel program model.	
<b>Workaround:</b> Disable FICON Tape Read Pipelining on the FCIP Tunnel.	

<b>Defect ID:</b> DEFECT000562569	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> Management GUI
<b>Symptom:</b> Stale frame monitors in switch on unexpected closure of webtool.	
<b>Condition:</b> This issue is observed when user installs frame monitors via webtool and the same is getting closed unexpectedly or connection between webtool and switch is lost.	

<b>Defect ID:</b> DEFECT000562624	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> Software Installation & Upgrade
<b>Symptom:</b> During firmwaredownload the following message may be seen on the console: "Operation failed - port is already configured as F_Port buffers enabled ...".	
<b>Condition:</b> This issue is seen when upgrading from v7.1.x to v7.2.x with any port configured for F_port buffers and qos enabled without adaptive networking license.	
<b>Workaround:</b> Ignore the message. It is benign and does not interfere with the firmwaredownload itself.	
<b>Recovery:</b> Firmwaredownload completes successfully. No recovery is necessary.	

<b>Defect ID:</b> DEFECT000563176	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Buffer Credit Management
<b>Symptom:</b> On a switch where user had manually performed "creditrecovmode --cfg off", Link Reset will still occur upon detecting credit leak. A future hareboot could also cause traffic disruption.	
<b>Condition:</b> This occurs on fixed port switch running FOS7.3.1b only, where a CLI "creditrecovmode --cfg off" had been previously invoked.	

<b>Defect ID:</b> DEFECT000563219	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Other
<b>Reported In Release:</b> FOS7.2.0	<b>Technology:</b> Other
<b>Symptom:</b> configshow and route_info CLI commands may output different settings for the edgeHoldTime parameter (0 for configshow & 500 for route_info).	
<b>Condition:</b> This difference in the setting is observed in supportsave as well as through regular CLI command invocations.	

<b>Defect ID:</b> DEFECT000563299	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> Fibre Channel Services
<b>Symptom:</b> Switch performs hareboot due to OOM condition.	
<b>Condition:</b> This issue occurs rarely when collecting supportsave from BNA.	

<b>Defect ID:</b> DEFECT000563346	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> Software Installation & Upgrade
<b>Symptom:</b> Upgrade/downgrade to FOS v7.3.x may not proceed with message indicating "Unable to uninstall old packages".	
<b>Condition:</b> This may be seen if previously a firmwaredownload -sf was performed from v6.4.x to v7.1.x. This leaves a stale package bpimage-swbd36 on the system that subsequently results in the above failure. This may also be seen during a downgrade from v7.4.x due to a similar discrepancy for another rpm package.	
<b>Workaround:</b> Run the following command on the CP where the "firmwaredownload -s" is being invoked from: rm -rf /mnt/var/images/* If executing a full (non-disruptive) firmwaredownload to both CPs, then additionally run the same command on the standby CP as well.	

<b>Defect ID:</b> DEFECT000563416	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS8.0.0	<b>Technology:</b> FICON
<b>Symptom:</b> Observed Kernal panic (Unable to handle kernal paging request) during single Channel running Local Control Unit Port (CUP).	
<b>Condition:</b> This is encountered on a switch that is enabled for FICON (FMS-enabled). This occurs due to an attempt to de-reference IU memory that has already been previously freed up.	
<b>Recovery:</b> No recovery is necessary since the switch recovers itself after rebooting from the panic.	

<b>Defect ID:</b> DEFECT000563638	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Distance
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> FCIP - Fibre Channel over IP
<b>Symptom:</b> Observed FICON CHPID IFCCs and job failures.	
<b>Condition:</b> When FICON Tape Pipelining needs to handle an abnormal sequence such as Attention in REPOSITION_PENDING_STATE.	

<b>Defect ID:</b> DEFECT000564334	
<b>Technical Severity:</b> Low	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> MAPS - Monitoring and Alerting Policy Suite
<b>Symptom:</b> MAPS indicates the switch state is marginal if only one power supply unit is present on Brocade 6505.	
<b>Condition:</b> This is only applicable to Brocade 6505 switch.	
<b>Workaround:</b> This erroneous message may be ignored.	

<b>Defect ID:</b> DEFECT000564402	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Configuration Fundamentals
<b>Symptom:</b> Observed FFDC after switch hit a verify error: "VERIFY - Failed expression: pt < C2_NUM_PORTS".	
<b>Condition:</b> It happened on an 8G idle switch without other noticeable functional impact.	

<b>Defect ID:</b> DEFECT000564733	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS6.4.2	<b>Technology:</b> Management GUI
<b>Symptom:</b> Frame monitor statistics correspond to performance graphs that are installed via WebTool cannot be checked through CLI.	
<b>Condition:</b> This issue is seen when user installs performance graph from WebTool.	

<b>Defect ID:</b> DEFECT000565526	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Bottleneck Detection (legacy)
<b>Symptom:</b> Automatic credit recovery does not occur but AN-1010 alert is still generated, when all transmit credits of a VC are lost on the 16G side of a 16G to 8G/4G ISL connection. 16G to 16G ISL is less likely to see this symptom.	
<b>Condition:</b> Defect 525347 (fixed in FOS7.2.1d, 7.3.1 and 7.4.0) addressed an issue where FE credit recovery interrupt was disabled on 16G side of 16G-8G/4G ISL after a hafailover. However, upgrade from a release without the fix to a release with the fix does not correct the condition upon hot code load. A further blade power cycle or port disable/enabled is needed for the fix to be effective.  With defect 565526 fix, the fix will be effective upon code upgrade.	
<b>Recovery:</b> Either a port disable/enable, (or power cycle of the blade if running FOS with defect 525347) is required to re-enable credit recovery on FE port in a 16G to 8G/4G ISL connection.	

<b>Defect ID:</b> DEFECT000565552	
<b>Technical Severity:</b> Low	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> FICON
<b>Symptom:</b> FICUD core file after a null pointer encountered.	
<b>Condition:</b> It happened when system is low on memory and memory allocation failed during configuration database read.	

<b>Defect ID:</b> DEFECT000565623	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Management GUI
<b>Symptom:</b> Entries in name server tab in Web Tool won't be removed on switchdisable.	
<b>Condition:</b> This issue is seen when user runs switchdisable/chassisdisable on a switch.	

<b>Defect ID:</b> DEFECT000565660	
<b>Technical Severity:</b> Low	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.1	<b>Technology:</b> Configuration Fundamentals
<b>Symptom:</b> Changing configuration on management ports using the CLI command ipaddrset may lead to the user being logged out of the current ssh session.	
<b>Condition:</b> This issue is specific to the ipaddrset CLI command only.	

<b>Defect ID:</b> DEFECT000565716	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Hardware Monitoring
<b>Symptom:</b> Running portloopbacktest -lb_mode 1 with external loopback plugs in all the ports causes 6510 to reboot.	
<b>Condition:</b> This issue is seen only when running portloopbacktest -lb_mode 1 on 6510.	
<b>Workaround:</b> Running portloopbacktest -lb_mode 1 on individual or a small group of ports will run successfully.	

<b>Defect ID:</b> DEFECT000565991	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> MAPS - Monitoring and Alerting Policy Suite
<b>Symptom:</b> After running slotstatsclear;statsclear commands, invalid MAPS MAPS-1001 & MAPS 1003 alerts for DEV_LATENCY_IMPACT may be logged, sometimes very delayed from the time stats were cleared.	
<b>Condition:</b> It occurs if stats were cleared on switch.	

<b>Defect ID:</b> DEFECT000566341	
<b>Technical Severity:</b> Low	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> SNMP - Simple Network Management Protocol
<b>Symptom:</b> When attempting to get the operational status of the VE tunnel port using SNMP, a value of 4 is returned (which indicates unknown) instead of the actual status.	
<b>Condition:</b> This behavior is specific to BR7840 switches.	

<b>Defect ID:</b> DEFECT000566389	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Fabric Watch
<b>Symptom:</b> Severity of high CPU usage trap has discrepancies between event traps and FW traps -- Event Trap reports informational, whilst FW trap reports warning.	
<b>Condition:</b> This happens in all firmware versions and all platforms.	

<b>Defect ID:</b> DEFECT000566644	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.4.1	<b>Technology:</b> Buffer Credit Management
<b>Symptom:</b> User may not see the flow metric collected in the AMP. The flow might be dropped at the source switch connecting AMP, since the source switch has QoS mode disabled.	
<b>Condition:</b> When the QoS mode is disabled in source switch port connecting to AMP, this issue happens.	
<b>Workaround:</b> Ensure that native switch port will have QoS mode enabled all the time.	
<b>Recovery:</b> Disable the port and try after enabling the QoS mode on the native switch port.	

<b>Defect ID:</b> DEFECT000567029	
<b>Technical Severity:</b> Critical	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Fibre Channel Routing
<b>Symptom:</b> After code upgrade, communication stopped between 3rd party storage controllers connected to the FCR fabric.	
<b>Condition:</b> This is observed with device that does not register for FC4 type but trying to fetch devices using port symbolic name. It happens with FOS7.2.x and above.	
<b>Recovery:</b> Customer has to downgrade to recover. Bounce Ex/E/F port or even reboot switch does not recover from the situation.	



<b>Defect ID:</b> DEFECT000567055	
<b>Technical Severity:</b> Low	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Fabric Watch
<b>Symptom:</b> Fabric Watch alerts logged in all logical switches when the value crosses the default threshold configuration irrespective of whether a custom threshold value configured or not for chassis wide thresholds.	
<b>Condition:</b> Happens with VF enabled and having logical switches created.	

<b>Defect ID:</b> DEFECT000567083	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Other
<b>Reported In Release:</b> FOS7.4.1	<b>Technology:</b> Other
<b>Symptom:</b> Front end credit recovery is enabled by default, but after code upgrade, it is shown as disabled in CLI creditrecovmode, even though the feature itself is enabled.	
<b>Condition:</b> Code upgrade has been performed.	
<b>Workaround:</b> Run "creditrecovmode --fe_crdloss on" to correct the display issue.	

<b>Defect ID:</b> DEFECT000567099	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS8.0.1	<b>Technology:</b> Fibre Channel Services
<b>Symptom:</b> Software VERIFYs with pattern "lgdb->port[port_dst] == NULL" may be seen during HA failover.	
<b>Condition:</b> This issue does not occur under normal HA conditions. This may happen under rare error conditions during HA recovery and it does not affect the regular functionality of the switch.	

<b>Defect ID:</b> DEFECT000567288	
<b>Technical Severity:</b> Low	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS6.4.2	<b>Technology:</b> APM - Advanced Performance Monitoring
<b>Symptom:</b> Duplicate frame monitors are allowed to install from WebTool.	
<b>Condition:</b> This issue is seen when user inputs same LUN numbers but in different order for performance graphs in WebTool.	

<b>Defect ID:</b> DEFECT000567324	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Extension
<b>Reported In Release:</b> FOS8.0.1	<b>Technology:</b> WAN Performance Analysis Tools
<b>Symptom:</b> The WAN Tool session reports higher than expected round trip times.	
<b>Condition:</b> This occurs when the WAN Tool session is configured with jumbo frames and has a committed rate equal to the physical interface speed.	
<b>Workaround:</b> Reconfigure the WAN Tool session's committed rate to be less than the physical interface speed.	

<b>Defect ID:</b> DEFECT000567540	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS8.0.1	<b>Technology:</b> Configuration Fundamentals
<b>Symptom:</b> System may encounter Raslogs ERCP-1000, RAS-1000 during firmwaredownload. For example: "[ERCP-1000], 7, FFDC   CHASSIS, CRITICAL, Skybolt214, Multiple DDR ECC errors are detected and the system will reload automatically". followed by "[RAS-1001], 8, CHASSIS, INFO, Skybolt214, First failure data capture (FFDC) event occurred".	
<b>Condition:</b> This is seen only on Brocade 7840 switch following firmwaredownload.	

<b>Defect ID:</b> DEFECT000567733	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> MAPS - Monitoring and Alerting Policy Suite
<b>Symptom:</b> After an upgrade to Fabric OS v7.4.x, MAPS may stop working and HA Sync may be lose on a director switch.	
<b>Condition:</b> This is seen only after an upgrade to FOS version v7.4.x from FOS versions v7.3.x or lower under the following conditions: <ol style="list-style-type: none"> <li>1. Time base values in Fabric Watch are set to any value other than "none" for the FABRIC class.</li> <li>2. And these Fabric Watch thresholds are converted to MAPS rules using "mapsconfig --fwconvert" command before the FOS upgrade occurs.</li> </ol>	

<b>Defect ID:</b> DEFECT000567817	
<b>Technical Severity:</b> Critical	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.1.0	<b>Technology:</b> Configuration Fundamentals
<b>Symptom:</b> Upgrade fails on a chassis and Standby CP stays in a constant powering up state.	
<b>Condition:</b> This can occur when an ethernet cable is plugged into the console port, in place of the serial console cable.	

<b>Defect ID:</b> DEFECT000568003	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Security
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> TACACS & TACACS+
<b>Symptom:</b> Software 'verify' error detected messages in RASLOG RAS-1004 and RAS-1012 - comp:weblinker.	
<b>Condition:</b> This is applicable for all the platforms and it happens everytime when bulk number of user login requests are being processed very frequently by weblinker using TACACS authentication module.	
<b>Workaround:</b> Avoid bulk number of user authentications via TACACS simultaneously.	
<b>Recovery:</b> HAreboot	

<b>Defect ID:</b> DEFECT000568377	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Software Installation & Upgrade
<b>Symptom:</b> Firmwaresync fails due to timeout when standby CP is running FOS 7.2 or older and active CP is running FOS 7.4.	
<b>Condition:</b> Occurs when active CP is running FOS 7.4 and standby CP is running FOS 7.2 or older, and when switch cpu is busy with snmp, BNA polling.	
<b>Workaround:</b> Perform firmwaresync again after 10 minutes.	
<b>Recovery:</b> Times out after 10 minutes, then firmware sync should pass	

<b>Defect ID:</b> DEFECT000568423	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Distance
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> FCIP - Fibre Channel over IP
<b>Symptom:</b> Intermittent I/O Failures through an 7800/FX8024 or 7840 FCIP Tunnel due to processing an Extended Link Services PDISC (Discover N_Port Service Parameters) Request.	
<b>Condition:</b> When processing a received ELS-PDISC on a FCIP non-emulating Tunnel.	

<b>Defect ID:</b> DEFECT000568850	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Security
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> AD - Admin Domains
<b>Symptom:</b> Default users are unable to delete local users who have access to VF "0".	
<b>Condition:</b> This behavior is seen in all platforms in FOS version greater than FOS v6.x, when a default user try to delete a local user which was created in FOS v6.x with Vf "0".	

<b>Defect ID:</b> DEFECT000569563	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS8.0.0	<b>Technology:</b> Port Bring-up
<b>Symptom:</b> Ports negotiated to N16 G-Port rather than E-port.	
<b>Condition:</b> This is specific to 16G FEC port bring up with Lossless and Trunking. With Lossless, the slave port would be included in the trunk before it completes the link reset. Occasionally, if FEC is having problems to gain sync, the trunk logic is not properly cleaned-up and the subsequent port bring-up would fail.	
<b>Recovery:</b> Run portdisable and portenable to retry.	

<b>Defect ID:</b> DEFECT000569674	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> Fibre Channel Services
<b>Symptom:</b> HA out of sync due to invalid zone configuration.	
<b>Condition:</b> This issue is observed when a user tries to add a zone member with more than 64 characters to a zone configuration and then does cfgsave or cfgenable in a chassis.	

<b>Defect ID:</b> DEFECT000569678	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> Hardware Monitoring
<b>Symptom:</b> Software Fault:Kernel Panic - Detected multiple termination of process emd.	
<b>Condition:</b> This occurs when polling scripts send large amount of portshow commands to the emd process in a short burst of time.	
<b>Workaround:</b> Modify the scripts to space out such polling bursts over a larger period of time, use port range in portshow commands rather than back to back consecutive polls of individual ports.	

<b>Defect ID:</b> DEFECT000570370	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS8.0.0	<b>Technology:</b> Configuration Fundamentals
<b>Symptom:</b> First Failure Detection Capture (FFDC) might be seen after D-port test.	
<b>Condition:</b> FFDC seen after a D-port test is ran on BR7840 which may cause memory corruption. The symptoms might be seen much later after the D-port test. There is no impact to data frames.	

<b>Defect ID:</b> DEFECT000570535	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology:</b> Rate Limiting and Shaping
<b>Symptom:</b> Though -ap option in aptpolicy command is removed from 7.3, user is still allowed to execute the command.	
<b>Condition:</b> This behavior is seen with all the platforms where aptpolicy command is supported.	

<b>Defect ID:</b> DEFECT000570789	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Fibre Channel Addressing
<b>Symptom:</b> In Name server table the "WWN Company ID" column is not populated.	
<b>Condition:</b> When the target device is connected to the Switch.	

<b>Defect ID:</b> DEFECT000572039	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> D-Port - Diagnostic Port
<b>Symptom:</b> portloopbacktest failed with "error opening /dev/fdpci diaglb_genNfd2FsdErrno: can't find matched nfd error number -1"	
<b>Condition:</b> Occurs when running diag test on BR6546 running FOS7.3.1, 7.3.1a, b, c patches. Other platforms are not impacted.	

<b>Defect ID:</b> DEFECT000573237	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.3.2	<b>Technology:</b> Port Bring-up
<b>Symptom:</b> F-ports show as persistently disabled on BR5432 with FOS7.3.1a, FOS7.3.1b, FOS7.3.1c.	
<b>Condition:</b> This only occurs with FOS7.3.1a, FOS7.3.1b, FOS7.3.1c, triggered by an intermittent problem on internal Fports after communication error with chassis management module.	

<b>Defect ID:</b> DEFECT000573629	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.1	<b>Technology:</b> Configuration Fundamentals
<b>Symptom:</b> IP configuration from Chassis Management Module (SVP) will fail the first time after power-cycle.	
<b>Condition:</b> Issue may be seen on embedded platforms.	
<b>Recovery:</b> Re-do the IP configuration from SVP. It will succeed after the first failure.	

<b>Defect ID:</b> DEFECT000574013	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Software Installation & Upgrade
<b>Symptom:</b> firmwarecommit -f may be required to be run manually on the standby CP to recover from a firmwaredownload failure from firmwaredownload timeout.	
<b>Condition:</b> In a rare situation, following a dual CP firmwaredownload timeout, the expected recovery of the standby CP may fail due to ping failure triggered by race condition.	
<b>Workaround:</b> Manually invoke firmwarecommit on the standby CP where firmwaredownload timedout.	
<b>Recovery:</b> Manually invoke firmwarecommit on the standby CP where firmwaredownload timedout.	

<b>Defect ID:</b> DEFECT000574253	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.0.1	<b>Technology:</b> SNMP - Simple Network Management Protocol
<b>Symptom:</b> Inconsistent enc_out stats between portstatshow and SNMP may be encountered.	
<b>Condition:</b> This may occur under rare circumstance where top 32 bits of internal error counter is incremented.	
<b>Workaround:</b> Portstatshow readings are accurate. Ignore the discrepancy seen in SNMP.	

<b>Defect ID:</b> DEFECT000574562	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Port Bring-up
<b>Symptom:</b> Some F ports may be fenced with error message " FEC TTS is only supported on F_Port".	
<b>Condition:</b> This may be encountered when a CEC has a power on reset.	

<b>Defect ID:</b> DEFECT000574717	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS6.4.3	<b>Technology:</b> Fibre Channel Services
<b>Symptom:</b> Software panic occurs due to Out of Memory condition.	
<b>Condition:</b> This could happen only when Admin Domain (AD) is activated and the device in the fabric send GAPNL query about another device (either remote or local) which is not part of same AD.	
<b>Recovery:</b> Perform proactive hareboot/hafilover when free memory is low.	

<b>Defect ID:</b> DEFECT000574943	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Extension
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> FCIP - Fibre Channel over IP
<b>Symptom:</b> Host Discovery issues after FOS upgrade in an FCR backbone to edge configuration. Edge to edge configurations are not impacted.	
<b>Condition:</b> Problem can occur in a multiple VEX port configuration after FOS upgrade from pre-FOS 7.2.0 to newer FOS level. There needs to be more than 1 VEX port in the configuration.	

<b>Defect ID:</b> DEFECT000575054	
<b>Technical Severity:</b> Low	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> Configuration Fundamentals
<b>Symptom:</b> Configuring a host name longer than 31 characters causes blank host name and also can't update any further host name.	
<b>Condition:</b> Configuring a host name longer than 31 characters.	
<b>Recovery:</b> Ftp or scp /etc/hosts, edit manually and replace in switch (requires root access).	

<b>Defect ID:</b> DEFECT000575740	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> SNMP - Simple Network Management Protocol
<b>Symptom:</b> The traps sent for Link up/Link down events of management fc interfaces that starts with fc0 contain incorrect ifindex as varbind.	
<b>Condition:</b> This happens on all the platforms and all the versions of FOS.	

<b>Defect ID:</b> DEFECT000576282	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Fibre Channel Services
<b>Symptom:</b> Brocade switches hareboot due to Out of Memory (OOM) condition.	
<b>Condition:</b> This is seen only on Brocade non-director switches (except Brocade BES, 7800 and 7840) running FOS versions v7.2.1f, v7.3.1c or v7.4.1. This occurs due to OOM condition from a memory leak during the periodic polling of digital diagnostic monitoring capable SFPs. Directors are not impacted.	
<b>Workaround:</b> Monitor memory availability before performing any memory intensive operations such as supportsave and perform hareboot as necessary. The switch does attempt autorecovery via hareboot upon hitting a low memory threshold to recover from this condition without impacting traffic.	
<b>Recovery:</b> No explicit recovery is required as the switch attempts a non disruptive autorecovery from the memory loss, via hareboot, upon hitting a low memory threshold. However performing certain operations such as supportsave while the system is in low memory state may lead to this Out of Memory Panic of the switch and impact traffic.	

<b>Defect ID:</b> DEFECT000576355	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> CLI - Command Line Interface
<b>Symptom:</b> After answer "n" to "reboot" CLI, switch is left in disabled state.	
<b>Condition:</b> It happens on BR5481, "reboot" CLI cannot be cancelled.	
<b>Recovery:</b> Use switchenable to enable switch ports back.	

<b>Defect ID:</b> DEFECT000576404	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Security
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> Security Policies
<b>Symptom:</b> Passwddefault CLI command should be for use by root users only. It is currently permitted for admin user.	
<b>Condition:</b> This is encountered with passwddefault CLI command.	

<b>Defect ID:</b> DEFECT000576721	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Fibre Channel Services
<b>Symptom:</b> Kernel Panic with zoned termination after zoned exceeds max thread.	
<b>Condition:</b> It happens where scripting with CLI such as portzonesthrow without much delay in between or excessive queries for admin domain list from external management application.	
<b>Workaround:</b> Reduce excessive polling for any zone command through external application or scripting. Adding proper delays between CLIs can also avoid this issue.	

<b>Defect ID:</b> DEFECT000577864	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.0_CBN	<b>Technology:</b> NPIV - N-Port ID Virtualization
<b>Symptom:</b> Multiple N-Port failovers on AG switch cause LUNs to disappear.	
<b>Condition:</b> It happens when Fports come online while there is no N-port online in the Port Group/switch, AG disables the port due to no N-ports, and later, when an N-port comes on line, N-port failback brings Fports back online. If Fports send ABTS at this time to abort the previous login, login entries are cleared from the switch DB.	

<b>Defect ID:</b> DEFECT000578360	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Extension
<b>Reported In Release:</b> FOS7.4.1	<b>Technology:</b> FCIP - Fibre Channel over IP
<b>Symptom:</b> IPSec enabled extension tunnels on Brocade 7840 will not establish when utilizing VLAN tagged IP interfaces.	
<b>Condition:</b> This is encountered when the Brocade 7840 pair has an IPSec enabled extension tunnel utilizing a VLAN tagged IP interface.	
<b>Workaround:</b> Disable IPSec on the extension tunnel, or utilize an untagged IP interface.	

<b>Defect ID:</b> DEFECT000579212	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> Software Installation & Upgrade
<b>Symptom:</b> Firmware upgrade from v7.2.x to v7.3.x may fail with the following error message even though ficonmanualcascading is disabled: WARNING!!! Ficonmanualcasacding feature is enabled on the following FID(s):128.	
<b>Condition:</b> This is encountered only if firmwaredownload is executed by a user that does not have the privilege to run ficonmanualcascading command.	
<b>Workaround:</b> Invoke firmwaredownload from a user has permissions to run firmwaremanualcascading command.	
<b>Recovery:</b> Invoke firmwaredownload from a user has permissions to run firmwaremanualcascading command.	

<b>Defect ID:</b> DEFECT000580719	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.4.0_AMP	<b>Technology:</b> Fibre Channel Routing
<b>Symptom:</b> Adding AMP to fabric caused device to lose connectivity.	
<b>Condition:</b> After upgrade from FOS v7.3.x to v7.4.0x and FOSv7.4.1, with existing F/E port on an ASIC chip, enable AE port on the same chip may cause routing problems in the switch.	
<b>Recovery:</b> Reboot switch to recover.	

<b>Defect ID:</b> DEFECT000580863	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> ISL - Inter-Switch Linking
<b>Symptom:</b> After hafailover, hosts may lose paths to storage devices in the fabric.	
<b>Condition:</b> For this issue to occur, the following conditions must exist: 1. Hosts are connected to a logical switch that has enabled XISL. 2. Storage devices are reachable across a logical ISL -- i.e. the ISLs are in the base switch. 3. The trunk master of a base switch ISL trunk (with two or more trunked ports) bounces. 4. hafailover or hareboot occurs -- either manually or as part of non-disruptive firmwaredownload.	
<b>Recovery:</b> There are two possible recovery scenarios: 1. Bounce all trunk ports -- i.e. Bring all ports in the trunk offline and then bring them all back online. ...or... 2. hafailover.	

<b>Defect ID:</b> DEFECT000581283	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> FICON
<b>Symptom:</b> The switch may encounter a ficon cup daemon (ficud) panic after observing IDC Timeout messages.	
<b>Condition:</b> This is seen in FICON environment when response messages come in at the same time as an outgoing directory diagnostics message.	

<b>Defect ID:</b> DEFECT000581627	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.2.1	<b>Technology:</b> Hardware Monitoring
<b>Symptom:</b> Switch may encounter false alarms for failed blowers and high temperatures, leading to an attempt to initiate switch shutdown.	
<b>Condition:</b> This may occur if ports with No_Modules (vacant ports) are periodically polled using sfpshow <port#> -f via external script or CLI. This external polling may clash with the periodic internal EM polls and result in misreadings from the blowers.	
<b>Workaround:</b> If possible avoid periodic external polling that uses CLI command sfpshow <port #> -f. Otherwise insert good SFPs in vacant ports.	
<b>Recovery:</b> Insert good SFPs in vacant ports and/or stop any external SFP polling script (that uses sfpshow <port#> -f) and then re-seat the failed blowers or reboot the switch.	

<b>Defect ID:</b> DEFECT000582539	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Traffic Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Fibre Channel Routing
<b>Symptom:</b> After a link reset on an inter fabric link (IFL) or the trunk master of an IFL trunk on a Fibre Channel Router (FCR) switch, traffic through the IFL or IFL trunk is halted.	
<b>Condition:</b> An hareboot or hafailover on a 8G FCR switch, followed by a link reset on an IFL or an IFL trunk master, then traffic can no longer flow through the IFL. If a fabric only has devices with proxy IDs that have Domain ID of 3 or every fourth ID after that (Ex: 3, 7, 11, 15, etc.), then the fabric is not impacted.  16G FCR switches are not impacted.	
<b>Recovery:</b> portdisable/portenable IFL or the full IFL trunk.	

<b>Defect ID:</b> DEFECT000584234	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.4.1	<b>Technology:</b> Analytics Monitoring
<b>Symptom:</b> Switch may report raslog MAPS-1003 alert, indicating greater than expected IOPs per second even though the IOP rate is below threshold.	
<b>Condition:</b> This condition may occur if the single ASIC is overloaded with traffic and AE port is on the same ASIC.	



<b>Defect ID:</b> DEFECT000584796	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Extension
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> FCIP - Fibre Channel over IP
<b>Symptom:</b> Extension tunnels on the 7840 may go down and stay in an “in-progress” state.	
<b>Condition:</b> This condition can occur on an extension tunnel whose IP addresses receive an extremely large amount of ICMP messages other than Echo Request(type 8), Echo Reply(type 0), or Time Exceeded(type 11).	
<b>Recovery:</b> A reboot is necessary to clear this condition.	

<b>Defect ID:</b> DEFECT000585430	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.4.1	<b>Technology:</b> High Availability
<b>Symptom:</b> Switch may report HA not in sync, along with raslog FSS-1009 2016/01/22-10:05:25, [FSS-1009], ,   FFDC   , ERROR, , FSS Error: fcs3-sw3: sync-failure: -6	
<b>Condition:</b> This may happen during device offline event on a busy system.	
<b>Recovery:</b> Reboot standby CP.	

<b>Defect ID:</b> DEFECT000585776	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Extension
<b>Reported In Release:</b> FOS8.0.1	<b>Technology:</b> FCIP Tunnel Management
<b>Symptom:</b> ESM-1101 error message seen with 'Unable to allocate memory' condition. Can also sometimes result in a esmd panic.	
<b>Condition:</b> Issuing 'portcfgshow ipflproutelfcipcircuit' or other extension related 'portcfgshow' commands can cause the error.	

<b>Defect ID:</b> DEFECT000586788	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> RAS - Reliability, Availability, and Serviceability
<b>Symptom:</b> Switch may encounter "Software Fault"/"Kernel Panic" triggered by too many memory parity interrupts from the 16G ASIC encryption block.	
<b>Condition:</b> Memory parity errors are rare. This panic may occur on a 16G switch, if memory parity errors are encountered when ASIC encryption is not enabled.	
<b>Recovery:</b> Usually recovers after a panic. If it persists, please replace blade.	

## Closed with Code Change in Fabric OS v7.3.1d

This section lists the defects with Critical, High and Medium Technical Severity closed with a code change as of November 12, 2015 in Fabric OS v7.3.1d.

<b>Defect ID:</b> DEFECT000567733	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Monitoring
<b>Reported In Release:</b> FOS7.4.0	<b>Technology:</b> MAPS - Monitoring and Alerting Policy Suite
<b>Symptom:</b> After an upgrade to Fabric OS v7.4.x, MAPS may stop working. And on a Brocade director switch, HA Sync may be lost .	
<b>Condition:</b> The issue is seen only after an upgrade to FOS version v7.4.x from FOS versions v7.3.x or lower under the following conditions: <ol style="list-style-type: none"> <li>1. Time base values in Fabric Watch are set to any value other than "none" for the FABRIC class.</li> <li>2. And these Fabric Watch thresholds are converted to MAPS rules using "mapsconfig --fwconvert" command before the FOS upgrade occurs.</li> </ol>	

<b>Defect ID:</b> DEFECT000576282	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> Brocade Fabric OS	<b>Technology Group:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology:</b> Fibre Channel Services
<b>Symptom:</b> Brocade switches hareboot due to Out of Memory (OOM) condition.	
<b>Condition:</b> This is seen only on Brocade non-director switches (except Brocade BES and 7840) running FOS versions v7.2.1f, v7.3.1c or v7.4.1. This occurs due to OOM condition from a memory leak during the periodic polling of digital diagnostic monitoring capable SFPs. Directors are not impacted.	
<b>Workaround:</b> Monitor memory availability before performing any memory intensive operations such as supportsave and perform hareboot as necessary. The switch does attempt autorecovery via hareboot upon hitting a low memory threshold to recover from this condition without impacting traffic.	
<b>Recovery:</b> No explicit recovery is required as the switch attempts a non disruptive autorecovery from the memory loss, via hareboot, upon hitting a low memory threshold. However performing certain operations such as supportsave while the system is in low memory state may lead to this Out of Memory Panic of the switch and impact traffic.	

## Closed with Code Change in Fabric OS v7.3.1c

This section lists the defects with Critical, High and Medium Technical Severity closed with a code change as of August 17, 2015 in Fabric OS v7.3.1c.

<b>Defect ID:</b> DEFECT000530663	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Virtualization
<b>Reported In Release:</b> FOS7.2.1	<b>Technology Area:</b> Access Gateway
<b>Symptom:</b> A device connected through Access Gateway cannot login into the switch.	
<b>Condition:</b> This issue will be seen only when the device sends a class 2 FLOGI and the edge switch does not support the class 2 frames.	

<b>Defect ID:</b> DEFECT000535808	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> Monitoring and Alerting Policy Suite (MAPS)
<b>Symptom:</b> After firmwaredownload to FOS v7.3.0c, taking Supportsave causes mdd termination. The issue persists even after reboot of the switch.	
<b>Condition:</b> Race condition during BNA polling of switch status policy	
<b>Workaround:</b> Avoid BNA polling	

<b>Defect ID:</b> DEFECT000541653	
<b>Technical Severity:</b> Low	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.0.0	<b>Technology Area:</b> Web Tools
<b>Symptom:</b> Unsupported thconfig security areas showed up in Webtools	
<b>Condition:</b> When using Webtools to configure thconfig security areas.	
<b>Workaround:</b> Use CLI	

<b>Defect ID:</b> DEFECT000542334	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> System
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> Component
<b>Symptom:</b> 7840 switch runs out of Control Processor file system disk space.	
<b>Condition:</b> This is seen when there are old trace files and corefiles left in /var/log or /mnt/var/log directory.	
<b>Workaround:</b> Use CLI "rm" to remove /var/log/core.* /mnt/var/log/core.*	

<b>Defect ID:</b> DEFECT000548512	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.3.0_HUR	<b>Technology Area:</b> Platform Services
<b>Symptom:</b> Switch experienced panic during system verification test and disabling switch during D-port test.	
<b>Condition:</b> This is seen in a race condition when diag test reset asic while asic is being accessed in parallel.	

<b>Defect ID:</b> DEFECT000550377	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> Monitoring and Alerting Policy Suite (MAPS)
<b>Symptom:</b> MAPS daemon may get terminated. If it is terminated multiple times in a short period of time, the switch may lose HA synchronization.	
<b>Condition:</b> The problem can happen when configdownload, mapspolicy command is run, or when a switch is polled for MAPS data before MAPS daemon has finished initialization.	
<b>Recovery:</b> When MAPS gets restarted, the system should work fine. If daemon restart fails and causes switch to get out of HA synchronization, a cold boot is needed to recover HA.	

<b>Defect ID:</b> DEFECT000550874	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology Area:</b> Platform Services
<b>Symptom:</b> With 16Gbps FC cards from a specific vendor connected to Brocade 6546, OS Boot failures occur at a high probability and the attached port on BR6546 becomes a G-Port.	
<b>Condition:</b> This may be encountered with HBAs from a specific vendor on a BR6546 platform.	

<b>Defect ID:</b> DEFECT000552552	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Traffic Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology Area:</b> Port Bring-up
<b>Symptom:</b> Speed will show higher (in switchshow) than actual SFP speed. For instance, 8G SFP will negotiate to 16G speed though SFP is not capable of 16G speed.	
<b>Condition:</b> This occurs when remote 16G capable port generates Loss of Signal (light cut-off and on) by cable plug-out/in after switch performed HA-failover.	
<b>Workaround:</b> Use 16G SFP on 16G port blade	
<b>Recovery:</b> Use CLI portdisable/portenable to recover the affected port. But the problem can reoccur if there is a subsequent hafailover on the switch and the remote 16G port cuts light again.	

<b>Defect ID:</b> DEFECT000555831	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> Brocade Network Advisor
<b>Symptom:</b> Memory leak caused weblinker to crash and restart	
<b>Condition:</b> Various operations such as configupload operation from BNA and LDAP authentication caused memory issue with weblinker.	
<b>Workaround:</b> Perform configupload via CLI. Avoid frequent configupload/stats from BNA	

<b>Defect ID:</b> DEFECT000558507	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Distance
<b>Reported In Release:</b> FOS7.2.0	<b>Technology Area:</b> FCIP
<b>Symptom:</b> FX8-24 DP Soft Faults due to SE Core Panic after [FICN-1056] FICON Emulation Error Error Code=7,	
<b>Condition:</b> Error case when XRC update traffic is running over FCIP XRC Emulation enabled tunnel.	
<b>Workaround:</b> Disable FICON XRC emulation on the FCIP Tunnel.	

<b>Defect ID:</b> DEFECT000560375	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> System
<b>Reported In Release:</b> FOS7.2.1	<b>Technology Area:</b> Component
<b>Symptom:</b> Faulty power supply may lead to Raslog HIL-1611 (MISMATCH in PSU-FAN Air Flow direction.) resulting in system shutdown in 2 minutes	
<b>Condition:</b> This is triggered by a faulty power supply causing read failures in power supply fan sensors.	
<b>Recovery:</b> Replace the faulty power supply to recover.	

<b>Defect ID:</b> DEFECT000560946	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Distance
<b>Reported In Release:</b> FOS7.1.0	<b>Technology Area:</b> Extended Fabrics
<b>Symptom:</b> When attempting to form an ISL over an extended fabric link through a third party DWDM, the link does not form.	
<b>Condition:</b> This may be encountered on an E-port connected to a third party DWDM.	
<b>Workaround:</b> Physically unplug the cable between the two DWDMs and plug it back in. The link should have fewer errors and come up after that.	

<b>Defect ID:</b> DEFECT000560963	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> FICON
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> FICON emulation
<b>Symptom:</b> IFCCs reported on mainframe console when shutting down Teradata connections.	
<b>Condition:</b> When shutting down the Teradata processes on the mainframe when the Teradata subsystem is accessed via a 7840 FICON Teradata Emulation FCIP tunnel.	
<b>Workaround:</b> Disable FICON Teradata Emulation on the 7840 FCIP Tunnel.	

<b>Defect ID:</b> DEFECT000561100	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology Area:</b> SNMPv2, SNMPv3 & MIBs
<b>Symptom:</b> SNMP mibwalk of fcipExtendedLinkTable fails on BR7840.	
<b>Condition:</b> It occurs when a BR7840 is configured with Virtual Fabrics and have the GE ports in the default switch and the VE port in a separate VF.	

<b>Defect ID:</b> DEFECT000562107	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> System
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> Component
<b>Symptom:</b> iswitch queue full seen in one of the Backbone switches	
<b>Condition:</b> This is seen when adding zones in a large edge fabric. It leads to iswitch queue full in one of the Backbone switches to which the large edge fabric connects to.	

<b>Defect ID:</b> DEFECT000562252	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Distance
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> FCIP
<b>Symptom:</b> XTUN-1008 indicating that the FCP DP complex is almost 100% out of DRAM2 memory followed by an FFDC event (BLS-5024)	
<b>Condition:</b> When running a specific FICON Tape Read Job that primarily uses only data chained reads. FICON emulation never acquires a model for this type of chain but rather consumes a large amount of DRAM2 attempting to define the read channel program model.	
<b>Workaround:</b> Disable FICON Tape Read Pipelining on the FCIP Tunnel.	

<b>Defect ID:</b> DEFECT000563176	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Traffic Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology Area:</b> Buffer Credit Recovery
<b>Symptom:</b> On a switch where user had manually performed “creditrecovmode --cfg off”, Link Reset will still occur upon detecting credit leak. A future hareboot could also cause traffic disruption.	
<b>Condition:</b> This occurs on fixed port switch running FOS7.3.1b only, where a CLI “creditrecovmode --cfg off” had been previously invoked.	

<b>Defect ID:</b> DEFECT000565526	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> Bottleneck Detection
<b>Symptom:</b> Automatic credit recovery does not occur but AN-1010 alert is still generated, when all transmit credits of a VC are lost on the 16G side of a 16G to 8G/4G ISL connection. 16G to 16G ISL is less likely to see this symptom.	
<b>Condition:</b> Defect 525347 (fixed in FOS7.2.1d, 7.3.1 and 7.4.0) addressed an issue where FE credit recovery interrupt was disabled on 16G side of 16G-8G/4G ISL after a hafailover. However, upgrade from a release without the fix to a release with the fix does not correct the condition upon hot code load. A further blade power cycle or port disable/enabled is needed for the fix to be effective.  With defect 565526 fix, the fix will be effective upon code upgrade.	
<b>Recovery:</b> Either a port disable/enable, (or power cycle of the blade if running FOS with defect 525347) is required to re-enable credit recovery on FE port in a 16G to 8G/4G ISL connection.	

## Closed with Code Change in Fabric OS v7.3.1b

This section lists the defects with Critical, High and Medium Technical Severity closed with a code change as of July 25, 2015 in Fabric OS v7.3.1b

<b>Defect ID:</b> DEFECT000494952	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.2.0_fuj	<b>Technology Area:</b> Web Tools
<b>Symptom:</b> In Webtools fabric watch explorer, F/FL copper Port class is missing.	
<b>Condition:</b> On embedded switch where internal ports 1 - 16 are copper ports.	

<b>Defect ID:</b> DEFECT000499559	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> System
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> Component
<b>Symptom:</b> Current diag reset sequence for Brocade 6510 does not work well on all units. It results in switch going faulty when diags are enabled.	
<b>Condition:</b> This does not happen under normal circumstances. This is seen on some of the Brocade 6510 units where continuous reboot is encountered with diagpost enabled.	

<b>Defect ID:</b> DEFECT000520333	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> FICON
<b>Reported In Release:</b> FOS7.2.0	<b>Technology Area:</b> FICON CUP
<b>Symptom:</b> CUP remained quiescent after firmware upgrade.	
<b>Condition:</b> It happens in a timing condition when the firmware download completion notification is missed by CUP.	

<b>Defect ID:</b> DEFECT000521204	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> System
<b>Reported In Release:</b> FOS6.4.3	<b>Technology Area:</b> Component
<b>Symptom:</b> During hafailover, customer encountered a switch panic.	
<b>Condition:</b> This was encountered during a rare PCI write failure to an ASIC chip. An invalid DMA descriptor was accessed without validation check.	
<b>Recovery:</b> Replace the faulty port blade.	

<b>Defect ID:</b> DEFECT000525413	
<b>Technical Severity:</b> Low	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Distance
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> FCIP
<b>Symptom:</b> The 'portcfgge <port> --show' command and 'portshow autoneg <port>' command do not show the valid output for 7800/FX8-24. It will report 'No GE configuration entries found' instead of reporting the actual data.	
<b>Condition:</b> This will occur every time the 'portcfgge <port> --show' and 'portshow autoneg <port>' commands are issued.	

<b>Defect ID:</b> DEFECT000528891	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Traffic Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> FC-FC routing
<b>Symptom:</b> Observed "queue iswitch: queue full" or iswitchd termination during stress test.	
<b>Condition:</b> This may be encountered in a FCR environment, during an overnight test run with FCR zone change, device change, and Fabric-ID change test cases.	

<b>Defect ID:</b> DEFECT000531192	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> FICON
<b>Reported In Release:</b> FOS7.2.0	<b>Technology Area:</b> FICON CUP
<b>Symptom:</b> During firmware upgrade, hosts lost paths due to FICON filter that was not properly cleaned up.	
<b>Condition:</b> On a FMS CUP enabled switch, if trunk master goes offline first, after hafailover FICON CUP filter is not properly removed.	
<b>Recovery:</b> Bounce trunk ports	

<b>Defect ID:</b> DEFECT000532726	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> Web Tools
<b>Symptom:</b> WebTools will not launch with Java 8 update 40.	
<b>Condition:</b> When Admin Domain is enabled in the switch.	
<b>Workaround:</b> If supported, enable virtual fabric.	

<b>Defect ID:</b> DEFECT000534141	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Traffic Management
<b>Reported In Release:</b> FOS7.3.0_HUR	<b>Technology Area:</b> Port Bring-up
<b>Symptom:</b> BR6543 switch takes very long time for the internal link to come online.	
<b>Condition:</b> This problem can be observed by disabling/enabling the port using portdisable/portenable CLI.	

<b>Defect ID:</b> DEFECT000534151	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> System
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> CLI
<b>Symptom:</b> Configdownload -vf fails with message "VF config file version is not compatible with the switch firmware version. Invalid header in config file.	
<b>Condition:</b> this is encountered when running the CLI command configdownload -vf	
<b>Recovery:</b> Rebuild VF config on switch.	

<b>Defect ID:</b> DEFECT000537108	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Traffic Management
<b>Reported In Release:</b> FOS6.4.3	<b>Technology Area:</b> Credit Loss
<b>Symptom:</b> Standby CP reboots due to software assert during a hafailover.	
<b>Condition:</b> If back-end credit recovery is enabled with Link Reset only option via CLI, creditrecovmode and credit recovery algorithms kick in. During that window if either core or edge blade goes offline, this can sometimes cause the standby CP to panic during a subsequent hafailover.	



<b>Defect ID:</b> DEFECT000537311	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Distance
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> FCIP
<b>Symptom:</b> Switchshow shows no ports found in the system.	
<b>Condition:</b> Run switchshow command.	

<b>Defect ID:</b> DEFECT000538046	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> System
<b>Reported In Release:</b> FOS7.1.1	<b>Technology Area:</b> Component
<b>Symptom:</b> Fabric Watch terminates in a busy system causing switch reboot.	
<b>Condition:</b> This is a very rare occurrence that may be encountered on systems that are very busy.	

<b>Defect ID:</b> DEFECT000538917	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> Management Server
<b>Symptom:</b> The Fibre Channel specification (FC-FS-3) pertaining to Read Diagnostic Parameters (RDP) has been updated with new descriptor codes and descriptor flags. This renders current implementation incompatible. Device will not get properly formatted RDP response.	
<b>Condition:</b> This happens in a fabric with device capable of RDP and running FOS v7.3.0 or above.	
<b>Workaround:</b> Disable device port capable of RDP	

<b>Defect ID:</b> DEFECT000539584	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> System
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> Optics
<b>Symptom:</b> 2KM QSFP ICL ports may see link errors such as CRC and FEC errors. The link errors may result in credit or frame loss and trigger link reset.	
<b>Condition:</b> Errors may be seen after any conditions that causes the port to be toggled, such as a portdisable or switchdisable.	
<b>Recovery:</b> Clear the stats. Toggle the port and check for link errors.	

<b>Defect ID:</b> DEFECT000540720	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> Equipment Status
<b>Symptom:</b> Even though the portpeerbeacon CLI does succeed and correctly lights up the LED on both end ports, a trace shows the 'Beacon on" sub-command is in the wrong format.	
<b>Condition:</b> When user executes portpeerbeacon CLI.	

<b>Defect ID:</b> DEFECT000540971	
<b>Technical Severity:</b> Low	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.2.1	<b>Technology Area:</b> Monitoring and Alerting Policy Suite (MAPS)
<b>Symptom:</b> In extreme conditions MAPS generates false alert for port errors such as LR etc.	
<b>Condition:</b> This false alert could be generated during state change of port and this happen in extreme conditions.	

<b>Defect ID:</b> DEFECT000542388	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Virtualization
<b>Reported In Release:</b> FOS7.1.1	<b>Technology Area:</b> Access Gateway
<b>Symptom:</b> Even though there are no mappings being shown in ag -mapshow for some ports, available F-ports cannot be mapped to existing N-ports. All F-ports are reported to be mapped to a non-existent N-port, and do not show up in ag -mapshow.	
<b>Condition:</b> Inconsistent config file is downloaded to the switch with configdownload. The inconsistency entails one of the following: - F-to-N-port mapping for F-Ports, or - No port config, but F-to-N-port mapping exists.	
<b>Recovery:</b> Configure all non-used ports (ports that are not N-port and not F-port) as N-port and then remove that configuration. In rare cases, even the F-ports may need to be temporarily configured as N-ports and then remove the configuration.	

<b>Defect ID:</b> DEFECT000542630	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Virtualization
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> Access Gateway
<b>Symptom:</b> In AG setup, fdmid daemon has memory leak after overnight I/O	
<b>Condition:</b> This is encountered in an AG setup following overnight I/O stress, resulting from memory allocated for nportInfo in fdmi query not being freed.	
<b>Recovery:</b> invoke hafailover/hareboot to free up the memory	

<b>Defect ID:</b> DEFECT000542770	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Traffic Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> Port Bring-up
<b>Symptom:</b> Port 60 on BR6520 cannot come online.	
<b>Condition:</b> This seems to happen with FOSv7.3.1 and later code.	
<b>Workaround:</b> Use a different port.	

<b>Defect ID:</b> DEFECT000542995	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Virtualization
<b>Reported In Release:</b> FOS7.2.1	<b>Technology Area:</b> Access Gateway
<b>Symptom:</b> Customer encounters a panic when enabling access gateway through webtools and then running commands through the CLI subsequently.	
<b>Condition:</b> Enable AG mode in the switch through webtools.	
<b>Recovery:</b> Auto-recovery after panic dump.	

<b>Defect ID:</b> DEFECT000543734	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Traffic Management
<b>Reported In Release:</b> FOS7.2.1	<b>Technology Area:</b> Name Server
<b>Symptom:</b> DCX CP reboots after a port blade going to faulty state.	
<b>Condition:</b> This happened when NPIV devices falsely detected duplicate PWWN as a result of path failover upon detect faulty blade. It could also happen if a device connected to a port blade which goes faulty and moving the device to other port blades in chassis without powering down the faulty blade.	

<b>Defect ID:</b> DEFECT000543921	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Security
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> Security Vulnerability
<b>Symptom:</b> CVE-2014-3570: Bignum squaring (BN_sqr) may produce incorrect results	
<b>Condition:</b> This bug occurs at random with a very low probability, and is not known to be exploitable in any way, though its exact impact is difficult to determine. Straightforward bug attacks fail - either the attacker cannot control when the bug triggers, or no private key material is involved.	

<b>Defect ID:</b> DEFECT000544160	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Security
<b>Reported In Release:</b> FOS7.2.1	<b>Technology Area:</b> Encryption
<b>Symptom:</b> After FS8-18 or BES was powered up, several LUNs were inaccessible. The LUN state was "LUN setup".	
<b>Condition:</b> After firmware download or power event, BES re-establish nexus for each Container-Host pair. It's not properly clean up and retry timed-out internal request.	
<b>Recovery:</b> Bounce affected port.	

<b>Defect ID:</b> DEFECT000545217	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> Web Tools
<b>Symptom:</b> End to End (EE) monitor is not supported in base switch, yet, when configuring it, improper message pops up such as: 1). "The SID is not associated with any devices. Do you still want to use this SID?" 2). "The DID is not associated with any devices. Do you still want to use this DID?" Rather than just error out with : "EE monitor not supported on base switch".	
<b>Condition:</b> It occurs when configuring EE monitor(SID/DID performance graph through WEBTools in base switch.	
<b>Workaround:</b> Use CLI.	

<b>Defect ID:</b> DEFECT000545930	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Virtualization
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> Access Gateway
<b>Symptom:</b> Failover policy on AG gets disabled after fastboot action	
<b>Condition:</b> This is seen on AG switch with failover policy defined having unused port	
<b>Workaround:</b> Configure all unused ports as N-ports (portcfgnport <port> 1) and then remove the N-port configuration from those ports (portcfgnport <port> 0).	

<b>Defect ID:</b> DEFECT000546941	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Distance
<b>Reported In Release:</b> FOS7.2.0	<b>Technology Area:</b> FCIP Fastwrite
<b>Symptom:</b> XTUN-1001 and XTUN-1008 RASLOG messages generated and failed FCIP Fast Write or Tape Pipelined I/O operations.	
<b>Condition:</b> When there are multiple logical switches each with an emulation feature enabled FCIP Tunnel (Fast Write and/or OSTP). If one of the Fast Write or OSTP configurations include a large number of discovered FCIP objects (ITNs and ITLs), the FCIP emulation memory manager may incorrectly allocate and cache too many I/O structures leading to out of memory conditions in any one of the different FCIP Tunnel logical switch configurations.	

<b>Defect ID:</b> DEFECT000547765	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Traffic Management
<b>Reported In Release:</b> FOS7.0.2	<b>Technology Area:</b> BB Credits
<b>Symptom:</b> Link reset events encountered on internal back-end (BE) port trunks while there are no link errors or credits lost.	
<b>Condition:</b> Under conditions of heavy congestion that cause frames to be dropped at internal Back-End ports and Front-End E-ports at the same time. If multiple overlapping frame drops are detected, then a Link Reset may be observed on a link even though no credits were actually lost. This defect only affects 8G Platforms.	
<b>Workaround:</b> Disable Front-End E-ports credit recovery.	
<b>Recovery:</b> Remove the source of congestion that is causing frame drops.	

<b>Defect ID:</b> DEFECT000547921	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Virtualization
<b>Reported In Release:</b> FOS7.3.1	<b>Technology Area:</b> Access Gateway
<b>Symptom:</b> In an AG fabric or NPIV environment, device is not found or HBA detects SCSI command timeout and fabric switch stops routing AG switch/NPIV device traffic.	
<b>Condition:</b> This may occur when fabric switch is configured for session based zoning and a device connected to AG switch or an NPIV device, that is not in any zone database, is enabled. This causes all traffic going through the same fabric switch F-port to be disrupted. This issue only impacts 16G fabric switch running FOSv7.4.0, FOSv7.3.1 and FOSv7.2.1d	
<b>Workaround:</b> Use hard zoning on fabric switch, or add the device into zoning database first before bringing it online.	
<b>Recovery:</b> Upon hitting this issue, the user may bring up ANY zoned member on AG switch or NPIV, that is using the fabric switch F-Port, to recover.	

<b>Defect ID:</b> DEFECT000548463	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Traffic Management
<b>Reported In Release:</b> FOS7.1.1	<b>Technology Area:</b> Port Bring-up
<b>Symptom:</b> Kernel panic encountered on a CP while taking over the Active Role, due to heartbeat loss, causing a cold recovery of the system.	
<b>Condition:</b> This may be encountered only when processing FDISC with duplicate PWWNs.	

<b>Defect ID:</b> DEFECT000548713	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Distance
<b>Reported In Release:</b> FOS7.2.0	<b>Technology Area:</b> FCIP
<b>Symptom:</b> Disk to disk mirroring application failures with associated XTUN-1001 RASLOG messages.	
<b>Condition:</b> When a specific Disk to Disk mirroring application encounters IO errors over a 7800 or FX8-24 FCIP Tunnel, it will issue an odd sequence of Extended Link Services commands (concurrent LOGO/LOGO and PLOGI sequences). The problem can be encountered if the FCIP Tunnel has OSTP and/or Fast Write enabled and there are still active FCP commands flowing when the ELS sequences are processed.	
<b>Recovery:</b> Reboot 7800 platform or slotpoweroff/slotpoweron the FX8-24 blade.	

<b>Defect ID:</b> DEFECT000548721	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS6.4.3	<b>Technology Area:</b> Fabric Watch
<b>Symptom:</b> E-port is fenced even after port fencing has been disabled.	
<b>Condition:</b> This issue would only happen if E-port and port classes are configured with the same thresholds for ST area. Disabling port fencing does not handle properly E-ports that have been fenced earlier under this condition.	
<b>Workaround:</b> Use the E-Port only threshold to monitor the State change of ISLs, or to monitor all the ports in general, choose different threshold values for E-port thresholds and port class thresholds (probably E-Port threshold + 5 ).	
<b>Recovery:</b> Bounce the port.	

<b>Defect ID:</b> DEFECT000550167	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.3.1	<b>Technology Area:</b> Fabric Watch
<b>Symptom:</b> porthconfig --show CLI doesnt show ST area configuration (either default or custom) for port class.	
<b>Condition:</b> All platforms exhibit this behavior with FOS 7.3.1 version and above	

<b>Defect ID:</b> DEFECT000550514	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> System
<b>Reported In Release:</b> FOS7.2.1	<b>Technology Area:</b> CLI
<b>Symptom:</b> Creditrecovmode --check fails between core blade and FX8-24 blade creditrecovmode --check 5/108,30 Error: Not Supported on this link.	
<b>Condition:</b> Error: Not Supported on this link is seen if an AP blade has ever had a VE port enabled without a reboot, manual credit recovery CLI "creditrecovmode" occurring. This is seen even if the VE port is currently disabled.	
<b>Recovery:</b> After rebooting the switch, the "creditrecovmode --check" will work on non-VE port AP blade.	

<b>Defect ID:</b> DEFECT000550684	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> Platform Services
<b>Symptom:</b> When an embedded switch configured in Access Gateway mode is connected to a 3rd party fibre channel switch, the Brocade embedded switch has a software assert error and reboots. [KSWD-1002], 18/14, FFDC   CHASSIS, WARNING, 5, Detected termination of process fdmid0:1226., hasm_swd.c.	
<b>Condition:</b> Error occurs during FDMI request response process with following embedded platforms: BR6547, 6548, M5424, M6505 running FOSv7.3.0 and higher. The error does not occur with v7.2.x.	

<b>Defect ID:</b> DEFECT000550923	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> System
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> CLI
<b>Symptom:</b> 3rd party application queries with an alias name that doesn't require padding often fail with an error code 0x9.	
<b>Condition:</b> This occurs when an user application tries to get zoning alias name information from switch.	
<b>Workaround:</b> Recommend that User application add 4 byte pad to the word-align alias name query	

<b>Defect ID:</b> DEFECT000551520	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Distance
<b>Reported In Release:</b> FOS7.2.0	<b>Technology Area:</b> WAN Performance Analysis Tools
<b>Symptom:</b> Brocade NMS monitoring services are unable to do snmpwalk of fcipExtendedLinkTable to collect statistical data.	
<b>Condition:</b> When a 7800 or FX8-24 blade is configure with Virtual Fabrics and have the GE ports in the default switch and the VE port in a separate VF the fcipExtendedLinkTable fails.  If the GE ports and VE port are in the same VF the snmpwalk will work without problems.	

<b>Defect ID:</b> DEFECT000551531	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Security
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> Security Vulnerability
<b>Symptom:</b> OpenSSL Security Advisory [19 Mar 2015]: CVE-2015-0286, CVE-2015-0288, CVE-2015-0289, CVE-2015-0292. These vulnerabilities allow various maliciously crafted data could trigger segment fault, memory corruption or DOS attack.	
<b>Condition:</b> To exploit these vulnerabilities in FOS requires access to switch after user authentication through console, Telnet, and SSH connections.	
<b>Workaround:</b> Place switch and other data center critical infrastructure behind firewall to disallow access from the Internet; Change all default account passwords; Delete guest accounts and temporary accounts created for one-time usage needs; Utilize FOS password policy management to strengthen the complexity, age, and history requirements of switch account passwords. Upgrading to a FOS version including this fix prevents exposures to the four CVEs noted in the defect Symptom.	
<b>Recovery:</b>	

<b>Defect ID:</b> DEFECT000551787	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Traffic Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> Routing
<b>Symptom:</b> FCR devices not imported for up to 10 minutes following hafailover, resulting in IO disruption.	
<b>Condition:</b> This may be encountered in an FCR setup, when ports(E/ExVex/Fport) are bounced in edge fabric during hafailover. This only impacts FOS7.3.x and FOS7.4.0 with staged port matching feature.	
<b>Workaround:</b> If there is VEx port in a FCR fabric, upgrade to a FOS version with this fix. If already running a version of FOS without this fix, contact tech support to disable staged port matching feature on backbone fabric to reduce future risk until able to upgrade to a version with fix.	
<b>Recovery:</b> Wait approximately 10 minutes for FCR to re-import the devices after an HaFailover or toggle end device to recover	

<b>Defect ID:</b> DEFECT000552474	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> FICON
<b>Reported In Release:</b> FOS7.2.1	<b>Technology Area:</b> FICON emulation
<b>Symptom:</b> Unable to run Teradata with Teradata FICON emulation enabled on the FCIP tunnel.	
<b>Condition:</b> When Teradata emulation is enabled on an FCIP tunnel and a read operation presents early ending status for a short read. This leads to an error in the FICON Teradata emulation logic and subsequent IOs fail.	
<b>Workaround:</b> Disable Teradata emulation on the FCIP Tunnel.	

<b>Defect ID:</b> DEFECT000553129	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> System
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> CLI
<b>Symptom:</b> Observed fcippathtest fail executing lb_mode 5 with -nframes options in Brocade 7800 with: BTR ETH Asic poort 0 Link Status FAILED 0x168 fcippathtest: Blaster port 50, bad lli status	
<b>Condition:</b> This may occur when fcippathtest is run for a high number of iterations	

<b>Defect ID:</b> DEFECT000553197	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Distance
<b>Reported In Release:</b> FOS7.3.1	<b>Technology Area:</b> OSTP - Open Systems Tape Pipelining
<b>Symptom:</b> I/O errors to BR7840 FCIP Open Systems Tape Pipelining connected FCP SID/DID pairs and XTUN-1000 Missed data frame RASLOG.	
<b>Condition:</b> This may occur when OSTP is currently in read pipelining when a FCP Inquiry command is received using the same OXID that is currently active for an OSTP read-ahead read command sequence.	
<b>Workaround:</b> Disable OSTP Read Pipelining on the BR7840 FCIP Tunnel.	

<b>Defect ID:</b> DEFECT000553920	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Virtualization
<b>Reported In Release:</b> FOS7.2.1	<b>Technology Area:</b> Virtual Fabrics
<b>Symptom:</b> Ports in logical switch may bounce following firmwaredownload or hareboot.	
<b>Condition:</b> In a VF environment with XISL on and base switch not defined, FMS is enabled on one logical switch, other logical switches without FMS mode enabled, will have FICON filters installed on ports by mistake and cause traffic disruption.	

<b>Defect ID:</b> DEFECT000554238	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> Firmware upload/download
<b>Symptom:</b> After swapping QSFP with 2km SFP on core blade ICL ports, downgrade to FOS v7.3.x is blocked.	
<b>Condition:</b> This is seen when QSFP is replaced by 2km SFP, and a firmware code downgrade is attempted.	
<b>Recovery:</b> Remove all 2km optics, find old standard QSFP optics and insert them into the empty ports previously occupied by the 2km optics, then perform firmware downgrade.	

<b>Defect ID:</b> DEFECT000554414	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> System
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> Component
<b>Symptom:</b> Link issues are seen when fcippathtest runs for a longer duration on BR7800.	
<b>Condition:</b> Running systemverification test in a loop of about 10+ iterations results in this issue.	

<b>Defect ID:</b> DEFECT000554530	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Traffic Management
<b>Reported In Release:</b> FOS7.2.1	<b>Technology Area:</b> Zoning
<b>Symptom:</b> Zone enforcement may not be properly enforced on an NPIV port which can lead to timeouts or frame loss at any of the NPIV devices on the same switch port	
<b>Condition:</b> This may be seen when a device on an NPIV port that has no zoning members (un-zoned device) existing on the same NPIV port as other devices with zoning members defined. Zoning configuration change (cfgsave or cfgenable) can lead to incorrect zoning enforcement on this port. Any non-NPIV ports that also have no zoning definition (no members defined) will also be left in a state where these un-zoned ports would be able to communicate with each other. No impact to ports that have zoning defined. This can be seen in FOS v7.2.1d, v7.2.1e, v7.3.1, v7.3.1a, v7.4.0, v7.4.0a	
<b>Workaround:</b> NS queries will properly block access to viewing any other devices, but physical access could still be allowed. To prevent any physical access, create a "dummy zone" for all ports that are currently un-zoned (no zoning members defined)	

<b>Defect ID:</b> DEFECT000554744	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology Area:</b> Web Tools
<b>Symptom:</b> The alias member revert back to an old offline WWPN as one switched from the "Alias" tab to the "Config" tab in Webtools.	
<b>Condition:</b> Name server dialog is opened with "Auto refresh" on, such that name server info, zoning info and switch details will be polled from switch and refreshed in webtools. As the zone information is refreshed, user changed zone alias will be overwritten.	
<b>Workaround:</b> Disable the auto refresh before doing any zoning changes in webtools	

<b>Defect ID:</b> DEFECT000554772	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Distance
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> FCIP
<b>Symptom:</b> BR7840 FCIP HCL Failure (firmware download is disruptive of FCIP traffic over the FCIP Tunnel)	
<b>Condition:</b> This is encountered when attempting to perform FCIP HCL on a BR7840 FICON Emulation enabled tunnel.	
<b>Workaround:</b> As a work around, schedule a maintenance window to perform disruptive firmware download.	

<b>Defect ID:</b> DEFECT000555286	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Distance
<b>Reported In Release:</b> FOS7.1.1	<b>Technology Area:</b> OSTP - Open Systems Tape Pipelining
<b>Symptom:</b> FCIP OSTP (Open Systems Tape Pipelining) Read I/O Job failures (block count mismatch or other errors).	
<b>Condition:</b> After tape server or tape server HBA code upgrade, SSC-2/3 (T10 standard) commands can be issued to an FCIP OSTP enabled tunnel to a tape device. FCIP currently does not have the SSC-2 command set implemented and therefore unknown errors can occur.	
<b>Workaround:</b> Disable OSTP Read Pipelining on the FCIP Tunnel between the server and the tape device.	



<b>Defect ID:</b> DEFECT000556108	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology Area:</b> Web Tools
<b>Symptom:</b> Zone Administration display is painted complete white and fails to display the buttons.	
<b>Condition:</b> When trying to fetch the vendor name using the OUI which doesn't exist in WebTools repository.	

<b>Defect ID:</b> DEFECT000556188	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Traffic Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> Buffer Credit Recovery
<b>Symptom:</b> On 16G director, while credit recovery feature is not turned on, if there is unstable back-end link, blade could be faulted.	
<b>Condition:</b> A blade could be faulted on 16G director when following conditions are met: <ol style="list-style-type: none"> <li>1. Credit recovery feature is off</li> <li>2. There is credit loss caused by link level error on back-end ports.</li> <li>3. The link cannot be recovery by an automatic Link Reset.</li> </ol> This can happen with FOS7.2.1e and 7.3.1a and FOS7.4.0; With earlier releases, the credit loss will result no further action until user manually link reset if credit recovery feature is off.	
<b>Workaround:</b> Turn on credit recovery "creditrecovmode --cfg onLrOnly" to limit the fault to a back-end port only under error condition.	
<b>Recovery:</b> Turn on credit recovery "creditrecovmode --cfg onLrOnly" to limit the fault to a back-end port only under error condition.	

<b>Defect ID:</b> DEFECT000556926	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Distance
<b>Reported In Release:</b> FOS8.0.0	<b>Technology Area:</b> FCIP
<b>Symptom:</b> DP Panics on BR7840 due to memory corruption	
<b>Condition:</b> This is a rare occurrence from a race condition where TCP Header access occurs after the wire buffer has been freed in ipV6 configuration	

<b>Defect ID:</b> DEFECT000557254	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> FICON
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> FICON CUP
<b>Symptom:</b> CUP goes offline when CSCTL priority is enabled on CUP port.	
<b>Condition:</b> Plogi response frame has priority bit set and CSCTL priority to the CUP is not supported.	

<b>Defect ID:</b> DEFECT000558511	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> System
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> Component
<b>Symptom:</b> Loss of CUP connectivity in a cascaded FICON environment, following the disruption of all ISL paths to a given CUP.	
<b>Condition:</b> Following disruption of all ISL paths to a given cascaded CUP, subsequent exchanges destined to the cascaded CUP cannot be delivered until a new PLOGI session is established.	
<b>Recovery:</b> Vary channel online to recover.	

<b>Defect ID:</b> DEFECT000558820	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> System
<b>Reported In Release:</b> FOS7.3.1	<b>Technology Area:</b> CLI
<b>Symptom:</b> Response time out happens with higher nframes value specified for fcippathtest.	
<b>Condition:</b> Issue happens when nframes value as high as 70 is specified for fcippathtest.	

<b>Defect ID:</b> DEFECT000558936	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> System
<b>Reported In Release:</b> FOS7.3.1	<b>Technology Area:</b> CLI
<b>Symptom:</b> HIF mode value is not always being displayed in switchshow output .	
<b>Condition:</b> This is encountered when HIF mode is disabled. HIF mode value is displayed only when HIF mode is enabled.	

<b>Defect ID:</b> DEFECT000559709	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology Area:</b> Web Tools
<b>Symptom:</b> Switch Health Report does not reflect accurate state of the ports: WebTools shows the Error Ports Monitor as DOWN - but displays "All ports are healthy"	
<b>Condition:</b> Error Ports Monitor does not correctly reflect the status through Web tools when there are ports with errors.	
<b>Workaround:</b> CLI command works properly and can be used as a workaround.	

<b>Defect ID:</b> DEFECT000559947	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.3.1	<b>Technology Area:</b> End-to-end Performance Monitoring
<b>Symptom:</b> Switch goes into rolling reboot following the execution of these sequence of commands: fmmonitor, configdefault, configupload/download.	
<b>Condition:</b> This may be encountered if configuration download and upload is performed when there are user defined frame monitors.	
<b>Workaround:</b> Avoid downloading configuration file with user defined frame monitors.	

## Closed with Code Change in Fabric OS v7.3.1a

This section lists the defects with Critical, High and Medium Technical Severity closed with a code change as of March 13, 2015 in Fabric OS v7.3.1a

<b>Defect ID:</b> DEFECT000431369	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.0.2	<b>Technology Area:</b> SNMPv2, SNMPv3 & MIBs
<b>Symptom:</b> Mib browser displays ascii-hex of populated fcportflag value. For example it displays "30" for 0, "31" for 1, where expected display is "0", "1".	
<b>Condition:</b> This is seen only for the MIB display of fcportflag.	

<b>Defect ID:</b> DEFECT000472607	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> System
<b>Reported In Release:</b> FOS7.2.0	<b>Technology Area:</b> CLI
<b>Symptom:</b> Brocade 6510 switch may become inaccessible via SSH and/or Telnet when a firmware upgrade of the switch initiated through Brocade Network Advisor results with “failed to enforce new iptable rules” error message,.	
<b>Condition:</b> It's a race condition caused by an existing ineffective file locking mechanism.	
<b>Workaround:</b> Activating (from console) a new policy with rules of default active policy will restore access to the switch. such as: Ipfilter –clone new_rules –from default_ipv4 Ipfilter –activate new_rules	

<b>Defect ID:</b> DEFECT000513544	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.1.1	<b>Technology Area:</b> Management Server
<b>Symptom:</b> During code upgrade, standby CP may run into repeated msd panics and may not come online to standby ready mode.	
<b>Condition:</b> This occurs when AG node name is missing on active CP during execution of the FC-GS-3 Register Platform (RPL) command.	

<b>Defect ID:</b> DEFECT000523845	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Virtualization
<b>Reported In Release:</b> FOS6.3.2	<b>Technology Area:</b> Access Gateway
<b>Symptom:</b> appearance of the configuration parameter "ag.fporttrunking" differs depending on reboot/hareboot	
<b>Condition:</b> After non-disruptive firmware upgrade from FOS v6.2 to FOS v6.3, configuration key ag.fporttrunking(introduced in FOS v6.3) created at boot stage is getting removed. And the issue persists when user performs non-disruptive firmware upgrade to higher firmware versions without reboot..	
<b>Recovery:</b> No other functional impact	

<b>Defect ID:</b> DEFECT000527025	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> APM - Advanced Performance Monitoring
<b>Symptom:</b> CLI command fmmonitor --delmonitor <fmtype> -port 2/2 returns with "Specified Frame type doesn't exist on the specified port" even though a new fm-type was created and added to port 2/2.	
<b>Condition:</b> This may be seen when user moves the frame monitor installed port from one logical switch to another and then moves back the same port to the original logical switch	

<b>Defect ID:</b> DEFECT000527506	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> System
<b>Reported In Release:</b> FOS7.1.0	<b>Technology Area:</b> Component
<b>Symptom:</b> I2C access failures leading to various symptoms such as: <ol style="list-style-type: none"> <li>1. slotshow command output may flag some components with an "*", indicating no i2c access to that component.</li> <li>2. switchshow command output may indicate "Speed Mismatch / Incompatible SFP"</li> <li>3. tempshow command output may display "unknown"</li> <li>4. Console log (dmesg) may include: pcf954x_select_mux: Failed to select the I2C mux (addr=76, val=08, err=-1 id=0)!</li> </ol>	
<b>Condition:</b> Brocade 6520 with the current version of software fails to properly reset or clear transient i2c faults. Consequently, Temporary or Transient errors on the I2C bus can result in what appears to be a permanent HW failure on a Brocade 6520.	
<b>Recovery:</b> Cold boot switch	

<b>Defect ID:</b> DEFECT000527862	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> Web Tools
<b>Symptom:</b> Name server table column position is not persistent across relaunch	
<b>Condition:</b> This name server table column display issue is seen when the switch is in non AG mode.	

<b>Defect ID:</b> DEFECT000528010	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Distance
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> FCIP
<b>Symptom:</b> FCIP HCL failure encountered due to a large number of FCIP objects in the configuration	
<b>Condition:</b> This is encountered when a large number of FCIP Objects (>> 20K FICON or FCP objects) are present.	
<b>Workaround:</b> Schedule a maintenance window for a disruptive FOS code load.	
<b>Recovery:</b> Recover environment after disruptive code load completes.	

<b>Defect ID:</b> DEFECT000528657	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Traffic Management
<b>Reported In Release:</b> FOS7.2.0	<b>Technology Area:</b> Name Server / Zoning
<b>Symptom:</b> FCPD termination encountered when device sends malformed response with incorrect R_CTL information during FCP probing	
<b>Condition:</b> This occurs only when the device responds with malformed frames during FCP probing	

<b>Defect ID:</b> DEFECT000532816	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Traffic Management
<b>Reported In Release:</b> FOS7.2.0	<b>Technology Area:</b> Trunking
<b>Symptom:</b> Traffic disruption in normal traffic encountered following an HA-failover during firmware upgrade.	
<b>Condition:</b> This may happen when an E-port trunk port with FEC active bounces during HA-failover phase of the firmware upgrade process.	

<b>Defect ID:</b> DEFECT000533925	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> FICON
<b>Reported In Release:</b> FOS7.1.0	<b>Technology Area:</b> FICON emulation
<b>Symptom:</b> FCIP FICON Emulated Tape device failures with FICN-1062 in RASLOG and LastStates=0x0000423F443F	
<b>Condition:</b> When attempting to complete read processing and the device presents Device Busy then Device End, FICON emulation logic incorrectly generated a No-Op command with chaining instead of accepting the Device End Status.	
<b>Workaround:</b> Disable FICON Read Pipelining	

<b>Defect ID:</b> DEFECT000534413	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.2.1	<b>Technology Area:</b> Monitoring and Alerting Policy Suite (MAPS)
<b>Symptom:</b> "logicalgroup --show" command will show more ports than switch has under "ALL_PORTS" group. MAP-1003 RASLOG messages on non-existent ports.	
<b>Condition:</b> This issue happens if the customer has MAPS enabled and performs hafailover or migrate firmware to MAPS supported versions with online F_Port trunk.	
<b>Workaround:</b> Bring up the F_port trunk ports after hafailover,	

<b>Defect ID:</b> DEFECT000534507	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Distance
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> FCIP
<b>Symptom:</b> Severe FICON workload disruption during 7840 HCL	
<b>Condition:</b> This is encountered when FCIP HCL is attempted on a single 7840 switch in a 7840 pair with HA and active FICON data flow,	
<b>Workaround:</b> Plan a disruptive firmware download.	

<b>Defect ID:</b> DEFECT000536455	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> Platform Services
<b>Symptom:</b> Both Active and Standby CPs panic in a director while processing Read Diagnostic Parameters (RDP) Extended Link Service (ELS) request from local device.	
<b>Condition:</b> This is triggered by a race condition when a local device repeatedly sends unsolicited RDP ELS request and the switch is running FOS7.3.0 or above.	
<b>Workaround:</b> Disable device port capable of RDP	

Defect ID: DEFECT000536632	
Technical Severity: High	Probability: High
Product: FOS	Technology: Monitoring/RAS
Reported In Release: FOS7.4.0	Technology Area: POST - Power-on Self-Test
Symptom: Diagnostic test "systemverification" failed with "NON_DIAG errors detected during run"	
Condition: This is encountered when running systemverification test on BR7840	

<b>Defect ID:</b> DEFECT000536832	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Traffic Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> In-flight Compression
<b>Symptom:</b> Port does not come online and raslog is flooded with the following message: "Brocade6520, S0,P51(114): Port is offline due to Encryption Compression Block error."	
<b>Condition:</b> This is seen when Inflight Encryption is enabled on an Ex-Port.	

<b>Defect ID:</b> DEFECT000537093	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Distance
<b>Reported In Release:</b> FOS7.1.1	<b>Technology Area:</b> OSTP - Open Systems Tape Pipelining
<b>Symptom:</b> Timeouts after Reservation Conflict Status with tape devices when Fastwrite and Tape-pipelining are enabled	
<b>Condition:</b> This occurs when multiple servers attempt to reserve the same tape device over OSTP enabled tunnel.	
<b>Workaround:</b> Disable OSTP on the FCIP Tunnel	

<b>Defect ID:</b> DEFECT000537848	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Traffic Management
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> FC-FC routing
<b>Symptom:</b> Host unable to discover target devices in an Edge-to-Edge FCR topology.	
<b>Condition:</b> When some of the edge fabric switches having trunked IFLs are rebooted, resulting in Fabric ID conflicts in any of the backbone fabric FCRs, few hosts may not be able to discover targets.	

<b>Defect ID:</b> DEFECT000538051	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> FICON
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> FICON emulation
<b>Symptom:</b> BR7840 FICON Emulation OXID usage overlap causes Interface Control Check error messages on the mainframe console.	
<b>Condition:</b> The issue can occur anytime when two or more devices are active in FICON emulation over an FCIP tunnel.	
<b>Workaround:</b> Disable FICON emulation features on the FCIP Tunnel.	

<b>Defect ID:</b> DEFECT000538092	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Virtualization
<b>Reported In Release:</b> FOS7.2.1	<b>Technology Area:</b> Access Gateway
<b>Symptom:</b> Following a FOS firmware upgrade or hareboot, traffic to and from the Access Gateway stops after the N-Port trunk master is disabled.	
<b>Condition:</b> This issue will occur when the following conditions occur: <ul style="list-style-type: none"> <li>- hareboot for any reason, including firmwaredownload.</li> <li>- N-port trunk with at least two trunk members.</li> <li>- Trunk master of the N-port trunk is disabled.</li> </ul>	
<b>Workaround:</b> Never disable the N-port trunk master when other trunk members are online. Instead, always disable all trunk members. Trunk slaves can be disabled with no issue.	
<b>Recovery:</b> To recover, do one of two things: <ol style="list-style-type: none"> <li>1. Bounce a host F_port on the Access Gateway. Or,</li> <li>2. Disable all trunk members and then enable all trunk members.</li> </ol>	

<b>Defect ID:</b> DEFECT000538492	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Distance
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> OSTP - Open Systems Tape Pipelining
<b>Symptom:</b> Error recovery issue when the last write in a small write block is dropped.	
<b>Condition:</b> Data Integrity Error can be exposed when the Last Write Data Frame in a small write (8k) Across 7840 FCIP Tunnel when TP is on.	

<b>Defect ID:</b> DEFECT000539167	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.1.1	<b>Technology Area:</b> Web Tools
<b>Symptom:</b> Weblinker termination when the TACACS+ server is unreachable	
<b>Condition:</b> Happens only when user tries to login to switch which has unreachable TACACS+ server for authentication.	
<b>Workaround:</b> Use local or other remote authentication(LDAP/RADIUS) for login	

<b>Defect ID:</b> DEFECT000539290	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Traffic Management
<b>Reported In Release:</b> FOS7.2.1	<b>Technology Area:</b> Buffer Credit Recovery
<b>Symptom:</b> On internal back end (BE) link with 16G core blade to 8G edge blade, credit is not automatically recovered.	
<b>Condition:</b> In the case of 16G core blade to 8G edge blade direction, if there is credit loss on VC and the "creditrecovmod --cfg onLROnly" command is not enabled in an early release, then once the 16G credit leak interrupt is triggered, the credit leak interrupt enabled bits will not be enabled again.	
<b>Workaround:</b> Run creditrecovmod --cfg onLROnly before credit is depleted.	
<b>Recovery:</b> Slotpoweroff /on core blade to recover the BE link	

<b>Defect ID:</b> DEFECT000540035	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology Area:</b> Licensing
<b>Symptom:</b> There is a new business requirement to offer a 20 port version of the Brocade 5432 switch plus 4 “port on demand” licensed ports.	
<b>Condition:</b> POD was not supported before.	
<b>Recovery:</b> Upgrade to the new FOS version to limit the switch to 20 licensed ports. To enable the additional 4 ports, the customer would need to purchase and install the POD license.	

<b>Defect ID:</b> DEFECT000540245	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Distance
<b>Reported In Release:</b> FOS7.1.0	<b>Technology Area:</b> FCIP
<b>Symptom:</b> Tunnels bounce caused FFDC event.	
<b>Condition:</b> This may occur if a FICON frame sequence is received with FC type of 0x1B or 0x1C, with one SOFi3 frame followed by more than 13 SOFn3 frames in sequence on an FCIP Tunnel. This is probably caused by a failed FICON adapter in a connected device.	

<b>Defect ID:</b> DEFECT000540469	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> FICON
<b>Reported In Release:</b> FOS7.1.0	<b>Technology Area:</b> FICON emulation
<b>Symptom:</b> Channel Detected Error message after a tape job failure.	
<b>Condition:</b> When running a tape write job that experiences a timeout (due to FC CRC errors occurring during the IO), the job will normally detect an MIH failure and go through error recovery and the error recovery could encounter the invalid token CDE.	
<b>Workaround:</b> Disable FICON Tape Pipelining or correct the cause of the FC CRC errors.	

<b>Defect ID:</b> DEFECT000540585	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.2.1	<b>Technology Area:</b> supportShow
<b>Symptom:</b> Support Save output does not include VE or GE port information	
<b>Condition:</b> This is seen after multiple logical switches have been created and one or more of the logical switches have been deleted and the VE ports reside in a logical switch that was created after one that was deleted.	
<b>Workaround:</b> Recreate empty logical switches up to the limit of logical switches in that chassis.	

<b>Defect ID:</b> DEFECT000540694	
<b>Technical Severity:</b> Critical	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.2.1	<b>Technology Area:</b> Top Talker Monitors
<b>Symptom:</b> Switch repeatedly logs the following raslog message: "[PS-1009], 16386, SLOT 7   FID 128, WARNING, , Failed to add the device updates in condb database." This can mislead the customer on the number of devices supported by name server, zoning and device connectivity.	
<b>Condition:</b> This happens when there are large number of devices zoned together and with "Performance Monitor license". There is no impact to device connectivity, but Top talkers may not be able to display the top talking flows	



<b>Defect ID:</b> DEFECT000541322	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> FICON
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> FICON emulation
<b>Symptom:</b> IOS050I CHANNEL DETECTED ERROR message on mainframe console after 0x70 Status from XRC primary controller.	
<b>Condition:</b> This is seen during FCIP FICON XRC emulated tunnel processing of 0x70 Status from the connected DASD controller.	
<b>Workaround:</b> Disable FICON XRC Emulation on the FCIP Tunnel.	

<b>Defect ID:</b> DEFECT000541661	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Virtualization
<b>Reported In Release:</b> FOS7.2.1	<b>Technology Area:</b> Virtual Fabrics
<b>Symptom:</b> Active CP Panic may occur while running Brocade SAN Health report.	
<b>Condition:</b> This may be encountered in a large virtual fabric environment when running back to back CLI commands "lfcfg --showall -xxxx"	

<b>Defect ID:</b> DEFECT000542559	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Distance
<b>Reported In Release:</b> FOS7.4.0	<b>Technology Area:</b> FCIP
<b>Symptom:</b> Tunnel bounce with an associated BLS-5024 FFDC event.	
<b>Condition:</b> This issue can occur after FCIP tunnel bounces due to WAN outage or other network issue.	

<b>Defect ID:</b> DEFECT000543727	
<b>Technical Severity:</b> Low	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> Logging
<b>Symptom:</b> The CP flash drive can run low on space due to the /var/log/esmd_lib.log file growing too large.	
<b>Condition:</b> The problem may occur on any switch other than the Brocade 7840 switch, when running with FOS7.3.0x and FOS7.3.1. The problem will not occur on the Brocade 7840 switch.	
<b>Recovery:</b> Manually delete the /var/log/esmd_lib.log file.	

<b>Defect ID:</b> DEFECT000547042	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology Area:</b> Firmware upload/download
<b>Symptom:</b> When BufOpMode is enabled for core blades, Firmware upgrade/downgrade to FOS versions not supporting BufOpMode on core blades is not being blocked (as should be the case).	
<b>Condition:</b> This is encountered when BufOpMode is enabled and firmware upgrade/downgrade to FOS version not supporting this feature is being attempted.	
<b>Workaround:</b> Check to see if BufOpMode is enabled and clear/reset it before attempting a firmwaredownload of FOS versions that do not support this feature.	

## Open in Fabric OS v7.3.1

This section lists the open defects with Critical, High and Medium Technical Severity as of December 12, 2014 in Fabric OS v7.3.1

<b>Defect ID:</b> DEFECT000497810	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.1.1	<b>Technology Area:</b> Diagnostic Port (D_Port)
<b>Symptom:</b> Core blade faults when dport tests are being run on ICL ports and ports are disabled.	
<b>Condition:</b> Disable port under testing	
<b>Workaround:</b> Don't disable ports when dport tests are in progress.	

<b>Defect ID:</b> DEFECT000529293	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology Area:</b> Ethernet Interface
<b>Symptom:</b> IFMODESET command does not change the mode of the interface.	
<b>Condition:</b> This is seen when the CLI command "ifmodeset" is run in non-interactive mode	
<b>Workaround:</b> Use interactive mode of this CLI command to set AN or Speed	

<b>Defect ID:</b> DEFECT000529395	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> System
<b>Reported In Release:</b> FOS7.3.1	<b>Technology Area:</b> CLI
<b>Symptom:</b> ipfilter --show command lists all ports as "permit".	
<b>Condition:</b> BR543x does not deny access to TCP/IP port 23 and 80 by default	
<b>Workaround:</b> Manual block ports	

<b>Defect ID:</b> DEFECT000529904	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Traffic Management
<b>Reported In Release:</b> FOS7.3.1	<b>Technology Area:</b> Port Bring-up
<b>Symptom:</b> Bounced ISL links may not come back to full speed setting when port speed is set to AN.	
<b>Condition:</b> This can only happen during hafailover with a fabric rebuild. This results from all ISL's going down at the same time.	
<b>Recovery:</b> Bounce ports to recover from this situation.	

<b>Defect ID:</b> DEFECT000531269	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Virtualization
<b>Reported In Release:</b> FOS7.3.1	<b>Technology Area:</b> Access Gateway
<b>Symptom:</b> Static mapped F-ports do not come back online after reboot, while all the non-static mapped ports come back online after the reboot.	
<b>Condition:</b> This is encountered when F-ports are statically mapped.	
<b>Workaround:</b> Toggle the F-port manually.	
<b>Recovery:</b> Disable and then enable the N-ports that the F-ports are static mapped to.	

## Open in Fabric OS v7.3.1

<b>Defect ID:</b> DEFECT000535664	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Distance
<b>Reported In Release:</b> FOS7.3.1	<b>Technology Area:</b> FCIP
<b>Symptom:</b> BR7840 switch may go down as a result of DP crash from ECC errors in memory controller DIMMs.	
<b>Condition:</b> This may occur on BR7840 under rare situation, as a result of ECC errors.	

## Closed with Code Change in Fabric OS v7.3.1

This section lists the defects with Critical, High and Medium Technical Severity closed with a code change as of December 12, 2014 in Fabric OS v7.3.1

<b>Defect ID:</b> DEFECT000436921	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> System
<b>Reported In Release:</b> FOS6.3.1_dcb	<b>Technology Area:</b> CLI
<b>Symptom:</b> Console may hang, leading to switch Panic from unexpected termination of daemons from Out of Memory condition.	
<b>Condition:</b> This may be observed while performing supportsave or other CLI management operations	

<b>Defect ID:</b> DEFECT000457373	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Virtualization
<b>Reported In Release:</b> FOS7.0.2	<b>Technology Area:</b> Access Gateway
<b>Symptom:</b> BR5480 embedded switch displays invalid message without functional impact.	
<b>Condition:</b> Invalid message "Request F-N Port Mappings for Access Gateway Change from SW" is observed while running in native switch mode.	
<b>Recovery:</b> No impact to switch functionality.	

<b>Defect ID:</b> DEFECT000470918	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.2.0	<b>Technology Area:</b> POST - Power-on Self-Test
<b>Symptom:</b> POST tests do not run when standard and extended levels of testing are chosen from CMM.	
<b>Condition:</b> Issue happens when post test is triggered from CMM on embedded switch.	

<b>Defect ID:</b> DEFECT000473541	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> System
<b>Reported In Release:</b> FOS6.4.3	<b>Technology Area:</b> CLI
<b>Symptom:</b> Large number of threads in environmental daemon (emd) cause system to run out of memory and panic.	
<b>Condition:</b> Over 100 portshow CLIs are concurrently running on a director.	
<b>Workaround:</b> Limit the number of concurrent CLIs to under 50 at a time.	

<b>Defect ID:</b> DEFECT000484261	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.2.1	<b>Technology Area:</b> Frame Monitoring
<b>Symptom:</b> CLI command "sloterrshow" reports timeout frame. However, "framelog -show" does not capture the timed out frame.	
<b>Condition:</b> This discrepancy with respect to timeout frames maybe noted when comparing outputs of CLI commands "sloterrshow" and "framelog -show"	

## Closed with code in Fabric OS v7.3.1

<b>Defect ID:</b> DEFECT000484537	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> System
<b>Reported In Release:</b> FOS7.1.1	<b>Technology Area:</b> Component
<b>Symptom:</b> Switch CP experienced rolling kernel panic at "indirect_read_config" during blade initialization	
<b>Condition:</b> When a not properly seating blade or failed blade hang the PCI bus.	
<b>Recovery:</b> Remove the problem blade.	

<b>Defect ID:</b> DEFECT000488832	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Virtualization
<b>Reported In Release:</b> FOS7.1.1	<b>Technology Area:</b> Virtual Fabrics
<b>Symptom:</b> During testing, embedded switch intermittently fails after reboot.	
<b>Condition:</b> After high reboot count, with less than 127 targets, switch will occasionally not respond to name server queries.	

<b>Defect ID:</b> DEFECT000489311	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS6.4.1	<b>Technology Area:</b> User Accounts
<b>Symptom:</b> Running "ifconfig eth0 down" on the console may lead to a panic and reboot of the switch.	
<b>Condition:</b> This may occur when the switch becomes inaccessible via the management port and the CLI command "ifconfig eth0 down" is executed from the serial console	

<b>Defect ID:</b> DEFECT000491910	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.2.1	<b>Technology Area:</b> Logging
<b>Symptom:</b> SNMP query connUnitPortStatCountBBCreditZero or CLI portstats64show could display an unexpected large value for tim64_txcrd_z counter in a very brief time	
<b>Condition:</b> This issue will be seen when there is a FC traffic slowness in fabric and statistic counter wraps.	
<b>Workaround:</b> Customer could use portstatsshow command to get the correct counter value.	

<b>Defect ID:</b> DEFECT000494270	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Security
<b>Reported In Release:</b> FOS7.1.0	<b>Technology Area:</b> Fabric Authentication
<b>Symptom:</b> Customer might see devices reported as unauthorized when they try to login to a switch even when DCC policy is configured properly. Sometimes when the DCC policy is activated, some of the ports might bounce.	
<b>Condition:</b> The WWN that starts with "80" has the most possibility to hit this issue. The issue might also be seen when the device WWNs starts with "C0", "50", "20", or "10".	
<b>Workaround:</b> Avoiding the device WWN that starts with "80" or greater from DCC policy would resolve the issue.	

<b>Defect ID:</b> DEFECT000499012	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> Platform Services
<b>Symptom:</b> Unable to stop the autoboot using the ESC key to get into command shell.	
<b>Condition:</b> This is encountered during boot up, where the escape sequence key is not functioning properly.	

## Closed with code in Fabric OS v7.3.1

<b>Defect ID:</b> DEFECT000499177	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Other
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> Other
<b>Symptom:</b> Some hosts from an edge fabric may fail to discover the LUNs in another edge fabric.	
<b>Condition:</b> After doing a switchdisable of all the switches in the edge fabric and doing simultaneous switchenable of the disabled switches.	
<b>Recovery:</b> Toggle the port, host and target. If condition persists, switchdisable/enable the switch.	

<b>Defect ID:</b> DEFECT000499356	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> SNMPv2, SNMPv3 & MIBs
<b>Symptom:</b> CLI command "snmptraps --block/unblock -port [slot]port   ALL" appears to permit configuration for ports beyond the valid range for a switch, without flagging any errors.	
<b>Condition:</b> This issue is seen when attempting to configure snmptraps for ports beyond the valid range for a given switch. No Error messages are shown to the user. However the problem itself is benign, with no functionality impact.	

<b>Defect ID:</b> DEFECT000501658	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.0.1	<b>Technology Area:</b> NTP - Network Time Protocol
<b>Symptom:</b> Switch panics after time server daemon failed to sync time with server.	
<b>Condition:</b> This may occur from an Ethernet network issue in the fabric resulting in a failure to resolve DNS names into IP addresses.	
<b>Workaround:</b> Use IP address instead of DNS server name in clock server configuration. Alternately do not configure DNS configuration in switch.	

<b>Defect ID:</b> DEFECT000503827	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Distance
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> Extended Fabrics
<b>Symptom:</b> VE port comes up as G-port when concurrent firmwaredownload is initiated on two BR7840.	
<b>Condition:</b> Concurrent firmwaredownload is not supported on 7840, but if performed, this issue can be hit.	

<b>Defect ID:</b> DEFECT000503942	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> EZSS Switch Manager
<b>Symptom:</b> Unable to configure 7840 using EZ Setup	
<b>Condition:</b> In some cases the EZ Setup for 7840 may fail with ambiguous error message and display issues.	
<b>Recovery:</b> Relaunch EZ Manager to restart EZ Setup	

## Closed with code in Fabric OS v7.3.1

<b>Defect ID:</b> DEFECT000504254	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Other
<b>Reported In Release:</b> FOS7.1.1	<b>Technology Area:</b> Other
<b>Symptom:</b> Intermittent systemverification failures may be encountered when the number of test runs are increased to 50 or more.	
<b>Condition:</b> This problem is encountered only when the parameters for systemverification test are modified to a different value which the system does not support. This works as expected under normal circumstance, with supported values.	

<b>Defect ID:</b> DEFECT000505389	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Other
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> Other
<b>Symptom:</b> Switch may be Disabled due to internal ports not being Online	
<b>Condition:</b> This may be encountered in rare circumstance on a Brocade 7840 switch	

<b>Defect ID:</b> DEFECT000507532	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> Monitoring and Alerting Policy Suite (MAPS)
<b>Symptom:</b> This is a display issue of dashboard. DB shows wrong or NULL flow name if user does slotpoweroff/on	
<b>Condition:</b> This is a cosmetic display issue seen on dashboard only when user performs slotpoweroff/on.	

<b>Defect ID:</b> DEFECT000511542	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.2.1	<b>Technology Area:</b> supportShow
<b>Symptom:</b> Running supportsave on a director switch with faulted FC8-48E blades may lead to panic and cold recovery.	
<b>Condition:</b> This may occur when supportsave is run with blades in faulted state with reason code of PCI timeout (90) or power issues (28)	

<b>Defect ID:</b> DEFECT000512347	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Virtualization
<b>Reported In Release:</b> FOS7.1.1	<b>Technology Area:</b> Access Gateway
<b>Symptom:</b> Logical port WWN displayed by the "portshow" CLI may change after hot code load or haReboot on a switch running in AG mode, followed by any subsequent offline/online event to the F_Port trunk ports.	
<b>Condition:</b> This may occur under the following conditions: <ul style="list-style-type: none"> <li>- Upgrade or downgrade to firmware versions v6.1.2d, v6.2.2, or v6.3.0 and above.</li> <li>- Hareboot on firmware versions v6.1.2d, v6.2.2, or v6.3.0 and above.</li> <li>- Then disable / enable all ports of F-port trunk.</li> </ul>	
<b>Workaround:</b> Cold boot of the switch in AG mode.	

## Closed with code in Fabric OS v7.3.1

<b>Defect ID:</b> DEFECT000512726	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.0.2	<b>Technology Area:</b> Fabric Watch
<b>Symptom:</b> Multiple FW-1038 and FW-1042 messages reported, indicating that the SFP RX and TX power are below boundary - current value 0 uwatts.	
<b>Condition:</b> This may occur only when a switch CPU is very busy.	

<b>Defect ID:</b> DEFECT000513806	
<b>Technical Severity:</b> Low	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Other
<b>Reported In Release:</b> FOS7.2.0	<b>Technology Area:</b> Other
<b>Symptom:</b> Sorting switch events by date does not function properly in webtools	
<b>Condition:</b> This issue is seen in webtools, only when sorting events on the Time column, following an upgrade to Fabric OS version v7.2.0d. This sorting operation on the Time column does not function properly.	

<b>Defect ID:</b> DEFECT000515187	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> System
<b>Reported In Release:</b> FOS7.1.2	<b>Technology Area:</b> CLI
<b>Symptom:</b> While performing CLI command "seccertutil delkey", the certificates/keys are truncated to zero but the "Certificate File" does not become "none". This may cause the switch to panic due to configuration inconsistencies.	
<b>Condition:</b> This may occur when executing the CLI command "seccertutil delkey".	

<b>Defect ID:</b> DEFECT000515313	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> Fabric Watch
<b>Symptom:</b> While performing a supportsave, user may see benign display messages, interspersed with the supportsave output.	
<b>Condition:</b> This may be seen when the user attempts a supportsave operation after deleting frame monitoring.	

<b>Defect ID:</b> DEFECT000515403	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.1.2	<b>Technology Area:</b> supportShow
<b>Symptom:</b> Some command names are missing in SSHOW files of supportsave.	
<b>Condition:</b> This issue occurs in Director class platforms.	

<b>Defect ID:</b> DEFECT000516108	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> Monitoring and Alerting Policy Suite (MAPS)
<b>Symptom:</b> QSFPs having serial number starting with "HUA" are being monitored using ALL_OTHER_SFP group. These should instead be monitored under ALL_QSFP or some other special QSFP group. All other QSFPs are correctly monitored under ALL_QSFP.	
<b>Condition:</b> This is encountered only with QSFPs having serial number starting with "HUA" .	



## Closed with code in Fabric OS v7.3.1

<b>Defect ID:</b> DEFECT000516196	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> System
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> CLI
<b>Symptom:</b> BNA users may witness failure in moving ports across LS's on Brocade 7840 switch.	
<b>Condition:</b> This may be encountered following the CLI command 'portCfgDefault' on GE ports of Brocade 7840 Switch.	

<b>Defect ID:</b> DEFECT000516309	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Virtualization
<b>Reported In Release:</b> FOS7.0.0_pha	<b>Technology Area:</b> Access Gateway
<b>Symptom:</b> Hosts have problems logging into the fabric through an Access Gateway.	
<b>Condition:</b> This may be encountered under the following conditions: <ul style="list-style-type: none"> <li>- Hosts are connected to an Access Gateway.</li> <li>- F-ports on Access Gateway have NPIV logins.</li> <li>- Different hosts login and logout of the same Access Gateway F-port, and</li> <li>- Access Gateway Persistent AL_PA feature is enabled.</li> </ul>	
<b>Recovery:</b> Identify all affected F-ports with duplicate ALPA entries ag --printalpamap <port#> Disable _all_ the affected F-ports with duplicate ALPA entries portdisable <port#> ag --clearalpamap <port#> portenable <port#>	

<b>Defect ID:</b> DEFECT000516632	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> CLI
<b>Symptom:</b> Userspace daemon mdd may crash after an extended period. This incident is benign since the daemon is automatically restarted	
<b>Condition:</b> This is a rare occurrence resulting from a very slow memory leak in L2 device monitoring. With the default polling rate of once per day the incident may occur about once a year. Accelerated polling will increase the frequency but the daemon is automatically restarted and the incident is rendered benign.	

<b>Defect ID:</b> DEFECT000517927	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Virtualization
<b>Reported In Release:</b> FOS7.2.1	<b>Technology Area:</b> Access Gateway
<b>Symptom:</b> Following an upgrade, BES panics when user attempts to enable access gateway.	
<b>Condition:</b> This is encountered on FOS v7.2.x and v7.3.x code streams; However, FOSv7.3 no longer support access gateway mode on BES switch, and FOS7.3.1 now enforces the no support.	
<b>Workaround:</b> Avoid enabling access gateway mode on encryption switches.	

<b>Defect ID:</b> DEFECT000519313	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Other
<b>Reported In Release:</b> FOS7.0.2	<b>Technology Area:</b> Other
<b>Symptom:</b> Internal ports may not be properly enabled or disabled after boot-up.	
<b>Condition:</b> This may be encountered on a very busy system, where expansion commands from SVP may not get processed in time.	
<b>Recovery:</b> The problem is intermittent. The expansion command can be re-triggered if any of the server blades is moved.	

## Closed with code in Fabric OS v7.3.1

<b>Defect ID:</b> DEFECT000519965	
<b>Technical Severity:</b> Critical	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Other
<b>Reported In Release:</b> FOS7.1.1	<b>Technology Area:</b> Other
<b>Symptom:</b> FCoE AP blades may be faulted following a firmware upgrade.	
<b>Condition:</b> This may occur due to ethernet connectivity issues on FCOE blades that have been up for a long period of time.	

<b>Defect ID:</b> DEFECT000520219	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> Monitoring and Alerting Policy Suite (MAPS)
<b>Symptom:</b> customer cannot achieve Port Decom even though that action is configured in the rule	
<b>Condition:</b> This is encountered if Port Fence and Port Decom are the only actions configured in the rule	

<b>Defect ID:</b> DEFECT000520550	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Traffic Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> Routing
<b>Symptom:</b> SW7840 Hot Code Load encountered an ESM fatal error during Failback which resulted in cold recovery.	
<b>Condition:</b> This may occur when a pair of SW7840s are tunnel-linked in all 4 Logical Partitions, and an HCL is performed on just one of the two SW7840s.	
<b>Recovery:</b> No recovery is necessary, after the HCL completes a cold reboot, the switch and tunnel(s) are stable again.	

<b>Defect ID:</b> DEFECT000521166	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Traffic Management
<b>Reported In Release:</b> FOS6.4.3	<b>Technology Area:</b> Name Server
<b>Symptom:</b> Corrupted frames cause nsd to panic and result in multiple switches in the fabric to cold boot.	
<b>Condition:</b> This may occur upon a rare hardware failure on a neighboring switch, resulting in corrupted nsd query response frames arriving at the other switches in the fabric.	
<b>Recovery:</b> Remove the failed blade or switch to eliminate the cause of these corrupted frames.	

<b>Defect ID:</b> DEFECT000521195	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> FICON
<b>Reported In Release:</b> FOS7.2.0	<b>Technology Area:</b> FICON
<b>Symptom:</b> Add ability to enable insistent domain ID (IDID) while the switch is online to permit non-disruptive upgrade v7.2.x to v7.3.	
<b>Condition:</b> As per design, upgrade to from FOS7.2.x to FOS v7.3 is blocked if customer has single switch fabric in FMS mode with SCC policy configured but IDID OFF. It requires a "switchdisable" in FOS v7.2.x to set IDID ON.	

## Closed with code in Fabric OS v7.3.1

<b>Defect ID:</b> DEFECT000521209	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> POST - Power-on Self-Test
<b>Symptom:</b> POST tests do not run as expected using CMM.	
<b>Condition:</b> Issue happens when POST tests are verified through CMM on embedded switches.	

<b>Defect ID:</b> DEFECT000521218	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Distance
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> Extended Fabrics
<b>Symptom:</b> Host discovery issues after upgrade to FOS7.2.x in FC Routed configuration over VE/VEX ports	
<b>Condition:</b> These host discovery issues may be encountered following upgrade to any FOS7.2.x release from a FOS version prior to FOS7.2.0, in FC Routed configuration over VE/VEX ports	
<b>Workaround:</b> Downgrade to a FOS release prior to FOS7.2.0.	

<b>Defect ID:</b> DEFECT000521272	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.2.1	<b>Technology Area:</b> Fabric Watch
<b>Symptom:</b> FW-1430 raslog messages logged to indicate possible faulty temperature sensor, but with no subsequent FW-1003 messages to indicate which sensor is triggering the alarms.	
<b>Condition:</b> This may be encountered if the sensor issue is transient in nature and problem recovers before triggering subsequent faults.	

<b>Defect ID:</b> DEFECT000521398	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Other
<b>Reported In Release:</b> FOS7.1.1	<b>Technology Area:</b> Other
<b>Symptom:</b> Before shutdown switch due to a high temperature alert, emd encountered an assert and caused switch to panic.	
<b>Condition:</b> This may happen during switch shutdown following a high temperature warning "Unit will be shut down in 2 minutes if temperature remains high"	

<b>Defect ID:</b> DEFECT000522602	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> System
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> CLI
<b>Symptom:</b> 'fabricshow -v' does not display FOS revision patch id under "Version" column.	
<b>Condition:</b> Display content overrun the declared array size.	

<b>Defect ID:</b> DEFECT000522807	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> Monitoring and Alerting Policy Suite (MAPS)
<b>Symptom:</b> User space daemon mdd might auto restart due to memory corruption.	
<b>Condition:</b> This happen when more than 5 rules get trigger for more than 2-3 hours.	

## Closed with code in Fabric OS v7.3.1

<b>Defect ID:</b> DEFECT000523092	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> System
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> CLI
<b>Symptom:</b> Unable to collect supportsave on BR5460 with error msg: "The switch does not have enough disk space to run full supportSave. Available Free disk space is 27 MB."	
<b>Condition:</b> This is encountered when Compact Flash available free space is low	

<b>Defect ID:</b> DEFECT000523193	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> FICON
<b>Reported In Release:</b> FOS7.1.0	<b>Technology Area:</b> FICON emulation
<b>Symptom:</b> IFCC during tape reads - Emulation Error Code=86 during REPOSITION_PENDING_STATE	
<b>Condition:</b> When FICON tape read pipelining is active and the device presents Short Busy status	
<b>Workaround:</b> Disable FICON Read Pipelining	
<b>Recovery:</b> The I/O recovers on its own - no further action is required.	

<b>Defect ID:</b> DEFECT000523451	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Other
<b>Reported In Release:</b> FOS7.2.0	<b>Technology Area:</b> Other
<b>Symptom:</b> Customer may experience a cold boot on the DCX after bouncing FCoE port	
<b>Condition:</b> This may occur during a small timing window, when an external FCoE interface goes down, the corresponding internal FI ports is moved to temporary internal state and ELS frames arrive at the same time, triggering a CPU busy condition.	
<b>Recovery:</b> Switch cold boots and recovers on its own. No further recovery action is necessary.	

<b>Defect ID:</b> DEFECT000523507	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.1.2	<b>Technology Area:</b> Fabric Watch
<b>Symptom:</b> Fabric Watch ST area of SFP class does not change to "pause" when executing CLI " thconfig --pause sfp -area all -port all" or gives any error to indicate that it's not supported.	
<b>Condition:</b> The issue is seen only when the ST area option is used with SFP class. ST is already deprecated in FOS v7.0.0 and no longer supported.	

<b>Defect ID:</b> DEFECT000523796	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Traffic Management
<b>Reported In Release:</b> FOS7.0.0	<b>Technology Area:</b> BB Credits
<b>Symptom:</b> Increased latency and negative performance impact may be encountered in an edge/core configured fabric.	
<b>Condition:</b> This may be observed when hosts exhibiting mild latency behavior are present, along with over-subscribed devices leading to congestion within the fabric.	
<b>Workaround:</b> Remove or Isolate latency devices into QoS zone to avoid impact to others in fabric	

<b>Defect ID:</b> DEFECT000524168	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> Diagnostic Port (D_Port)
<b>Symptom:</b> AG ports get disabled, instead of coming up as N-ports.	
<b>Condition:</b> It happens when connecting AG to switch with On-Demand D_Port's ports.	

## Closed with code in Fabric OS v7.3.1

<b>Defect ID:</b> DEFECT000524328	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> Monitoring and Alerting Policy Suite (MAPS)
<b>Symptom:</b> User will not see rules triggered for utilization statistic.	
<b>Condition:</b> This only applies to FOS7.3.0 and later	

<b>Defect ID:</b> DEFECT000525285	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> System
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> CLI
<b>Symptom:</b> CLI command "firmwaredownload" may fail with SULB-1011 raslog message "Firmwaredownload command failed. Unexpected reboot occurred during firmware download. The command is aborted." but with no apparent unexpected actual reboot.	
<b>Condition:</b> This may occur in a rare situation from a failure in setting an internal state variable. The resulting unexpected state leads firmwaredownload to infer there has been an unexpected reboot.	
<b>Recovery:</b> Rerun the firmwaredownload command.	

<b>Defect ID:</b> DEFECT000525347	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Traffic Management
<b>Reported In Release:</b> FOS7.0.2	<b>Technology Area:</b> FC-FC routing
<b>Symptom:</b> Customer may observe performance issues between multiple servers and storage with EX-port connected to VDX	
<b>Condition:</b> This may occur when there are link level errors that trigger credit loss on 16G EX port and there was prior HA warm recovery that disabled credit leak detection.	
<b>Recovery:</b> Bounce the port to recover	

<b>Defect ID:</b> DEFECT000525834	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> Web Tools
<b>Symptom:</b> Invalid IP Address/Domain is populated in the "Please Login" WEB Tools dialog display, disregarding the configured details.	
<b>Condition:</b> When both ipv4/ipv6 are configured: 1. ipv4 address is shown when attempting to login via ipv6  2. ipv4 address is shown when attempting to login with domain name	

<b>Defect ID:</b> DEFECT000526158	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Other
<b>Reported In Release:</b> FOS7.0.2	<b>Technology Area:</b> Other
<b>Symptom:</b> Customer may observe increasing er_crc_good_eof and er_enc_in errors on backend ports, leading to performance problems.	
<b>Condition:</b> This may be seen in a DCX 8510-8 system with FC8-64 port blades in slots 1, 2, 11, 12;	
<b>Recovery:</b> Additional tuning on DCX-4s with FC8-16, FC8-32, FC8-48 and FC8-64.	

## Closed with code in Fabric OS v7.3.1

<b>Defect ID:</b> DEFECT000526777	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.2.0_hit	<b>Technology Area:</b> Platform Services
<b>Symptom:</b> When SVP sends the expansion commands, the BR6546 doesn't respond to the requests intermittantly. The result is that some of the internal ports may not be properly enabled/disabled.	
<b>Condition:</b> The issue happens when BR6546 is busy processing the previous request and can't respond to the new ones. And the additional polling period is larger than the SVP's retry interval so it can't catch the retry requests from SVP.	
<b>Workaround:</b> The issue has been fixed by optimizing the polling mechanism and the request response routines so that it won't miss the retries from SVP.	
<b>Recovery:</b> Combined with the fix on IOSW, the issue can be recovered if SVP sends retry request at proper intervals.	

<b>Defect ID:</b> DEFECT000526934	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Distance
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> FCIP
<b>Symptom:</b> CLI "portcfg ipif ge2.dp0 delete 2102:211:31:dead::2:7" returns "IP Address configuration on BCM failed" message	
<b>Condition:</b> Run a scrip to perform tunnel deletion/creation in a loop, issue was seen during second deletion	

<b>Defect ID:</b> DEFECT000527848	
<b>Technical Severity:</b> High	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> FICON
<b>Reported In Release:</b> FOS7.2.0	<b>Technology Area:</b> FICON emulation
<b>Symptom:</b> FCIP FICON emulated Tape VM SPOOL DUMP jobs fail after FOS upgrade	
<b>Condition:</b> This may be seen upon upgrade to FOS v7.2.0d, when using FICON Tape Emulation for VM tape operations	
<b>Workaround:</b> Disable FCIP FICON Tape emulation or downgrade to a FOS version without fix for TR 414719	

<b>Defect ID:</b> DEFECT000527997	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Management
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> Licensing
<b>Symptom:</b> FOS7.3.0 LicenseShow no longer shows capacity values for capacity based licenses on switches.	
<b>Condition:</b> Customer using "licenseshow" with FOS7.3.0 or later. Director products are not impacted.	

<b>Defect ID:</b> DEFECT000528085	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Traffic Management
<b>Reported In Release:</b> FOS7.2.1	<b>Technology Area:</b> Name Server / Zoning
<b>Symptom:</b> Devices are unable to discover their targets due to failure of login (PLOGI) to the Name Server because the PLOGI never receives a response.	
<b>Condition:</b> This may be encountered when running FOS versions v7.2.1a or higher and back-to-back FLOGIs are sent from a device such that the second FLOGI is sent before the device receives an ACC for the first FLOGI.	

## Closed with code in Fabric OS v7.3.1

<b>Defect ID:</b> DEFECT000528207	
<b>Technical Severity:</b> Medium	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Monitoring/RAS
<b>Reported In Release:</b> FOS7.1.0	<b>Technology Area:</b> Bottleneck Detection
<b>Symptom:</b> Inconsistent slot/port display format in Bottleneck Detection related RASLOG messages make it hard to read, track, and program to monitor these messages.	
<b>Condition:</b> This may occur when there is congestion or slow drain devices in a fabric.	

<b>Defect ID:</b> DEFECT000528631	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Traffic Management
<b>Reported In Release:</b> FOS6.4.2	<b>Technology Area:</b> Name Server / Zoning
<b>Symptom:</b> Fibre Channel Common Transport (FC_CT) response to GPL query exceeds maximum allowed size and causes 3rd party HBA in a non-responsible state.	
<b>Condition:</b> This happens when HBA makes the GPL query to remote switch. Query to directly connected switch is not impacted.	

<b>Defect ID:</b> DEFECT000531265	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Distance
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> Extended Fabrics
<b>Symptom:</b> During an upgrade of BR7800 from FOS v7.1.0 or later to FOS v7.1.2a, FOSv7.1.2b, FOSv7.3.0, v7.3.0a, v7.3.0b, v7.3.0c, the switch may go into a rolling reboot.	
<b>Condition:</b> This is encountered only if the switch was shipped with FOS7.1.0GA or later.	

<b>Defect ID:</b> DEFECT000531517	
<b>Technical Severity:</b> High	<b>Probability:</b> High
<b>Product:</b> FOS	<b>Technology:</b> Traffic Management
<b>Reported In Release:</b> FOS7.0.2	<b>Technology Area:</b> Port Bring-up
<b>Symptom:</b> Link to host failed to come up when configured at 'Fixed 4 Gbps'. Trace dump shows that the host issued NOS/OLS/LIP primitives after speed negotiation, but the switch did not respond.	
<b>Condition:</b> Switch port configured with "Fixed 4G" mode may get its RX incorrect when connected to 8G HBA in Auto Negotiate (AN) mode.	

<b>Defect ID:</b> DEFECT000531571	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Traffic Management
<b>Reported In Release:</b> FOS7.0.0	<b>Technology Area:</b> Port Bring-up
<b>Symptom:</b> Port blade remained faulted after a power event.	
<b>Condition:</b> This may occur in a rare scenario, when CP is up for a while and memory is utilized to cache file system buffers and a blade is power cycled. In this small timing window, this may lead to free memory not being readily available for blade initialization.	
<b>Recovery:</b> slotpoweroff/on the blade to recovery	

## Closed with code in Fabric OS v7.3.1

<b>Defect ID:</b> DEFECT000532851	
<b>Technical Severity:</b> High	<b>Probability:</b> Low
<b>Product:</b> FOS	<b>Technology:</b> Security
<b>Reported In Release:</b> FOS7.3.0	<b>Technology Area:</b> Security Vulnerability
<b>Symptom:</b> Security vulnerability CVE-2009-1895 makes it easier for local users to leverage the details of memory usage.	
<b>Condition:</b> The personality subsystem in the Linux kernel before 2.6.31-rc3 has a PER_CLEAR_ON_SETID setting does not clear the security-relevant compatibility flags when executing a setuid or setgid by a program, which makes it easier for local users to leverage the details of memory usage to (1) conduct NULL pointer dereference attacks,(2)bypass the mmap_min_addr protection mechanism, or(3)defeat address space layout randomization	

<b>Defect ID:</b> DEFECT000532888	
<b>Technical Severity:</b> Medium	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> FICON
<b>Reported In Release:</b> FOS7.1.0	<b>Technology Area:</b> FICON emulation
<b>Symptom:</b> I/O Errors to FICON extended device over an FCIP Tunnel with FICON Emulation features enabled.	
<b>Condition:</b> When running FICON channel programs to an extended device that includes Repeat Execution CCW commands (typically used in Disk I/O channel programs).	
<b>Workaround:</b> Disable the FCIP FICON emulation Idle Status Accept feature. The feature can be disabled via the following command: portcfg fcip tunnel <slot/>vePort modify --ficon-debug NewFlags Where NewFlags includes the 0x1000 bit.	



## Closed without Code Change in Fabric OS v7.3.1

This section lists the defects with Critical, High and Medium Technical Severity closed without a code change as of December 12, 2014 in Fabric OS v7.3.1

<b>Defect ID:</b> DEFECT000533422	<b>Technical Severity:</b> High
<b>Reason Code:</b> Already Fixed in Release	<b>Probability:</b> Medium
<b>Product:</b> FOS	<b>Technology:</b> Traffic Management
<b>Reported In Release:</b> FOS7.2.1	<b>Technology Area:</b> FC-FC routing
<b>Symptom:</b> Fabric router switch may observe panic upon receiving invalid frame from edge switch.	
<b>Condition:</b> This happens when fabric router running FOS7.2.x or earlier receives unknown Fibre Channel Common Transport (FC_CT) request from edge switch with zero sized payload. This does not apply to FOS v7.3.x or later.	
<b>Recovery:</b> Disable edge switch port and upgrade.	

