

December 19, 2017



Fabric OS v8.0.2d for Brocade SAN Product Family Release Notes v1.0

Copyright © 2017 Brocade Communications Systems LLC. All Rights Reserved.

Brocade and the stylized B logo are among the trademarks of Brocade Communications Systems LLC. Broadcom, the pulse logo, and Connecting everything are among the trademarks of Broadcom. The term "Broadcom" refers to Broadcom Limited and/or its subsidiaries

Brocade, a Broadcom Limited Company, reserves the right to make changes without further notice to any products or data herein to improve reliability, function, or design. Information furnished by Brocade is believed to be accurate and reliable. However, Brocade does not assume any liability arising out of the application or use of this information, nor the application or use of any product or circuit described herein, neither does it convey any license under its patent rights nor the rights of others.

The product described by this document may contain open source software covered by the GNU General Public License or other open source license agreements. To find out which open source software is included in Brocade products, view the licensing terms applicable to the open source software, and obtain a copy of the programming source code, please visit <http://www.brocade.com/support/oscd>.

Contents

Document History	7
Preface	8
Contacting Brocade Technical Support	8
Brocade Customers	9
Brocade OEM customers	9
Related Documentation	9
Locating product manuals and Release Notes	10
Locating product manuals	10
Selecting by Product	11
Selecting by Operating System	14
Locating release notes	15
Document feedback	17
Overview	18
Resolution of Important Defects	18
Software features	18
Modified software features	18
What is New in FOS v8.0.2	19
Hardware	19
New Hardware	19
New optical transceivers	19
New blades	19
Software features	19
Modified software features	19
What is New in FOS v8.0.1b	20
Software features	20
Modified software features	20
What is New in FOS v8.0.1	21
Hardware	21
New devices	21
New blades	21
Deprecated hardware	22
Software features	22
New software features	22

Modified software features	22
Fabric Performance Impact (FPI) monitoring.....	22
Monitoring and Alerting Policy Suite (MAPS)	22
Flow Vision	24
FCIP and IP Extension.....	24
Zoning.....	26
Security	26
RAS	27
Fibre Channel Routing (FCR)	27
ClearLink Diagnostics (D_Port).....	28
DHCP for Management Interface.....	28
Management Server	28
SNMP.....	28
Miscellaneous Enhancements	28
Deprecated software features	29
Bottleneck Detection	29
Port Mirroring	29
Administrative Domain	29
CLI Changes	30
New Commands.....	30
Modified Commands.....	30
Deprecated commands.....	30
Supported standards and RFCs	30
Software License Support	31
Optionally Licensed Software	31
Temporary License Support	33
Hardware Support.....	35
Supported devices.....	35
Supported blades	35
DCX 8510-8/DCX 8510-4 blade support.....	35
X6-8/X6-4 blade support.....	35
Supported power supplies	36
Brocade G620 Power Supplies	36
DCX8510-8 Power Supply Requirements.....	36

DCX8510-4 Power Supply Requirements.....	38
X6-8 Power Supply Requirements	38
X6-4 Power Supply Requirements	39
Supported optics.....	39
Software Upgrades and Downgrades	40
Image filenames.....	40
Migration Path	40
Migrating from FOS v8.0.1	40
Migrating from FOS v8.0.0	40
Migrating from FOS v7.4	40
Migrating from FOS v7.3	40
Upgrade/downgrade considerations	40
Limitations and Restrictions.....	42
Scalability	42
Compatibility/interoperability	42
Brocade Network Advisor Compatibility.....	42
WebTools Compatibility.....	43
SMI Compatibility.....	43
Fabric OS Compatibility.....	43
SNMP Support.....	44
Obtaining the MIBs	44
Important Notes.....	45
In-flight Encryption and Compression	45
ClearLink Diagnostics (D_Port).....	45
Forward Error Correction (FEC).....	45
Access Gateway	45
Ingress Rate Limiting.....	45
Ethernet Management Interface	46
Extension.....	46
Brocade Analytics Monitoring Platform.....	46
Flow Vision	48
FICON	48
Miscellaneous	48
Defects	49

Closed with code changes in Fabric OS 8.0.2d.....	49
Closed with code changes in Fabric OS 8.0.2c	55
Closed with code changes in Fabric OS 8.0.2b.....	60
Closed with code changes in Fabric OS 8.0.2a	68
Closed with code changes in Fabric OS 8.0.2.....	74
Closed with code changes in Fabric OS 8.0.1b.....	125
Closed with code changes in Fabric OS 8.0.1a	126
Closed with code changes in Fabric OS 8.0.1.....	134
Closed without code changes in Fabric OS 8.0.1	164
Open Defects in Fabric OS 8.0.1.....	171

Document History

Version	Summary of Changes	Publication Date
v1.0	Initial Release	December 19, 2017

Preface

Contacting Brocade Technical Support

As a Brocade customer, you can contact Brocade Technical Support 24x7 online, by telephone, or by email. Brocade OEM customers contact their OEM/Solutions provider. To expedite your call, have the following information immediately available:

1. General Information

- Technical Support contract number, if applicable
- Switch model
- Switch operating system version
- Error numbers and messages received
- **supportSave** command output and associated files
- For dual CP platforms running FOS v6.2 and above, the **supportSave** command gathers information from both CPs and any AP blades installed in the chassis
- Detailed description of the problem, including the switch or fabric behavior immediately following the problem, and specific questions
- Description of any troubleshooting steps already performed and the results
- Serial console and Telnet session logs
- Syslog message logs

2. Switch Serial Number

The switch serial number is provided on the serial number label, examples of which are shown here:



The serial number label is located as follows:

- Brocade 6510, 6505, 6520, G620 — On the switch ID pull-out tab located on the bottom of the port side of the switch
- Brocade 7840 — On the pull-out tab on the front left side of the chassis underneath the serial console and Ethernet connection and on the bottom of the switch in a well on the left side underneath (looking from front)
- Brocade DCX 8510-8 — Bottom right of the port side
- Brocade DCX 8510-4 — Back, upper left under the power supply
- Brocade X6-8, X6-4 — Lower portion of the chassis on the nonport side beneath the fan assemblies

3. World Wide Name (WWN)

When the Virtual Fabric feature is enabled on a switch, each logical switch has a unique switch WWN. Use the **wwn** command to display the switch WWN.

If you cannot use the **wwn** command because the switch is inoperable, you can get the primary WWN from the same place as the serial number.

4. License Identifier (License ID)

There is only one License Identifier associated with a physical switch or director/backbone chassis. This License Identifier is required as part of the ordering process for new FOS licenses.

Use the **licenseIdShow** command to display the License Identifier.

Brocade Customers

For product support information and the latest information on contacting the Technical Assistance Center, go to <http://www.brocade.com/services-support/index.html>.

If you have purchased Brocade product support directly from Brocade, use one of the following methods to contact the Brocade Technical Assistance Center 24x7.

Online	Telephone	E-mail
Preferred method of contact for non-urgent issues:	Required for Sev 1-Critical and Sev 2-High issues:	support@brocade.com
• My Cases through MyBrocade • Software downloads and licensing tools • Knowledge Base	• Continental US: 1-800-752-8061 • Europe, Middle East, Africa, and Asia Pacific: +800-AT FIBREE (+800 28 34 27 33) • For areas unable to access toll free number: +1-408-333-6061 • Toll-free numbers are available in many countries.	Please include: • Problem summary • Serial number • Installation details • Environment description

Brocade OEM customers

If you have purchased Brocade product support from a Brocade OEM/Solution Provider, contact your OEM/Solution Provider for all of your product support needs.

- OEM/Solution Providers are trained and certified by Brocade to support Brocade® products.
- Brocade provides backline support for issues that cannot be resolved by the OEM/Solution Provider.
- Brocade Supplemental Support augments your existing OEM support contract, providing direct access to Brocade expertise. For more information, contact Brocade or your OEM.
- For questions regarding service levels and response times, contact your OEM/Solution Provider.

Related Documentation

Visit the Brocade website to locate related documentation for your product and additional Brocade resources such as white papers, online demonstrations, and data sheets.

You can download additional publications supporting your product at www.brocade.com. You can either use the search tool at the top right of the page, or navigate to the pages specific to your product. To do this, click the Brocade Products & Services tab, then click the Brocade product type, and finally click on the name or image for your product to open the individual product page. The user manuals are available in the Resources section at the bottom of the page.

To get up-to-the-minute information on Brocade products and resources, go to MyBrocade.com. You can register at no cost to obtain a user ID and password. Release notes are available on MyBrocade under Product Downloads.


Locating product manuals and Release Notes

The following sections outline how to locate and download Brocade product manuals and release notes from mybrocade.com. While the illustrations show Fabric OS (OS), they work for all Brocade products and operating systems.


Locating product manuals

Complete the following steps to locate your product manuals in MyBrocade.com.

1. Open <http://my.brocade.com> and log in.
If you do not have a login, registration is free. Click on **Register Now** and follow the directions.
2. Once you have logged in, the product manuals can be found by clicking **Documentation Library**.



3. Select **Products** to browse product guides and overview information, or select Operating Systems to browse by Brocade operating system. Alternatively, you can enter a term in the search bar.



Selecting by Product

1. If you click **Product**, choose your Product from the displayed panel.


Choose a Product or Operating System

Select Products to browse product guides and overview information by hardware or software product. To browse by Brocade operating system, select Operating Systems..


Products	Operating Systems
Application Delivery Controllers	
Mobile Networking	
Network Automation Platforms	
Network Management	
Network Visibility & Analytics	
Routers	
Software Networking	
Storage Networking	
Switches	
Transceivers	
Wireless LAN	

As you make your selections, the columns to the right will fill in with the available options.

The following illustration shows an example of selecting **Storage Networking** and **Fibre Channel**.




2. Click on the product whose documentation you want to view. This opens the Document Library for that product.




3. Click on the link for the document you want to read, and then open or save it. You may have to scroll inside the results to see the document you want.

Selecting by Operating System

1. If you click **Operating System**, choose your Operating System from the displayed panel.



2. Click on the name of the Operating System whose documentation you want to view. This opens the Document Library for that OS.
3. Locate and select the manuals you want to view from the results on the Product Guides tab.




4. Click on the link for the document you want to read, and then open or save it. You may have to scroll inside the results to see the document you want.


Locating release notes

Complete the following steps to locate the release notes for your product in MyBrocade.com.


1. Open <http://my.brocade.com> and log in.
If you do not have a login, registration is free. Click on **Register Now** and follow the directions.
2. Once you have logged in, the product manuals can be found using the following procedure.
3. Click **Software & Driver Downloads** under Licenses & Downloads.
4. Select the product type or enter the product name in the search field, and click **Search**.



5. The most recent release note document is shown.



6. Clicking the down arrow expands to show more results.



Browse or

Fabric Operating System (FOS) 8.X ^

[Brocade Fabric OS Target Path Selection Guide \(html, 0.51 KB\)](#)

Fabric Operating System (FOS) 8.0.x	08-31-2016	^
Fabric Operating System (FOS) 8.0.1b GA	08-31-2016	v
Fabric Operating System (FOS) 8.0.1a GA	06-30-2016	v
Fabric Operating System (FOS) 8.0.1 Manuals	09-27-2016	v
Fabric Operating System (FOS) 8.0.1 GA	04-22-2016	v
Fabric Operating System (FOS) 8.0.0_GFT Brocade GA	03-21-2016	v
Fabric Operating System (FOS) 8.0.0 Manuals	05-27-2016	v
Fabric Operating System (FOS) 8.0.0 GA	12-16-2015	v

Fabric Operating System (FOS) 7.X v

7. Select the Release Notes you want from the displayed results.

Document feedback

To send feedback and report errors in the documentation you can use the feedback form posted with the document or you can e-mail the documentation team.

Quality is our first concern at Brocade and we have made every effort to ensure the accuracy and completeness of this document. However, if you find an error or an omission, or you think that a topic needs further development, we want to hear from you. You can provide feedback in two ways:

- Through the online feedback form in the HTML documents posted on www.brocade.com.
- By sending your feedback to documentation@brocade.com.

Provide the publication title, part number, and as much detail as possible, including the topic heading and page number if applicable, as well as your suggestions for improvement.

Overview

Fabric OS v8.0.2d is a patch release based on FOS v8.0.2c. All hardware platforms and features supported in FOS v8.0.2c are also supported in FOS v8.0.2d. This release contains fixes for defects listed at the end of this document.

Resolution of Important Defects

- DEFECT000656422 - Webtools client launch will be blocked by Java Security.

Software features

The following section lists new, modified, and deprecated software features for this release.

Modified software features

The following software features have been modified in this release.

- MAPS monitoring of Class 3 Timeout Discard Frames (C3TXTO) metric under the Port Health category to detect and alert C3TXTO error when it exceeds threshold during a port offline and online.

What is New in FOS v8.0.2

Hardware

The following section lists new hardware introduced or existing hardware support added with this release as well as hardware that are no longer supported with this release.

New Hardware

FOS v8.0.2 merges in the support for the following embedded platforms, in addition to all hardware platforms supported in FOS v8.0.1b.

- Brocade 6542 (embedded switch)

New optical transceivers

FOS v8.0.2 supports the following new optical transceivers on the noted devices

- 40GbE ER4 40km QSFP (part number 57-1000327-01) on Brocade 7840
- SmartOptics 8G DWDM 70km SFP+ (part number 8G-ZR-Dxxx-BR1) on Brocade 6505, 6510, 6520, 7840, and DCX8510.
- SmartOptics 16Gbps DWDM 40km SFP+ (part number 16G-ER-Dxxx-BR1) on Brocade G620, X6 with FC32-48 and SX6.
- SmartOptics 16Gbps DWDM 40km SFP+ (part number 16G-ER-Dxxx-BR2) on Brocade 6505, 6510, 7840, DCX8510, G620, X6 with FC32-48 and SX6. Not supported on 6520.
- SmartOptics 16Gbps ER 40km SFP+ (part number 16G-ER-BR2) on Brocade 6505, 6510, 7840, DCX8510, G620, X6 with FC32-48 and SX6. Not supported on 6520.

New blades

FOS v8.0.2 adds the support of the following blades in Brocade DCX8510. Earlier FOS v8.x releases, including FOS v8.0.0, FOS v8.0.1, FOS v8.0.1a, and FOS v8.0.1b, do not support these blades.

- FC8-32E, FC8-48E, and FC8-64.

Software features

The following section lists new, modified, and deprecated software features for this release.

Modified software features

The following software features have been modified in this release.

- Remove TACACS+ shared secret configuration from supportSave files.
- Add **–force** or **–f** option to **cfgSave**, **cfgEnable**, and **cfgDisable** command to bypass the confirmation prompt

What is New in FOS v8.0.1b

Software features

The following section lists new, modified, and deprecated software features for this release.

Modified software features

The following software features have been modified in this release.

- Web Tools system logs capture Switch Admin and Zone Admin configuration changes.
- Web Tools Ethernet IPSec policies disable IKE policy creation.
- Enhancement to RAS-1007 message to log username when reboot is initiated through SNMP user.

What is New in FOS v8.0.1

Hardware

The following section lists new hardware introduced with this release as well as hardware that are no longer supported with this release.

New devices

Product name	Device Name
Brocade X6-8 Director	Gen 6 Fibre Channel 8-slot Director
Product features	Key features • Up to 384 ports at 32 Gbps • 32 UltraScale ICLs equivalent to 128 32-Gbps ports • 16.2 Tbps aggregate chassis bandwidth • 1.5 Tbps bandwidth per slot • Fabric Vision features and IO Insight capability
Brocade X6-4 Director	Gen 6 Fibre Channel 4-slot Director
Product features	Key features • Up to 192 ports at 32 Gbps • 16 UltraScale ICLs equivalent to 64 32-Gbps ports • 8.1 Tbps aggregate chassis bandwidth • 1.5 Tbps bandwidth per slot • Fabric Vision features and IO Insight capability

New blades

Blade	Description	Compatible devices
Brocade SX6 Extension Blade	Gen 6 Fibre Channel and IP Extension Blade with 16 x 32 Gbps Fibre Channel ports, 16 x 1/10 GbE and 2 x 40 GbE ports	Brocade X6 Director
Brocade FC32-48 Port Blade	Gen 6 Fibre Channel port blade with 48 x 32 Gbps ports	Brocade X6 Director
Brocade CPX6 Control Processor Blade	Control processor blade for Brocade X6 Director	Brocade X6 Director
Brocade CR32-4 Core Routing Blade	Core routing blade for Brocade X6-4 Director	Brocade X6-4 Director
Brocade CR32-8 Core Routing Blade	Core routing blade for Brocade X6-8 Director	Brocade X6-8 Director

Deprecated hardware

The following Brocade devices are no longer supported starting with this release.

- 300, 5100, 5300, 7800, VA-40FC, Brocade Encryption Switch, DCX, DCX-4S
- 5410, M5424, 5430, 5431, 5432, 5450, 5460, 5470, 5480, NC-5480

The following blades are no longer supported starting with this release.

- FC8-16, FC8-32, FC8-48, FS8-18, FCOE10-24.

Note: Support for FC8-32E, FC8-48E, and FC8-64 blades in DCX 8510 platforms has not been deprecated. However, FOS v8.0.1 does not support these blades in DCX 8510 platforms. Support for these blades is added to FOS v8.0.2.

Software features

The following section lists new, modified, and deprecated software features for this release.

New software features

The following software features are new in this release.

- Support for Brocade X6 Director with FC32-48 port blades and SX6 extension blades.
- Support for IO Insight — a built-in device-level IO performance and latency instrumentation capability

Modified software features

The following software features have been modified in this release.

Fabric Performance Impact (FPI) monitoring

FOS v8.0.1 enhances FPI monitoring to include the FPI monitoring rules and thresholds in the MAPS default base policy. Switches running FOS v8.0.1 without a Fabric Vision license are monitored by MAPS for congestion and slow drain device conditions.

Note: FOS v8.0.1 adds Email and SNMP alerts with the MAPS base policy. The available actions with the MAPS base policy are RASLog, Email, and SNMP alerts. Other actions, including Port Fencing, Port Decommissioning, Port Toggle, and Slow Drain Device Quarantine, require a valid Fabric Vision license.

Monitoring and Alerting Policy Suite (MAPS)

FOS v8.0.1 includes following MAPS enhancements:

Monitor 32Gbps Optics

FOS v8.0.1 adds monitoring of supported 32 Gbps SWL SFP, 32 Gbps LWL SFP, and 4x32 Gbps SWL QSFP optics on Gen 6 platforms to the default MAPS policy. These new optics are monitored within their respective new logical groups.

Monitor Security Certificate Expiration

FOS v8.0.1 adds monitoring the validity period of digital security certificates present on Brocade switches. This provides administrators expiry notification before any security certificates actually expire.

Monitor Gigabit Ethernet Ports

FOS v8.0.1 adds the ability to monitor link layer error statistics for Gigabit Ethernet ports on extension platforms, which includes the Brocade 7840, FX8-24 blades, and SX6 blades. This monitoring provides advanced notification of Ethernet link layer problems that could result in performance degradation or disruption to the distance extension traffic. This monitoring does not apply to the management Ethernet interface on Brocade switches.

Monitor FCIP Tunnel and Tunnel QoS

FOS v8.0.1 extends MAPS monitoring of FCIP tunnels and the tunnels at each QoS level to the SX6 blade. Bandwidth utilization and state change are monitored for FCIP tunnels, while utilization and packet loss are monitored for FCIP tunnels for each QoS level. The pre-defined thresholds and rules for SX6 blades are the same as those for the Brocade 7840 platform in FOS v7.4.

Monitor IP Extension Circuit and Tunnel

FOS v8.0.1 adds MAPS monitoring for IP circuits and tunnels on the Brocade 7840 extension platform and SX6 blades. IP Extension monitoring provides advanced notification of WAN performance and latency problems and helps with troubleshooting IP storage traffic that has been extended through WANs.

Monitor System Air Flow

FOS v8.0.1 adds MAPS monitoring for system airflow directions to provide alerts if the air flow directions of the fan or power supply FRUs in the hardware platforms are installed incorrectly. This avoids potential disruptive shutdown of hardware platforms resulting from mismatched air flow directions. MAPS airflow direction monitoring applies to the following hardware platforms that support different airflow direction configurations: Brocade 6505, 6510, 6520, 7840, X6-8, X6-4, and G620.

Monitor Initiator and Target Device Ratio

FOS v8.0.1 adds the ability to monitor the ratio between initiator and target devices zoned together across entire zoning configuration. Initiator-to-target or target-to-initiator ratios higher than best practices have the potential of causing slow IO response time that may impact fabric performance. This monitoring can alert administrators to this condition, enabling them to take corrective action.

Monitor IO Insight Metrics

FOS v8.0.1 adds the support in MAPS to monitor the IO Insight metrics for initiator-target or initiator-target-LUN flow monitors that are created with the Flow Vision feature on Brocade Gen 6 platforms. This monitoring allows administrators to be alerted if application or storage device level IO performance and latency measures drop below predetermined thresholds such as those mandated by service level agreements.

Quiet Time Support for SNMP

FOS v8.0.1 extends the quiet time support to the SNMP alert actions so that users can configure MAPS rules to bypass sending duplicate SNMP trap messages for repeat violations.

MAPS platform dependent default policies

FOS v8.0.1 changes MAPS default policies so that only rules applicable to a specific platform are included in the default policies for that platform. Please refer to the *MAPS rules and groups altered in this release* section of the *Brocade Monitoring and Alerting Policy Suite Configuration Guide* for detailed policy changes.

Miscellaneous

FOS v8.0.1 includes the following miscellaneous MAPS usability enhancements.

- MAPS dashboard displays fenced extension circuits for Brocade 7840, FX8-24, and SX6.
- MAPS dashboard history data value display includes unit symbol to improve readability.
- MAPS RASLog and email alerts for switch ports include switch port names.
- MAPS RASLog and email alerts for back-end port include added peer connection port numbers.
- If MAPS detects an email alert delivery failure, a RASLog message (MAPS-1206) is recorded.
- MAPS email alert message content enhancements to improve readability.
- Removal of SW_MARGINAL and SW_CRITICAL actions from **mapsConfig** command. These actions are now enabled by default and cannot be disabled.

Flow Vision

FOS v8.0.1 provides the following new capabilities and enhancements to Flow Vision.

Flow Monitor support for IO Insight

FOS v8.0.1 extends the Flow Monitor feature to support the IO Insight capability built in to Brocade Gen 6 platforms. Flow Monitor provides administrators the capability to non-disruptively and non-invasively obtain key SCSI IO performance and latency metrics for initiator-target or initiator-target-LUN flows.

Flow Monitor on VE port

FOS v8.0.1 supports Flow Monitor static and learning flow support on VE ports on the Brocade 7840 and the SX6 blade. The Flow Monitor support on VE ports is equivalent to those provided on E_Ports available in FOS v7.4.

SRR Frame Type

FOS v8.0.1 supports a new frame type in Flow Vision, the Sequence Retransmission Request (SRR) frame, which is used in FC-Tape backup for error recovery. This frame type support allows administrators to see that the FC-Tape devices are in error recovery mode, which increases application response time.

Fabric Flow Dashboard Enhancements

FOS v8.0.1 enhances the Flow Dashboard with the following new data:

- MAPS history data for ports and back-end ports
- Identification of ports that have been fenced, decommissioned, or quarantined by MAPS actions

FCIP and IP Extension

FOS v8.0.1 provides additional enhancements to Brocade storage extension products beyond supporting the new SX6 blade in X6-8 and X6-4 directors.

Extension Non-disruptive Firmware Download on X6

FOS v8.0.1 supports non-disruptive firmware download for the FCIP extension traffic on the SX6 blades in an X6-8 or X6-4 director. Non-disruptive firmware download is performed in parallel on the maximum number of SX6 blades supported in a director. SX6 blades in different configuration modes, i.e., 10VE, 20VE, or hybrid, are supported with non-disruptive firmware download. The FOS **firmwaredownloadstatus** includes the firmware download completion status of the extension platform data processor (DP). If a DP has not completed firmware download, additional **firmwaredownload**, **firmwarerestore**, **hafailover** or **hareboot** commands will be blocked.

IP Extension PBR Support for LAN Traffic

FOS v8.0.1 adds policy-based routing (PBR) topology support for LAN connectivity of IPEXT traffic. This allows L3 (routing) connections in addition to the L2 (direct) connections to the extension platform. In PBR configuration, LAN ports are connected to routers and the next-hop gateway is configured in the Data Processor of the distance extension platform. Similarly, PBR is configured in the router to route traffic between host and distance extension platform.

IP LAN Connection History

FOS v8.0.1 enhances the command output of the **portshow lan-stats --hist-stats** command to provide additional information about the TCP connections that have been extended via IPEXT emulation. These enhancements provide the TCP flag used to close the connection, the last five TCP states of the connection, the location/reason why the connection closure occurred, and the creation of a freeze/thaw functionality.

Extension Trunking Spillover Load Balancing Algorithm

FOS v8.0.1 supports a new load balancing algorithm for tunnels named “spillover”. This algorithm allows administrators to define circuits that will only be used under high bandwidth utilization and/or congestion conditions. The default algorithm is failover, which will only use higher metric circuits when lower metric circuits are down.

Automatic WAN Tool

FOS v8.0.1 introduces the automatic WAN Tool (AWT) support to extend the WAN Test Tool. With this support, WAN Tool tests can run automatically in accordance with defined Service Level Agreement (SLA) parameters. An FCIP circuit is enhanced to support a SLA policy. This allows AWT to bring a circuit online/offline based on the SLA of the WAN network.

Miscellaneous

FOS v8.0.1 includes the following miscellaneous extension enhancements

- The **extnfcfg** command allows the extension configuration to be reset
- The traffic Control List (TCL) configuration command **portcfg tcl** now supports port ranges and well-known application names.
- The **portshow tcl** command output now supports sorting and priority matching
- Filter options are added to **portshow fcipunnel**, **portshow fcipcircuit**, **portshow tcl**, **portshow ipif**, **portshow lan-stats**, and **portshow iproute** commands to customize output and display only the specific information requested by users.

- Support LAN non-terminated TCP flow to allow control type TCP traffic from IP storage devices across the WAN.
- Generate RASLog message (XTUN-3100 and 3101) when IP-Extension TCP connection count per DP is equal to and greater than 500.
- Increase the maximum number of supported Traffic Control List (TCL) per DP from 128 to 256.

Zoning

FOS v8.0.1 provides the following enhancements to zoning.

Peer Zoning RSCN Enhancement

FOS v8.0.1 generates a Peer Zoning Change RSCN when administrator actions result in the addition or removal of a Target-Driven Peer Zone from the effective zoning configuration or when the Target Driven Zoning mode on a port is enabled or disabled.

Automatic Zone Configuration Creation for Target Driven Zoning

FOS v8.0.1 automatically creates a zone configuration if one does not exist when the fabric receives supported Target Driven Zoning commands.

zoneShow Command Enhancements

FOS v8.0.1 enhances the **zoneshow --alias** command to accept a string pattern to search for zones that match the pattern among zoning configuration database.

Zoning Name Enforcement to Avoid Boot LUN Zone Conflict

FOS v8.0.1 enforces zoning creation rules to disallow a zone to be created with “BFA_” as a zone name prefix or “_BLUN” as a zone name suffix. In addition, any WWN with prefix “00:00:00:..” is rejected to avoid conflicts with boot LUN zones.

Security

FOS v8.0.1 provides the following enhancements to system security.

Stronger Switch Password Hash Algorithm

FOS v8.0.1 adds the support for both SHA-256 and SHA-512 as password hash algorithms to increase the security protection of switch passwords. MD5 password hash continues to be supported for backward compatibility. The default password hash is SHA-512 for a switch with FOS v8.0.1 installed from manufacturing.

Password Policy Enhancements

FOS v8.0.1 enhances switch password policy to add the support of setting a minimum character set in the password policy and disallowing usernames as part of a password.

Restricted Time of Day Access

FOS v8.0.1 adds the ability to specify a time-of-day restriction on user accounts. Once configured, the accounts can only access the switch during the specified time of day. The “time of day” access restriction applies to all interfaces that a FOS switch supports, including Telnet, Console, SSH, and HTTP/HTTPS.

Removal of “factory” Account

FOS v8.0.1 removes the legacy “factory” default account. Removing this account does not have any impact on switch operational or administrative operation.

Factory disabling of “root” Account

The default switch “root” account is disabled on switches that have FOS v8.0.1 installed at the factory. For administrators that want to enable the “root” account, a new command **rootAccess** is provided to control the management interfaces allowed to have root account login. In addition, the **userConfig --show** command is enhanced to display an asterisk (*) character next to the account name for any default switch account that has the default factory password set.

Self-Signed HTTPS Certificate

FOS v8.0.1 supports the switch HTTPS certificate generation with self-signing. With this support, administrators can choose to use a self-signed HTTPS certificate or to import a switch certificate signed by an external Certificate Authority (CA).

secCryptoCfg Enhancement

FOS v8.0.1 extends the **secCryptoCfg** command to accept a cipher configuration template file. A template supports configuration for TLS and SSH ciphers.

RAS

FOS v8.0.1 includes the following enhancements to RAS functionalities.

Reset Ethernet Management Interface Counters

FOS v8.0.1 adds the support to reset management Ethernet interface error counters. Resetting the counters helps to troubleshoot Ethernet management interface connectivity problems. The support is provided through the existing **ethif** command. This is supported on Brocade 7840, G620, and X6 only.

Syslog Server

FOS v8.0.1 supports server host names in syslog server configuration. FOS retains the server configuration, either as a host name or as an IP address, as provided by administrators to the **syslogadmin** command.

RASLog

FOS v8.0.1 increases the number of RASLog messages that are persistently saved to 8192 entries for Brocade G620 and X6 platforms. This allows the system to capture more RASLog messages during SupportSave.

Fibre Channel Routing (FCR)

FOS v8.0.1 supports following FCR-related software license enforcement changes.

- Integrated Routing Ports-on-Demand license on Brocade X6 director — FOS v8.0.1 checks the maximum supported EX_Ports when the EX_Port is configured.
- Enterprise ICL license on DCX 8510 directors — FOS v8.0.1 enforces the Enterprise ICL (EICL) license on Inter-Fabric Link (IFL) connections on Brocade DCX 8510 chassis that are using ICL connections. In earlier firmware only ISL connections were counted for enforcing the EICL rule.

ClearLink Diagnostics (D_Port)

FOS v8.0.1 supports D_Ports on Gen 6 platforms with 32 Gbps SFP and 4x32 Gbps QSFPs.

- For 4x32 Gbps QSFPs, the electrical loopback and optical loopback tests are skipped.
- D_Port tests on Gen 6 platforms support ISLs and device connections to third party HBAs.
- In addition to Gen 6 platform support, D_Port tests have been enhanced to allow administrators to specify long duration optical loopback tests. Long-duration optical loopback tests can be run on only one port at a time, and long-duration electrical loopback tests are not supported.

DHCP for Management Interface

FOS v8.0.1 enhances the DHCP support for the management Ethernet interface to include the following:

- DHCP support on DCX 8510 and X6 directors with redundant control processor (CP) blades
- DHCPv6 support for IPv6 address configuration (RFC3315)
- Stateless DHCPv6 server configuration (RFC3736) support for Brocade G620 and X6 to configure parameters for DNS recursive name servers, DNS search lists, and SIP servers.

Management Server

FOS v8.0.1 adds the support for the FC-GS-4 standard “Get Port Speed Capabilities (GPSC)” command in the Management Server.

SNMP

FOS v8.0.1 includes the following enhancements and changes for SNMP.

- The **snmpConfig** command now supports a non-interactive mode to improve configuration through scripting.
- Support for system resource (memory, CPU, and flash) monitoring in Access Gateway mode in the AG MIB.
- Support for 64-bit TX/RX statistics in the SW MIB under the connUnitPortStatEntry object and removal of 32-bit TX/RX statistics under the swFCPort object.

Miscellaneous Enhancements

islShow Command

FOS v8.0.1 increases the supported **islShow** switch name length to 32 characters, so that switch names longer than 15 characters can be fully displayed.

nodeFind Command

FOS v8.0.1 supports entering a WWN as the device input to the **nodefind** command without the colon “:” character between two nibbles. This simplifies the input when running this command.

Dynamic Portname

FOS v8.0.1 enhances the dynamic portname feature to support user-defined formats for dynamic port names. The supported port name fields include: switch name, port type, port index, slot number/port number, F_Port alias, FDMI host name, and remote switch name.

Switch Name

FOS v8.0.1 supports switch names that begin with a numerical character.

portCfgEportCredit Command

FOS v8.0.1 supports BB credit configuration range values from 5 to 160 for Gen 6 (G620 and X6) platforms. The range is unchanged for Gen 5 (16 Gbps) platforms.

portStatsShow Command

FOS v8.0.1 enhances the **portStatsShow** output to include Forward Error Correction (FEC) counter output. Counters are now displayed regardless of whether FEC is configured or a port is online. For Gen 6 platforms (G620 and X6) the FEC correctable counter is replaced with a new FEC corrected rate counter. In addition, the **portStatsShow** command displays additional TXQ latency counters that are available from Gen 6 platforms.

sfpShow Command

FOS v8.0.1 removes the “Alarm/Warn” thresholds displayed by the **sfpShow** command output. These thresholds are inconsistent with the SFP datasheet. Removing these thresholds does not have any functional impact.

Automatic Non-DFE and portCfgNonDfe Command

FOS v8.0.1 automatically activates non-DFE mode on Gen 5 (16 Gbps) platforms if a port non-DFE configuration is disabled, the port is in 8G or N8 speed, and the port receives a fillword of IDLE's. There is no change to ports with non-DFE configuration enabled. The **portCfgNonDfe** command is also enhanced to display the non-DFE activation state of a port.

Deprecated software features

The following software features are deprecated beginning with this release.

Bottleneck Detection

FOS v8.0.1 deprecates support for the Bottleneck Detection feature. The Bottleneck Detection feature included congestion monitoring and latency monitoring through the Advanced Networking (AN) module. Users configured Bottleneck Detection feature using the **bottleneckMon** command. The Bottleneck Detection feature has been replaced with Fabric Performance Impact (FPI) monitoring. FOS v8.0.1 supports FPI monitoring without requiring a Fabric Vision license. Firmware upgrades to FOS v8.0.1 from FOS v7.4.x or earlier version will automatically disable Bottleneck Detection monitoring.

Port Mirroring

FOS v8.0.1 deprecates the Port Mirror feature. This feature is replaced by Flow Mirror within Flow Vision.

Administrative Domain

FOS v8.0.1 deprecates the support for the Admin Domain feature, but does not remove the Admin Domain functionality. However attempts to create, activate, rename, save, or make any other configuration changes to Admin Domains will cause a warning message to be displayed. Support for this feature will be removed in a future release.

CLI Changes

The following section lists new, modified, and deprecated commands for this release.

New Commands

The following commands are new in this release.

- diagStatus
- openSource
- rootAccess

Modified Commands

Refer to the “Modified commands” section in the *Brocade Fabric OS Command Reference* supporting Fabric OS v8.0.1.

Deprecated commands

Refer to the “Deprecated commands” section in the *Brocade Fabric OS Command Reference* supporting Fabric OS v8.0.1.

Supported standards and RFCs

This software conforms to the Fibre Channel standards in a manner consistent with accepted engineering practices and procedures. In certain cases, Brocade might add proprietary supplemental functions to those specified in the standards. For a list of FC standards conformance, visit the following Brocade Web site: <http://www.brocade.com/sanstandards>.

Software License Support

Optionally Licensed Software

Fabric OS 8.0.1 includes all basic switch and fabric support software, as well as optionally-licensed software enabled using license keys.

Optionally-licensed features include:

Brocade Ports on Demand — Allows customers to instantly scale the fabric by provisioning additional SFP ports via license key upgrade. (Applies to select models of switches).

Brocade Q-Flex Ports on Demand — Allows customers to further scale the fabric and increase flexibility by provisioning additional 4x32G QSFP ports via license key upgrade. Applies to Brocade G620 only.

Brocade Extended Fabrics — Provides greater than 10km of switched fabric connectivity at full bandwidth over long distances (depending on platform this can be up to 3000km).

Brocade ISL Trunking — Provides the ability to aggregate multiple physical links into one logical link for enhanced network performance and fault tolerance. Also includes Access Gateway ISL Trunking on those products that support Access Gateway deployment.

Brocade Fabric Vision — Enables support for MAPS (Monitoring and Alerting Policy Suite), Flow Vision, and ClearLink (D_Port) when connecting to non-Brocade devices. MAPS enables rules-based monitoring and alerting capabilities, provides comprehensive dashboards to quickly troubleshoot problems in Brocade SAN environments. Flow Vision enables host to LUN flow monitoring, application flow mirroring for non-disruptive capture and deeper analysis, and test traffic flow generation function for SAN infrastructure validation. D_Port to non-Brocade devices support allows extensive diagnostic testing of links to devices other than Brocade switches and adapters.

Note: On Brocade G620, Brocade X6-8, and Brocade X6-4 platforms, this license enables the use of IO Insight capability. The license itself will be identified as “Fabric Vision and IO Insight” license on these platforms.

FICON Management Server — Also known as “CUP” (Control Unit Port), this enables host control of switches in mainframe environments.

Integrated Routing — This license allows any Fibre Channel port in a DCX 8510-8, DCX 8510-4, Brocade 6510, Brocade 6520, Brocade 7840, or Brocade G620 to be configured as an EX_Port supporting Fibre Channel Routing. This eliminates the need to add an FR4-18i blade or use a Brocade 7500 for FCR purposes, and also provides either quadruple or octuple the bandwidth for each FCR connection (when connected to another 16Gbs or 32Gbs-capable port).

Integrated Routing Ports on Demand — This license allows any Fibre Channel port in a Brocade X6-8 or Brocade X6-4 to be configured as an EX_Port supporting Fibre Channel Routing. The maximum number of EX_Ports supported per platform is provided in the license. This eliminates the need to add an FR4-18i blade or use a Brocade 7500 for FCR purposes, and also provides octuple the bandwidth for each FCR connection (when connected to another 32Gbs-capable port).

Advanced Extension — This license enables two advanced extension features: FCIP Trunking and Adaptive Rate Limiting. The FCIP Trunking feature allows multiple IP source and destination address pairs (defined as FCIP Circuits) via multiple 1 GbE or 10 GbE interfaces to provide a high bandwidth FCIP tunnel and failover resiliency. In addition, each FCIP circuit supports four QoS classes (Class-F, High, Medium and Low Priority), each as a TCP connection. The Adaptive Rate Limiting feature provides a minimum bandwidth guarantee for each tunnel with full utilization of the available network bandwidth without impacting throughput performance under high traffic load. This license is available on the DCX 8510-8/DCX 8510-4 for the FX8-24 on an individual slot basis.

10GbE FCIP/10G Fibre Channel — This license enables the two 10GbE ports on the FX8-24 and/or the 10G FC capability on FC16-xx blade ports supported on DCX 8510 platforms except for the FC16-64 blade. On the Brocade 6510, Brocade 6520 this license enables 10G FC ports. This license is not applicable to the Brocade 7840, Brocade G620, or Brocade X6 platforms.

On FX8-24:

With this license installed and assigned to a slot with an FX8-24 blade, two additional operating modes (in addition to 10x1GbE ports mode) can be selected:

- 10x1GbE ports and 1x10GbE port, or
- 2x10GbE ports

On FC16-xx:

- Enables 10G FC capability on an FC16-xx blade in a slot that has this license.

On Brocade 6510, Brocade 6520:

- Enables 10G FC capability on Brocade 6510 and Brocade 6520 switches.

This license is available on the DCX 8510-8 and DCX 8510-4 on an individual slot basis.

Advanced FICON Acceleration — This licensed feature uses specialized data management techniques and automated intelligence to accelerate FICON tape read and write and IBM Global Mirror data replication operations over distance, while maintaining the integrity of command and acknowledgement sequences. This license is available on the Brocade 7840 and the DCX 8510-8 and DCX 8510-4 for the FX8-24 on an individual slot basis.

ICL POD License — This license activates ICL ports on DCX 8510 or X6 platform core blades. An ICL license must be installed on the director platforms at both ends of the ICL connection.

On Brocade DCX8510-8 and X6-8:

The 1st ICL POD license enables 16 (half of the total) UltraScale ICL QSFP ports on DCX 8510-8 or X6-8 directors, enabling eight ICL ports on each core blade. These are QSFP port number 0, 1, 2, 3, 4, 5, 6, and 7 on DCX8510-8; while on X6-8, the QSFP port numbers are 0, 1, 2, 3, 8, 9, 10, and 11. The 2nd ICL POD license enables the remaining 16 UltraScale ICL QSFP ports on the directors. These are QSFP port number 8, 9, 10, 11, 12, 13, 14, and 15 on each core blade of DCX8510-8; while on X6-8, these are QSFP port number 4, 5, 6, 7, 12, 13, 14, and 15 on each core blade. Note that the trunk boundaries are different between CR32-8 core blades on X6-8 and CR16-8 core blades on DCX8510-8.

On Brocade DCX8510-4 and X6-4:

ICL POD licenses are different between X6-4 and DCX8510-4 directors. On an X6-4, the 1st ICL POD license enables eight (half of the total) UltraScale ICL QSFP ports on the director, enabling four ICL ports on each core blade, which are QSFP port number 0, 1, 4, and 5. The 2nd ICL POD

license on X6-4 enables the remaining eight UltraScale ICL QSFP ports on the director, which are QSFP port number 2, 3, 6, and 7 on each core blade. On a DCX8510-4, a single ICL POD license enables all 16 UltraScale ICL QSFP ports on the director.

Enterprise ICL (EICL) License — The EICL license is required on a Brocade DCX 8510 chassis when that chassis is connected to four or more Brocade DCX 8510 chassis via ICLs. This license is not applicable to X6 Directors.

This license requirement does not depend upon the total number of DCX 8510 chassis that exist in a fabric, but only on the number of other chassis connected to a DCX 8510 via ICLs. This license is recognized/displayed when operating with FOS v7.0.1 and enforced by FOS v7.1.0 or later.

Note: The EICL license supports a maximum of nine (9) DCX 8510 chassis connected in a full mesh topology or up to twelve (12) DCX 8510 chassis connected in a core-edge topology. Refer to the Brocade SAN Scalability Guidelines document for additional information.

WAN Rate Upgrade 1 License — The WAN Rate Upgrade 1 license provides the additional WAN throughput up to 10 Gbps on a Brocade 7840. The base configuration for a Brocade 7840 without this license provides WAN throughput up to 5 Gbps.

WAN Rate Upgrade 2 License — The WAN Rate Upgrade 2 license provides unlimited WAN throughput (up to the hardware limit) on a Brocade 7840. WAN Rate Upgrade 2 licenses also enable the use of two 40GbE ports on a Brocade 7840. The 40GbE ports cannot be configured without the WAN Rate Upgrade 2 license. A WAN Rate Upgrade 1 license must be installed on a Brocade 7840 before a WAN Rate Upgrade 2 license is installed. A WAN Rate Upgrade 1 license cannot be removed before the WAN Rate Upgrade 2 license has been removed.

Note: The WAN Rate Upgrade 1 and WAN Rate Upgrade 2 licenses apply only to Brocade 7840 platforms. They control the aggregate bandwidth for all tunnels on that Brocade 7840. The entire capacity controlled by the licenses can be assigned to a single tunnel, or a portion of the capacity can be assigned to multiple tunnels. The total bandwidth aggregated for all tunnels should not exceed the limits established by the licenses.

Temporary License Support

The following licenses are available in Fabric OS 8.0.1 as either Universal Temporary or regular temporary licenses:

- Fabric (E_Port) license
- Extended Fabric license
- Trunking license
- High Performance Extension license
- Advanced Performance Monitoring license
- Fabric Watch license
- Integrated Routing license
- Integrated Routing Ports on Demand license
- Advanced Extension license
- Advanced FICON Acceleration license
- 10GbE FCIP/10GFibre Channel license

- FICON Management Server (CUP)
- Enterprise ICL license
- Fabric Vision license
- WAN Rate Upgrade 1 license
- WAN Rate Upgrade 2 license

Note: Temporary Licenses for features available on a per-slot basis enable the feature for any and all slots in the chassis.

Temporary and Universal Temporary licenses have durations and expiration dates established in the licenses themselves. FOS will accept up to two temporary licenses and a single Universal license on a unit. Universal Temporary license keys can only be installed once on a particular switch, but can be applied to as many switches as desired. Temporary use duration (the length of time the feature will be enabled on a switch) is provided with the license key. All Universal Temporary license keys have an expiration date upon which the license can no longer be installed on any unit.

Hardware Support

Supported devices

The following devices are supported in this release:

- G620, X6-8, X6-4
- 6505, 6510, 6520, DCX8510-8, DCX8510-4
- 6542, 6543, 6545, 6546, 6547, 6548, M6505, 6558
- 7840

Supported blades

DCX 8510-8/DCX 8510-4 blade support

Fabric OS v8.0.2 software is fully qualified and supports the blades for the DCX8510-8 and DCX8510-4 noted in the table below:

Blades	OS support
FC16-32, FC16-48 16G FC blades	FOS v7.0 or later.
FC16-64 blade ^{1, 2}	FOS v7.3 or later.
FC8-64 64 port 8Gbit port blade	FOS v7.x. FOS v8.0.2 or later
FC8-32E, FC8-48E	FOS v7.x FOS v8.0.2 or later.
FCIP/FC Router blade (FR4-18i)	Not supported.
Virtualization/Application Blade (FA4-18)	Not supported.
Encryption Blade (FS8-18)	Not supported.
Extension Blade (FX8-24)	Up to a maximum of 4 blades of this type.
FCoE/L2 CEE blade FCOE10-24	Not supported.

X6-8/X6-4 blade support

Fabric OS v8.0.1 software is fully qualified and supports the blades for the X6-8 and X6-4 noted in the table below. None of the legacy blades (16G or lower speed) are supported in the Gen 6 chassis.

Blades	OS support
FC32-48 32G FC blade	FOS v8.0.1 or later.

¹ 8510 core blade QSFPs, part numbers 57-1000267-01 and 57-0000090-01, are not supported in FC16-64. The QSFPs supported in FC16-64, part number 57-1000294-02, is also supported on 8510 core blades.

² E_port connections on FC16-64 blade have the following restriction: connecting a QSFP port between a FC16-64 blade and an ICL QSFP port on a core blade is not supported.

SX6 Gen 6 Distance Extension Blade

FOS v8.0.1 or later.

Up to maximum of 4 blades of this type.

Note: The QSFPs supported in FC16-64, part number 57-1000294-02, is also supported on X6 core blades with the condition that the port speed must be configured at fixed 16 Gbps. Otherwise, the optics will be faulted.

Supported power supplies

Brocade G620 Power Supplies

The following table lists the power supplies for Brocade G620 supported in this release:

Part number	Description	Compatible devices
XBRG250WPSAC-F	Power supply and fan assembly, nonport-side air exhaust	Brocade G620
XBRG250WPSAC-R	Power supply and fan assembly, nonport-side air intake	Brocade G620

DCX8510-8 Power Supply Requirements

Typical Power Supply Requirements Guidelines for Blades in DCX 8510-8

(For specific calculation of power draw with different blade combinations, please refer to Appendix A: Power Specifications in the *Brocade DCX 8510-8 Backbone Hardware Reference Manual*.)

Configured Number of Ports	Blades	Type of Blade	DCX 8510-8 @110 VAC (Redundant configurations)	DCX 8510-8 @200-240 VAC (Redundant configurations)	Comments
Any combination of 8Gb or 16Gb ports with QSFP ICLs	FC16-32, FC16-64, FC8-32E	Port Blade	4 Power Supplies	2 Power Supplies	200-240 VAC: 1+1 Power Supplies 110 VAC: 2+2 ¹ Power Supplies
256 16Gb ports + QSFP ICLs	FC16-32, FC16-48 (Maximum of fully populated FC16-32 blades), FC16-64	Port Blade	4 Power Supplies	2 Power Supplies	200-240 VAC: 1+1 Power Supplies 110 VAC: 2+2 ¹ Power Supplies Max 8 FC16-32 port blades
256 8Gb ports + QSFP ICLs	FC8-32E, FC8-48E (Maximum of fully populated FC8-32E blades)	Port Blade	4 Power Supplies	2 Power Supplies	200-240 VAC: 1+1 Power Supplies 110 VAC: 2+2 ¹ Power Supplies

¹ When 2+2 power supply combination is used, the users are advised to configure the MAPS setting for switch Marginal State to be one Bad Power Supply.

					Max 8 FC8-32E port blades
192 16Gb Ports & max 2 intelligent blades (FX8-24) with QSFP ICLs	FC16-32, FC16-48, FC16-64, FX8-24	Port / Intelligent Blade	4 Power Supplies	2 Power Supplies	200-240 VAC: 1+1 Power Supplies 110 VAC: 2+2 ¹ Power Supplies Max four FC16-48 port blades and max 2 Intelligent blades
192 8Gb Ports & max 2 intelligent blades (FX8-24) with QSFP ICLs	FC8-32E, FC8-48E, FX8-24	Port / Intelligent Blade	4 Power Supplies	2 Power Supplies	200-240 VAC: 1+1 Power Supplies 110 VAC: 2+2 ¹ Power Supplies Max four FC8-48E port blades and max 2 Intelligent blades
336 16Gb ports + QSFP ICLs	FC16-48 (Maximum of seven FC16-48 blades, with one empty port blade slot)	Port Blade	4 Power Supplies	2 Power Supplies	200-240 VAC: 1+1 Power Supplies 110 VAC: 2+2 ¹ Power Supplies Max 7 FC16-48 port blades
336 8Gb ports + QSFP ICLs	FC8-48E (Maximum of seven FC8-48E blades, with one empty port blade slot)	Port Blade	4 Power Supplies	2 Power Supplies	200-240 VAC: 1+1 Power Supplies 110 VAC: 2+2 ¹ Power Supplies Max 7 FC8-48E port blades
384 16Gb ports + QSFP ICLs	FC16-48	Port Blade	Not Supported	4 Power Supplies	200-240 VAC: For DCX 8510-8, four (2+2) ¹ 220 VAC Power Supplies are required
384 16Gb ports + QSFP ICLs	FC16-64	Port Blade	4 Power Supplies	2 Power Supplies	200-240 VAC: 1+1 Power Supplies 110 VAC: 2+2 ¹ Power Supplies
384 8Gb ports + QSFP ICLs	FC8-48E	Port Blade	4 Power Supplies	4 Power Supplies	200-240 VAC: For DCX 8510-8, four (2+2) ¹ 220 VAC Power Supplies are required
Any combination of 8Gb or 16Gb ports and intelligent blades with QSFP ICLs	FC16-32, FC16-48, FC8-64, FC8-32E, FC8-48E, FX8-24	Intelligent Blade / Combination	Dependent on configuration. Requires power calculation for specific configuration	2 or 4 Power Supplies, depending on configuration	For DCX 8510-8, four (2+2) ¹ 220 VAC Power Supplies are required when any special purpose blade are installed

512 16Gb ports	FC16-64	Port Blade	4 Power Supplies	2 Power Supplies	200-240 VAC: 1+1 Power Supplies 110 VAC: 2+2 ¹ Power Supplies
512 16Gb ports + QSFP ICLs	FC16-64	Port Blade	4 Power Supplies	2 Power Supplies	200-240 VAC: 1+1 Power Supplies 110 VAC: 2+2 ¹ Power Supplies

DCX8510-4 Power Supply Requirements

Typical Power Supply Requirements Guidelines for Blades in DCX 8510-4

(For specific calculation of power draw with different blade combinations, please refer to Appendix A: Power Specifications in the *Brocade DCX 8510-4 Backbone Hardware Reference Manual*.)

Configured Number of Ports	Blades	Type of Blade	DCX 8510-4 @110 VAC (Redundant configurations)	DCX 8510-4 @200-240 VAC (Redundant configurations)	Comments
96 ports max with QSFP ICLs	FC16-32, FC8-32E	Port Blade	2 Power Supplies	2 Power Supplies	1+1 redundancy with 110 or 200-240 VAC power supplies
Any combination of 8Gb or 16 Gb ports and intelligent blades with QSFP ICLs	FC16-32, FC16-48, FC16-64, FC8-32E, FC8-48E, FC8-64, FX8-24	Intelligent Blade / Combination	Not Supported	2 Power Supplies	200-240 VAC: 1+1 Power Supplies

X6-8 Power Supply Requirements

Typical Power Supply Requirements Guidelines for Blades in X6-8

(For specific calculation of power draw with different blade combinations, please refer to Power consumption section in the *Brocade X6-8 Director Hardware Installation Guide*.)

Configured Number of Ports	Blades	Type of Blade	X6-8 @100-120 VAC (Redundant configurations) ¹	X6-8 @200-240 VAC (Redundant configurations) ¹
144 32 Gbps ports + QSFP ICLs	FC32-48	Port Blade	3 or 4 Power Supplies (2+1 or 2+2 redundancy)	2 Power Supplies (1+1 redundancy)

¹ For N+1 or N+N redundancy N PSUs must be available for system to support the load. In other words, failure of up to 1 PSU in N+1 configuration or N in N+N configuration will not impact system's operation.

384 32 Gbps ports + QSFP ICLs	FC32-48	Port Blade	Not Supported	3 or 4 Power Supplies (2+1 or 2+2 redundancy)
Any combination of 32 Gbps ports and Extension blades with QSFP ICLs	FC32-48 SX6	Port Blade Extension Blade	Not Supported	3 or 4 Power Supplies (2+1 or 2+2 redundancy)

X6-4 Power Supply Requirements

Typical Power Supply Requirements Guidelines for Blades in X6-4

(For specific calculation of power draw with different blade combinations, please refer to Power consumption section in the *Brocade X6-4 Director Hardware Installation Guide*.)

Configured Number of Ports	Blades	Type of Blade	X6-4 @100-120 VAC (Redundant configurations) ¹	X6-4 @200-240 VAC (Redundant configurations) ²
Any combination of 32 Gbps ports and Extension blades with QSFP ICLs	FC32-48 SX6	Port Blade Extension Blade	Not Supported	2 Power Supplies (1+1 redundancy)

Supported optics

For a list of supported fiber-optic transceivers that are available from Brocade, refer to the latest version of the Brocade Optics Family Data Sheet available online at www.brocade.com.

¹ For 1+1 redundancy 1 PSU must be available for system to support the load. In other words, failure of up to 1 PSU will not impact system's operation.

Software Upgrades and Downgrades

Image filenames

Download the following images from www.brocade.com.

Image filename	Description
v8.0.2d.zip	Fabric OS v8.0.2d for Windows
v8.0.2d_tar.gz	Fabric OS v8.0.2d for Linux
v8.0.2d.md5	Fabric OS v8.0.2d Checksum
v8.0.2d_all_mibs.tar.gz	Fabric OS v8.0.2d MIBs
v8.0.2d_releasenotes_v1.0.pdf	Fabric OS v8.0.2d Release Notes v1.0

Migration Path

This section contains important details to consider before migrating to or from this FOS release.

Migrating from FOS v8.0.1

Any Brocade G620 or X6 running any FOS v8.0.1 firmware can be non-disruptively upgraded to FOS v8.0.2d.

Migrating from FOS v8.0.0

Any Brocade G620 running any FOS v8.0.0 firmware can be non-disruptively upgraded to FOS v8.0.2d.

Migrating from FOS v7.4

Brocade 16G (Gen 5) director DCX8510 and all blades in the Supported blades table running any FOS v7.4 firmware can be non-disruptively upgraded to FOS v8.0.2d.

Non-disruptive upgrade on any other Gen 5 platforms running any v7.4.0x firmware version directly to FOS v8.0.2d is not supported. Instead, they must be non-disruptively upgraded to a FOS version with a fix for defect 563559 (FOS v7.4.1 or later) first and then upgraded to FOS v8.0.2d.

Migrating from FOS v7.3

Any Brocade 16G (Gen 5) platform and all blades in the Supported blades table operating at any FOS v7.3 firmware must be upgraded to FOS v7.4.1 or later firmware before it can be non-disruptively upgraded to FOS v8.0.2d.

Upgrade/downgrade considerations

Any firmware activation on a DCX 8510-8 or DCX 8510-4 with a FX8-24 blade installed will disrupt I/O traffic on the FCIP links.

Disruptive upgrades to Fabric OS v8.0.2d are allowed and supported from FOS v7.3.x (up to a two-level migration) using the optional “-s” parameter with the *firmwaredownload* command.

Limitations and Restrictions

Scalability

All scalability limits are subject to change. Limits may be increased once further testing has been completed, even after the release of this version of the Fabric OS. For current scalability limits for Fabric OS, refer to the Brocade SAN Scalability Guidelines document, available at www.brocade.com.

Compatibility/interoperability

Brocade Network Advisor Compatibility

Brocade Network Advisor is available with flexible packaging and licensing options for a wide range of network deployments and for future network expansion. Brocade Network Advisor 14.0.1 is available in the following editions:

- SAN-only
- IP-only
- SAN+IP

For SAN Management, Network Advisor 14.0.1 is available in three editions:

- **Network Advisor Professional:** a fabric management application that is ideally suited for small-size businesses that need a lightweight management product to manage their smaller fabrics. It manages two FOS fabric at a time and up to 300 switch ports. It provides support for Brocade FC switches, Brocade HBAs / CNAs, and Fibre Channel over Ethernet (FcoE) switches.
- **Network Advisor Professional Plus:** a SAN management application designed for medium-size businesses or departmental SANs for managing up to thirty-six physical or virtual fabrics (FOS) and up to 2,560 switch ports. It supports Brocade director products (X6-4, DCX 8510-4/DCX-4S, 48Ks, etc.), FC switches, Fibre Channel Over IP (FCIP) switches, Fibre Channel Routing (FCR) switches/ Integrated Routing (IR) capabilities, Fibre Channel over Ethernet (FcoE) / DCB switches, and Qlogic and Emulex HBAs / CNAs.
- **Network Advisor Enterprise:** a management application designed for enterprise-class SANs for managing up to one hundred physical or virtual fabrics and up to 15,000 switch ports. Network Advisor SAN Enterprise supports all the hardware platforms and features that Network Advisor Professional Plus supports, and adds support for the Brocade directors (X6-8, DCX 8510-8/DCX) and Fiber Connectivity (FICON) capabilities.

More details about Network Advisor's new enhancements can be found in the Network Advisor 14.0.1 Release Notes, Network Advisor 14.0.1 User Guide, and Network Advisor 14.0.1 Installation, Migration, & Transition Guides.

Notes:

- Brocade Network Advisor 14.0.1 or later is required to manage switches running Fabric OS 8.0.1 or later.
- The Brocade Network Advisor seed switch should always have the highest FOS version used in the fabric.

WebTools Compatibility

Fabric OS 8.0.2d is qualified and supported with Oracle Java version 8 update 77 and Java version 8 update 111. Please refer to the “Other Important Notes and Recommendations” section for more details.

SMI Compatibility

It is important to note that host SMI-S agents cannot be used to manage switches running Fabric OS 8.0.1 or later. If you want to manage a switch running Fabric OS 8.0.1 or later using the SMI-S interface, you must use Brocade Network Advisor’s integrated SMI agent.

Fabric OS Compatibility

- The following table lists the earliest versions of Brocade software supported in this release, that is, the *earliest* supported software versions that interoperate. Brocade recommends using the *latest* software versions to get the greatest benefit from the SAN.
- To ensure that a configuration is fully supported, always check the appropriate SAN, storage or blade server product support page to verify support of specific code levels on specific switch platforms prior to installing on your switch. Use only Fabric OS versions that are supported by the provider.
- For a list of the effective end-of-life dates for all versions of Fabric OS, visit the following Brocade website: <http://www.brocade.com/en/support/product-end-of-life.html>

Supported Products	Fabric OS Interoperability
4100, 4900, 7500, 7500e, 5000, 200E, 48K Brocade 4012, 4016, 4018, 4020, 4024, 4424	No support for interoperability in the same fabric or Access Gateway connection — must use FCR
Brocade 5410, 5480, 5424, 5430, 5431, 5432, 5450, 5460, 5470, NC-5480, VA-40FC	v7.3.1 or later
Brocade DCX, DCX-4S, 300, 5100, 5300	v7.3.1 or later
Brocade DCX with FS8-18 blade(s), Brocade Encryption Switch	v7.3.1 or later
Brocade 7800, DCX and DCX-4S with FCOE10-24 or FX8-24 blades	v7.3.1 or later
Brocade 8000	v7.1.2 or later ¹
Brocade DCX/DCX-4S with FA4-18 blade(s)	No support for interoperability in the same fabric — must use FCR ²
Brocade DCX 8510-8/DCX 8510-4	FOS v7.3.1 or later
Brocade DCX 8510-8/DCX 8510-4 with FC16-64 blade	FOS v7.3.1 or later
Brocade DCX 8510-8 with FCOE10-24 blade	FOS v7.3.1 or later
Brocade 6510, 6505, 6530, 7840	FOS v7.3.1 or later

¹ Brocade 8000 is not supported with Fabric OS v7.2.x or later.

² FA4-18 is not supported in a DCX/DCX-4S that is running Fabric OS v7.0 or later.

6548, 6547, M6505, 6545, 6546	FOS v7.3.1 or later
6543	FOS v7.4.1 or later
6558	FOS v8.0.1 or later ¹
Brocade G620	FOS v8.0.0 or later
Brocade X6-8/X6-4	FOS v8.0.1 or later
Brocade X6-8/X6-4 with FC32-48 blade or SX6 blade	FOS v8.0.1 or later
Brocade 6542	FOS v8.0.2 or later ¹
48000 with FA4-18 blade(s), Brocade 7600	Not Supported
Mi10k, M6140 (McDATA Fabric Mode and Open Fabric Mode)	Not Supported

Multi-Protocol Router Interoperability

Brocade 7500, 7500e	Not Supported
McDATA SANRouters 1620 and 2640	Not Supported

SNMP Support

Fabric OS 8.0.1 documents the supported MIBs in the *MIB Reference Guide* supporting Fabric OS 8.0.1. For information about SNMP support in Fabric Operating System (FOS) and how to use MIBs, refer to the *Fabric OS Administrator's Guide* supporting Fabric OS 8.0.1.

Obtaining the MIBs

You can download the MIB files required for this release from the downloads area of the MyBrocade site. To download the Brocade-specific MIBs from the Brocade Technical Support website, you must have a user name and password. Use the following steps to obtain the MIBs you want.

1. On your web browser, go to <http://my.brocade.com>.
2. Login with your user name and password.
3. Click the downloads tab.
4. On the downloads tab, under Product Downloads, select All Operating Systems from the Download by list.
5. Select Fabric Operating System (FOS), and then navigate to the release.
6. Navigate to the link for the MIBs package and either open the file or save it to disk.

NOTE: Distribution of standard MIBs has been stopped. Download the required standard MIBs from the <http://www.oidview.com/> or <http://www.mibdepot.com/> website.

¹ Support merged from embedded FOS releases.

Important Notes

In-flight Encryption and Compression

- Fabric OS 8.0.1 does not support in-flight encryption on Brocade G620 or X6 directors. The CLI command for port configuration for in-flight encryption is blocked in Fabric OS 8.0.1.
- In-flight compression is supported in Fabric OS v8.0.1 on Brocade G620 and X6 directors.
- In-flight encryption and compression are supported on 6510, 6520, and DCX 8510 platforms.

ClearLink Diagnostics (D_Port)

- Fabric OS 8.0.1 supports D_Port tests between two Brocade switches and between Brocade switches and Gen 5 (16 Gbps) and Gen 6 (32 Gbps) Fibre Channel Adapters from QLogic and Emulex. Following are specific adapter models and driver versions tested by Brocade with Fabric OS v8.0.1 for ClearLink.

	Emulex 16G Adapter	Emulex 32G Adapter	QLogic 16G Adapter	QLogic 32G Adapter
Adapter Model	LPe16002B-M6	LPe32000 (LPe31002-M6)	QLE2672	QLE2742
Adapter Firmware	10.6.144.21	11.0.243.11	7.04.01	8.03.03
Adapter Driver	10.6.114.0	11.0.247.0	STOR Miniport 9.1.15.21	STOR Miniport 9.1.17.21

- The D_Port long duration test can only be run on one port at a time.
- Long-duration optical loopback tests can be run on only one port at a time.
- Long-duration electrical loopback tests are not supported.

Forward Error Correction (FEC)

- FEC is mandatory with Gen 6 Fibre Channel operating at 32 Gbps. This means that the **portCfgFec** command only applies to ports running at 16 Gbps or 10 Gbps.
- FEC capability is not supported with all DWDM links. This means that FEC may need to be disabled on 16 Gbps or 10 Gbps ports when using DWDM links with some vendors. This is done using the **portCfgFec** command. Failure to disable FEC on these DWDM links may result in link failure during port bring up. Refer to the *Brocade Fabric OS 8.x Compatibility Matrix* for supported DWDM equipment and restrictions on FEC use.

Access Gateway

- The 32G links with 4x32G QSFP ports (port 48–port 63) do not have default mappings. These ports will be disabled by default when a Brocade G620 is enabled for Access Gateway mode or the configuration set to default.
- The Brocade G620 supports cascaded Access Gateway topology with FOS v8.0.1a and later.

Ingress Rate Limiting

- Fabric OS 8.0.1 does not support ingress rate limiting on Brocade G620 or X6 platforms.

Ethernet Management Interface

- Enabling IPsec on management interface is not supported on Brocade G620 switches. The **IPSecConfig** command is blocked to prevent enabling the configuration.
- The recommended interface speed configuration for a Brocade G620 is 1G auto-negotiate. If a G620 is configured for 10/100M Gbps forced-speed and fails to establish a link, Brocade recommends using a cross-over cable.
- If a Brocade switch management interface is running at 10Mbit/sec, certain FOS operations such as **firmwareDownload** may fail.
- The 10 Gbps management interface on CPX6 blades is not supported.
- The half-duplex mode for the X6 director and Brocade 7840 is not supported and is blocked.

Extension

- IP Extension (IPEXT) between a Brocade 7840 and a SX6 blade is supported only if the 7840 is running FOS v8.0.1 or later. FCIP extension between a Brocade 7840 with FOS v7.4 and a SX6 blade with FOS v8.0.1 is supported. The following table documents the combinations.

Site1 Switch/Blade	Site1 Firmware	Site2 Switch/Blade	Site2 Firmware	Supported
7840	8.0.1	7840	7.4.X	Both FCIP and IPEXT traffic
SX6	8.0.1	7840	7.4.X	FCIP traffic but not IPEXT traffic
SX6	8.0.1	7840	8.0.1	Both FCIP and IPEXT traffic
SX6	8.0.1	SX6	8.0.1	Both FCIP and IPEXT traffic

- It is recommended that administrators not to configure the HA VE pair (VE16, VE26), (VE17, VE27), (VE18, VE28), etc. where each VE in the pair is in a different LS with different traffic policy (port based routing and exchange based routing). The workaround is to configure different HA VE pairs such as (VE16, VE27), (VE17, VE26), etc. when putting each VE pair in different LS with different traffic policy.
- When Non-Terminate TCP (NT-TCP) is enabled on Traffic Control Lists (TCLs) and a firmware downgrade to FOS v7.4.1d is attempted on Brocade 7840, the downgrade will be blocked. Users must remove NT-TCP from the TCLs with NT-TCP enabled in order to downgrade the firmware. After firmware is downgraded to FOS v7.4.1d, users can re-enable the NT-TCP flag.

Brocade Analytics Monitoring Platform

- FOS v8.0.1a and later supports vTap on Brocade Gen 5 and Gen 6 platforms to be monitored by the Brocade Analytics Monitoring Platform. The supported Brocade platforms include: 6510, 6505, 6520, DCX 8510, 6543, 6545, 6546, 6547, 6548, M6505, 6558, G620, X6
- FOS AMPOS 1.5.0 is required on Brocade Analytics Monitoring Platform to monitor fabric switches running FOS v8.0.1a or later. Analytics Switch Links (ASLs) will segment between a fabric switch running FOS v8.0.1a or later and an Analytics Monitoring Platform with FOS_v7.4.0_4 or earlier version. It is recommended to upgrade Analytics Monitoring Platform to FOS AMPOS 1.5.0 before

upgrading fabric switches to FOS v8.0.1a or later. vTap flows will implicitly de-activate during firmware upgrade to FOS v8.0.1a or later and re-activate after FOS v8.0.1a or later upgrade.

- When a D_Port mode configuration mismatch between a fabric source switch and Analytics Monitoring Platform leads to a segmented analytic switch link, the source switch will display the segmented AE_Port as a segmented E_Port. This is tracked as defect 563489.
- vTap and auto-discovered AF_Port do not support high availability. In the event that an AF_port is re-discovered by a fabric switch after a domain change on the attached Analytics Monitoring Platform and followed by a hfailover or hareboot of the fabric switch, the remote AF_port information would be stale and vTap flows cannot be activated. In this case, use one of the following workarounds:
 - Manually configure the AF_Port after hfailover or hareboot
 - Disable and then enable the AF_Port on the Analytics Monitoring Platform
 - Deactivate vTap flow before firmware download, hfailover, or hareboot and activate vTap flow again.
- vTap and CS_CTL are mutually exclusive on a fabric switch. If CS_CTL is enabled on one port, the entire switch cannot enable vTap. An F_Port trunk supporting CS_CTL must have all ports in the trunk group enabling CS_CTL. Similarly, in order to enable vTap, all ports in an F_Port trunk must have CS_CTL disabled. In addition, the master port of a trunk should remain the same between CS_CTL enable and disable. If this sequence is not followed, vTap may remain active even after CS_CTL is enabled on an F_Port, or the error message “Disable QoS zones error” may be observed when enabling vTap. A suggested method is to use the following sequence:
 - When enabling CS_CTL mode, enable on all slave ports, followed by enabling on the master port, noted as port M.
 - When disabling CS_CTL mode, disable all active ports in the trunk, except the master port M. Disable CS_CTL mode on port M. Enable all ports in the trunk followed by disabling CS_CTL mode on the remaining ports.
 - When CS_CTL is enabled on a port without any connection, after reboot and disabling CS_CTL, vTap cannot be enabled. The workaround is to enable the port as a SIM port after disabling CS_CTL, then toggle the port and remove the SIM port configuration.
- vTap and in-flight encryption or compression compatibility is supported only on the following platforms: Brocade DCX8510, X6, G620, and 6520. On DCX8510 and 6520 platforms, the ports with vTap enabled and ports with in-flight encryption or compression enabled must belong to different ASICs. Please refer to the hardware installation guides of these platforms for port to ASIC mapping boundary. The RAS log message FV-1003 displays the incorrect user port range for which the encryption or compression is not enabled.
- Attempt to activate a vTap flow that is already activated will receive an incorrect error message: “Activated features(s) not currently enforced for this flow because either AF port is not reachable or it is disabled.” This is tracked as defect 603032.
- After a **slotpoweroff** and **slotpoweron** a blade in an X6 director with an AE_port, a vTap mirrored flow may stop but the number of mirrored frames may continue incrementing. To recover from this condition, port disable and enable the AE_port, or de-activate and activate the vTap flow. This is tracked as defect 603698.
- Running **flow --show sys_analytics_vtap** command when vTap and QoS High compatibility mode is enabled but vTap flow is not active may display incorrect the message: “Enable vTap and QoS High

Priority Zone Compatibility Mode to active vTap flow. Please use `configurechassis` command to enable this compatibility mode.” This is tracked as defect 604429

- After a **configuredownload** followed by **switchenable**, or a flow statistics reset on Brocade X6 and G620, MAPS may incorrectly reports VTAP IOPS > 250,000 violation.

Flow Vision

- Flow Vision supports only logical group names that begin with alphabetic characters.
- Frame count statistics of a Flow Monitoring flow may stop incrementing after a **statsclear** command. To work around the problem, users may run the **slotStatsClear** command. To recover from such condition, users should run the following steps:
 1. Disable all flows in the logical switch.
 2. Delete the problem flow.
 3. Create a new flow to replace the problem flow.
 4. Activate the new replacement flow.
 5. Verify the new replacement flow.
 6. Enable all other flows.

FICON

For FICON-qualified releases, please refer to the “Additional Considerations for FICON Environments” section of the Appendix for details and notes on deployment in FICON environments. (This appendix is only included for releases that have completed FICON qualification).

Miscellaneous

- If the ambient temperature is above the recommended operational limit, the power supply units may shut down, in particular when the ambient temperature is above 62C degree for Brocade X6 directors. This will result in the switch being shut down without any warning. Please refer to the *Brocade G620 Hardware Installation Guide* and the *Brocade X6-8/X6-4 Hardware Installation Guides* for the recommended ambient temperature limits for the switches.
- After a Power Supply unit is removed from a Brocade G620, the **historyShow** command may miss the entries for this FRU removal or insertion event. In addition, the RASLog ERROR message EM-1028 may be logged when the Power Supply is removed. This condition can be corrected by a power-cycle of the switch.
- After running offline diagnostics mode 1 on QSFP ports, a Brocade G620 must be rebooted before operational use.
- All links in an ICL QSFP connection on an X6 director must be configured to the same speed using the **portCfgSpeed** command from one of the following supported list: 16 Gbps, 32 Gbps, or ASN.

Defects

Some defects listed in the following tables do not apply to the Brocade G620 or X6 platforms but were disclosed in a previous release.

Closed with code changes in Fabric OS 8.0.2d

This section lists software defects with Critical, High, and Medium Technical Severity closed with a code change as of December 19, 2017 in version 8.0.2d.

Defect ID:	DEFECT000617360		
Technical Severity:	Medium	Probability:	Medium
Product:	Brocade Fabric OS	Technology Group:	RAS - Reliability, Availability, and Serviceability
Reported In Release:	FOS8.1.0	Technology:	Monitoring
Symptom:	Observed <code>"/fabos/link_bin/supportshow: [: missing `"]</code> while executing supportshow.		
Condition:	When execute supportshow CLI directly		
Workaround:	Use Supportsave		

Defect ID:	DEFECT000618216		
Technical Severity:	High	Probability:	High
Product:	Brocade Fabric OS	Technology Group:	FICON
Reported In Release:	FOS8.1.0	Technology:	Traffic Management
Symptom:	Traffic issues may be observed across an ISL or IFL. Such as fspf cannot pass HLO frame on a good link with NBFS-1005, host and device cannot pass traffic through ISL or IFL		
Condition:	This is a very rare race condition and happens on Pre-v8.1.0 FOS on GEN6 ASIC. It happens after a warm failover, when there is high CPU designated traffic. It is possible the exposure is observed long after hafailover happened.		
Workaround:	Make sure no unnecessary monitoring of the switch to cause high daemon traffic.		
Recovery:	Hafailover when monitoring traffic is low.		

Defect ID:	DEFECT000620259		
Technical Severity:	High	Probability:	Low
Product:	Brocade Fabric OS	Technology Group:	Hardware Monitoring
Reported In Release:	FOS8.1.0	Technology:	Monitoring
Symptom:	Chassis critical error C4-1010 observed during fastboot due to parity error in FTB stats memory		
Condition:	These errors may be observed during fastboot stress tests on Gen6 platforms.		

Defect ID:	DEFECT000628793		
Technical Severity:	High	Probability:	Low
Product:	Brocade Fabric OS	Technology Group:	RAS - Reliability, Availability, and Serviceability
Reported In Release:	FOS8.1.0	Technology:	Monitoring
Symptom:	User may observe slow response times or performance degradation for requests to switch.		
Condition:	This may be observed when FMS is enabled and applications poll the switch for stats on a 1-minute cycle. Issue is seen if MAPS FPI TX/RX Utilization rules are configured and active with a 1-minute time-base and TX/RX Utilization thresholds defined in active MAPS rules are exceeded.		

Defect ID:	DEFECT000631036		
Technical Severity:	Medium	Probability:	High
Product:	Brocade Fabric OS	Technology Group:	CLI - Command Line Interface
Reported In Release:	FOS8.0.2	Technology:	Management
Symptom:	CLI Command 'slotstatsclear -s' does not work as specified with respect to the default value for slot number.		
Condition:	This may be encountered for CLI command slotstatsclear on all platforms.		

Defect ID:	DEFECT000631276		
Technical Severity:	High	Probability:	Medium
Product:	Brocade Fabric OS	Technology Group:	Buffer Credit Management
Reported In Release:	FOS8.1.0	Technology:	Traffic Management
Symptom:	Observed C3-1002 followed by blade fault on switch while doing FWDL when there is SIM port (Flow Gen traffic).		
Condition:	This issue could happen while the SIM port filter resource is shared with any other filter in that chip and HA triggered on that chip. Once in this scenario, all the traffic that's going to that SIM port will be stuck and could introduce credit loss on the BE link which in turn to blade faults.		

Defect ID:	DEFECT000633624		
Technical Severity:	Medium	Probability:	Medium
Product:	Brocade Fabric OS	Technology Group:	Configuration Fundamentals
Reported In Release:	FOS8.0.2	Technology:	Management
Symptom:	Root access level may be deleted when configuration file uploaded from FOS7.4.x is downloaded to FOS8.x		
Condition:	This may occur on all platforms		

Defect ID:	DEFECT000633820		
Technical Severity:	Medium	Probability:	High
Product:	Brocade Fabric OS	Technology Group:	NTP - Network Time Protocol
Reported In Release:	FOS7.4.1	Technology:	Management
Symptom:	Brocade FC5022 switches do not sync NTP after CMM upgrade.		
Condition:	This occurs following upgrade to CMM using SHA1 keys.		

Defect ID:	DEFECT000637701		
Technical Severity:	High	Probability:	High
Product:	Brocade Fabric OS	Technology Group:	NTP - Network Time Protocol
Reported In Release:	FOS8.0.2	Technology:	Management
Symptom:	Switch may be unable to set the secondary NTP server following the failure of the primary NTP server synchronization.		
Condition:	This is observed when multiple NTP servers are configured and the Primary NTP server fails, for example due to shutdown.		

Defect ID:	DEFECT000640130		
Technical Severity:	High	Probability:	Low
Product:	Brocade Fabric OS	Technology Group:	High Availability
Reported In Release:	FOS8.0.1	Technology:	Management
Symptom:	Kernel panic after a software dead lock condition.		
Condition:	This is seen with FOS v8.x while monitoring and reporting hardware asic errors, such as asic parity error, CRC with Good EoF.		

Defect ID:	DEFECT000640577		
Technical Severity:	High	Probability:	High
Product:	Brocade Fabric OS	Technology Group:	Fibre Channel Services
Reported In Release:	FOS8.1.0	Technology:	Management
Symptom:	Switch panic may be observed, resulting from fdmid daemon termination.		
Condition:	This occurs when there is application or a specific 3rd party storage polling frequently using FDMI register/deregister command, such as FDMI_GPAT. This results in Memory Leak in the fdmid daemon code.		

Defect ID:	DEFECT000640661		
Technical Severity:	High	Probability:	Medium
Product:	Brocade Fabric OS	Technology Group:	FCIP - Fibre Channel over IP
Reported In Release:	FOS7.4.1	Technology:	Extension
Symptom:	Upgrading a switch to FOS7.4.x or higher versions may result in degraded FCIP performance.		
Condition:	FCIP 20% performance degradation occurs when running in very specific configurations with certain IO profile. Issue exists in FOSv7.4.0 and later. Fixed in FOS7.4.2b, FOS8.1.2 and FOS8.2.0.		

Defect ID:	DEFECT000643334		
Technical Severity:	High	Probability:	Medium
Product:	Brocade Fabric OS	Technology Group:	FCIP - Fibre Channel over IP
Reported In Release:	FOS7.4.1	Technology:	Extension
Symptom:	After running for an extended period of time, XTUN-1000 RASLOGs and other issues (potentially BLS-5024 DP Panic) may be seen.		
Condition:	After running for a long period of time in an FCIP FCR configuration, the DP WQE buffer pool is depleted (2.5 million are lost in 70 days in a large FCR configuration (>> 10,000 imported SID/DID pairs). The pool is initialized with 7.5 million WQE buffers. So it would take about 210 days to consume the entire pool.		
Workaround:	Reboot the blade/switch before 210 days have passed in a large FCIP FCR configuration.		

Defect ID:	DEFECT000646307		
Technical Severity:	Medium	Probability:	High
Product:	Brocade Fabric OS	Technology Group:	Management GUI
Reported In Release:	FOS8.1.1	Technology:	Management
Symptom:	Launching Webtools may lead to failure from SSL Handshake alert of "unrecognized_name".		
Condition:	This may be encountered with HTTPS & Fully Qualified Domain Name (FQDN).		

Defect ID:	DEFECT000647361		
Technical Severity:	Medium	Probability:	High
Product:	Brocade Fabric OS	Technology Group:	FCIP - Fibre Channel over IP
Reported In Release:	FOS7.4.1	Technology:	Extension
Symptom:	Combination of the occurrence of the following RASLOGs XTUN-1001 with "FTNL Tunnel 24 Memory allocation failed tracker 3" and XTUN-1008 where memory usage is greater than 75%.		
Condition:	In an FCIP 7840 or SX6 configuration with many SID/DID pairs traversing the FCIP Tunnel. The 7840 and SX6 each have 2 DPs and each DP has 1.2 Gigabytes of control block memory. The XTUN-1001 RASLOG with tracker 3 indicates that the control block memory allocation failed. In the customer case, they failed after about 9,900 SID/DID pairs were discovered on the tunnel (each with 6 LUNs).		
Workaround:	Limit the number of SID/DID pairs that flow through one FCIP DP. Use logical switches create 2 VE ports (one on DP0 e.g. VE 24 and one on DP1 e.g. VE34) and split the flows over both DPs. Monitor XTUN-1008 RASLOGs and adjust configuration as necessary.		

Defect ID:	DEFECT000647922		
Technical Severity:	High	Probability:	Medium
Product:	Brocade Fabric OS	Technology Group:	Hardware Monitoring
Reported In Release:	FOS8.2.0	Technology:	Monitoring
Symptom:	User will see Raslog C4-1010 being logged continuously, with no other impact. Further inspection of internal raslog will reveal this unique signature: [C4-5672], , , ERROR, , S7,C0: FTB block 1st = 0x20, intr_cause = 0x100 User may also encounter switch panic following the repeated logging of Raslog C4-1010.		
Condition:	This is a rare occurrence observed when there is asic parity error on frame statistics memory block. This only impacts 32G platforms.		
Recovery:	A power cycle usually clears parity errors.		

Defect ID:	DEFECT000651997		
Technical Severity:	High	Probability:	High
Product:	Brocade Fabric OS	Technology Group:	FCIP - Fibre Channel over IP
Reported In Release:	FOS8.0.2	Technology:	Extension
Symptom:	One or more XTUN-1008 RASLOGs followed by tunnel down notifications at the peer switch and BLZ-5024 RASLOGs on the impacted switch.		
Condition:	Server with NPIV connections to fabric is frequently logging in and out of the fabric and issuing PLOGIs/PRLIs to devices over an FCIP Tunnel. Each PLOGI/PRLI has a new SID as the NPIV PID normally changes at each fabric login.		

Closed with code changes in Fabric OS 8.0.2c

This section lists software defects with Critical, High, and Medium Technical Severity closed with a code change as of May 30, 2017 in version 8.0.2c.

Defect ID: DEFECT000597800	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Traffic Management
Reported In Release: FOS8.0.1	Technology: Port Bring-up
Symptom: Core blade back-end ports are all disabled on 32G directors.	
Condition: This is a very rare case observed when 32G back-end ports need to retry port initialization.	

Defect ID: DEFECT000609100	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: RAS - Reliability, Availability, and Serviceability
Symptom: Issuing switch reboot from CLI might result in a kernel panic.	
Condition: During successive reboots on the switch via CLI.	

Defect ID: DEFECT000622092	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: Hardware Monitoring
Symptom: "Baud Rate" in "sfps show" with 32G SFP is expected to be shown as "280" not "255".	
Condition: Run Sfps show CLI on 32G sfp.	

Defect ID: DEFECT000623963	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.1.0	Technology: MAPS - Monitoring and Alerting Policy Suite
Symptom: MAPS reports port 0 as Online Port instead of E-Port or F-Port, such as MAPS-1004 messages shows as "Online-Port 0" instead of "F-Port 0":	
Condition: When maps message is triggered on port 0.	

Defect ID: DEFECT000627748	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: MAPS - Monitoring and Alerting Policy Suite
Symptom: Degraded Eport keeps switch state to remain healthy during customized maps configuration.	
Condition: 1. Configure a rule for MARG_PORT with action as SW_MARGINAL and add that rule to a custom policy and now enable that custom policy. 2. Configure a E-Port to become buffer limited (Degraded). Once the E-Port becomes buffer limited "mapsdb --show all " reports the switch status as HEALTHY instead of MARGINAL.	

Defect ID: DEFECT000633739	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.2	Technology: MAPS - Monitoring and Alerting Policy Suite
Symptom: User can set a negative value (up to -99999) for DAYS TO EXPIRE.	
Condition: Occurs when executing CLI: mapsrule --config ALL_CERTS_DAYS_TO_EXPIRE -value -99999.	

Defect ID: DEFECT000635286	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Traffic Management
Reported In Release: FOS8.1.1	Technology: Port Bring-up
Symptom: User might observe error counts increasing when running traffic through a 16G QSFP.	
Condition: When traffic is running through 16G 2KM QSFPs connected between Gen5 directors. This only impacts FOSv8.0.x and v8.1.0a.	

Defect ID: DEFECT000635743	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management

Reported In Release: FOS8.1.1	Technology: Inband Management
Symptom: Daemons terminate after reading corrupted frame buffer.	
Condition: During a race condition when there is a frame trapped to CPU for handling or when there is multi-frame sequence received out of order or incomplete.	

Defect ID: DEFECT000637087	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.2	Technology: Configuration Fundamentals
Symptom: rpcd option in configure CLI is still present when there is VF configured.	
Condition: When running configure CLI with VF, the following line is still available though non functional: rpcd attributes (yes, y, no, n): [no]	

Defect ID: DEFECT000638134	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Security
Reported In Release: FOS8.0.2	Technology: AAA - Authentication, Authorization, and Accounting
Symptom: 16G platforms output 'rbash: SHLVL: readonly variable' error when user issues login command on admin/user privilege.	
Condition: On 16G switches, issue login via admin/user privilege: sw0:FID128:admin> login rbash: SHLVL: readonly variable <----- sw0:FID128:user> login rbash: SHLVL: readonly variable <----- Root works as expected: sw0:FID128:root> login 32G was fixed in FOS v8.0.2a	

Defect ID: DEFECT000640442	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Traffic Management
Reported In Release: FOS7.3.1	Technology: Port Bring-up
Symptom: Link may not properly initialize and CRC errors or other link others may be observed. In some cases the switch may also panic when attempting to read from non qualified QSFPs.	
Condition: Installing an non qualified optic (QSFP or SFP) into Gen-5 DCX platform.	
Workaround: Do not install non qualified QSFPs or SFPs into the switch.	
Recovery: The non qualified QSFP or SFP should be removed from the system.	

Defect ID: DEFECT000640591	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.1.0	Technology: Management GUI
Symptom: Memory leak observed with webtools.	
Condition: When using BNA and webtools to monitor the switches running FOS v7.4.2 or FOS v8.0.2b with FQDN.	
Workaround: User can configure the FQDN again after upgrade to avoid memory leak.	

Closed with code changes in Fabric OS 8.0.2b

This section lists software defects with Critical, High, and Medium Technical Severity closed with a code change as of March 23, 2017 in version 8.0.2b.

Defect ID: DEFECT000542251	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.1.2	Technology: NTP - Network Time Protocol
Symptom: Customer would not be able to block the NTP update using Ipfilter rules for IPv6 NTP server address.	
Condition: Applicable for IPv6 Network. Configure Ipv6 address on both switch and NTP server, block port 123 as destination port through ipfilter and activate the ipfilter policy.	

Defect ID: DEFECT000575740	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.3.1	Technology: SNMP - Simple Network Management Protocol
Symptom: Link up/Link down trap events of management fc interfaces that starts with fc0 contain incorrect ifindex as varbind.	
Condition: This happens on all the platforms and all the versions of FOS.	

Defect ID: DEFECT000576361	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Security
Reported In Release: FOS7.2.1	Technology: ACLs - Access Control Lists
Symptom: FCS and SCC Policies in fabric disappear when changes are made to DCC policy.	
Condition: This behavior is seen in all platforms when setting the fabric data distribution configuration to SCC,DCC and FCS.	

Defect ID: DEFECT000600771	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Security
Reported In Release: FOS7.4.1	Technology: LDAP - Lightweight Directory Access Protocol
Symptom: supportsave data does not include output from "ldapcfg --show"	
Condition: This is required to help troubleshoot LDAP issues.	

Defect ID: DEFECT000603168	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Traffic Management
Reported In Release: FOS8.0.1	Technology: Fibre Channel Routing

Symptom: Host connection problem after Plogin ACC is dropped by switch.
Condition: Race condition triggered during port disable/enable testing on FOSv 8.0.1 or higher
Workaround: Bounce port

Defect ID: DEFECT000604071	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS7.2.1	Technology: Fabric Watch
Symptom: Logs in DP's RAS_PRE.txt is incomplete.	
Condition: This issue is seen rarely while collecting supportsave from BR7800.	

Defect ID: DEFECT000612329	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.1.0	Technology: Licensing
Symptom: CLI to set switch configuration to default never completes.	
Condition: Running "configdefault" when slot-based licenses are installed.	

Defect ID: DEFECT000614911	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: RAS - Reliability, Availability, and Serviceability
Symptom: Switch may go into rolling reboot with the following console message: "The Hardware Clock does not contain a valid time, so we cannot set the System Time from it. Unable to set system clock."	
Condition: This may occur under a rare circumstance where the hardware clock goes faulty or corrupted.	

Defect ID: DEFECT000616744	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.1.0	Technology: Inband Management
Symptom: User daemon terminated causing a switch panic after reading a corrupted frame buffer.	
Condition: During race condition when there is a frame trapped to CPU for handling or when there is a multi-frame sequence received out of order.	

Defect ID: DEFECT000618536	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: Management GUI

Symptom: "PCS Block Errors" and "Power On Time" details not shown for 32G switches in WebTools.
Condition: Using WebTool on 32G switch.

Defect ID: DEFECT000620060	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.1.0	Technology: Configuration Fundamentals
Symptom: User may encounter duplicate zone error when creating peerzone using CLI command "zonecreate --peerzone .."	
Condition: This may occur on all platforms due to false duplicate entry reporting during peerzone creation	

Defect ID: DEFECT000622430	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Security
Reported In Release: FOS7.4.1	Technology: User Accounts & Passwords
Symptom: Login failure is observed for LDAP users.	
Condition: This issue is seen when LDAP user tries to login to switch using username without domain name.	

Defect ID: DEFECT000624659	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: CLI - Command Line Interface
Symptom: ethif command does not allow the user to choose the advertised link modes and uses the given speed alone for negotiation.	
Condition: All platforms running FOS8.0.x and above will see this behavior.	

Defect ID: DEFECT000624897	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: Software Installation & Upgrade
Symptom: firmwarecleaninstall to a FOS version without a fix for defect 595584 is permitted but may fail.	
Condition: This occurs only on BR6505, BR6510 and BR300 switches when firmwarecleaninstall is performed to a FOS version without the fix for defect 595584.	

Defect ID: DEFECT000626173	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: Port Mirroring
Symptom: CLI "sfps show -f" does not display the updated values.	
Condition: This will be seen on all the platforms and in all FOS versions.	
Workaround: Execute sfps show again to see the updated values.	

Defect ID: DEFECT000626610	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS7.2.1	Technology: FCIP - Fibre Channel over IP
Symptom: DP went down and impacted FCIP traffic.	
Condition: Internal back pressure on FX8-24/BR7800 caused DP stuck. Monitor such condition and fault the blade if it happens; Also added enhancement to dump more register contents for IP extension platforms.	

Defect ID: DEFECT000627826	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.2	Technology: CLI - Command Line Interface
Symptom: Chassis Role:user allows sysShutDown command to be ran.	
Condition: User account is allowed to execute the "sysshutdown" command when the role of the chassis level user is configured.	

Defect ID: DEFECT000628189	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Security
Reported In Release: FOS8.1.0	Technology: SSH - Secure Shell
Symptom: SSH connection intermittently fails	
Condition: SSH connection with public key (password less login) may fail to login to switch. This condition happens rarely on G620 and BR7840 platforms	
Workaround: Disconnect and establish the connection again.	

Defect ID: DEFECT000628482	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: CLI - Command Line Interface
Symptom: The switch fails to remove the killed session immediately from the "List of Sessions" table when logged into with multiple telnet sessions and 'killtelnet' is executed.	
Condition: Running the CLI on FOS v8.0.x.	
Workaround: Hit the enter key again before the killed session is gone from the list.	

Defect ID: DEFECT000629335	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS7.4.1	Technology: FCIP - Fibre Channel over IP
Symptom: Reduced performance between FCIP connected SID/DID pairs and presence of repeated fabric rejects for ELS PLOGI, RNID and PDISC sequences through the configuration.	
Condition: FCIP configuration in a VF environment with a mixture of fabrics that do and do not include zoning enforcement.	

Defect ID: DEFECT000630618	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS7.4.1	Technology: RAS - Reliability, Availability, and Serviceability
Symptom: Enhance code to track PCI address of blade that caused CPs reboot.	
Condition: This is rarely seen in director class products when there is a bad blade in the system or when the blade is improperly seated.	
Recovery: Reseat/replace identified blade.	

Defect ID: DEFECT000631045	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.2	Technology: SNMP - Simple Network Management Protocol
Symptom: When the offset of time is configured with the "tstimezone" command, the specified offset is reflected in system time zone. But in the time stamp of swEventTrap, the reverse GMT offset is displayed.	
Condition: All platforms running FOS8.0.x are affected.	

Defect ID: DEFECT000631969	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS8.0.2	Technology: FCIP - Fibre Channel over IP
Symptom: Continuous remote FC I/O errors: a FC analyzer will show missing sequences and FC frames with CRC errors.	
Condition: When Fast Write and/or Open Systems Tape Pipelining and Fast Deflate compression is enabled on a FCIP Tunnel. This problem is only in FOS8.0.2a on BR7840/SX6.	
Workaround: Do not upgrade to FOS8.0.2a on BR7840/SX6	

Defect ID: DEFECT000632217	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS7.2.1	Technology: RAS - Reliability, Availability, and Serviceability
Symptom: Switch panic or cold boot during firmware upgrade.	
Condition: In rare condition during hot code load, if there is a mismatch in switch internal data and any online user port media speed settings, the switch will panic when upgrade to FOS v7.3.1e, v7.3.2a, v7.4.1c, and v8.0.1 or later on these code streams. Director upgrade could be cold boot.	
Workaround: portdisable/enable speed mismatch ports before upgrade.	

Defect ID: DEFECT000632253	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.1.0	Technology: Configuration Fundamentals
Symptom: Could not move a series of ports between Fabric IDs	
Condition: When ports were quarantined in a previous FID even though the ports no longer resided in the original quarantined FID..	
Recovery: Return ports to the original FID and unquarantine all ports which were still in a quarantined state.	

Defect ID: DEFECT000632469	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS7.4.1	Technology: Fastwrite
Symptom: Standard processing of ELS PRLI causes open pending exchanges to be cleaned up. This will cause timeouts for all pending IOs	
Condition: With an application that uses ELS PRLI Sequences with Image Pair established over an FX8-24 or 7800 FCIP Tunnel.	

Defect ID: DEFECT000633179	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.2	Technology: Management GUI
Symptom: Webtools tooltip does not display the CRC errors incremented in the given polling interval, instead it displays the counter value itself.	
Condition: This is applicable for all FOS platforms.	

Defect ID: DEFECT000633432	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.2	Technology: Management GUI
Symptom: L port is listed in "Port Admin" tab and also in "FC Port Configuration Wizard" when user clicks 'Actions and Edit' in General tab	
Condition: Fabric OS version 8.0 and above supports only 16G/32G Products which do not support L-Port(loop port)	

Defect ID: DEFECT000633848	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.2	Technology: CLI - Command Line Interface
Symptom: Help page for CLI command passwdcfg needs update to the -charset value section.	
Condition: This is applicable only for the help page for the passwdcfg CLI command.	

Defect ID: DEFECT000634964	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.4.1	Technology: Access Gateway
Symptom: Switch panic after a long up time in AG environment	
Condition: Small memory leak when running agshow CLI or BNA polling AG information in the background	

Defect ID: DEFECT000635739	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.2	Technology: High Availability
Symptom: CP encountered kernel panic (Detected termination of mdd) during a firmware downgrade from FOS v8.1.0x to FOS v8.0.x.	
Condition: This may occur on a switch running FOS v8.1.0x with an empty MAPS policy before the downgrade. Pre-FOS v8.1.0 downgrade is not impacted. The panic is addressed in FOSv8.0.2b and v7.4.2, but a subsequent migration to an un-fixed FOS v8.0.1x or v7.x will cause the MDD panic again. This will be fixed in FOSv8.1.0b so migrations from FOS v8.1.0b down will not be affected.	
Workaround: Add a Rule to the MAPS Policy so it is not empty to avoid this panic.	

Defect ID: DEFECT000635804	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: MAPS - Monitoring and Alerting Policy Suite
Symptom: Loading MAPS policies and rules causes high memory utilization.	
Condition: : It can happen when BNA polls Advance Monitors System (AMS) group. In addition, memory can be exhausted within a few minutes during Maps policy load when there is NPV device port range configured in MAPS dflt_aggressive_policy.	
Workaround: Avoid to use port range in Maps policy configuration.	
Recovery: hafailover when memory is extremely low	

Closed with code changes in Fabric OS 8.0.2a

This section lists software defects with Critical, High, and Medium Technical Severity closed with a code change as of January 17, 2017 in version 8.0.2a.

Defect ID: DEFECT000597468	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: CLI - Command Line Interface
Symptom: IPv6 address will be truncated in killtelnet CLI output.	
Condition: This applies for telnet session; SSH session works fine.	

Defect ID: DEFECT000605675	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: Hardware Monitoring
Symptom: Port Status in the Logical Switch is white not Green on WEBTools even though it's healthy. And in the "portshow" output, "portHealth" value isn't shown in the Default switch once Logical switches created.	
Condition: Issue seems to manifest both in CLI and in GUI when the port is in an Logical Switch, and only reproduced in FOS v8.0.1x.	

Defect ID: DEFECT000606923	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: Licensing
Symptom: Customer can only form 2-port ICL trunks with the first ICL POD license.	
Condition: This applies to X6 directors running FOS v8.0.2, FOS v8.0.1b, or earlier.	
Workaround: Upgrade to fixed release and bounce unlicensed ICL ports to form additional trunks.	

Defect ID: DEFECT000614282	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS8.1.0	Technology: FCIP - Fibre Channel over IP
Symptom: User may encounter "DIAG: execDiagCmd FAILED" while performing fcippathtest on SX6 blade.	
Condition: This occurs when performing fcippathtest on a SX6 blade.	

Defect ID: DEFECT000619161	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS7.4.1	Technology: FCIP - Fibre Channel over IP
Symptom: I/O errors and low performance were observed on FCIP tunnels after Hot Code Load (HCL) sequences completed.	
Condition: After FCIP HCL completes on a BR7840 FCIP tunnel in a large configuration, the switch can get stuck in a persistent flow control state.	
Recovery: Manually reboot the impacted 7840s after FCIP HCL.	

Defect ID: DEFECT000619917	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: SNMP - Simple Network Management Protocol
Symptom: CLI command "snmpconfig --set mibcapability" may not properly update the value of snmpMibCap.	
Condition: The improper value of snmpMidCap may be seen following configdownload in FOSv7.4.x or later, snmp.mibCap.	

Defect ID: DEFECT000620536	
Technical Severity: Low	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Traffic Management
Reported In Release: FOS7.4.1	Technology: QoS - Quality of Service
Symptom: Following a firmware upgrade, the setup loses its prior tuned serdes values on FX8-24 blade.	
Condition: This occurs on ports 7/7, 7/10, 3/30 of FX8-24 port blade when tuning on transmit side.	

Defect ID: DEFECT000620664	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Traffic Management
Reported In Release: FOS8.0.1	Technology: TIZ - Traffic Isolation Zoning
Symptom: New ports assigned to an existing TI Zone are not in effect until a port bounce.	
Condition: This is seen with FOS v8.0.x. On pre-FOS 8.0.x, the ports are treated as TI zone members immediately.	
Recovery: Bounce port.	

Defect ID: DEFECT000621064	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: Configuration Fundamentals
Symptom: Inconsistency in the value of snmp.mibCap.FCMGMT-MIB between default and manual configurations.	
Condition: This is applicable to all FOS platforms running >= FOS7.4.x.	

Defect ID: DEFECT000621079	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: Management GUI
Symptom: Port Admin view within webtools may show "Advanced mode and not Basic as was expected.	
Condition: This may occur with the following steps: - Set view of menu bar on webtools at the "Advanced" mode. - Close web browser(webtools's session). - Open your web browser again and start Web Tools. - Change view of Port Admin tab to "Basic" mode. - Click "Switch View" tab. And, please click the FC port in the G620 switch view. Port Admin view is now in "Advanced mode (as in first step)" not Basic as was expected.	

Defect ID: DEFECT000621521	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: MAPS - Monitoring and Alerting Policy Suite
Symptom: The numbers of STATE_CHG in "mapsdb --show all" increase on ports with no POD license and with no device connected to them.	
Condition: This will be seen on all platform that has POD ports.	

Defect ID: DEFECT000622163	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS8.1.0	Technology: FCIP - Fibre Channel over IP
Symptom: User may encounter Raslogs RTWR-1003 "RTWR retry 48 to domain 15, iu_data 1000000".	
Condition: This is observed when BR 7840 is added to the fabric.	

Defect ID: DEFECT000622212	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.1.0	Technology: MAPS - Monitoring and Alerting Policy Suite
Symptom: MAPS - C3TXTO is not monitored for resident N-ports or F-ports with any default policy in Access Gateway (AG) mode.	
Condition: This is encountered on resident N-ports or F-ports in AG mode.	

Defect ID: DEFECT000622873	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.4.1	Technology: Fibre Channel Services
Symptom: Cfgupload file does not` contain an entry for "zoning.TIZoneFilter" when the functionality is enabled.	
Condition: This is encountered with configdownload for TIZoneFilter.	

Defect ID: DEFECT000623098	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Traffic Management
Reported In Release: FOS7.4.1	Technology: Fibre Channel Routing
Symptom: User may encounter a switch hang/panic from "Oops: Exception in kernel mode, sig: 5 [#1]".	
Condition: This may be seen on a Brocade 6520 when there is asic parity error.	
Recovery: Reboot switch.	

Defect ID: DEFECT000623984	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.1.0	Technology: RAS - Reliability, Availability, and Serviceability
Symptom: An internal raslog "PLAT-7001" is flooding raslog.	
Condition: This message will be coming when users run WebTools and connect to BR6542 FC Switch system.	

Defect ID: DEFECT000624488	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.1.0	Technology: RAS - Reliability, Availability, and Serviceability
Symptom: User may encounter "Detected termination of mdd0:1649 (4) : HAM: swd_close_proc:exit code:134, exit sig:17, parent sig:0".	
Condition: This may be observed during firmwaredownload from a rare condition.	

Defect ID: DEFECT000624563	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS7.4.1	Technology: FCIP - Fibre Channel over IP
Symptom: Slow or aborted FC Exchanges.	
Condition: After BR7840 FCIP HCL with large number of FC devices in the configuration.	
Workaround: Perform disruptive firmwaredownload.	
Recovery: Reboot switch.	

Defect ID: DEFECT000625435	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS8.0.1	Technology: FCIP Tunnel Management
Symptom: 10GbE SFP may not be recognized in SX6 blade. It functionally works as expected but may not display SFP data in sfpshow command.	
Condition: This is encountered only for SFPs with Vendor PN AP823A.	

Defect ID: DEFECT000625469	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Traffic Management
Reported In Release: FOS7.4.1	Technology: Port Bring-up
Symptom: Long distance links using SFPs with Part Numbers FTLX3670SCC**B08 may not come online.	
Condition: This occurs only for SPFs with part numbers FTLX3670SCC**B08.	

Defect ID: DEFECT000625584	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Security
Reported In Release: FOS7.4.0	Technology: Security Vulnerability
Symptom: CVE-2016-5195 (a.k.a. Dirty COW): Unprivileged local users could gain write access to otherwise read-only memory mappings, and thus increase their privileges on the system.	
Condition: This can only be exploited by someone who has access to the switch already and is limited to G620 and BR7840 platforms.	
Workaround: Protect switch management interface against unauthorized access.	

Defect ID: DEFECT000625806	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.1.0	Technology: Configuration Fundamentals
Symptom: "TASK = 90fb5820[1285] 'fcippathtest' Last syscall: -1" may be observed while performing fcippathtest on Gen-6 chassis.	
Condition: This may be encountered when performing fcippathtest on Gen-6 chassis with SX-6 blade.	

Defect ID: DEFECT000626709	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.1.0	Technology: Configuration Fundamentals
Symptom: "Slot 3 fcippathtest lbMode 2 speed 10G packets 4 length 164 bytes FAILED" may be encountered after performing FCIPpathtest on SX-6 blade in Brocade X6 chassis.	
Condition: This may occur with fcippathtest on SX-6 blade in Brocade X6 chassis.	

Defect ID: DEFECT000626893	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: Configuration Fundamentals
Symptom: CLI command "configure" permits configuration of rpcd attributes, even though rpcd has been deprecated in FOS 8.0.1.	
Condition: This is seen while executing the configure CLI command in FOS 8.0.1 and subsequent FOS versions.	

Defect ID: DEFECT000628163	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.2	Technology: SNMP - Simple Network Management Protocol
Symptom: Snmptests --show in FOS v8.0.2 lists T11-FC-ZONE-SERVER-MIB twice.	
Condition: This will be seen on all platforms running FOS v8.0.2.	

Closed with code changes in Fabric OS 8.0.2

This section lists software defects with Critical, High, and Medium Technical Severity closed with a code change as of November 10, 2016 in version 8.0.2.

Defect ID: DEFECT000418780	
Technical Severity: Low	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.1.0	Technology: SNMP - Simple Network Management Protocol
Symptom: Single event in the switch triggers more than expected number of traps sent to the trapreceiver.	
Condition: 1. Need to configure same trap receiver IP address multiple times in the trap configuration. 2. Use snmpsendtraps test command to send the traps.	
Workaround: Configure only one trap receiver for the given trap receiver IP, to avoid duplicate traps being sent.	

Defect ID: DEFECT000506068	
Technical Severity: Low	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.1.2	Technology: Configuration Fundamentals
Symptom: CLI chassiscfgperrthreshold parameter settings are not saved to configuration, for parameters such as: system.perrFaultFlg and system.perrThreshold. Though the setting is in effect and persists through cold boot, but CLI, such as configshow or configdownlaod, show the value as 0.	
Condition: This issue is seen when enabling parity threshold using CLI chassiscfgperrthreshold.	

Defect ID: DEFECT000536439	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS7.2.1	Technology: RAS - Reliability, Availability, and Serviceability
Symptom: Switch panic after reaching out of memory(OOM) condition.	
Condition: Misbehaving device is sending a zero-length frame at the end of a multi-frame sequence of FC frames.	

Defect ID: DEFECT000540101	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS7.2.1	Technology: MAPS - Monitoring and Alerting Policy Suite
Symptom: SNMP query reports a fan speed of 0.	
Condition: Erroneous fan speed report occurs only when switch hits transient I2C failure and it will be recovered automatically.	

Defect ID: DEFECT000540971	
Technical Severity: Low	Probability: Low
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS7.2.1	Technology: MAPS - Monitoring and Alerting Policy Suite
Symptom: In extreme conditions MAPS generates false alert for port errors such as LR etc.	
Condition: This false alert could be generated during state change of port and this happen in extreme conditions.	

Defect ID: DEFECT000559528	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS7.3.1	Technology: MAPS - Monitoring and Alerting Policy Suite
Symptom: MAPS traps are not sent as part of snmpTraps --send(test traps) command.	
Condition: All FOS platforms with MAPS enabled are affected. FOS 7.4 and above there is no support for Fabric Watch or MAPS traps in snmptraps command.	

Defect ID: DEFECT000563629	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS7.2.1	Technology: FCIP - Fibre Channel over IP
Symptom: One or more IPSec enabled FCIP circuits may continuously bounce or go down and not recover. The affected DP will report Authentication Tag Mismatch errors continually.	
Condition: This may be encountered when IPSec is enabled on an FCIP tunnel between a pair of FX8-24 blades.	
Recovery: Reboot the affected FX8-24 blade.	

Defect ID: DEFECT000563757	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.4.1	Technology: Access Gateway
Symptom: After a hard power off the server, HBA port remains online in Brocade 5450 switch running in AG mode.	
Condition: This issue will be observed when Brocade 5450 in AG mode is connected to an HBA port and the server connected via that port is powered off.	

Defect ID: DEFECT000564334	
Technical Severity: Low	Probability: Low
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS7.4.0	Technology: MAPS - Monitoring and Alerting Policy Suite
Symptom: MAPS indicates the switch state is marginal if only one power supply unit is present on Brocade 6505.	
Condition: This is only applicable to Brocade 6505 switch.	
Workaround: This erroneous message may be ignored.	

Defect ID: DEFECT000564450	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.4.0	Technology: Management GUI
Symptom: After using "seccertutil import -config cacert" to import an SSL CA cert in .cer (binary) format, HTTPD fails to start and hareboot fails with a message "system is not ready yet or other LS/HA config is in progress, rc = -1".	
Condition: This may be encountered when using Windows Active Directory (AD) Server Certificate Authority (CA) to sign the CSRs and import the Windows AD Sever CA cert into the switch.	
Workaround: CA certificate is allowed only with the base64 encoded certificate along with .pem extension.	

Defect ID: DEFECT000564909	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.3.1	Technology: CLI - Command Line Interface
Symptom: Switches upgraded to FOSv7.x firmware from FOSv6.4.x with long distance ISLs configured will see "Desired Buffers = 0" in portshow output instead of the configured distance.	
Condition: This issue is seen in the output of the CLI command portshow, on all platforms upgraded from FOSv6.4.x with Long distance ISLs configured. However, the ISL itself is correct and functional.	
Workaround: Use portbuffershow CLI to view the correct distance/buffer as configured.	

Defect ID: DEFECT000567733	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS7.4.0	Technology: MAPS - Monitoring and Alerting Policy Suite
Symptom: After an upgrade to Fabric OS v7.4.x, MAPS may stop working and HA Sync may be lost on a director switch.	
Condition: This is seen only after an upgrade to FOS version v7.4.x from FOS versions v7.3.x or lower under the following conditions: 1. Time base values in Fabric Watch are set to any value other than "none" for the FABRIC class. 2. And these Fabric Watch thresholds are converted to MAPS rules using "mapsconfig --fwconvert" command before the FOS upgrade occurs.	

Defect ID: DEFECT000571469	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS7.3.1	Technology: Hardware Monitoring
Symptom: Dual CP rolling reboots might occur when there is a bad blade inserted in the chassis.	
Condition: Presence of bad C3 blade that fails PCI scanning in chassis based systems might result in Rolling Reboot.	

Defect ID: DEFECT000572038	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Security
Reported In Release: FOS7.1.1	Technology: SSH - Secure Shell
Symptom: Authorized keys were deleted after distributing the PWD policy across the fabric.	
Condition: While distributing the PWD policy using distribute -PWD command,	

Defect ID: DEFECT000573229	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Traffic Management
Reported In Release: FOS7.2.1	Technology: TIZ - Traffic Isolation Zoning
Symptom: Invalid TI zones constraints may affect traffic on other ports.	
Condition: This occurred when user created invalid TI zone configuration which did not include all member of the trunk group in the TI zone.	
Recovery: Delete the invalid TI Zone and toggle effected ports	

Defect ID: DEFECT000573714	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.3.1	Technology: Fibre Channel Services
Symptom: Response to Management Server queries for Get Port List may be incomplete.	
Condition: This may be encountered while trying to get the port list by using the switch wwn	

Defect ID: DEFECT000575054	
Technical Severity: Low	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.2.1	Technology: Configuration Fundamentals
Symptom: Configuring a host name longer than 31 characters causes blank host name and the user cannot update host name any further.	
Condition: This occurs when a host name longer than 31 characters is configured.	
Recovery: ftp or scp /etc/hosts from the switch, edit it manually and ftp/scp it back to the switch to fix the impacted hosts (This does require root access).	

Defect ID: DEFECT000575837	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS7.3.1	Technology: APM - Advanced Performance Monitoring
Symptom: 'Port Snapshot Error ' screen on webtools performance graphs indicates a number of CRC errors graphically, but the 'tool tip' when hovering the mouse over the error indication still lists 0.0 frames / sec.	
Condition: When using webtool tool tip.	

Defect ID: DEFECT000575899	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.3.1	Technology: SNMP - Simple Network Management Protocol
Symptom: SNMP requests from BNA are sent to the chassis ip address but the switch responds back with the active CP IP. This may lead to BNA discovery issues.	
Condition: This issue will be seen on director class products only.	

Defect ID: DEFECT000576048	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.3.1	Technology: CLI - Command Line Interface
Symptom: Switch panic after an invalid input parameter to a CLI command.	
Condition: This occurs if the user inputs invalid blade port number to "creditrecovmode --check" CLI command.	
Workaround: do not enter invalid input.	

Defect ID: DEFECT000577234	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.3.1	Technology: Management GUI
Symptom: User cannot login via web tool	
Condition: This issue is encountered when FID is swapped between default and other logical switch and login to default switch via webtool using user whose home LF is 128.	

Defect ID: DEFECT000578229	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Traffic Management
Reported In Release: FOS7.4.0	Technology: QoS - Quality of Service
Symptom: Frame prioritization may not be effective in device applications even though CSCTL configuration is enabled for the switch and ports.	
Condition: This is a rare occurrence that may be encountered on a switch or chassis in a FICON environment.	

Defect ID: DEFECT000578556	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS7.2.1	Technology: Extended Fabrics
Symptom: Detected termination of iswitchd and switch panic.	
Condition: This may be encountered upon receiving ELS (ADISC) ACC frame with invalid size from devices.	
Workaround: Disable misbehaving 3rd party device.	

Defect ID: DEFECT000578895	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS6.3.2	Technology: NTP - Network Time Protocol
Symptom: NTP server details may not be propagated when an edge switch is attached	
Condition: This may be encountered while doing portdisable and portenable frequently.	

Defect ID: DEFECT000579051	
Technical Severity: Low	Probability: Low
Product: Brocade Fabric OS	Technology Group: Security
Reported In Release: FOS8.0.1	Technology: AAA - Authentication, Authorization, and Accounting
Symptom: Observed "Permission Denied" while executing the command apploginhistory with option "show" for the roles Admin and Factory.	
Condition: This occurs when CLI command "apploginhistory --show" is invoked.	

Defect ID: DEFECT000580692	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS7.3.1	Technology: FCIP - Fibre Channel over IP
Symptom: BR7800 failed to come online after logging diagnostic failure.	
Condition: Timing issue caused by fcippathtest as part of diag POST on BR7800	
Workaround: Disable POST.	

Defect ID: DEFECT000581254	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.4.1	Technology: SNMP - Simple Network Management Protocol
Symptom: User is unable to change mibcapability i.e Action to enable or disable a MIB/TRAP fails.	
Condition: This issue is seen on all platforms with FOS v7.4 and above when the user tries modifying mibcapability.	

Defect ID: DEFECT000582539	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Traffic Management
Reported In Release: FOS7.3.1	Technology: Fibre Channel Routing
Symptom: After a link reset on an inter fabric link (IFL) or the trunk master of an IFL trunk on a Fibre Channel Router (FCR) switch, traffic through the IFL or IFL trunk is halted.	
Condition: This occurs after an hareboot or hafailover on a 8G FCR switch, followed by a link reset on an IFL or an IFL trunk master, then traffic can no longer flow through the IFL. If a fabric only has devices with proxy IDs that have Domain ID of 3 or every fourth ID after that (Ex: 3, 7, 11, 15, etc.), then the fabric is not impacted. 16G FCR switches are not impacted.	
Recovery: portdisable/portenable IFL or the full IFL trunk.	

Defect ID: DEFECT000583512	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.4.0	Technology: Management GUI
Symptom: The switch Administration dialog uses Bandwidth and provides no clue if it is uni-directional or bi-directional bandwidth.	
Condition: The Switch Administration dialog in WebTools doesn't provide details if the bandwidth is uni-directional (Tx or Rx) or bi-directional(Tx + Rx) bandwidth similar to command line interface.	

Defect ID: DEFECT000585439	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: Access Gateway
Symptom: When switch is put in AG mode, the F-port goes into G-port and cannot be recovered	
Condition: This occurs when 3rd party device is sending back to back FLOGI requests before getting FLOGI response for the first FLOGI request.	

Defect ID: DEFECT000586141	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: High Availability
Symptom: CP goes for reboot after ASSERT on new Active CP after hafailover.	
Condition: This issue occurred during stress test with hafailover on full populated X6-8 chassis in large fabric with lot of devices.	

Defect ID: DEFECT000587033	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: Configuration Fundamentals
Symptom: A switch panic may be seen when spinfab is disrupted while in progress.	
Condition: The panic is seen only when all ports or the switch are manually disabled while D-Port or spinfab (online tests) are running. Note that such manual disabling of ports/switch is not recommended while these tests are in progress.	

Defect ID: DEFECT000587351	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS8.0.1	Technology: FCIP - Fibre Channel over IP
Symptom: Failed FCIP I/O (FICON or FCP) sequences. IFCCs on server console or errors on FCP imitators. FTRACE analysis shows duplicate FC frame sequences and missing sequences.	
Condition: During traffic burst, over BR7840 FCIP Tunnel.	

Defect ID: DEFECT000589602	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.4.0	Technology: Virtual Fabrics
Symptom: After a flooding of Class 2 FICON frames hit switch CPU, various symptoms may be encountered, such as: CP cards cannot initialize FOS or loss of Logical switch configuration.	
Condition: This may occur in FICON setup where device floods switch with class 2 RNID frames at a high rate.	
Workaround: Disable ports that send switch flooding frames.	
Recovery: Recreate missing FID after rebooting switch.	

Defect ID: DEFECT000590383	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Security
Reported In Release: FOS7.3.1	Technology: Fabric Authentication
Symptom: Certain devices are denied access to login to the switch when they have a DCC policy configured with proper WWNs.	
Condition: This may occur when either of the WWN words have the most significant bit set. For example WWNs like c0:xx:xx:xx:xx:xx:xx:xx or xx:xx:xx:xx:c0:xx:xx:xx might see this problem when DCC is configured.	

Defect ID: DEFECT000590397	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: Management GUI
Symptom: In Webtools, the list of users is not displayed instead user sees "fatal: Null Pointer Exception" error .	
Condition: It occurs when Users tab is launched from Switch Admin in Webtools	

Defect ID: DEFECT000590472	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: Flow Vision
Symptom: Sort by option for flow show in sys_mon_all_fports does not take the SID column into consideration.	
Condition: When 'flow --show sys_mon_all_fports -sortby column2' CLI is executed, it takes the DID column to sort the output instead of the SID column.	

Defect ID: DEFECT000590689	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Security
Reported In Release: FOS7.3.2	Technology: Security Policies
Symptom: When "seccertutil gencsr" is executed to generate CSR file, unneeded integer number is displayed between "Generating CSR, file name is:" and "Done." messages.	
Condition: This issue is seen on all platforms running FOSv7.3.2 but there is no functional impact.	

Defect ID: DEFECT000590931	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: Software Installation & Upgrade
Symptom: System checks during firmware install can add several minutes delay when downgrading a 32G platform to FOS v7.3.x or v7.4.x from FOS v8.0.1.	
Condition: On 32G platforms during firmware downgrade to FOS v7.3.x or v7.4.x from FOS v8.0.1.	

Defect ID: DEFECT000590946	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Traffic Management
Reported In Release: FOS7.3.1	Technology: Fibre Channel Routing
Symptom: After moving an unused port from one logical switch to another, connectivity could not be established between two other ports.	
Condition: The moved unused port shares an area with a used port in the same logical switch as the two ports which lost connectivity. After being moved, the moved port has a Port ID with an area with area and AL_PA fields that match one of the ports which lost connectivity.	
Workaround: Same as recovery.	
Recovery: Choose different ports to move to other logical switches.	

Defect ID: DEFECT000591297	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.3.1	Technology: CLI - Command Line Interface
Symptom: Customer may observe standby CP clock does not properly synchronize with the active CP.	
Condition: Customer might see this issue rarely after code upgrade or a standby CP replacement. This issue is only seen on subordinate switch in fabric.	
Recovery: Hfailover will sync the time once the standby CP becomes active CP.	

Defect ID: DEFECT000591718	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.3.2	Technology: SNMP - Simple Network Management Protocol
Symptom: auditcfg config key is not getting updated properly if the VF is enabled and switch has Logical Switches created.	
Condition: This will happen in system with logical switches setup.	
Recovery: Use hareboot/hafailover to create the keys properly.	

Defect ID: DEFECT000591754	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.4.0	Technology: Configuration Fundamentals
Symptom: Attempts to change IP address on embedded switch fails intermittently.	
Condition: This may be seen with Brocade M5424 switch, when IP address change is performed through CMC management module.	
Workaround: Log into serial console and use "ipaddrset" to change IP address.	

Defect ID: DEFECT000591792	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: Configuration Fundamentals
Symptom: Executing CLI "ifModeset" command displays error message "Error: ifModeSet - Permission denied"	
Condition: The ifModeset CLI is deprecated. There is no loss of functionality.	

Defect ID: DEFECT000591922	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS8.0.1	Technology: FCIP - Fibre Channel over IP
Symptom: Unable to modify an enabled TCL when max TCLs are active.	
Condition: Maximum number of TCLs configured and enabled on the system.	
Workaround: Use portcfg tcl <name> modify --admin-status disable to disable the TCL first and then can modify the required parameter and re-enable the TCL.	

Defect ID: DEFECT000592041	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.3.2	Technology: Configuration Fundamentals
Symptom: Supportffdc configuration is not persistent across firmwaredownload.	
Condition: This behavior is seen in all platforms with FOS Versions v7.3.2 and prior	

Defect ID: DEFECT000592079	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.2.0	Technology: High Availability
Symptom: HA synchronization issues may be encountered, or portnames may be lost in switch configuration database on both primary and secondary partitions following an hafailover.	
Condition: This may be encountered if a carriage return is inserted into a portname. The configuration database is not properly synced in such situations.	
Workaround: Reconfigure all ports (that have a carriage return in the portname) to remove the carriage returns from the portnames.	
Recovery: Reconfigure missing portnames, taking proper caution not to insert any carriage return in the portnames.	

Defect ID: DEFECT000592244	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Security
Reported In Release: FOS8.0.1	Technology: Security Policies
Symptom: Ipfiler policies do not apply to IPFC addresses.	
Condition: Create IPFC addresses on same subnet as switch IP for a virtual fabric, ipfilter rules are not applied to these IPFC addresses.	

Defect ID: DEFECT000592779	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Traffic Management
Reported In Release: FOS8.0.1	Technology: Port Bring-up
Symptom: The 16G QSFP can only get sync at 16G. It is not supporting 4G or 8G connections. If the speed is fixed to either of those two speeds, the QSFP port gets a C4-1001 port faulted due to invalid SFP or laser fault.	
Condition: If the speed is fixed to 4G/8G, C4-1001 will be seen on 16G QSFP port.	
Workaround: Please set the port to AN mode.	
Recovery: Configure the port speed to AN/16G and toggle the port.	

Defect ID: DEFECT000592802	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: D-Port - Diagnostic Port
Symptom: Porttest command fails.	
Condition: This occurs when CLI command porttest is executed on ports in a logical switch or base switch that are configured as D-port.	
Workaround: Use D-port for running link diagnostics	

Defect ID: DEFECT000593302	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS8.0.1	Technology: Extended Fabrics
Symptom: Small data transfers fail on TCP connections running through IP Extension.	
Condition: A very short lived TCP connection that sends a small amount of data immediately after it is established and is followed by an immediate close, may close without transferring any data. The TCP connection must be terminated through IP Extension.	

Defect ID: DEFECT000593472	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Security
Reported In Release: FOS8.0.1	Technology: HTTP/HTTPS
Symptom: The security certificate DAYS_TO_EXPIRE rule violation will not be highlighted in Summary Report's Todays section instead, it will be highlighted in Last 7 days section even when the rule was violated today.	
Condition: The issue is observed due to dashboard backup is after the rule violation.	
Workaround: For security certificate DAYS_TO_EXPIRE rule violation, please refer RASLOG message.	

Defect ID: DEFECT000593482	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: Software Installation & Upgrade
Symptom: Firmwaredownloadstatus command does not reflect the activation completed message.	
Condition: When the firmwaredownload is triggered stagewise using firmwaredownload -r. Once the firmwaredownload is completed, then firmwaredownloadstatus message displays all stages completion logs, but the firmwareactivate stage completed message was missing in the firmwaredownloadstatus command output.	

Defect ID: DEFECT000593528	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Traffic Management
Reported In Release: FOS7.3.1	Technology: Port Bring-up
Symptom: Ports on certain blades are always coming up as G-Port	
Condition: Two different conditions may cause this defect: 1. Interrupt the configure CLI when changing the address mode from "1" to "0". ...or... 2. Replace the port2BoundAreaMap of a switch in address mode "0" with the port2BoundAreaMap of a switch that was in address mode "1" and reboot. The number of ports on each slot of each switch must match.	
Workaround: Don't interrupt the switch in any way during an Address Mode change and don't use an incompatible port2BoundAreaMap.	
Recovery: Change the address mode to "1" and then change it again to "0".	

Defect ID: DEFECT000593549	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS8.0.1	Technology: FCIP - Fibre Channel over IP
Symptom: SFP on GE port comes up as Laser_Flt.	
Condition: This is seen on 10G tunable SFP.	

Defect ID: DEFECT000593645	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Traffic Management
Reported In Release: FOS8.0.1	Technology: Port Bring-up
Symptom: Some ports are not logging in following a bladedisable/enable or switchdisable/enable.	
Condition: Rare condition after executing stress test of a loop of bladedisable/enable or switchdisable/enable.	
Recovery: Try another disable/enable or reboot as last resort.	

Defect ID: DEFECT000593653	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.2.0	Technology: CLI - Command Line Interface
Symptom: The portcfgportcredits CLI command does not appear to set the credits specified in the command input.	
Condition: This issue may be observed with various platforms running FOS7.2.1f, 7.3.1c, 7.4.1 or later releases.	
Recovery: Bounce the affected port after running portcfgportcredits.	

Defect ID: DEFECT000593734	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: D-Port - Diagnostic Port
Symptom: While running DPORT tests on a port connected to QLogic 16G HBA, observed test fail with reason "Device does not support DPORT functionality".	
Condition: Continuously configuring the port as DPORT and toggling to run the DPORT tests can occasionally cause this.	
Recovery: Re-running the test will make it pass.	

Defect ID: DEFECT000593781	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS7.3.1	Technology: MAPS - Monitoring and Alerting Policy Suite
Symptom: CLI "mapsdb --show" gives the sum of all the violations related to the category rather than the number of violated rules per each category as the "Rule Count" counter.	
Condition: This is encountered on Switch using MAPS with the specified CLI.	

Defect ID: DEFECT000594196	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Security
Reported In Release: FOS7.4.0	Technology: Encryption
Symptom: Decommission fails for LUNs having special character "/" in LSN.	
Condition: In encryption environment(BES/FS8-18), if LUN is added for encryption with special character "/" in LSN, then decommissioning of the LUN fails.	

Defect ID: DEFECT000594259	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS7.4.1	Technology: MAPS - Monitoring and Alerting Policy Suite
Symptom: False MAPS alerts reported for SFP RX/TX Power as value is 0.	
Condition: This is applicable to all platforms and it happens when i2c access is temporarily not available.	

Defect ID: DEFECT000594354	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: RAS - Reliability, Availability, and Serviceability
Symptom: SSHOW_OS timeout during SS collection from CLI.	
Condition: In fully loaded setup while collecting SS, SSHOW_OS command exceeds its threshold timeout value (8min) and gets timeout. In that fully loaded setup it crossed 8min timeout while traversing pt_throttle_info proc entry for all ports.	
Workaround: Run supportsave with -t option (timeout multiplier option).	

Defect ID: DEFECT000594797	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: Management GUI
Symptom: Temperature display table in WebTools shows incorrect values for sensor index column.	
Condition: This issue will occur when temperature sensor index is greater than 240.	

Defect ID: DEFECT000594896	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.3.1	Technology: Software Installation & Upgrade
Symptom: Director or switch cannot boot up after reboot/hareboot/hafailover. It reports "The system is coming up, please wait..." but does not progress further.	
Condition: This is more likely to happen on switch/director that is configured with NTP service with FOS v7.2.1e, v7.3.1, v7.4.1 and later releases that contains the fix for Defect 501658. Impacted platforms are: DCX, DCX-4S, DCX8510-8, DCX8510-4, Brocade 5300, Brocade 6520, Brocade Encryption Switch	
Workaround: For director, before any reboot, run > /sbin/hwclock RTC_RD_TIME: Bad address ioctl() to /dev/rtc to read the time failed. If it reports above error, perform hafailover and reset CP so recovery is non-directruptive. For switch, please schedule a window for a disruptive POR.	
Recovery: Reseat the impacted / hung CP blade. POR the impacted switch.	

Defect ID: DEFECT000594904	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS8.0.1	Technology: FCIP - Fibre Channel over IP
Symptom: After issuing 'extnfcg --config -clear -slot <slot>' to a SX6 slot, the user will be required to reboot the chassis before any further configuration changes are allowed.	
Condition: Will occur when the 'extnfcg --config -clear -slot <slot>' command is issued on an SX6 blade.	

Defect ID: DEFECT000595314	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS8.0.1	Technology: FCIP - Fibre Channel over IP
Symptom: ESMd panic can occur on tunnel delete / cleanup.	
Condition: Rare timing case that can occur during any tunnel deletion / cleanup event. This can occur during a slotpoweroff, execution of 'portcfg fcip tunnel <ve> delete' command, execution of 'portcfg default <ve>' command, etc.	

Defect ID: DEFECT000595324	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS7.4.1	Technology: Hardware Monitoring
Symptom: CF space utilization may go to 100%, mostly from large file /var/log/slpd_xmalloc.log.	
Condition: This may be seen on Brocade BR6547 switch.	

Defect ID: DEFECT000595368	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.4.0	Technology: Management GUI
Symptom: In Webtools zone configuration tab, two zone nodes will be displayed instead of one zone node.	
Condition: This may be encountered when launching zone admin in FOS 7.4 version and later.	

Defect ID: DEFECT000595429	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS8.0.1	Technology: FCIP - Fibre Channel over IP
Symptom: SX6 blade in Gen6 chassis may experience a panic on DP.	
Condition: This may be encountered on Gen6 chassis.	

Defect ID: DEFECT000595443	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS8.0.1	Technology: FCIP - Fibre Channel over IP
Symptom: On config replay after reboot, the SLA flag can be removed from the fcip circuit configuration.	
Condition: This can occur in large configuration scenarios (2+ SX6 blades, 7+ Logical switches configured, 10+ FCIP tunnels configured). It is seen on reboot of the chassis during the config replay when there may be a timeout when attempting to modify the wtool session. Upon the timeout, the SLA is removed from the circuit instead of being put into a error state.	

Defect ID: DEFECT000595452	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS8.0.1	Technology: FCIP - Fibre Channel over IP
Symptom: FICON interface timeout detected messages/IOS005I messages during FCIP hot code load.	
Condition: Problem occurs after retry-able HCL Feature Disable errors occur, with active FICON traffic on an FCIP tunnel that has FICON emulation features enabled.	

Defect ID: DEFECT000595467	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: Configuration Fundamentals
Symptom: Preservation of the vTap/QoSH compatibility mode setting is non-deterministic across firmware downgrade from FOSv8.0.x to FOSv8.0.0, and/or on upgrade from FOSv8.0.0 to FOSv8.0.x.	
Condition: Downgrade will not be blocked as a result of vTap/QoSH compatibility setting; downgrade is allowed even when the mode is enabled. The setting may or may not persist through downgrade and subsequent upgrades; that is, there is no effort made by the Fabric OS firmware to maintain, nor clear, this setting as part of downgrade/upgrade. With FOS v8.0.1, vTap/QoSH compatibility mode is disabled by default.	
Workaround: It is recommended that vTap/QoSH compatibility mode, if enabled, be manually disabled by the user if downgrading from FOS v8.0.x to FOSv8.0.0.	

Defect ID: DEFECT000595474	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: Software Installation & Upgrade
Symptom: The power usage of CPX6 blade or SX6 extension blade might display higher in the chassisshow output than the actual power usage.	
Condition: FOS erroneously calculates the power usage of the CPX6 blades.	

Defect ID: DEFECT000595573	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS7.3.2	Technology: Flow Vision
Symptom: Customer observes a "/" following the * in the ingressport display of sys_analytics_vtap.	
Condition: This is seen when AMP is used for monitoring the fabric performance.	
Workaround: This is a cosmetic issue and functionality is not impacted.	

Defect ID: DEFECT000595586	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: Management GUI
Symptom: Memory, equal to the size of the hash configured, lost during each authentication. Over a long period of time, system may become unstable and report memory leak issue.	
Condition: On switches having WebTools and BNA management sessions.	

Defect ID: DEFECT000595599	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Traffic Management
Reported In Release: FOS8.0.1	Technology: Fibre Channel Routing
Symptom: A port in a 32G trunk group, after bounce, formed a separate trunk due to FEC state mismatch with master port.	
Condition: This problem applies for 32G trunking ports and occurs when the port goes offline because of Link failure and then comes online and tries to join master port.	

Defect ID: DEFECT000595635	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Traffic Management
Reported In Release: FOS8.0.1	Technology: FSPF - Fabric Shortest Path First
Symptom: User may observe memory allocation failure and system stuck in unresponsive state.	
Condition: This may be very rarely encountered when user terminates a running D_Port test using "portDportTest -stop <port>" command.	
Recovery: Perform power cycle to recover the switch from this state.	

Defect ID: DEFECT000595760	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.2.1	Technology: CLI - Command Line Interface
Symptom: After switch run out of shared memory, processes terminate or CLI cannot be run with error: shmInit: shmget failed: No space left on device.	
Condition: After multiple iterations of exiting the process doing configshow/configupload before getting a response from CVLM.	

Defect ID: DEFECT000595761	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: Software Installation & Upgrade
Symptom: Fan speed continuously oscillate between two speed levels every 30 minutes. Customers will see HIL-1516 raslog every time the fan speed increases as part of this oscillation.	
Condition: The fan oscillation happens on X6-4 and X6-8 chassis.	

Defect ID: DEFECT000595768	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS7.4.1	Technology: Fastwrite
Symptom: Repetitive XTUN-1001 and associated XTUN-1997 or XTUN-1999 RASLOGs reported from active FCIP DP Complex.	
Condition: Problem can occur when a particular Disk controller to controller mirroring application is active over the FCIP Tunnel, and uses an FC ELS-PRLI sequence as a heartbeat mechanism.	

Defect ID: DEFECT000595812	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Traffic Management
Reported In Release: FOS7.3.0	Technology: Buffer Credit Management
Symptom: Hosts may experience aborts and frame loss without visible errors on switch.	
Condition: This is a rare occurrence that may be triggered by a bit corruption on BE port leading to frame loss	

Defect ID: DEFECT000595881	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS8.0.1	Technology: WAN Performance Analysis Tools
Symptom: FCIP Circuit is in an Online Warning state after applying an SLA, due to SLA misconfiguration.	
Condition: Configuring an FCIP Circuit with an SLA when the circuit is in a Down state.	
Workaround: Apply SLA configuration as part of the FCIP circuit create command, or after the circuit state reaches In Progress or Online.	

Defect ID: DEFECT000595919	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Traffic Management
Reported In Release: FOS8.0.1	Technology: Port Bring-up
Symptom: Two FCIP-linked SW7840s with 40Gb LWL QSFP transitioned to a Laser Flt during firmwareupgrade	
Condition: Using 40Gb LWL QSFP on GE ports during port enable.	
Recovery: Recovery was to physically unplug/re-plug both GE0 40Gb LWL optics and both ports transitioned Online.	

Defect ID: DEFECT000596021	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.0	Technology: Configuration Fundamentals
Symptom: SFP/QSFP NO_MODULE Ports that do not have the POD license installed ,on portloopbacktest, the LEDs will glow amber.	
Condition: On running portloopbacktest, the NO_MODULE ports with no POD License glows amber.	

Defect ID: DEFECT000596027	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS7.4.1	Technology: FCIP - Fibre Channel over IP
Symptom: FCIP FCP and FICON I/O Errors during FCIP HCL Failover or Failback processing on FCP or FICON Emulation enabled tunnels.	
Condition: When running active FICON and FCP traffic over a FICON emulation and FCP emulation enabled FCIP tunnel (or different tunnels) and performing an FCIP HCL firmware upgrade or downgrade.	

Defect ID: DEFECT000596055	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS8.0.1	Technology: FCIP - Fibre Channel over IP
Symptom: Non-disruptive upgrade resulted in soft fault on DP.	
Condition: This can occur when running concurrent non-disruptive HCL on both sides of the extension tunnel with multiple extension tunnels configured between the two switches.	
Workaround: When upgrading firmware via non-disruptive HCL with extension tunnels, upgrade all switches in series allowing each switch to complete before starting the next switch.	

Defect ID: DEFECT000596066	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.2.0_hit	Technology: CLI - Command Line Interface
Symptom: Brocade 6546 units may occasionally signal to the chassis management module that a power supply voltage has reached a “fatal” level, leading to switch to be powered off.	
Condition: This is encountered only while performing AC power on/off cycling with Full POST enabled during outgoing inspection.	

Defect ID: DEFECT000596073	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: Flow Vision
Symptom: Flow Monitor with option frametype doesn't count frames.	
Condition: Flow created with option frametype.	

Defect ID: DEFECT000596090	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: Virtual Fabrics
Symptom: User may not be able to move a port to another Logical Switch.	
Condition: This may occur on ge10 port of SX6 blade.	

Defect ID: DEFECT000596220	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS8.0.1	Technology: FCIP - Fibre Channel over IP
Symptom: Upon GE port disable or switchdisable, connections are not cleared, as a result buffers are not freed up.	
Condition: This occurs following GE port disable or switchdisable with IPSec configured tunnels.	

Defect ID: DEFECT000596474	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: Flow Vision
Symptom: The user cannot configure frame monitors in Egress port on Brocade 6520 switch.	
Condition: This is encountered only on Brocade 6520 switch	

Defect ID: DEFECT000596504	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Security
Reported In Release: FOS8.0.1	Technology: IPsec - IP Security
Symptom: "IKE: Session DP1.1 Shared Key Authentication failure" errors on an FCIP tunnel - configured with an ipsec-policy having 64-bit PSK value.	
Condition: This can occur between two 7840s when one side is running 7.4.x code and the other is running 8.0.1 when there is an IPSec policy being used with a full 64 byte pre-shared key value.	
Recovery: Reconfigure the ipsec policy to use a key less than 64 bytes.	

Defect ID: DEFECT000596527	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Security
Reported In Release: FOS8.0.1	Technology: Fabric Authentication
Symptom: Port may become disabled after a firmware download from FOS v8.0.1 to FOS v7.4.x with port authentication set to DHCHAP.	
Condition: Firmwaredownload from FOS v8.0.1 to FOS v7.4.x.	
Workaround: Remove the DHCHAP keys using "secauthsecret --remove --all" and add the keys back after downgrade to FOS v7.4.x.	

Defect ID: DEFECT000596539	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: MAPS - Monitoring and Alerting Policy Suite
Symptom: Brocade 6505 model switch when shipped with single FAN/PS FRU which is the default ship configuration for this model will show WARNING message and MARGINAL switch state.	
Condition: Brocade 6505 model that is shipped with single FAN/PS FRU.	

Defect ID: DEFECT000596542	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.4.1	Technology: Fibre Channel Addressing
Symptom: In a FICON environment, timeouts occur between the mainframe and the FICON CUP which causes lots of error messages to appear on the mainframe console.	
Condition: This is more likely to occur when: 1) increase the number of Brocade Network Advisors (BNAs) monitoring the fabric, and/or 2) increase the number logical FICON paths between the mainframe and the FICON CUP.	
Workaround: Reduce the number of Brocade Network Advisors (BNA) monitoring the fabric. And/or reduce the number of logical FICON paths.	
Recovery: Same as the workaround.	

Defect ID: DEFECT000596564	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS8.0.1	Technology: FCIP - Fibre Channel over IP
Symptom: User may see a termination of process esmd.	
Condition: This can occur on heavily configured extension systems where we are near max resource limit.	

Defect ID: DEFECT000596570	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: Flow Vision
Symptom: RFM flow stats increment though mirrored frames are not being sent out through the AE-Port.	
Condition: This issue happens when a slot is power toggled or a slot is powered on when RFM flow is active and enforced.	

Defect ID: DEFECT000596578	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: Configuration Fundamentals
Symptom: FOS needs to update the APIs to support BNA in validating switchname is not all numeric.	
Condition: This is applicable to Brocade Network Advisor switchname validation only.	
Workaround: Do not use characters that are not alphanumeric, dash, underscore, or dash in a Write Port Address Name for port 0xFE.	

Defect ID: DEFECT000596587	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Traffic Management
Reported In Release: FOS8.0.1	Technology: FSPF - Fabric Shortest Path First
Symptom: When LOLA is enabled on a switch, an ISL Port offline rerouting performance enhancement results in a regression where stale routes remain programmed. The stale routes may result in frame loss or fabric domains not marked as unreachable. An FSPF crash may be observed following a non-disruptive reboot or failover.	
Condition: The stale routes can be observed following multiple E-Ports going offline in quick succession (on order of 10s of milliseconds), some of which need to include trunk master changes, when the Location ID is configured on the switch. If trunks come back online and domains become reachable again, frames may be discarded due the inclusion of the stale routes. The FSPF crash may happen if the non-disruptive reboot or failover is performed more than 30 minutes following the bulk offline.	
Workaround: When the Location ID is enabled on the switch, perform ISL port bring-down in a slower, more controlled fashion, leaving at least 1 to 2 seconds between each port disable.	
Recovery: A cold recovery or switch disable cleans up the stale routing information.	

Defect ID: DEFECT000596616	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.0.2	Technology: High Availability
Symptom: Termination of weblinker is observed.	
Condition: This issue is seen rarely during configupload operation from management application.	

Defect ID: DEFECT000596728	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS8.0.1	Technology: WAN Performance Analysis Tools
Symptom: An extension circuit will remain in a Test state for a longer period of time than expected once the packet loss on the circuit goes below the configured SLA threshold.	
Condition: Large amounts of packet loss experienced on the network for an extended period of time during an Automated WAN Tool test can cause the SLA requirements to fail even after the packet loss has been corrected.	
Recovery: Issue a stop command for the Automated WAN Tool session.	

Defect ID: DEFECT000596729	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: Licensing
Symptom: After a time based (ie trial) Integrated Routing license on Gen6 chassis has expired, EX ports are coming up even after a reboot/switchdisable/switchenable commands were issued.	
Condition: EX Ports can be activated with an expired Trial/Temp Integrated Routing Ports on Demand license installed.	

Defect ID: DEFECT000596765	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: Flow Vision
Symptom: The counters on a User created flow monitor on F-ports with frame type swr/srd are zero or have random values	
Condition: This occurs on user created flow monitors on F-ports	

Defect ID: DEFECT000597464	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: RAS - Reliability, Availability, and Serviceability
Symptom: IPv6 address not logged in SEC-1023 raslog message	
Condition: This applies for telnet session; SSH session logs fine.	

Defect ID: DEFECT000597570	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: Configuration Fundamentals
Symptom: Link level error may be seen on unsupported 32G QSFP in 16G switch ICL port.	
Condition: 32G QSFP Vendor Name: BROCADE, Vendor OUI: 00:05:1e, Vendor PN: 57-1000331-01 when inserted in a 16G chassis.	

Defect ID: DEFECT000597572	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS7.1.0	Technology: FCIP - Fibre Channel over IP
Symptom: Channel Detected Error message on z/OS console and extended tape read job failure.	
Condition: This is seen when FCIP FICON Tape Read Pipelining is active and the tape controller returns an immediate command retry status (0x4E status) to the active read command.	

Defect ID: DEFECT000598105	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: Flow Vision
Symptom: FFlow termination of npd may occur.	
Condition: This may be encountered during configdownload.	

Defect ID: DEFECT000598549	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.3.2	Technology: Management GUI
Symptom: Https with FQDN will not work if switch CSR is generated from Non- default switch FID.	
Condition: VF enabled switch might exhibit this issue.	
Workaround: Switch CSR needs to be generated only on default switch.	
Recovery: Please delete switch csr and recreate the csr from default switch ID.	

Defect ID: DEFECT000598560	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: Flow Vision
Symptom: Flow Dev Latency Impact and slow drain device messages may be seen shortly after enabling sys_gen_all_simports as follows flow --act sys_gen_all_simports	
Condition: These may be false latency reports, resulting from erroneous adjustments to currently running latency counters.	

Defect ID: DEFECT000598592	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS7.3.1	Technology: FCIP Tunnel Management
Symptom: Application traffic is disrupted without recovery after credit loss on internal trunk between C2 and FPGA/FCIP block. Enhance code to allow user configure for faulting FX8-24 in this condition.	
Condition: When there are any kind of FPGA internal or DP errors resulted in credit not returned back to the FC block on FX8-24.	
Recovery: Slotpoweroff/Slotpoweron FX8-24 blade under this condition.	

Defect ID: DEFECT000598768	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Security
Reported In Release: FOS8.0.1	Technology: Fabric Authentication
Symptom: User may encounter a Raslog ERROR Message: [AUTH-1042] - "Port <n> has been disabled, because authentication failed with code 'Authentication Failure' and explanation 'Authentication Failed'.	
Condition: This occurs when port is being enabled and DHCHAP secret is set.	

Defect ID: DEFECT000599105	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.0.2	Technology: Software Installation & Upgrade
Symptom: DCX Power Supply may encounter "unknown header" after performing a reboot via firmwaredownload or hafailover that may result in a faulty power supply unit, where Chassisshow command shows PS as follows: POWER SUPPLY Unit: <n> Unknown	
Condition: This is a very rare occurrence that may lead to FRU header corruption in the power supply internal EEPROM.	

Defect ID: DEFECT000599416	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS7.4.1	Technology: Syslog
Symptom: Changing MIB capability in SNMP does not report proper old and new values in RAS log.	
Condition: This is applicable to all platforms.	

Defect ID: DEFECT000599746	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Traffic Management
Reported In Release: FOS7.3.2	Technology: ISL - Inter-Switch Linking
Symptom: The switch.login.perSwitchMax parameter of 'F-port login setting' is removed after user issued configure setting or configdefault.	
Condition: Configkey "switch.login.perSwitchMax" gets removed only when the default value is configured. This is applicable to all platforms.	

Defect ID: DEFECT000599939	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS7.3.2	Technology: RAS - Reliability, Availability, and Serviceability
Symptom: The integer value after the string INTEGER in SNMP trap does not match with ifindex.	
Condition: This issue is applicable for all platforms.	

Defect ID: DEFECT000599994	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Traffic Management
Reported In Release: FOS8.0.1	Technology: FICON
Symptom: Chassis reboot may be encountered with a (***) glibc detected (***) ficud: malloc(): memory corruption: 0x1035f978 (***)	
Condition: The problem should only be possible to encounter for sites running zHealth Checker on the host and FMS Mode on the switches. The problem would also require having multiple switches connected with ICL links and having the switches running Device Based Routing mode.	
Workaround: Disable ICLs or change to a routing policy other than DBR or do not initiate director diagnostics queries that might traverse an ICL	

Defect ID: DEFECT000600016	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS7.3.0	Technology: MAPS - Monitoring and Alerting Policy Suite
Symptom: Kernel Panic may be encountered, triggered by "Detected termination of MAPS mdd process".	
Condition: This may occur when executing the CLI command "mapsdb --show" to get the MAPS dashboard.	

Defect ID: DEFECT000600653	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS7.3.1	Technology: FCIP - Fibre Channel over IP
Symptom: FCIP Tunnel down errors and accompanying BLZ-5024 RASLOG.	
Condition: This is seen with FCIP FICON Emulation configured tunnel and channel path error recovery occurring between channel(s) and control unit(s) or between control unit(s) and channel(s) causing OXID registration errors on the DP (only visible via FTRACE).	

Defect ID: DEFECT000600859	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: Flow Vision
Symptom: Config download with CSCTL Mode OFF does not deactivate remote flow mirroring (RFM) and mirroring still is happening.	
Condition: This occurs following config download with CM set to OFF.	

Defect ID: DEFECT000601378	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.1.0	Technology: Configuration Fundamentals
Symptom: Switch may encounter Detected termination of process mdd:2176.	
Condition: This may occur during system verification tests.	

Defect ID: DEFECT000601394	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: Management GUI
Symptom: Web Tools flyover on an X6-8 (only) Core blade in slots 7 or 8 shows far-left row of ports as Port 8 and not as port 0.	
Condition: This is seen only on X6-8 chassis, upon launching Web Tools Hardware session with X6-8 Logical Switch.	

Defect ID: DEFECT000601716	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: FA-PWWN - Fabric-Assisted Port WWN
Symptom: The FOS CLI command fapwwn on FOS embedded platforms return "This operation is not supported on this platform".	
Condition: This is encountered only on embedded platforms.	

Defect ID: DEFECT000601756	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: MAPS - Monitoring and Alerting Policy Suite
Symptom: CUP Diags may report "BRP103-LostFrame" in Health Summary when the actual error was a Link Failure MAPS threshold violation.	
Condition: 1. FMS is enabled. 2. Switch online to MVS 3. IBM Health Checker running, with IOS_FABRIC_MONITOR. 4. FMS action is enabled in MAPS config 5. MAPS rule for Link Failure threshold has the FMS action enabled 6 Link Failure threshold violation is detected by MAPS	

Defect ID: DEFECT000601844	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Traffic Management
Reported In Release: FOS8.0.1	Technology: Port Bring-up
Symptom: FC8-32E, FC8-48E and FC8-64 blades are not supported in FOS8.0.1.	
Condition: FC8-32E, FC8-48E and FC8-64 blade support was disabled/discontinued in v8.0.1. The support for these blades is reinstated in FOS8.0.2 and beyond.	

Defect ID: DEFECT000601910	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.4.1	Technology: SNMP - Simple Network Management Protocol
Symptom: User won't be able to receive HA traps even after enabling the mibcapability.	
Condition: This issue is seen in all the platform upgraded to FOS v7.4.x or later from lower versions with MIB capability disabled.	

Defect ID: DEFECT000602113	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Traffic Management
Reported In Release: FOS8.0.1	Technology: Buffer Credit Management
Symptom: The applicability of fe_crdloss option is not clear.	
Condition: This is an issue for switches running v8.0 or higher which do not support FE credit recovery.	

Defect ID: DEFECT000602116	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: Syslog
Symptom: Switch may panic due to CF getting 100% full.	
Condition: This may occur in some specific syslog-ng server connection retry cases that generates huge messages to /var/log/syslog.log.	

Defect ID: DEFECT000602264	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS8.0.1	Technology: Fastwrite
Symptom: I/O errors over an FCIP Tunnel with Fast Write enabled.	
Condition: After processing a target initiated ELS-RRQ sequence on a FCIP Tunnel that has Fast Write enabled.	
Workaround: Disable Fast Write feature on the FCIP Tunnel.	

Defect ID: DEFECT000602406	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Traffic Management
Reported In Release: FOS8.0.1	Technology: FEC - Forward Error Correction
Symptom: FEC lock and TIMEOUT errors encountered during diagnostic portloopbacktest -lb_mode 1 -ports 57-58,62 on Brocade G620 32G switch.	
Condition: This is encountered only on Brocade G620 switch.	

Defect ID: DEFECT000602632	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.2.1	Technology: Software Installation & Upgrade
Symptom: Active and standby CP failed to gain HA sync during HCL.	
Condition: Rare timing condition caused ipadmin daemon to start up late during firmware upgrade in director class products.	
Recovery: Reboot of active CP is need to recover.	

Defect ID: DEFECT000602919	
Technical Severity: Low	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: SNMP - Simple Network Management Protocol
Symptom: SNMPv1 community string does not update if the updated string is the same but different case. For example changing from STRING-1_RW to STRING-1_rw.	
Condition: This is encountered only when using CLI command line mode. This is not an issue in CLI interactive mode.	

Defect ID: DEFECT000603254	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: Flow Vision
Symptom: Firmware downgrade blocking message displayed is not clear "The vTap and QOS compatibility mode is ON at the switch FID: xx".	
Condition: This may occur when compatibility mode is ON while trying to downgrade from v8.0.1 to v7.4.x.	

Defect ID: DEFECT000603339	
Technical Severity: Low	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: MAPS - Monitoring and Alerting Policy Suite
Symptom: The description of swMemUsage/swmemUsageLimit in sw.Mib provides total memory conflicting with MIB description where it shows "memory usage limit".	
Condition: Applicable to all platforms that run MAPS.	

Defect ID: DEFECT000603533	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.3.2	Technology: Inband Management
Symptom: User may not be able to login to one or more LS through IPFC address after upgrading from FOS7.3.x to higher FOS versions.	
Condition: Most likely to see this issue if the user deletes the LS that was not the last one created.	
Workaround: Create a dummy LS if any LS was deleted before upgrading to new version.	
Recovery: Create a dummy LS after hitting the issue.	

Defect ID: DEFECT000603672	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: Hardware Monitoring
Symptom: Observed OOM condition with cached memory going up very high (>70% of total memory) during IO, with no apparent memory leak.	
Condition: This may be encountered more often with BNA polling FCR fabrics.	
Recovery: Perform an hafailover/hareboot to recover.	

Defect ID: DEFECT000603905	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.4.1	Technology: Software Installation & Upgrade
Symptom: FOS may attempt a CP firmware autosync even when the standby CP is at FOS levels below v6.4.0.	
Condition: This is seen only when Active CP is at v6.4.0 or higher FOS version and a standby CP with FOS version lower than v6.4.0 is inserted.	
Workaround: Manually invoke firmwaredownload to bring the standby CP in sync with the same FOS version as the active CP.	

Defect ID: DEFECT000604151	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: Hardware Monitoring
Symptom: Tempshow output may display incorrect information.	
Condition: Incorrect index may be displayed when tempshow is used with the -details option.	

Defect ID: DEFECT000604324	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS7.4.1	Technology: FCIP - Fibre Channel over IP
Symptom: FCIP Tunnel keep alive timeout failures and tunnel does not recover without a blade or switch reboot.	
Condition: Problem occurs as a result of the FCIP DP complex running out of WIRE buffers. The WIRE buffer pool is below 41% free and Ethernet port input is limited due to flow control mechanisms. The WIRE buffers are lost after processing received non-IKE UDP Unicast frames.	
Workaround: Prevent non-IKE UDP frames from being sent to the 7800/FX8-24 GE port IP Addresses.	

Defect ID: DEFECT000604960	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: MAPS - Monitoring and Alerting Policy Suite
Symptom: Switch state remains in CRITICAL even when all the switch status contributing parameters change from critical to marginal state.	
Condition: This behavior is seen in all platforms with FOS version 8.x.	

Defect ID: DEFECT000604974	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Security
Reported In Release: FOS7.3.2	Technology: HTTP/HTTPS
Symptom: After upgrade to FOS v7.3.2a the customer get an error message when attempting to add a new commonCA.pem file using the seccertutil command.	
Condition: This issue hit only on FOSv7.3.2a (fixed in 7.3.2b) as this is side effect of fix done for the Defect 564450. This defect does not impact any other FOS7.x and FOS 8.x running in field.	
Workaround: Import certificates in non-interactive mode will get succeed.	

Defect ID: DEFECT000605149	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS7.4.0	Technology: Hardware Monitoring
Symptom: MAPS 'dflt_base_policy' will not warn the user when 1 of its 2 PS is missing or faulty	
Condition: On Brocade switches such as Brocade7800 and 5300 where FANS and Power Supplies are separate units and when PS fails with FOS v7.4 or later.	
Workaround: This problem can be worked around with FV license until switch can be upgraded.	

Defect ID: DEFECT000605207	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS7.4.1	Technology: Hardware Monitoring
Symptom: Increase in memory utilization which could potentially lead to OOM.	
Condition: Applicable to all platforms run FOS7.4.x and above when the switch is being discovered and undiscovered by BNA continuously/periodically. Many KmsgHandler process are shown on the switch when this happens.	

Defect ID: DEFECT000605295	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.3.1	Technology: High Availability
Symptom: Observed ports went offline and online on 8G pizza box during hareboot or firmwaredownload.	
Condition: This happens on 8G switches when there is class3 timeout frame during hareboot.	
Workaround: Remove conditions that could cause class3 timeout frame drop, such as slow drain device, before a hareboot happens.	

Defect ID: DEFECT000605414	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.4.1	Technology: Software Installation & Upgrade
Symptom: Firmwaredownload using SCP protocol may fail with reason: Cannot download the requested firmware because the firmware doesn't support this platform.	
Condition: This firmwaredownload failure is encountered when using SCP and the network in use is slow or error prone.	
Workaround: 1. Investigate and fix possible network issue. 2. Use firmwaredownload with FTP or 3. Retry firmwaredownload with SCP.	
Recovery: Use firmwaredownload with FTP or retry firmwaredownload using SCP.	

Defect ID: DEFECT000606375	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: Hardware Monitoring
Symptom: The LED color during a portloopback test on 32G switch will flash Green.	
Condition: This defect is applicable to 32G platforms running loopback test.	

Defect ID: DEFECT000606560	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.2	Technology: Management GUI
Symptom: Web Tool showing E-port type is allowed for internal port.	
Condition: It may be seen on embedded switches.	

Defect ID: DEFECT000607159	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.4.1	Technology: Configuration Fundamentals
Symptom: CP panicked when blades were PORed and initializing.	
Condition: Race condition while power-cycle the blade running turboram diag test.	
Workaround: Avoid power-cycle the blade while diag test is not completed.	

Defect ID: DEFECT000607458	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: SNMP - Simple Network Management Protocol
Symptom: User is able to see community string details in Snmpconfig.html file from WT supportsave.	
Condition: This is an issue with Webtools supportsave.	

Defect ID: DEFECT000607510	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS7.4.1	Technology: RAS - Reliability, Availability, and Serviceability
Symptom: DIAG messages flooding RAS log causing raslog to wrap.	
Condition: This is exposed with background polling from application with FOS v7.4.1 and later.	

Defect ID: DEFECT000607518	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS8.0.1	Technology: FCIP - Fibre Channel over IP
Symptom: Observed Panic and switch went to rolling reboot when user tries to enable “20VE & FCIP mode” from “10Ve & Hybrid mode” on 7840 switch.	
Condition: This will occur in a multi-LS environment if there are LAN ports configured in the default switch, and the 'extnfcg --app-mode' command is issued in a non-default switch.	
Workaround: Issue 'extnfcg' command to change the app-mode in the default switch.	

Defect ID: DEFECT000607529	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS7.4.1	Technology: FCIP - Fibre Channel over IP
Symptom: FICON IFCCs on FCIP FICON emulated extended devices.	
Condition: In a FICON FCIP Emulation enabled configuration a Z/OS channel driver upgrade (to channel driver level 27 or higher) has been completed or if a DS8X00 firmware upgrade has been completed (upgrade to DS8870 Release 7.5 SP3/87.51.38.0 or later or DS8880 Release 8.01 R8.0SP1/88.1.17.0 or later).	
Workaround: Change the FICON FCIP Tunnel OXID Base to 0x9000. This can be completed with the following CLI command and subsequent tunnel bounce: portcfg fcipunnel <slot/>vePort modify --oxid-base 9000.	

Defect ID: DEFECT000607627	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS7.4.0	Technology: FCIP - Fibre Channel over IP
Symptom: VE Port stuck in G-Port state after FCIP tunnel down event.	
Condition: BR7800 or FX8-24 FCIP Tunnel with moderate or aggressive software compression enabled after a decompression error (a rare event).	
Recovery: Reboot the BR7800 or slot power off and on the FX8-24 blade.	

Defect ID: DEFECT000607971	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS7.3.1	Technology: FCIP - Fibre Channel over IP
Symptom: TSM gets ANR9999D CheckPosition - Position error volume writing to tape.	
Condition: On an FCIP OSTP enabled Tunnel, if there are FC sequence errors, there are cases when OSTP will not attempt sequence recovery (ELS-REC and FC4 SSR processing). In those cases, there will be a tape creation or recall error.	

Defect ID: DEFECT000608539	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.3.1	Technology: Access Gateway
Symptom: The agshow command with the --local option shows AGs that are "local/remote" when they are only local.	
Condition: Stale AG data received from a remote switch is not cross referenced with the remote database on the local switch.	
Workaround: Same as recovery.	
Recovery: If it is known on which switch the remote AG is stale, run agshow on that switch to clean out the stale entry. After that, the agshow command should show the correct output when run on the switch showing the issue. NOTE: more than one other switch may have the stale AG as a local entry.	

Defect ID: DEFECT000608551	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.1.0	Technology: MAPS - Monitoring and Alerting Policy Suite
Symptom: When the ports are added to a logical group using dynamic definition, the members of the group won't be removed though their names are changed through portcfgdefault.	
Condition: This issue is seen when the ports are added to a logical group through dynamic definition and their names are changed on portcfgdefault.	

Defect ID: DEFECT000608726	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.1.0	Technology: Configuration Fundamentals
Symptom: No expected error message observed during EX_ports configuration.	
Condition: When one or more ICL ports that belongs to same QSPF group present in non-base switch, configuring EX_port results in no error being displayed.	
Recovery: All ICL ports belonging to the same QSFP group should be in base switch in order to configure EX_port.	

Defect ID: DEFECT000609380	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.2	Technology: Access Gateway
Symptom: CLI 'agshow' output on one of the edge switch doesn't display ipv6 address of AG switch it is connected to.	
Condition: When AG mode switch is connected to two switches and set ipv6 address on AG, one switch will show ipv6 info while the other does not.	
Workaround: On the AG connected to switch not showing IPv6 address, disable all the N-ports together, then enable them.	

Defect ID: DEFECT000609393	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.3.2	Technology: Licensing
Symptom: When attempting to access the Extended Fabrics tab via Web Tools, it gives a message "Access to this and other advanced Web Tools features requires installation of the Enhanced Group Management (EGM) license on this switch."	
Condition: EGM license was not included in FOS by default on 16G embedded switches.	

Defect ID: DEFECT000609437	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: Inband Management
Symptom: 3rd party management chassis shows previous static IP address instead of address assigned by DHCP server.	
Condition: It impacts 3rd party management chassis with embedded switch.	

Defect ID: DEFECT000609479	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Security
Reported In Release: FOS8.0.1	Technology: AAA - Authentication, Authorization, and Accounting
Symptom: "charset" option in passwdcfg is not properly checked.	
Condition: Perform passwdcfg --set -charset and passwdcfg --set -minlength, but minlenth is not verified with error message.	

Defect ID: DEFECT000609504	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Security
Reported In Release: FOS8.0.1	Technology: HTTP/HTTPS
Symptom: Customer will see the message:/fabos/sbin/configSslNoti: /fabos/libexec/rpcdcfgghandler: No such file or directorywhen configuring SSL certificate file name via the "configure" command.	
Condition: It happens when ssl attribute is configured/changed on switches running FOSv8.0.1, v8.0.1a and v8.0.1b only.	

Defect ID: DEFECT000609546	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Security
Reported In Release: FOS8.0.1	Technology: Fabric Authentication
Symptom: Error message in output of executing `seccertutil import` and `seccertutil export` with interactive mode. The message shows "stty: invalid argument `/bin/echo' Try `stty --help' for more information.". And in executing these commands, input password is displayed.	
Condition: Issuing seccertutil import/export command.	

Defect ID: DEFECT000610053	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.4.1	Technology: High Availability
Symptom: Switch went into rolling reboot after load a config file with a MAPs policy rule >= 40 characters.	
Condition: A MAPs policy rule Name from previous version got downloaded to a switch with version higher than FOSv7.4.0	
Workaround: Remove the MAPs policy rule with >=40 rule length before download.	
Recovery: Contact TAC to assist with stop switch from rolling reboot: swap boot partition or firmwarecleaninstall can be used to bring the switch back.	

Defect ID: DEFECT000610300	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.1.0	Technology: MAPS - Monitoring and Alerting Policy Suite
Symptom: A newly created MAPS rule may get associated with existing policy and rule deletion may fail.	
Condition: This occurs when policy name is not mentioned while creating the MAPS rule.	

Defect ID: DEFECT000610619	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: Hardware Monitoring
Symptom: G620 has 3 fans in each PSU. Incorrect fan speed and status are observed when any of the fan in G620's PSU is stopped.	
Condition: This issue is seen on stopping any of the fan in G620.	

Defect ID: DEFECT000610657	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.1.0	Technology: Hardware Monitoring
Symptom: Tempshow command would display sensor index even without -detail option.	
Condition: This issue is observed on executing tempshow command.	

Defect ID: DEFECT000611046	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Security
Reported In Release: FOS7.4.1	Technology: Security Policies
Symptom: CLI ipfilter allows user to block TCP port 514 which cause BR7840 bring up timeout reboot loop. .	
Condition: This impacts BR7840 and Analytics Monitoring Platform. Use the following command to check the ipfilter policy: ipfilter -show 7 any tcp 514 deny	
Workaround: Remove TCP port 514 from ipfilter block list to bring up switch.	

Defect ID: DEFECT000611167	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.1.0	Technology: High Availability
Symptom: Ifmd termination encountered on core base switch along with Critical raslog message: [KSWD-1002], 44/2, SLOT 2 FFDC CHASSIS, WARNING, ?, Detected termination of process ifmd [HAM-1014], 4, SLOT 2 CHASSIS, CRITICAL, ?, Non restartable component (lfm (pid=2758)) died.	
Condition: This occurs after switch is disabled and enabled in all edge base switches.	

Defect ID: DEFECT000611430	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: Configuration Fundamentals
Symptom: New Log file will be created to capture the logs from Switch and Zone admin tab.	
Condition: Applicable to all switches.	

Defect ID: DEFECT000612205	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Security
Reported In Release: FOS8.0.1	Technology: IPsec - IP Security
Symptom: In IKE policy tab in WebTools, Add and Edit button are enabled. They needs to be disabled.	
Condition: Applicable to all switch types.	

Defect ID: DEFECT000612616	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.4.1	Technology: CLI - Command Line Interface
Symptom: Request enhancement that using -f - force options to bypass prompt for following CLIs: cfgsave, cfgenable, cfgdisable.	
Condition: Run CLI cfgsave, cfgenable, cfgdisable.	

Defect ID: DEFECT000613200	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.1.0	Technology: Configuration Fundamentals
Symptom: A Kernel Panic is observed during zoning configuration update.	
Condition: This occurs after setting defzone to noaccess followed by cfgsave.	

Defect ID: DEFECT000613468	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.1.0	Technology: High Availability
Symptom: Ifmd termination and switch panic encountered along with Critical raslog message: [HAM-1014], 35, CHASSIS, CRITICAL, Stinger84, Non restartable component (lfm (pid=1558)) died	
Condition: This occurs after hareboot/hafailover on other switches in the fabric, while rebooting the core switch in the same fabric.	

Defect ID: DEFECT000613656	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS7.4.1	Technology: FCIP Tunnel Management
Symptom: Following an upgrade, the FCIP tunnels may not come back up fully. DP status in "portshow fcip tunnel --hcl-status" CLI output still shows the DPs being stuck at the previous firmware version.	
Condition: This may be encountered following an upgrade or downgrade with VF enabled.	
Recovery: Revert back to the previous firmware version that the DPs were stuck at reboot to bring the tunnels back up.	

Defect ID: DEFECT000613767	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS8.1.0	Technology: FCIP - Fibre Channel over IP
Symptom: IPEXT traffic fails to start due to ARP resolution issues.	
Condition: This may occur when changing modes from WAN to LAN.	

Defect ID: DEFECT000613801	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS7.4.1	Technology: FCIP - Fibre Channel over IP
Symptom: Frequent XTUN-1997 messages logged on BR7840.	
Condition: Problem occurs on a BR7840 FCIP tunnel that has Fast Write and/or Fast Write and OSTP enabled when certain ELS Sequences are received from a target.	

Defect ID: DEFECT000613805	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Traffic Management
Reported In Release: FOS8.1.0	Technology: Fibre Channel Routing
Symptom: Following hfailover traffic is dropped and does not recover.	
Condition: This may occur in a VF switch with edge to edge traffic when there is a segmented E-port in the logical switch which is connected as edge fabric.	
Workaround: Remove the segmented e-port which triggers "build fabric" after warm recovery in the FCR.	

Defect ID: DEFECT000613818	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.0.0	Technology: Fibre Channel Services
Symptom: Large accumulation of CRC errors over time on FC8-64 cards in DCX+ and DCX-4S+ switch. Usually these errors manifest as CRC with Good EOF.	
Condition: Error conditions only occur on some customer configurations, but generally occur with high BE traffic loads on DCX+ and DCX-4S+ when FC8-64 cards are installed.	

Defect ID: DEFECT000613976	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.2	Technology: Configuration Fundamentals
Symptom: Unlimited dhclient processes are created, causing system resource to run out and other daemons to panic randomly. Also dhclient generates flooding of logs.	
Condition: This occurs when DHCP is enabled but there is no IP address obtained from the DHCP server.	

Defect ID: DEFECT000614336	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.1.0	Technology: MAPS - Monitoring and Alerting Policy Suite
Symptom: MAPS - Unmonitored designation for rules is inconsistent across policies.	
Condition: This designation (referring to the * that is prepended to some rules) is inconsistent especially with the aggressive policy.	

Defect ID: DEFECT000615004	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Security
Reported In Release: FOS7.4.1	Technology: Encryption
Symptom: FFDC and software verify error occurs when running cryptocfg --initnode command from BES CLI.	
Condition: This would happen only on BES switches running FOS v7.4.1d release.	

Defect ID: DEFECT000615272	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: MAPS - Monitoring and Alerting Policy Suite
Symptom: Output of "mapsrule --help" is incomplete.	
Condition: Run "mapsrule --help" CLI.	

Defect ID: DEFECT000615557	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.2.1	Technology: High Availability
Symptom: DCX 8510 and DCX 8510-4S may report faulty fans falsely.	
Condition: This occurs under heavy CPU load situation.	
Recovery: Re-seat the impacted FAN FRU.	

Defect ID: DEFECT000615648	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.3.2	Technology: Access Gateway
Symptom: May encounter continuous occurrence of FCPH-1007 RASLOG messages.	
Condition: This occurs when the following conditions are met: - Access Gateway with FOS v7.3.1c or above. - Multiple Access Gateway N-ports connected to the same fabric switch. - Devices connected to Access Gateway go offline immediately after logging in. - Access Gateway sends the same single event on multiple N-ports at the same time.	
Recovery: If possible, prevent devices from going offline immediately after logging in.	

Defect ID: DEFECT000615687	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS8.1.0	Technology: Extended Fabrics
Symptom: Switch is set to a faulty state when a reboot is performed on local node during hot code load.	
Condition: This may occur following creation of MAX tunnels between Brocade 7840 and SX-6.	

Defect ID: DEFECT000616486	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Security
Reported In Release: FOS7.4.1	Technology: SSH - Secure Shell
Symptom: Unable to authenticate an SSH session after importing public key to switch.	
Condition: This is encountered by admin level users on a switch running Fabric OS v7.4.1d.	

Defect ID: DEFECT000616690	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: NTP - Network Time Protocol
Symptom: After running CLI "tstimezone --old -6" to change the time to GMT -6, CLI date will show it as GMT+6.	
Condition: Run "tstimezone --old" option.	

Defect ID: DEFECT000616781	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.3.2	Technology: High Availability
Symptom: CPs may drop HA sync after Network Patroller daemon (NPD) panic during firmware upgrade.	
Condition: This may be encountered during firmware upgrade on systems with multiple Logical Switches, and each LS has some ports with csctl_mode enabled.	
Recovery: Reboot active CP in a maintenance window.	

Defect ID: DEFECT000616852	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: CLI - Command Line Interface
Symptom: Port state of LISL ports in switchshow output is misaligned.	
Condition: This behavior is seen only for LISL ports.	

Defect ID: DEFECT000616857	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: Analytics Monitoring
Symptom: Activation of vTAP flow fails.	
Condition: It happens when vtap was modified on slave port, and then try to deactivated and activated the vtap on master port.	

Defect ID: DEFECT000616896	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.0.1	Technology: Flow Vision
Symptom: FFDC event along with the following Critical Raslog may be encountered during firmwareupgrade. [HAM-1014], 793, SLOT 4 CHASSIS, CRITICAL, Brocade_DCX4S, Non restartable component (ess (pid=2120)) died.	
Condition: This may occur during firmwareupgrade from FOS v7.4.1x.	
Workaround: Maintain a stable fabric during Firmware upgrade, where all domains in the fabric remain online during the entire firmware upgrade process.	

Defect ID: DEFECT000617157	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS8.1.0	Technology: MAPS - Monitoring and Alerting Policy Suite
Symptom: User may encounter MAPS termination of mdd and assert error.	
Condition: This may be encountered while using sfp monitor user defined rules.	

Defect ID: DEFECT000617706	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: CLI - Command Line Interface
Symptom: When executing the "-m 32" operand of the portcfgspeed command, the speed of portcfgshow is displayed as "??".	
Condition: This will be seen in all 32G platform running FOS 8.0.0 and 8.0.1.	

Defect ID: DEFECT000617788	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: Configuration Fundamentals
Symptom: Encountered configDownload failure with an error message : Generic Error- Process function of configdownload failed for filter "snmp".	
Condition: This is encountered only, in the following scenario: 1) Block ports using snmptraps block command. 2) Unblock using snmptraps unblock port ALL. 3) Execute configupload. 4) Execute configdownload.	

Defect ID: DEFECT000618464	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS7.4.1	Technology: MAPS - Monitoring and Alerting Policy Suite
Symptom: The Maps daemon (MDD) panicked and did not restart on active CP. As a result the director lost HA SYNC.	
Condition: This happened when standby CP was in and out of faulty state very frequently, and HA could not be recovered even after standby CP replacement.	
Recovery: Reboot active CP in a maintenance window.	

Defect ID: DEFECT000618708	
Technical Severity: Low	Probability: High
Product: Brocade Fabric OS	Technology Group: Security
Reported In Release: FOS7.4.1	Technology: User Accounts & Passwords
Symptom: When logging in to a user defined account with user defined role, access to udrole directory runs into the error "No directory /fabos/users/udrole!".	
Condition: This is encountered when a user defined user with user defined role is created.	

Defect ID: DEFECT000619258	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: CLI - Command Line Interface
Symptom: 'reseterror' option in 'ethif' CLI cannot be issued on a G620 switch.	
Condition: This issue is seen while executing the command 'ethif --reseterror eth0' on G620.	

Defect ID: DEFECT000619435	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS7.3.1	Technology: FCIP - Fibre Channel over IP
Symptom: Observed FFDC and peer side FCIP Tunnel bounce.	
Condition: When activating zOS paths over a FICON Emulation enabled FCIP Tunnel.	

Defect ID: DEFECT000620268	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS7.4.1	Technology: FCIP Tunnel Management
Symptom: During upgrade of BR7840s with Virtual Fabric enabled, the tunnels never fully came back up. It showed "empty" and "incomplete".	
Condition: Uninitialized data contains invalid values which cause the tunnel configuration to not be applied after an HA event.	
Recovery: Back down to pre-FOSv7.4.x version and reboot.	

Defect ID: DEFECT000620551	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS7.4.1	Technology: FCIP - Fibre Channel over IP
Symptom: Multiple XTUN-1997 per day with minimal zOS reported IFCCs on extended CHPIDs.	
Condition: Invalid FTRACE trigger (should not be a trigger) occurs when FCIP is processing ELS-RDP SOFi2 sequences on a FICON Emulation enabled FCIP Tunnel. The receipt of a BA-ACC will generate the XTUN-1997 message and trigger a trace buffer on BR7840.	

Defect ID: DEFECT000621111	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.3.2	Technology: High Availability
Symptom: After Out of memory (OOM) is detected, the switch may encounter panic when hareboot is attempted to recover from OOM.	
Condition: This may occur under intense file activities, especially on FC Router switches, when greater than 70% of total memory is moved to cache pool by Linux.	
Recovery: Manual hareboot when free memory is at 15% of total memory.	

Defect ID: DEFECT000621163	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Monitoring
Reported In Release: FOS7.4.1	Technology: RAS - Reliability, Availability, and Serviceability
Symptom: Customer noticed the corrupt of audit class configuration: sw0:admin> configshow grep audit audit.cfg.class:1,2,3,4,5,7,8,9,1010, <<< Strange value "1010,".	
Condition: Observed after firmwaredownload to FOS v7.4.1d and FOS v8.0.1x.	

Defect ID: DEFECT000621636	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS8.0.1	Technology: Management GUI
Symptom: In zone admin dialog, the zone configuration will not list the members for the peer zone.	
Condition: This is applicable only for the cloned peer zone configuration.	

Closed with code changes in Fabric OS 8.0.1b

This section lists software defects with Critical, High, and Medium Technical Severity closed with a code change as of August 31, 2016 in version 8.0.1b.

Defect ID: DEFECT000589602	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.4.0	Technology: Virtual Fabrics
Symptom: Various symptoms after a flooding of Class 2 FICON frame hit switch CPU such as: CP cards cannot initialize FOS or loss of Logical switch configuration.	
Condition: This may occur in FICON setup where device flood switch with class 2 RNID frames at a high rate.	
Workaround: Disable ports that send switch flooding frames.	
Recovery: Recreate missing FID after rebooting switch.	

Defect ID: DEFECT000594896	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.3.1	Technology: Software Installation & Upgrade
Symptom: Director or switch cannot boot up after reboot/hareboot/hafailover. It reports "The system is coming up, please wait..." but does not progress further.	
Condition: This is more likely to happen on switch/director that is configured with NTP service with FOS v7.2.1e, v7.3.1, v7.4.1 or later releases that contains the fix for Defect 501658. Impacted platforms are: DCX, DCX-4S, DCX8510-8, DCX8510-4, Brocade 5300, Brocade 6520, and Brocade Encryption Switch	
Workaround: For director, before any reboot, run <pre>> /sbin/hwclock RTC_RD_TIME: Bad address ioctl() to /dev/rtc to read the time failed.</pre> If it reports above error, perform hafailover and reset CP so recovery is non-directruptive. For switch, please schedule a window for a disruptive POR.	
Recovery: Reseat the impacted / hung CP blade. POR the impacted switch.	

Defect ID: DEFECT000596542	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.4.1	Technology: Fibre Channel Addressing
Symptom: In a FICON environment, timeouts occur between the mainframe and the FICON CUP which causes lots of error messages to appear on the mainframe console.	
Condition: This is more likely to occur when there is an: 1) increase in the number of Brocade Network Advisors (BNAs) monitoring the fabric, and/or 2) increase in the number logical FICON paths between the mainframe and the FICON CUP.	
Workaround: Reduce the number of Brocade Network Advisors (BNA) monitoring the fabric, and/or reduce the number of logical FICON paths.	
Recovery: Same as the workaround.	

Closed with code changes in Fabric OS 8.0.1a

This section lists software defects with Critical, High, and Medium Technical Severity closed with a code change as of June 30, 2016 in version 8.0.1a.

Defect ID: DEFECT000561871	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology Group: Management
Reported In Release: FOS7.3.1	Technology: Fibre Channel Services
Symptom: If the portEportCredits and portFportBuffers are set on ports using these respective CLI commands, then performing a configdownload that does not include these 'keys' results in the ports being set back to the default setting.	
Condition: This occurs upon configdownload of a configuration file with portEportCredits and portFportBuffers keys absent.	
Workaround: Do not remove port eportcredits and fportbuffers configuration from the configdownload configuration file.	
Recovery: reconfigure the impacted ports by invoking portEportCredits and portFportBuffers CLI commands.	

Defect ID: DEFECT000563629	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology Group: Extension
Reported In Release: FOS7.2.1	Technology: FCIP - Fibre Channel over IP
Symptom: One or more IPSec enabled FCIP circuits may continuously bounce or go down and not recover. The affected DP will report Authentication Tag Mismatch errors continually.	
Condition: This may be encountered when IPSec is enabled on an FCIP tunnel between a pair of FX8-24 blades.	
Recovery: Reboot the affected FX8-24 blade.	

Defect ID:	DEFECT000576596		
Technical Severity:	High	Probability:	Medium
Product:	Brocade Fabric OS	Technology Group:	Monitoring
Reported In Release:	FOS8.0.0	Technology:	RAS - Reliability, Availability, and Serviceability
Symptom:	When configremoveall is issued, FFDC SNMP-1004 error is seen.		
Condition:	The FFDC SNMP-1004 error occasionally can be seen during a configremoveall.		

Defect ID:	DEFECT000587033		
Technical Severity:	High	Probability:	Low
Product:	Brocade Fabric OS	Technology Group:	Management
Reported In Release:	FOS8.0.1	Technology:	Configuration Fundamentals
Symptom:	A switch panic may be seen when spinfab is disrupted while in progress.		
Condition:	The panic is seen only when all ports or the switch are manually disabled while D-Port or spinfab (online tests) are running. Note that such manual disabling of ports/switch is not recommended while these tests are in progress.		

Defect ID:	DEFECT000587533		
Technical Severity:	High	Probability:	Low
Product:	Brocade Fabric OS	Technology Group:	Monitoring
Reported In Release:	FOS8.0.1	Technology:	D-Port - Diagnostic Port
Symptom:	When the D-Port test is run on a range of ports containing more than 30 ports, the D-Port test may occasionally fail on one port.		
Condition:	The issue occurs only when the D-Port test is run simultaneously on more than the recommended number (8) of ports.		
Workaround:	Rerun the D-Port test on the failed ports.		

Defect ID:	DEFECT000590472		
Technical Severity:	Medium	Probability:	Medium
Product:	Brocade Fabric OS	Technology Group:	Monitoring
Reported In Release:	FOS8.0.1	Technology:	Flow Vision
Symptom:	Sort by option for flow show in sys_mon_all_fports does not take the SID column into consideration.		
Condition:	When 'flow --show sys_mon_all_fports -sortby column2' CLI is executed, it takes the DID column to sort the output instead of the SID column.		

Defect ID:	DEFECT000590689		
Technical Severity:	Medium	Probability:	Medium
Product:	Brocade Fabric OS	Technology Group:	Security
Reported In Release:	FOS7.3.2	Technology:	Security Policies
Symptom:	When "seccertutil gencsr" is executed to generate CSR file, unneeded integer number is displayed between "Generating CSR, file name is:" and "Done." messages.		
Condition:	This issue is seen on all platforms running FOSv7.3.2 but there is no functional impact.		

Defect ID:	DEFECT000590890		
Technical Severity:	High	Probability:	Medium
Product:	Brocade Fabric OS	Technology Group:	Monitoring
Reported In Release:	FOS8.0.1	Technology:	MAPS - Monitoring and Alerting Policy Suite
Symptom:	Maps CIR_UTIL violation may display large % value in configurations having 8 logical switches.		
Condition:	Extension Service Module may run out of resources when an IPEX tunnel in the base switch is shared by multiple logical switches		

Defect ID:	DEFECT000590931		
Technical Severity:	Medium	Probability:	Low
Product:	Brocade Fabric OS	Technology Group:	Management
Reported In Release:	FOS8.0.1	Technology:	Software Installation & Upgrade
Symptom:	System checks during firmware install can add several minutes delay when downgrading a GEN5 platform to FOS v7.3.x or v7.4.x from FOS v8.0.1.		
Condition:	On Gen5 platforms during firmware downgrade to FOS v7.3.x or v7.4.x from FOS v8.0.1.		

Defect ID:	DEFECT000591754		
Technical Severity:	High	Probability:	High
Product:	Brocade Fabric OS	Technology Group:	Management
Reported In Release:	FOS7.4.0	Technology:	Configuration Fundamentals
Symptom:	Attempts to change IP address on embedded switch fails intermittently.		
Condition:	This may be seen with Brocade M5424 switch, when IP address change is performed through CMC management module.		
Workaround:	Log into serial console and use "ipaddrset" to change IP address.		

Defect ID:	DEFECT000591792		
Technical Severity:	Medium	Probability:	Medium
Product:	Brocade Fabric OS	Technology Group:	Management
Reported In Release:	FOS8.0.1	Technology:	Configuration Fundamentals
Symptom:	Executing the ethif CLI command displays error message "Error: ifModeSet - Permission denied"		
Condition:	The ifModeset CLI is deprecated. There is no loss of functionality.		

Defect ID:	DEFECT000591922		
Technical Severity:	Medium	Probability:	Medium
Product:	Brocade Fabric OS	Technology Group:	Extension
Reported In Release:	FOS8.0.1	Technology:	FCIP - Fibre Channel over IP
Symptom:	Unable to modify an enabled TCL when max TCLs are active.		
Condition:	Maximum number of TCLs configured and enabled on the system.		
Workaround:	Use portcfg tcl <name> modify --admin-status disable to disable the TCL first and then can modify the required parameter and re-enable the TCL.		

Defect ID:	DEFECT000592802		
Technical Severity:	Medium	Probability:	High
Product:	Brocade Fabric OS	Technology Group:	Monitoring
Reported In Release:	FOS8.0.1	Technology:	D-Port - Diagnostic Port
Symptom:	Porttest command fails on ports in a logical switch or base switch that are configured as D-port.		
Condition:	Porttest command failure is seen when executed on ports in a logical switch or base switch that are configured as D-port.		
Workaround:	Use D-port for running link diagnostics		

Defect ID:	DEFECT000593302		
Technical Severity:	Medium	Probability:	Medium
Product:	Brocade Fabric OS	Technology Group:	Extension
Reported In Release:	FOS8.0.1	Technology:	Extended Fabrics
Symptom:	Small data transfers fail on TCP connections running through IP Extension.		
Condition:	A very short lived TCP connection that sends a small amount of data immediately after it is established and is followed by an immediate close, may close without transferring any data. The TCP connection must be terminated through IP Extension.		

Defect ID:	DEFECT000593472		
Technical Severity:	High	Probability:	Medium
Product:	Brocade Fabric OS	Technology Group:	Security
Reported In Release:	FOS8.0.1	Technology:	HTTP/HTTPS
Symptom:	The security certificate DAYS_TO_EXPIRE rule violation will not be highlighted in Summary Report's Todays section instead, it will be highlighted in Last 7 days section even when the rule was violated today.		
Condition:	The issue is observed due to dashboard backup is after the rule violation.		
Workaround:	For security certificate DAYS_TO_EXPIRE rule violation, please refer RASLOG message.		

Defect ID:	DEFECT000593549		
Technical Severity:	High	Probability:	High
Product:	Brocade Fabric OS	Technology Group:	Extension
Reported In Release:	FOS8.0.1	Technology:	FCIP - Fibre Channel over IP
Symptom:	SFP on GE port comes up as Laser_Flt		
Condition:	This is seen on 10G tunable SFP.		

Defect ID:	DEFECT000593653		
Technical Severity:	High	Probability:	Low
Product:	Brocade Fabric OS	Technology Group:	Management
Reported In Release:	FOS7.2.0	Technology:	CLI - Command Line Interface
Symptom:	The portcfgportcredits CLI command does not appear to set the credits specified in the command input.		
Condition:	This issue may be observed with various platforms running FOS7.2.1f, 7.3.1c, 7.4.1 or later releases.		
Recovery:	Bounce the affected port after running portcfgportcredits.		

Defect ID:	DEFECT000595452		
Technical Severity:	Medium	Probability:	Low
Product:	Brocade Fabric OS	Technology Group:	Extension
Reported In Release:	FOS8.0.1	Technology:	FCIP - Fibre Channel over IP
Symptom:	FICON interface timeout detected messages/IOS005I messages during FCIP HCL		
Condition:	Problem occurs after retry-able HCL Feature Disable errors occur, with active FICON traffic on an FCIP tunnel that has FICON emulation features enabled.		

Defect ID:	DEFECT000595474		
Technical Severity:	Medium	Probability:	Low
Product:	Brocade Fabric OS	Technology Group:	Management
Reported In Release:	FOS8.0.1	Technology:	Software Installation & Upgrade
Symptom:	The power usage of CPX6 blade or SX6 extension blade might display higher in the chassisshow output than the actual power usage.		
Condition:	FOS erroneously calculates the power usage of the CPX6 blades.		

Defect ID:	DEFECT000595586		
Technical Severity:	High	Probability:	Low
Product:	Brocade Fabric OS	Technology Group:	Management
Reported In Release:	FOS8.0.1	Technology:	Management GUI
Symptom:	Memory, equal to the size of the hash configured, lost during each authentication. Over a long period of time, system may become unstable and report memory leak issue.		
Condition:	On switches having WebTools and BNA management sessions.		

Defect ID:	DEFECT000595599		
Technical Severity:	High	Probability:	Medium
Product:	Brocade Fabric OS	Technology Group:	Traffic Management
Reported In Release:	FOS8.0.1	Technology:	Fibre Channel Routing
Symptom:	When the port that is online at 32G goes offline because of link failure and comes back online, the port can form a separate trunk because of the FEC state mismatch with master port. This problem applies for 32G trunking ports.		
Condition:	This problem applies for 32G trunking ports and occurs when the port goes offline because of Link failure and then comes online and tries to join master port.		

Defect ID:	DEFECT000595761		
Technical Severity:	Medium	Probability:	Medium
Product:	Brocade Fabric OS	Technology Group:	Management
Reported In Release:	FOS8.0.1	Technology:	Software Installation & Upgrade
Symptom:	Fan speed continuously oscillate between two speed levels every 30 minutes. Customers will see HIL-1516 raslog every time the fan speed increases as part of this oscillation.		
Condition:	The fan oscillation happens on X6-4 and X6-8 chassis.		

Defect ID:	DEFECT000595768		
Technical Severity:	High	Probability:	High
Product:	Brocade Fabric OS	Technology Group:	Extension
Reported In Release:	FOS7.4.1	Technology:	Fastwrite
Symptom:	Repetitive XTUN-1001 and associated XTUN-1997 or XTUN-1999 RASLOGs reported from active FCIP DP Complex.		
Condition:	Problem can occur when a particular Disk controller to controller mirroring application is active over the FCIP Tunnel, and uses an FC ELS-PRLI sequence as a heartbeat mechanism.		

Defect ID:	DEFECT000595881		
Technical Severity:	Medium	Probability:	Medium
Product:	Brocade Fabric OS	Technology Group:	Extension
Reported In Release:	FOS8.0.1	Technology:	WAN Performance Analysis Tools
Symptom:	FCIP Circuit is in an Online Warning state after applying an SLA, due to SLA misconfiguration.		
Condition:	Configuring an FCIP Circuit with an SLA when the circuit is in a Down state.		
Workaround:	Apply SLA configuration as part of the FCIP circuit create command, or after the circuit state reaches In Progress or Online.		

Defect ID:	DEFECT000596027		
Technical Severity:	High	Probability:	Medium
Product:	Brocade Fabric OS	Technology Group:	Extension
Reported In Release:	FOS7.4.1	Technology:	FCIP - Fibre Channel over IP
Symptom:	FCIP FCP and FICON I/O Errors during FCIP HCL Failover or Failback processing on FCP or FICON Emulation enabled tunnels		
Condition:	When running active FICON and FCP traffic over a FICON emulation and FCP emulation enabled FCIP tunnel (or different tunnels) and performing an FCIP HCL firmware upgrade or downgrade.		

Defect ID:	DEFECT000596220		
Technical Severity:	High	Probability:	Medium
Product:	Brocade Fabric OS	Technology Group:	Extension
Reported In Release:	FOS8.0.1	Technology:	FCIP - Fibre Channel over IP
Symptom:	Upon GE port disable or switchdisable, connections are not cleared, as a result buffers are not freed up.		
Condition:	This occurs following GE port disable or switchdisable with IPSec configured tunnels		

Defect ID:	DEFECT000596527		
Technical Severity:	Medium	Probability:	Low
Product:	Brocade Fabric OS	Technology Group:	Security
Reported In Release:	FOS8.0.1	Technology:	Fabric Authentication
Symptom:	Port may become disabled after a firmware download from FOS v8.0.1 to FOS v7.4.x with port authentication set to DHCHAP		
Condition:	Firmwaredownload from FOS v8.0.1 to FOS v7.4.x		
Workaround:	Remove the DHCHAP keys using "secauthsecret --remove --all" and add the keys back after downgrade to FOS v7.4.x		

Defect ID:	DEFECT000596539		
Technical Severity:	Medium	Probability:	High
Product:	Brocade Fabric OS	Technology Group:	Monitoring
Reported In Release:	FOS8.0.1	Technology:	MAPS - Monitoring and Alerting Policy Suite
Symptom:	Brocade 6505 model switch when shipped with single FAN/PS FRU which is the default ship configuration for this model will show WARNING message and MARGINAL switch state.		
Condition:	Brocade 6505 model that is shipped with single FAN/PS FRU.		

Defect ID:	DEFECT000597572		
Technical Severity:	High	Probability:	Low
Product:	Brocade Fabric OS	Technology Group:	Extension
Reported In Release:	FOS7.1.0	Technology:	FCIP - Fibre Channel over IP
Symptom:	Channel Detected Error message on z/OS console and extended tape read job failure		
Condition:	This is seen when FCIP FICON Tape Read Pipelining is active and the tape controller returns an immediate command retry status (0x4E status) to the active read command.		

Defect ID:	DEFECT000599105		
Technical Severity:	High	Probability:	High
Product:	Brocade Fabric OS	Technology Group:	Management
Reported In Release:	FOS7.0.2	Technology:	Software Installation & Upgrade
Symptom:	DCX Power Supply may encounter "unknown header" after performing a reboot via firmwaredownload or hafailover that may result in a faulty power supply unit, where Chassisshow command shows PS as follows: POWER SUPPLY Unit: <n> Unknown		
Condition:	This is a very rare occurrence that may lead to FRU header corruption in the power supply internal EEPROM.		

Defect ID:	DEFECT000600653		
Technical Severity:	Medium	Probability:	High
Product:	Brocade Fabric OS	Technology Group:	Extension
Reported In Release:	FOS7.3.1	Technology:	FCIP - Fibre Channel over IP
Symptom:	FCIP Tunnel down errors and accompanying BLZ-5024 RASLOG		
Condition:	This is seen with FCIP FICON Emulation configured tunnel and channel path error recovery occurring between channel(s) and control unit(s) or between control unit(s) and channel(s) causing OXID registration errors on the DP (only visible via FTRACE).		

Defect ID:	DEFECT000603905		
Technical Severity:	Medium	Probability:	High
Product:	Brocade Fabric OS	Technology Group:	Management
Reported In Release:	FOS7.4.1	Technology:	Software Installation & Upgrade
Symptom:	FOS may attempt a CP firmware autosync even when the standby CP is at FOS levels below v6.4.0		
Condition:	This may be seen only when Active CP is at v6.4.0 or higher FOS version and a standby CP with FOS version lower than v6.4.0 is inserted		
Workaround:	manually invoke firmwaredownload to bring the standby CP in sync with the same FOS version as that on the active CP.		

Closed with code changes in Fabric OS 8.0.1

This section lists software defects with Critical, High, and Medium Technical Severity closed with a code change as of April 22, 2016 in version 8.0.1.

Defect ID: DEFECT000471762	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.2.0	Technology Area: Flow Vision
Symptom: Two bi-directional flows monitoring a common subset of traffic do not monitor the frame and byte parameters for one of the flows.	
Condition: Two bi-directional (- bidir option) flows on the same chip monitoring a common subset of traffic and with one of the device parameters (srcdev or dstdev) not specified.	

Defect ID: DEFECT000507871	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.3.0	Technology Area: RAS - Reliability, Availability, and Serviceability
Symptom: If framelog is disabled before HAFailover, then after HAFailover framelog will be enabled	
Condition: The defect will be hit only if the following sequence happens: 1. Install new firmware 2. Change framelog config using framelog --disable 3. HAFailover After HAFailover completes, framelog will show enabled and disabling or changing framelog configuration will not be effective	
Recovery: Recovery is to do a HAFailover again and restore framelog configuration to default (enabled)	

Defect ID: DEFECT000523247	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.3.0	Technology Area: Flow Vision
Symptom: Flow command functions inconsistently after creating multiple flows with Egress E_Ports	
Condition: The issue will happen under stress test where one creates more than ten flows with same sid/did pair.	
Recovery: configdownload the previous working configuration on the switch.	

Defect ID: DEFECT000524199	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.3.0	Technology Area: Flow Vision
Symptom: There are no Tx counts on ingress F_Port for frame size and there are no Rx frame counts on the Egress on the same flow being monitored on the E_Port, when Flows are configured on the same ASIC chip.	
Condition: If Rx/Tx frame size counts are zero on ingress/egress ports for flows created on same chip, i.e. ASIC chip duplicate flows.	

Defect ID: DEFECT000524532	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.2.1	Technology Area: Bottleneck Detection (legacy)
Symptom: Unwarranted Bottleneck Detection alerts may be encountered on a switch.	
Condition: This issue stems from a failing API leading to incorrect computations. When applying consistent latency into the switch, the AN-1003 messages for the specific F_Port show very low affected percentages with a slowdown value of 0.	

Defect ID: DEFECT000526904	
Technical Severity: Low	Probability: High
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.2.1	Technology Area: SNMP - Simple Network Management Protocol
Symptom: Desired severity of swEventTrap and swFabricWatchTrap are set to none after configdownload (SNMP config replication from one switch to another using BNA)	
Condition: happens when the swEventTrap and swFabricWatchTrap configuration in switch and configuration file are different, but their desired severity levels are same.	

Defect ID: DEFECT000532799	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.3.0	Technology Area: Management GUI
Symptom: WebTools fails to launch from browser if HTTPS and fully qualified domain name (FQDN) are used.	
Condition: FQDN names may not work after upgrading to FOS 7.2.x and above.	
Workaround: Use switch IP address instead of fully qualified domain name.	

Defect ID: DEFECT000533422	
Technical Severity: Low	Probability: Low
Product: Brocade Fabric OS	Technology: Traffic Management
Reported In Release: FOS7.2.1	Technology Area: Fibre Channel Routing
Symptom: Fabric router switch may observe panic upon receiving invalid frame from edge switch.	
Condition: This happens when fabric router running FOS7.2.x or earlier receives unknown Fibre Channel Common Transport (FC_CT) request from edge switch with zero sized payload. This does not apply to FOS v7.3.x or later.	
Recovery: Disable edge switch port and upgrade.	

Defect ID: DEFECT000537498	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.4.0	Technology Area: Management GUI
Symptom: Switch hardware view shows the blade status LED as black instead of amber, if the FC16-64 port blade is in faulty state.	
Condition: Switch hardware view shows the blade status LED as black when the FC16-64 port blade goes to faulty state.	

Defect ID: DEFECT000537571	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.2.0	Technology Area: Hardware Monitoring
Symptom: CRC errors with good EOF at 4G speed may be encountered when with some SFPs.	
Condition: This may be seen when using 4G LW SFP part number 57-1000027-02.	

Defect ID: DEFECT000541364	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.4.0	Technology Area: Configuration Fundamentals
Symptom: Customer may notice few links get stuck at "Hard_Flt" state and may notice "C3-1002" RAS events	
Condition: F port trunk disable/enable may cause this	
Recovery: Toggle the port. If problem persists, reboot the switch.	

Defect ID: DEFECT000544678	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.3.0	Technology Area: Configuration Fundamentals
Symptom: The warning message for supportInfoClear CLI command needs more clarity and explicitness to better assist the user of this command.	
Condition: This is a suggested enhancement to the warning message of supportInfoClear CLI command only.	

Defect ID: DEFECT000546719	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Traffic Management
Reported In Release: FOS7.4.0	Technology Area: Fibre Channel Routing
Symptom: Proxy creation failure may be observed along with RASLog message WARNING FCR-1021 00 0x0004 Local LSAN device entries exhausted while updating LSAN zone %s device entries.	
Condition: In a large Meta SAN, if 10,000 proxy devices already exist and there is an attempt to add more proxy devices, the proxy device creation will be failed.	
Recovery: Run fcrproxyconfig CLI command to determine the total number of proxy devices in the switch. If the total count shows 10,000 proxy devices, use " fcrproxyconfig -r " to remove some proxy devices.	

Defect ID: DEFECT000547722	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Other
Reported In Release: FOS7.1.2	Technology Area: Other
Symptom: Configuration keys corresponds to credit recovery feature may not be consistently reflected in configshow .	
Condition: This issue is seen when user changes credit recovery feature configuration.	
Recovery: Only display issue, the feature works as expected.	

Defect ID: DEFECT000547833	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.4.0	Technology Area: MAPS - Monitoring and Alerting Policy Suite
Symptom: Following the user invocation of the slotstatsclear CLI command, MAPS may report large latency percentages for IO_PERF_IMPACT.	
Condition: This may be seen only after the execution of the CLI command slotstatsclear . This stems from incorrect data values for the CRED_ZERO counter returned by the ASIC driver to MAPS.	
Workaround: No workaround.	
Recovery: The latency messages related to the IO_PERF_IMPACT should be ignored if there is big latency reported few minutes after slotstatsclear command is issued. The problem if it happens does with 2 minutes after the command.	

Defect ID: DEFECT000547835	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.4.0	Technology Area: MAPS - Monitoring and Alerting Policy Suite
Symptom: FOS does not generate MAPS-1010 RASLOG message if BNA fences the F_Port.	
Condition: It is applicable if the switch or fabric is monitored by BNA and port decommission is configured and enabled. If BNA is unable to decommission an F_Port it then fences the port as a fall back action and in this case MAPS-1010 RASLOG message is not generated. Note, port decommission action always fences associated port so, if BNA fails to decommission F_Port then it fences the port.	

Defect ID: DEFECT000548700	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.4.0	Technology Area: Flow Vision
Symptom: A learning flow created on an egress port shows frame size as "--" after multiple monitoring resets or the total frame size is sometimes off by 8 bytes.	
Condition: User has a learned monitoring flow created on the egress port.	
Recovery: Deactivate and reactivate the flow.	

Defect ID: DEFECT000550089	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.4.0	Technology Area: Flow Vision
Symptom: Predefined learn flow statistics does not increment in a Backbone-to-Edge setup after monitoring traffic for some time.	
Condition: Predefined monitor learn flow is active with continuous traffic.	
Recovery: Deactivate and reactivate the predefined learn flow.	

Defect ID: DEFECT000550520	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Distance
Reported In Release: FOS7.4.0	Technology Area: FCIP - Fibre Channel over IP
Symptom: Switchshow displays LAN port as online when no Ethernet cable is attached in 7840	
Condition: Switchshow is run on 7840 where once present Ethernet cable has been removed for a LAN port	
Recovery: Disable and enable the affected port	

Defect ID: DEFECT000550554	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Traffic Management
Reported In Release: FOS7.4.0	Technology Area: FICON
Symptom: With CUP Diagnostics and zOS HealthChecker, a port that reports a SlowDrain or Bottleneck Detected event, may persist in reporting this state, even though the condition has cleared.	
Condition: The CUP may persist in reporting this port performance problem, when actually, the problem has been cleared.	
Recovery: Vary the port offline and online or for E_Ports, disable and enable the port.	

Defect ID: DEFECT000550634	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.4.0	Technology Area: Software Installation & Upgrade
Symptom: <code>firmwarecleaninstall</code> with sftp option fails	
Condition: sftp protocol is not supported for this CLI however, the CLI usage help indicates that it is supported.	
Workaround: Use scp or ftp option to run <code>firmwarecleaninstall</code>	

Defect ID: DEFECT000550681	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Distance
Reported In Release: FOS7.4.0	Technology Area: FCIP - Fibre Channel over IP
Symptom: 7840 becomes non-operational (faulty).	
Condition: A 7840 becomes non-operational (faulty) as a result of another firmwaredownload being run while a previous non-disruptive firmwaredownload is in progress.	
Workaround: Do not initiate another firmwaredownload while a previous non-disruptive firmwaredownload is already in progress.	
Recovery: Reboot the 7840.	

Defect ID: DEFECT000553134	
Technical Severity: Low	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.4.0	Technology Area: CLI - Command Line Interface
Symptom: Diagnostic run may fail with RASLog "[BLZ-5040], 0, CHASSIS, ERROR, Brocade 7840, S0,P8(105) [OID 0x43028829]: Sending ipp port fault for reason 1".	
Condition: When running diagnostics on BR7840.	

Defect ID: DEFECT000553454	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Monitoring

Reported In Release: FOS7.2.1	Technology Area: MAPS - Monitoring and Alerting Policy Suite
Symptom: DCX/DCX-4S WWN status may show unknown status	
Condition: In rare occurrences where the i2cReset may fail to properly reset the WWN card	
Recovery: Re-seat the WWN card in question	

Defect ID: DEFECT000553786	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.2.0	Technology Area: Fibre Channel Services
Symptom: HA State Synchronization failed when switch detected there is duplicated WWN.	
Condition: HA Sync is stopped when the delete operation on AG duplicated device entry on standby fails.	
Recovery: Reboot standby CP to recover.	

Defect ID: DEFECT000554393	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Distance
Reported In Release: FOS7.4.0	Technology Area: FCIP - Fibre Channel over IP
Symptom: Data Processor (DP) panicked on FCIP tunnel modify or FCIP circuit bounce causing an interruption in traffic.	
Condition: The FCIP tunnel and/or circuit is bouncing and it has IPSec enabled on it.	
Workaround: Disable IPSec on the FCIP tunnel.	

Defect ID: DEFECT000555826	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.3.0_CNG	Technology Area: Management GUI
Symptom: Error will be shown for user description field while creating new user from switch admin.	
Condition: Error will be shown if user description text length is provided between 33 to 40 characters.	

Defect ID: DEFECT000556479	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Security
Reported In Release: FOS7.1.1	Technology Area: Zoning
Symptom: Zoned terminated and caused switch to panic.	
Condition: Zone contains alias name as member and zone is renamed such that both zone and member contains same name and user executes zone --validate <zone_name> .	

Defect ID: DEFECT000557644	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Traffic Management
Reported In Release: FOS7.4.0	Technology Area: FICON
Symptom: CUP fails to correctly establish new Reporting Logical Path after receiving Sel Reset	
Condition: It failed under following conditions during test: 1. FMS enabled. 2. Switch online to MVS 3. Health Checker running, with IOS_FABRIC_MONITOR. 4. FMS action is enabled in MAPS config 5. MAPS rules having the FMS action are triggered.	

Defect ID: DEFECT000558610	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.2.0	Technology Area: SNMP - Simple Network Management Protocol
Symptom: User does not see the swFCPortDisableReason as part of the SNMP trap.	
Condition: This issue is seen in all platforms, when the user receives swFCPortScn SNMP trap for port disable event.	

Defect ID: DEFECT000559352	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.2.0	Technology Area: SNMP - Simple Network Management Protocol
Symptom: Unlike the display for other SNMP test traps, swDeviceStatus test Trap displays only varbind "swTestString".	
Condition: This behavior is seen on all platforms for swDeviceStatus test trap.	

Defect ID: DEFECT000559929	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Other
Reported In Release: FOS7.3.0_CNG	Technology Area: Other
Symptom: Ports get segmented when switch with long distance ports is moved to Access Gateway mode.	
Condition: 1) Setup long distance (LD) ports on SW6558 and SAN switch using command "portcfglongdistance" 2) Make sure the LD ports came up as ISL E_Ports 3) Now change the switch mode from native to AG mode 4) Notice errors on the LD ports	
Workaround: Disable long distance mode on ports in native mode before converting switch to access gateway mode.	

Defect ID: DEFECT000560593	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.3.1	Technology Area: Fibre Channel Services
Symptom: The parameter "switch.login.perSwitchMax" is not shown in configshow output.	
Condition: By design, when a key is not defined (that is, not yet configured by the user), system will display the default value for it. But this key is different in that it does not have a fixed default value. The default value is computed dynamically as a function of the platform. As such this behavior anomaly is per design.	

Defect ID: DEFECT000560645	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.3.1	Technology Area: Configuration Fundamentals
Symptom: Management access (via assigned IP address of logical switch) is lost and changing IP addresses is not possible.	
Condition: This may happen when multiple logical switches have been created and assigned individual IP addresses for management purpose.	
Workaround: Create an extra logical switch, then make the appropriate IP address changes.	

Defect ID: DEFECT000560771	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.4.0	Technology Area: Configuration Fundamentals
Symptom: CLI fcippathtest failures are seen on FX8-24 blade when diagnostics are verified for a longer period.	
Condition: Stress testing may result in this issue on some of the boards. Should not occur under normal conditions.	

Defect ID: DEFECT000560880	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.3.1	Technology Area: MAPS - Monitoring and Alerting Policy Suite
Symptom: SNMP traps are received even when the action for the maps rule is "none".	
Condition: This behavior is seen in all platforms with MAPS enabled, when the action specified for maps rule is "NONE".	

Defect ID: DEFECT000561049	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Security
Reported In Release: FOS7.2.1	Technology Area: Security Vulnerability
Symptom: Configuration key corresponds to crypto key length may have invalid value 40 or 56.	
Condition: Crypto key length 40 and 56 are invalid and the same has been removed in v7.2.1. This issue is observed when switch is running firmware lower to v7.2.1, user sets the crypto key length to invalid value 40 or 56 and upgrades the switch to firmware version v7.2.1 or above.	
Workaround: Set the crypto key length to valid value 128 prior to upgrade to firmware version v7.2.1 or above.	

Defect ID: DEFECT000563497	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Distance
Reported In Release: FOS7.3.0	Technology Area: FCIP - Fibre Channel over IP
Symptom: Degraded FCIP Tunnel throughput, potentially causing I/O errors and or slow application response times.	
Condition: After many internal hardware errors have occurred the path between the FCIP FPGA and the FCIP data processing complexes.	

Defect ID: DEFECT000564261	
Technical Severity: Low	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.4.0	Technology Area: Configuration Fundamentals
Symptom: The board revision in switchshow changes from 77.3 to 77.0 following an upgrade of DCX-4S to v7.4.x	
Condition: This is a switchshow display issue with board revision only for DCX-4S in v7.4.x	

Defect ID: DEFECT000565123	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Distance
Reported In Release: FOS7.4.0	Technology Area: FCIP - Fibre Channel over IP
Symptom: Following RAS Logs would be observed, the values could be different. It could be DP0 or DP1. VE tunnel no. could be 24-33 on DP0 and 34-43 on DP1. [ESM-1010], 3475, FID 128, INFO, DS_7840_i2052142, DP0 is OFFLINE. [ESM-2105], 3476, FID 128, INFO, DS_7840_i2052142, VE tunnel 25 is DEGRADED. [RAS-1001], 3477, CHASSIS, INFO, Brocade7840, First failure data capture (FFDC) event occurred.	
Condition: Traffic running on a VE tunnel configured with compression level as aggr-deflate.	
Workaround: Change the VE tunnel compression level from aggr-deflate to deflate.	

Defect ID: DEFECT000565355	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.4.0	Technology Area: Flow Vision
Symptom: The vtap flow would not mirror the frames to the AMP when the AE ports between the switch and AMP is toggled.	
Condition: AE port toggle would result in the scenario.	

Defect ID: DEFECT000565623	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.3.1	Technology Area: Management GUI
Symptom: Entries in name server tab in Web Tool won't be removed on switchdisable .	
Condition: This issue is seen when user runs switchdisable/chassisdisable on a switch.	

Defect ID: DEFECT000566341	
Technical Severity: Low	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.3.1	Technology Area: SNMP - Simple Network Management Protocol
Symptom: When attempting to get the operational status of the VE tunnel port using SNMP, a value of 4 is returned (which indicates unknown) instead of the actual status.	
Condition: This behavior is specific to BR7840 switches.	

Defect ID: DEFECT000566666	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS8.0.1	Technology Area: Extended Fabrics
Symptom: Error log will report warnings, with code XTUN-1997, stating DP ftrace triggers. DP ftrace will show errors stating: "iapi0762 should have been tcpCbRxQueueHandler()". FCIP and/or IPEX tunnels may go into Degraded or Down state and will not recover. FCIP and/or IPEX I/O may fail and will not recover.	
Condition: Connecting the BR7840 to a network device transmitting multicast Ethernet 802.2 LLC frames, such as Spanning Tree Protocol BPDU (Bridge Protocol Data Units).	
Recovery: Reboot of the BR7840.	

Defect ID: DEFECT000566840	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.0	Technology Area: APM - Advanced Performance Monitoring
Symptom: Ports marked as slow drain device and quarantined are removed from slow drain quarantine list after a switch reboot	
Condition: When rebooting the switch, slow drained devices are removed the quarantine list	
Recovery: Devices in the slow drain device condition will automatically be added back to the quarantine list.	

Defect ID: DEFECT000567099	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.1	Technology Area: Fibre Channel Services
Symptom: Software VERIFYS with pattern "lgdb->port[port_dst] == NULL" may be seen during HA failover.	
Condition: This issue does not occur under normal HA conditions. This may happen under rare error conditions during HA recovery and it does not affect the regular functionality of the switch.	

Defect ID: DEFECT000567324	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS8.0.1	Technology Area: WAN Performance Analysis Tools
Symptom: The WAN Tool session reports higher than expected round trip times.	
Condition: This occurs when the WAN Tool session is configured with jumbo frames and has a committed rate equal to the physical interface speed.	
Workaround: Reconfigure the WAN Tool session's committed rate to be less than the physical interface speed.	

Defect ID: DEFECT000567513	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS7.3.1	Technology Area: FCIP - Fibre Channel over IP
Symptom: Tape backup job receives a "Position error" when trying to append data to a partially written tape volume.	
Condition: When Fast Write and Open Systems Tape Pipelining are enabled on a 7800/FX8-24 or 7840 Tunnel.	

Defect ID: DEFECT000567540	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.1	Technology Area: Configuration Fundamentals
Symptom: System may encounter RASLog ERCP-1000, RAS-1000 during firmwaredownload. For example: "[ERCP-1000], 7, FFDC CHASSIS, CRITICAL, Skybolt214, Multiple DDR ECC errors are detected and the system will reload automatically". followed by "[RAS-1001], 8, CHASSIS, INFO, Skybolt214, First failure data capture (FFDC) event occurred".	
Condition: This is seen only on Brocade 7840 switch following firmwaredownload.	

Defect ID: DEFECT000567733	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.4.0	Technology Area: MAPS - Monitoring and Alerting Policy Suite
Symptom: After an upgrade to Fabric OS v7.4.x, MAPS may stop working and HA Sync may be lose on a director switch.	
Condition: This is seen only after an upgrade to FOS version v7.4.x from FOS versions v7.3.x or lower under the following conditions: 1. Time base values in Fabric Watch are set to any value other than "none" for the FABRIC class. 2. And these Fabric Watch thresholds are converted to MAPS rules using " mapsconfig -fwconvert " command before the FOS upgrade occurs.	

Defect ID: DEFECT000567817	
Technical Severity: Critical	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.1.0	Technology Area: Configuration Fundamentals
Symptom: Firmware upgrade fails on a director with the standby CP remaining in a constant powering up state.	
Condition: This can occur when an Ethernet cable is plugged into the console port, instead of a serial console cable.	

Defect ID: DEFECT000568003	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Security
Reported In Release: FOS7.2.1	Technology Area: TACACS & TACACS+
Symptom: Software 'verify' error detected messages in RASLOG RAS-1004 and RAS-1012 - comp:weblinker.	
Condition: This is applicable for all the platforms and it happens every time when bulk number of user login requests are being processed very frequently by weblinker using TACACS authentication module.	
Workaround: Avoid bulk number of user authentications via TACACS simultaneously.	
Recovery: HAreboot	

Defect ID: DEFECT000568377	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.4.0	Technology Area: Software Installation & Upgrade
Symptom: Firmwaresync fails due to timeout when standby CP is running FOS 7.2 or older and active CP is running FOS 7.4.	
Condition: Occurs when active CP is running FOS 7.4 and standby CP is running FOS 7.2 or older, and when switch CPU is busy with SNMP, BNA polling.	
Workaround: Perform firmwaresync again after 10 minutes.	
Recovery: Times out after 10 minutes, then firmware sync should pass	

Defect ID: DEFECT000568423	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology: Distance
Reported In Release: FOS7.2.1	Technology Area: FCIP - Fibre Channel over IP
Symptom: Intermittent I/O Failures through an 7800/FX8024 or 7840 FCIP Tunnel due to processing an Extended Link Services PDISC (Discover N_Port Service Parameters) Request.	
Condition: When processing a received ELS-PDISC on a FCIP non-emulating Tunnel.	

Defect ID: DEFECT000568850	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Security
Reported In Release: FOS7.3.1	Technology Area: AD - Admin Domains
Symptom: Default users are unable to delete local users who have access to VF "0".	
Condition: This behavior is seen in all platforms in FOS version greater than FOS v6.x, when a default user try to delete a local user which was created in FOS v6.x with Vf "0".	

Defect ID: DEFECT000569237	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS7.4.0	Technology Area: FCIP - Fibre Channel over IP
Symptom: Second circuit not coming up (GE12) after configuring duplicate IP addresses and mis-cabled.	
Condition: The issue happens due to user mistake to configure the same WAN IP address on multiple ports. Due to the underline defect, 7840 stuck in the state that are not allowed new TCP connection to be established.	

Defect ID: DEFECT000569309	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.4.0	Technology Area: MAPS - Monitoring and Alerting Policy Suite
Symptom: MAPS mdd process terminates when running supportsave .	
Condition: This occurs from a race condition that sometimes may cause a NULL pointer access during MAPS data collection performed as part of supportsave .	

Defect ID: DEFECT000569665	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.3.1	Technology Area: Software Installation & Upgrade
Symptom: Termination of NPD detected on new Active CP during firmware upgrade. Firmwaredownload completes successfully but system fails to regain HA sync.	
Condition: This may be observed due to a very high CPU usage condition, during which time IPC messages may time out and lead to NPD termination by software watchdog.	
Recovery: schedule a maintenance window and reboot the active CP to regain HA sync.	

Defect ID: DEFECT000569674	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.3.0	Technology Area: Fibre Channel Services
Symptom: HA out of sync due to invalid zone configuration.	
Condition: This issue is observed when a user tries to add a zone member with more than 64 characters to a zone configuration and then does cfgsave or cfgenable in a chassis.	

Defect ID: DEFECT000570356	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS8.0.1	Technology Area: FCIP - Fibre Channel over IP
Symptom: FCIP DP FFDC after multiple DRAM2 memory pool warnings via XTUN-1008 messages	
Condition: After running WAN tool to test an FCIP Circuit, DP events caused complete depletion of the DRAM2 pool on a DP.	
Workaround: Insure that all WAN tool tests are deleted after running tests.	

Defect ID: DEFECT000570535	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology: Traffic Management
Reported In Release: FOS7.3.0	Technology Area: Rate Limiting and Shaping
Symptom: Though -ap option in aptpolicy command is removed from 7.3, user is still allowed to execute the command.	
Condition: This behavior is seen with all the platforms where aptpolicy command is supported.	

Defect ID: DEFECT000570606	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS7.4.0	Technology Area: FCIP - Fibre Channel over IP
Symptom: Small frames may be delayed up to one millisecond through the extension tunnel.	
Condition: On a 7840 during periods of low throughput on a compression enabled extension tunnel, small frames may be delayed up to 1ms.	

Defect ID: DEFECT000571927	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS8.0.1	Technology Area: FCIP - Fibre Channel over IP
Symptom: Disruptive reboot of the FCIP DPs on BR7840 during Hot Code Load (HCL).	
Condition: When HCL is attempted after one or more tunnel bounces, the FC Flush logic can examine an internal credit counter and assume that FC flush failed.	

Defect ID: DEFECT000572790	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.4.0	Technology Area: Inband Management
Symptom: VPD version 2.05 and EHCM-L3 Capability bits are not set for Brocade 6547 switch and consequently not shown in vpd_show command.	
Condition: This is seen only on Brocade 6547.	

Defect ID: DEFECT000572880	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.0	Technology Area: Management GUI
Symptom: During a firmware migration, Web Tools displays an incorrect information message about Peer Zoning treated as a regular zone displays	
Condition: Performing firmware download within the FOS v8.0.0 release using different build ids	

Defect ID: DEFECT000573081	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Traffic Management
Reported In Release: FOS8.0.0	Technology Area: Port Bring-up
Symptom: ITW and er_enc_out counters may increment in the thousands when port transitions from offline to online. This is expected behavior for the new GEN 6 ports. After port is online, these counters should behave just like GEN 5 ports. MAPS monitoring function will not be affected since MAPS starts monitoring these counters only after port comes online.	
Condition: This happens only when port is transitioning from offline to online. An example would be if a port is disabled and re-enabled or during switchdisable/switchenable operation.	

Defect ID: DEFECT000573629	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.4.1	Technology Area: Configuration Fundamentals
Symptom: IP configuration from Chassis Management Module (SVP) will fail the first time after power-cycle.	
Condition: Issue may be seen on embedded platforms.	
Recovery: Re-do the IP configuration from SVP. It will succeed after the first failure.	

Defect ID: DEFECT000573691	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.0	Technology Area: Software Installation & Upgrade
Symptom: The firmwarecommit started and completed messages will be shown during the firmwarecommit execution. But the firmware is not committed. The messages shown during the commit operation is misleading.	
Condition: The firmwarecommit copies an updated firmware image to the secondary partition. Executing firmwarecommit on already committed secondary partition leads to misleading commit messages.	
Workaround: The firmwarecommit command should be used only to update the new firmware to the secondary partition. Avoid using firmwarecommit on already committed firmware	

Defect ID: DEFECT000574013	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.3.1	Technology Area: Software Installation & Upgrade
Symptom: The command 'firmwarecommit -f' may need to be run manually on the standby CP to recover from a firmwaredownload failure after a firmwaredownload timeout.	
Condition: In a rare situation, following a dual CP firmwaredownload timeout, the expected recovery of the standby CP may fail due to ping failure triggered by race condition.	
Workaround: Manually invoke firmwarecommit on the standby CP where firmwaredownload timed out.	
Recovery: Manually invoke firmwarecommit on the standby CP where firmwaredownload timed out.	

Defect ID: DEFECT000574253	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.0.1	Technology Area: SNMP - Simple Network Management Protocol
Symptom: Inconsistent enc_out stats between portstatsshow and SNMP may be encountered.	
Condition: This may occur under rare circumstance where top 32 bits of internal error counter is incremented.	
Workaround: Portstatsshow readings are accurate. Ignore the discrepancy seen in SNMP.	

Defect ID: DEFECT000574717	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS6.4.3	Technology Area: Fibre Channel Services
Symptom: Software panic occurs due to Out of Memory condition.	
Condition: This could happen only when Admin Domain (AD) is activated and the device in the fabric send GAPNL query about another device (either remote or local) which is not part of same AD.	
Recovery: Perform proactive hareboot/hafailover when free memory is low.	

Defect ID: DEFECT000574862	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.2.1	Technology Area: RAS - Reliability, Availability, and Serviceability
Symptom: Raslog message severity is not synced between active and standby.	
Condition: This issue is seen when user changes the severity of RASLog message using rasadmin command.	

Defect ID: DEFECT000574865	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.0	Technology Area: Access Gateway
Symptom: Unable to delete the WWN Static Mapping in Access Gateway mode after issuing the ag – delwwnpgamapping command	
Condition: Observed when WWN Static Mappings are configured and user has deleted the port group where the WWN is mapped.	

Defect ID: DEFECT000574877	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.0	Technology Area: Software Installation & Upgrade
Symptom: Diagnostics command turboramtest will accept invalid values for passcnt argument	
Condition: Issue is seen only when turboramtest command is executed from command line	
Workaround: Provide valid input as argument for passcnt option when executing turboramtest command	

Defect ID: DEFECT000574943	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS7.2.1	Technology Area: FCIP - Fibre Channel over IP
Symptom: Host Discovery issues after FOS upgrade in an FCR backbone to edge configuration. Edge to edge configurations are not impacted.	
Condition: Problem can occur in a multiple VEX port configuration after FOS upgrade from pre-FOS 7.2.0 to newer FOS level. There needs to be more than 1 VEX port in the configuration.	

Defect ID: DEFECT000575101	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Traffic Management
Reported In Release: FOS8.0.0	Technology Area: FICON
Symptom: Encountered unexpected cold reboot of the system triggered by kernel panic.	
Condition: This is seen in FICON environment during device power on and off stress test.	

Defect ID: DEFECT000575740	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.3.1	Technology Area: SNMP - Simple Network Management Protocol
Symptom: The traps sent for Link up/Link down events of management fc interfaces that starts with fc0 contain incorrect ifindex as varbind.	
Condition: This happens on all the platforms and all the versions of FOS.	

Defect ID: DEFECT000576018	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.0	Technology Area: Hardware Monitoring
Symptom: Spinfab test reports failure on F_Ports connected to non-Brocade HBAs. Spinfab should not have been run on non-Brocade HBAs.	
Condition: Issue will be seen when spinfab is run on some F_Ports connected to non-Brocade HBAs	
Workaround: Do not run spinfab on F_Ports connected to non-Brocade HBAs	

Defect ID: DEFECT000576355	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.3.1	Technology Area: CLI - Command Line Interface
Symptom: After answer "n" to "reboot" CLI, switch is left in disabled state.	
Condition: It happens on BR5481, "reboot" CLI cannot be cancelled.	
Recovery: Use switchenable to enable switch ports back.	

Defect ID: DEFECT000576404	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology: Security
Reported In Release: FOS7.4.0	Technology Area: Security Policies
Symptom: passwddefault CLI command should be for use by root users only. It is currently permitted for admin user.	
Condition: This is encountered with passwddefault CLI command.	

Defect ID: DEFECT000576721	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.3.1	Technology Area: Fibre Channel Services
Symptom: Kernel panic with zoned termination after zoned exceeds max thread.	
Condition: It happens where scripting with CLI commands such as portzoneshow without much delay in between or excessive queries for admin domain list from external management application.	
Workaround: Reduce excessive polling for any zone command through external application or scripting. Adding proper delays between CLIs can also avoid this issue.	

Defect ID: DEFECT000576933	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Traffic Management
Reported In Release: FOS8.0.0	Technology Area: Port Bring-up
Symptom: Switch reset may occur when there is FICON traffic with two or more RNID aborts. The switch reset is rare and unlikely to occur	
Condition: FICON abort traffic was flowing.	

Defect ID: DEFECT000576960	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.4.0	Technology Area: Configuration Fundamentals
Symptom: The Restore Factory Defaults command may fail midway and certain features like zoning config may not be set to default values.	
Condition: This may be encountered when attempting to restore factory default configuration.	

Defect ID: DEFECT000577166	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology: Traffic Management
Reported In Release: FOS7.4.1	Technology Area: Port Bring-up
Symptom: F_Ports change into In_sync state or route error triggered on E_Port trunk causing frame drop during a firmware upgrade.	
Condition: This may be seen if media validation check failed on ports during HA. SFP media validation failure may be triggered by an insertion of a SFP while the port was disabled the switch had been upgraded to FOS v7.4.1, 7.4.1a or 7.4.1b from FOS v7.0.x or earlier through non-disruptive firmware upgrade path.	
Workaround: Run sfpshow -f before upgrading from FOS v7.0.x releases to FOS v7.4.1,7.4.1a, and 7.4.1b; or directly upgrade to FOS v7.4.1c with the fix.	
Recovery: For F_Port, bounce the port to recover. For trunk ports, disable ports in the trunk one at a time and then enable all ports.	

Defect ID: DEFECT000577183	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.3.0	Technology Area: Software Installation & Upgrade
Symptom: BR5432-24 fails firmware upgrade from FOS7.3.0c to FOS7.4.1 leading to a Kernel panic from - Oops: kernel bad area, sig: 11	
Condition: This issue is specific to BR5432-24 when upgrading from FOS7.3.0c to FOS7.4.1	

Defect ID: DEFECT000577245	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.4.0	Technology Area: Software Installation & Upgrade
Symptom: After firmware upgrade, the ip address of management interface may be not set up correctly.	
Condition: Enabled dhcp for management interface before firmware upgrade. The problem only happens on firmware upgrade to FOS v7.4.x.	
Recovery: Reboot switch after firmwaredownload.	

Defect ID: DEFECT000577604	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.0	Technology Area: Hardware Monitoring
Symptom: ITW and er_enc_out counters may increment in the thousands when port transitions from offline to online. This is expected behavior for the new Condor4 chip. After port is online, these counters should behave just like Condor3 ports. MAPS monitoring function will not be affected since MAPS starts monitoring these counters only after port comes online.	
Condition: This happens only when port is transitioning from offline to online. An example would be if a port is disabled and re-enabled or during switchdisable/switchenable operation.	

Defect ID: DEFECT000577646	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.0	Technology Area: Flow Vision
Symptom: Frames are monitored for an ingress flow with frametype specified and srcdev/dstdev not specified even though the frames ingressing at the specified port do not match the frametype.	
Condition: This issue happens only when ingress frames are monitored and the monitor flow has frametype specified with srcdev/dstdev not specified.	

Defect ID: DEFECT000577864	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.4.0_CBN	Technology Area: NPIV – N_Port ID Virtualization
Symptom: Multiple N_Port failovers on AG switch cause LUNs to disappear.	
Condition: It happens when F_Ports come online while there is no N_Port online in the Port Group/switch, AG disables the port due to no N_Ports, and later, when an N_Port comes on line, N_Port failback brings F_Ports back online. If F_Ports send ABTS at this time to abort the previous login, login entries are cleared from the switch DB.	

Defect ID: DEFECT000578229	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Traffic Management
Reported In Release: FOS7.4.0	Technology Area: QoS - Quality of Service
Symptom: Frame prioritization may not be effective in device applications even though CSCTL configuration is enabled for the switch and ports.	
Condition: This is a rare occurrence that may be encountered on a switch or chassis in a FICON environment.	

Defect ID: DEFECT000578360	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS7.4.1	Technology Area: FCIP - Fibre Channel over IP
Symptom: IPSec enabled extension tunnels on Brocade 7840 will not establish when utilizing VLAN tagged IP interfaces.	
Condition: This is encountered when the Brocade 7840 pair has an IPSec enabled extension tunnel utilizing a VLAN tagged IP interface.	
Workaround: Disable IPSec on the extension tunnel, or utilize an untagged IP interface.	

Defect ID: DEFECT000578576	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.0_GFT	Technology Area: Licensing
Symptom: Using webtools and network advisor to removed new DPOD feature on 6558 Embedded Switch, Webtools and network advisor fail to remove a DPOD license. Webtools sometimes closes itself or it refreshes and the DPOD license is still present.	
Condition: Issue was introduced with new support for capacity based POD licenses on platforms. Web tools error message is not correctly decoded when attempting to remove POD license.	
Workaround: Workaround is available - use the FOS CLI to remove the license instead, or remove the POD assignments before attempting to remove the POD license.	

Defect ID: DEFECT000578927	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS8.0.1	Technology Area: FCIP - Fibre Channel over IP
Symptom: BR7840 encountering [C3-1012], 5/3, CHASSIS, WARNING,, S0,P-1(8): Link Timeout on internal port with lost credits.	
Condition: When running FCIP traffic over the FCIP Tunnel - appears to be related to bursty nature of the I/O over the tunnel.	

Defect ID: DEFECT000579769	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Traffic Management
Reported In Release: FOS8.0.0	Technology Area: Port Bring-up
Symptom: Symptom: portcfgshow -i <index> does not show same references to FEC as portcfgshow <port> and portcfgfec --show. It is still showing: FEC: ON FEC: via TTS Instead of: 10G/16G FEC: ON 16G FEC via TTS: OFF	
Condition: When user issues "portcfgshow -i <index>"	

Defect ID: DEFECT000580006	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.0	Technology Area: Hardware Monitoring
Symptom: The following RASLog error might be seen whenever a Power Supply FRU is plugged out of the system. "EM-1028 00 0x000c HIL Error: failed to access history log for FRU" In addition, the FRU plugged-out and plugged-in entries might also be missing from historyshow output.	
Condition: Programming the systemairflow will introduce the issue. The CLI to program the systemairflow is a factory-only command and not available for general users.	
Workaround: Power on reset of the system will recover the issue.	

Defect ID: DEFECT000580096	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.4.0	Technology Area: Configuration Fundamentals
Symptom: 16G director has kernel panic while gather flow statistics.	
Condition: It happens after a hafailover on a 16G director with network patroller flow configured.	

Defect ID: DEFECT000580719	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Traffic Management
Reported In Release: FOS7.4.0_AMP	Technology Area: Fibre Channel Routing
Symptom: Adding AMP to fabric caused device to lose connectivity.	
Condition: After upgrade from FOS v7.3.x to v7.4.0x and FOSv7.4.1, with existing F/E_Port on an ASIC chip, enabling an AE_Port on the same chip may cause routing problems in the switch.	
Recovery: Reboot switch to recover.	

Defect ID: DEFECT000580863	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology: Traffic Management
Reported In Release: FOS7.3.1	Technology Area: ISL - Inter-Switch Linking
Symptom: After hafailover , hosts may lose paths to storage devices in the fabric.	
Condition: For this issue to occur, the following conditions must exist: 1. Hosts are connected to a logical switch that has enabled XISL. 2. Storage devices are reachable across a logical ISL -- i.e. the ISLs are in the base switch. 3. The trunk master of a base switch ISL trunk (with two or more trunked ports) bounces. 4. hafailover or hareboot occurs -- either manually or as part of non-disruptive firmwaredownload.	
Recovery: There are two possible recovery scenarios: 1. Bounce all trunk ports -- i.e. Bring all ports in the trunk offline and then bring them all back online. ...or... 2. hafailover.	

Defect ID: DEFECT000581598	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS7.4.0	Technology Area: FCIP - Fibre Channel over IP
Symptom: IOS000I - CHANNEL PROTOCOL ERROR on FICON emulated tape device displayed on device console.	
Condition: FCIP Tunnel with FICON Tape Pipelining enabled when a 3590 (or tape device) replies to a generated No-Op command with Command Retry Status.	
Workaround: Disable FICON Tape Pipelining on the tunnel or insure that there are more devices online between the LPAR and the controller than there are active tape jobs. If there is an idle tape device, the controller will present the attention on that device instead of an active device and will avoid the issue.	

Defect ID: DEFECT000581627	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.2.1	Technology Area: Hardware Monitoring
Symptom: Switch may encounter false alarms for failed blowers and high temperatures, leading to an attempt to initiate switch shutdown.	
Condition: This may occur if ports with No_Modules (vacant ports) are periodically polled using sfps show <port#> -f via external script or CLI. This external polling may clash with the periodic internal EM polls and result in misreadings from the blowers.	
Workaround: If possible avoid periodic external polling that uses CLI command sfps show <port #> -f . Otherwise insert good SFPs in vacant ports.	
Recovery: Insert good SFPs in vacant ports and/or stop any external SFP polling script (that uses sfps show <port#> -f) and then re-seat the failed blowers or reboot the switch.	

Defect ID: DEFECT000581775	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology: Traffic Management
Reported In Release: FOS7.4.0	Technology Area: FICON
Symptom: Identical Node descriptors observed for two different physical ports.	
Condition: This may occur in a FICON environment, where duplicates node descriptors may be generated in a director with large port-counts.	

Defect ID: DEFECT000582900	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.2.1_HIL	Technology Area: Access Gateway
Symptom: The user may encounter mismatch in AG Port Group configuration, where N_Ports remain part of a user defined Port Group instead of being associated with the default Port Group.	
Condition: This may occur when Load Balancing Policy is enabled for the Port Group and all N_Ports are part of the same user defined Port Group.	
Workaround: User can Manually delete N_Ports from the user defined Port Group using "ag --pgdel" CLI.	

Defect ID: DEFECT000584234	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.4.1	Technology Area: Analytics Monitoring
Symptom: Switch may report raslog MAPS-1003 alert, indicating greater than expected IOPs per second even though the IOP rate is below threshold.	
Condition: This condition may occur if the single ASIC is overloaded with traffic and AE port is on the same ASIC.	

Defect ID: DEFECT000584796	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS7.3.1	Technology Area: FCIP - Fibre Channel over IP
Symptom: Extension tunnels on the 7840 may go down and stay in an "in-progress" state.	
Condition: This condition can occur on an extension tunnel whose IP addresses receive an extremely large amount of ICMP messages other than Echo Request(type 8), Echo Reply(type 0), or Time Exceeded(type 11).	
Recovery: A reboot is necessary to clear this condition.	

Defect ID: DEFECT000585430	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.4.1	Technology Area: High Availability
Symptom: Switch may report HA not in sync, along with raslog FSS-1009 2016/01/22-10:05:25, [FSS-1009], , FFDC , ERROR, , FSS Error: fcsW3-swc: sync-failure: -6	
Condition: This may happen during device offline event on a busy system.	
Recovery: Reboot standby CP.	

Defect ID: DEFECT000585776	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS8.0.1	Technology Area: FCIP Tunnel Management
Symptom: ESM-1101 error message seen with 'Unable to allocate memory' condition. Can also sometimes result in a esmd panic.	
Condition: Issuing ' portcfgshow ipif iproute fcipunnel fcipcircuit ' or other extension related ' portcfgshow ' commands can cause the error.	

Defect ID: DEFECT000586412	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS8.0.1	Technology Area: Extended Fabrics
Symptom: DPs on BR7840 switch panic and recovery while disabling compression.	
Condition: After modifying the FCIP Tunnel to not have software compression enabled (when disabling "Deflate" or "Aggr-Deflate" on an active FCIP Tunnel).	

Defect ID: DEFECT000586788	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.3.1	Technology Area: RAS - Reliability, Availability, and Serviceability
Symptom: Switch may encounter "Software Fault"/"Kernel Panic" triggered by too many memory parity interrupts from the 16G ASIC encryption block.	
Condition: Memory parity errors are rare. This panic may occur on a 16G switch, if memory parity errors are encountered when ASIC encryption is not enabled.	
Recovery: Usually recovers after a panic. If it persists, please replace blade.	

Defect ID: DEFECT000588368	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Traffic Management
Reported In Release: FOS7.4.0	Technology Area: Port Bring-up
Symptom: Third party tape devices may have problems coming online.	
Condition: Port will experience error when connecting certain types of 3rd party tape devices with Brocade 16G platforms.	
Workaround: Use portcfnondfe CLI to enable optimal mode 3rd party tapes.	

Defect ID: DEFECT000588485	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Traffic Management
Reported In Release: FOS7.2.1	Technology Area: Port Bring-up
Symptom: Switch in AG mode reboots.	
Condition: This may occur when host is rebooted and switch did not discard the ABTS frame for the FLOGI while N_Port is undefined.	

Defect ID: DEFECT000588834	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS7.4.0	Technology Area: Extended Fabrics
Symptom: Continuous DP panics on BR7840 and loss of ip interface configurations.	
Condition: When there is Ethernet jumbo frames (non-IP) coming on the LAN/WAN ingress paths.	

Defect ID: DEFECT000589265	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS8.0.1	Technology Area: FCIP Tunnel Management
Symptom: DP panic during Hot Code Load (HCL) failover/failback with non-emulated FC traffic and HCL failures.	
Condition: Multiple LS with FCIP tunnels whose VE share the same VC and use different routing policies during FCIP HCL processing.	

Defect ID: DEFECT000589472	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Security
Reported In Release: FOS7.4.0	Technology Area: Security Policies
Symptom: CLI ipfilter disallows configuring a port value greater than 1024.	
Condition: This occurs when creating an ipfilter policy rule with port value greater than 1024. This is not permitted and results in an error message: "Invalid port number(range) for IP filter policy rule."	

Defect ID: DEFECT000590415	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.2.1	Technology Area: Access Gateway
Symptom: Discrepancy is seen between the outputs of CLI commands "ag --show" and "ag --mapshow" on AG switch.	
Condition: This may occur on AG switches in no policy mode. When the F_port comes online, the mapped N_Port is not updated as the current N_Port for the F_Ports.	

Defect ID: DEFECT000590745	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.1	Technology Area: Flow Vision
Symptom: Flow Vision daemon (npd) may crash on a switch during firmwaredownload.	
Condition: User may encounter this behavior only on an Analytics Monitoring Platform enabled fabric during a switch disable/enable or reboot or hfailover operations.	
Recovery: Deactivate sys_analytics_vtap flow and restart npd daemon.	

Defect ID: DEFECT000591136	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.3.1	Technology Area: High Availability
Symptom: Customer may encounter a CP panic during a rare PCI access errors	
Condition: This may be encountered as a result of a faulty blade that triggered CP to process a bad PCI read data.	
Recovery: Replace the faulty blade	

Defect ID: DEFECT000554759	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology Group: Traffic Management
Reported In Release: FOS7.4.0	Technology: FICON
Symptom: MQ-1005 RAS log events on the Standby CP indicating "ficu: queue full".	
Condition: Switch running in ficon mode with a large number of Logical Paths, and constant RMF related CCW activity.	
Workaround: Reducing the number of Logical Paths to 2 per CEC will minimize the probability of this issue.	

Defect ID: DEFECT000586993	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology Group: Security
Reported In Release: FOS8.0.1	Technology: User Accounts & Passwords
Symptom: Switch panic when distribute password in a farbic with a mixed FOS version and also the oldpassword parameter is not distributed to AG switch.	
Condition: Run "distribute -p PWD -d" command on a switch with a FOS versions earlier than v7.4.0 to a switch that has v7.4.0 and above, the newer version switch will panic while processing data received from FOS versions earlier than v7.4.0.	
Workaround: Run the command from switches with FOS v7.4.0 or later versions, or upgrade receiving switches to FOS v7.4.2a or FOS v8.0.1 or later which has the fix.	

Defect ID: DEFECT000592702	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS7.4.1	Technology Area: FCIP - Fibre Channel over IP
Symptom: Limited tunnel performance after completing Extension HCL – Tunnel(s) is/are in flow control.	
Condition: After completing a firmware download to a new FOS release with Extension HCL enabled.	
Workaround: Perform disruptive firmware download.	
Recovery: Disable and re-enable the VE ports/FCIP Tunnels.	

Closed without code changes in Fabric OS 8.0.1

This section lists software defects with Critical, High, and Medium Technical Severity closed without a code change as of April 22, 2016 in version 8.0.1.

Defect ID: DEFECT000495229	Technical Severity: High
Reason Code: Not Reproducible	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.2.1_HIL	Technology Area: Software Installation & Upgrade
Symptom: After a non-disruptive firmware download, portstatshow may display increased instances of fec_uncor_detected errors on front end port.	
Condition: This may be encountered only on embedded platforms.	

Defect ID: DEFECT000535836	Technical Severity: High
Reason Code: Not Reproducible	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.4.0	Technology Area: Configuration Fundamentals
Symptom: Link issues are observed on port blade when post tests are run after a reboot.	
Condition: Setup specific issue wherein the blade turns faulty 51 after reboot with diags enabled.	
Workaround: Currently, there is no workaround for this issue as both the port blade and core blade goes faulty 21 with diags disabled. This is being looked at by driver team now.	

Defect ID: DEFECT000540198	Technical Severity: High
Reason Code: Will Not Fix	Probability: High
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.1.2	Technology Area: Fabric Watch
Symptom: FW RAS message encountered, indicating switch status state change while LOS (Loss of signal) area of fop_Port class is paused. This is not the case when LF(Link failure) area of fop_Port class is paused,	
Condition: This is encountered when LOS area systemmonitor is configured as pause, and switch status policy is configured as based on port class.	

Defect ID: DEFECT000540971	Technical Severity: Low
Reason Code: Will Not Fix	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.2.1	Technology Area: MAPS - Monitoring and Alerting Policy Suite
Symptom: In extreme conditions MAPS generates false alert for port errors such as LR etc.	
Condition: This false alert could be generated during state change of port and this happen in extreme conditions.	

Defect ID: DEFECT000543441	Technical Severity: Medium
Reason Code: Feature/Function Not Supported	Probability: High
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.4.0	Technology Area: SNMP - Simple Network Management Protocol
Symptom: Customer would not be able to use SCP and SFTP Protocols for Firmwaredownload and Supportsave in SNMP Interface. The support is only provided for FTP.	
Condition: The error will be returned when SET operation is tried out using SCP/SFTP Protocols.	

Defect ID: DEFECT000547173	Technical Severity: Medium
Reason Code: Not Reproducible	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.4.0	Technology Area: RAS - Reliability, Availability, and Serviceability
Symptom: On chassis based systems, when syslog is configured, configured server details are not reflected on the standby CP.	
Condition: Applicable only on chassis based systems when syslog server is configured only on active CP.	
Workaround: Configure the syslog server details on both active and standby CPs.	
Recovery: Configure the server details after HA to ensure that the logs are updated.	

Defect ID: DEFECT000559178	Technical Severity: Medium
Reason Code: Feature/Function Not Supported	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.3.1	Technology Area: Fabric Watch
Symptom: Message corresponding to an unsupported feature shows as: Only "root" can turn ON certain zoning features.	
Condition: This is observed when user tries to change zoning operation parameters "Disable NodeName Zone Checking" through configure command.	

Defect ID: DEFECT000560401	Technical Severity: Medium
Reason Code: Not Reproducible	Probability: Low
Product: Brocade Fabric OS	Technology: Other
Reported In Release: FOS7.3.0_CNG	Technology Area: Other
Symptom: After moving switch to another slot (Movement Detection triggers) and switch reseal, first ipaddrset to set static IPv4 address takes up to 5 minutes to work.	
Condition: Static IP address configuration is required after the SW6558 is moved from one bay to another or one chassis to another.	

Defect ID: DEFECT000561694	Technical Severity: High
Reason Code: Already Fixed in Release	Probability: Medium
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.4.0	Technology Area: Flow Vision
Symptom: The active CP gets rebooted due to software panic and stack frame is displayed on the console.	
Condition: Poweroff of the port blade consisting AE_Ports.	

Defect ID: DEFECT000563299	Technical Severity: Medium
Reason Code: Feature/Function Not Supported	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.2.1	Technology Area: Fibre Channel Services
Symptom: Switch performs hareboot due to OOM condition.	
Condition: This issue occurs rarely when collecting supportsave from BNA.	

Defect ID: DEFECT000565946	Technical Severity: Medium
Reason Code: Not Reproducible	Probability: High
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.4.1	Technology Area: Management GUI
Symptom: The "Enable DPOD" feature option continues to be shown in Web Tools after POD license is installed on switches with POD capability.	
Condition: This is an issue encountered only in Web Tools on switches with POD capability.	

Defect ID: DEFECT000567618	Technical Severity: High
Reason Code: Will Not Fix	Probability: High
Product: Brocade Fabric OS	Technology: Traffic Management
Reported In Release: FOS8.0.0	Technology Area: Fibre Channel Routing
Symptom: User may encounter device discovery issue in a FCR Edge to Edge setup with TI zones.	
Condition: When an Edge fabric is connected to both local FCR switch and remote FCR switch, and the FCR TI zone is configured on the remote FCR switch EX_Port.	
Workaround: If an Edge fabric is connected to both local FCR switch and remote FCR switch, user can configure TI zone only on the local FCR switch EX_Port.	
Recovery: Disable the local FCR EX_Port that is connected to the Edge fabric and restart the discovery.	

Defect ID: DEFECT000567900	Technical Severity: Medium
Reason Code: Not Reproducible	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.0	Technology Area: Management GUI
Symptom: The Hash type for authentication does not display correctly when fcap auth util is set.	
Condition: When fcap authentication is set, the Web Tools user interface does not display to correct Hash type.	
Workaround: Use the FOS CLI command ' authutil --show ' to see the correct Hash type	

Defect ID: DEFECT000568564	Technical Severity: Medium
Reason Code: Not Reproducible	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.2.1	Technology Area: Access Gateway
Symptom: 3rd party devices connected to an Access Gateway see errors due to switch not responding to Name Server queries GID_PN or GPN_ID.	
Condition: The issue is seen when: -16G based Access Gateway. - Device connected to the Access Gateway initiates an NS query. - As the NS response returns through the Access Gateway, it sometimes gets stuck in an internal queue due to the queue not being promptly serviced.	

Defect ID: DEFECT000571336	Technical Severity: High
Reason Code: Will Not Fix	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.0	Technology Area: Virtual Fabrics
Symptom: Weblinker module termination error might be seen after deleting a logical switch.	
Condition: When there is a pending weblinker request and the logical switch is deleted	

Defect ID: DEFECT000571567	Technical Severity: High
Reason Code: Not Reproducible	Probability: Medium
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.0	Technology Area: MAPS - Monitoring and Alerting Policy Suite
Symptom: MAPS dashboard may show incorrect UTIL value in the current day or in the last column in the history data table.	
Condition: In rare conditions the MAPS dashboard may display incorrect UTIL value.	

Defect ID: DEFECT000572227	Technical Severity: High
Reason Code: Already Fixed in Release	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.2.1_HIL	Technology Area: Access Gateway
Symptom: When a host and target are connected to the same AG switch and mapped to same N_Port, host may not see target.	
Condition: Host may not see targets only when host and targets are connected to same AG and mapped to same N_Port.	

Defect ID: DEFECT000572616	Technical Severity: High
Reason Code: Not Reproducible	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.0	Technology Area: Software Installation & Upgrade
Symptom: Some CLI commands such as ipaddrshow , ssh , telnet etc. may depict slow execution times and impact the user's ability to enter a follow-up CLI command particularly if it follows a previous command and user doesn't wait for the CLI prompt.	
Condition: This may be encountered when IPv6 is enabled in the switch and in the presence of an IPv6 router in the network.	

Defect ID: DEFECT000574586	Technical Severity: High
Reason Code: Not Reproducible	Probability: High
Product: Brocade Fabric OS	Technology: Traffic Management
Reported In Release: FOS8.0.0	Technology Area: Port Bring-up
Symptom: In stress test, sometimes the port might be stuck in "in_sync" or "no_sync" state (this state can be observed in switchshow command). Should not occur under normal maintenance operation.	
Condition: As part of speed negotiation sequence, a 4G setting is done which is causing this issue.	
Workaround: This issue can be observed in stress test. So, for the ports with 10G SFP's (with and without DWDM), the stress test can be avoided.	
Recovery: If the port is stuck in "in_sync" or "no_sync" state, toggle the port using portdisable and portenable.	

Defect ID: DEFECT000577380	Technical Severity: High
Reason Code: Not Reproducible	Probability: Low
Product: Brocade Fabric OS	Technology: Traffic Management
Reported In Release: FOS8.0.0	Technology Area: Fibre Channel Routing
Symptom: User might see FCR routing issue which might cause frame drop, host or target can't be discovered.	
Condition: All the following conditions must be met to trigger this issue. 1. EX_Port are trunk ports 2. One of EX_Ports is bouncing very frequently. 3. Master port changes due to port bouncing. 4. The area of master port also changes. 5. The changes in condition 3 and condition 4 happen too quickly that FCR could not update the routing event in time resulting the route update is out of order.	

Defect ID: DEFECT000577628	Technical Severity: Medium
Reason Code: Not Reproducible	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.0	Technology Area: Software Installation & Upgrade
Symptom: Firmwaredownload command on the G620 with Ethernet management port at 10Mbps full duplex using sftp times out and fails.	
Condition: Firmwaredownload command tried with sftp protocol on the G620 fails when the Ethernet interface is configure with 10Mbps FD mode on the switch.	
Workaround: Firmwaredownload with sftp protocol should not be issued on the G620 when ethernet interface is configured with 10Mbps and FD	

Defect ID: DEFECT000579654	Technical Severity: Medium
Reason Code: Not Reproducible	Probability: Medium
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.0	Technology Area: MAPS - Monitoring and Alerting Policy Suite
Symptom: Dashboard shows port utilization value less than the actual value in history table.	
Condition: This is harmless and does not happen often	
Workaround: In this case user should use RX, TX values.	

Defect ID: DEFECT000581283	Technical Severity: Medium
Reason Code: Already Fixed in Release	Probability: Low
Product: Brocade Fabric OS	Technology: Traffic Management
Reported In Release: FOS7.3.1	Technology Area: FICON
Symptom: The switch may encounter a ficon cup daemon (ficud) panic after observing IDC Timeout messages.	
Condition: This is seen in FICON environment when response messages come in at the same time as an outgoing directory diagnostics message.	

Defect ID: DEFECT000582539	Technical Severity: High
Reason Code: Already Fixed in Release	Probability: Low
Product: Brocade Fabric OS	Technology: Traffic Management
Reported In Release: FOS7.3.1	Technology Area: Fibre Channel Routing
Symptom: After a link reset on an inter fabric link (IFL) or the trunk master of an IFL trunk on a Fibre Channel Router (FCR) switch, traffic through the IFL or IFL trunk is halted.	
Condition: An hareboot or hafailover on a 8G FCR switch, followed by a link reset on an IFL or an IFL trunk master, then traffic can no longer flow through the IFL. If a fabric only has devices with proxy IDs that have Domain ID of 3 or every fourth ID after that (Ex: 3, 7, 11, 15, etc.), then the fabric is not impacted. 16G FCR switches are not impacted.	
Recovery: portdisable/portenable IFL or the full IFL trunk.	

Defect ID: DEFECT000583695	Technical Severity: High
Reason Code: Will Not Fix	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.3.2	Technology Area: D_Port - Diagnostic Port
Symptom: If a blade or switch is disabled while the D_Port test is running, the switch/blade might move to disabled state permanently which requires a reboot of the blade/switch to recover.	
Condition: It could happen with all platforms	
Workaround: Avoid disabling blade/switch when D_Port test is running.	
Recovery: Reboot the blade/switch.	

Open Defects in Fabric OS 8.0.1

This section lists open software defects with Critical, High, and Medium Technical Severity as of April 22, 2016 in version 8.0.1.

Defect ID: DEFECT000463170	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.2.0	Technology Area: Configuration Fundamentals
Symptom: ipsecconfig command may hang the command line	
Condition: ipsecconfig --disable command may hang and not work properly. Subsequent disable/re-enables may fail.	

Defect ID: DEFECT000470634	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.2.0	Technology Area: Flow Vision
Symptom: A static and a learning flow cannot monitor the same traffic at two ports on the same chip.	
Condition: A static and a learning flow created on same chip where the traffic on the static flow is a subflow for the learning flow.	

Defect ID: DEFECT000498330	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.3.0	Technology Area: D_Port - Diagnostic Port
Symptom: Increase in er_unroutable and er_other_discard counts in port statistics on the local D_Port when the switch at the remote end of the link is rebooted or HA rebooted.	
Condition: When a link which has static D_Port configured between two switches and the switch at one end of the link is rebooted or HA fail over is done.	

Defect ID: DEFECT000509850	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.3.0	Technology Area: Management GUI
Symptom: Unable to view the current updated FCIP details after clicking Refresh Now Option.	
Condition: Changes to the FCIP tunnels in the 7840 platform are not updated in the WebTools views.	
Workaround: Navigate to another tab and return to see the updated values of FCIP Tunnel.	

Defect ID: DEFECT000512746	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.3.0	Technology Area: Flow Vision
Symptom: A WWN-based flow will not be deactivated automatically, when the WWN of the generator port is changed using the command fapwwn .	
Condition: WWN of the generator port is changed using the command fapwwn .	
Recovery: Deactivate and activate the flow manually.	

Defect ID: DEFECT000537487	
Technical Severity: Low	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.4.0	Technology Area: Management GUI
Symptom: When the IP address is provided for specific logical switch context, the default switch context will be launched.	
Condition: Launching WebTools for logical switch context which has IPFC and subnet mask address configured.	
Workaround: Launch WebTools for the default switch context and navigate to specific logical switch context.	

Defect ID: DEFECT000540101	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.2.1	Technology Area: MAPS - Monitoring and Alerting Policy Suite
Symptom: SNMP query reports a fan speed of 0.	
Condition: Erroneous fan speed report occurs only when switch hits transient I2C failure and it will be recovered automatically.	

Defect ID: DEFECT000548803	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Security
Reported In Release: FOS7.1.1	Technology Area: Zoning
Symptom: After an offline/online event of storage ports in a session based zone, hosts are no longer able to connect to the storage ports.	
Condition: This may be seen in largely over-subscribed storage ports	
Workaround: portdisable/portenable storage ports.	

Defect ID: DEFECT000549417	
Technical Severity: Low	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.4.0	Technology Area: Configuration Fundamentals
Symptom: If dynamic port name is configured on the switch, any change in port name will not be handled by MAPS dynamic group for which "feature" is specified as port name. After change in port name, the group membership may not reflect correct members.	
Condition: Using MAPS and dynamic port naming	

Defect ID: DEFECT000549628	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.3.1	Technology Area: Hardware Monitoring
Symptom: Panic may be seen if POST tests are interrupted by a supportsave operation.	
Condition: Issue happens when supportsave is triggered in the middle of POST tests or vice versa.	
Workaround: Supportsave to be executed at the end of post tests.	

Defect ID: DEFECT000549856	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Other
Reported In Release: FOS7.4.0	Technology Area: Other
Symptom: When a Quarantined port is moved out of the current Logical Switch, the port is listed as -1/-1 in the output of ' sddquarantine --show ' executed in the current Logical Switch.	
Condition: Moving a quarantined port in disabled state to a different Logical Switch in a chassis-based switch	
Workaround: Remove the port from quarantined state using sddquarantine --clear <slot/port> before moving the port to a different logical switch	

Defect ID: DEFECT000554685	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.3.1	Technology Area: RAS - Reliability, Availability, and Serviceability
Symptom: swSsn varbind is missed in the swEventTrap trap if swExtTrap is set to "No" .	
Condition: This behavior is seen on all platforms when the user sets swExtTrap to "No" .	

Defect ID: DEFECT000555276	
Technical Severity: Low	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.4.0	Technology Area: Fibre Channel Services
Symptom: CLI command " portcfgshow " options (-s/-i) for slot/index does not display the fillword field.	
Condition: CLI command " portcfgshow " does not display the fillword if input parameters are used. This is due to chip type conditions taken into consideration while options like -s/-i provided.	
Workaround: Use the CLI command " portcfgshow " without any input parameters.	

Defect ID: DEFECT000558941	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.4.0_AMP	Technology Area: Flow Vision
Symptom: Due to ISLs enabled by error or unintentional configuration between two unique fabrics, vTap flow may be mirrored to a wrong Analytics Monitoring Platform (AMP) or to a wrong AF_Port on AMP when the inadvertently merged fabric is connected to the same logical switch on the AMP.	
Condition: The customer may face this issue if the same logical switch on AMP is connected to two unique fabrics which inadvertently merged.	
Workaround: Avoid inadvertent fabric merge or if merge is intentional, deactivate vTap flow, configure the correct AF port, activate vTap flow.	
Recovery: Remove ISL causing the inadvertent merge, deactivate vTap flow, configure the correct AF port, and activate vTap flow.	

Defect ID: DEFECT000559528	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.3.1	Technology Area: MAPS - Monitoring and Alerting Policy Suite
Symptom: MAPS traps are not sent as part of snmpTraps -send (test traps) command.	
Condition: All FOS platforms with MAPS enabled are affected. FOS 7.4 and above there is no support for Fabric Watch or MAPS traps in snmptraps command.	

Defect ID: DEFECT000561914	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Security
Reported In Release: FOS7.3.0	Technology Area: User Accounts & Passwords
Symptom: The description of userconfig -d is specified in the man pages and documentation to be 40 characters, but is actually only 32 characters.	
Condition: This is specific to the CLI command userconfig -d	

Defect ID: DEFECT000563298	
Technical Severity: Low	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.4.0_AMP	Technology Area: Flow Vision
Symptom: The output of " flow --show sys_mon_analytics -srcdev <SID> -dstdev <DID> " CLI does not display the metrics table for the specified single flow between the pair of source and destination devices.	
Condition: The condition is observed when there is no traffic between the specified source and destination devices.	
Recovery: Re-issue " flow --show sys_mon_analytics -srcdev <SID> -dstdev <DID> " command after traffic restarts between source and destination	

Defect ID: DEFECT000563629	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS7.2.1	Technology Area: FCIP - Fibre Channel over IP
Symptom: One or more IPSec enabled FCIP circuits may continuously bounce or go down and not recover. The affected DP will report Authentication Tag Mismatch errors continually.	
Condition: When IPSec enabled on an FCIP tunnel between a pair of FX8-24 blades.	
Recovery: Reboot the affected FX8-24 blade.	

Defect ID: DEFECT000564187	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS6.4.2	Technology Area: RAS - Reliability, Availability, and Serviceability
Symptom: User can still configure FA-TRAP/ISCSI-TRAP on FOS v6.4.x, though FA-MIB/ISCSI-MIB was set to 'NO' prior to code upgrade via CLI snmpconfig -set.	
Condition: When upgrade from FOS v6.3.x to FOS v6.4.x with FA-MIB/ISCSI-MIB set to 'NO'	

Defect ID: DEFECT000564241	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.4.0_AMP	Technology Area: Flow Vision
Symptom: Fabric latency metrics for 10 sec / 5 min intervals are displayed in the brief metrics output even after the traffic is stopped.	
Condition: This is observed when a user has enabled vTap from host ports and target ports to monitor fabric latency.	
Recovery: Data will adjust when the traffic resumes.	

Defect ID: DEFECT000564334	
Technical Severity: Low	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.4.0	Technology Area: MAPS - Monitoring and Alerting Policy Suite
Symptom: MAPS indicates the switch state is marginal if only one power supply unit is present on Brocade 6505.	
Condition: This is only applicable to Brocade 6505 switch.	
Workaround: This erroneous message may be ignored.	

Defect ID: DEFECT000564909	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.3.1	Technology Area: CLI - Command Line Interface
Symptom: Switches upgraded to FOSv7.x firmware from FOSv6.4.x with long distance ISLs configured would see "Desired Buffers = 0" in portshow output instead of the configured distance.	
Condition: This issue will be seen on all the platforms upgraded from FOSv6.4.x with Long distance ISLs configured via CLI portshow. But the ISL itself is correct and functional	
Workaround: Use portbuffershow CLI for the correct distance/buffer as configured.	

Defect ID: DEFECT000566393	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.0	Technology Area: Flow Vision
Symptom: Unable to configure a SIM port when QOS is enabled.	
Condition: When a port has QOS enabled, the SIM port enablement will fail	
Workaround: Disable QOS on the port, then enable SIM port, followed by re-enable QOS.	

Defect ID: DEFECT000566919	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.0	Technology Area: RAS - Reliability, Availability, and Serviceability
Symptom: The audit log message "SULB-1001" will not be shown after firmware upgraded to new version.	
Condition: Configure and enable audit filter for firmware class. Then Upgrade firmware from one version to another. After the firmware download is complete, the audit log SULB-1001 message will not be shown.	
Workaround: Use errdump to see the "SULB-1001" message as a RAS log message.	

Defect ID: DEFECT000567870	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.0	Technology Area: Management GUI
Symptom: "IP filter operation is not allowed in this switch instance" error message when configuring an IP filter	
Condition: When an IP Filter configuration is performed on logical switch context	

Defect ID: DEFECT000569827	
Technical Severity: Low	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.0	Technology Area: Fibre Channel Services
Symptom: Port beaconing stops after spinfab is ran.	
Condition: When port beaconing is enabled on a port, LED blink pattern stops after spinfab is ran.	
Recovery: Disable and then re-enable port beaconing on the port.	

Defect ID: DEFECT000569927	
Technical Severity: Low	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.0	Technology Area: Management GUI
Symptom: The speed display in the WebTools Switch Throughput Graph is not display the X-axis correctly for the G620 switch.	
Condition: The X-axis display problem occurs for all GEN6 platforms	
Workaround: Maximize the Web Tools Switch Throughput Graph for proper display	

Defect ID: DEFECT000570383	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Traffic Management
Reported In Release: FOS7.3.1	Technology Area: FICON
Symptom: Soon after a CFG-POR (mainframe reboot) operation, channels in a Logical Switch lost connectivity with Control Units in its neighbor Logical Switch. At the point of lost connectivity, all Logical Fabrics lost connectivity through the Base Fabric to their common-zoned targets in the remote Logical Fabric.	
Condition: A two chassis topology having three Logical Partitions in each chassis and there a Base Fabric with ISL links.	
Workaround: Hfailover to prevent the issue.	
Recovery: Set the non-base logical switches offline and then online.	

Defect ID: DEFECT000570541	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.0	Technology Area: Management GUI
Symptom: Web Tools Switch Throughput Graph closes after error message "null Switch throughput graph will be closed" displays.	
Condition: The WebTools Switch Throughput Graph closes if kept open for more than 2 days	
Workaround: Close and re-open the Web Tools Switch Throughput Graph every 2 days.	

Defect ID: DEFECT000570830	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.4.0_AMP	Technology Area: MAPS - Monitoring and Alerting Policy Suite
Symptom: State Changes notifications on trunked AE port are not generated.	
Condition: AMP needs to be connected to fabric switch via a multi_Port trunk.	

Defect ID: DEFECT000570976	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.0	Technology Area: SNMP - Simple Network Management Protocol
Symptom: In some cases the SNMP data does not display in a tabular format.	
Condition: The SNMP packets are not properly processed to support data display in tabular format.	

Defect ID: DEFECT000572497	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Traffic Management
Reported In Release: FOS7.3.0	Technology Area: Port Bring-up
Symptom: Switch cold boot due to "Software Fault:ASSERT"	
Condition: The following conditions may cause this timing issue: - multiple switch ports bouncing repeatedly over the course of several minutes. - port bounces are initiated by the devices rebooting which causes the offline and online to occur very close together.	

Defect ID: DEFECT000573218	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.0	Technology Area: D_Port - Diagnostic Port
Symptom: At the end of D_Port test, user may observe the message "no matched registered entry" on the console.	
Condition: When user is running D_Port test on multiple ports between a switch and a QLogic HBA.	

Defect ID: DEFECT000573229	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Traffic Management
Reported In Release: FOS7.2.1	Technology Area: TIZ - Traffic Isolation Zoning
Symptom: Invalid TI zones constraints may affect traffic on other ports.	
Condition: This occurred when user created invalid TI zone configuration which did not include all member of the trunk group in the TI zone.	
Recovery: Delete the invalid TI Zone and toggle effected ports	

Defect ID: DEFECT000574429	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.4.0_AMP	Technology Area: Flow Vision
Symptom: When total flow count reaches the maximum but IT and ITL counts are less than their respective maximum limits and there are idle flows, flow aging may not happen.	
Condition: Aging is done based on IT and ITL usage counts. It can so happen both IT and ITL counts are well under the limits but total flow count in the system can exceed the aging threshold. In this case, aging will not happen and no new IT and ITL can get created.	
Recovery: Use a flow reset to clear the flows and restart the monitoring.	

Defect ID: DEFECT000575105	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.0	Technology Area: MAPS - Monitoring and Alerting Policy Suite
Symptom: Switch could go out of memory if user creates thousands of MAPS rules.	
Condition: This is rare condition and should not happen in normal situation.	

Defect ID: DEFECT000576048	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.3.1	Technology Area: CLI - Command Line Interface
Symptom: Switch panic after an invalid input parameter to a CLI.	
Condition: User inputed invalid blade port number to " creditrecovmode --check " CLI.	
Workaround: Avoid to use invalid input.	

Defect ID: DEFECT000576361	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Security
Reported In Release: FOS7.2.1	Technology Area: ACLs - Access Control Lists
Symptom: FCS- and SCC Policy's in fabric disappears when changes made to DCC policy	
Condition: This behavior is seen in all platforms when setting the fabric data distribution configuration to SCC,DCC, and FCS	

Defect ID: DEFECT000576382	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.0	Technology Area: Management GUI
Symptom: User is not able to disable QoS configuration of ports when multiple Auto Enabled QoS Ports are selected in Webtools	
Condition: When multiple Auto Enabled QoS Ports are selected	
Workaround: Disable one port at a time	

Defect ID: DEFECT000577686	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Security
Reported In Release: FOS7.0.2	Technology Area: Encryption
Symptom: Certain 3rd party HBA hosts connected to a regular FC switch, talking to Virtual Targets connected to BES FC switch can see a traffic issue.	
Condition: This issue could occur only with a specific 3rd party HBA that does not handle all the RSCNs sent by FC switch properly.	
Workaround: Connect host directly to BES switch.	

Defect ID: DEFECT000577772	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.1	Technology Area: Flow Vision
Symptom: History data for the F_Port trunk master does not display in the Fabric Flow Dashboard.	
Condition: When the F_Port index is different than trunk mater user port number, information will be displayed based on user port number which is equal to trunk port index. In this case slave port information may display instead of trunk master.	

Defect ID: DEFECT000577989	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.0	Technology Area: SNMP - Simple Network Management Protocol
Symptom: SNMP "entPhysicalClass" objects does not display correct values for one of the PhysicalClass named as "other" and its associate "entPhysicalSerialNum"	
Condition: When doing SNMP walk on "entPhysicalClass" objects	

Defect ID: DEFECT000578031	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.0	Technology Area: D_Port - Diagnostic Port
Symptom: The user may observe a difference in estimated buffers required between the output of command " portDportTest --show " and " portBufferShow ".	
Condition: With a long distance link connected through a DWDM box, the user may observe a difference in required buffers between the output of command " portDportTest --show " and " portBufferShow ".	

Defect ID: DEFECT000581120	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.1	Technology Area: Configuration Fundamentals
Symptom: Zoned ports might change zone enforcement to Session Based HARD Zoning [ZONE-1004] or [Zone-1004]	
Condition: During the handling of zone enforcement change	

Defect ID: DEFECT000581219	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.1	Technology Area: SNMP - Simple Network Management Protocol
Symptom: SNMP get/getnext walk fails.	
Condition: When the SNMP access control list is configured with an invalid IP address	
Workaround: Remove the invalid IPaddress entry in the SNMP access control list.	
Recovery: Remove the invalid IPaddress entry in the SNMP access control list.	

Defect ID: DEFECT000581753	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.3.1	Technology Area: MAPS - Monitoring and Alerting Policy Suite
Symptom: The following error message occurs when the customer tries to create MAPS rules. "The feature is not supported on standby CP"	
Condition: This issue happens when the firmware version in the standby CP is less than the Active CP (FOSv7.3)	
Workaround: hafailover.	

Defect ID: DEFECT000582386	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS8.0.1	Technology Area: Extended Fabrics
Symptom: The GE ports of the SX6 extension blade displays the port state as "No_Light" rather than "Mod_Inv" when a 32G SFP+ is inserted	
Condition: When a 32G SFP+ is inserted into the GE port of a SX6 extension blade.	

Defect ID: DEFECT000583693	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS8.0.1	Technology Area: FCIP - Fibre Channel over IP
Symptom: FCIP circuit spillover feature may not meet expectations	
Condition: When the tunnel's bandwidth is not fully saturated or utilized. As in the case a tunnel's throughput is below the configured bandwidth and the bandwidth is modified, the actual throughput may move in the opposite direction from the bandwidth value modified. The bandwidth of a tunnel can change based on the circuit's bandwidth changing, tunnel's load-level algorithm changing, and/or the metric of a circuit changing.	
Workaround: There is no predictable configuration since the host application's configured block sizes and outstanding I/Os can vary.	

Defect ID: DEFECT000585585	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.1	Technology Area: D_Port - Diagnostic Port
Symptom: Spinfab test may fail to run successfully on ports configured as D_Ports when attached to a Qlogic HBA. Functionality of the switch is not affected.	
Condition: Spinfab failure maybe observed when running on a port configured as D_Port attached to a Qlogic HBA with "-F_Ports 1" option	

Defect ID: DEFECT000585875	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.1	Technology Area: Flow Vision
Symptom: System-defined flow does not collect flow monitor stats for F_Port trunks.	
Condition: When a system defined flow "sys_mon_all_F_Port" is activated on a switch which has F_Port trunk. After a few portdisable/portenable of the slave ports, it has been observed that stats are not displayed for master F_Port.	

Defect ID: DEFECT000586502	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.1	Technology Area: Configuration Fundamentals
Symptom: The customer may see timeout messages from support save due to disruptive operation like pulling blades out.	
Condition: It is not recommended to pull blades during a support save.	

Defect ID: DEFECT000586624	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.1	Technology Area: Hardware Monitoring
Symptom: "State Transitions" in the sfpshow output may not match the "State Transitions" in the portshow output, which may exceed the physical state transition when SFP is inserted and removed multiple times.	
Condition: A specific F_Port is pulled and inserted multiple times resulting in various software state transitions for both media state as well as software port state.	

Defect ID: DEFECT000587033	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.1	Technology Area: Configuration Fundamentals
Symptom: A switch panic may be seen when spinfab is disrupted while in progress.	
Condition: Although not recommended, the panic is seen when all ports or the switch are manually disabled while D_Port or spinfab is running, which is an online test.	

Defect ID: DEFECT000587533	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.1	Technology Area: D_Port - Diagnostic Port
Symptom: When the D_Port test is run on a range of ports containing more than 30 ports, the D_Port test may occasionally fail on one port.	
Condition: The issue occurs only when the D_Port test is run simultaneously on more than the recommended number (8) of ports.	
Workaround: Rerun the D_Port test on the failed ports.	

Defect ID: DEFECT000588840	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.1	Technology Area: D_Port - Diagnostic Port
Symptom: D_Port fails when DWDM is applied to it	
Condition: When DWDM is enabled on a port configured as D_Port.	
Workaround: Disable the D_Port configuration using " portcfgdport --disable <port #> " and then execute the command " portcfgdport --enable -dwdm <port #> "	

Defect ID: DEFECT000589666	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS8.0.1	Technology Area: FCIP - Fibre Channel over IP
Symptom: Loss of device connectivity during non-disruptive firmware migration on Brocade 7840	
Condition: Occasional during a non-disruptive firmware migration on an extension platform, when DP upgrade is happening, frames are dropped when the routes change to support DP fail over and DP fallback process	

Defect ID: DEFECT000590383	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Security
Reported In Release: FOS7.3.1	Technology Area: Fabric Authentication
Symptom: Certain devices are denied access to login to the switch when they have a DCC policy configured with proper WWNs.	
Condition: This may occur when either of the WWN words have the most significant bit set. For example WWNs like c0:xx:xx:xx:xx:xx:xx:xx or xx:xx:xx:xx:c0:xx:xx:xx might see this problem when DCC is configured.	

Defect ID: DEFECT000590472	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.1	Technology Area: Flow Vision
Symptom: Sort by option for flow --show in sys_mon_all_F_Ports does not take the sid column into consideration.	
Condition: When “ flow --show sys_mon_all_F_Ports -sortby column2 ” CLI is executed, it takes the DID column to sort the output instead of the SID column.	

Defect ID: DEFECT000590653	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Traffic Management
Reported In Release: FOS8.0.1	Technology Area: QoS - Quality of Service
Symptom: After enabling QoS in a fabric, frame timeout may be observed under heavy congestion condition.	
Condition: While implementing QoS in an existing fabric, IO was stopped, QoS High was enabled and IO was started again. When the IO started running, latency was reported and C3 discards were observed.	
Workaround: Remove the slow-drain devices in the fabric.	
Recovery: Disabled the QoS zones and reverted back to standard zoning.	

Defect ID: DEFECT000590780	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS8.0.1	Technology Area: FCIP - Fibre Channel over IP
Symptom: During a reboot operation, there are rare instances of internal blade port bring up failures resulting in the switch becoming faulty.	
Condition: During a reboot operation, in rare instances the switch becomes faulty.	

Defect ID: DEFECT000590890	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.1	Technology Area: MAPS - Monitoring and Alerting Policy Suite
Symptom: Maps CIR_UTIL violation may display large % value in configurations having 8 logical switches.	
Condition: Extension Service Module may run out of resources when an IPEX tunnel in the base switch is shared by multiple logical switches	

Defect ID: DEFECT000590931	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.1	Technology Area: Software Installation & Upgrade
Symptom: System checks during firmware install can add several minutes delay when downgrading a GEN5 platform to FOS v7.3.x or v7.4.x from FOS v8.0.1.	
Condition: On Gen5 platforms during firmware downgrade to FOS v7.3.x or v7.4.x from FOS v8.0.1.	

Defect ID: DEFECT000591695	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.1	Technology Area: Hardware Monitoring
Symptom: Portstatsshows counters er_single_credit_loss and er_multi_credit_loss do not increment for credit loss on an IFL connections	
Condition: The error credit count in portStatsShow do not increment when the ASIC detects the following errors: 1. Software based link time out logic (RASLOG Cx-1012 BE port) 2. ASIC based credit leak (RASLOG Cx-1011) Only RASLOG is triggered to notify these errors.	

Defect ID: DEFECT000591754	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.4.0	Technology Area: Configuration Fundamentals
Symptom: Attempts to change IP address on embedded switch fails intermittently.	
Condition: This may be seen with Brocade M5424 switch, when an IP address change is performed through CMC management module.	
Workaround: Log into serial console and use "ipaddrset" to change the IP address.	

Defect ID: DEFECT000591792	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.1	Technology Area: Configuration Fundamentals
Symptom: Executing the ethif CLI command displays error message "Error: ifModeSet - Permission denied"	
Condition: The ifModeset CLI is deprecated. There is no loss of functionality.	

Defect ID: DEFECT000591922	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS8.0.1	Technology Area: FCIP - Fibre Channel over IP
Symptom: Unable to modify an enabled TCL when max TCLs are active.	
Condition: Maximum number of TCLs configured and enabled on the system.	
Workaround: Use portcfg tcl <name> modify --admin-status disable to disable the TCL first and then can modify the required parameter and re-enable the TCL.	

Defect ID: DEFECT000592012	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology: Layer 3 Routing/Network Layer
Reported In Release: FOS8.0.1	Technology Area: IP Addressing
Symptom: Unable to telnet to switch when IP over FC is configured.	
Condition: When the switch's management port is configured with a static IP address having the same subnet mask of IP over FC address.	
Workaround: Reconfigure the IP over FC address after the management IP is configured.	

Defect ID: DEFECT000592079	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.2.0	Technology Area: High Availability
Symptom: HA synchronization issues may be encountered, or portnames may be lost in switch configuration database on both primary and secondary partitions following an hafailover.	
Condition: This may be encountered if a carriage return is inserted into a portname. The configuration database is not properly synced in such situations.	
Workaround: Reconfigure all ports (that have a carriage return in the portname) to remove the carriage returns from the portnames.	
Recovery: Reconfigure missing portnames, taking proper caution not to insert any carriage return in the portnames.	

Defect ID: DEFECT000592535	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.1	Technology Area: Configuration Fundamentals
Symptom: Missing blocking message when performing a configdownload of a file from a different platform type.	
Condition: When issuing a configdownload using a file from platform of different type.	
Workaround: Only perform a configdownload using files from the same platform type	

Defect ID: DEFECT000592537	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.1	Technology Area: Fibre Channel Services
Symptom: Termination of Weblinker process when the standby Brocade CPX blade is removed.	
Condition: Although not recommended, when removing the standby Brocade CPX blade and the Weblinker polling is running.	
Recovery: The Weblinker is a restartable process.	

Defect ID: DEFECT000592567	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.1	Technology Area: MAPS - Monitoring and Alerting Policy Suite
Symptom: Some of the slow drain ports may not be enforced with a quarantine action. This can be verified from sddquarantine ---show CLI.	
Condition: When the device takes unusually long duration to come online and the switch port is already quarantined.	

Defect ID: DEFECT000592609	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.1	Technology Area: CLI - Command Line Interface
Symptom: When using the CLI command " portcfg lag LAG1 --delete -f " the user may see the warning message: WARNING: While making configuration changes the modified LAN GE ports will be disabled. Please run "portenable" command to manually enable the modified LAN GE ports after completing all the configuration changes. Operation timed out.	
Condition: When deleting Lags	
Workaround: This is cosmetic error with a timeout and there should not be any functionality loss.	

Defect ID: DEFECT000592802	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.1	Technology Area: D_Port - Diagnostic Port
Symptom: porttest command fails on ports in a logical switch or base switch that are configured as D_Port.	
Condition: porttest command failure is seen when executed on ports in a logical switch or base switch that are configured as D_Port.	
Workaround: Use D_Port for running link diagnostics	

Defect ID: DEFECT000593194	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.1	Technology Area: Software Installation & Upgrade
Symptom: During a disruptive firmwaredownload, the RASlogs do not show the firmware download for the SX6 extension blade.	
Condition: During a disruptive firmware download on the SX6 extension blade	
Workaround: There is no loss of functionality.	

Defect ID: DEFECT000593302	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS8.0.1	Technology Area: Extended Fabrics
Symptom: Small data transfers fail on TCP connections running through IP Extension.	
Condition: A very short lived TCP connection that sends a small amount of data immediately after it is established and is followed by an immediate close, may close without transferring any data. The TCP connection must be terminated through IP Extension.	

Defect ID: DEFECT000593461	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.1	Technology Area: Fibre Channel Services
Symptom: CLI "agshow" may not display all F_Ports.	
Condition: After a disruptive operation, CLI "agshow" may not display all F_Ports	
Workaround: F_Port information can be found in output of CLI 'switchshow' display on the attached switch and in Access Gateway.	

Defect ID: DEFECT000593472	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Security
Reported In Release: FOS8.0.1	Technology Area: HTTP/HTTPS
Symptom: The security certificate DAYS_TO_EXPIRE rule violation will not be highlighted in Summary Report's Todays section instead, it will be highlighted in Last 7 days section even when the rule was violated today.	
Condition: The issue is observed due to dashboard backup is after the rule violation.	
Workaround: For security certificate DAYS_TO_EXPIRE rule violation, please refer RASLOG message.	

Defect ID: DEFECT000593734	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.1	Technology Area: D_Port - Diagnostic Port
Symptom: While running DPORT tests on a port connected to QLogic 16G HBA, observed test fail with reason "Device does not support DPORT functionality"	
Condition: Continuously configuring the port as DPORT and toggling to run the DPORT tests can occasionally cause this.	
Recovery: Re-running the test will make it pass.	

Defect ID: DEFECT000593757	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.1	Technology Area: Software Installation & Upgrade
Symptom: F_Ports will remain disabled in AG and user need to manually enable the ports to bring up the F_Ports.	
Condition: switchdisable/enable without any delay on Wedge platform alone will make the F_Ports stay in the disabled state	
Workaround: Toggling the port will recover it.	

Defect ID: DEFECT000594002	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS8.0.1	Technology Area: FCIP - Fibre Channel over IP
Symptom: Operational status displays as 'degraded' when using the --qos or --ha flag with the 'portshow fciptunnel' command when SLA is running. Should show as 'Testing' instead.	
Condition: When SLA test is running on a circuit and the "portshow fciptunnel" command is issued with either the --qos or --ha option specified (but not both).	

Defect ID: DEFECT000594100	
Technical Severity: High	Probability: High
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.1	Technology Area: CLI - Command Line Interface
Symptom: Unable to clear ASIC stats.	
Condition: When issuing CLI command "statsclear" on GEN6 platforms.	

Defect ID: DEFECT000595186	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS7.4.1	Technology Area: Flow Vision
Symptom: With MAPS logical group as ingress port for vTap flow, portdisable/enable of a F_Port belonging to a MAPS group may result in halting of vTap-mirroring .	
Condition: 1. Maps logical group as ingress port for vTAP flow. 2. Repetitive portdisable/enable of F_Ports belonging to MAPS group.	
Workaround: hailure.	
Recovery: hailure.	

Defect ID: DEFECT000595368	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.4.0	Technology Area: Management GUI
Symptom: In zone configuration tab, two zone nodes will be displayed instead of one zone node	
Condition: This may be encountered when launching zone admin in FOS 7.4 version and later	

Defect ID: DEFECT000595452	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS8.0.1	Technology Area: FCIP - Fibre Channel over IP
Symptom: FICON interface timeout detected messages/IOS005I messages during FCIP HCL	
Condition: Problem occurs after retryable HCL Feature Disable errors occur, with active FICON traffic on an FCIP tunnel that has FICON emulation features enabled.	

Defect ID: DEFECT000595474	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.1	Technology Area: Software Installation & Upgrade
Symptom: The power usage of CPX6 blade, displayed in chassisshow output, might be higher than what the actual power usage is.	
Condition: FOS erroneously calculates the power usage of the CPX6 blades.	

Defect ID: DEFECT000595586	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.1	Technology Area: Management GUI
Symptom: Memory, equal to the size of the hash configured, lost during each authentication. Over a long period of time, system may become unstable and report memory leak issue.	
Condition: On switches having WebTools and BNA management sessions.	

Defect ID: DEFECT000595599	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Traffic Management
Reported In Release: FOS8.0.1	Technology Area: Fibre Channel Routing
Symptom: When the port that is online at 32G goes offline because of link failure and comes back online, the port can form a separate trunk because of the FEC state mismatch with master port. This problem applies for 32G trunking ports.	
Condition: This problem applies for 32G trunking ports and occurs when the port goes offline because of Link failure and then comes online and tries to join master port.	

Defect ID: DEFECT000595761	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.1	Technology Area: Software Installation & Upgrade
Symptom: Fan speed continuously oscillate between two speed levels every 30 minutes. Customers will see HIL-1516 raslog every time the fan speed increases as part of this oscillation.	
Condition: The fan oscillation happens on X6-4 and X6-8 chassis.	

Defect ID: DEFECT000595881	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS8.0.1	Technology Area: WAN Performance Analysis Tools
Symptom: FCIP Circuit is in a Online Warning state after applying an SLA, due to SLA misconfiguration.	
Condition: Configuring an FCIP Circuit with an SLA when the circuit is in a Down state.	
Workaround: Apply SLA configuration as part of the FCIP circuit create command, or after the circuit state reaches In Progress or Online.	

Defect ID: DEFECT000596027	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Extension
Reported In Release: FOS7.4.1	Technology Area: FCIP - Fibre Channel over IP
Symptom: FCIP FCP and FICON I/O Errors during FCIP HCL Failover or Failback processing on FCP or FICON Emulation enabled tunnels	
Condition: When running active FICON and FCP traffic over a FICON emulation and FCP emulation enabled FCIP tunnel (or different tunnels) and performing an FCIP HCL firmware upgrade or downgrade.	

Defect ID: DEFECT000596073	
Technical Severity: High	Probability: Low
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.1	Technology Area: Flow Vision
Symptom: Flow Monitor with option -frametype doesn't count frames	
Condition: Flow created with option -frametype	

Defect ID: DEFECT000596200	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.1	Technology Area: RAS - Reliability, Availability, and Serviceability
Symptom: Brocade 6520 platform missing raslog event "[SULB-1044], 4, CHASSIS, INFO, Brocade_6505C3, Firmwaredownload to secondary partition has completed successfully."	
Condition: During firmwaredownload on the Brocade 6520 platform	
Workaround: Use firmwaredownloadstatus to see the status.	

Defect ID: DEFECT000596524	
Technical Severity: Medium	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS8.0.1	Technology Area: Virtual Fabrics
Symptom: SNMP fruclass object returning switch blade as application blade and in chassisshow it shows as a SW blade instead of an AP blade.	
Condition: Fruclass is incorrect for application blade	

Defect ID: DEFECT000596527	
Technical Severity: Medium	Probability: Low
Product: Brocade Fabric OS	Technology: Security
Reported In Release: FOS8.0.1	Technology Area: Fabric Authentication
Symptom: Port may become disabled after a firmware download from FOS v8.0.1 to FOS v7.4.x with port authentication set to DHCHAP	
Condition: Firmware download from FOS v8.0.1 to FOS v7.4.x	
Workaround: Remove the DHCHAP keys using " secauthsecret --remove --all " and add the keys back after downgrade to FOS v7.4.x	

Defect ID: DEFECT000596539	
Technical Severity: Medium	Probability: High
Product: Brocade Fabric OS	Technology: Monitoring
Reported In Release: FOS8.0.1	Technology Area: MAPS - Monitoring and Alerting Policy Suite
Symptom: Brocade 6505 model switch when shipped with single FAN/PS FRU which is the default ship configuration for this model will show WARNING message and MARGINAL switch state.	
Condition: Brocade 6505 model that is shipped with single FAN/PS FRU.	

Defect ID: DEFECT000596616	
Technical Severity: High	Probability: Medium
Product: Brocade Fabric OS	Technology: Management
Reported In Release: FOS7.0.2	Technology Area: High Availability
Symptom: Termination of weblinker is observed	
Condition: This issue is seen rarely during configupload operation from management application.	

