

LACP Trouble Shooting

Models: N5860 Series; N8560 Series; NC8200 Series; NC8400 Series

Contents

1. Fault Phenomenon.....	1
2. Possible Cause of Failure.....	1
3. Processing Steps.....	1
3.1 Check Whether There Is a Link Failure On the Aggregation Member Port.....	1
3.2 Check the Port Properties of Both Devices.....	1
3.3 Check Whether the Link Aggregation Member Ports and Link Aggregation Groups Are Normal.....	2
3.4 Check the Aggregation Port Configuration Is Correct.....	3
3.5 Check Whether the Configuration of the Peer Device Is Correct.....	3
4. Seek FS Technical Support.....	3

1. Fault Phenomenon

Port aggregation is unsuccessful.

2. Possible Cause of Failure

- ① Physical link failure.
- ② LACP negotiation was unsuccessful.
- ③ There is no change in the packet flow and the matching part of the balance factor.
- ④ The duplex, rate, and transmission medium at both ends are inconsistent.

3. Processing Steps

3.1 Check Whether There Is a Link Failure On the Aggregation Member Port

FS#show interface status //Check whether the port status of the aggregation member port is up.

FS#show interfaces status

Interface	Status	Vlan	Duplex	Speed	Type
TenGigabitEthernet 0/18	down	1	Unknown	Unknown	fiber
TenGigabitEthernet 0/19	up	1	Full	10G	fiber
TenGigabitEthernet 0/20	up	1	Full	10G	fiber

If the member port is down, check the physical port connection. Make sure the member is up. If conditions permit, replace other member ports, confirm whether the aggregation member port can be up, and exclude the member port from physical failure.

3.2 Check the Port Properties of Both Devices

Use the show interface XX command to view the port's media properties, focusing on the port's speed, flow control, and media type, and it needs to be configured in full-duplex mode to eliminate the problem that the port cannot be up

FS#show interfaces tenGigabitEthernet 0/19

Index(dec):19 (hex):13

TenGigabitEthernet 0/19 is UP , line protocol is UP

Hardware is TenGigabitEthernet, address is 300d.9e43.38de (bia 300d.9e43.38de)

Interface address is: no ip address

Interface IPv6 address is:

No IPv6 address

MTU 1500 bytes, BW 10000000 Kbit

Encapsulation protocol is Ethernet-II, loopback not set

Keepalive interval is 10 sec , set

Carrier delay is 2 sec

Ethernet attributes:

Last link state change time: 2020-07-15 10:10:35

Time duration since last link state change: 0 days, 0 hours, 12 minutes, 29 seconds

Priority is 0

Medium-type is Fiber

Admin duplex mode is AUTO, oper duplex is Full

```

Admin speed is AUTO, oper speed is 10G
Flow control admin status is OFF, flow control oper status is OFF
Admin negotiation mode is OFF, oper negotiation state is OFF
Storm Control: Broadcast is OFF, Multicast is OFF, Unicast is OFF
Rxload is 1/255, Txload is 1/255
Input peak rate: 205 bits/sec, at 2020-07-15 10:11:45
Output peak rate: 304 bits/sec, at 2020-07-15 10:11:45
10 seconds input rate 0 bits/sec, 0 packets/sec
10 seconds output rate 0 bits/sec, 0 packets/sec
29 packets input, 6616 bytes, 0 no buffer, 0 dropped
Received 1 broadcasts, 0 runts, 0 giants
0 input errors, 0 CRC, 0 frame, 0 overrun, 0 abort
52 packets output, 9512 bytes, 0 underruns, 0 no buffer, 0 dropped
0 output errors, 0 collisions, 0 interface resets

```

3.3 Check Whether the Link Aggregation Member Ports and Link Aggregation Groups Are Normal

State: Member port negotiation status, bndl indicates that the negotiation is successful, susp indicates that the negotiation fails, and down indicates that the link status of the interface is down

FS#show lacp summary 1

System Id:32768, 300d.9e7a.74c0

Flags: S - Device is requesting Slow LACPDUs F - Device is requesting Fast LACPDUs.

A - Device is in active mode.

P - Device is in passive mode.

Aggregate port 1:

Local information:

Port	Flags	State	LACP port	Oper	Port	Port
			Priority	Key	Number	State
Te0/19	SA	bndl	32768	0x1	0x13	0x3d
Te0/20	SA	bndl	32768	0x1	0x14	0x3d

Partner information:

Port	Flags	LACP port	Dev ID	Oper	Port	Port
				Key	Number	State
Te0/19	SA	32768	300d.9e43.38de	0x1	0x13	0x3d
Te0/20	SA	32768	300d.9e43.38de	0x1	0x14	0x3d

FS#show aggregatePort 1 summary

Aggregate Port	MaxPorts	SwitchPort Mode	Load balance	Ports
Ag1	8	Enabled	ACCESS enhanced profile	Te0/19 ,Te0/20

AggregatePort :AP Interface name

MaxPorts: AP The maximum number of interfaces that can be supported.

SwitchPort: AP Whether the interface is a Layer 2 port, Enabled indicates a Layer 2 port, and Disabled indicates not a Layer 2 port.

Mode: AP The attributes of the Layer 2 interface of the interface, including: ACCESS, TRUNK, TUNNEL, HYBRID, UPLINK, HOST, and PROMIS, when the AP interface is not a Layer 2 interface, the display is empty.

Load balance: AP Balance mode of the interface

Ports :AP Balance mode of the interface

3.4 Check the Aggregation Port Configuration Is Correct

```
FS#show running-config interface TenGigabitEthernet 0/19
```

```
Building configuration...
```

```
Current configuration: 62 bytes
```

```
interface TenGigabitEthernet 0/19
```

```
port-group 1 mode active
```

There are two LACP port modes: Active and Passive

3.5 Check Whether the Configuration of the Peer Device Is Correct

If the LACP mode of both ports of the device is passive mode, the aggregation relationship cannot be established. Both ends are in active mode, or one side is in active mode and one is in passive mode.

4. Seek FS Technical Support

If the fault cannot be solved after the above steps are checked, please collect the following fault information and contact FS technical support for assistance.

```
show run
```

```
show version
```

```
show version slot
```

```
show lacp summary X
```

```
show lacp summary X
```

```
show logging
```



 <https://www.fs.com>



The information in this document is subject to change without notice. FS has made all efforts to ensure the accuracy of the information, but all information in this document does not constitute any kind of warranty.