

HPE 3PAR OS 3.2.2 MU6 Patch 137 Release Notes

Abstract

This release notes document is for 3.2.2 MU6 P137.

Part Number: QL226-10018a Published: February 2019

Edition: 2

© Copyright 2018 Hewlett Packard Enterprise Development LP

© 2014-2018, Hewlett Packard Enterprise Development LP

The information contained herein is subject to change without notice. The only warranties for Hewlett Packard Enterprise products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. Hewlett Packard Enterprise shall not be liable for technical or editorial errors or omissions contained herein.

Confidential computer software. Valid license from Hewlett Packard Enterprise required for possession, use, or copying. Consistent with FAR 12.211 and 12.212, Commercial Computer Software, Computer Software Documentation, and Technical Data for Commercial Items are licensed to the U.S. Government under vendor's standard commercial license.

Export of the information contained in this publication may require authorization from the U.S. Department of Commerce.

Links to third-party websites take you outside the Hewlett Packard Enterprise website. Hewlett Packard Enterprise has no control over and is not responsible for information outside the Hewlett Packard Enterprise website.

Acknowledgements

Microsoft and Windows are U.S. registered trademarks of Microsoft Corporation.

Adobe® and Acrobat® are trademarks of Adobe Systems Incorporated.

Java and Oracle are registered trademarks of Oracle and/or its affiliates.

UNIX® is a registered trademark of The Open Group.

Intel®, Itanium®, Pentium®, Intel Inside®, and the Intel Inside logo are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Purpose

The HPE 3PAR OS 3.2.2 MU6 Patch 137 provides support for new drives and drive firmware upgrades.

IMPORTANT: See the <u>HPE 3PAR OS and Service Processor Software Update Guide (HPE 3PAR OS 3.2.x HPE 3PAR Service Processor 4.x)</u> for instructions on updating your specific software.

Guidance

This is a critical patch for arrays that are utilizing the affected drive models. Arrays running on prior to 3.2.2 MU6 P115 should not upgrade to P115, P124, P136 and should instead use P137.

Prerequisites

- Minimum Service Processor required: SP-4.4.0 MU6 + latest SP patch.
- Base OS: 3.2.2 MU6. See the Requires field in the Patch details.

Patch details

Patch ID: P137

Synopsis: Provides support for new drives and drive FW upgrades

Date: January 03, 2019, 14:08:06 PST

Description: See the Release Notes for details about this patch

Affected Packages: tpd-drivefw, tpd-fwdb, tpd-prerevert

Obsoletes: OS-3.2.2.709-P136

Requires: OS-3.2.2.709-MU6,OS-3.2.2.709-P99,OS-3.2.2.709-P119,OS-3.2.2.709-P123 Build Version:

3.2.2.777

Patches Included: None.

Patches Partially Superseded: None.

Patches Obsolete by Combination: None.

Supports Revert: Yes

Patch ID: P136

Synopsis: Provides support for drive FW updates

Date: October 04, 2018, 13:46:41 PDT

Description: See the Release Notes for details about this patch

Affected Packages: tpd-drivefw, tpd-fwdb, tpd-prerevert

Obsoletes: OS-3.2.2.709-P124

Requires: OS-3.2.2.709-MU6,OS-3.2.2.709-P99,OS-3.2.2.709-P119,OS-3.2.2.709-P123

Build Version: 3.2.2.766

Notes: Description of the obsoleted patches:

Patch ID: P124

Synopsis: Provides support for new drives.

Date: August 06, 2018, 14:55:25 PDT

Description: See the Release Notes for details about this patch

Affected Packages: tpd-drivefw, tpd-fwdb, tpd-prerevert

Obsoletes: OS-3.2.2.709-P115

Requires: OS-3.2.2.709-MU6,OS-3.2.2.709-P99,OS-3.2.2.709-P119,OS-3.2.2.709-P123

Build Version: 3.2.2.757

Notes: Description of the obsoleted patches:

Patch ID: P115

Synopsis: Provides support for drive FW updates

Date: July 18, 2018, 11:20:31 PDT

Description: See the Release Notes for details about this patch

Affected Packages: tpd-drivefw, tpd-fwdb, tpd-prerevert

Obsoletes: OS-3.2.2.709-P112 Requires: OS-3.2.2.709-MU6

Build Version: 3.2.2.752

Notes: Description of the obsoleted patches:

Patch ID: P112

Synopsis: Provides support for drive FW updates

Date: June 29, 2018, 13:03:10 PDT

Description: See the Release Notes for details about this patch

Affected Packages: tpd-drivefw, tpd-fwdb, tpd-prerevert

Obsoletes: OS-3.2.2.709-P104 Requires: OS-3.2.2.709-MU6

Build Version: 3.2.2.747

Notes: Description of the obsoleted patches:

Patch ID: P104

Synopsis: Provides support for drive FW updates

Date: April 05, 2018, 13:09:16 PDT

Description: See the Release Notes for details about this patch

Affected Packages: tpd-drivefw, tpd-fwdb, tpd-prerevert

Obsoletes: OS-3.2.2.709-P96 Requires: OS-3.2.2.709-MU6

Build Version: 3.2.2.732

Notes: Description of the obsoleted patches:

Patch ID: P96

Synopsis: Provides support for drive FW updates.

Date: November 20, 2017, 09:44:32 PST

Description: See the Release Notes for details about this patch

Affected Packages: tpd-fwdb, tpd-prerevert

Obsoletes: None

Requires: OS-3.2.2.709-MU6

Build Version: 3.2.2.711

Notes:

This patch is revertible, however, revert after the supported drives are in use makes them unavailable.

NOTE:

Hewlett Packard Enterprise recommends installing patches in the same sequence as they are released, unless instructed otherwise.

Modifications

HPE 3PAR OS 3.2.2 MU6 Patch 137 will upgrade DOPM3840S5xnNMR drives with 3P01 firmware to 3P04. This patch upgrades DOPE0480S5xnNMRI and DOPE1920S5xnNMRI drives with 3P01 firmware to 3P07. Patch 137 provides support for the following new drives and firmware updates.

Drive	Catego ry	Capacity	Speed	StoreSer v 10000	StoreSer v 7000	StoreSer v 20000	StoreSer v 8000	FW
AREX0480S 5xnNTRI	SSD	480GB	100K	No	Yes	Yes	Yes	3P07
AREX0920S 5xnNTRI	SSD	920GB	100K	No	Yes	No	No	3P07
AREX1920S 5xnNTRI	SSD	1.92TB	100K	Yes	Yes	Yes	Yes	3P07
AREX3840S 5xnNTRI	SSD	3.84TB	100K	No	Yes	Yes	Yes	3P07
AREX0400S 5xnNTRI	SSD	400GB	150K	Yes	Yes	Yes	Yes	3P03
AREX0920S 5xnFTRI	SSD	920GB	100K	No	Yes	Yes	Yes	3P03
AREX1920S 5xnFTRI	SSD	1.92TB	100K	No	Yes	Yes	Yes	3P03
AREX3840S 5xnFTRI	SSD	3.84TB	100K	No	Yes	Yes	Yes	3P03
STHB0600S 5xeN010	FC	600GB	10K	Yes	Yes	Yes	Yes	3P03
STHB1200S 5xeN010	FC	1.2TB	10K	Yes	Yes	Yes	Yes	3P03
STHB1800S 5xeN010	FC	1.8TB	10K	Yes	Yes	Yes	Yes	3P03
ARFX0920S 5xnNTRI	SSD	920GB	150K	No	Yes	Yes	Yes	3P00

Table Continued

ARFX1920S 5xnNTRI	SSD	1.92TB	100K	Yes	Yes	Yes	Yes	3P00
ARFX3840S 5xnNTRI	SSD	3.84TB	100K	No	Yes	Yes	Yes	3P00
ARFX7680S 5xnNTRI	SSD	7.68TB	100K	No	No	Yes	Yes	3P00
ARFX15T4S 5xnNTRI	SSD	15.3TB	100K	No	No	Yes	Yes	3P00
King Cobra F	FC	300GB	15K	Yes	Yes	Yes	Yes	3P04
King Cobra F	FC	600GB	15K	Yes	Yes	Yes	Yes	3P04
King Cobra F FIPS	FC	600GB	15K	Yes	Yes	Yes	Yes	3P04
SKST0300S 5xeN015	FC	300GB	15K	Yes	Yes	Yes	Yes	3P00
SKST0600S 5xeN015	FC	600GB	15K	Yes	Yes	Yes	Yes	3P00
SKST0600S 5xeF015	FC	600GB	15K	Yes	Yes	Yes	Yes	3P00

Affected components

Component	Version
Firmware Database	3.2.2.777 (P137)
Drive Firmware	3.2.2.777 (P137)

NOTE: Applying an HPE 3PAR OS patch can cause a restart of the affected OS components. This restart is an expected behavior, which will generate events and alerts. The system continues to serve data, but existing CLI or SSMC sessions could be interrupted.

Installing Drive/Cage Firmware

After a firmware patch is installed successfully, the firmware (drive or cage) must be updated manually. To update the firmware, run the CLI command starttask admithw -ni. This command runs the update process as a task. Record the task ID for monitoring purposes. Monitor the task for successful completion using the CLI command showtask -d <task_ID>. See the appropriate upgrade documentation for details on patch installation. If the task fails, resolve the issue due to which the task failed. After the issue is resolved, issue the CLI command starttask admithw -ni. Note the new task ID number and monitor the admithw task completion. Run the admithw task to successful completion as soon as possible after installing patches.

IMPORTANT: While revert is possible, HPE does not recommended reverting a patch that delivers (<u>!</u>) firmware after the admithw command has been executed. The admithw command will activate/ update the new firmware. If the patch is reverted prior to admithw being executed, use the command showfirmwaredb -1 after the patch revert has completed to ensure that the FW status is changed from degraded (old firmware) to normal (current). If the OS on the array is upgraded to a later version after a firmware patch is installed, install firmware patches prior to executing admithw.

Verification

The installation of Patch 137 can be verified from an interactive CLI session. Issue the CLI command showversion -a -b to verify that Patch 137 is listed:

showversion -a -b

Release version 3.2.2.709 (MU6) Patches: P99,P119,P123,P137

Component Name	77
Component Name	Version
CLI Server CLI Client	3.2.2.750 (P119)
	3.2.2.750 3.2.2.750 (P119)
System Manager Kernel	
TPD Kernel Code	
TPD Kernel Patch	3.2.2.750 (P119)
CIM Server	3.2.2.750 (P119)
WSAPI Server	3.2.2.750 (P119)
Console Menu	3.2.2.709 (MU6)
Event Manager	3.2.2.709 (MU6)
Internal Test Tools	3.2.2.709 (MU6)
LD Check Tools	3.2.2.709 (MU6)
Network Controller	3.2.2.725 (P99)
Node Disk Scrubber	3.2.2.709 (MU6)
PD Scrubber	3.2.2.709 (MU6)
Per-Node Server	3.2.2.725 (P99)
Persistent Repository	3.2.2.709 (MU6)
Powerfail Tools	3.2.2.709 (MU6)
Preserved Data Tools	3.2.2.709 (MU6)
Process Monitor	3.2.2.709 (MU6)
Rolling Upgrade Tools	3.2.2.709 (MU6)
Software Updater	3.2.2.750 (P119)
TOC Server	3.2.2.725 (P99)
VV Check Tools	3.2.2.725 (P99)
File Persona	1.2.4.3-20170601
SNMP Agent	1.8.0
SSH	6.6p1-4~bpo70+1
VASA Provider	2.2.12 (P119)
Firmware Database	3.2.2.777 (P137)
Drive Firmware	3.2.2.777 (P137)
UEFI BIOS	04.08.39
MCU Firmware (OKI)	4.8.29
MCU Firmware (STM)	5.2.53
Cage Firmware (DC1)	4.44
Cage Firmware (DC2)	2.64
Cage Firmware (DC3)	08
Cage Firmware (DC4)	2.64
Cage Firmware (DCN1)	4078
Cage Firmware (DCN2)	4078
Cage Firmware (DCS1)	4078
Cage Firmware (DCS2)	4078
Cage Firmware (DCS5)	2.86
Cage Firmware (DCS6)	2.86
Cage Firmware (DCS7)	4078
Cage Firmware (DCS8)	4078
QLogic QLA4052C HBA Firmware	03.00.01.77
QLogic QLE8242 CNA Firmware	04.15.08
QLogic 8300 HBA FC Firmware	08.01.05
QLogic 8300 HBA FCoE Firmware	08.01.05

QLogic	8300 HBA	iSCSI Firmware	05.07.07
Emulex	LP11002 H	IBA Firmware	02.82.x10
Emulex	LPe12002	HBA Firmware	02.10.x03
Emulex	LPe12004	HBA Firmware	02.10.x03
Emulex	LPe16002	HBA Firmware	10.6.248.8
Emulex	LPe16004	HBA Firmware	10.6.248.8
3PAR FC	044X HBA	Firmware	200A8
LSI 920	1-16e HBA	A Firmware	17.11.00
LSI 920	5-8e HBA	Firmware	17.11.00
LSI 930	0-8e HBA	Firmware	07.10.01

NOTE: When displaying the showversion command output from the SP, the CLI Client version is static in the SP code and may differ from the output from any other system.

Websites

General websites

Hewlett Packard Enterprise Information Library

www.hpe.com/info/EIL

Single Point of Connectivity Knowledge (SPOCK) Storage compatibility matrix

www.hpe.com/storage/spock

Storage white papers and analyst reports

www.hpe.com/storage/whitepapers

For additional websites, see **Support and other resources**.

Support and other resources

Accessing Hewlett Packard Enterprise Support

• For live assistance, go to the Contact Hewlett Packard Enterprise Worldwide website:

http://www.hpe.com/assistance

To access documentation and support services, go to the Hewlett Packard Enterprise Support Center website:

http://www.hpe.com/support/hpesc

Information to collect

- Technical support registration number (if applicable)
- Product name, model or version, and serial number
- Operating system name and version
- Firmware version
- Error messages
- · Product-specific reports and logs
- Add-on products or components
- · Third-party products or components

Accessing updates

- Some software products provide a mechanism for accessing software updates through the product interface. Review your product documentation to identify the recommended software update method.
- To download product updates:

Hewlett Packard Enterprise Support Center

www.hpe.com/support/hpesc

Hewlett Packard Enterprise Support Center: Software downloads

www.hpe.com/support/downloads

Software Depot

www.hpe.com/support/softwaredepot

· To subscribe to eNewsletters and alerts:

www.hpe.com/support/e-updates

To view and update your entitlements, and to link your contracts and warranties with your profile, go to the Hewlett Packard Enterprise Support Center More Information on Access to Support Materials page:

www.hpe.com/support/AccessToSupportMaterials

IMPORTANT: Access to some updates might require product entitlement when accessed through the Hewlett Packard Enterprise Support Center. You must have an HPE Passport set up with relevant entitlements.

Customer self repair

Hewlett Packard Enterprise customer self repair (CSR) programs allow you to repair your product. If a CSR part needs to be replaced, it will be shipped directly to you so that you can install it at your convenience. Some parts do not qualify for CSR. Your Hewlett Packard Enterprise authorized service provider will determine whether a repair can be accomplished by CSR.

For more information about CSR, contact your local service provider or go to the CSR website:

http://www.hpe.com/support/selfrepair

Remote support

Remote support is available with supported devices as part of your warranty or contractual support agreement. It provides intelligent event diagnosis, and automatic, secure submission of hardware event notifications to Hewlett Packard Enterprise, which will initiate a fast and accurate resolution based on your product's service level. Hewlett Packard Enterprise strongly recommends that you register your device for remote support.

If your product includes additional remote support details, use search to locate that information.

Remote support and Proactive Care information

HPE Get Connected

www.hpe.com/services/getconnected

HPE Proactive Care services

www.hpe.com/services/proactivecare

HPE Proactive Care service: Supported products list

www.hpe.com/services/proactivecaresupportedproducts

HPE Proactive Care advanced service: Supported products list

www.hpe.com/services/proactivecareadvancedsupportedproducts

Proactive Care customer information

Proactive Care central

www.hpe.com/services/proactivecarecentral

Proactive Care service activation

www.hpe.com/services/proactivecarecentralgetstarted

Warranty information

To view the warranty information for your product, see the links provided below:

HPE ProLiant and IA-32 Servers and Options

www.hpe.com/support/ProLiantServers-Warranties

HPE Enterprise and Cloudline Servers

www.hpe.com/support/EnterpriseServers-Warranties

HPE Storage Products

www.hpe.com/support/Storage-Warranties

HPE Networking Products

www.hpe.com/support/Networking-Warranties

Regulatory information

To view the regulatory information for your product, view the Safety and Compliance Information for Server, Storage, Power, Networking, and Rack Products, available at the Hewlett Packard Enterprise Support Center:

www.hpe.com/support/Safety-Compliance-EnterpriseProducts

Additional regulatory information

Hewlett Packard Enterprise is committed to providing our customers with information about the chemical substances in our products as needed to comply with legal requirements such as REACH (Regulation EC No 1907/2006 of the European Parliament and the Council). A chemical information report for this product can be found at:

www.hpe.com/info/reach

For Hewlett Packard Enterprise product environmental and safety information and compliance data, including RoHS and REACH, see:

www.hpe.com/info/ecodata

For Hewlett Packard Enterprise environmental information, including company programs, product recycling, and energy efficiency, see:

www.hpe.com/info/environment

Documentation feedback

Hewlett Packard Enterprise is committed to providing documentation that meets your needs. To help us improve the documentation, send any errors, suggestions, or comments to Documentation Feedback (docsfeedback@hpe.com). When submitting your feedback, include the document title, part number, edition, and publication date located on the front cover of the document. For online help content, include the product name, product version, help edition, and publication date located on the legal notices page.