



**Hewlett Packard
Enterprise**

HPE 3PAR OS 3.3.1 GA/EGA Release Notes

Abstract

This document describes the features and issues included in HPE 3PAR OS 3.3.1 and is intended for use by Hewlett Packard Enterprise customers, partners and field representatives.

Part Number: QL226-99604
Published: June 2017
Edition: 1

The information contained herein is subject to change without notice. The only warranties for Hewlett Packard Enterprise products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. Hewlett Packard Enterprise shall not be liable for technical or editorial errors or omissions contained herein.

Confidential computer software. Valid license from Hewlett Packard Enterprise required for possession, use, or copying. Consistent with FAR 12.211 and 12.212, Commercial Computer Software, Computer Software Documentation, and Technical Data for Commercial Items are licensed to the U.S. Government under vendor's standard commercial license.

Links to third-party websites take you outside the Hewlett Packard Enterprise website. Hewlett Packard Enterprise has no control over and is not responsible for information outside the Hewlett Packard Enterprise website.

Acknowledgments

Google™ is a trademark of Google Inc.

Linux® is a trademark of Linus Torvalds in the U.S. and other countries.

Microsoft®, Windows®, and Hyper-V® are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries.

Mozilla® and Firefox® are trademarks of Mozilla Incorporated.

Red Hat® is a trademark of Red Hat, Inc. in the United States and other countries.

UNIX® is a registered trademark of The Open Group.

VMware®, VMware® ESX®, VMware® ESXi™, VMware® vCenter™, and VMware vSphere® are U.S. registered trademarks of VMware, Inc.

Contents

| | |
|---|---------------|
| HPE 3PAR OS 3.3.1 GA Release Notes..... | 5 |
| Online Upgrade Considerations..... | 5 |
| Supported Platforms..... | 5 |
| Notes..... | 5 |
| Components | 5 |
| What's New in the OS..... | 8 |
| Modifications to the HPE 3PAR OS..... | 12 |
| Known Issues with the OS..... | 25 |
| Modifications to File Persona..... | 36 |
| Known Issues with File Persona..... | 38 |
| HPE 3PAR 3.3.1 CLI Release Notes..... | 44 |
| Installation Notes for the CLI..... | 44 |
| Supported Operating Systems..... | 44 |
| What's New in the CLI..... | 45 |
| New Commands..... | 45 |
| Changed Commands..... | 45 |
| Modifications to the CLI..... | 48 |
| HPE 3PAR CIM API Release Notes..... | 55 |
| What's New with the CIM API and SNMP Software | 55 |
| Modifications to the 3PAR CIM API..... | 55 |
| Web Services API Release Notes..... | 57 |
| What's New with the Web Services API Software | 57 |
| Modifications to the 3PAR Web Services API..... | 58 |
| HPE 3PAR OS 3.3.1 EGA Release Notes..... | 60 |
| Online Upgrade Considerations..... | 60 |
| Notes..... | 60 |
| Supported Platforms..... | 60 |
| Affected components..... | 60 |
| Modifications | 63 |
| Support and other resources..... | 68 |
| Accessing Hewlett Packard Enterprise Support..... | 68 |
| Accessing updates..... | 68 |
| Websites..... | 69 |
| Customer self repair..... | 69 |
| Remote support..... | 69 |
| Documentation feedback..... | 69 |
| Warranty and regulatory information..... | 70 |

| | |
|---------------------------|----|
| Warranty information..... | 70 |
|---------------------------|----|

HPE 3PAR OS 3.3.1 GA Release Notes

Online Upgrade Considerations

The HPE 3PAR OS can be upgraded concurrently with I/O activity on the attached hosts, provided certain conditions are met. For more information on planning for online upgrades, refer to the latest version of the *HPE 3PAR Operating System Upgrade Pre-Planning Guide*. To obtain a copy of this documentation, go to the Hewlett Packard Enterprise Information Library.

Supported Platforms

This HPE 3PAR OS release supports HPE 3PAR StoreServ Storage. For more information, see the HPE Single Point of Connectivity Knowledge (SPOCK) website:

<http://www.hpe.com/storage/spock>

The minimum Service Processor version that supports HPE 3PAR OS 3.3.1 is SP 5.0.0.

Notes



WARNING:

3PAR Remote Copy asynchronous streaming configurations do not support compression. Do not use the asynchronous streaming replication mode with compressed volumes.



WARNING:

3PAR Deduplication and compression are resource intensive operations, and as loads increase to these volumes, File Persona volume performance can decrease significantly. The load applied to volumes with these services enabled may need to be controlled in order to manage the impact to other volumes specifically volumes used by File Persona feature set as part of a File Provisioning Group.

Components

| Component | Version |
|-----------------|-----------|
| OS | 3.3.1.215 |
| Patches | None |
| CLI Server | 3.3.1.215 |
| CLI Client | 3.3.1.215 |
| System Manager | 3.3.1.215 |
| Kernel | 3.3.1.215 |
| TPD Kernel Code | 3.3.1.215 |

Table Continued

| Component | Version |
|-----------------------|-------------------------|
| CIM Server | 3.3.1.215 |
| WSAPI Server | 3.3.1.215 |
| Console Menu | 3.3.1.215 |
| Event Manager | 3.3.1.215 |
| Internal Test Tools | 3.3.1.215 |
| LD Check Tools | 3.3.1.215 |
| Network Controller | 3.3.1.215 |
| Node Disk Scrubber | 3.3.1.215 |
| PD Scrubber | 3.3.1.215 |
| Per-Node Server | 3.3.1.215 |
| Persistent Repository | 3.3.1.215 |
| Powerfail Tools | 3.3.1.215 |
| Preserved Data Tools | 3.3.1.215 |
| Process Monitor | 3.3.1.215 |
| Software Updater | 3.3.1.215 |
| TOC Server | 3.3.1.215 |
| VV Check Scripts | 3.3.1.215 |
| Upgrade Check Scripts | 170330.U004 (3.3.1.215) |
| File Persona | 1.3.0.74-20170309 |
| SNMP Agent | 1.10.0 |
| SSH | 6.0p1-4+deb7u5 |
| VASA Provider | 3.0.12 |
| Firmware Database | 3.3.1.215 |
| Drive Firmware | 3.3.1.215 |
| UEFI BIOS | 05.02.54 |

Table Continued

| Component | Version |
|----------------------------------|-------------|
| MCU Firmware (OKI) | 4.8.60 |
| MCU Firmware (STM) | 5.3.17 |
| Cage Firmware (DC1) | 4.44 |
| Cage Firmware (DC2) | 2.64 |
| Cage Firmware (DC3) | 08 |
| Cage Firmware (DC4) | 2.64 |
| Cage Firmware (DCN1) | 4082 |
| Cage Firmware (DCN2) | 4082 |
| Cage Firmware (DCS1) | 4082 |
| Cage Firmware (DCS2) | 4082 |
| Cage Firmware (DCS5) | 2.78 |
| Cage Firmware (DCS6) | 2.78 |
| Cage Firmware (DCS7) | 4082 |
| Cage Firmware (DCS8) | 4082 |
| QLogic QLA4052C HBA Firmware | 03.00.01.77 |
| QLogic QLE8242 CNA Firmware | 04.15.27 |
| QLogic 260x HBA FC Firmware | 174.03.70 |
| QLogic 27xx/268x HBA FC Firmware | 174.03.70 |
| QLogic 83xx HBA FCoE Firmware | 08.01.05 |
| QLogic 8300 HBA iSCSI Firmware | 05.07.35 |
| Emulex LP11002 HBA Firmware | 02.82.x10 |
| Emulex LPe12002 HBA Firmware | 02.10.x02 |
| Emulex LPe12004 HBA Firmware | 02.10.x02 |
| Emulex LPe16002 HBA Firmware | 11.1.220.6 |
| Emulex LPe16004 HBA Firmware | 11.1.220.6 |

Table Continued

| Component | Version |
|---------------------------|----------|
| 3PAR FC044X HBA Firmware | 200A8 |
| LSI 9201-16e HBA Firmware | 17.11.03 |
| LSI 9205-8e HBA Firmware | 17.11.03 |
| LSI 9300-8e HBA Firmware | 10.00.08 |

What's New in the OS

New and enhanced features include:

3PAR OS 3.3.1

- Inline Compression—Inline for optimal efficiency
- Data Packing—Combines data reduction and flash efficiency technologies to maintain peak capacity efficiency over time
- Adaptive data reduction—New support for inline compression and data packing designed to reduce the data footprint
- Adaptive Sparing 2.0
- Express Layout Enhancements—Express Layout is now supported for all drives, and not just solid-state drives (SSDs)
- Self Identifying Drives—3PAR systems can now automatically recognize a newly introduced drive without needing a software patch
- More Raw Capacity—Support for more raw capacity. Twice the SSD raw capacity supported compared to HPE 3PAR OS 3.2.2
- Loop topology connection mode for direct connection to 16 Gbps FC 3PAR StoreServ target
- Larger Volume Sizes—Full and thin provisioning virtual volume maximum sizes increased to 64 TiB
- `setcpg` growth and warning limits are no longer capped at 1 PiB
- New TDVV format—Enhanced deduplication and reporting
- Write Cache behavior options during single node operational states—New options to turn on write back cache to improve performance.
- Default RAID type is 6 for all drive types
- IPv6 now supports default gateways

3PAR File Persona

- NTFS Security Mode and cross protocol locking for seamless group file sharing—SMB and NFS
- Static and Dynamic User Mapping for mapping AD and LDAP users for cross protocol access
- File Lock Enterprise Mode to meet corporate governance requirements
- Larger File Provisioning Group size of 64 TiB with up to 250 million files for simpler scaling of large data sets
- Online File System Check to complement inherent file system integrity
- 3PAR Web Service API to automate File Persona management
- Enhancements to the Object Access API to support file copy and partial file access
- Support for Sophos antivirus scan engine
- Antivirus bulk quarantine support
- Inclusion of share folder ACLs in the VFS configuration backup/restore process
- Support for FTP/FTPS shares
- Internationalization of user names, share names, and File Store names
- Thin Persistence support for File Provisioning Groups

- Growth of File Provisioning Groups by growing the underlying volumes (rather than adding additional volumes)
- Incremental improvements to file random IO performance

SmartSAN 2.0

- 3PAR StoreServ Management Console (SSMC) 3.1 Integration
- 3PAR Federation Zoning
- Expanded ecosystem and diagnostics

3DC Peer Persistence—Now supports a tertiary passive site in addition to the two existing active sites.

Remote Copy—Async streaming supported using RCIP over 10 GbE ports

! IMPORTANT:

Remote Copy Async Streaming does not support Compressed volumes.

VMware Virtual Volumes (VVols)

- Now support 3PAR Remote Copy replication for 1:1 mapping of virtual maps to storage volumes
- Support for iSCSI

Combo Cards Supported on 3PAR 8000 Systems

- 16 Gb FC/10 GbE NIC combo HBA
- 10 GbE iSCSI/10 GbE NIC combo HBA

DC PCM Support—New 48 VDC power cooling module (PCM) to offer DC power on 3PAR 8000 systems

Enhanced serviceability—Actionable alerts that contain spare part numbers of failed components

- Alert messages are now internationalized and can be displayed in Japanese or simplified Chinese via the Service Processor or StoreServ Management Console (SSMC).

Direct Attach Cable (DAC) Support

The HPE 3PAR StoreServ Storage System DAC qualification matrix was expanded to accommodate new Active DAC cables including AP818A, AP820A, new passive cables QK701A and QK702A, and new HPE BladeSystem cables 487655-B21, 537963-B21 and 487658-B21. These new supported DAC cables are all HPE qualified/ supported with 3PAR. See the complete listing of 3PAR DAC cables supported in the *3PAR Platforms and Required DAC OS Support* table.

NOTE:

- The term “direct” refers to the direct attach of the cable to the SFP+ housing, instead of attaching to a SFP+ module that plugs into the SFP+ housing.
 - DAC cable support for 3PAR StoreServ 8000 and 20000 storage platforms requires OS version 3PAR OS 3.2.2 MU3 and later.
-

Table 1: 3PAR Platforms and Required DAC OS Support

| 3PAR StoreServ Platforms and Required DAC OS Support | | | | | | |
|--|------------|----------------|----------------|----------------|----------------|----------------------------------|
| DAC Description | DAC Part # | 7000 | 10000 | 8000 | 20000 | Speed/ Protocols Supported |
| HPE 3COM (H3C) | | | | | | |
| HPE X240 10G SFP+ to SFP+ 0.65m DAC | JD095C | 3.1.3 or later | 3.1.3 or later | Not supported | Not supported | 10GbE, iSCSI, FCoE, File*, RCIP |
| HPE X240 10G SFP+ to SFP+ 1.2m DAC Cable | JD096C | 3.1.3 or later | 3.1.3 or later | 3.2.2 MU3 | 3.2.2 MU3 | 10GbE, iSCSI, FCoE, File*, RCIP |
| HPE X240 10G SFP+ to SFP+ 3m DAC Cable | JD097C | 3.1.3 or later | 3.1.3 or later | 3.2.2 MU3 | 3.2.2 MU3 | 10GbE, iSCSI, FCoE, File*, RCIP |
| HPE X240 10G SFP+ to SFP+ 5m DAC | JG081C | 3.1.3 or later | 3.1.3 or later | 3.2.2 MU3 | 3.2.2 MU3 | 10GbE, iSCSI, FCoE, File*, RCIP |
| HPE x240 QSFP+ 4x10G SFP+ 1m DAC Cable | JG329A | 3.2.2 MU3 | 3.2.2 MU3 | 3.2.2 MU3 | 3.2.2 MU3 | 10GbE, iSCSI, FCoE, File*, RCIP |
| HPE X240 10G SFP+ to SFP+ 7m DAC | JC784C | 3.1.3 or later | 3.1.3 or later | 3.1.3 or later | 3.1.3 or later | 10GbE, iSCSI, FCoE, File*, RCIP |
| HPE x240 QSFP+ 4x10G SFP+ 3m DAC Cable | JG330A | 3.2.2 MU3 | 3.2.2 MU3 | 3.2.2 MU3 | 3.2.2 MU3 | 10GbE, iSCSI, FCoE, File*, RCIP |
| HPE x240 QSFP+ 4x10G SFP+ 5m DAC Cable | JG331A | 3.2.2 MU3 | 3.2.2 MU3 | 3.2.2 MU3 | 3.2.2 MU3 | 10GbE, iSCSI, FCoE, File*, RCIP |
| HPE Procurve | | | | | | |
| HPE 10-GbE SFP+ 1m DAC | J9281B | 3.1.3 or later | 3.1.3 or later | 3.2.2 MU3 | 3.2.2 MU3 | 10GbE, iSCSI, FCoE, File*, RCIP |
| HPE 10-GbE SFP+ 3m DAC | J9283B | 3.1.3 or later | 3.1.3 or later | 3.2.2 MU3 | 3.2.2 MU3 | 10GbE, iSCSI, FCoE, File*, RCIP |

Table Continued

| 3PAR StoreServ Platforms and Required DAC OS Support | | | | | | |
|---|------------|----------------|----------------|----------------|----------------|----------------------------------|
| DAC Description | DAC Part # | 7000 | 10000 | 8000 | 20000 | Speed/ Protocols Supported |
| HPE X242 10G SFP+ to SFP+ 7m DAC | J9285B | 3.1.3 or later | 3.1.3 or later | 3.1.3 or later | 3.1.3 or later | 10GbE, iSCSI, FCoE, File*, RCIP |
| HPE StoreFabric | | | | | | |
| HPE C-series 3m Passive Copper SFP+ Cable | K2Q21A | 3.1.3 or later | 3.1.3 or later | 3.2.2 MU3 | 3.2.2 MU3 | 10GbE, iSCSI, FCoE, File*, RCIP |
| HPE C-series 5m Passive Copper SFP+ Cable | K2Q22A | 3.1.3 or later | 3.1.3 or later | 3.2.2 MU3 | 3.2.2 MU3 | 10GbE, iSCSI, FCoE, File*, RCIP |
| HPE C-series 7m Passive Copper SFP+ Cable | QK701A | 3.1.3 or later | 3.1.3 or later | 3.1.3 or later | 3.1.3 or later | 10GbE, iSCSI, FCoE, File*, RCIP |
| HPE C-series 10m Passive Copper SFP+ Cable | QK702A | 3.1.3 or later | 3.1.3 or later | 3.1.3 or later | 3.1.3 or later | 10GbE, iSCSI, FCoE, File*, RCIP |
| HPE 1m B-series Active Copper SFP+ Cable | AP818A | 3.1.3 or later | 3.1.3 or later | 3.1.3 or later | 3.1.3 or later | 10GbE, iSCSI, FCoE, File*, RCIP |
| HPE 3m B-series Active Copper SFP+ Cable | AP819A | 3.2.2 MU4 | 3.2.2 MU4 | 3.2.2 MU4 | 3.2.2 MU4 | 10GbE, iSCSI, FCoE, File*, RCIP |
| HPE 5m B-series Active Copper SFP+ Cable | AP820A | 3.1.3 or later | 3.1.3 or later | 3.1.3 or later | 3.1.3 or later | 10GbE, iSCSI, FCoE, File*, RCIP |
| HPE Blade System | | | | | | |
| HPE BladeSystem c-Class 10 GbE SFP+ to SFP+ 3m Direct Attach Copper Cable | 487655-B21 | 3.1.3 or later | 3.1.3 or later | 3.1.3 or later | 3.1.3 or later | 10GbE, iSCSI, FCoE, File*, RCIP |

Table Continued

| 3PAR StoreServ Platforms and Required DAC OS Support | | | | | | |
|---|------------|----------------|----------------|----------------|----------------|----------------------------------|
| DAC Description | DAC Part # | 7000 | 10000 | 8000 | 20000 | Speed/ Protocols Supported |
| HPE BladeSystem c-Class 10 GbE SFP+ to SFP+ 5m Direct Attach Copper Cable | 537963-B21 | 3.1.3 or later | 3.1.3 or later | 3.1.3 or later | 3.1.3 or later | 10GbE, iSCSI, FCoE, File*, RCIP |
| HPE BladeSystem c-Class 10 GbE SFP+ to SFP+ 7m Direct Attach Copper Cable | 487658-B21 | 3.1.3 or later | 3.1.3 or later | 3.1.3 or later | 3.1.3 or later | 10GbE, iSCSI, FCoE, File*, RCIP |

Notes:

- DAC cable support for HPE 3PAR StoreServ 8000 and 20000 platforms requires HPE 3PAR OS version 3.2.2. MU3 and later.
- All protocols are supported only with HPE 3PAR OS 3.2.2 MU3 and later.
- File* protocol is supported only with HPE 3PAR OS 3.2.2 and later.

Modifications to the HPE 3PAR OS

The following issues have been addressed in this release.

| |
|--|
| <p>Issue IDs: 106328</p> |
| <p>Issue summary: Upgrade checks are too aggressive when performing an offline upgrade, preventing an upgrade when it should proceed.</p> |
| <p>Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000</p> |
| <p>Affected software versions: 3.1.3, 3.2.1, 3.2.2</p> |
| <p>Issue description: The <code>checkupgrade</code> command is used to determine the system readiness to perform an upgrade. Offline upgrades have fewer restrictions because host I/O interruption is a given. The <code>checkupgrade</code> command was using online criteria for performing the checks despite an offline upgrade being performed, blocking the upgrade from proceeding when it should have been allowed to proceed.</p> |
| <p>Symptoms: An offline upgrade may not proceed due to a check that is only applicable for online upgrades being executed.</p> |
| <p>Conditions of occurrence: When using SPOCC to complete an offline HPE 3PAR OS upgrade.</p> |
| <p>Impact: Medium</p> |
| <p>Customer circumvention: None</p> |
| <p>Customer recovery steps: Resolve the condition that resulted in the upgrade check failure before attempting the upgrade again.</p> |

Issue IDs: 126114

Issue summary: Certain data backup solutions cannot access the secondary array in Remote Copy Peer Persistence configurations.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.1.3, 3.2.1, 3.2.2

Issue description: Allows data backup solutions, such as VADP (VMware vStorage API for Data Protection), to access data from the secondary site in Remote Copy Peer Persistence configurations. With the HPE 3PAR OS, the backup solution must use the Generic (non-ALUA) host persona when presenting volumes in a Remote Copy Peer Persistence group to the backup application.

Symptoms: Data backup solutions cannot read data from a Remote Copy secondary array.

Conditions of occurrence: Volumes in Remote Copy Peer Persistence groups on the secondary array when the backup solution tries to access the data on those volumes.

Impact: Medium

Customer circumvention: Set up the data backup solution to access the Remote Copy Peer Persistence primary system.

Customer recovery steps: Use primary system instead of the secondary system for backup operations.

Issue IDs: 141617

Issue summary: Unified Extensible Firmware Interface (UEFI) restart failure alert delivery can be delayed for an indefinite amount of time if an EEPROM read encounters a transient failure.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.2.2

Issue description: Transient read problems of a controller node's EEPROM data can postpone the delivery of restart failure alerts indefinitely. Because a reread of the data is based on a restart of the system manager process, the delivery of the alerts can be suppressed. This can cause what appears to be a stale alert to be posted at some later time.

Symptoms: UEFI restart failure alerts are not reported in a timely manner if a transient read failure is encountered, despite a controller node having been unable to restart previously.

Conditions of occurrence: A transient read failure can delay the posting of a UEFI restart failure alert indefinitely.

Impact: Low

Customer circumvention: None

Customer recovery steps: None

| |
|--|
| <p>Issue IDs: 142277</p> <p>Issue summary: <code>removecert</code> removed certificates for both <code>ekm-server</code> and <code>ekm-client</code> when just a individual <code>ekm</code> service was specified.</p> <p>Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000</p> <p>Affected software versions: 3.2.1 GA & All MUs</p> <p>Issue description: This issue has been corrected. A <code>removecert</code> command will now only remove a certificate of the specified <code>ekm</code> service.</p> <p>Symptoms: <code>removecert</code> for <code>ekm-client</code> or <code>ekm-server</code> would remove certificates for both <code>ekm-client</code> and <code>ekm-server</code>.</p> <p>Conditions of occurrence: Having an <code>ekm_client</code> and <code>ekm_server</code> certificate installed and removing a single one.</p> <p>Impact: High</p> <p>Customer circumvention: None</p> <p>Customer recovery steps: Re-import the removed certificates.</p> |
| <p>Issue IDs: 144868</p> <p>Issue summary: Controller nodes with full internal boot drives cause <code>sysmgr</code> to not start if controller nodes are restarted in that state.</p> <p>Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000</p> <p>Affected software versions: 3.1.2, 3.1.3, 3.2.1, 3.2.2</p> <p>Issue description: A full internal boot drive file system on a controller node will cause <code>sysmgr</code> and other system services to not start.</p> <p>Symptoms: While starting an online upgrade, system manager does not restart.</p> <p>Conditions of occurrence: The root file system of a node drive has run out of space.</p> <p>Impact: Medium</p> <p>Customer circumvention: None</p> <p>Customer recovery steps: None</p> |
| <p>Issue IDs: 146146</p> <p>Issue summary: An unhelpful message is displayed when an attempt to add more File Persona (FP) nodes to a system with FP installed in some nodes but not in a running state.</p> |

Table Continued

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.3.1

Issue description: Addition of more File Persona (FP) nodes requires FP to be running on nodes which have it already configured. The error message displayed when FP on those nodes is in a shutoff state was unhelpful and provided no guidance as to the reason for this. The error message produced when adding new nodes to an existing FP cluster which are not running has been updated to: "File Persona is installed on nodes x,y but not running. To configure additional nodes run the command: `startfs -enable`."

Symptoms: `startfs` used to add new nodes to the File Persona configuration yields the message "File Persona must be running to allow additional nodes to be configured."

Conditions of occurrence: File Persona is installed but not running and an attempt is made to add FP on more nodes.

Impact: Low

Customer circumvention: Check that FP is running on all nodes it has previously been installed onto before attempting to install FP on more nodes. Run the command `showfs` to display the FP status.

Customer recovery steps:

1. Run `showfs` to determine that FP nodes are not in a running state.
2. Run `startfs -enable` to start any nodes which are currently not running.

Issue IDs: 146489, 146490

Issue summary: Change to SSH ciphers to align with industry best practices for security and network integrity.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: SSH clients used prior to 3.3.1.GA

Table Continued

Issue description: SSH Client update may be necessary! SSH Ciphers have a been changed; only the following ciphers groups are now supported.

Supported Ciphers

- **KexAlgorithms:** diffie-hellman-group-exchange-sha256
- **Ciphers:** chacha20-poly1305@openssh.com, aes256gcm@openssh.com, aes128-gcm@openssh.com, aes256-ctr, aes192-ctr, **and** aes128-ctr.
- **MACs:** hmac-sha2-512-etm@openssh.com, hmac-sha2-256-etm@openssh.com, hmac-ripemd160-etm@openssh.com, umac-128-etm@openssh.com, hmac-sha2-512, hmac-sha2-256, hmac-ripemd160, **and** umac-128@openssh.com.

Previously supported Ciphers

- **KexAlgorithms:** curve25519-sha256@libssh.org, ecdh-sha2-nistp256, ecdh-sha2-nistp384, ecdh-sha2-nistp521, diffie-hellman-group-exchange-sha256, diffie-hellman-group-exchange-sha1, diffie-hellman-group14-sha1, diffie-hellman-group1-sha1
- **Ciphers:** aes192-ctr, aes256-ctr, aes128-ctr, aes192-cbc, aes256-cbc, aes128-cbc, 3des-cbc
- **MACs:** hmac-sha1 **and** hmac-sha1-96

Customers using the OpenBSD SSH client can examine their supported ciphers to determine compatibility by examining `man 5 ssh_config`. There must be at least 1 Cipher in common in each three Cipher groups for the client to be compatible with HPE 3PAR OS.

Symptoms: SSH access to the array may be impacted when using clients which were used with prior versions of HPE 3PAR OS.

Conditions of occurrence: Updating to 3.3.1GA or later and attempting to use an older SSH cypher.

Impact: High

Customer circumvention: None

Customer recovery steps: SSH Client update or configuration.

Issue IDs: 146805

Issue summary: In a Remote Copy configuration, when a full sync on the primary array is stopped before it completes and a promotion happens on secondary array, subsequent resync could cause data inconsistency. This issue only applies to periodic group.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: Detected in 3.2.1 and 3.2.2; fixed in 3.3.1

Issue description: When full sync on primary array is stopped before it completes, a promotion occurs on secondary array to overwrite the base volume. As a result of the promotion, data between primary and secondary became inconsistent. A subsequent resync continues from the point where the previous full sync left off leading to miscompare. This issue only applies to periodic group.

Symptoms: There is data inconsistency on the remote copy target volumes.

Table Continued

Conditions of occurrence:

1. Full sync on primary is stopped before it completes.
2. A promotion automatically occurs on the secondary array to overwrite the base volume.
3. A subsequent resync is started on primary array.

Impact: Low

Customer circumvention: To prevent getting this issue, make sure arrays do not run out of space within the CPG. You can set the snapshot space allocation warning and user space allocation warning using the `setvv` command.

Customer recovery steps: Do another full sync to recover.

Issue IDs: 146991

Issue summary: CPG alerts in `showcpvg` output may not automatically clear.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.1.3, 3.2.1, 3.2.2

Issue description: Prior to 3.3.1, the CPG Alerts fields in `showcpvg` output may indicate an alert is set after the underlying condition has been resolved.

Symptoms: Response from CLI `showcpvg -alert` may indicate a W/F/L alert is set ('Y') after the associated condition and alert have been cleared.

Conditions of occurrence:

- A CPG Grow operation which triggers a Warning, Fail or Limit alert.
- The condition which caused the alert is resolved.
- The corresponding alert (W/F/L) indicator to remain set ('Y') after the associated condition was resolved.

Impact: Low

Customer circumvention: Issue is resolved in 3.3.1

Customer recovery steps: The user can correct the display by issuing a redundant `setcpvg` command to the affected CPG. For example, if the current CPG occupancy percentage warning is 50%, then issuing a CLI `setcpvg -aw 50` to the affected CPG will clear the condition.

Issue IDs: 153893

Issue summary: `movetodomain` may cause the system manager to restart (recursive thread stack overflow).

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.2.1, 3.2.2

Table Continued

Issue description: Using `movetodomain` with a very complex web of related VVs, LDs, CPGs, sets, RC groups and hosts may be unsuccessful. Recursion is no longer used to discover the complete list of objects that have to be moved to the new domain.

Symptoms: `movetodomain` may not succeed on complex web of objects, and you may receive the following message: "Eagle IPC transport error: EA_PROCESS_DOWN --Message canceled because of process down."

Conditions of occurrence: Using the CLI command `movetodomain` to operate on a large number of objects that are related.

Impact: High

Customer circumvention: Plan ahead and set up virtual domains before creating several hundred hosts, VVs, CPGs, sets, and RC groups.

Customer recovery steps: None

Issue IDs: 156155

Issue summary: Array becomes unresponsive if the system manager restarts while region moves are in progress.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.2.2

Issue description: In extreme cases where multiple very large conversions are happening at once when the system manager restarts, then processing a lot of mirroring regions causes the system manager to become unresponsive.

Symptoms: Longer system manager restart times when system manager restarts in the middle of region movement on very large VVs.

Conditions of occurrence: The system manager is restarted while moving regions on large VVs. System manager has to restart.

Impact: Low

Customer circumvention: None

Customer recovery steps: Wait for system manager to complete its restart.

Issue IDs: 158195

Issue summary: User is unable to remove a Virtual Volume using `removevv`.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.2.2

Table Continued

Issue description: A scenario was created where the admin space was marked to be dropped and not able to be removed. Once this happened, the `removevv` command refused to remove the VV it thought was in the middle of having its admin space dropped.

Symptoms: A VV cannot be removed and returns the message: "Cannot remove volume as the entire snapshot tree is being removed."

Conditions of occurrence: An unexpected system manager or controller node restart when removing an entire VV tree using admin drop (normal removes don't use this).

Impact: Low

Customer circumvention: Do not perform controller node reboots while running `removevv`. Avoid operations known to restart the system manager while running `removevv`, such as installing a patch that contains the system manager component.

Customer recovery steps: None

Issue IDs: 159520

Issue summary: A VV block can occur every second when a large number of VV conversions are in progress, which can lead to host I/O stalling.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.1.2, 3.1.3, 3.2.1, 3.2.2

Issue description: A condition exists on the array that is preventing the VV blocking mechanism to work as designed while converting multiple VVs. This generally leads to the VV conversion failing.

Symptoms: Host I/O appears to be stalled while VV conversions are in progress.

Conditions of occurrence: Something prevents blocks attempting to convert more than 30 VVs simultaneously.

Impact: Low

Customer circumvention: Don't convert more than 30 VVs at once.

Customer recovery steps: None

Issue IDs: 160406

Issue summary: Host I/O stalls after attempting volume removal.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: All versions since 3PAR OS 3.2.1 MU3 Patch 38

Issue description: System resources attempt to access the same internal system locks multiple times with different requests in between the duplicate lock requests that results in a deadlock which results in the array's inability to share data.

Table Continued

Symptoms: The array becomes unresponsive and requires restart.

Conditions of occurrence: It is a timing issue. Theoretically, issuing a `freespace` command at the same time as removing a VV which had data on it could cause the issue. Because it's a timing issue, the probability to encounter the issue is low.

Impact: High

Customer circumvention: Do not run `freespace` while there is a volume removal in process.

Customer recovery steps: None

Issue IDs: 169491

Issue summary: `srdataac` log file grows too large because the system does not rotate the log file.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.2.2 MU2

Issue description: When the `srdataac` log file has no limit on the log file size, which leads to excessive use of space on the node disk for this log file.

Symptoms: Excess space on the node disk being used by the `srdataac` log file.

Conditions of occurrence: Excessive writing to `srdataac` log file when System Reporter is experiencing startup issues.

Impact: Medium

Customer circumvention: None

Customer recovery steps: None

Issue IDs: 178014

Issue summary: Adaptive Optimization (AO) does not complete data region moves because a memory buffer cannot be allocated..

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.1.2, 3.1.3, 3.2.1, 3.2.2

Issue description: Inability to allocate a memory buffer in one individual LD can cause 64 LDs to fail region statistic collection, resulting in inability to run Adaptive Optimization accurately against a significant number of LDs.

Symptoms: AO does not move data between tiers as expected.

Conditions of occurrence: The only indication that the buffer allocation will adversely affect AO is seen in the `/var/log/tpd/aomover` log file: "Error in getstatldrg ... LD XYZ region stats not active".

Table Continued

Impact: Low

Customer circumvention: None

Customer recovery steps: Use customer circumvention steps.

Issue IDs: 180117

Issue summary: Reduced RAID protection after recovery from replaced or unavailable drive.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.2.1 MU5 P53, 3.3.1

Issue description: When a drive will be replaced, the RAID system relocates data away from that drive in order to preserve the desired RAID protection. After the drive has been replaced, the RAID system will migrate back to the new drive to maintain the balanced I/O load. In certain circumstances, it is possible that the RAID protection will be degraded as a result of the migration back.

Symptoms: Reduced RAID availability seen in `showld -d`.

Conditions of occurrence: An unavailable or replaced drive that contains user data.

Impact: Medium

Customer circumvention: None

Customer recovery steps: Manually move the affected data regions to spares, which will pick the best RAID level available.

Issue IDs: 181090

Issue summary: In rare cases it was possible for any System Reporter (SR) cli command (or SSMC SR report) with the `-compareby` option to return an incomplete set of results.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.2.1, 3.2.2

Issue description: System Reporter requests with the `-compareby` option always included a defined number of objects for which to return data. Because of an error in the query logic, it was possible for a reduced number of objects to be included in the final results.

Symptoms: System Reporter (SR) CLI command (or SSMC SR report) with the `-compareby` option return an incomplete set of results.

Conditions of occurrence: Run SR where the range of time specified (`-btsecs` and `-etsecs`) for SR spans the internal SR database files. The user cannot easily determine if the SR DB files are spanned.

Impact: Low

Table Continued

Customer circumvention: In order to completely avoid the problem it is necessary to avoid using the `-compareby` functionality. The likelihood of encountering the problem of a reduced data set can be greatly reduced by requesting data in smaller time windows (`-btsecs` to `-etsecs`), and making use of more granular data (hourly or daily) as appropriate for longer time windows.

Customer recovery steps: None

Issue IDs: 183278

Issue summary: Event log is flooded with internal connection messages.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.2.2

Issue description: An "infinite" loop in `srdataac` causes it to send CLI commands continuously, which causes an event for each iteration.

Symptoms: An excessive number of events, about one every second, similar to: "Debug Informational CLI server process event sw_cli User logged in Id:516 User:3parsvc Level:super Addr:127.0.0.1 (client local) app:CLI"

Conditions of occurrence: Occurs when a single controller node which is not the System Reporter owner node is restarted.

Impact: Low

Customer circumvention:

Re-starting the System Reporter processes can temporarily stop the flood of events:

```
cli stopsr -f
cli startsr -f
```

Customer recovery steps: None

Issue IDs: 184670

Issue summary: On four and eight node systems, an unexpected array restart closely following an unexpected controller node down can prohibit cluster integration.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.2.1, 3.2.2

Issue description: First, there is a single controller node outage event. Following this event, during node rejoin, there is another unexpected event, such as a power loss. When the array is restarting, another controller node experiences a resource contention it can't handle because of the dual unexpected event. This small timing window and sequence of events has been resolved. This can only occur on systems with four or more nodes.

Symptoms: The array will restart three times.

Table Continued

Conditions of occurrence:

1. A controller node goes down.
2. The array unexpectedly restarts while the node in step #1 was coming back online.
3. When the entire array restarts from #2, another controller node, not the same controller node in step #1 is not able to completely recover due to resource contention. When this specific scenario occurs, the array restarts three times to clear the conditions to come back online.

Impact: High

Customer circumvention: None

Customer recovery steps: None

Issue IDs: 185414

Issue summary: `showcase -d` lacked an enclosure overall state field.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.2.2

Issue description: Because `showcase -d` was lacking an enclosure overall state field, the enclosure status obtained through other software, like SSMC, would not have an equivalent counterpart in `showcase cli`. Conditions like a missing IO card connection or an outdated firmware would cause SSMC to show a "degraded" enclosure overall state, while in `showcase -d` there will be no equivalent 'degraded' state.

Symptoms: SSMC displays a "degraded" overall status for the enclosure but there's no equivalent "degraded" status in `showcase -d`.

Conditions of occurrence: Having an enclosure that has a missing I/O card connection or an outdated firmware.

Impact: Medium

Customer circumvention: None

Customer recovery steps: None

Issue IDs: 189474

Issue summary: Unbalanced performance with a disproportionate mixture of merge cache buckets for 100k and 150k SSDs.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.2.1 MU5

Table Continued

Issue description: On a storage array with both SSD 100 and SSD 150 drives, where there are a lot more of one drive type than another, hosts may see much larger I/O latencies for I/O targeted to the smaller population of drives.

Symptoms: Long I/O latencies for the host only when using the smaller pool of SSD.

Conditions of occurrence: A large number of SSD 100/SSD 150 and a small number of the other. There is also a significant IOPs host load.

Impact: Medium

Customer circumvention: Install the drive types in a balanced setup, or do not mix drive types.

Customer recovery steps: Until the system is balanced, relocate data away from the drive type with fewer drives.

Issue IDs: 191018

Issue summary: Physical VV copy takes a long time copying to a VV that is a much larger size.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.1.2, 3.1.3, 3.2.1, 3.2.2

Issue description: In order to finish a VV copy to a larger destination VV, the difference in size needs to be zeroed in order to ensure that the volumes are equal. This zeroing can add significant time. The issue is improved by adding logic to detect that the destination VV is completely empty and therefore does not need to have any zero writes applied.

Symptoms: Physical copy takes longer than expected.

Conditions of occurrence: Physical copy from a source VV to another VV of significantly larger size.

Impact: Low

Customer circumvention: A faster option can be to size the destination VV the same as the source VV then, after the copy is complete, grow the destination VV to its desired final size.

Customer recovery steps: None

Issue IDs: 203495/201975

Issue summary: Defrag IO logs is not well handled in node down recovery.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.3.1.215

Issue description: When defrag is IO running and a node down happens, the logs for defrag IO are not handled. When another IO comes to the same offset after recovery, it will cause another node down due to the unhandled log. The result is the recovery node will reboot or the cluster down.

Table Continued

Symptoms: Unexpected node restart or cluster down after a node down.

Conditions of occurrence: Node down happens during defrag IO and logs from defrag are left over.

Impact: Medium

Customer circumvention: Install P01.

Customer recovery steps: After one more node down, it will be automatically recovered.

Known Issues with the OS

Issue IDs: 94331

Issue summary: The Management Console Volume Raw Space pie chart on the Physical Disks Summary tab incorrectly displays value on StoreServ with Adaptive Optimization software active.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions:

Issue description: The Volume Raw Space pie chart on the Physical Disks Summary tab incorrectly displays value for the selected device type on a StoreServ with Adaptive Optimization software active. This is due to the Management Console just adding up the virtual size of the virtual volume initially created from a Common Provisioning Group with the selected device type. With Adaptive Optimization software active, some of the virtual volume's regions might have been moved to another tier, and this needs to be taken into account when calculating the raw space for this pie chart.

Symptoms: The Management Console Volume Raw Space pie chart on the Physical Disks Summary tab incorrectly displays value.

Conditions of occurrence: Occurs when Adaptive Optimization is active.

Impact: Low

Customer circumvention: None

Customer recovery steps: None

Issue IDs: 112187

Issue summary: The `startfs` commands does not complete and time outs without configuring the File Persona cluster.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.2.2.GA-3.2.2.MU4, 3.3.1.GA

Issue description: In rare circumstances, `startfs n:sp n:sp....` may not complete after displaying the message "Executing `createfsvm fs_cpg`." This will be accompanied by an alert indicating that the `createfsvm` task has failed.

Table Continued

Symptoms: The `startfs` command hangs does not complete the tasks to create the File Persona configuration on one or more node does not complete.

Conditions of occurrence: Normal operation

Impact: Medium

Customer circumvention: The `startfs` command should be rerun after the previous invocation of the `startfs` command, including the tasks started by it, and any configuration created is automatically rolled back.

Customer recovery steps: Rerun the `startfs` command after the rollback recovery is complete.

Issue IDs: 131710

Issue summary: SR commands can return errors.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.1.1.*, 3.1.2.*, 3.2.1.*, 3.2.2.GA-3.2.2.MU4, 3.3.1.GA

Issue description: SR command can return a message if it internally requires large amounts of data.

Symptoms: SR commands return an "EA_PROCESS down" message.

Conditions of occurrence: Send an SR command that reads large amounts of data internally.

Impact: Medium

Customer circumvention: Do not use SR commands if seen.

Customer recovery steps: None. The system automatically recovers.

Issue IDs: 133562

Issue summary: iSCSI IO latency spikes

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.2.1.GA - 3.2.1.MU5, 3.2.2.GA - 3.2.2.MU2

Issue description: iSCSI IO latency spikes as the IO requests and transfers would stall for up to 30 seconds before getting a response.

Symptoms: IO requests and transfers would stall for up to 30 seconds before getting a response.

Conditions of occurrence: The driver was using an interrupt mask that would cause an interrupt to be missed causing the IO delay by up to 30 seconds, depending on the next NOP_In/Out occurrence..

Impact: Low

Table Continued

Customer circumvention: Work around can be applied for reducing the heartbeat_interval to 1 to cause the iSCSI NOP_IN to occur every second:

```
tcli -e "kvar set -n iscsi_heartbeat_misses -v 120"
```

```
tcli -e "kvar set -n iscsi_heartbeat_interval -v 1"
```

Customer recovery steps: The system would recover from the IO pause on its own within the heartbeat time interval which is 30 seconds by default.

Issue IDs: 160232

Issue summary: Volumes with TPGID in range 3 to 256 are not allowed to join RC group.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.1.3 MU3, 3.2.2 MU3 - 3.2.2 MU4, 3.3.1

Issue description: When volumes are migrated from other arrays using Online Import Utility (OIU), it is possible for its TPGID to be in the range 3 to 256. When we try to add these volumes to Remote Copy group, it will produce the message "tpgid <tpgid vlaue> does not match with group <group name>'s tpgid <257/258>". Volumes with TPGID 0, 1 or 2 do not have this issue.

Symptoms: Volumes cannot be added to Remote Copy group.

Conditions of occurrence: Adding volume with TPGID in the range 3 to 256 to an RC group.

Impact: Medium

Customer circumvention: None

Customer recovery steps: Change the TPGID of the volume to 1 or 2 using command `setvv -settpgid <1/2> <vvname>`. After changing the TPGID, it can be added to RC group.

Issue IDs: 165063

Issue summary: Online conversions, online copy, online promote, `updatevv`, and imports have long I/O stall times on 20000 systems.

Affected platforms: StoreServ 20000

Affected software versions: 3.2.2.GA - 3.2.2.MU4, 3.3.1.GA

Issue description: Online conversions, online copy, online promote, `updatevv`, and imports have long I/O stall times on StoreServ 20000 systems due to internal structure invalidation.

Symptoms: Long I/O stall times during online conversions, online copy, online promote, `updatevv`, and imports.

Table Continued

Conditions of occurrence:

- Have a StoreServ 20000 system
- Start an online conversions, online copy, online promote, `updatevv`, or import
- See a long I/O stall time

Impact: High

Customer circumvention: Avoid online conversions, online copy, online promote, `updatevv`, and imports on StoreServ 20000 systems.

Customer recovery steps: The hosts will time out. Use standard recovery for host timeouts.

Issue IDs: 187897

Issue summary: Disk enclosures report a power control module (PCM) inlet temperature sensor reporting a "non_critical/under_warning" falsely implying that the inlet temperature is too cold.

Affected platforms: StoreServ 7000, StoreServ 8000

Affected software versions: 3.3.1

Issue description: Array logging event/alert: "non_critical/under_warning" for drive cage FW enclosure PCM0 or PCM1 inlet sensor.

Symptoms: Array logging event/alert: "non_critical/under_warning" for drive cage FW enclosure PCM0 or PCM1 inlet sensor.

Conditions of occurrence: Drive cage FW 406a or prior and cold data centers (< 10 degrees Celsius)

- System running drive cage FW version 406a on cage models DCN1, DCS1, DCS2, DCN2, DCS7, DCS8.
- Inlet temperature low enough to confuse drive cage FW into interpreting PCM0/1 inlet temp as below low temp threshold.

Impact: High

Customer circumvention: Ignore event. The event/alert is misleading, but low temperature threshold violations do not trigger any array recovery behavior that would cascade into an outage or data loss.

Customer recovery steps: None

Issue IDs: 192368

Issue summary: `cachesvr` process memory consumption may cause other processes to stop.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.2.1.GA - 3.2.1.MU3, 3.2.2.GA - 3.2.2.MU3

Table Continued

Issue description: Over time the `cachesvr` process on the cluster master node may exhaust free memory, causing other user processes to halt. When this occurs, the affected process will restart and may continue to halt until the `cachesvr` process is restarted. Once the `cachesvr` process is restarted, its memory utilization is reset and the problem will not occur for some time, based upon system configuration and management activities performed.

Symptoms: `cachesvr` process memory size grows over time and causes other process to halt with the message "Unable to allocate xxxxxxxx bytes."

Conditions of occurrence: The issue is most likely to occur on systems which have large configurations and which execute frequent array management interactions.

Impact: Medium

Customer circumvention: None

Customer recovery steps: None

Issue IDs: 193758

Issue summary: Large number of `updatevv` operations could lead to rare and unexpected IO stalls.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 322GA-322MU4, 3.3.1

Issue description: A large number of `updatevv` operations could lead to rare and unexpected IO stalls.

Symptoms: IO stalls could be encountered on StoreServ which goes through frequent and large number of `updatevv` operations.

Conditions of occurrence: Frequent and intense `updatevv` operations on snapshot volumes.

Impact: Medium

Customer circumvention: Reduce the frequency of events leading to intense `updatevv` operations.

Customer recovery steps: None

Issue IDs: 193846

Issue summary: `tunesys` does not apply the `-fulldiskpct` or `-chunkpct` options to the intra-node phase when active-active PDs are present.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.3.1.GA (all PDs)

Table Continued

Issue description: An issue has been found with `tunesys` when custom values for `-fulldiskpct` or `-chunkpct` are supplied to control the chunklet movement phase and LD re-layout phases of the intra-node tuning, respectively. This affects all drive types.

Symptoms: `-fulldiskpct` and `-chunkpct` are used to customize intra-node re-balancing. When these options are used, expected tunes are not generated.

Conditions of occurrence: `tunesys -fulldiskpct <value> -chunkpct <value>` does not generate expected intra-node tunes.

Impact: Low

Customer circumvention: None

Customer recovery steps: Run manual intra-node tunes in consultation with HPE support.

Issue IDs: 196124

Issue summary: The CLI command `startfs -enable` does not complete due to the number of `rsh` connections open exceeding the allowed limit.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.3.1 GA

Issue description: A configuration with a large number of FPGs (>32 on an 8 node, >64 on a 4 node) causes the CPG to run out of space, the ensuing intentional deactivation of affected FPGs may cause subsequent `startfs enable` commands not to work.

Symptoms: The `startfs -enable` command failed with error " Failed to get bridge list: Could not run {/sbin/brctl show} on node0: node0: Connection refused."

Conditions of occurrence: A large number of FPGs > 32 on 8 node, > 64 on 4 node; the CPG containing the FPGs is full and File Persona has shut down the FPGs; or `startfs -enable` is run.

Impact: High

Customer circumvention: Ensure the CPG which has the FPGs never runs out of space.

Customer recovery steps: None

Issue IDs: 196633

Issue summary: `setcpg` can default the RAID type of SD space to RAID 6.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.3.1.GA

Table Continued

Issue description: An issue has been reported with the CLI `setcpg` command if no RAID type is explicitly defined in the new option list. In this case the existing RAID type will be removed from the list of stored options, and the CPG will silently inherit the system default of RAID 6. This applies to all `devtypes` (SSD,FC,NL).

Symptoms: After `setcpg` is used to update the CPG creation options customers may experience any or all of the following:

- VV Creation or growth failures
- Snapspace growth failures resulting in stale snapshots

Conditions of occurrence: This will only happen on systems where it is not possible to create RAID 6 `setsize 8` sets with cage availability (e.g. where RAID 5 or RAID 1 was configured previously).

Impact: Medium

Customer circumvention: Always explicitly specify ALL options when `setcpg` is used from the CLI. (This issue does not affect changing the CPG settings via the SSMC.)

Customer recovery steps: Use `setcpg` to refresh the CPG creation options to include all relevant parameters; in particular this should include the RAID type, set size, device type and availability.

Issue IDs: 196758

Issue summary: The `tunevv` command may unexpectedly not work or change a volume to the default RAID 6 `setsize 8` if the target CPG has an undefined RAID type.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.3.1.GA

Issue description: An issue has been reported with the `tunevv` command where, if the target CPG has no RAID type defined, the tune may either not work or change the volume to RAID 6 `setsize 8` unexpectedly. (Note that the `tunesys` command will warn the user and will not rebalance any volumes where any associated CPG does not have a defined RAID type. This check is missing from the `tunevv` command.)

Symptoms: If the target CPG has no defined RAID type the following may occur:

- The tune may fail if the system does not have resource to create tune destination LDs with RAID 6 `setsize 8`, cage availability.
- The tune will succeed but will modify the volume to be the new system default RAID type of RAID 6.

Conditions of occurrence: This may occur if the target CPG of the tune has no configured RAID type.

Impact: Medium

Customer circumvention: Make sure that the target CPG of all tunes have a specified RAID type.

Customer recovery steps: Use `setcpg` to refresh the CPG creation options to include all relevant parameters; in particular this should include the RAID type, set size, device type and availability.

| |
|--|
| <p>Issue IDs: 199218</p> <p>Issue summary: Imports and <code>updatevv</code> have long host I/O stall times.</p> <p>Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000</p> <p>Affected software versions: 3.3.1.GA</p> <p>Issue description: Imports or <code>updatevv</code> with a large list of VVs will have long I/O stall times.</p> <p>Symptoms: Long host I/O stall time.</p> <p>Conditions of occurrence:</p> <ul style="list-style-type: none"> • Start an import or <code>updatevv</code> with a large list of VVs • Long host I/O stall time <p>Impact: High</p> <p>Customer circumvention: Avoid using imports or <code>updatevv</code> with a large list of VVs.</p> <p>Customer recovery steps: The hosts will time out. Use standard recovery for host timeouts.</p> |
| <p>Issue IDs: 199904/168180</p> <p>Issue summary: StoreServ controller node unexpectedly restarts while handling IO.</p> <p>Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000</p> <p>Affected software versions: 3.3.1</p> <p>Issue description: StoreServ controller node(s) unexpectedly restarts while handling host IO.</p> <p>Symptoms: Restart of StoreServ controller node.</p> <p>Conditions of occurrence: This is a corner case situation with blockless region moves happening. Region moves could be due to tuning, conversions.</p> <p>Impact: Medium</p> <p>Customer circumvention: Disable blockless region move with help from HPE support.</p> <p>Customer recovery steps: StoreServ self recovery as in the case of any situation needing a controller node restart.</p> |
| <p>Issue IDs: 200606</p> <p>Issue summary: <code>showvv -s</code> can display negative numbers for Used size for compressed volumes.</p> <p>Affected platforms: StoreServ 8000, StoreServ 10000, StoreServ 20000</p> <p>Affected software versions: 3.3.1</p> |

Table Continued

Issue description: The `showvv -s` command, used to show space information, can sometimes display a negative value for the one of the used size columns (Snp, Usr, Total) for compressed volumes.

Symptoms: An obviously incorrect and negative value in one or more of the used size columns for a compressed volume.

Conditions of occurrence: This is a transient and infrequent occurrence when running `showvv -s` on compressed volumes.

Impact: Low

Customer circumvention: The `HostWr` column will display an accurate value for the amount of data written to the volume.

Customer recovery steps: The condition will resolve itself as more data is written.

Issue IDs: 201039

Issue summary: Performance of existing File Persona workloads may decrease more than expected when adding block workloads leveraging deduplication and compression.

Affected platforms: StoreServ 7000c, StoreServ 8000, StoreServ 20000

Affected software versions: 3.2.2, 3.3.1

Issue description: Deduplication and compression are resource intensive operations, and as the IO load to volumes with these services increases, the performance of other volumes that may or may not be using these services can decrease significantly. This impact can include both internal volumes used by the File Persona feature set as part of a File Provisioning Group and volumes consumed by external hosts.

Symptoms: Symptoms: Lower than expected performance.

Conditions of occurrence: Introduction of block workloads leveraging deduplication and compression.

Impact: Medium

Customer circumvention: The load applied to volumes with deduplication and/or compression enabled may need to be controlled in order to manage the impact to other volumes. One way to control the impact from these services is via the use of the 3PAR Priority Optimization feature set. You can create and modify threshold limits including I/O per second, bandwidth and latency on the volumes leveraging deduplication and/or compression in order to reduce their impact on the performance of other volumes and services.

Customer recovery steps: Reduce the newly introduced workload and then implement the circumvention recommendations.

Issue IDs: 201182

Issue summary: Recovery of File Persona FPGs (File Provisioning Groups) with names longer than 12 characters may require additional time.

Table Continued

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.2.2, 3.3.1

Issue description: In the event that a File Persona FPG needs to be checked during a recovery, long FPG names will require support personnel to perform additional actions, potentially prolonging any outage.

Symptoms: Attempts by support personnel to perform an online check of the FPG does not work due to a long name.

Conditions of occurrence: FPGs with names greater than 12 characters exist; an FPG recovery check (`fsck`) is required.

Impact: Medium

Customer circumvention: Limit FPG names to 12 characters.

Customer recovery steps: None

Issue IDs: 203126

Issue summary: Express layout with a minimal configured system must use restricted set sizes.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.3.1.GA

Issue description: In order to provide RAID protection, the maximum set size of an LD must be restricted. Considering the number of PDs that match the LD specification (for example, `-ha`, `-p`, `-devtype`), the maximum set size for the LD must be no more than the number of PDs, less the fault tolerance.

Symptoms: A failed disk immediately leads to a degraded LD, and the RAID protection shown in the LD is not actually available.

Conditions of occurrence: An LD layout selecting PDs where the set size of the LD, plus the fault tolerance of the RAID type is less than the number of those PDs.

Impact: High

Customer circumvention: Ensure the set size is limited as described.

Customer recovery steps: Tune the LD onto a new LD that follows the limitation.

Issue IDs: 206190

Issue summary: When an HPE 3PAR Online Upgrade from a release prior to 3.3.1 GA or 3.3.1 EGA is performed while a Windows Cluster online migration is in progress, it can result in an unexpected restart of the array.

Table Continued

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.3.1 GA, 3.3.1 EGA

Issue description: Performing an HPE 3PAR Online Upgrade from a release prior to 3.3.1 GA or EGA while a Windows Cluster online migration is in progress can result in cyclic System Manager restarts and ultimately an unexpected array restart.

Symptoms: The Cluster Shared Volumes for the Windows Cluster will go offline.

The HPE 3PAR OS Online Upgrade does not complete.

Conditions of occurrence: Performing a Windows Cluster online migration.

Performing an HPE 3PAR OS Online Upgrade.

Impact: High

Customer circumvention: Allow Windows Cluster online migration to complete successfully before performing the HPE 3PAR OS Online Upgrade.

Customer recovery steps: Wait for the array to come back online, wait for Windows Cluster Shared Volumes to come back online, and then restart these applications.

By using StoreServ Management Console, resume the peer motion action. Allow the Windows Cluster online migration to complete successfully.

Once the migration is complete, perform the HPE 3PAR OS Online Upgrade.

Issue IDs: 206190

Issue summary: When an HPE 3PAR Online Upgrade from a release prior to 3.3.1 GA or 3.3.1 EGA is performed while a Windows Cluster online migration is in progress, it can result in an unexpected restart of the array.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.3.1 GA, 3.3.1 EGA

Issue description: Performing an HPE 3PAR Online Upgrade from a release prior to 3.3.1 GA or EGA while a Windows Cluster online migration is in progress can result in cyclic System Manager restarts and ultimately an unexpected array restart.

Symptoms: The Cluster Shared Volumes for the Windows Cluster will go offline.

The HPE 3PAR OS Online Upgrade does not complete.

Conditions of occurrence: Performing a Windows Cluster online migration.

Performing an HPE 3PAR OS Online Upgrade.

Impact: High

Table Continued

Customer circumvention: Allow Windows Cluster online migration to complete successfully before performing the HPE 3PAR OS Online Upgrade.

Customer recovery steps: Wait for the array to come back online, wait for Windows Cluster Shared Volumes to come back online, and then restart these applications.

By using StoreServ Management Console, resume the peer motion action. Allow the Windows Cluster online migration to complete successfully.

Once the migration is complete, perform the HPE 3PAR OS Online Upgrade.

Modifications to File Persona

Issues that have been addressed in this release.

| Issue ID | Summary | Description |
|----------|--|--|
| 67397 | A request to stop file services on a node may result in them restarting. | Infrequently, a request to stop file services on a node may result in the services restarting instead of going to a stopped state. |
| 68476 | Cannot change only the VLAN tag of a node IP address. | The VLAN tag for a node IP address could not be changed without first moving the IP address to a different subnet temporarily. |
| 76213 | Antivirus scanning impacts read/write performance for small files. | Small file performance was significantly degraded when antivirus support was enabled. |
| 76395 | Password expiration policy changed for local users requires reset before effective. | Password expiration policy for local users has changed to "never expires." In previous releases, the default required passwords to be changed for local users after 30 days. |
| 76846 | Renaming a parent directory when child directory is open with directory change notification causes SMB users to be disconnected from node. | All SMB users could be temporarily disconnected from a node if a parent directory was renamed while a child directory was open with a directory change notification. |
| 77559 | Local users and groups do not show up in Windows if Active Domain is missing in Provider Order. | Local users and groups could not be enumerated from a client if the system was joined to Active Directory, but Active Directory was not included in the provider stacking order. |
| 78078 | File Persona services become unavailable temporarily. | The management of File Persona services could periodically become unavailable for some time and then become available again on their own. |

Table Continued

| Issue ID | Summary | Description |
|----------|--|---|
| 80075 | Intermittent failure in scheduled snapshots/ snapshot reclamation. | The tracking of a snapshot space reclamation task would be interrupted and would require support assistance to recover. |
| 80897 | Share directory is not created when creating share using MMC. | Starting with 3.3.1 GA, to ensure proper behavior in conjunction with the cross protocol support added in the release, if a share is created through MMC, it is now expected that the user must: <ol style="list-style-type: none"> 1. Go through explorer. 2. Create the directory. 3. Share the directory once it is created. |
| 89743 | When a File Provisioning Group (FPG) has a large number of objects, FPG performance may be decreased. | When an FPG object count approaches the 250,000,000 threshold, FPG performance may be decreased as the object count increases. With HPE 3PAR OS 3.3.1, the following system alert (message code 0x0720001) has been added when this threshold has been reached: "FPG cc_fpg102 object count is approaching or has exceeded the maximum supported, 250000000. FPG performance may decrease as the object count increases." |
| 92322 | Only files and directories from the live view are included in the Files Used field displayed by the <code>showfpg -d</code> command. | The "Files" value in the <code>showfpg -d</code> output now includes snapshot versions of files and other internal metadata objects. |
| 92967 | SMB protocol access scenario leads to excessively high CPU usage. | Using a certain SMB protocol access scenario could lead to excessively high CPU usage (and lower performance.) |
| 93127 | Filename wild carding from CMD "DOS" does not work correctly on Windows Server 2012 R2. | Looking for files using a wildcard pattern containing multiple '.' characters from a Windows Server 2012 client resulted in unexpected response. |

Table Continued

| Issue ID | Summary | Description |
|----------|---|---|
| 94964 | Snapshot plugin sometimes fails with cannot get actor reference, and actor system is terminated. | File Store snapshot creation would fail with the message "cannot get actor reference. Actor system is terminated", and a restart of file services on the impacted node was required to recover. |
| 95776 | The update record status is not handled properly after an unexpected restart of file services during the upgrade process. | Unexpected restart of file services during the upgrade process could leave the upgrade in a state where support intervention was required to complete the upgrade. |

Known Issues with File Persona

| Issue ID | Summary | Description | Corrective Action |
|----------|--|---|--|
| 74861 | <p>"Unknown error 528" error message on NFSv3 during <code>setfacl</code>.</p> <p>Unknown error 528 may be encountered when using Network File System (NFS) version 3 (NFSv3) to set file permissions using the <code>setfacl</code> utility or from access contention handling when accessing the file Access Control List (ACL).</p> | <p>Unknown error 528 may be encountered when using Network File System (NFS) version 3 (NFSv3) to set file permissions using the <code>setfacl</code> utility or from access contention handling when accessing the file Access Control List (ACL).</p> <p>This issue may occur in any NFSv3 implementation but is more likely to occur in a Lightweight Directory Access Protocol (LDAP) authenticated environment. Per NFSv3 specifications, clients should retry operations of this type, should the command fail. See section 4.5 in the NFSv3 specifications at: https://www.ietf.org/rfc/rfc1813.txt</p> | <p>To prevent this issue, user must either utilize a client that complies with the NFSv3 specification for retries, or do not use <code>setfacl</code> via script or utility that would allow multiple operations to occur in a short period of time.</p> <p>To recover from this issue, retry the failed operation. Several retries may be needed during periods of heavy <code>setfacl</code> call load.</p> |
| 75737 | Setting Access Control Entries via a UID/GID that cannot be resolved will fail. | Setting access control entry via UID or GID fails if ID cannot be properly resolved to user or group name. | Make sure the UID and GUID are added to the name server before trying to use them on a file or directory. |

Table Continued

| Issue ID | Summary | Description | Corrective Action |
|----------|---|---|--|
| 75911 | Metadata inconsistency reported on NFS I/O after failover event. | In some versions of NFS clients, on rare occasions while using V4 could result in file metadata inconsistencies during heavy I/O and failover. | Using the <code>noac</code> option during NFS mount would help address these situations of incorrect file attribute cache handling. But using the <code>noac</code> option will have a significant performance impact, and it is recommend to use it only for those applications which exhibit these issues. |
| 77773 | Avoiding name collisions when creating users and groups in AD. | When creating a user in AD, there are two name fields, one called "User logon name" and the other called "User logon name (pre-Windows 2000)." | To prevent possible name collisions and confusion with names stored in ACLs, the following is recommended: <ol style="list-style-type: none"> 1. Make sure that neither of the two name fields is the same as the name of any other user or group in the domain. 2. Set both of the two name fields to the same name when creating a user. |
| 79212 | Need better messaging (alert) when data is unavailable due to time sources being out of sync. | If the system is not configured for NTP before starting file services, and the system is joined to active directory, if the system time and active directory time are not in sync, some unexpected behaviors may occur. | It is important to configure NTP on the system before starting file services if you are planning to use Active Directory for authentication. |
| 82177 | Severe performance problems for file operations. | If files have UID values that cannot be mapped to a known user via one of the enabled authentication providers, accessing those files can result in higher than expected CPU utilization and lower performance. | Ensure that users can be mapped successfully to a name. |
| 83268 | Internal error: Mapping operation failed : 40,404 | This condition happens when the "ToName" user or group has been configured with a UID/GID value of less than 1. | Ensure that UID/GID values less than 1 are not used in the "ToName" user or group. |

Table Continued

| Issue ID | Summary | Description | Corrective Action |
|----------|--|--|--|
| 83635 | Creating SMB share on existing VFS using MMC, breaks share enumeration on the CLI. | Do not use Windows management tool MMC to create shares at the root of the VFS. Doing this will cause shares to stop enumerating. | To restore enumeration, remove the share using MMC. |
| 83701 | User can change permissions of C\$ share, but eventually fails with error. | Do not use Windows management commands to add ACEs to c\$ share. Attempting to change permissions at this top level will fail. | To get the permissions applied correctly, the command must be run at a lower level in the directory structure. |
| 86217 | Status of AD server in health is always 'Online' | The AD server connection health is not currently monitored. | The administrator of the Active Directory (AD) server can verify it is up and running. The cluster administrator can verify the AD host name is resolvable and pingable. |
| 88762 | Tight loop of HTTP requests or FTP requests creates large log on LDAP server. | When files are accessed frequently over FTP or Object Access API shares, there will be a high number of authentication requests to the LDAP server when using LDAP for authentication. If the log file is not managed on the LDAP server, then the file system of the LDAP server can be filled and cause the LDAP service to stop responding. | Make sure an appropriate log rotation policy is in place on the LDAP server when using it for authentication. |

Table Continued

| Issue ID | Summary | Description | Corrective Action |
|----------|--|--|---|
| 89456 | Excessive I/O load during multiple Roaming user logoff may cause sync issue. | <p>Excessive stress through creation of a huge I/O load across multiple roaming profile users (42 sessions) and then deletion followed by re-creation at the same time may have data sync issues observed for few of the files/folders during Logoff.</p> <p>The error following error message is displayed:</p> <p>"Windows cannot copy file <Local Windows path> to location <Share path>. This error may be caused by network problems or insufficient security rights. DETAIL - Access is denied."</p> | It is recommended to copy those files/folders specifically in such a scenario. |
| 91456 | Race condition during saves to SMB share using Notepad on nearly full FPG results in user data not being saved and no user error returned. | When using certain applications such as Notepad that do not honor indications of disk full during write requests (only during preallocation), and when writing to a nearly full FPG that consists of more than one VV, the application may indicate that data has been saved when in fact the disk was full. | Make sure to respond to the alerts indicating the FPG is 80% or 90% full and grow the FPG. |
| 92080 | Stopping Active management node immediately after cluster expansion can loose LDAP configuration. | After successfully starting file services on additional nodes and configuring networking for those newly added nodes, the existing LDAP configuration can take up to 10 minutes to get replicated to all the new nodes. If the currently active node (as shown by showfs) is stopped during this time, the LDAP configuration may be disabled. | If this occurs, the user will need to reconfigure the LDAP provider using <code>setfs</code> command. To avoid this issue, avoid stopping any node within 10 minutes of configuring additional nodes. |

Table Continued

| Issue ID | Summary | Description | Corrective Action |
|----------|---|--|---|
| 93279 | Spurious <code>monitor.startprocess.ok</code> event reported. | Occasionally, an event with the identifier <code>monitor.startprocess.ok</code> may be reported unexpectedly. | This event can be safely ignored. |
| 93701 | Unable to use the same name for local user and local group. | Same name for local group and user is not supported with AD. | Use LDAP as the name provider. |
| 94190 | Manual intervention may be required to reestablish connectivity if AD server connectivity is interrupted. | If connectivity to the Active Directory server is interrupted, manual intervention may be required to reestablish connectivity. | Connectivity can be reestablished by issuing the <code>stopfs</code> command followed by the <code>startfs -enable</code> command for any impacted node. Alternatively, support can be engaged to accurately diagnose the issue and recover without restarting the entire file services for the node. |
| 94267 | All snapshots fail when Snapshot component is not functional. Cannot get actor reference, and actor system is terminated. | When all snapshot operations fail with "Snapshot component is not functional. Cannot get actor reference", manual intervention may be required to reestablish snapshot capabilities. | Snapshot capabilities can be reestablished by issuing the <code>stopfs</code> command following by the <code>startfs -enable</code> command for any impacted node. Alternatively, support can be engaged to accurately diagnose the issue and recover without restarting the entire file services for the node. |
| 96847 | No snapshots listed even though snapshots exist.. | When there is a significant load of snapshot related activity, for example, several snapshot creation / deletion / reclamation jobs are run in parallel, sometimes <code>showfsnap</code> command returns "No snapshots listed." | Re-trying the same operation after some time when the load eases will be listed accordingly. If a create/delete snapshot operation failed with error "Futures timed out," internally the operation would have completed successfully, and can be validated using the <code>showfsnap</code> command. |

Table Continued

| Issue ID | Summary | Description | Corrective Action |
|----------|---|---|---|
| 97092 | With AD configured after LDAP in auth stack and with unreachable LDAP, server may cause status to reported as Starting. | <p>With LDAP configured before Active Directory in Auth stacking order, any AD user/group lookup requests will go through the LDAP provider first before sending it Active Directory.</p> <p>If LDAP is down/not-reachable, any AD user/group lookup requests becomes unresponsive, and the management interface and reporting of Starting state via <code>showfs</code> may be unresponsive.</p> | If this occurs, checking and repairing the health of LDAP provider should restore the ability to manage the system. |
| 97253 | Executing multiple <code>showfsquota</code> commands can cause system to respond slowly or cause subsequent commands to fail. | When LDAP server is unavailable (LDAP is configured), executing the <code>showfsquota</code> CLI command multiple times might cause the system to respond very slowly or fail the execution of subsequent commands. | An admin should ensure that the LDAP server is up and running. Admin is notified through system alerts when the LDAP server has gone down. |
| 97662 | Unable to rediscover VTLs after node reboot. | If a node is rebooted, VTL tapes associated with NDMP backup may no longer be seen. | <p>Perform the following steps to rediscover attached VTLs:</p> <ol style="list-style-type: none"> Execute following command on the HPE 3PAR CLI: <pre>showfsndmp -vtl vtldevices</pre> <p>It will list VTL device IPs similar to the following:</p> <pre>VtlDeviceIp 1.1.1.1 1.1.1.2</pre> Execute following command by providing all above IPs separated by commas: <pre>setfsndmp vtl +1.1.1.1,1.1.1.2</pre> <p>All VTLs will be rediscovered.</p> |

HPE 3PAR 3.3.1 CLI Release Notes

Installation Notes for the CLI

Deprecated Commands and Options

The deprecated options for the `cli`, `createuser`, and `setpassword` commands have been removed from the documentation.

Compatibility Changes in this Release

Remote CLI Client versions prior to 3.2.2 cannot connect to version 3.3.1 of the 3PAR OS without using the `-nosockssl` option.

NOTE:

The 3.3.1 Remote CLI Client is not backward compatible with 3.2.2 GA, 3.2.2 MU1, and releases prior to 3.2.1 MU5.

Compatibility changes in the next release

The following options will be removed:

`cli`: `-pwf`, `-user`, `-password`, and variable environment `TPDPWFILE`

`createuser`: `-e`

`setpassword`: `-save`, `-saveonly`, `-file`

Operating systems no longer supported:

- Red Hat Enterprise Linux 5 (RHEL 5)
- SUSE Linux Enterprise Server 10 (SLES 10)
- Ubuntu 12.04 LTS

Installation Directory

Default installation locations are new in 3PAR CLI 3.3.1:

- **Windows 32-bit:** `C:\Program Files\Hewlett Packard Enterprise\HPE 3PAR CLI`
- **Windows 64-bit:** `C:\Program Files (x86)\Hewlett Packard Enterprise\HPE 3PAR CLI`
- **UNIX and Linux:** `/opt/hpe_3par_cli`

In Windows, the Programs Menu has changed: Start->Programs->HPE 3PAR CLI->HPE 3PAR CLI <version>

Supported Operating Systems

For the list of supported operating systems, see the *3PAR CLI Remote Client* document on the SPOCK website at [**SPOCK**](#).

Support for the following additional operating systems is provided in this release:

- Red Hat Enterprise Linux 6 Update 7 (RHEL 6.7)
- Red Hat Enterprise Linux 6 Update 8 (RHEL 6.8)
- Red Hat Enterprise Linux 7 Update 2 (RHEL 7.2)
- Red Hat Enterprise Linux 7 Update 3 (RHEL 7.3)
- SUSE Linux Enterprise Server 12 (SLES 12)
- Ubuntu 16.04 LTS

- Windows 10 Enterprise
- Windows Server 2016

What's New in the CLI

A Linux Control group has been added to restrict memory used by CLI and `tpdtcl` processes running on the array. This limitation under severe low memory situations will improve overall system stability. Under severe memory pressure, the performance of the Remote CLI may be hindered and potentially cause CLI sessions to terminate. These include tasks and other programs invoked indirectly by the CLI or `tpdtcl` server.

New Commands

- `removefsarchive`
- `setfsarchive`
- `showfsarchive`
- `srstatiscsi`
- `srstatiscsisession`
- `srstatvv`
- `srsysspace`
- `startfsarchive`
- `stopfsarchive`

Changed Commands

| Command | Description |
|--------------------------------|---|
| <code>checkhealth</code> | New <code>-d</code> option |
| <code>checkvv</code> | New <code>-compr_dryrun</code> option |
| <code>controlsr</code> | New subcommands <code>setperiod</code> and <code>setretention</code> |
| <code>createfpg</code> | Max size 64 TiB |
| <code>createfshare</code> | New subcommand <code>ftp</code> |
| <code>createfststore</code> | New mandatory <code>-secmode</code> option |
| <code>creategroupsv</code> | New <code>-addtoiset</code> , <code>-match</code> option |
| <code>creategroupvvcopy</code> | New <code>-compr</code> and <code>-deupcompression</code> options |
| <code>createsched</code> | <code>importvv</code> now allowed, command limit 1023 bytes |
| <code>createsralertcrit</code> | Additional space categories, New <code>%_average</code> condition comparisons; Added <code>SYSSPACE</code> type |
| <code>createsv</code> | New <code>-addtoiset</code> option |

Table Continued

| Command | Description |
|-----------------|---|
| createvv | Added three new policies for host DIF support; extended <code>-f</code> option to skip DIF policy change warning message; Compression changes |
| growfpg | Max size 64 TiB |
| histpd | New <code>-devsvtime</code> option |
| importvv | New <code>-compr</code> and <code>-dedup</code> compression options |
| locatecage | Support locate commands on HPE 3PAR StoreServ 8000 Storage system |
| removedomain | Added <code>-pat</code> option |
| removedomainset | Added <code>-pat</code> option |
| removefshare | New subcommand <code>ftp</code> |
| removehost | Added <code>-pat</code> option |
| removehostset | Added <code>-pat</code> option |
| removevvset | Added <code>-pat</code> option |
| setfpg | New <code>-upgrade</code> option |
| setfs | New subcommand <code>usermap</code> |
| setfsav | New <code>-quar_file</code> ; SOPHOS added to <code>-vendor</code> |
| setfshare | New subcommand <code>ftp</code> |
| setfstore | New <code>-secop_errsuppress</code> and <code>-secmode</code> options |
| setrcopygroup | New policy <code>mt_pp</code> |
| setrcopytarget | New subcommand <code>autotunelinks</code> |
| setsralertcrit | Allows more changes, Merges SSD100 and SSD150 metrics |
| setsys | Added <code>OverprovRatioLimit</code> , <code>OverprovRatioWarning</code> , <code>allowR5OnFCDrives</code> , <code>DisableCompr</code> , <code>AllowWrtbackUpgrade</code> , and <code>AllowWrtbackSingleNode</code> |
| setvv | New policies: <code>3par_host_dif</code> , <code>std_host_dif</code> , <code>no_host_dif</code> |

Table Continued

| Command | Description |
|------------------|---|
| showcpg | New <code>-listcols</code> and <code>-showcols</code> , output format changes |
| showfs | New <code>-usermap</code> option |
| showfsarchive | New <code>-importfile</code> , <code>-export</code> options and subcommand <code>export</code> |
| showfshare | New subcommand <code>ftp</code> |
| showfstore | Output changes |
| showhost | Output changes for <code>-agent</code> |
| showiscsisession | New <code>-d</code> option |
| showld | New <code>-ck</code> option |
| shownode | New <code>-pci</code> type "combo" |
| showportdev | New <code>-d</code> option for subcommand <code>tzone</code> , new subcommand <code>uns</code> |
| showsys | New <code>-vvspace</code> option |
| showtask | Limit increased to 2000 |
| showuserconn | Output for <code>-d</code> lists memory |
| showvlun | New <code>-pathsum</code> columns |
| showvv | New <code>showvv -pol</code> output for host DIF settings; New compression output changes, changes to output of <code>showvv -s</code> and <code>showvv -d</code> |
| sr* | New <code>-compareby</code> option |
| srcpgspace | Compression output changes |
| srhistvlun | VVOL filtering |
| srrgiodensity | Added <code>-totpct</code> option |
| srstatvlun | New <code>-vlun</code> , VVOL filtering |
| srvvspace | VVOL filtering. Compression output changes. |

Table Continued

| Command | Description |
|---------|---|
| statpd | Added -devsvtime option |
| tunesys | New -force, -slsz, -slth, -compactmb, -cleanwait, -maxnodetasks and -ss |

Modifications to the CLI

| |
|---|
| <p>Issue IDs: 79971</p> <p>Issue summary: <code>checkhealth</code> doesn't detect degraded SFPs in converged network adapters (CNAs).</p> <p>Affected platforms: StoreServ 10000</p> <p>Affected software versions: 3.1.1 (MU2)</p> <p>Issue description: <code>checkhealth</code> doesn't detect degraded SFPs in converged network adapters (CNAs).</p> <p>Symptoms: None</p> <p>Conditions of occurrence: <code>checkhealth</code> doesn't detect degraded SFPs in converged network adapters (CNAs).</p> <p>Impact: Low</p> <p>Customer circumvention: None</p> <p>Customer recovery steps: None</p> |
| <p>Issue IDs: 126970</p> <p>Issue summary: New controller nodes that are connected and not yet powered on or admitted may go unreported by <code>checkhealth</code>. These controller nodes may prevent a successful upgrade.</p> <p>Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000</p> <p>Affected software versions: 3.1.1 (MU2)</p> <p>Issue description: New controller nodes that are connected and not yet powered on or admitted may go unreported by <code>checkhealth</code>. These controller nodes may prevent a successful upgrade.</p> <p>Symptoms: Upgrade stalls.</p> <p>Conditions of occurrence: A StoreServ with controller nodes not powered or not admitted to the cluster, but the cables are connected and the system is aware that something is plugged into those node slots.</p> <p>Impact: Medium</p> |

Table Continued

Customer circumvention: Avoid leaving new controller nodes in a state where they are cabled, but not admitted.

Customer recovery steps: Power on affected nodes and run the CLI command `admithw`.

Issue IDs: 136799

Issue summary: `checkhealth` should detect phantom connections due to a stall on a socket read.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.2.1 (MU3)

Issue description: The CLI `checkhealth` network should flag `tpdtcl` SSL sessions that do not finished authenticating within 5 minutes. These are presumed to be stalled

Symptoms: Login stalls with message, "Too many CLI connections."

Conditions of occurrence: CLI connection stall.

Impact: Medium

Customer circumvention: None

Customer recovery steps: Quit unresponsive CLI connection process.

Issue IDs: 138748

Issue summary: `checkhealth` does not provide a warning when the node time and `hwclock` (hardware clock) differ.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.2.1 (MU2)

Issue description: If the node time and `hwclock` differ, then `checkhealth` should log a corresponding error.

Symptoms: There is a time difference between the node time and `hwclock`.

Conditions of occurrence: There are no specific conditions for this issue to appear except for a notable time difference (more than 60 seconds) between the hardware clock and the node time.

Impact: Low

Customer circumvention: None

Customer recovery steps: `hwclock --systohc` forces the current software clock's time to match the hardware clock.

Issue IDs: 146487

Issue summary: TLS v1.0 and 1.1 have been disabled to align with industry best practices for security and network integrity.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: All TLS client software

Issue description: TLS v1.0 and 1.1 have been disabled to align with industry best practices for security and network integrity.

Symptoms: TLS clients which are configured for older TLS versions may no longer connect to the 3PAR array after the array is updated to 3.3.1.

Conditions of occurrence: Update to 3.3.1GA.

Impact: High

Customer circumvention: None

Customer recovery steps: Update, or reconfigure, affected TLS clients to use TLS 1.2.

Issue IDs: 152319

Issue summary: CLI on HP-UX stalls when /home is NFS mounted and the NFS server is not available.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.2.1, 3.2.2

Issue description: If /home is NFS mounted and NFS server is not available, Remote CLI client on HP-UX stalls.

Symptoms: Remote CLI client on HP-UX stalls.

Conditions of occurrence: /home is NFS mounted and NFS server is not available. Customer is trying to use the Remote CLI client. This issue is seen only on HP-UX.

Impact: High

Customer circumvention: Use SSH or 3.3.1 HPE 3PAR CLI Remote Client to connect the HPE StoreServ system. For a list of supported versions of each operating system, go to the Single Point of Connectivity Knowledge (SPOCK) for HPE Storage Products at <http://www.hpe.com/storage/spock>.

Customer recovery steps: This issue occurs because `ActiveTcl` is trying to access the `/home/andreask` directory, which most likely is not available in the customer setup. Creation of `/home/andreask` locally can mitigate this issue.

| |
|--|
| <p>Issue IDs: 155314</p> <p>Issue summary: Starting in 3.3.1, the HPE 3PAR CLI will have a new default certificate directory. This will cause previously accepted certificates to be ignored.</p> <p>Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000</p> <p>Affected software versions: 3.3.1</p> <p>Issue description: Starting in 3.3.1, the HPE 3PAR CLI will have a new default certificate directory.</p> <p>Old:</p> <p>Linux, HP-UX, Solaris and AIX: \$HOME/.hp3par</p> <p>Windows: %USERPROFILE%\hp3par</p> <p>New:</p> <p>Linux, HP-UX, Solaris and AIX: \$HOME/.hpe3par</p> <p>Windows: %USERPROFILE%\hpe3par</p> <p>If already using TPD CERTDIR environment variable or the <code>-certdir</code> option, no additional changes are needed.</p> <p>Symptoms: When attempting to connect using the 3.3.1 HPE 3PAR CLI, the authenticity of the storage system cannot be established. Any applications that sit on top of the CLI may not be expecting this new message/dialog and may fail.</p> <p>Conditions of occurrence: Use of the 3.3.1 HPE 3PAR CLI and not using the TPD CERTDIR environment variable or <code>-certdir</code> option.</p> <p>Impact: High</p> <p>Customer circumvention: Users of older HPE 3PAR CLI versions prior 3.3.1 will need to move/copy/link certificates located in the old directory to the new directory. A separate copy may be needed if using older versions of the CLI to communicate with older arrays with the same shared home directory. Copying the certificate files would be more convenient than accepting each existing certificate. As an alternative to copying the certificate files, the TPD CERTDIR environment variable or <code>-certdir</code> option can be used to point to the previous certificate directory being used.</p> <p>Customer recovery steps: None</p> |
| <p>Issue IDs: 159572</p> <p>Issue summary: CLI TLS Cipher Changes.</p> <p>Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000</p> <p>Affected software versions: All Prior to 3.3.1GA</p> <p>Issue description: Cli TLS Cipher Changes:</p> <p>Supported: AES128-SHA, AES256-SHA, DHE-RSA-AES128-SHA, DHE-RSA-AES256-SHA</p> <p>Previously Supported: DHE-RSA-AES256-GCM-SHA384, DHE-RSA-AES128-GCM-SHA256</p> |

Table Continued

Symptoms: CLI clients which are configured for prior HPE 3PAR OS versions may no longer connect to the HPE 3PAR StoreServ Storage system after the array is updated to 3.3.1.

Conditions of occurrence: The HPE 3PAR array is running 3.3.1 or later and a non-supported cypher is used.

Impact: High

Customer circumvention: None

Customer recovery steps: If connectivity issues occur, reconfigure the clients to use currently supported cipher from the above list.

Issue IDs: 167576

Issue summary: Array unexpectedly reconfigures Remote Copy Fibre Channel (RCFC) ports to host mode when executing `admithw`.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.2.2

Issue description: `admithw` reconfigures all Fibre Channel ports, including RC ports, that are in a "free" state to host connection mode.

Symptoms: A possible loss of RC ports used during HPE 3PAR OS or hardware upgrade when `admithw` is executed.

Conditions of occurrence: Having RC in use, but temporary free or disconnected, during `admithw` execution.

Impact: High

Customer circumvention: Guarantee that before executing `admithw`, all FC ports, including RC ports, are properly connected and not showing as `free` in `showport`.

Customer recovery steps: Reconfigure any incorrectly configured RC port back to Remote Copy mode.

Issue IDs: 179378

Issue summary: Users with edit or higher permissions are able to use `updatevv` on virtual volumes in their domains.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: All versions before 3.3.1

Table Continued

Issue description: Previously, a super-user would have to issue the command `setuseracl <username> updatevv <virtual volume name>` to allow a non-super user to utilize the `updatevv` command. This process is no longer required given the user is granted edit or higher permissions for the domains to which the virtual volumes belong. The user can then use `updatevv` without requiring a super-user issue the `setuseracl` command.

Symptoms: When a non-super user, issues the command `updatevv <virtual volume name>` the user will get a "permission denied" message, given the command `setuseracl` was not issued for them.

Conditions of occurrence: The user does not have edit or higher permissions for the domain to which the virtual volume belongs.

Impact: Low

Customer circumvention: None

Customer recovery steps: None

Issue IDs: 184028

Issue summary: WSAPI audit trail support: `tpdtcl` needs to put original request IP/port info in the `eventlog` and `showuserconn`.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.2.1, 3.2.2

Issue description: The event log now includes the remote IP and port of WSAPI sessions. This will also change the `showuserconn` output to include the port number *For example:* `100.100.100.100:port`. The port will also be included for CLI, SSMC, SSH and MC connections in both `eventlogs` and `showuserconn`.

Symptoms: WSAPI sessions always have an array local address of 127.0.0.1 or 127.127.0.1 to 127.127.0.8. Port info is missing for the IP addresses.

Conditions of occurrence: WSAPI connections always have local IP.

Impact: Medium

Customer circumvention: None

Customer recovery steps: None

Issue IDs: 186303

Issue summary: `checkhealth` does not cover a DDS or VVol `internal_consistency_error` issue.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Table Continued

Affected software versions: 3.2.1 (MU3)

Issue description: `checkhealth` VV missing checks

Symptoms: `checkhealth` addresses internal consistency errors for system volumes.

Conditions of occurrence: `checkhealth` addresses internal consistency errors for system volumes.

Impact: Medium

Customer circumvention: `checkhealth` addresses internal consistency errors for system volumes.

Customer recovery steps: None

HPE 3PAR CIM API Release Notes

What's New with the CIM API and SNMP Software

New and enhanced features include:

- CIM API
 - Support for compression.
 - Disabled SSL zlib compression to address the "CRIME" vulnerability.
 - HTTPS is now enabled by default while HTTP is disabled by default. This is only true for new systems: firmware upgrades will not change the existing configuration.
 - A new "SparePartNumber" property was added to the Alert Indication class to indicate the customer-orderable replacement part number for faulty components.
- SNMP
 - The 3PAR MIB has been updated with a cpuStatsMIB that contains CPU statistics for each Node in a StoreServ array.
 - SNMP Alerts now contain fields for event tier and spare part information. The spare part information is shown if it is available for hardware tier alerts.

Modifications to the 3PAR CIM API

| |
|---|
| Issue IDs: 145085 |
| Issue summary: A cimserver <code>IndicationSubscription</code> cannot be deleted. |
| Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000 |
| Affected software versions: 3.2.1, 3.2.2 |
| Issue description: <code>CIM_IndicationFilter</code> instances that exist only in the root/tpd but not interop namespace cannot be enumerated and deleted. |
| Symptoms: The cimserver API will return a NOT FOUND error when attempting to delete a <code>CIM_IndicationSubscription</code> . |
| Conditions of occurrence: <code>CIM_IndicationFilter</code> is created in root/tpd namespace only. |
| Impact: Low |
| Customer circumvention: None |
| Customer recovery steps: Create the exact same <code>CIM_IndicationFilter</code> in interop namespace also. |

| |
|--|
| Issue IDs: 161149 |
| Issue summary: Volumes created with <code>CreateStorageVolumeFromStoragePoolWithTemplate</code> do not use the snapshot CPG specified by the storage setting. |

Table Continued

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.2.2

Issue description: The snapshot CPG specified by the `TPD_StorageSetting` template is not configured for volumes created with the CIM API call

`CreateStorageVolumeFromStoragePoolWithTemplate`.

Symptoms: `CreateStorageVolumeFromStoragePoolWithTemplate` creates a storage volume without the snapshot CPG specified by the `SnapDSPName` property of the `TPD_StorageSetting` template instance.

Conditions of occurrence: Call the `CreateStorageVolumeFromStoragePoolWithTemplate` API function with a `TPD_StorageSetting` that has the property `SnapDSPName` specified with a valid CPG name.

Impact: Medium

Customer circumvention: None

Customer recovery steps: Stop and restart the cimserver by running the following CLI command:

```
setvv -snp_cpg <cpgName> <vvname>
```

Issue IDs: 192537

Issue summary: Frequent polling of cage status by applications using the CIM API may cause invalid events indicating a cage interface card failure when none has occurred.

Affected platforms: StoreServ 7000, StoreServ 20000

Affected software versions: 3.2.2

Issue description: Customers with applications issuing frequent CIM API requests for controller nodes, drive cage, power supply, battery, or magazine information observe erroneous events that indicate an interface card failure.

Symptoms: The event log will contain events indicating the failure and recovery of Interface cards even though no failure has occurred:

2016-11-29 13:35:45 CET 0 Major Component state change hw_cage:4,hw_cage_ifc:0 Cage 4, Interface Card 0 Failed

2016-11-29 13:36:16 CET 0 Informational Component state change hw_cage:4,hw_cage_ifc:0 Cage 4, Interface Card 0 Normal

Conditions of occurrence: The CIM API (CIM server) is enabled as shown by the `showcim` CLI command. A customer application such as "CA Unified Manager v8.4" is polling the CIM API for controller node, drive cage, power supply, battery or magazine information.

Impact: Medium

Customer circumvention: Disable the CIM API with the `stopcim` command.

Customer recovery steps: None

Web Services API Release Notes

What's New with the Web Services API Software

New and enhanced features include:

- Support for Compression
- Support for File Persona—Create/Update/Delete functions for VFSs, FPGs, file stores, file shares, quotas, snapshots, and directory permissions
- Improved API response time
- Audit trail for the Web Services API in the HPE 3PAR OS system event log
- Added a `uuid` field to volume set and host set objects
- Added `id`-based and `uuid`-based filtering for volume sets and host sets
- Added ability to query virtual copy objects, given a parent virtual volume
- Added ability to specify a volume set target during the creation of a virtual copy
- Added a list of patches installed on the system, accessible at URI `.../api/v1/system`
- Added detailed task message for single instance of GET tasks
- Returns `deviceName` as part of `portdevices` query
- Supports `hostDIF` volume policy
- Now supports the following System Parameters: `remoteSyslogSecurityHost`, `hostDIFTemplate`, `disableChunkletInitUNMAP`, `personaProfile`, `remoteCopyHostThrottling`, `AllowR5OnFCDrives`, and `AllowR5OnNLDrives`.
- Additions to Remote Copy functionality:
 - Pattern matching for queries of RC groups
 - Added an option (`allowRemoteCopyParent`) so promotion of a virtual copy can proceed even if the RW parent volume is currently in a Remote Copy volume group, if said group has not been started
 - Detailed information for remote copy links
- Additions to System Reporter (SR):
 - Added ability to query SR VLUN statistic data based on VLUN filters. The SR VLUN statistic data is limit to VLUNs that are matching the specified combination of `host`, `VV`, `LUN id` and `port`.
 - Added `privateSpaceMiB`, `sharedSpaceMiB`, `freeSpaceMiB`, and `totalSpaceMiB` fields to SR CPG space and CPG information.
 - Added `compression` and `hostWriteMiB` fields to SR volume space.
 - Added SR data for CPU
- Cluster Extension capabilities:
 - Embedded 3PAR Cluster Extension storage failover logic in 3PAR OS with access by 3PAR Web Services API.
 - Changed Cluster Extension Host software for Microsoft Windows to include Microsoft Windows Cluster integration logic only and to use 3PAR Web Services API to perform planned migration and disaster recovery for the Microsoft failover cluster integrated applications.

Modifications to the 3PAR Web Services API

Issue IDs: 160211

Issue summary: Intermittent `NON_EXISTENT_VOL` message reported by WSAPI after volume creation

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.2.2

Issue description: If a volume creation and volume query is done in quick successions via WSAPI, a message may be generated where WSAPI reports a `NON_EXISTENT_VOL` for the volume query request, even though the volume is successfully created. This has been resolved.

Symptoms: If a volume creation and volume query is done in quick successions via WSAPI.

Conditions of occurrence: WSAPI client issues a `POST /volumes` to create a volume and then `GET /volumes/<new volume name>` in quick succession.

Impact: Low

Customer circumvention: WSAPI client can wait a bit after a volume creation before issuing the GET request.

Customer recovery steps: None. The volume is actually created.

Issue IDs: 160385

Issue summary: ZLIB compression is enabled in WSAPI and is a known vulnerability in TLS1.x.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.1.3, 3.2.1, 3.2.2

Issue description: HTTP usage of ZLIB compression in TLS 1.x must be disabled to prevent exposure to the CRIME (Compression Ratio Information-leak Made Easy) security vulnerability.

Symptoms: TLS compression was enabled for WSAPI HTTPS connection, which could be vulnerable to CRIME, see CVE-2012-4929 TLS/CRIME.

Conditions of occurrence: WSAPI client communicates with WSAPI server over HTTPS (port 5989) with TLS compression enabled.

Impact: Low

Customer circumvention: WSAPI client can disable HTTPS TLS compression on its end.

Customer recovery steps: None

Issue IDs: 189113

Issue summary: WSAPI returns an error when System Reporter records exceed limit.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.2.2

Issue description: When System Reporter returns a large number of records, the error code returned by WSAPI is not clear and clients would not know how to fix the issue.

Symptoms: WSAPI request will return Error code 329 when System Reporter query results in a large number of records.

Conditions of occurrence: It can mostly occur while using `groupby`, and there are large number of objects on the system but not limited to this condition.

Impact: Medium

Customer circumvention: Reduce the scope of the request, such that the number of records are reduced.

Customer recovery steps: Retry the operation after reducing the scope of the request.

HPE 3PAR OS 3.3.1 EGA Release Notes

Online Upgrade Considerations

The HPE 3PAR OS can be upgraded concurrently with I/O activity on the attached hosts, provided certain conditions are met. For more information on planning for online upgrades, refer to the latest version of the *HPE 3PAR Operating System Upgrade Pre-Planning Guide*. For more information regarding the required order for upgrade and installation of software components, see the *HPE 3PAR OS 3.3.1 EGA Upgrade Instructions*. To obtain a copy of this documentation, go to the Hewlett Packard Enterprise Information Library.

Notes



WARNING:

3PAR Remote Copy asynchronous streaming configurations do not support compression. Do not use the asynchronous streaming replication mode with compressed volumes.



WARNING:

3PAR Deduplication and compression are resource intensive operations, and as loads increase to these volumes, File Persona volume performance can decrease significantly. The load applied to volumes with these services enabled may need to be controlled in order to manage the impact to other volumes specifically volumes used by File Persona feature set as part of a File Provisioning Group.

Supported Platforms

This HPE 3PAR OS release supports HPE 3PAR StoreServ Storage. For more information, see the HPE Single Point of Connectivity Knowledge (SPOCK) website:

<http://www.hpe.com/storage/spock>

The minimum Service Processor version that supports HPE 3PAR OS 3.3.1 EGA is Service Processor (SP) 5.0.0.0 + latest SP patch.

Affected components

| Component | Version |
|----------------|-----------------|
| OS | 3.3.1.215 |
| Patches | P01, P02 |
| CLI Server | 3.3.1.228 (P02) |
| CLI Client | 3.3.1.228 |
| System Manager | 3.3.1.228 (P02) |
| Kernel | 3.3.1.215 |

Table Continued

| Component | Version |
|-----------------------|-------------------------|
| TPD Kernel Code | 3.3.1.228 (P02) |
| TPD Kernel Patch | 3.3.1.228 (P02) |
| CIM Server | 3.3.1.215 |
| WSAPI Server | 3.3.1.215 |
| Console Menu | 3.3.1.215 |
| Event Manager | 3.3.1.215 |
| Internal Test Tools | 3.3.1.215 |
| LD Check Tools | 3.3.1.215 |
| Network Controller | 3.3.1.215 |
| Node Disk Scrubber | 3.3.1.215 |
| PD Scrubber | 3.3.1.215 |
| Per-Node Server | 3.3.1.228 (P02) |
| Persistent Repository | 3.3.1.215 |
| Powerfail Tools | 3.3.1.215 |
| Preserved Data Tools | 3.3.1.215 |
| Process Monitor | 3.3.1.215 |
| Software Updater | 3.3.1.228 (P02) |
| TOC Server | 3.3.1.228 (P02) |
| VV Check Scripts | 3.3.1.217 (P01) |
| Upgrade Check Scripts | 170330.U004 (3.3.1.215) |
| File Persona | 1.3.0.74-20170309 |
| SNMP Agent | 1.10.0 |
| SSH | 6.0p1-4+deb7u5 |
| VASA Provider | 3.0.12 |
| Firmware Database | 3.3.1.217 (P01) |

Table Continued

| Component | Version |
|----------------------------------|-------------|
| Drive Firmware | 3.3.1.215 |
| UEFI BIOS | 05.02.54 |
| MCU Firmware (OKI) | 4.8.60 |
| MCU Firmware (STM) | 5.3.17 |
| Cage Firmware (DC1) | 4.44 |
| Cage Firmware (DC2) | 2.64 |
| Cage Firmware (DC3) | 08 |
| Cage Firmware (DC4) | 2.64 |
| Cage Firmware (DCN1) | 4082 |
| Cage Firmware (DCN2) | 4082 |
| Cage Firmware (DCS1) | 4082 |
| Cage Firmware (DCS2) | 4082 |
| Cage Firmware (DCS5) | 2.78 |
| Cage Firmware (DCS6) | 2.78 |
| Cage Firmware (DCS7) | 4082 |
| Cage Firmware (DCS8) | 4082 |
| QLogic QLA4052C HBA Firmware | 03.00.01.77 |
| QLogic QLE8242 CNA Firmware | 04.15.27 |
| QLogic 260x HBA FC Firmware | 174.03.70 |
| QLogic 27xx/268x HBA FC Firmware | 174.03.70 |
| QLogic 83xx HBA FCoE Firmware | 08.01.05 |
| QLogic 8300 HBA iSCSI Firmware | 05.07.35 |
| Emulex LP11002 HBA Firmware | 02.82.x10 |
| Emulex LPe12002 HBA Firmware | 02.10.x02 |
| Emulex LPe12004 HBA Firmware | 02.10.x02 |

Table Continued

| Component | Version |
|------------------------------|------------|
| Emulex LPe16002 HBA Firmware | 11.1.220.6 |
| Emulex LPe16004 HBA Firmware | 11.1.220.6 |
| 3PAR FC044X HBA Firmware | 200A8 |
| LSI 9201-16e HBA Firmware | 17.11.03 |
| LSI 9205-8e HBA Firmware | 17.11.03 |
| LSI 9300-8e HBA Firmware | 10.00.08 |

Modifications

The following issues are addressed in this release:

| |
|---|
| Issue IDs: 159516 |
| <p>Issue summary: Reduced I/O block times for consistent imports</p> <p>Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000</p> <p>Affected software versions:3.2.2 MU4, 3.3.1 GA</p> <p>Issue description: Reduces host I/O stall times near the end of a Peer Motion migration where consistency groups are being used.</p> <p>Symptoms: Host may see longer I/O stall times of about 1 to 2 minutes near the end of migration.</p> <p>Conditions of occurrence: Using consistency groups for migration with large number of volumes or large sized volumes.</p> <p>Impact: High, Medium</p> <p>Customer circumvention: Avoid using consistency groups for migration as a workaround.</p> <p>Customer recovery steps: None.</p> |

Issue IDs:165063

Issue summary: Online conversions, online copy, online promote, **updatevv**, and imports have long I/O stall times.

Affected platforms: StoreServ 20000

Affected software versions:3.2.2 GA, 3.2.2 MU4, 3.3.1 GA

Issue description: Online conversions, online copy, online promote, **updatevv**, and imports have long I/O stall times due to internal structure invalidation.

Symptoms: Host may experience longer than normal service times at the end of migration.

Conditions of occurrence: Starting Online Imports, peer-motion imports or **updatevv**.

Impact: High

Customer circumvention: Avoid online conversions, online copy, online promote, **updatevv**, and imports on StoreServ 20000 systems.

Customer recovery steps: Use standard recovery for host timeouts.

Issue IDs:188463

Issue summary: Single node will not boot after clean shutdown when 2nd node has a bad voltage regulator.

Affected platforms: StoreServ 7000

Affected software versions:3.2.1 MU3, 3.2.1 MU5, 3.2.2 MU4, 3.3.1 GA

Issue description: After properly shutting down the system, if a power regulator failure prevents a controller node from booting, the system will not boot because it is waiting for the missing controller node to boot.

Symptoms: On a 2 node system, after a proper shutdown, the array does not boot while waiting for the other controller node to join the cluster.

Conditions of occurrence: When a 2 node array is shutdown and simultaneously encounters a power regulator failure.

Impact: High

Customer circumvention: None

Customer recovery steps: None

Issue IDs:199218

Issue summary: Imports and `updatevv` have long host I/O stall times.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions:3.3.1 GA

Issue description: Imports or `updatevv` with a large list of VVs will have long I/O stall times.

Symptoms: Longer than normal host service times on VLUNS.

Conditions of occurrence: Start an import or `updatevv` with multiple list of VVs, a VVset or consistency group.

Impact: High

Customer circumvention: Avoid using imports or `updatevv` with a large list of VVs.

Customer recovery steps: Use standard recovery for host timeouts.

Issue IDs:200023

Issue summary: The `showpatch -hist` command output shows the **Id** as NA.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions:3.2.2 MU4, 3.3.1 GA

Issue description:The `showpatch -hist` command output shows the **Id** as NA

Symptoms:The `showpatch -hist` command output shows the **Id** as NA

Conditions of occurrence: Running the CLI command `showpatch -hist`

Impact: Low

Customer circumvention: None

Customer recovery steps: None

Issue IDs:200464

Issue summary: The command `updatevv -removeandcreate` skips the addition of some of the VVs within a virtual volume set. The resultant VVs are missing from virtual volume set.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.2.1 GA, 3.2.1 MUx, 3.2.2 GA, 3.2.2 MUx, 3.3.1 GA

Issue description: `updatevv -removeandcreate`, may skip A VV while adding it in Virtual Volume Set (VVSet).

Symptoms:`updatevv -removeandcreate` all snapshots may not be added back to the VVSET.

Conditions of occurrence: Using `updatevv -removeandcreate`

Impact: High

Customer circumvention: Do not user `updatevv -removeandcreate`.

Customer recovery steps:Create the snapshot manually in the VVSet.

Issue IDs:205041

Issue summary: When retention is applied, a scheduled task to create a snapshot is marked failed even though snapshot creation and removal are successful.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.3.1 GA

Issue description: When scheduled task of createfsnap is created with a retention period, the creation of the snapshot and removal of the old snapshot is successful from PML, but CLI intermittently indicates a failure in task details.

Symptoms: Even though the snapshot creation and reclamation is successful, the task indicates that the operation has not completed successfully.

Conditions of occurrence: When system is serving a heavy load and the customer executes numerous snapshot tasks.

Impact: Medium

Customer circumvention: None

Customer recovery steps: No recovery steps are required since creation and removal of snapshots are successful.

Issue IDs:206194

Issue summary: When compressed or compressed deduplicated volume grows over 4TB, the VV master controller node may restart unexpectedly.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.3.1 GA

Issue description: Unexpected controller node restart that may result in unexpected array restart

Symptoms: Master controller node restarts unexpectedly, subsequent master controller node may also restart unexpectedly, triggering a full array restart.

Conditions of occurrence: Use of compressed or compressed deduplicated volume larger than 4TB in size.

Impact: High

Customer circumvention: Install Patch 02 or 3.3.1-EGA.

Customer recovery steps: None

Issue IDs:206441

Issue summary: Unexpected array restarts in response to meta-data inconsistencies.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.3.1 GA

Issue description: After removing all Thinly Deduplicated Virtual Volumes (TDVV) within a CPG, and a controller node reboot or system manager restart, the next TDVV creation may result in LDs being reused.

Symptoms: The array or controller node may not successfully restart.

Conditions of occurrence: A new TDVV is created in a new CPG, after all TDVV are removed from an existing CPG and the array, a controller node or System Manager is restarted.

Impact: High

Customer circumvention: After removing all TDVVs within a CPG do not immediately reboot or shutdown the array.

Customer recovery steps: None

Issue IDs:206840

Issue summary: Array unexpectedly restarts during Remote Copy operation when a read is requested from a disk during disk firmware upgrade.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.3.1 GA

Issue description: During an online upgrade to 3.3.1, HDD/SSD firmware is upgraded. It is possible for two HDD/SSD to be involved in the firmware upgrade process, one is in logging mode while other one is in log playback mode.

Symptoms: Customer applications may abort if array unexpectedly restarts as data is temporarily unavailable.

Conditions of occurrence: Online upgrade with Remote Copy active.

Impact:High

Customer circumvention: Perform the online upgrade to 3.3.1-EGA

Customer recovery steps: None.

HPE 3PAR OS 3.3.1 EGA combines all of the modifications and features provided by HPE 3PAR OS 3.3.1 Patch 01.

Refer to the release notes documents for each patch for a full list of modifications, features and supported drives. To learn more about each patch, use the links provided to access the individual patch release notes.

| 3PAR OS 3.3.1 Patch | Description | Obsoletes | Links to Documentation |
|---------------------|--|-----------|--|
| Patch 01 | P01 provides several quality improvements. | None | HPE 3PAR OS 3.3.1 Patch 01 Release Notes |

Support and other resources

Accessing Hewlett Packard Enterprise Support

- For live assistance, go to the Contact Hewlett Packard Enterprise Worldwide website:
<http://www.hpe.com/assistance>
- To access documentation and support services, go to the Hewlett Packard Enterprise Support Center website:
<http://www.hpe.com/support/hpesc>

Information to collect

- Technical support registration number (if applicable)
- Product name, model or version, and serial number
- Operating system name and version
- Firmware version
- Error messages
- Product-specific reports and logs
- Add-on products or components
- Third-party products or components

Accessing updates

- Some software products provide a mechanism for accessing software updates through the product interface. Review your product documentation to identify the recommended software update method.
- To download product updates:

Hewlett Packard Enterprise Support Center

www.hpe.com/support/hpesc

Hewlett Packard Enterprise Support Center: Software downloads

www.hpe.com/support/downloads

Software Depot

www.hpe.com/support/softwaredepot

- To subscribe to eNewsletters and alerts:
www.hpe.com/support/e-updates
- To view and update your entitlements, and to link your contracts and warranties with your profile, go to the Hewlett Packard Enterprise Support Center **More Information on Access to Support Materials** page:
www.hpe.com/support/AccessToSupportMaterials



IMPORTANT:

Access to some updates might require product entitlement when accessed through the Hewlett Packard Enterprise Support Center. You must have an HPE Passport set up with relevant entitlements.

Websites

| Website | Link |
|--|---|
| Hewlett Packard Enterprise Information Library | <u>www.hpe.com/info/enterprise/docs</u> |
| Hewlett Packard Enterprise Support Center | <u>www.hpe.com/support/hpesc</u> |
| Contact Hewlett Packard Enterprise Worldwide | <u>www.hpe.com/assistance</u> |
| Subscription Service/Support Alerts | <u>www.hpe.com/support/e-updates</u> |
| Software Depot | <u>www.hpe.com/support/softwaredepot</u> |
| Customer Self Repair | <u>www.hpe.com/support/selfrepair</u> |
| Single Point of Connectivity Knowledge (SPOCK) Storage compatibility matrix | <u>www.hpe.com/storage/spock</u> |
| Storage white papers and analyst reports | <u>www.hpe.com/storage/whitepapers</u> |

Customer self repair

Hewlett Packard Enterprise customer self repair (CSR) programs allow you to repair your product. If a CSR part needs to be replaced, it will be shipped directly to you so that you can install it at your convenience. Some parts do not qualify for CSR. Your Hewlett Packard Enterprise authorized service provider will determine whether a repair can be accomplished by CSR.

For more information about CSR, contact your local service provider or go to the CSR website:

www.hpe.com/support/selfrepair

Remote support

Remote support is available with supported devices as part of your warranty, Care Pack Service, or contractual support agreement. It provides intelligent event diagnosis, and automatic, secure submission of hardware event notifications to Hewlett Packard Enterprise, which will initiate a fast and accurate resolution based on your product's service level. Hewlett Packard Enterprise strongly recommends that you register your device for remote support.

For more information and device support details, go to the following website:

www.hpe.com/info/insightremotesupport/docs

Documentation feedback

Hewlett Packard Enterprise is committed to providing documentation that meets your needs. To help us improve the documentation, send any errors, suggestions, or comments to Documentation Feedback (docsfeedback@hpe.com). When submitting your feedback, include the document title, part number, edition, and publication date located on the front cover of the document. For online help content, include the product name, product version, help edition, and publication date located on the legal notices page.

Warranty and regulatory information

For important safety, environmental, and regulatory information, see *Safety and Compliance Information for Server, Storage, Power, Networking, and Rack Products*, available at www.hpe.com/support/Safety-Compliance-EnterpriseProducts.

Warranty information

HPE ProLiant and x86 Servers and Options

www.hpe.com/support/ProLiantServers-Warranties

HPE Enterprise Servers

www.hpe.com/support/EnterpriseServers-Warranties

HPE Storage Products

www.hpe.com/support/Storage-Warranties

HPE Networking Products

www.hpe.com/support/Networking-Warranties