



Hewlett Packard
Enterprise

HPE 3PAR OS 3.3.1 Patch 02 Release Notes

Abstract

This release notes document is for Patch 02 and intended for HPE 3PAR Operating System Software 3.3.1.215.

Part Number: QL226-99554
Published: June 2017
Edition: 1

Notices

The information contained herein is subject to change without notice. The only warranties for Hewlett Packard Enterprise products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. Hewlett Packard Enterprise shall not be liable for technical or editorial errors or omissions contained herein.

Confidential computer software. Valid license from Hewlett Packard Enterprise required for possession, use, or copying. Consistent with FAR 12.211 and 12.212, Commercial Computer Software, Computer Software Documentation, and Technical Data for Commercial Items are licensed to the U.S. Government under vendor's standard commercial license.

Export of the information contained in this publication may require authorization from the U.S. Department of Commerce.

Links to third-party websites take you outside the Hewlett Packard Enterprise website. Hewlett Packard Enterprise has no control over and is not responsible for information outside the Hewlett Packard Enterprise website.

Acknowledgements

Microsoft and Windows are U.S. registered trademarks of Microsoft Corporation.

Adobe® and Acrobat® are trademarks of Adobe Systems Incorporated.

Java and Oracle are registered trademarks of Oracle and/or its affiliates.

UNIX® is a registered trademark of The Open Group.

Intel®, Itanium®, Pentium®, Intel Inside®, and the Intel Inside logo are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Contents

- Purpose.....4**
 - Modifications 4
 - Affected components..... 9
 - Verification.....9
- Websites..... 12**
- Support and other resources.....13**
 - Accessing Hewlett Packard Enterprise Support..... 13
 - Accessing updates.....13
 - Customer self repair.....14
 - Remote support..... 14
 - Warranty information.....14
 - Regulatory information.....15
 - Documentation feedback..... 15

Purpose

The HPE 3PAR OS 3.3.1 Patch 02 provides several quality improvements.

Guidance

- This patch is intended for HPE 3PAR OS 3.3.1 GA.
- This is a recommended patch.
- All HPE 3PAR StoreServ Storage Systems running HPE 3PAR OS 3.3.1 GA are susceptible to the issues corrected in this patch.

Prerequisites

- SP prerequisite: SP-5.0.0.0-22913 or later
- OS prerequisites: OS-3.3.1.215-GA, OS-3.3.1.215-P01

Patch details

Patch ID: P02

Synopsis: Provides several quality improvements

Date: May 30, 2017, 18:38:44 PDT

Description: See the Release Notes for details about this patch

Affected Packages: tpd-cli, tpd-sysmgr, tpd-tocsvr, tpd-kernelpatch, tpd-libcli, tpd-nodesvr, tpd-update, tpd-prerevert

Obsoletes: None

Requires: OS-3.3.1.215-GA, OS-3.3.1.215-P01

Build Version: 3.3.1.228

Supports Revert: Yes

Notes:

NOTE:

- Applying this patch to the 3PAR OS might restart the affected OS components. With these restarts, events and alerts might be generated and this is an expected behavior. The system continues to serve data, but existing CLI or SSMC sessions might be interrupted.
 - Hewlett Packard Enterprise recommends installing patches in the same sequence as they are released, unless instructed otherwise.
 - When displaying the `showversion` command output from the SP, the CLI Client version is fixed in the SP code and might differ from the output displayed from any other system.
-

Modifications

The following issues are addressed in this release:

Issue IDs:159516

Issue summary: Reduced I/O block times for consistent imports

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions:3.2.2 MU4, 3.3.1 GA

Issue description: Reduces host I/O stall times near the end of a Peer Motion migration where consistency groups are being used.

Symptoms: Host may see longer I/O stall times of about 1 to 2 minutes near the end of migration.

Conditions of occurrence: Using consistency groups for migration with large number of volumes or large sized volumes.

Impact: High, Medium

Customer circumvention: Avoid using consistency groups for migration as a workaround.

Customer recovery steps: None.

Issue IDs:165063

Issue summary: Online conversions, online copy, online promote, **updatevv**, and imports have long I/O stall times.

Affected platforms: StoreServ 20000

Affected software versions:3.2.2 GA, 3.2.2 MU4, 3.3.1 GA

Issue description: Online conversions, online copy, online promote, **updatevv**, and imports have long I/O stall times due to internal structure invalidation.

Symptoms: Host may experience longer than normal service times at the end of migration.

Conditions of occurrence: Starting Online Imports, peer-motion imports or **updatevv**.

Impact: High

Customer circumvention: Avoid online conversions, online copy, online promote, **updatevv**, and imports on StoreServ 20000 systems.

Customer recovery steps: Use standard recovery for host timeouts.

<p>Issue IDs:188463</p>
<p>Issue summary: Single node will not boot after clean shutdown when 2nd node has a bad voltage regulator.</p> <p>Affected platforms: StoreServ 7000</p> <p>Affected software versions:3.2.1 MU3, 3.2.1 MU5, 3.2.2 MU4, 3.3.1 GA</p> <p>Issue description: After properly shutting down the system, if a power regulator failure prevents a controller node from booting, the system will not boot because it is waiting for the missing controller node to boot.</p> <p>Symptoms: On a 2 node system, after a proper shutdown, the array does not boot while waiting for the other controller node to join the cluster.</p> <p>Conditions of occurrence: When a 2 node array is shutdown and simultaneously encounters a power regulator failure.</p> <p>Impact: High</p> <p>Customer circumvention: None</p> <p>Customer recovery steps: None</p>
<p>Issue IDs:199218</p>
<p>Issue summary: Imports and <code>updatevv</code> have long host I/O stall times.</p> <p>Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000</p> <p>Affected software versions:3.3.1 GA</p> <p>Issue description: Imports or <code>updatevv</code> with a large list of VVs will have long I/O stall times.</p> <p>Symptoms: Longer than normal host service times on VLUNS.</p> <p>Conditions of occurrence: Start an import or <code>updatevv</code> with multiple list of VVs, a VVset or consistency group.</p> <p>Impact: High</p> <p>Customer circumvention: Avoid using imports or <code>updatevv</code> with a large list of VVs.</p> <p>Customer recovery steps: Use standard recovery for host timeouts.</p>
<p>Issue IDs:200023</p>
<p>Issue summary: The <code>showpatch -hist</code> command output shows the <code>Id</code> as NA.</p> <p>Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000</p> <p>Affected software versions:3.2.2 MU4, 3.3.1 GA</p> <p>Issue description:The <code>showpatch -hist</code> command output shows the <code>Id</code> as NA</p> <p>Symptoms:The <code>showpatch -hist</code> command output shows the <code>Id</code> as NA</p> <p>Conditions of occurrence: Running the CLI command <code>showpatch -hist</code></p> <p>Impact: Low</p> <p>Customer circumvention: None</p> <p>Customer recovery steps: None</p>

Issue IDs:200464

Issue summary: The command `updatevv -removeandrecrreate` skips the addition of some of the VVs within a virtual volume set. The resultant VVs are missing from virtual volume set.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.2.1 GA, 3.2.1 MUx, 3.2.2 GA, 3.2.2 MUx, 3.3.1 GA

Issue description: `updatevv -removeandrecrreate`, may skip A VV while adding it in Virtual Volume Set (VVSet).

Symptoms:`updatevv -removeandrecrreate` all snapshots may not be added back to the VVSET.

Conditions of occurrence: Using `updatevv -removeandrecrreate`

Impact: High

Customer circumvention: Do not user `updatevv -removeandrecrreate`.

Customer recovery steps:Create the snapshot manually in the VVSet.

Issue IDs:205041

Issue summary: When retention is applied, a scheduled task to create a snapshot is marked failed even though snapshot creation and removal are successful.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.3.1 GA

Issue description: When scheduled task of createfsnap is created with a retention period, the creation of the snapshot and removal of the old snapshot is successful from PML, but CLI intermittently indicates a failure in task details.

Symptoms: Even though the snapshot creation and reclamation is successful, the task indicates that the operation has not completed successfully.

Conditions of occurrence: When system is serving a heavy load and the customer executes numerous snapshot tasks.

Impact: Medium

Customer circumvention: None

Customer recovery steps: No recovery steps are required since creation and removal of snapshots are successful.

Issue IDs:206194

Issue summary: When compressed or compressed deduplicated volume grows over 4TB, the VV master controller node may restart unexpectedly.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.3.1 GA

Issue description: Unexpected controller node restart that may result in unexpected array restart

Symptoms: Master controller node restarts unexpectedly, subsequent master controller node may also restart unexpectedly, triggering a full array restart.

Conditions of occurrence: Use of compressed or compressed deduplicated volume larger than 4TB in size.

Impact: High

Customer circumvention: Install Patch 02 or 3.3.1-EGA.

Customer recovery steps: None

Issue IDs:206441

Issue summary: Unexpected array restarts in response to meta-data inconsistencies.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.3.1 GA

Issue description: After removing all Thinly Deduplicated Virtual Volumes (TDVV) within a CPG, and a controller node reboot or system manager restart, the next TDVV creation may result in LDs being reused.

Symptoms: The array or controller node may not successfully restart.

Conditions of occurrence: A new TDVV is created in a new CPG, after all TDVV are removed from an existing CPG and the array, a controller node or System Manager is restarted.

Impact: High

Customer circumvention: After removing all TDVVs within a CPG do not immediately reboot or shutdown the array.

Customer recovery steps: None

Issue IDs:206840

Issue summary: Array unexpectedly restarts during Remote Copy operation when a read is requested from a disk during disk firmware upgrade.

Affected platforms: StoreServ 7000, StoreServ 8000, StoreServ 10000, StoreServ 20000

Affected software versions: 3.3.1 GA

Issue description: During an online upgrade to 3.3.1, HDD/SSD firmware is upgraded. It is possible for two HDD/SSD to be involved in the firmware upgrade process, one is in logging mode while other one is in log playback mode.

Symptoms: Customer applications may abort if array unexpectedly restarts as data is temporarily unavailable.

Conditions of occurrence: Online upgrade with Remote Copy active.

Impact:High

Customer circumvention: Perform the online upgrade to 3.3.1-EGA

Customer recovery steps: None.

Affected components

Component	Version
CLI Client	3.3.1.228
System Manager	3.3.1.228 (P02)
TOC Server	3.3.1.228 (P02)
TPD Kernel Patch	3.3.1.228 (P02)

Verification

The installation of P02 can be verified from an interactive CLI session. Issue the CLI command `showversion -a -b` to verify that P02 is listed:

```
cli% showversion -a -b
Release version 3.3.1.215
Patches: P01,P02
```

Component Name	Version
CLI Server	3.3.1.228 (P02)
CLI Client	3.3.1.228
System Manager	3.3.1.228 (P02)
Kernel	3.3.1.215
TPD Kernel Code	3.3.1.215
TPD Kernel Patch	3.3.1.228 (P02)
CIM Server	3.3.1.215
WSAPI Server	3.3.1.215
Console Menu	3.3.1.215
Event Manager	3.3.1.215
Internal Test Tools	3.3.1.215
LD Check Tools	3.3.1.215
Network Controller	3.3.1.215
Node Disk Scrubber	3.3.1.215
PD Scrubber	3.3.1.215
Per-Node Server	3.3.1.228 (P02)
Persistent Repository	3.3.1.215
Powerfail Tools	3.3.1.215
Preserved Data Tools	3.3.1.215
Process Monitor	3.3.1.215
Software Updater	3.3.1.228 (P02)
TOC Server	3.3.1.228 (P02)
VV Check Tools	3.3.1.217 (P01)
Upgrade Check Scripts	170330.U004 (3.3.1.215)
File Persona	1.3.0.74-20170309
SNMP Agent	1.10.0
SSH	6.0p1-4+deb7u5
VASA Provider	3.0.12
Firmware Database	3.3.1.217 (P01)
Drive Firmware	3.3.1.215
UEFI BIOS	05.02.54
MCU Firmware (OKI)	4.8.60
MCU Firmware (STM)	5.3.17
Cage Firmware (DC1)	4.44
Cage Firmware (DC2)	2.64
Cage Firmware (DC3)	08
Cage Firmware (DC4)	2.64
Cage Firmware (DCN1)	4082
Cage Firmware (DCN2)	4082
Cage Firmware (DCS1)	4082
Cage Firmware (DCS2)	4082
Cage Firmware (DCS5)	2.78
Cage Firmware (DCS6)	2.78
Cage Firmware (DCS7)	4082
Cage Firmware (DCS8)	4082
QLogic QLA4052C HBA Firmware	03.00.01.77
QLogic QLE8242 CNA Firmware	04.15.27
QLogic 260x HBA FC Firmware	174.03.70
QLogic 27xx/268x HBA FC Firmware	174.03.70

QLogic 83xx HBA FCoE Firmware	08.01.05
QLogic 8300 HBA iSCSI Firmware	05.07.35
Emulex LP11002 HBA Firmware	02.82.x10
Emulex LPe12002 HBA Firmware	02.10.x02
Emulex LPe12004 HBA Firmware	02.10.x02
Emulex LPe16002 HBA Firmware	11.1.220.6
Emulex LPe16004 HBA Firmware	11.1.220.6
3PAR FC044X HBA Firmware	200A8
LSI 9201-16e HBA Firmware	17.11.03
LSI 9205-8e HBA Firmware	17.11.03
LSI 9300-8e HBA Firmware	10.00.08

Websites

General websites

Hewlett Packard Enterprise Information Library

www.hpe.com/info/EIL

Single Point of Connectivity Knowledge (SPOCK) Storage compatibility matrix

www.hpe.com/storage/spock

Storage white papers and analyst reports

www.hpe.com/storage/whitepapers

For additional websites, see [Support and other resources](#).

Support and other resources

Accessing Hewlett Packard Enterprise Support

- For live assistance, go to the Contact Hewlett Packard Enterprise Worldwide website:
<http://www.hpe.com/assistance>
- To access documentation and support services, go to the Hewlett Packard Enterprise Support Center website:
<http://www.hpe.com/support/hpesc>

Information to collect

- Technical support registration number (if applicable)
- Product name, model or version, and serial number
- Operating system name and version
- Firmware version
- Error messages
- Product-specific reports and logs
- Add-on products or components
- Third-party products or components

Accessing updates

- Some software products provide a mechanism for accessing software updates through the product interface. Review your product documentation to identify the recommended software update method.
- To download product updates:

Hewlett Packard Enterprise Support Center

www.hpe.com/support/hpesc

Hewlett Packard Enterprise Support Center: Software downloads

www.hpe.com/support/downloads

Software Depot

www.hpe.com/support/softwaredepot

- To subscribe to eNewsletters and alerts:
www.hpe.com/support/e-updates
- To view and update your entitlements, and to link your contracts and warranties with your profile, go to the Hewlett Packard Enterprise Support Center **More Information on Access to Support Materials** page:
www.hpe.com/support/AccessToSupportMaterials



IMPORTANT:

Access to some updates might require product entitlement when accessed through the Hewlett Packard Enterprise Support Center. You must have an HPE Passport set up with relevant entitlements.

Customer self repair

Hewlett Packard Enterprise customer self repair (CSR) programs allow you to repair your product. If a CSR part needs to be replaced, it will be shipped directly to you so that you can install it at your convenience. Some parts do not qualify for CSR. Your Hewlett Packard Enterprise authorized service provider will determine whether a repair can be accomplished by CSR.

For more information about CSR, contact your local service provider or go to the CSR website:

<http://www.hpe.com/support/selfrepair>

Remote support

Remote support is available with supported devices as part of your warranty or contractual support agreement. It provides intelligent event diagnosis, and automatic, secure submission of hardware event notifications to Hewlett Packard Enterprise, which will initiate a fast and accurate resolution based on your product's service level. Hewlett Packard Enterprise strongly recommends that you register your device for remote support.

If your product includes additional remote support details, use search to locate that information.

Remote support and Proactive Care information

HPE Get Connected

www.hpe.com/services/getconnected

HPE Proactive Care services

www.hpe.com/services/proactivecare

HPE Proactive Care service: Supported products list

www.hpe.com/services/proactivecaresupportedproducts

HPE Proactive Care advanced service: Supported products list

www.hpe.com/services/proactivecareadvancedsupportedproducts

Proactive Care customer information

Proactive Care central

www.hpe.com/services/proactivecarecentral

Proactive Care service activation

www.hpe.com/services/proactivecarecentralgetstarted

Warranty information

To view the warranty for your product or to view the *Safety and Compliance Information for Server, Storage, Power, Networking, and Rack Products* reference document, go to the Enterprise Safety and Compliance website:

www.hpe.com/support/Safety-Compliance-EnterpriseProducts

Additional warranty information

HPE ProLiant and x86 Servers and Options

www.hpe.com/support/ProLiantServers-Warranties

HPE Enterprise Servers

www.hpe.com/support/EnterpriseServers-Warranties

HPE Storage Products

www.hpe.com/support/Storage-Warranties

Regulatory information

To view the regulatory information for your product, view the *Safety and Compliance Information for Server, Storage, Power, Networking, and Rack Products*, available at the Hewlett Packard Enterprise Support Center:

www.hpe.com/support/Safety-Compliance-EnterpriseProducts

Additional regulatory information

Hewlett Packard Enterprise is committed to providing our customers with information about the chemical substances in our products as needed to comply with legal requirements such as REACH (Regulation EC No 1907/2006 of the European Parliament and the Council). A chemical information report for this product can be found at:

www.hpe.com/info/reach

For Hewlett Packard Enterprise product environmental and safety information and compliance data, including RoHS and REACH, see:

www.hpe.com/info/ecodata

For Hewlett Packard Enterprise environmental information, including company programs, product recycling, and energy efficiency, see:

www.hpe.com/info/environment

Documentation feedback

Hewlett Packard Enterprise is committed to providing documentation that meets your needs. To help us improve the documentation, send any errors, suggestions, or comments to Documentation Feedback (docsfeedback@hpe.com). When submitting your feedback, include the document title, part number, edition, and publication date located on the front cover of the document. For online help content, include the product name, product version, help edition, and publication date located on the legal notices page.