

HP 3PAR OS 3.1.3 MU2 Patch 14 Release Notes

This release notes document is for Patch 14 and intended for HP 3PAR Operating System Software 3.1.3.262 (MU2).

HP Part Number: QL226-98129
Published: April 2015
Edition: 1



© Copyright 2015 Hewlett-Packard Development Company, L.P.

Confidential computer software. Valid license from HP required for possession, use or copying. Consistent with FAR 12.211 and 12.212, Commercial Computer Software, Computer Software Documentation, and Technical Data for Commercial Items are licensed to the U.S. Government under vendor's standard commercial license.

The information contained herein is subject to change without notice. The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.

Acknowledgments

Intel®, Itanium®, Pentium®, Intel Inside®, and the Intel Inside logo are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Microsoft® and Windows® are trademarks of the Microsoft group of companies.

Adobe® and Acrobat® are trademarks of Adobe Systems Incorporated.

Java and Oracle are registered trademarks of Oracle and/or its affiliates.

UNIX® is a registered trademark of The Open Group.

Documentation

For the latest version of this document, go to <http://www.hp.com/go/3par/>, navigate to your product page, click **Support for your product**, and then click **Manuals**.

Contents

1 Overview of HP 3PAR OS.....	4
Supported Platforms.....	4
Patch Details.....	4
Included in This Patch.....	4
Affected components.....	5
Modifications to the HP 3PAR OS.....	5
Verifying the patch installation.....	5

1 Overview of HP 3PAR OS

This release notes document describes the modifications and known issues for Patch 14. This is only intended to be applied to HP 3PAR OS 3.1.3.262 (MU2). This patch is provided on an as-needed basis when the specific hardware identified in the release notes is installed on the array.

The installation of this patch affects the following packages:

- tpd-prerevert
- tpd-fwdb
- tpd-drivefw

Supported Platforms

The HP 3PAR Configuration Matrix for HP 3PAR OS 3.1.3 contains information about supported hardware and software platforms. For additional information, see the Single Point of Connectivity Knowledge for HP Storage Products (SPOCK) website: <http://www.hp.com/storage/spock>.

Patch Details

- Patch Name: HP 3PAR OS 3.1.3 MU2 P14
- Prerequisite: The Service Processor must be at release level SP-4.2.0.GA-29 + the latest available patch
- This patch applies to: HP 3PAR OS Release 3.1.3.262 (MU2)
- Obsoletes: None

NOTE: This patch is revertible but HP does not recommend revert.

NOTE: Applying this patch to the HP 3PAR OS might restart the affected OS components. With these restarts, events and alerts might be generated and this is an expected behavior. The system continues to serve data, but existing CLI or IMC sessions might be interrupted.

Included in This Patch

HP 3PAR OS 3.1.3 MU2 P14 includes:

- Issue ID: 117694, 119887
- Description: Support for SAWK1000S5xnN7.2, SMKR2000S5xeN7.2, and SMKR4000S5xeN7.2 drives on 3.1.3 MU2.
- Affected Packages: tpd-fwdb, tpd-drivefw, tpd-prerevert
- Obsoletes: None
- Requires: OS-3.1.3.262-MU2
- Build Version: 3.1.3.274

NOTE: HP recommends installing patches in the same sequence as they are released, unless instructed otherwise.

Affected components

Component	Version
Firmware Database	20150330
Drive Firmware	20150330

Modifications to the HP 3PAR OS

This release addresses the following items:

Issue number	Description
117694	New drive support for: <ul style="list-style-type: none">• SMKR2000S5xeN7.2 drive• SMKR4000S5xeN7.2 drive
119887	New drive support for SAWK1000S5xnN7.2 drive

The firmware provides support for the following drives:

- SMKR2000S5xeN7.2 and SMKR4000S5xeN7.2 drives on HP 3PAR StoreServ 7xxx Storage systems and HP 3PAR StoreServ P10000 Storage systems
- SAWK1000S5xnN7.2 drives on F-class and T-class systems

Verifying the patch installation

The installation of Patch 14 can be verified from an interactive CLI session. Issue the CLI command `showversion -a -b` to verify that Patch 14 is listed.

```
cli% showversion -a -b
Release version 3.1.3.262 (MU2)
Patches: P14

Component Name      Version
CLI Server          3.1.3.262 (MU2)
CLI Client           3.1.3.262
System Manager       3.1.3.262 (MU2)
Kernel               3.1.3.262 (MU2)
TPD Kernel Code      3.1.3.262 (MU2)
CIM Server           3.1.3.262 (MU2)
.
.
.
Firmware Database    20150330
Drive Database        20150330
```

NOTE: When displaying the `showversion` command output from the Service Processor, the CLI Client version is fixed in the SP code, and might differ from the output displayed on another system.

After a firmware patch is installed successfully, the firmware (drive or cage) must be updated manually. To update the firmware, run the CLI command `starttask admithw -ni`. The `starttask admithw -ni` command runs the update process as a task. Record the task ID for monitoring purposes. Monitor the task for successful completion using the CLI command `showtask -d <task_ID>`. See the appropriate upgrade documentation for details on patch installation.