



Hewlett Packard
Enterprise

HPE 3PAR OS 3.2.2 MU6 Patch 115

Release Notes

Abstract

This release notes document is for Patch 115.

Part Number: QL226-99924a
Published: August 2018
Edition: 1

Notices

The information contained herein is subject to change without notice. The only warranties for Hewlett Packard Enterprise products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. Hewlett Packard Enterprise shall not be liable for technical or editorial errors or omissions contained herein.

Confidential computer software. Valid license from Hewlett Packard Enterprise required for possession, use, or copying. Consistent with FAR 12.211 and 12.212, Commercial Computer Software, Computer Software Documentation, and Technical Data for Commercial Items are licensed to the U.S. Government under vendor's standard commercial license.

Export of the information contained in this publication may require authorization from the U.S. Department of Commerce.

Links to third-party websites take you outside the Hewlett Packard Enterprise website. Hewlett Packard Enterprise has no control over and is not responsible for information outside the Hewlett Packard Enterprise website.

Acknowledgements

Microsoft and Windows are U.S. registered trademarks of Microsoft Corporation. Adobe® and Acrobat® are trademarks of Adobe Systems Incorporated.

Java and Oracle are registered trademarks of Oracle and/or its affiliates.

UNIX® is a registered trademark of The Open Group.

Intel®, Itanium®, Pentium®, Intel Inside®, and the Intel Inside logo are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Purpose

The HPE 3PAR OS 3.2.2 MU6 Patch 115 provides support for drive firmware updates.

IMPORTANT:

See the [HPE 3PAR OS and Service Processor Software Update Guide \(HPE 3PAR OS 3.2.x HPE 3PAR Service Processor 4.x\)](#) for instructions on updating your specific software.

Guidance

This is an as needed patch.

Prerequisites

- SP prerequisite: SP-4.4.0.GA-88 plus the latest SP patch
- Base OS: OS-3.2.2.709-MU6. See Requires in Patch details.

Patch details

Patch ID: P115

Synopsis: Provides support for drive FW updates

Date: July 18, 2018, 11:20:31 PDT

Description: See the Release Notes for details about this patch

Affected Packages: tpd-drivefw, tpd-fwdb, tpd-prerevert

Obsoletes: OS-3.2.2.709-P112

Requires: OS-3.2.2.709-MU6

Build Version: 3.2.2.752

Patches Partially Superseded: None

Patches Included: None

Patches Obsolete by Combination: None

Supports Revert: Yes

Notes: Description of the obsoleted patches:

Patch ID: P112

Synopsis: Provides support for new drives

Date: June 29, 2018, 13:03:10 PDT

Description: See the Release Notes for details about this patch

Affected Packages: tpd-drivefw, tpd-fwdb, tpd-prerevert

Obsoletes: OS-3.2.2.709-P104

Requires: OS-3.2.2.709-MU6

Build Version: 3.2.2.747

Notes: Description of the obsoleted patches:

Patch ID: P104

Synopsis: Provides support for drive FW updates

Date: April 05, 2018, 13:09:16 PDT

Description: See the Release Notes for details about this patch

Affected Packages: tpd-drivefw, tpd-fwdb, tpd-prerevert

Obsoletes: OS-3.2.2.709-P96

Requires: OS-3.2.2.709-MU6

Build Version: 3.2.2.732

Notes: Description of the obsoleted patches:

Patch ID: P96

Synopsis: Provides support for drive FW updates.

Date: November 20, 2017, 09:44:32 PST

Description: See the Release Notes for details about this patch

Affected Packages: tpd-fwdb, tpd-prerevert

Obsoletes: None

Requires: OS-3.2.2.709-MU6

Build Version: 3.2.2.711

Notes:

NOTE:

Hewlett Packard Enterprise recommends installing patches in the same sequence as they are released, unless instructed otherwise.

Modifications

Patch 115 provides support for drive firmware upgrades.

Drive	Category	Capacity	Speed	StoreServ 10000	StoreServ 7000	StoreServ 20000	StoreServ 8000	FW
AREX0480S5xnNTRI	SSD	480GB	100K	No	Yes	Yes	Yes	3P07
AREX0920S5xnNTRI	SSD	920GB	100K	No	Yes	No	No	3P07
AREX1920S5xnNTRI	SSD	1.92TB	100K	Yes	Yes	Yes	Yes	3P07
AREX3840S5xnNTRI	SSD	3.84TB	100K	No	Yes	Yes	Yes	3P07
AREX0400S5xnNTRI	SSD	400GB	150K	Yes	Yes	Yes	Yes	3P03
AREX0920S5xnFTRI	SSD	920GB	100K	No	Yes	Yes	Yes	3P03
AREX1920S5xnFTRI	SSD	1.92TB	100K	No	Yes	Yes	Yes	3P03
AREX3840S5xnFTRI	SSD	3.84TB	100K	No	Yes	Yes	Yes	3P03
DOPM3840S5xnNMRI	SSD	3.84TB	100K	No	Yes	Yes	Yes	3P07
DOPE0480S5xnNMRI	SSD	480GB	100K	No	Yes	Yes	Yes	3P0A
DOPE1920S5xnNMRI	SSD	1.92TB	100K	No	Yes	Yes	Yes	3P0A
STHB0600S5xeN010	FC	600GB	10K	Yes	Yes	Yes	Yes	3P03
STHB1200S5xeN010	FC	1.2TB	10K	Yes	Yes	Yes	Yes	3P03
STHB1800S5xeN010	FC	1.8TB	10K	Yes	Yes	Yes	Yes	3P03

Patch 115 addresses the following issues.

Issue ID: 210885

Issue Summary: Certain drive models cause data miscompare due to undetected writer head degradation.

Platforms affected: All StoreServ

Affected Software versions: 3.2.2 MU3 – MU6, 3.3.1 MU1 – MU2

Issue Description: The affected drive models can cause a data miscompare due to head element degradation, which, over time, loses the capability to overwrite existing data with new data. This firmware update increases the monitoring frequency and will remove the degraded disk from the system.

The following drive models are affected:

STHB0600S5xeN010

STHB1200S5xeN010

STHB1800S5xeN010

STHB0900S5xeN010

Symptoms: Data inconsistency.

Conditions of Occurrence: The affected drive models are installed.

Impact: Low

Customer Circumvention: None.

Customer Recovery Steps: None.

Issue ID: 207486, 211833, 221852, 235211, 231272, 235211

Issue Summary: Unsuccessful upgrade of HDD firmware for drive models beginning with DOPE and DOPM.

Platforms affected: All StoreServ

Affected Software versions: 3.2.1 MU5, 3.2.2 MU3 – MU6, 3.3.1 MU1 – MU2

Issue Description: The DOPE 3P0A firmware corrects an issue when upgrading DOPE drive models from firmware versions prior to 3P07. All versions of DOPE firmware can now be upgraded using version 3P0A.

The DOPM 3P07 firmware corrects an issue when upgrading DOPM drive models from firmware versions prior to 3P05. All versions of DOPM firmware can now be upgraded using version 3P07.

Symptoms: Data inconsistency.

Conditions of Occurrence: Upgrading firmware on DOPE/DOPM disk drives.

Impact: Medium

Customer Circumvention: None.

Customer Recovery Steps: None.

Issue ID: 215795, 196915

Issue Summary: This upgrades drive firmware on drives with the model name beginning with AREX.

Platforms affected: All StoreServ

Affected Software versions: 3.2.1 MU5, 3.2.2. MU3 – MU6, 3.3.1 MU1 – MU2

Issue Description: Firmware versions previous to 3P03 or 3P07 for certain AREX drive models can cause a data inconsistency issue.

Symptoms: Data inconsistency was reported.

Conditions of Occurrence: AREX0920S5xnFTRI, AREX1920S5xnFTRI, AREX3840S5xnFTRI drives with firmware prior to version 3P03.

AREX0400S5xnNTRI drives with firmware prior to version 3P03.

AREX0480S5xnNTRI, AREX0920S5xnNTRI, AREX1920S5xnNTRI, AREX3840S5xnNTRI drives with firmware prior to version 3P07.

Impact: High

Customer Circumvention: None.

Customer Recovery Steps: Upgrade the drive FW.

Affected components

Component	Version
Firmware Database	3.2.2.752 (P115)
Drive Firmware	3.2.2.752 (P115)

NOTE:

Applying an HPE 3PAR OS patch can cause a restart of the affected OS components. This restart is an expected behavior, which will generate events and alerts. The system continues to serve data, but existing CLI or SSMC sessions could be interrupted.

Installing Drive Firmware

After a firmware patch is installed successfully, the firmware (drive or cage) must be updated manually. To update the firmware, run the CLI command `starttask admithw -ni`. This command runs the update process as a task. Record the task ID for monitoring purposes. Monitor the task for successful completion using the CLI command `showtask -d <task_ID>`. See the appropriate upgrade documentation for details on patch installation. If the task fails, resolve the issue due to which the task failed. After the issue is resolved, issue the CLI command `starttask admithw -ni`. Note the new task ID number and monitor the `admithw` task completion. The `admithw` task should be run to successful completion as soon as possible after installing patches.

This patch is revertible, however, revert after the supported drives are in use makes them unavailable.

IMPORTANT:

Drive firmware patches that are installed and then reverted prior to activation of the firmware upgrade require that the CLI command `showfirmwaredb -l` is executed after the patch revert is completed. This final, manual step in the revert process ensures that the physical disk state is changed from degraded `old_firmware` back to `normal`. While revert is possible, it is not recommended to revert a patch that delivers firmware after activation (`admthw` has been run).

Verification

The installation of P115 can be verified from an interactive CLI session. Issue the CLI command `showversion -a -b` to verify that P115 is listed.

```
$ showversion -a -b
Release version 3.2.2.709 (MU6)
Patches: P115
```

Component Name	Version
CLI Server	3.2.2.709 (MU6)
CLI Client	3.2.2.709
System Manager	3.2.2.709 (MU6)
Kernel	3.2.2.709 (MU6)
TPD Kernel Code	3.2.2.709 (MU6)
CIM Server	3.2.2.709 (MU6)
WSAPI Server	3.2.2.709 (MU6)
Console Menu	3.2.2.709 (MU6)
Event Manager	3.2.2.709 (MU6)
Internal Test Tools	3.2.2.709 (MU6)
LD Check Tools	3.2.2.709 (MU6)
Network Controller	3.2.2.709 (MU6)
Node Disk Scrubber	3.2.2.709 (MU6)
PD Scrubber	3.2.2.709 (MU6)
Per-Node Server	3.2.2.709 (MU6)
Persistent Repository	3.2.2.709 (MU6)
Powerfail Tools	3.2.2.709 (MU6)
Preserved Data Tools	3.2.2.709 (MU6)
Process Monitor	3.2.2.709 (MU6)
Rolling Upgrade Tools	3.2.2.709 (MU6)
Software Updater	3.2.2.709 (MU6)
TOC Server	3.2.2.709 (MU6)
VV Check Tools	3.2.2.709 (MU6)
File Persona	1.2.4.3-20170601
SNMP Agent	1.8.0
SSH	6.6p1-4~bpo70+1
VASA Provider	2.2.10
Firmware Database	3.2.2.752 (P115)

Drive Firmware	3.2.2.752 (P115)
UEFI BIOS	04.08.39
MCU Firmware (OKI)	4.8.29
MCU Firmware (STM)	5.2.53
Cage Firmware (DC1)	4.44
Cage Firmware (DC2)	2.64
Cage Firmware (DC3)	08
Cage Firmware (DC4)	2.64
Cage Firmware (DCN1)	4078
Cage Firmware (DCN2)	4078
Cage Firmware (DCS1)	4078
Cage Firmware (DCS2)	4078
Cage Firmware (DCS5)	2.86
Cage Firmware (DCS6)	2.86
Cage Firmware (DCS7)	4078
Cage Firmware (DCS8)	4078
QLogic QLA4052C HBA Firmware	03.00.01.77
QLogic QLE8242 CNA Firmware	04.15.08
QLogic 8300 HBA FC Firmware	08.01.05
QLogic 8300 HBA FCoE Firmware	08.01.05
QLogic 8300 HBA iSCSI Firmware	05.07.07
Emulex LP11002 HBA Firmware	02.82.x10
Emulex LPe12002 HBA Firmware	02.10.x03
Emulex LPe12004 HBA Firmware	02.10.x03
Emulex LPe16002 HBA Firmware	10.6.248.8
Emulex LPe16004 HBA Firmware	10.6.248.8
3PAR FC044X HBA Firmware	200A8
LSI 9201-16e HBA Firmware	17.11.00
LSI 9205-8e HBA Firmware	17.11.00
LSI 9300-8e HBA Firmware	07.10.01

NOTE:

When displaying the showversion command output from the SP, the CLI Client version is fixed in the SP code and may differ from the output from any other system.

Websites

General websites

Hewlett Packard Enterprise Information Library

www.hpe.com/info/EIL

Single Point of Connectivity Knowledge (SPOCK) Storage compatibility matrix

www.hpe.com/storage/spock

Storage white papers and analyst reports

www.hpe.com/storage/whitepapers

For additional websites, see [Support and other resources](#).

Support and other resources

Accessing Hewlett Packard Enterprise Support

- For live assistance, go to the Contact Hewlett Packard Enterprise Worldwide website:
<http://www.hpe.com/assistance>
- To access documentation and support services, go to the Hewlett Packard Enterprise Support Center website:
<http://www.hpe.com/support/hpesc>

Information to collect

- Technical support registration number (if applicable)
- Product name, model or version, and serial number
- Operating system name and version
- Firmware version
- Error messages
- Product-specific reports and logs
- Add-on products or components
- Third-party products or components

Accessing updates

- Some software products provide a mechanism for accessing software updates through the product interface. Review your product documentation to identify the recommended software update method.
- To download product updates:

Hewlett Packard Enterprise Support Center

www.hpe.com/support/hpesc

Hewlett Packard Enterprise Support Center: Software downloads

www.hpe.com/support/downloads

Software Depot

www.hpe.com/support/softwaredepot

- To subscribe to eNewsletters and alerts:
www.hpe.com/support/e-updates
- To view and update your entitlements, and to link your contracts and warranties with your profile, go to the Hewlett Packard Enterprise Support Center **More Information on Access to Support Materials** page:
www.hpe.com/support/AccessToSupportMaterials

IMPORTANT:

Access to some updates might require product entitlement when accessed through the Hewlett Packard Enterprise Support Center. You must have an HPE Passport set up with relevant entitlements.

Customer self-repair

Hewlett Packard Enterprise customer self-repair (CSR) programs allow you to repair your product. If a CSR part needs to be replaced, it will be shipped directly to you so that you can install it at your convenience.

Some parts do not qualify for CSR. Your Hewlett Packard Enterprise authorized service provider

will determine whether a repair can be accomplished by CSR.

For more information about CSR, contact your local service provider or go to the CSR website:

<http://www.hpe.com/support/selfrepair>

Remote support

Remote support is available with supported devices as part of your warranty or contractual support agreement. It provides intelligent event diagnosis, and automatic, secure submission of hardware event notifications to Hewlett Packard Enterprise, which will initiate a fast and accurate resolution based on your product's service level. Hewlett Packard Enterprise strongly recommends that you register your device for remote support.

If your product includes additional remote support details, use search to locate that information.

Remote support and Proactive Care information

HPE Get Connected

www.hpe.com/services/getconnected

HPE Proactive Care services

www.hpe.com/services/proactivecare

HPE Proactive Care service: Supported products list

www.hpe.com/services/proactivecaresupportedproducts

HPE Proactive Care advanced service: Supported products list

www.hpe.com/services/proactivecareadvancedsupportedproducts

Proactive Care customer information

Proactive Care central

www.hpe.com/services/proactivecarecentral

Proactive Care service activation

www.hpe.com/services/proactivecarecentralgetstarted

Warranty information

To view the warranty for your product or to view the *Safety and Compliance Information for Server, Storage, Power, Networking, and Rack Products* reference document, go to the Enterprise Safety and Compliance website:

www.hpe.com/support/Safety-Compliance-EnterpriseProducts

Additional warranty information

HPE ProLiant and x86 Servers and Options

www.hpe.com/support/ProLiantServers-Warranties

HPE Enterprise Servers

www.hpe.com/support/EnterpriseServers-Warranties

HPE Storage Products

www.hpe.com/support/Storage-Warranties

HPE Networking Products

www.hpe.com/support/Networking-Warranties

Regulatory information

To view the regulatory information for your product, view the *Safety and Compliance Information for Server, Storage, Power, Networking, and Rack Products*, available at the Hewlett Packard Enterprise

Support Center:

www.hpe.com/support/Safety-Compliance-EnterpriseProducts

Additional regulatory information

Hewlett Packard Enterprise is committed to providing our customers with information about the chemical substances in our products as needed to comply with legal requirements such as REACH (Regulation EC No 1907/2006 of the European Parliament and the Council). A chemical information report for this product can be found at:

www.hpe.com/info/reach

For Hewlett Packard Enterprise product environmental and safety information and compliance data, including RoHS and REACH, see:

www.hpe.com/info/ecodata

For Hewlett Packard Enterprise environmental information, including company programs, product recycling, and energy efficiency, see:

www.hpe.com/info/environment

Documentation feedback

Hewlett Packard Enterprise is committed to providing documentation that meets your needs. To help us improve the documentation, send any errors, suggestions, or comments to Documentation Feedback (**docsfeedback@hpe.com**). When submitting your feedback, include the document title, part number, edition, and publication date located on the front cover of the document. For online help content, include the product name, product version, help edition, and publication date located on the legal notices page.