## **NOKIA**

**BSC** 

# Availability of Nokia S9 and S10 Releases

Technical Note No. 800



The information in this document is subject to change without notice and describes only the product defined in the introduction of this documentation. This document is intended for the use of Nokia's customers only for the purposes of the agreement under which the document is submitted, and no part of it may be reproduced or transmitted in any form or means without the prior written permission of Nokia. The document has been prepared to be used by professional and properly trained personnel, and the customer assumes full responsibility when using it. Nokia welcomes customer comments as part of the process of continuous development and improvement of the documentation.

The information or statements given in this document concerning the suitability, capacity, or performance of the mentioned hardware or software products cannot be considered binding but shall be defined in the agreement made between Nokia and the customer. However, Nokia has made all reasonable efforts to ensure that the instructions contained in the document are adequate and free of material errors and omissions. Nokia will, if necessary, explain issues which may not be covered by the document.

Nokia's liability for any errors in the document is limited to the documentary correction of errors. NOKIA WILL NOT BE RESPONSIBLE IN ANY EVENT FOR ERRORS IN THIS DOCUMENT OR FOR ANY DAMAGES, INCIDENTAL OR CONSEQUENTIAL (INCLUDING MONETARY LOSSES), that might arise from the use of this document or the information in it.

This document and the product it describes are considered protected by copyright according to the applicable laws.

NOKIA logo is a registered trademark of Nokia Oyj.

Other product names mentioned in this document may be trademarks of their respective companies, and they are mentioned for identification purposes only.

Copyright © Nokia Ovi 2004. All rights reserved.

TN Version No. 1.0

Edited by 03. September 2004 Susanna Tarvainen Approved by 06. September 2004 Petri Hahl



## TN800: Availability of Nokia S9 and S10 Releases

**Validity:** 

<u>Software</u> <u>E</u>		<b>ETSI</b>	environment	<u>ANS</u>	<b>ANSI</b> environment				
	X	<b>S9</b>	X	GSM 900	X	GSM 800			
	X	S10 (ANSI)	X	GSM 1800	X	GSM 1900			
		S10.5		•		_			

#### **Kevwords:**

S9, S10, maintenance, availability

**S10.5 ED** 

**S11** 

#### **Summary:**

GSM/EDGE BSC & SW Product Line has made a decision to discontinue the production, support and maintenance of the BSC S9 and S10 (ANSI) level software releases on 31.12.2004.

#### **Description:**

Nokia Oyj, Radio Networks, GSM/EDGE BSC & SW Product Line, has made a decision to discontinue the production, support and maintenance of the BSC S9 and BSC S10 (ANSI) level software releases on the 31st of December 2004. This decision follows the principles of Nokia Availability of Network Elements and the Software Support Terms.

The decision has become possible by introducing new S10.5, S10.5 ED and S11 software releases (n+2), which are now all available and in wide use. The S10.5 software release has been available since December 2002, the S10.5 ED software release since March 2003 and the S11 software release has been available since April 2004.

The introduction of the new releases has eliminated the market need for the S9 and S10 (ANSI) software releases. Furthermore, field experience has proven the performance of the new releases.

For further information on this issue, please contact your local BSS (BSC) Solution Manager.

Markku Ellilä GSM/EDGE BSC & SW Product Line Nokia Oyj

Instructions:	
Note:	
Reference:	

#### **Technical Note Revision History**

Date	Version Editor		Summary of changes
31.08.04	1.0	S. Tarvainen	The first official version
03.09.04	03.09.04 1.1 S. Tarvainen		Added S10 discontinuation information



### **List of Active Technical Notes**

Set	Nbr	Title	TN Vers	S9	S10	S10.5	S10.5 ED	S11	S11.5	S12
	800	Availability of Nokia S9 and S10 Releases	1.0	Х	Х					
	799	GSM800/GSM1900 Common BCCH and MULTI BCF	1.0				Х	Х	х	х
	798	AMR usage in SEGMENT	1.0			Х	Х	Х		
	797	Usage of G40 segment with CP4x CPUs equipped	1.0					Х	х	
	796	SW Support for Nokia BSCE, TCSME, BSC2E and BSC2A	1.0						х	Х
		Products								
	795	System Level Trace Reporting	1.0				Х			
	794	Transmission delay impact to LapD throughput	1.0	Х	Х	Х	Х	Χ		
	793	Installing S11 compatible ET2 plug-in unit SW	1.0			Х	Х	Х		
	792	Activating data filtering for FER measurement in UL and DL direction and changing filtering threshold	1.0				х			
	791	Removing semipermanent Trunk- to-Trunk circuits after S9	1.0			х	Х			
	790	Guidelines for (E)GPRS radionetwork planning to get full benefit of improved intra PCU cell re-selection in S10.5(ED)	1.0			Х	Х			
	789	Dynamic Abis configuration	1.0				Х			
	788	Instructions to use child cells when segment usage is activated	1.0				Х			
	787	GSM900/GSM1800 Common BCCH (ETSI)	1.0				Х			
	786 785	GSM800/GSM1900 Common BCCH (ANSI) Load based TCH handover in Common BCCH	1.0				X			
	784	Using frequency hopping in segment with several BTS	2.0			Х	X X			
	783	Defining a maximum transmission power of GSM 800 frequency band BTS in segment environment	1.0			X	X			
	781	New traffic measurement counter for calculating network accessibility	1.0	Х	х	х	х			
	780	Change Delivery requirement for S9-S10.5 upgrade	1.0	Х		Х	Х			
	779	New traffic measurement counter for dropped calls	1.0	Х		Х	Х			
	778	Message Bus fault investigation after SUPPROGX 7.12-4 correction	1.0	Х	Х	х	Х			
	777	1GB Winchester disks with S10.5 software	1.0			Х	Х			
		Accessing PCU service terminal	1.0	Х	Х	Х	Х			
	775	Logical file connections of GALARM in MCMU	1.0	Х	Х	Х	Х			
	774 773	FACCH call set-up and handovers with AMR  Delaying call set-up to ensure MS measurement report availability in a segment environment	1.0		Х	X	X			
	772	Clarifications to GPRS territory handling and allocation	1.0	Х	Х					
		AMR Codec mode settings	1.0		Х					
		Pool Switch Indicator for AMR circuit pool	1.0		Х	Х	Χ			
		TCSM2 SW in S10 package	1.0		Х					
		Illegal initialisation value for DRX_TIMER_MAX	1.0		Х	Х	Χ			
		BTS synchronisation	1.0		Х					
		BSC IP- Address in High Capacity upgrade	1.0	X	.,	V	v			
		Adding a TRX to a GPRS enabled cell SPLIT_PG_CYCLE support deactivation / activation	1.3	X	X	X	X			
		CS TCH allocation with GPRS, Half Rate and BB-hopping	2.0		^	X	X			
		CS TCH allocation with GPRS, Half Rate and BB-hopping	1.0	Х	Х	X	X			
		Interaction between HSCSD and GPRS after BSC S9 SW CD 4.0 GEN	1.0	Х	Х	X	X			
	759	Defining directory sizes when extracting files from a ZIP archive	1.1	Х	х	Х	Х			
		Supervision of Transmission Equipment in Q1 Bus	1.1	Х	Х	Х	Χ			
	756	TCSM2E/A recovery problem after a power break with TRCO eprom version 5.7-0	1.1	х						
		SCCP Broadcast status settings in BSC	1.0	Х	<u> </u>					
		Gb interface loss due to MCMU switchover	1.0	Х		.,	.,			
		Instructions to replace ET2E/ET2E-C with ET2E-S/ET2E-SC	1.1	X	X	X	X			
	752	Modifying Parameter "Bad Quality Experience Guard Time"	1.0	X	Х	Х	Х			
	751	PCU Improvements	1.0	Х	1	L			Ь	



750   Corrupted Sy TCSM2 software on floppy											
748   PCU Configuration Instructions   1.4   x   x   x   x   x				1.0	Х						
747   Patching BTS LOAD INFO TIMER with BSC (eature AMH   1.0   x		749			Х						
746   BSC Remote SW Upgrade		748		1.4	Х						
745   BCSU Recovery and Alarms 690, 691 and 1001		747	Patching BTS LOAD INFO TIMER with BSC feature AMH	1.0	Х	Х					
744   TSM2 SW floppy disk is corrupted		746	BSC Remote SW Upgrade	1.1	Х	Х	Χ	Х			
743		745	BCSU Recovery and Alarms 690, 691 and 1001	1.1	Х	Х	Χ	Х			
0.3 installation recommendations		744	TCSM2 SW floppy disk is corrupted	1.0	Х						
742   PCU boot SW compatibility   1.1		743	PCU boot SW updating and BSC Change Deliveries 0.2 and	1.1	Х						
740   Installing BSC SW without conversions   1.3   x   x   X   X   X   X   X   X   X   X			0.3 installation recommendations								
740   Installing BSC SW without conversions   1.3   x   x   X   X   X   X   X   X   X   X		742	PCU boot SW compatibility	1.1	Х						
739   MMI Password Encryption Based on Public Algorithms and   1.0   x		740				Х	Χ	Х			
S9 Release Upgrade					Х						
738   GPRS enabling and BTS SW support											
Sec Q3 interface compatibility with different NMS SW releases   Parameters in MML command groups EO and EM   1.2		738		1.1	Х	Х	Х	Х			
releases							Х				
0002   734   Parameters in MML command groups E0 and EM					^		**				
991   729   Correction for GEN 637: File size of BSC measurements	0002	734		1.2	х	х	Х	Х			
9921   729   Correction for GEN 637: File size of BSC measurements											1
9920         728         Handover Adjacent Cell Measurement Counters         x											
9916   721   Correction for GEN 715: A-interface Recovery and BSS8018   2.0   x   x   x   x   x   x   x   x   x						v	Y	Y			1
SCCP Improvement				2.0		^	^	_ ^			
9911   712   TCSM2 Routine Testing Notes   1.1   x   x   x   X   X   X   X   X   Y   Y   Y   Y   Y	9910	121		2.0	Α						
9911 711 HSCSD Power Control parameters after S7 upgrade Validity 9907 702 DSP Software Update of TR Plug-In Unit 9907 702 Optimised Abis and not_in_use channels / Improvement for GEN 579 9901 683 Unreliable activation of TCSM SMHW 02E correction 9901 680 Unequal MNC values cause failures in location update 1.2 x x x X X 9824 671 BTS alarms blocked after the SW upgrade 1.2 x x x X X 9821 657 Functionality of the online call tracing observation 1.2 x x X X 9818 648 Implementation of BSS7210, Dual band MS access to IUO-lay 1.1 x x X X 9818 640 Actions before a system restart 1.2 x x X X X 9813 632 Effects of BCSU working state change from W0 to TE 1.3 x X X X 9813 632 Correction for GEN 547:BSC parameter DISABLE INTERNAL 1.3 x X X X 9813 631 Correction for GEN 547:BSC parameter DISABLE INTERNAL 1.3 x X X X 9813 631 Correction for GEN 546: CCS7 30 Minutes freezing done 9813 631 Correction for GEN 547:BSC parameter DISABLE INTERNAL 1.3 x X X X 9803 605 Dimensioning capacity of SS#7 links 1.2 x X X X 9719 595 Super-reuse TRX in BL-US state increases handover failure 1.1 x X X X X 9719 595 Super-reuse TRX in BL-US state increases handover failure 1.1 x X X X X 9719 595 PCM failure alarm missing in PCM break in ISDN Abis 9712 574 Using Satellite Abis and Landline Abis in the same BSC 1.2 x X X X X 9719 558 Problems with synchronized handovers in PrimeSite 1.1 x X X X X 9719 575 Problems with synchronized handovers in PrimeSite 1.1 x X X X X 9719 575 Problems of Nokia BSCE and TCSME Equipment 1.1 x X X X X X 9710 575 Problems with synchronized handovers in PrimeSite 1.1 x X X X X X 9710 575 Problems with synchronized handovers in PrimeSite 1.1 x X X X X X 9710 575 Problems with synchronized handovers in PrimeSite 1.1 x X X X X X X X X X X X X X X X X X X	0011	71.2		1 1	v	v	v	v			
9907   703   DSP Software Update of TR Plug-In Unit				1.1		Χ	^	^			1
9907 702 Optimised Abis and not_in_use channels / Improvement for GEN 579  9901 683 Unreliable activation of TCSM SMHW 02E correction  9901 680 Unequal MNC values cause failures in location update  9824 671 BTS alarms blocked after the SW upgrade  9821 657 Functionality of the online call tracing observation  9828 1 Implementation of BSS7210, Dual band MS access to IU0-  1											-
GEN 579				1.2			V				
9901 683 Unreliable activation of TCSM SMHW 02E correction 9901 680 Unequal MNC values cause failures in location update 1.2	9907	702		1.2	Х	Х	X	Х			
9901 680 Unequal MNC values cause failures in location update 1.2	9901	683			х						
9824         671         BTS alarms blocked after the SW upgrade         1.2         x         X         x         x         X<				1.2		Х	Х	Х			
9821 657 Functionality of the online call tracing observation 9818 648 Implementation of BSS7210, Dual band MS access to IUO- Information about Fallback usage 9816 640 Actions before a system restart 9817 635 Effects of BCSU working state change from W0 to TE 9818 635 Effects of BCSU working state change from W0 to TE 9819 632 Correction for GEN 547:BSC parameter DISABLE INTERNAL H0 is highly recommended to have value N0 9813 631 Correction for GEN 546: CCS7 30 Minutes freezing done 9813 631 Correction for GEN 546: CCS7 30 Minutes freezing done 9819 595 Super-reuse TRX in BLUS state increases handover failure counter values in statistics 9719 595 Super-reuse TRX in BLUS state increases handover failure counter values in statistics 9710 574 Using Satellite Abis and Landline Abis in the same BSC 9710 574 Using Satellite Abis and Landline Abis in the same BSC 9710 574 Using Satellite Abis and Landline Abis in PrimeSite 9711 574 Using Satellite Abis and Landline Abis in PrimeSite 9712 574 Using Satellite Abis and Landline Abis in PrimeSite 9713 574 Using Satellite Abis and Landline Abis in PrimeSite 9714 Satellite Abis and Landline Abis in PrimeSite 9715 575 Problems with synchronized handovers in PrimeSite 9716 578 Problems with synchronized handovers in PrimeSite 9717 578 Problems with synchronized handovers in PrimeSite 9718 579 SCCP broadcast status settings in BSC 9719 34 Remove proms from the plug-in unit when sending them to repairing 9710 150 Potential overload problem, Transcoder/MSC interaction 9710 151 Potential overload problem, Transcoder/MSC interaction 9710 151 Potential overload problem, Transcoder/MSC interaction 9711 151 VX											
9818 648 Implementation of BSS7210, Dual band MS access to IUO-lay 9816 641 Information about Fallback usage 9816 640 Actions before a system restart 9818 635 Effects of BCSU working state change from W0 to TE 9813 635 Effects of BCSU working state change from W0 to TE 9813 631 Correction for GEN 547:BSC parameter DISABLE INTERNAL H0 is highly recommended to have value N0 9813 631 Correction for GEN 546: CCS7 30 Minutes freezing done 9813 631 Correction for GEN 546: CCS7 30 Minutes freezing done 9813 635 Dimensioning capacity of SS#7 links 1.2 x X X X X 9803 605 Dimensioning capacity of SS#7 links 1.2 x X X X X 9709 595 Super-reuse TRX in BL-US state increases handover failure counter values in statistics 9718 590 PCM failure alarm missing in PCM break in ISDN Abis 9712 574 Using Satellite Abis and Landline Abis in the same BSC 9709 565 Command Calendar output destination 9707 558 Problems with synchronized handovers in PrimeSite 9718 591 Availability of Nokia BSCE and TCSME Equipment 1.2 x X X X X 9709 561 S0 SCCP broadcast status settings in BSC 9719 34 Removing TRCO PIU from the TCIC cartridge 9710 151 Potential overload problem, Transcoder/MSC interaction 9710 151 X X X X X X X X X X X X X X X X X X											1
lay											1
9816 641 Information about Fallback usage 9816 640 Actions before a system restart 9817 635 Effects of BCSU working state change from W0 to TE 9818 632 Correction for GEN 547:BSC parameter DISABLE INTERNAL H0 is highly recommended to have value N0 9818 631 Correction for GEN 546: CCS7 30 Minutes freezing done 9818 631 Correction for GEN 546: CCS7 30 Minutes freezing done 9819 605 Dimensioning capacity of SS#7 links 9819 1.2	3020	0.0			^						
9816 640 Actions before a system restart  9817 635 Effects of BCSU working state change from W0 to TE  9818 632 Correction for GEN 547:BSC parameter DISABLE INTERNAL H0 is highly recommended to have value N0  9818 631 Correction for GEN 546: CCS7 30 Minutes freezing done 9819 605 Dimensioning capacity of SS#7 links 9819 1.2 x X X X X X X X X X X X X X X X X X X	9816	641		1.1	х	х	Х	Х			
9813 635 Effects of BCSU working state change from W0 to TE 9813 632 Correction for GEN 547:BSC parameter DISABLE INTERNAL H0 is highly recommended to have value N0 9813 631 Correction for GEN 546: CCS7 30 Minutes freezing done 9803 605 Dimensioning capacity of SS#7 links 9719 595 Super-reuse TRX in BL-US state increases handover failure counter values in statistics 9718 590 PCM failure alarm missing in PCM break in ISDN Abis 9712 574 Using Satellite Abis and Landline Abis in the same BSC 9709 565 Command Calendar output destination 9707 558 Problems with synchronized handovers in PrimeSite 9718 591 Availability of Nokia BSCE and TCSME Equipment 1.2 x x x x x x 9613 514 Removing TRCO PIU from the TC1C cartridge 9719 34 Remove proms from the plug-in unit when sending them to repairing 9710 To Potential overload problem, Transcoder/MSC interaction 1.1 x x x x x x x x x x x x x x x x x x											<b>†</b>
9813 632 Correction for GEN 547:BSC parameter DISABLE INTERNAL H0 is highly recommended to have value NO  9813 631 Correction for GEN 546: CCS7 30 Minutes freezing done 9803 605 Dimensioning capacity of SS#7 links 1.2 x X X X X  9719 595 Super-reuse TRX in BL-US state increases handover failure counter values in statistics  9718 590 PCM failure alarm missing in PCM break in ISDN Abis 9712 574 Using Satellite Abis and Landline Abis in the same BSC 9709 565 Command Calendar output destination 1.1 x X X X X  9707 558 Problems with synchronized handovers in PrimeSite 1.1 x X X X X  9618 531 Availability of Nokia BSCE and TCSME Equipment 1.2 x X X X  9613 509 SCCP broadcast status settings in BSC 9519 34 Remove proms from the plug-in unit when sending them to repairing 9512 15 Potential overload problem, Transcoder/MSC interaction 1.1 x X X X X X	-										
H0 is highly recommended to have value N0  9813 631 Correction for GEN 546: CCS7 30 Minutes freezing done  9803 605 Dimensioning capacity of SS#7 links  9719 595 Super-reuse TRX in BL-US state increases handover failure counter values in statistics  9718 590 PCM failure alarm missing in PCM break in ISDN Abis  9712 574 Using Satellite Abis and Landline Abis in the same BSC  9709 565 Command Calendar output destination  9707 558 Problems with synchronized handovers in PrimeSite  9718 591 Availability of Nokia BSCE and TCSME Equipment  9709 501 501 Removing TRCO PIU from the TC1C cartridge  9709 501 501 Potential overload problem, Transcoder/MSC interaction  9709 301 Tax X X X X X X X X X X X X X X X X X X X											
9813 631 Correction for GEN 546: CCS7 30 Minutes freezing done 9803 605 Dimensioning capacity of SS#7 links 9719 595 Super-reuse TRX in BL-US state increases handover failure counter values in statistics 9718 590 PCM failure alarm missing in PCM break in ISDN Abis 9712 574 Using Satellite Abis and Landline Abis in the same BSC 9709 565 Command Calendar output destination 9707 558 Problems with synchronized handovers in PrimeSite 9718 591 Availability of Nokia BSCE and TCSME Equipment 9719 592 SCCP broadcast status settings in BSC 9710 SCCP broadcast status settings in BSC 9711 STAN Remove proms from the plug-in unit when sending them to repairing 9712 15 Potential overload problem, Transcoder/MSC interaction 1.1 X X X X X X X X X X X X X X X X X X	3013	032		1.5	^	^	^	^			
9803 605 Dimensioning capacity of SS#7 links  9719 595 Super-reuse TRX in BL-US state increases handover failure counter values in statistics  9718 590 PCM failure alarm missing in PCM break in ISDN Abis  9712 574 Using Satellite Abis and Landline Abis in the same BSC  9709 565 Command Calendar output destination  9707 558 Problems with synchronized handovers in PrimeSite  9718 591 Availability of Nokia BSCE and TCSME Equipment  9719 591 34 Remove proms from the plug-in unit when sending them to repairing  9710 15 Potential overload problem, Transcoder/MSC interaction	9813	631		13	v	v	Y	Y			
9719 595 Super-reuse TRX in BL-US state increases handover failure counter values in statistics  9718 590 PCM failure alarm missing in PCM break in ISDN Abis  9712 574 Using Satellite Abis and Landline Abis in the same BSC  9709 565 Command Calendar output destination  9707 558 Problems with synchronized handovers in PrimeSite  9718 591 Availability of Nokia BSCE and TCSME Equipment  1.2 x x x x x x x x x x x x x x x x x x x											-
counter values in statistics  9718 590 PCM failure alarm missing in PCM break in ISDN Abis  9712 574 Using Satellite Abis and Landline Abis in the same BSC  9709 565 Command Calendar output destination  9707 558 Problems with synchronized handovers in PrimeSite  9708 531 Availability of Nokia BSCE and TCSME Equipment  1.2 x x x x x  9618 531 Availability of Nokia BSCE and TCSME Equipment  1.2 x x x x x  9613 514 Removing TRCO PIU from the TC1C cartridge  9709 500 SCCP broadcast status settings in BSC  9709 9709 9709 9709 9709 9709 9709 970											
9718 590 PCM failure alarm missing in PCM break in ISDN Abis 9712 574 Using Satellite Abis and Landline Abis in the same BSC 9709 565 Command Calendar output destination 9707 558 Problems with synchronized handovers in PrimeSite 9708 531 Availability of Nokia BSCE and TCSME Equipment 1.2 x x x x x 9618 531 Availability of Nokia BSCE and TCSME Equipment 1.2 x x x x x 9613 514 Removing TRCO PIU from the TC1C cartridge 1.1 x x x x x x 9613 509 SCCP broadcast status settings in BSC 9519 34 Remove proms from the plug-in unit when sending them to repairing 9512 15 Potential overload problem, Transcoder/MSC interaction 1.1 x x x x x x	9119	292		1.1	Α	Α	^	^			
9712574Using Satellite Abis and Landline Abis in the same BSC1.2xxXXX9709565Command Calendar output destination1.1xxxxx9707558Problems with synchronized handovers in PrimeSite1.1xxxxx9618531Availability of Nokia BSCE and TCSME Equipment1.2xxxxx9613514Removing TRCO PIU from the TC1C cartridge1.1xxxx9613509SCCP broadcast status settings in BSCxxxx951934Remove proms from the plug-in unit when sending them to repairing1.2xxxx951215Potential overload problem, Transcoder/MSC interaction1.1xxxx	0710	500			v						1
9709565Command Calendar output destination1.1xxxx9707558Problems with synchronized handovers in PrimeSite1.1xxxx9618531Availability of Nokia BSCE and TCSME Equipment1.2xxxx9613514Removing TRCO PIU from the TC1C cartridge1.1xxxx9613509SCCP broadcast status settings in BSCx951934Remove proms from the plug-in unit when sending them to repairing1.2xxxx951215Potential overload problem, Transcoder/MSC interaction1.1xxxx				1 2		.,	v	v			1
9707     558     Problems with synchronized handovers in PrimeSite     1.1     x     x     x     x       9618     531     Availability of Nokia BSCE and TCSME Equipment     1.2     x     x     x     x       9613     514     Removing TRCO PIU from the TCIC cartridge     1.1     x     x     x     x       9613     509     SCCP broadcast status settings in BSC     x     x     x       9519     34     Remove proms from the plug-in unit when sending them to repairing     1.2     x     x     x       9512     15     Potential overload problem, Transcoder/MSC interaction     1.1     x     x     x										-	<del>                                     </del>
9618 531 Availability of Nokia BSCE and TCSME Equipment 1.2										-	<u> </u>
9613     514     Removing TRCO PIU from the TC1C cartridge     1.1     x     x     x     x       9613     509     SCCP broadcast status settings in BSC     x     x     x     x       9519     34     Remove proms from the plug-in unit when sending them to repairing     1.2     x     x     x     x       9512     15     Potential overload problem, Transcoder/MSC interaction     1.1     x     x     x										-	<u> </u>
9613     509     SCCP broadcast status settings in BSC     x        9519     34     Remove proms from the plug-in unit when sending them to repairing     1.2     x     x     x       9512     15     Potential overload problem, Transcoder/MSC interaction     1.1     x     x     x										-	<u> </u>
9519 34 Remove proms from the plug-in unit when sending them to repairing 9512 15 Potential overload problem, Transcoder/MSC interaction 1.1 x x x x x				1.1		Х	Х	Х			<u> </u>
to repairing  9512 15 Potential overload problem, Transcoder/MSC interaction 1.1 x x x x x x x x x x x x x x x x x x										ļ	<u> </u>
9512 15 Potential overload problem, Transcoder/MSC interaction 1.1 x x x x	9519	34		1.2	Х	Х	Х	Х			
										ļ	<u> </u>
9510   13   Different interpretation of DL DTX setting in MSCs   1.2   x   x   x   x										-	<u> </u>
	9510	13	Different interpretation of DL DTX setting in MSCs	1.2	Х	Χ	Х	Х	<u> </u>	L	<u> </u>