

NOKIA

Nokia UltraSite EDGE Base Station

BTS SW release CX4.0-5

**Technical Note
No. 52**

The information in this document is subject to change without notice and describes only the product defined in the introduction of this documentation. This document is intended for the use of Nokia's customers only for the purposes of the agreement under which the document is submitted, and no part of it may be reproduced or transmitted in any form or means without the prior written permission of Nokia. The document has been prepared to be used by professional and properly trained personnel, and the customer assumes full responsibility when using it. Nokia welcomes customer comments as part of the process of continuous development and improvement of the documentation.

The information or statements given in this document concerning the suitability, capacity, or performance of the mentioned hardware or software products cannot be considered binding but shall be defined in the agreement made between Nokia and the customer. However, Nokia has made all reasonable efforts to ensure that the instructions contained in the document are adequate and free of material errors and omissions. Nokia will, if necessary, explain issues which may not be covered by the document.

Nokia's liability for any errors in the document is limited to the documentary correction of errors. NOKIA WILL NOT BE RESPONSIBLE IN ANY EVENT FOR ERRORS IN THIS DOCUMENT OR FOR ANY DAMAGES, INCIDENTAL OR CONSEQUENTIAL (INCLUDING MONETARY LOSSES), that might arise from the use of this document or the information in it.

This document and the product it describes are considered protected by copyright according to the applicable laws.

NOKIA logo is a registered trademark of Nokia Oyj.

Other product names mentioned in this document may be trademarks of their respective companies, and they are mentioned for identification purposes only.

Copyright © Nokia Oyj 2005. All rights reserved.

**TN Version
No. 1.0.0**

**Edited by
Date May 6th 2005
Name Markku Jokela**

**Approved by
Date May 6th 2005
Name Jaakko Mikkola**

BTS SW release CX4.0-5

Validity:

Product	GSM 800	GSM 900	GSM 1800	GSM 1900
Nokia UltraSite EDGE	X	X	X	X
Nokia ConnectSite 100				

Keywords: GSM, EDGE, BTS, SW, CX4.0-4, CX4.0-5, UltraSite

Summary: This Technical Note informs about the release of UltraSite EDGE BTS SW CX4.0-5.

Description: In Technical Note 51 Nokia informed about the problems seen by customers during the rollout of BTS SW CX4.0-4. To correct these problems Nokia has decided to release BTS SW CX4.0-5.

The following problems have been identified in CX4.0-4:

TRXs carrying no traffic

- The problem symptoms:
 - Incoming handovers fail to the BTS
 - 7738 'BTS WITH NO TRANSACTIONS alarm at BSC after a defined time at BSC
 - 7743 MEAN HOLDING TIME BELOW DEFINED THRESHOLD and/or 7745 CHANNEL FAILURE RATE ABOVE DEFINED THRESHOLD alarm for the affected TRX
 - BCF lock/unlock clears the problem, but the problem may come back during normal operation
- The identified root cause:
 - The root cause for the problem has been identified to be in the implementation of 'Runtime Diagnostics and Recovery for 7606 TRX FAULTY alarms in UltraSite', which was implemented in CX4.0-4
 - The 7606 TRX FAULTY alarms that are checked by the diagnostics are not sent to the BSC. The alarm descriptions for the affected 7606 alarms can be found in the CX4.0-4 Generic Failure Report for the Runtime Diagnostics (ref 13225ES08P)
 - The problem occurs with non-hopping and RF-hopping

After BTS SW CX4.0-4 activation, TRXs stay in blocked state:

- The problem symptoms:
 - After the CX4.0-4 SW activation, some TRX units do not come into WO-state.
 - A typical alarm seen is 7606 TRX FAULTY "Interface problems between O&M and DSP software'.
 - The alarm may be seen when BB-hopping and Antenna Hopping is in use.
 - In non-hopping and RF-hopping, the alarm is not sent to BSC, because of the problem in the Runtime Diagnostics causing the TRX carrying no traffic.
- The problem root causes:
 - Problem occurs with Runtime Diagnostics write operation to BB2x board flash memory during the downloading of EQDSP SW.

Correction to the problems:

- Both problems have been identified to be in the Runtime Diagnostics functionality introduced in BTS SW CX4.0-4.
- The Runtime Diagnostics and Recovery functionality has been removed from CX4.0-5.

BTS SW Release CX4.0-5 schedule

The plan is to release CX4.0-5 in NOLS on 23rd of May 2005.

Instructions: None

Note: None

Reference: None

Technical Note Revision History

DATE	VERSION	EDITOR	SUMMARY OF CHANGES
May 6th 2005	1.0.0	Markku Jokela	Approved version

List of Active Technical Notes for NOKIA UltraSite EDGE Base Station:

TN No	Title of TN
10	Base Band – TRX Unit Cross Connection Functionality
13	An Update on BTS/Transmission SW Releases
18	EDGE HW compatibility
21	Simulation of baseband card BB2x failure by using hot extract
25	Change in WCxA appearance
27	EDAP modification on runtime
29	Update on BTS transmission cables
32	An Update on BTS/ Transmission SW Releases
34	BB2F, new Base Band Unit
35	An Update on BTS/ Transmission SW Releases
36	2G- 3G Inter System Handover
44	An Update on SiteWizard and Transmission SW Releases
45	Update on BTS SW releases
46	Update on BTS SW releases
47	Update on BTS SW releases
48	Error in TSxB labels
49	Update on BTS SW releases
50	Outdoor BTS Extreme Climate Air Filter Kits
51	Problems with BTS SW CX4.0-4
52	BTS SW release CX4.0-5