

## Motorola Solutions Technical Notification (MTN)

**TITLE:** WebRCM doesn't show more than 10 stormplans

**TECHNOLOGY:** ASTRO 25

**SYMPTOMS:**

In WebRCM customers may see a maximum of 10 stormplans even if more are created in the PM.

**MODELS / SYSTEM RELEASES / KITS / DATECODES AFFECTED:**

**A2022.1/A2022.HS:** ATR

**ATR:** ATR version ASTM-07.32.03.24 or prior

**A2020.1/A2021.1/A2020.HS:** ATR

**ATR:** version ASTM-07.31.02.43 or prior

**A2019.2:** ATR

**ATR:** version ATR-Astro-07.19.01.95 or prior

**SEVERITY RECOMMENDATION:**

**Medium / Operational** - Schedule to implement

**ROOT CAUSE:**

Software defect

**DEFINITIVE TEST:**

None

**WORKAROUNDS:**

N/A

**CORRECTIVE ACTIONS:**

Install the appropriate version of software listed in the "PARTS REQUIRED (HARDWARE/SOFTWARE):" section below.

**RESOLUTIONS AND REPAIR PROCEDURES:**

Upgrade to the appropriate version as listed in the "PARTS REQUIRED (HARDWARE/SOFTWARE):" section below, based on the model.

**To obtain software:**

- 1) Initiate a software request case through Motorola Solutions, Inc. Centralized Managed Support Operations (CMSO) at 800-MSI-HELP (800-674-4357) or 302-444-9800
- 2) Await confirmation email from Motorola Solutions Software Factory (MSSF) with instructions
- 3) Complete the Motorola Solutions Software Factory Software Order Form:
  - a) Reference **MTN-0013-23-NA** in the 'Reason for Software/Hardware Change' section of the software order form.

DOCUMENT NUMBER: MTN-0013-23-NA  
APC: 877  
ISSUE DATE: Mar-2023  
EXPIRATION DATE: 31-Mar-2024  
Bulletin Type: Informational Only

- b) List the part number (**KC #** as listed under "PARTS REQUIRED (HARDWARE/SOFTWARE)" below) in the 'Part # or Version #' section of the software order form.
- 4) Email completed Software Order Form to MSSF for processing

**TIME TO IMPLEMENT/SYSTEM IMPACT:**

**Estimated time to implement** - 2h (per ATR)

**High** - Loss of functionalities/audio/downtime - No data will be provided to clients (e.g. to Zone Watch, RCM, Dynamic Reports, Historical Reports, Genesis, CAD, ATIA log viewer, Affiliation Display, Cirrus) by the ATR during install time

**PARTS REQUIRED (HARDWARE/SOFTWARE):**

**A2022.1/A2022.HS:** ATR version ASTM-07.32.03.29 - KC877V0AY000220102 or later

**A2020.1/A2021.1/A2020.HS:** ATR version ASTM-07.31.02.44 - KC877V0AY000200107 or later

**A2019.2:** ATR version ASTM-07.19.01.97 - KC877V0AY000190207 or later

**ADDITIONAL INFORMATION:**

N/A

**REFERENCE THE FOLLOWING DOCUMENTS/PROCESSES FOR INSTALLATION PROCEDURES:**

Private Network Management Servers Feature Guide - [MN007171A01](#)

**WHEN TO APPLY RESOLUTION:**

After failure \_X\_

During maintenance \_X\_

**LABOR ALLOWANCE:**

This is an informational bulletin. No labor warranty is implied, intended or authorized for U.S. Domestic Partners/Customers. Other regions should follow their own standard procedures.

**If, after attempting to perform the solution steps, you are having issues with the resolution in the MTN then please contact your MSI Technical support center.**

In NALA [https://www.motorolasolutions.com/en\\_us/support.html](https://www.motorolasolutions.com/en_us/support.html)

In EMEA [https://www.motorolasolutions.com/en\\_xu/support.html](https://www.motorolasolutions.com/en_xu/support.html)

In Asia [https://www.motorolasolutions.com/en\\_xp/support.html](https://www.motorolasolutions.com/en_xp/support.html)

**SW ORDER FORM IS AVAILABLE UNDER THE LINK:**

[http://www.motorolasolutions.com/content/dam/msi/docs/robots/motorola-technical-notification/SW\\_order\\_form.pdf](http://www.motorolasolutions.com/content/dam/msi/docs/robots/motorola-technical-notification/SW_order_form.pdf)