

DOCUMENT NUMBER: MTN-0014-18-NA

APC: 877 DATE: 03-2018

ISSUE DATE: 03-2018 EXPIRATION DATE: 31-03-2019

Bulletin Type: Informational Only

Motorola Solutions Technical Notification (MTN)

TITLE: ESXi loses connection with DAS (Model 3520) attached by HPE H241 and/or Fans are running at high speed on HP DL380 Gen9 servers

TECHNOLOGY: ASTRO 25

SYMPTOMS:

- ESXi loses connection with DAS (Model 3520) attached by HPE H241. DAS was reporting generic controller issues to UFM.
- 2. Fans are running at high speed in servers despite no actual reason for them to do so on HP DL380 Gen9 servers.

MODELS / SYSTEM RELEASES / KITS / DATE/CODES AFFECTED:

ProLiant DL380 Gen9 with HBA H241 Card / Dot Hill Model 3520 VMware ESXi 5.5(7.14, 7.15, 7.16), 6.0(7.17)

SEVERITY RECOMMENDATION:


High / Safety - Perform Immediately

ROOT CAUSE / DEFINITIVE TEST:

- Issue is caused by a combination of third party vendor firmware and driver defects. Older storage controller firmware issue
 can cause VMS storage to become unreachable and VMS to loose connection to both datastores (local and the das) and
 the DAS becoming inoperable.
- 2. Due to a defect in HP firmware the HP Active Health System (AHS) or HPE Integrated Lights-Out (iLO) logs may indicate that the fans are running at high speeds (for example, above 70% duty)

WORKAROUNDS AND CORRECTIVE ACTIONS:

- 1. Complete "Disable Application" procedure if it is applicable for a virtual machine.
- 2. Shutdown all virtual machines.
- 3. Reboot ESXi server.



RESOLUTIONS AND REPAIR PROCEDURES:



This is general recommended update for all Customers.

RESOLUTION:

Before You Begin:

- An NM Client with a network connection to the storage controller enclosure (DAS) is required.
- The Dothill Firmware Media is required and is inserted into the optical drive of the NM Client.

ANY USE NOT APPROVED BY MOTOROLA SOLUTIONS IS PROHIBITED. This Motorola Technical Notification (MTN) is issued pursuant to Motorola's ongoing review of the quality, effectiveness, and performance of its products. The information provided in this bulletin is intended for use by trained, professional technicians only, who have the expertise to perform the service described in the MTN. Motorola disclaims any and all liability for product quality or performance if the recommendations in this MTN are not implemented, or not implemented in compliance with the instructions provided here. Implementation of these recommendations may be necessary for the product to remain compliant with applicable laws or regulations. Please be advised, that failure to implement these recommendations in the manner instructed may also invalidate applicable warranties, or otherwise impact any potential contractual rights or obligations. MOTOROLA, MOTO, MOTOROLA SOLUTIONS, and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. ©2016 Motorola Solutions, Inc. All rights reserved."

Verify whether it is a single-controller or a dual-controller storage enclosure (DAS).
 Either visually verify that there are two physical storage controllers in the DAS or determine this from the system configuration: L1/M1 configurations are non-redundant, all other configurations are redundant.

Proceed to appendices. First perform instructions in Appendix A. and then perform instructions in Appendix B.

PARTS REQUIRED (HARDWARE/SOFTWARE):

Media Name	KC Number	Release
Dothill Firmware Media	KC877V0B0000071710	A7.14/A7.15/A7.16/A7.17
HP Firmware Install Media (DL380 G9)	KC877L0DJ000071755	A7.14/A7.15/A7.16/A7.17
VMware vSphere 5.5 Upgrade Media	KC877V0CS000071604	A7.14/A7.15/A7.16
VMware vSphere 6.0 Upgrade Media	KC877V0CS000071702	A7.17

ADDITIONAL INFORMATION:

NA

REFERENCE THE FOLLOWING DOCUMENTS/PROCESSES FOR INSTALLATION PROCEDURES:

NA

WHEN TO APPLY RESOLUTION:

After reboot
After (re)installation _X_
After upgrade _
After power cycle
After database restoration
After failure
On FRU replacement
During maintenance
Immediately _X_
As instructed X_
Information only

LABOR ALLOWANCE:

This is an informational bulletin. No labor warranty is implied, intended or authorized for U.S. Domestic Partners/Customers. Other regions should follow their own standard procedures.

For assistance with this bulletin please contact your MSI Technical support centre $\underline{\text{https://www.motorolasolutions.com/en_us/support.html}}$

Appendix A: Updating Storage Controller Modules Firmware

Conventions	3
Signing In	3
Viewing System Status	3
Shutting Down Virtual Machines	3
Single-Controller Configuration	4
Management Controller Restart	4
Updating Controller-Module Firmware	4
Final Check	4
Dual-Controller Configuration	5
Disabling PFU	5
Firmware Update	5
Management Controller Restart	5
Updating Controller-Module Firmware	5
Final Check	6



If you are about to apply this procedure in the time when symptom #1 is observable, please apply instructions in <u>WORKAROUNDS AND CORRECTIVE ACTIONS</u> section of this document before continuing.



Please contact SSC team for further assistance in case of an abnormal completion of any step or unsuccessful execution of any script within the scope of this procedure.



Perform all steps consequently; run next script only after the previous script's execution is completed.

Conventions

- Storage controller module A installed into upper slot of the controller enclosure.
- Storage controller module B installed into bottom slot of the controller enclosure and is available for only dual-controller configuration.
- IP addresses of network ports of the above controllers hereinafter referred to as <controller-a-ipaddr> and <controller-b-ipaddr> respectively.

Viewing System Status

- 1. On NM Client, run Internet Explorer and in the web browser address field, type https://<controller-a-ipaddr>/ and press Enter. Login in to RAIDar management webpage using username manage.
- 2. In the **Configuration View** panel, right-click the system and select **View > Overview**. Be sure that the system health status is OK. If system health status is not OK, please capture screenshots of the errors/alarms/warnings and DAS logs. This information will be requested when contacting the SSC for support.

Shutting Down Virtual Machines

Shut down all virtual machines, which use this storage controller enclosure as their datastore (be sure you completed it for all ESXi hosts connected to this storage controller enclosure).



Proceed to the appropriate chapter depending on the storage controller enclosure configuration:

For single-controller storage enclosure, continue with chapter Appendix A > Single-Controller Configuration.

For dual-controller storage enclosure, continue with chapter Appendix A > Dual-Controller Configuration.

Single-Controller Configuration

Management Controller Restart

Perform a restart of the Management Controller A:

- 1. Run Internet Explorer.
- 2. Sign in to RADar management webpage https://controller-a-ipaddr>/ using username manage.
- 3. In the Configuration View panel, right-click the local system and select Tools > Shut Down or Restart Controller.
- 4. In the main panel, set the options:
 - a. Select the Restart operation.
 - b. Select the type of controller processor to restart Management.
 - c. Select to restart the processor in controller A.
- 5. Click **Restart now**. A confirmation dialog appears.
- 6. Click **Yes** to continue, a second confirmation dialog appears.
- 7. Click **Yes** to continue, a message describes restart activity.

The restart should take approximately two minutes. Once the restart is complete, the log-in page appears. Continue as soon as you can successfully login back to https://controller-a-ipaddr>/

Updating Controller-Module Firmware

To update controller-module firmware:

- In the Configuration View panel, right-click the system and select Tools > Update Firmware. The table titled Current Controller Versions shows the currently installed versions.
- 2. Click **Browse** and navigate to the *Dothill Firmware Media*. Search a file with extension .bin in directory \firmware\DH3520\.
- 3. Select the found firmware file to install and click **Open**.
- 4. Click **Install Controller-Module Firmware File**. A dialog box shows firmware-update progress. The process starts by validating the firmware file:
 - a. If the file is invalid, verify that you specified the correct firmware file. If you did, try downloading it again from the source location.
 - b. If the file is valid, the process continues.
- 5. When firmware upload starts user will see a progress screen, user will be automatically signed out after the upload finishes and the Management Controller A will restart. Until the restart is complete, the RAIDar Sign In page will be unavailable. Wait around 15 minutes until the user can login to the controller's RAIDar Sign page.
- 6. In the Internet Explorer, click **Gear icon** and then select **Internet Options**. In **Internet Options** window, click **Delete** in **Browsing history** section. In a new window, check the following checkboxes: **Temporary Internet files and website files** and **Cookies and website data**, and click **Delete**.
- 7. Then sign in back to RAIDar webpage https://controller-a-ipaddr>/.

Final Check


- 1. Right-click the top item of the tree in the **Configuration View** panel.
- 2. Select Tools > Update Firmware.
- 3. Result: The table titled Current Controller Versions shows the currently installed versions.
- 4. In the **Current Controller Versions** table, verify that the **Bundle Version** value for Controller A is equal to the name of the file that you selected earlier for the firmware update.

Dual-Controller Configuration

Disabling PFU

- 1. Run Internet Explorer.
- 2. Sign in to RADar management webpage https://controller-a-ipaddr>/ using username manage.
- 3. Right-click the top item of the tree in the **Configuration View** pane tree hierarchy. Click **Configuration > Advanced Settings > Firmware**.
- 4. Verify that the check box for **Partner Firmware Update** is unchecked. If it is checked then clear it and **Apply** your changes.

Firmware Update



Perform the following instructions below for controller A first. As soon as firmware update for the controller A is finished successfully repeat the same instruction for controller B.

Management Controller Restart

Restart the Management Controller in the controller to be updated. To perform a restart:

- 1. In the Configuration View panel, right-click the local system and select Tools > Shut Down or Restart Controller.
- 2. In the main panel, set the options:
 - a. Select the **Restart** operation.
 - b. Select the type of controller processor to restart Management.
 - c. Select to restart the processor in controller A(B).
- 3. Click **Restart now**. A confirmation dialog appears.
- 4. Click **Yes** to continue, a second confirmation dialog appears.
- 5. Click **Yes** to continue, a message describes restart activity.

The restart should take approximately two minutes. Once the restart is complete, the log-in page appears. Continue as soon as you can successfully login back to https://controller-a-ipaddr>/(https://controller-b-ipaddr>/).

Updating Controller-Module Firmware

To update controller-module firmware:

- 1. In the **Configuration View** panel, right-click the system and select **Tools > Update Firmware**. The table titled **Current Controller Versions** shows the currently installed versions.
- 2. Click **Browse** and navigate to the *Dothill Firmware Media*. Search a file with extension .bin in directory \firmware\DH3520\.
- 3. Select the found firmware file to install and click **Open**.
- 4. Click **Install Controller-Module Firmware File**. A dialog box shows firmware-update progress. The process starts by validating the firmware file:
 - a. If the file is invalid, verify that you specified the correct firmware file. If you did, try downloading it again from the source location.
 - b. If the file is valid, the process continues.
- 5. When firmware update on the controller A(B) is complete, user is automatically signed out and the Management Controller A(B) will restart. Until the restart is complete, the RAIDar Sign In page will say that the system is currently unavailable. Wait until this message is cleared.
- 6. In the Internet Explorer, click **Gear icon** and then select **Internet Options**. In **Internet Options** window, click **Delete** in **Browsing history** section. In a new window, check the following checkboxes: **Temporary Internet files and website files** and **Cookies and website data**, and click **Delete**.

7. Then sign in back to RAIDar webpage https://controller-a-ipaddr>/.

Final Check

- 1. Right-click the top item of the tree in the **Configuration View** panel.
- 2. Select Tools > Update Firmware.
- 3. Result: The table titled **Current Controller Versions** shows the currently installed versions.
- 4. In the **Current Controller Versions** table, verify that the **Bundle Version** value for Controller A(B) is equal to the name of the file that you selected earlier for the firmware update.

Appendix B: Updating HP DL380 Gen9 BIOS/iLO Firmware and VMware ESXi

Conventions	7
Preparing for Service Mode	7
Changing the ESXi Host Boot Order	7
Uploading Software Depot to the ESXi	8
Updating the Host Firmware and ESXi Software	8



If you are about to apply this procedure in the time when symptom #1 is observable, please apply instructions in <u>WORKAROUNDS AND CORRECTIVE ACTIONS</u> section of this document before continuing.



Please contact SSC team for further assistance in case of an abnormal completion of any step or unsuccessful execution of any script within the scope of this procedure.



Perform all steps consequently; run next script only after the previous script's execution is completed. Always wait until a script completes its execution.

Conventions

- <ilo_ipaddr> an IP address of iLO network port, where iLO web interface available.
- <cd_drive> a drive letter assigned to CD-ROM or DVD-ROM disc drive in your NM client.
- <esxi_ipaddr> an IP address of network management port of the affected ESXi host (VMS).

Preparing for Service Mode

- 1. Insert HP Firmware Install Media disc into the ESXi host's (VMS) optical disc drive.
- 2. Insert the VMware Vsphere Upgrade Media disc into the optical drive of the NM Client.
- 3. Run VMware vSphere Client on your NM Client and login in to the affected ESXi host using <esxi_ipaddr> and account root.
- 4. Disable (if applicable) and then shut down all virtual machines, which are running on the affected ESXi host (VMS).
- 5. Browse to the host in the vSphere Web Client navigator, then Right-click the host and select **Maintenance Mode** > **Enter Maintenance Mode**.

Changing the ESXi Host Boot Order

Run Internet Explorer and in the web browser address field, type https://<ilo_ipaddr>/ and press Enter. Login in to iLO web interface using username Administrator.

Click **Expand All** on the top-left corner of the page and in the navigation tree view on the left side of the page, click **Boot Order**. Select an **CD/DVD Drive** option from the **Select One-Time Boot Option** list and click **Apply**.

Uploading Software Depot to the ESXi

Open an Administrator Command Prompt window (run as administrator) on an NM Client and at this command prompt, run powershell.exe command.

At the PowerShell prompt, change directory to <cd_drive>:\bin and then run two commands in series;

```
Start-Transcript
.\upload-patches.ps1
```

At the dialogue's questions prompt, enter corresponding answers (values): <esxi_ipaddr>, password of this ESXi root account, and a path to depot - <cd_drive>: \depot. Confirm your entered values by entering y character.

During execution, upload-patches.ps1 script outputs a path string started with /vmfs and ended with /depot. Save this path string since it is required to use it in steps below (hereinafter referred to as <depot_path>).

Updating the Host Firmware and ESXi Software

Open a command prompt window as Administrator (run as administrator) on your NM client and at this command prompt, run powershell.exe command.

At the PowerShell prompt, change directory to <cd_drive>:\bin and then run two commands in series;

```
Start-Transcript
.\upgrade-esxi.ps1 -noreboot
```

At the dialogue's questions prompt, enter corresponding answers (values): <esxi_ipaddr>, password of this ESXi root account, and the path string to depot <depot_path>. Confirm your entered values by entering y character.

Run VMware vSphere Client on your NM Client and login in to the affected ESXi host using <esxi_ipaddr> and account root.

Browse to the host in the vSphere Web Client navigator, then Right-click the host and select **Maintenance Mode > Exit Maintenance Mode**.

Browse to the host in the vSphere Web Client navigator, then Right-click the host and select **Reboot**. Provide a reason for the reboot.



Please be noted that further steps are executed automatically with the following process:

- Rebooting
- Booting HP Firmware Install Media disc
- *Updating the host firmware*
- Rebooting
- Updating of ESXi hypervisor
- Rebooting
- Starting the ESXi hypervisor



Upgrade Operations Software Team

Software Order Form Phone Number: (800) 221-7144

SECTION 1: Ge	neral Information			
NOTE: PRICE QUOTES	GIVEN BY UOST ARE VALI	ID FOR ONLY 90 DAYS		
	Date		Case Number	
	System ID		Site ID	
	System Name		Site Name	
	Customer		•	
	Name		_	
	Famos			
	Form		Field Contact	
	Completed by		Field Contact	
			Organization	
	Phone		Dhana Numban	
	Number		Phone Number	
	Pager Number		Pager Number	
	Fax Number		Fax Number	
SECTION 2: Or	der Information			
Product Type:			Serial Number	
	are / Hardware Chang , list current and targe	-		
-	_			
Software / Hardw	are Description:			
Part # or Version	# 		Quantity	
Date Required				
SECTION 3: Sh	ipping / Billing Info	ormation		
Ship To:			Bill To:	
			-	
Email:			-	
Attn:			Attn:	
Aun.			- Au.	
Phone:			Phone:	
	Cuetemen Billin			Internal Dilling
P.O. #:	Customer Billing		PROJECT #:	Internal Billing
CUST #:			FSB #:	
TAG #:			DEPT #:	
17.0 11.			APC #:	
			m = m.	



Software Order Form

Phone Number: (800) 221-7144

Upgrade Operations Software Team

- This form has been sent to you because you have requested an order from the Upgrade Operations Software Team.
- Please fill out the order form and email back to the Upgrade Operations Software Team
- ° If desired, please provide your email address on the order form and we will provide a tracking number when your order ships for your convenience.
- ° Orders will normally be processed in 3-5 business days once all information has been received.
- of If additional space is required for software information, please use the optional addendum on page 3 below in addition to the original order form. This form is for use with large orders with multiple part numbers.

NOTE:

- 1) If this in an SSA CUSTOMER please order via Motorola factory order.
- 2) Limited Liability is Implied to the maximum of order amount.
- 3) Price quotes provided by UOST are valid for 90 days

Thank you and have a good day!

Supplemental Order Information Addendum

(Optional)

Software Description		
Part# or Version #		
Quantity:		
Software Description		
Part# or Version #		
Quantity:	 -	
Software Description		
Part# or Version #		
Quantity:		
Software Description		
Part# or Version #		
Quantity:	_	
Software Description		
Part# or Version #		
Quantity:		
Software Description		
Part# or Version #		
Quantity:	 	