

## Motorola Solutions Technical Notification (MTN)


**TITLE:** "NAND" flash devices may not initialize or mount properly, which may cause a variety of symptoms on HP DL3x0 Servers

**TECHNOLOGY:** All ASTRO releases in the RNI and CEN using HPE DL380 Gen8 and Gen9 servers

### **SYMPTOMS:**

**May include 1 or more of the following Symptoms**

1. During HPE firmware upgrade, after reboot, server is stuck in a reboot loop
2. During System upgrade:
  - a. ESXi fails to upgrade with the message (Reason: Unable to partition Embedded media device)
  - b. After upgrading iLO on Gen9 server to newer version "Configure-ASTROBiosSettings.ps1" script fails on:Update-biossettings() "Cannot bind argument to parameter 'suburi' because it is an empty string"
3. iLO Password was reset to default or iLO License was cleared out after HP Firmware Install
4. iLO event logs show an error message: "Embedded Flash/SD-CARD: Embedded media manager failed initialization"
5. The iLO Diagnostic tab will display the following error message:
  - a. "Embedded media manager failed initialization"
  - b. "The AHS file system mount failed with (No such device)"
  - c. "The AHS file system mount failed with (I/O error)"
  - d. "Controller firmware revision 2.xx.xx Could not partition embedded media device"
  - e. "Embedded Media Manager encountered SL\_AbortHandler during init"
  - f. "Embedded Media initialization failed due to media write-verify test failure"
6. Intelligent Provisioning will not execute when selecting F10.
7. A yellow splash window appears on the iLO interface. The example is from iLO 2.60, but is essentially the same for iLO 2.61.



### **MODELS / SYSTEM RELEASES / KITS / DATECODES AFFECTED:**

HPE Gen8 and HPE Gen9 servers with iLO software lower than 2.61 or 2.61 software with yellow splash screen

### **SEVERITY RECOMMENDATION:**

**Medium / Operational** - Schedule to implement locally using physical media.

ANY USE NOT APPROVED BY MOTOROLA SOLUTIONS IS PROHIBITED. This Motorola Technical Notification (MTN) is issued pursuant to Motorola's ongoing review of the quality, effectiveness, and performance of its products. The information provided in this bulletin is intended for use by trained, professional technicians only, who have the expertise to perform the service described in the MTN. Motorola disclaims any and all liability for product quality or performance if the recommendations in this MTN are not implemented, or not implemented in compliance with the instructions provided here. Implementation of these recommendations may be necessary for the product to remain compliant with applicable laws or regulations. Please be advised, that failure to implement these recommendations in the manner instructed may also invalidate applicable warranties, or otherwise impact any potential contractual rights or obligations. MOTOROLA, MOTO, MOTOROLA SOLUTIONS, and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. ©2016 Motorola Solutions, Inc. All rights reserved."

**ROOT CAUSE / DEFINITIVE TEST:**

HPE has confirmed that the problem is a hardware level issue, where the system board contains a non-replaceable memory chip, which reaches a read/write cycle limit after multiple reads and writes.

**WORKAROUNDS AND CORRECTIVE ACTIONS:**

There is no definitive workaround that will work each time. The most reliable and common one is to:

1. Shut down virtual machines
2. Shut down server (completely power off the server)
3. Unplug power cords
4. Wait around 5 minutes
5. Plug in the power cords
6. Power up the server

**NOTE:** After a workaround is done successfully, if iLO version is lower than 2.61, upgrade it using media from PARTS REQUIRED Section.

**RESOLUTIONS AND REPAIR PROCEDURES:**

- If **WORKAROUNDS AND CORRECTIVE ACTIONS** section does not resolve the issue and the server will not boot, upgrade using HPE Firmware DVD from PARTS REQUIRED Section.
- If after applying the HPE Firmware DVD and the issues / symptoms still persist contact SSC at 1-800-221-7144 .

Upgrade to the appropriate version as listed in the "**PARTS REQUIRED (HARDWARE/SOFTWARE):**" section below, based on the model.

1. **To obtain software:**
2. Initiate a software request case through Motorola Solutions, Inc. System Support Center (SSC) at 1-800-221-7144 (1-302-444-9800)
3. Await confirmation email from UOST with instructions
4. Complete the Upgrade Operations Software Team (UOST) Software Order Form:
  - a. Reference **MTN-0018-19-NA** in the 'Reason for Software/Hardware Change' section of the software order form.
  - b. List the part number (**KC #** as listed under "**PARTS REQUIRED (HARDWARE/SOFTWARE):**" below) in the 'Part # or Version #' section of the software order form.
  - c. Email completed Software Order Form to UOST for processing

**PARTS REQUIRED (HARDWARE/SOFTWARE):**

HPE Firmware DVD for Gen8 (KC877L0DN000071702)

HPE Firmware DVD for Gen9 (KC877L0DK000071702)

**ADDITIONAL INFORMATION:**

New HPE firmware provides additional server diagnostics on various components. Problems not identified in older versions of HPE firmware may appear with the update.

**REFERENCE THE FOLLOWING DOCUMENTS/PROCESSES FOR INSTALLATION PROCEDURES:**

- Confirm recent backup of all servers to the BAR server incorporates that latest system changes
- Transfer backups to offline NAS or export to offline ISO files and transfer to storage separate from ESXi server/DAS
- Schedule server downtime with the system manager using these rough time guidelines:
- All VMs on the ESXi server must be disabled (if applicable) and shutdown.
- Shutdown the ESXi server.
- Perform the HPE Firmware update using the necessary steps in Manual "Virtual Management Server Software" section "Updating BIOS and iLO Firmware" starting with the insertion of the of the installation media on the optical drive.
- Offline Update - Generally allow approximately 60 minutes per server
- Re-enable VMs as necessary and confirm normal system operations

**WHEN TO APPLY RESOLUTION:**

After reboot \_\_\_  
After (re)installation \_\_\_  
After upgrade \_\_\_  
After power cycle \_\_\_  
After database restoration \_\_\_  
After failure \_\_\_  
On FRU replacement \_\_\_  
During maintenance **X**  
Immediately \_\_\_  
As instructed **X**  
Information only \_\_\_

**LABOR ALLOWANCE:**

This is an informational bulletin. No labor warranty is implied, intended or authorized for U.S. Domestic Partners/Customers. Other regions should follow their own standard procedures.

For assistance with this bulletin please contact your MSI Technical support centre

[https://www.motorolasolutions.com/en\\_us/support.html](https://www.motorolasolutions.com/en_us/support.html)

*Upgrade Operations Software Team**Software Order Form*

Phone Number: (800) 221-7144

**SECTION 1: General Information**

NOTE: PRICE QUOTES GIVEN BY UOST ARE VALID FOR ONLY 90 DAYS

Date \_\_\_\_\_  
System ID \_\_\_\_\_  
System Name \_\_\_\_\_  
Customer  
Name \_\_\_\_\_

Case Number \_\_\_\_\_  
Site ID \_\_\_\_\_  
Site Name \_\_\_\_\_

Form  
Completed by \_\_\_\_\_  
Organization \_\_\_\_\_  
Phone  
Number \_\_\_\_\_  
Pager  
Number \_\_\_\_\_  
Fax Number \_\_\_\_\_

Field Contact \_\_\_\_\_  
Organization \_\_\_\_\_  
Phone Number \_\_\_\_\_  
Pager Number \_\_\_\_\_  
Fax Number \_\_\_\_\_

---

**SECTION 2: Order Information**

Product Type: \_\_\_\_\_

Serial Number \_\_\_\_\_

Reason for Software / Hardware Change: \_\_\_\_\_

Downgrade? If so, list current and target releases. \_\_\_\_\_

Software / Hardware Description: \_\_\_\_\_

Part # or Version # \_\_\_\_\_

Quantity \_\_\_\_\_

Date Required \_\_\_\_\_

---

**SECTION 3: Shipping / Billing Information**

Ship To: \_\_\_\_\_  
\_\_\_\_\_

Bill To: \_\_\_\_\_  
\_\_\_\_\_

Email: \_\_\_\_\_  
Attn: \_\_\_\_\_

Attn: \_\_\_\_\_

Phone: \_\_\_\_\_

Phone: \_\_\_\_\_

**Customer Billing**

P.O. #: \_\_\_\_\_  
CUST #: \_\_\_\_\_  
TAG #: \_\_\_\_\_

**Internal Billing**

PROJECT #: \_\_\_\_\_  
FSB #: \_\_\_\_\_  
DEPT #: \_\_\_\_\_  
APC #: \_\_\_\_\_

## ***Software Order Form***

*Upgrade Operations Software Team*

Phone Number: (800) 221-7144

- ° This form has been sent to you because you have requested an order from the Upgrade Operations Software Team.
- ° Please fill out the order form and email back to the Upgrade Operations Software Team
- ° If desired, please provide your email address on the order form and we will provide a tracking number when your order ships for your convenience.
- ° Orders will normally be processed in 3-5 business days once all information has been received.
- ° If additional space is required for software information, please use the optional addendum on page 3 below in addition to the original order form. This form is for use with large orders with multiple part numbers.

**NOTE:**

- 1) If this is an SSA CUSTOMER please order via Motorola factory order.
- 2) Limited Liability is Implied to the maximum of order amount.
- 3) Price quotes provided by UOST are valid for 90 days

***Thank you and have a good day!***

# ***Supplemental Order Information Addendum***

(Optional)

Software Description

---

Part# or Version #

---

Quantity:

---

Software Description

---

Part# or Version #

---

Quantity:

---

Software Description

---

Part# or Version #

---

Quantity:

---

Software Description

---

Part# or Version #

---

Quantity:

---

Software Description

---

Part# or Version #

---

Quantity:

---

