

DOCUMENT NUMBER: **MTN-0024-25**ISSUE DATE: **2025-03**

MOTOROLA SOLUTIONS TECHNICAL NOTIFICATION (MTN)

Title

The CommandCentral AXS Dispatch Console resets when the USB headset or USB microphone is connected while a long alert tone is playing

Technology

ASTRO® 25

Severity Recommendation

Medium/Operational - Schedule to implement during the maintenance window.

Symptoms

Connecting USB devices (microphone or headset) to the AXS console while an Alert Tone is being transmitted on the console may cause the console to reset. When this occurs, the console will return to operation after approximately 1 minute. This issue may only occur when connecting USB accessories and only during an Alert Tone transmission.

Models / System Releases / Kits / Datecodes Affected

| System Release | Name / SW version |
|---|--|
| A2022.1 / A2022.HS / AN2024.1 / AN2024.HS | CommandCentral AXS Dispatch Console software version 3.4.159 |

When To Apply

During maintenance

Resolution And Repair Procedure

Upgrade to the appropriate version as listed in the "Software/Hardware Parts Required" section below, based on the model.

To obtain software:

1. Initiate a software request case through Motorola Solutions, Inc. Centralized Managed Support Operations (CMSO) - see contact numbers at <https://motorolasolutions.com/support> (for NA call directly: 800-MSI-HELP (800-674-4357) or 302-444-9800)
2. Await confirmation email from Motorola Solutions Software Factory (MSSF) with instructions
3. Complete the Motorola Solutions Software Factory Software Order Form:
 - Reference MTN-0024-25 in the 'Reason for Software/Hardware Change' section of the software order form.

MOTOROLA SOLUTIONS TECHNICAL NOTIFICATION

ANY USE NOT APPROVED BY MOTOROLA SOLUTIONS IS PROHIBITED. This Motorola Technical Notification (MTN) is issued pursuant to Motorola's ongoing review of the quality, effectiveness, and performance of its products. The information provided in this bulletin is intended for use by trained, professional technicians only, who have the expertise to perform the service described in the MTN. Motorola disclaims any and all liability for product quality or performance if the recommendations in this MTN are not implemented, or not implemented in compliance with the instructions provided here. Implementation of these recommendations may be necessary for the product to remain compliant with applicable laws or regulations. Please be advised that failure to implement these recommendations in the manner instructed may also invalidate applicable warranties, or otherwise impact any potential contractual rights or obligations. MOTOROLA, MOTO, MOTOROLA SOLUTIONS, and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. © 2023 Motorola Solutions, Inc. All rights reserved.

| | |
|------------------|--------------------|
| DOCUMENT NUMBER: | MTN-0024-25 |
| ISSUE DATE: | 2025-03 |

- List the part number (KC # as listed under "Software Parts Required" below) in the 'Part # or Version #' section of the software order form.
4. Email completed Software Order Form to MSSF for processing

Time To Implement/System Impact

Estimated time to implement - per operator position - 15 min

High - Loss of functionalities/audio/downtime - Operator position will be unavailable for 15 minutes (during the software installation)

Software Parts Required

| System Release | Name / SW version | |
|---|--|-----------------------------|
| A2022.1 / A2022.HS / AN2024.1 / AN2024.HS | CommandCentral AXS Dispatch Console software version 3.4.160 and later | KC504V00E000250002 or later |

Reference The Following Documents/Processes For Installation Procedures

AXS Dispatch Console Installation Guide - MN010309A01-J

Chapter 2: Installing the AXS Dispatch Console Inside the RNI

Labor Allowance

This is an informational bulletin. No labor warranty is implied, intended, or authorized.

For assistance with this bulletin please contact your MSI Technical Support Centre at <https://motorolasolutions.com/support>

MOTOROLA SOLUTIONS TECHNICAL NOTIFICATION

ANY USE NOT APPROVED BY MOTOROLA SOLUTIONS IS PROHIBITED. This Motorola Technical Notification (MTN) is issued pursuant to Motorola's ongoing review of the quality, effectiveness, and performance of its products. The information provided in this bulletin is intended for use by trained, professional technicians only, who have the expertise to perform the service described in the MTN. Motorola disclaims any and all liability for product quality or performance if the recommendations in this MTN are not implemented, or not implemented in compliance with the instructions provided here. Implementation of these recommendations may be necessary for the product to remain compliant with applicable laws or regulations. Please be advised that failure to implement these recommendations in the manner instructed may also invalidate applicable warranties, or otherwise impact any potential contractual rights or obligations. MOTOROLA, MOTO, MOTOROLA SOLUTIONS, and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. © 2023 Motorola Solutions, Inc. All rights reserved.