

Motorola Solutions Technical Notification (MTN)

TITLE: Key Management Facility (KMF) Server application stops working.

TECHNOLOGY: ASTRO 25

SYMPTOMS: The KMF application stops working. A status check of the KMF Server Service shows it is not running. If the KMF is configured to support redundancy and to switchover automatically, a switchover does not occur on a KMF failure. The KMF that failed, remains in the active state. While in this state, a manual switchover to the Standby KMF can be performed successfully. If another manual switchover from the Standby KMF back to the Main KMF is performed, the switchover and the starting of the Main KMF application are successful.

This issue will be seen if a remote KMF Client PC remains logged into the KMF Server for an extended period of time (after several weeks). The KMF Client login will not time out when the Operation Status screen is displayed.

MODELS / SYSTEM RELEASES / KITS / DATECODES AFFECTED:

KMF Software Application versions:

R07.18.0442

R10.00.0523 - R10.01.0050

SEVERITY RECOMMENDATION:

High / Safety - Perform Immediately

ROOT CAUSE:

3rd party software defect

DEFINITIVE TEST:

NA

WORKAROUNDS AND CORRECTIVE ACTIONS:

As a best practice it is recommended to logout whenever you are not actively using KMF - this would prevent the issue from occurring.

If the KMF experiences the symptoms above, restarting the KMF Server Service will clear the problem. However, this does not prevent the symptoms from occurring again.

RESOLUTIONS AND REPAIR PROCEDURES:

Standalone KMF configuration:

1. Log on to the KMF Server with local Windows Administrator privileges.
2. Check the status of the KMF Server Service. If the service is not running, start the service.
 - To check and/or start the KMF Server Service, refer to the section titled, *KMF Server Management*, in the Key Management User Guide.
3. Log into the KMF Client and backup the database.
 - Refer to the section titled, *Backing Up the Active KMF Server Manually*, in the Key Management User Guide.
4. Stop the KMF Server Service.
 - Refer to the section titled, *KMF Server Management*, in the Key Management User Guide.
5. Open Windows Explorer and navigate to C:\Program Files (x86)\Motorola\KMF Server\server\standalone\configuration.
6. Open the file, standalone.xml. Perform the following modification:
`<buffer-pool name="default"/>`
to
`<buffer-pool name="default" direct-buffers="false"/>`
7. Save and close the file.
8. Reboot the KMF Server.

Redundant KMF configuration:

1. Perform the following steps on the Standby KMF Server.
 - a. Log on to the Standby KMF Server with local Windows Administrator privileges.
 - b. If the Standby KMF Server is active, perform a manual switchover to the Main KMF Server.
 - Refer to the section titled, *Performing the KMF Server Switchover Manually*, in the Key Management User Guide.
 - c. Open Windows Explorer and navigate to C:\Program Files (x86)\Motorola\KMF Standby Server\server\standalone\configuration.
 - d. Execute steps 6 - 8 in the Standalone KMF procedure above.
2. On the Main KMF Server, execute the Standalone KMF procedure above.

Note: For KMFs that support redundancy, two switchover operations and two server reboots executed during the patching process will cause the KMF service to be not operational for up to 25 minutes.

PARTS REQUIRED (HARDWARE/SOFTWARE):

NA

ADDITIONAL INFORMATION:

No software update required.

DOCUMENT NUMBER: MTN-0038A-22-NA

APC: 137

ISSUE DATE: 03-2022

EXPIRATION DATE: 31-03-2023

Bulletin Type: Informational Only

REFERENCE THE FOLLOWING DOCUMENTS/PROCESSES FOR INSTALLATION PROCEDURES:

Key Management User Guide

R07.18.0442:

MN006220A01-G

R10.00.0523 - R10.01.0050:

MN007432A01-D

WHEN TO APPLY RESOLUTION:

Immediately _x_

LABOR ALLOWANCE:

This is an informational bulletin. No labor warranty is implied, intended or authorized for U.S. Domestic Partners/Customers. Other regions should follow their own standard procedures.

If, after attempting to perform the solution steps, you are having issues with the resolution in the MTN then please contact your MSI Technical support center.

https://www.motorolasolutions.com/en_us/support-topics.html

SW ORDER FORM IS AVAILABLE UNDER THE LINK:

http://www.motorolasolutions.com/content/dam/msi/docs/robots/motorola-technical-notification/SW_order_form.pdf

ANY USE NOT APPROVED BY MOTOROLA SOLUTIONS IS PROHIBITED. This Motorola Technical Notification (MTN) is issued pursuant to Motorola's ongoing review of the quality, effectiveness, and performance of its products. The information provided in this bulletin is intended for use by trained, professional technicians only, who have the expertise to perform the service described in the MTN. Motorola disclaims any and all liability for product quality or performance if the recommendations in this MTN are not implemented, or not implemented in compliance with the instructions provided here. Implementation of these recommendations may be necessary for the product to remain compliant with applicable laws or regulations. Please be advised, that failure to implement these recommendations in the manner instructed may also invalidate applicable warranties, or otherwise impact any potential contractual rights or obligations. MOTOROLA, MOTO, MOTOROLA SOLUTIONS, and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. ©2021 Motorola Solutions, Inc. All rights reserved.