

DOCUMENT NUMBER: MTN-0049-20-NA

APC: 877 ISSUE DATE: 04-2020

EXPIRATION DATE: 30-04-2021

**Bulletin Type: Informational Only** 

# Motorola Solutions Technical Notification (MTN)

TITLE: New IMW software versions resolve multiple issues as defined in the SYMPTOM section

**TECHNOLOGY: ASTRO25** 

#### **SYMPTOMS:**

Note: Please see Appendix-A for 5.2.1 and Appendix B for 5.2.2 additional symptom details

#### MODELS / SYSTEM RELEASES / KITS / DATECODES AFFECTED:

IMW 5.2.1 release prior to 5.2.1.013 IMW 5.2.2 release prior to 5.2.2.110

#### **SEVERITY RECOMMENDATION:**

Low / Maintenance - Perform if system exhibits above symptoms

#### **ROOT CAUSE / DEFINITIVE TEST:**

Software Defect

#### **WORKAROUNDS AND CORRECTIVE ACTIONS:**

#### **RESOLUTIONS AND REPAIR PROCEDURES:**

Upgrade to the appropriate version as listed in the "PARTS REQUIRED (HARDWARE/SOFTWARE):" section below, based on the model.

#### To obtain software:

- 1. Initiate a software request case through Motorola Solution, Inc. System Support Center (SSC) at 1-800-221-7144 (1-302-444-9800)
- 2. Await confirmation email from Motorola Solutions Software Factory with instructions
- 3. Complete the Motorola Solutions Software Factory Software Order Form:
  - Reference MTN-0049-20-NA in the 'Reason for Software/Hardware Change' section of the software order form.
  - b. List the part number (KC # as listed under "PARTS REQUIRED (HARDWARE/SOFTWARE)" below) in the 'Part # or Version #' section of the software order form.
- 4. Email completed Software Order Form to the Motorola Solutions Software Factory for processing

#### PARTS REQUIRED (HARDWARE/SOFTWARE):

KC232L06K000522001

#### **ADDITIONAL INFORMATION: .**

#### REFERENCE THE FOLLOWING DOCUMENTS/PROCESSES FOR INSTALLATION PROCEDURES:

ReadMe file on media content.

#### WHEN TO APPLY RESOLUTION:

After reboot	
After (re)installation _	
After upgrade	

ANY USE NOT APPROVED BY MOTOROLA SOLUTIONS IS PROHIBITED. This Motorola Technical Notification (MTN) is issued pursuant to Motorola's ongoing review of the quality, effectiveness, and performance of its products. The information provided in this bulletin is intended for use by trained, professional technicians only, who have the expertise to perform the service described in the MTN. Motorola disclaims any and all liability for product quality or performance if the recommendations in this MTN are not implemented, or not implemented in compliance with the instructions provided here. Implementation of these recommendations may be necessary for the product to remain compliant with applicable laws or regulations. Please be advised, that failure to implement these recommendations in the manner instructed may also invalidate applicable warranties, or otherwise impact any potential contractual rights or obligations. MOTOROLA, MOTO, MOTOROLA SOLUTIONS, and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. ©2016 Motorola Solutions, Inc. All rights reserved."

After power cycle
After database restoration
After failure
On FRU replacement
During maintenance
Immediately
As instructed _X_
Information only

## **LABOR ALLOWANCE:**

This is an informational bulletin. No labor warranty is implied, intended or authorized for U.S. Domestic Partners/Customers. Other regions should follow their own standard procedures.

For assistance with this bulletin please contact your MSI Technical support center <a href="https://www.motorolasolutions.com/en-us/support.html">https://www.motorolasolutions.com/en-us/support.html</a>

## Appendix A – Resolution details for IMW 5.2.1.013

**Abstract:** MongoDB log file does not rotate **System Platforms Affected:** IMW 5.2.1

Special Configurations: N/A

User Symptoms: MongoDB log files constantly growing without any rotation mechanism, causing disk space

exhaustion.

Abstract: LRRP Api does not send notification about presence status change

System Platforms Affected: IMW 5.2.1

Special Configurations: Astro

User Symptoms: LRRP Api client will not get presence status update

Abstract: Reporting threshold changes with cadence change from 3rd party application tied into IMW

System Platforms Affected: IMW 5.2.1

Special Configurations: Astro

User Symptoms: Change cadence operation performed on LRRP API accidentally turned off threshold parameter.

**Abstract**: Emergency GPS time inaccurate **System Platforms Affected**: IMW 5.2.1

Special Configurations: Astro

User Symptoms: Location report without GPS included cause time increment on IMW and triggered notification

update to LRRP client application

Abstract: Sensor Profile update changes not reflected on ASTRO radio

System Platforms Affected: IMW 5.2.1

Special Configurations: Astro

User Symptoms: Core Sensor service restart is needed to have configuration changes completed.

Abstract: UNS Presence service reaches restart limit

System Platforms Affected: IMW 5.2.1

**Special Configurations:** Astro

User Symptoms: Querying for non existing devices via PN Watcher interface causes service to restart. Few

occurrences could trigger switchover in case of redundant configuration

Abstract: Button Reset UNS provisioning Data in AdminClient crash IMW data

System Platforms Affected: IMW 5.2.1

Special Configurations: N/A

User Symptoms: In case of clicking 'Reset UNS provisioning data' button IMW Presence stopped to communicate

with other services and external APIs.

Abstract: Core VM out of memory caused unplanned IMW switchover

System Platforms Affected: IMW 5.2.1

Special Configurations: N/A

User Symptoms: Discovery service memory consumption constantly growing and in case of no restart for a few

months, out of memory exception can occur.

Abstract: CoreLocation dropping location reports when astro devices share ip addresses

System Platforms Affected: IMW 5.2.1

Special Configurations: Astro

**User Symptoms:** In case small IP pool or dropping presence deregistration message an issue may occur where Core Location service have incorrect IP assigned to device ID. As a result location reports are dropped and not sent to client application.

# Appendix B - Resolution details for IMW 5.2.2.110

Abstract: UNS Presence service reaches restart limit

**System Platforms Affected: IMW** 5.2.2

Special Configurations: Astro

User Symptoms: Querying for non existing devices via PN Watcher interface causes service to restart. Few

occurrences could trigger switchover in case of redundant configuration.

Abstract: When quickly close was subscription, it might be not correctly removed from system, what will cause

memory leak

System Platforms Affected: IMW 5.2.2

Special Configurations: N/A

User Symptoms: Web socket subscription opened and closed very quickly, may cause subscription removal issue

and memory that is constantly growing on AE machine.

Abstract: IMW Configuration Manager shows error when trying to edit device.

System Platforms Affected: IMW 5.2.2

**Special Configurations:** IMW with Presence license (no Location license)

User Symptoms: When IMW configured to work with Presence only an issue occurs when trying to edit device

parameters in Configuration Manager.

**Abstract**: Script to enable McAfee on RHEL **System Platforms Affected**: IMW 5.2.2

Special Configurations: Astro

User Symptoms: Deploying McAfee antivirus from CSMS is not possible on IMW RHEL without included script.



Software Order Form

Phone Number: (800) 221-7144

SECTION 1: Ge	neral Information			
NOTE: PRICE QUOTES	GIVEN BY UOST ARE VAL	ID FOR ONLY 90 DAYS		
	Date		Case Number	
	System ID		Site ID	
	System Name		Site Name	
	Customer			
	Name		_	
	Form			
	Completed by		Field Contact	
	Organization		Organization	
	Phone			
	Number		Phone Number	
	Pager Number		Pager Number	
	Fax Number		Fax Number	
SECTION 2: Or	der Information			
Product Type:			Serial Number	
			_	
Reason for Softwa	are / Hardware Chan	ge:		
Downgrade? If so	, list current and targ	et releases.		
Software / Hardwa	are Description:			
Part # or Version	#		Quantity	
Date Required				
<b>SECTION 3: Sh</b>	ipping / Billing Inf	ormation		
Ship To:			Bill To:	
omp ro.			-	
			_	
Email:			_	
Attn:			- Attn:	
Aun.			- Aui.	
Phone:			Phone:	
i floric.			-	
	Customer Billing			Internal Billing
P.O. #:	oustoiner bining		PROJECT #:	internal bining
CUST #:			FSB #:	
TAG #:			 DEPT #:	
$\pi$ .			_ APC #:	
			Ai 0 #.	



# Software Order Form

Phone Number: (800) 221-7144

Motorola Solutions Software Factory

- ° This form has been sent to you because you have requested an order from the Motorola Solutions Software Factory Team.
- ° Please fill out the order form and email back to the Motorola Solutions Software Factory Team
- ° If desired, please provide your email address on the order form and we will provide a tracking number when your order ships for your convenience.
- ° Orders will normally be processed in 3-5 business days once all information has been received.
- ° If additional space is required for software information, please use the optional addendum on page 3 below in addition to the original order form. This form is for use with large orders with multiple part numbers.

# NOTE:

- 1) If this in an SSA CUSTOMER please order via Motorola factory order.
- 2) Limited Liability is Implied to the maximum of order amount.
- 3) Price quotes provided by SCHSWF are valid for 90 days

Thank you and have a good day!

# Supplemental Order Information Addendum

(Optional)

Software Description		
Part# or Version #		
Quantity:		
Software Description		
Part# or Version #		
Quantity:		
Software Description		_
Part# or Version #		
Quantity:		
Software Description		
Part# or Version #		
Quantity:		
Software Description		
Part# or Version #		
Quantity:		
Software Description		
Part# or Version #		
Quantity:	 	