

DOCUMENT NUMBER: MTN-0050-22-NA

APC: 877

ISSUE DATE: 03-2022 EXPIRATION DATE: 31-03-2023

Bulletin Type: Informational Only

# Motorola Solutions Technical Notification (MTN)

TITLE: Unwanted logout entries in ESXi events log

**TECHNOLOGY: ASTRO 25** 

#### **SYMPTOMS:**

 When using the VMware ESXi Embedded Host Client, entries similar to the following may be displayed every 30 seconds under the Events window:

User root@127.0.0.1 logged out (login time: Friday, May 21, 2021 8:09:04 AM UTC, number of API invocations: 7, user agent: pyvmomi Python/3.5.9 (VMkernel; 7.0.2; x86\_64))

/var/log/syslog.log similar entries are seen:

2021-04-30T07:58:28Z root: vusb:

2021-04-30T07:58:28Z root: VIRTUAL NIC:\*\*\*\*NO VUSB0 AVAILABLE

2021-04-30T07:58:28Z root: Call wait loop

2021-04-30T07:58:28Z root: Virtual NIC: in wait loop

/var/log/hostd.log similar entries are seen:

2021-04-30T07:58:28Z info hostd[2101028] [Originator@6876 sub=Vimsvc.TaskManager opID=esxcli-39-7234 user=root]

Task Created: haTask--vim.EsxCLI.network.nic.list-1269523045

2021-04-30T07:58:28Z info hostd[2100413] [Originator@6876 sub=Vimsvc.TaskManager opID=esxcli-39-7237 user=root]

Task Created: haTask--vim.SessionManager.logout-1269523047

#### MODELS / SYSTEM RELEASES / KITS / DATECODES AFFECTED:

A2020.1 with ESXi 7.0, A2020.HSE and A2021.1 ESXi versions 7.0.1 and 7.0.2

# **SEVERITY RECOMMENDATION:**

Low / Maintenance - Perform if system exhibits above symptoms

#### **ROOT CAUSE:**

Third-party OS defect affecting MSI application

ANY USE NOT APPROVED BY MOTOROLA SOLUTIONS IS PROHIBITED. This Motorola Technical Notification (MTN) is issued pursuant to Motorola's ongoing review of the quality, effectiveness, and performance of its products. The information provided in this bulletin is intended for use by trained, professional technicians only, who have the expertise to perform the service described in the MTN. Motorola disclaims any and all liability for product quality or performance if the recommendations in this MTN are not implemented, or not implemented in compliance with the instructions provided here. Implementation of these recommendations may be necessary for the product to remain compliant with applicable laws or regulations. Please be advised that failure to implement these recommendations in the manner instructed may also invalidate applicable warranties, or otherwise impact any potential contractual rights or obligations. MOTOROLA, MOTO, MOTOROLA SOLUTIONS, and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. ©2021 Motorola Solutions, Inc. All rights reserved.



DOCUMENT NUMBER: MTN-0050-22-NA

APC: 877

ISSUE DATE: 03-2022 EXPIRATION DATE: 31-03-2023

Bulletin Type: Informational Only

#### **DEFINITIVE TEST:**

N/A

## **WORKAROUNDS:**

None - these messages can be safely ignored. There is no operational nor security impact.

# **CORRECTIVE ACTIONS:**

## **RESOLUTIONS AND REPAIR PROCEDURES:**

If you want these messages to disappear, you can use the following procedure:

- 1. Enable SSH service on the ESXi host.
  - See: Enabling/Disabling ESXi SSH Access in Virtual Management Server Software User Guide.
- 2. Login to ESXi using PuTTY
- 3. Execute following command:

```
ps -c | grep vnic
```

Example output: 527045 527045 sh /bin/sh /etc/init.d/vnicen.sh start 529575 529575 grep grep vnic

4. Execute following commands:

```
kill [PID of vnicen.sh]
chkconfig vnicen.sh off
```

Where [PID of vnicen.sh] is the first number in the line containing /etc/init.d/vnicen.sh of step 3 output. Example:

```
kill 527045 chkconfig vnicen.sh off
```

5. In order to confirm the settings are correct execute the following command:

```
chkconfig --list | grep vnicen
```

Expected output:

vnicen.sh off

6. Disable SSH service on the ESXi host.

See: Enabling/Disabling ESXi SSH Access in Virtual Management Server Software User Guide

In the event of disaster recovery or reinstallation this MTN needs to be reapplied.

ANY USE NOT APPROVED BY MOTOROLA SOLUTIONS IS PROHIBITED. This Motorola Technical Notification (MTN) is issued pursuant to Motorola's ongoing review of the quality, effectiveness, and performance of its products. The information provided in this bulletin is intended for use by trained, professional technicians only, who have the expertise to perform the service described in the MTN. Motorola disclaims any and all liability for product quality or performance if the recommendations in this MTN are not implemented, or not implemented in compliance with the instructions provided here. Implementation of these recommendations may be necessary for the product to remain compliant with applicable laws or regulations. Please be advised that failure to implement these recommendations in the manner instructed may also invalidate applicable warranties, or otherwise impact any potential contractual rights or obligations. MOTOROLA, MOTO, MOTOROLA SOLUTIONS, and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. ©2021 Motorola Solutions, Inc. All rights reserved.



DOCUMENT NUMBER: MTN-0050-22-NA

APC: 877

ISSUE DATE: 03-2022 EXPIRATION DATE: 31-03-2023

Bulletin Type: Informational Only

## TIME TO IMPLEMENT/SYSTEM IMPACT:

**Low** - not time consuming, no loss of functionalities Estimated time to implement - per machine - 10 minutes

## PARTS REQUIRED (HARDWARE/SOFTWARE):

N/A

### **ADDITIONAL INFORMATION:**

## REFERENCE THE FOLLOWING DOCUMENTS/PROCESSES FOR INSTALLATION PROCEDURES:

Virtual Management Server Software User Guide

## WHEN TO APPLY RESOLUTION:

Fresh system \_x\_ After (re)installation \_x\_ After upgrade \_x\_ After failure \_x\_

#### LABOR ALLOWANCE:

This is an informational bulletin. No labor warranty is implied, intended or authorized for U.S. Domestic Partners/Customers. Other regions should follow their own standard procedures.

If, after attempting to perform the solution steps, you are having issues with the resolution in the MTN then please contact your MSI Technical support center.

https://www.motorolasolutions.com/en\_us/support-topics.html

#### SW ORDER FORM IS AVAILABLE UNDER THE LINK:

http://www.motorolasolutions.com/content/dam/msi/docs/robots/motorola-technical-notification/SW\_order\_form.pdf

ANY USE NOT APPROVED BY MOTOROLA SOLUTIONS IS PROHIBITED. This Motorola Technical Notification (MTN) is issued pursuant to Motorola's ongoing review of the quality, effectiveness, and performance of its products. The information provided in this bulletin is intended for use by trained, professional technicians only, who have the expertise to perform the service described in the MTN. Motorola disclaims any and all liability for product quality or performance if the recommendations in this MTN are not implemented, or not implemented in compliance with the instructions provided here. Implementation of these recommendations may be necessary for the product to remain compliant with applicable laws or regulations. Please be advised that failure to implement these recommendations in the manner instructed may also invalidate applicable warranties, or otherwise impact any potential contractual rights or obligations. MOTOROLA, MOTO, MOTOROLA SOLUTIONS, and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. ©2021 Motorola Solutions, Inc. All rights reserved.