

APC: 147

ISSUE DATE: Aug-2023 EXPIRATION DATE: 31-Aug-2024

Bulletin Type: Informational Only

Motorola Solutions Technical Notification (MTN)

TITLE: Juniper SRX1500 and Juniper SRX345 router positions security firmware update 20.2X42.10

TECHNOLOGY: ASTRO 25

SYMPTOMS:

The following CVEs were resolved:

CVE-2023-22396

CVE-2021-36690

CVE-2021-20227

CVE-2020-15358

CVE-2020-13871

CVE-2020-13632

CVE-2020-13631

CVE-2020-13435

CVE-2020-13434

CVE-2020-11655

CVE-2020-9327

CVE-2020-11656

CVE-2020-13630

CVE-2021-31364

MODELS / SYSTEM RELEASES / KITS / DATECODES AFFECTED:

ASTRO releases: A7.18/A2019.2/A2020.x/A2021.1/A2022.x with Juniper SRX routers. This DOES NOT apply to the Juniper SRX on firewall positions.

SEVERITY RECOMMENDATION:

High / Safety - Security update not data/voice impacting

ROOT CAUSE:

Third party vendor software vulnerabilities

DEFINITIVE TEST:

User runs JunOS version 20.2X42.8 or older

WORKAROUNDS:

None

CORRECTIVE ACTIONS:

To obtain the latest security updates, upgrade Juniper SRX routers to the version listed below (or later).



APC: 147

ISSUE DATE: Aug-2023 EXPIRATION DATE: 31-Aug-2024

Bulletin Type: Informational Only

RESOLUTIONS AND REPAIR PROCEDURES:

Upgrade to the appropriate version as listed in the "PARTS REQUIRED (HARDWARE/SOFTWARE):" section below, based on the model number.

To obtain software:

- 1) Initiate a software request case through Motorola Solutions, Inc. Centralized Managed Support Operations (CMSO) at 800-MSI-HELP (800-674-4357) or 302-444-9800
- Await confirmation email from Motorola Solutions Software Factory (MSSF) with instructions
- S) Complete the Motorola Solutions Software Factory Software Order Form:
 - a) Reference MTN-0050A-23-NA in the 'Reason for Software/Hardware Change' section of the software order form.
 - b) List the part number (KC # as listed under "PARTS REQUIRED (HARDWARE/SOFTWARE)" below) in the 'Part # or Version #' section of the software order form.
- 4) Email completed Software Order Form to MSSF for processing

Order of upgrade:

- Check your current UNC (Unified Network Configurator) and UEM (Unified Event Manager) version. If your system is
 running a version lower than listed in the section PARTS REQUIRED (HARDWARE/SOFTWARE) below, upgrade
 UNC and/or UEM to the minimum version specified below or later. Otherwise, go to the next step.
- 2. Generate TNCT configuration using the version listed below.
 - TNCT version is important due to the JunOS/TNCT configuration compatibility.
- 3. Upgrade Juniper SRX 1500 and SRX345 JunOS for all routers in the system.

Follow the order:

- Edges (Even then Odd),
- Prime Access Routers (Even, Odd)
- Site Routers (Even, Odd)

For every router:

- a. Upgrade OS
- b. Deploy configuration
- c. Reboot router

TIME TO IMPLEMENT/SYSTEM IMPACT: - Juniper upgrade

Estimated time to implement - per machine - depends on the router version up to 70 min **Medium** - time consuming but no loss of functionalities

TIME TO IMPLEMENT/SYSTEM IMPACT - UEM upgrade (if applicable)

Estimated time to implement - per machine - 30 - 60 minutes to install UEM

Low - No loss of functionality (except for the UEM availability during the software installation)

TIME TO IMPLEMENT/SYSTEM IMPACT - UNC upgrade (if applicable)

Estimated time to implement - per machine - Approximately 1-2 hours for UNC upgrade **Medium -** time consuming but no loss of functionalities



APC: 147

ISSUE DATE: Aug-2023 EXPIRATION DATE: 31-Aug-2024

Bulletin Type: Informational Only

PARTS REQUIRED (HARDWARE/SOFTWARE):

A2022.HS/A2022.1:

Product	Software Version	KC Number
UNC UNCDS	UNC-Astro-07.22.01.12-00 or later UNCDS-Astro-07.22.01.12-00 or later	KC877L0AT000220100 or later KC877L0AT000220150 or later
UEM	UEM-Astro-22.01.00.93 or later	KC877V0AW000220100 or later
MCTE	JunOS 20.2X42.10 TNCT Version: 26.106.00 or later	KC147V01M000071713

A2020.1/A2020.HS/A2021.1:

ALULU: II/ALULU: III/ALUL IIII				
Product	Software Version	KC Number		
UNC UNCDS	UNC-Astro-07.20.03.84-00 or later UNCDS-Astro-07.20.03.84-00 or later	KC877L0AT000200106 or later KC877L0AT000200156 or later		
UEM	UEM-Astro-20.01.04.83-00 or later	KC877V0AW000200105 or later		
MCTE	JunOS 20.2X42.10 TNCT Version: 26.106.00 or later	KC147V01M000071713		

A2019.2:

	12010121			
Product	Software Version	KC Number		
UNC UNCDS	UNC-Astro-07.19.03.58-00 or later UNCDS-Astro-07.19.03.58-00 or later	KC877L0AT000190210 or later KC877L0AT000190260 or later		
UEM	UEM-Astro-19.02.10.01-00 or later	KC877V0AW000190206 or later		
MCTE	JunOS 20.2X42.10 TNCT Version: 24.176.00 or later	KC147V01M000071713		

A7.18:

Product	Software Version	KC Number		
UNC UNCDS	UNC-Astro-07.18.00.97-00 or later UNCDS-Astro-07.18.00.97-00 or later	KC877L0AT000718010 or later KC877L0AT000718060 or later		
UEM	UEM-Astro-07.18.10.02-00 or later	KC877V0AW000718009 or later		
MCTE	JunOS 20.2X42.10 TNCT Version: 24.176.00 or later	KC147V01M000071713		



APC: 147

ISSUE DATE: Aug-2023 EXPIRATION DATE: 31-Aug-2024

Bulletin Type: Informational Only

ADDITIONAL INFORMATION:

NOTE 1

This MTN applies to Juniper SRX devices on router positions in the ASTRO system. This DOES NOT apply to the Juniper SRX on firewall positions.

NOTE 2

Juniper SRX1500 upgrade time is 65 minutes, OS size: 1220 MB Juniper SRX345 upgrade time is 20 minutes, OS size: 404 MB

For the reference:

GGM8000/S6000 upgrade time is 5 minutes, OS size: 7 MB

NOTE 3

Before Juniper upgrade, confirm that your system runs minimum UNC and UEM version listed in the section PARTS REQUIRED (HARDWARE/SOFTWARE) above.

NOTE 4

Juniper routers across the system must use the same version of the JunOS for all SRX1500s and SRX345s. It can be kept on different versions during the upgrade process (for a limited time).

REFERENCE THE FOLLOWING DOCUMENTS/PROCESSES FOR INSTALLATION PROCEDURES:

<u>Unified Network Configurator User Guide</u> - chapter Updating OS Images and Software on Devices

Private Network Management Servers (for appropriate release) - chapter Upgrading Linux-Based Virtual Machines

WHEN TO APPLY RESOLUTION:

During maintenance _X_ As instructed __X

LABOR ALLOWANCE:

This is an informational bulletin. No labor warranty is implied, intended or authorized for U.S. Domestic Partners/Customers. Other regions should follow their own standard procedures.

If, after attempting to perform the solution steps, you are having issues with the resolution in the MTN then please contact your MSI Technical support center.

https://www.motorolasolutions.com/en_us/support.html - for NALA customers https://www.motorolasolutions.com/en_xu/support.html - for EMEA customers https://www.motorolasolutions.com/en_xp/support.html - for APAC customer

SW ORDER FORM IS AVAILABLE UNDER THE LINK:

http://www.motorolasolutions.com/content/dam/msi/docs/robots/motorola-technical-notification/SW_order_form.pdf