

Motorola Solutions Technical Notification (MTN)

TITLE: Periodic miss of packets from a subnet with paired redundant routers after some specific link failure and recovery events have taken place.

TECHNOLOGY:

Susceptible are any A7.x routers in the redundant configuration that share the common IP address on a subnet through Virtual Router Redundancy Protocol (VRRP). Additionally both routers are to be enabled for OSPF dynamic routing on a physical port connected to that network.

So far the issue was seen in few IP simulcast sites with paired S2500 subsite routers however the failure might be encountered also on site routers.

SYMPTOMS:

User might hear periodic cracks or missed syllables.

The other possible symptom is Infrastructure Link Alarm even though routers are stable.

MODELS / SYSTEM RELEASES / KITS / DATECODES AFFECTED:

SQM01SUM0194A S2500 MULTIPROTOCOL WAN ROUTER

SQM01SUM0205A GGM 8000 CORE GATEWAY

SQM01SUM0294A SRC7500 SWITCHING ROUTING CENTER SOFTWARE UPGRADE/EXPANSION

SEVERITY RECOMMENDATION:

Medium / Operational - Schedule to implement

ROOT CAUSE / DEFINITIVE TEST:

This is a defect in EOS software. The problem intermittently occurs on the Open Shortest Path First (OSPF) LAN segment when a router port goes down and up, e.g. due to link failure, and consequently OSPF service for this port goes down and up. Another precondition is that Virtual Router Redundancy Protocol (VRRP) is configured on the port.

It might happen that EOS software triggers OSPF Designated Router (DR) election process faster than changing the port status from down to up. In such case, EOS doesn't start the periodic Hello Timer (default is 1 sec) responsible for sending of Hello messages.

When the other router encounters no OSPF Hello packets, it presumes after 4 missed Hellos (4 seconds) that its peer is dead which is advertised in the OSPF LAN. The peer replies that it is still alive and both routers are synchronizing OSPF routing information whereas they are missing some network traffic. Because of missing Hellos, the situation is repeated in 4 seconds again.

The user may confirm that the redundant routers are in the bad state by examining the output from OSPF statistics on both routers:

show -sys statistics -ospf

In such case, the number of OSPF Hello messages received differs from transmitted Hellos significantly whereas they should be close to each other since there are 2 OSPF neighbor routers in the network.

WORKAROUNDS AND CORRECTIVE ACTIONS:

None.

ANY USE NOT APPROVED BY MOTOROLA SOLUTIONS IS PROHIBITED. This Motorola Technical Notification (MTN) is issued pursuant to Motorola's ongoing review of the quality, effectiveness, and performance of its products. The information provided in this bulletin is intended for use by trained, professional technicians only, who have the expertise to perform the service described in the MTN. Motorola disclaims any and all liability for product quality or performance if the recommendations in this MTN are not implemented, or not implemented in compliance with the instructions provided here. Implementation of these recommendations may be necessary for the product to remain compliant with applicable laws or regulations. Please be advised, that failure to implement these recommendations in the manner instructed may also invalidate applicable warranties, or otherwise impact any potential contractual rights or obligations. MOTOROLA, MOTO, MOTOROLA SOLUTIONS, and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. ©2016 Motorola Solutions, Inc. All rights reserved."

RESOLUTIONS AND REPAIR PROCEDURES:

Upgrade to the appropriate version as listed in the "**PARTS REQUIRED (HARDWARE/SOFTWARE):**" section below, based on the model.

To obtain software:

1. Initiate a software request case through Motorola Solution, Inc. System Support Center (SSC) at 1-800-221-7144 (1-302-444-9800)
2. Await confirmation email from UOST with instructions
3. Complete the Upgrade Operations Software Team (UOST) Software Order Form:
 - a. Reference **MTN-0058-17-NA** in the 'Reason for Software/Hardware Change' section of the software order form.
 - b. List the part number (**KC #** as listed under "**PARTS REQUIRED (HARDWARE/SOFTWARE):**" below) in the 'Part # or Version #' section of the software order form.
4. Email completed Software Order Form to UOST for processing

PARTS REQUIRED (HARDWARE/SOFTWARE):

ASTRO Release	KC number/EOS version
A7.16	KC147C079000071604: - EOS 16.8.4.03 for S6000 and GGM 8000 - EOS 16.2.9.52 for S2500
A7.14	KC147C079000071404: - EOS 16.6.4.02 for S6000 and GGM 8000 - EOS 16.2.9.10 for S2500
A7.17	EOS Box Release is targeted by the end of May 2017
A7.15	EOS delivery is planned in early July 2017

ADDITIONAL INFORMATION:

As A7.17 and A7.15 software is released this MTN will be updated

REFERENCE THE FOLLOWING DOCUMENTS/PROCESSES FOR INSTALLATION PROCEDURES:

N/A

WHEN TO APPLY RESOLUTION:

After reboot ____
After (re)installation ____
After upgrade ____
After power cycle ____
After database restoration ____
After failure X____
On FRU replacement ____
During maintenance X____
Immediately ____
As instructed ____
Information only ____

LABOR ALLOWANCE:

- Applies to **U.S. Domestic** Partners/Customers only. Other regions should follow their own warranty/reimbursement procedures.
- Labor up to **10** minutes per **Box**, plus travel up to **2** hours maximum, per **site**.
- Labor and travel reimbursement will be provided to Authorized Service Partners under the terms of the Labor Warranty Guidelines (v.21), and applies to **in-warranty** units only. Labor and travel for out of warranty units will not be reimbursed.

NOTE: please type 'MTN-0058-17-NA' in the SP Authorization No field, and 'SQM01.....' in the Model Number field on the MOL claim being submitted.

For assistance with this bulletin please contact your MSI Technical support centre
https://www.motorolasolutions.com/en_us/support.html



MOTOROLA SOLUTIONS

Upgrade Operations Software Team

Software Order Form

Phone Number: (800) 221-7144

SECTION 1: General Information

NOTE: PRICE QUOTES GIVEN BY UOST ARE VALID FOR ONLY 90 DAYS

Date _____
System ID _____
System Name _____
Customer _____
Name _____

Case Number _____
Site ID _____
Site Name _____

Form _____
Completed by _____
Organization _____
Phone _____
Number _____
Pager Number _____
Fax Number _____

Field Contact _____
Organization _____
Phone Number _____
Pager Number _____
Fax Number _____

SECTION 2: Order Information

Product Type: _____

Serial Number _____

Reason for Software / Hardware Change:

Downgrade? If so, list current and target releases.

Software / Hardware Description:

Part # or Version # _____

Quantity _____

Date Required _____

SECTION 3: Shipping / Billing Information

Ship To: _____

Bill To: _____

Email: _____
Attn: _____

Attn: _____

Phone: _____

Phone: _____

Customer Billing

P.O. #: _____
CUST #: _____
TAG #: _____

Internal Billing

PROJECT #: _____
FSB #: _____
DEPT #: _____
APC #: _____

- ° This form has been sent to you because you have requested an order from the Upgrade Operations Software Team.
- ° Please fill out the order form and email back to the Upgrade Operations Software Team
- ° If desired, please provide your email address on the order form and we will provide a tracking number when your order ships for your convenience.
- ° Orders will normally be processed in 3-5 business days once all information has been received.
- ° If additional space is required for software information, please use the optional addendum on page 3 below in addition to the original order form. This form is for use with large orders with multiple part numbers.

NOTE:

- 1) If this is an SSA CUSTOMER please order via Motorola factory order.
- 2) Limited Liability is Implied to the maximum of order amount.
- 3) Price quotes provided by UOST are valid for 90 days

Thank you and have a good day!

Supplemental Order Information Addendum

(Optional)

Software Description

Part# or Version #

Quantity:

Software Description

Part# or Version #

Quantity:

Software Description

Part# or Version #

Quantity:

Software Description

Part# or Version #

Quantity:

Software Description

Part# or Version #

Quantity:

Software Description

Part# or Version #

Quantity:
