

DOCUMENT NUMBER:	MTN-0059-25
ISSUE DATE:	2025-04

MOTOROLA SOLUTIONS TECHNICAL NOTIFICATION (MTN)

Title

After some period of time following an ATR upgrade to AN2024.1, new ATIA messages are not displayed on ATIAlog Viewer, new statistics are not displayed in Historical Reports and RCM reports are not being generated.

Technology

ASTRO Infrastructure - ASTRO® 25

Severity Recommendation

High/Safety - Perform Immediately - if upgrade was performed to A2024

Symptoms

The following issues may be observed on ATR after an upgrade to AN2024.1:

On the ATIAlog Viewer, new ATIA messages are not available. The partition: /opt/Motorola/stm/atialog/logs becomes full, as a result new ATIA packets are not collected.

On the Historical Reports, new statistics are not available. The partition: /opt/Motorola/stm/stats/stats_files becomes full, as a result new statistics are not collected.

New scheduled RCM reports are not being generated. The partition: /opt/Motorola/stm/reports/export becomes full

Models / System Releases / Kits / Datecodes Affected

All ATRs upgraded to AN2024.1 with versions up to ATR-Astro-07.33.00.35-00

When To Apply

After upgrade _X_ Immediately _X_

Workaround/Recovery

Login to ATR as root account, and launch following commands: chown wildfly /var/log/mot/atia/atia_arch.log chown systats /var/log/mot/stats_files/stats_files_cleanup.log

MOTOROLA SOLUTIONS TECHNICAL NOTIFICATION

ANY USE NOT APPROVED BY MOTOROLA SOLUTIONS IS PROHIBITED. This Motorola Technical Notification (MTN) is issued pursuant to Motorola's ongoing review of the quality, effectiveness, and performance of its products. The information provided in this bulletin is intended for use by trained, professional technicians only, who have the expertise to perform the service described in the MTN. Motorola disclaims any and all liability for product quality or performance if the recommendations in this MTN are not implemented, or not implemented in compliance with the instructions provided here. Implementation of these recommendations may be necessary for the product to remain compliant with applicable laws or regulations. Please be advised that failure to implement these recommendations in the manner instructed may also invalidate applicable warranties, or otherwise impact any potential contractual rights or obligations. MOTOROLA, MOTO, MOTOROLA SOLUTIONS, and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. © 2023 Motorola Solutions, Inc. All rights reserved.



DO	CUMENT NUMBER:	MTN-0059-25
	ISSUE DATE:	2025-04

chown tempest /var/log/mot/rpts/rpts_rotation.log

If a partition was full, new data will start to be collected after logs will be rotated again

- In case of ATIA logs it will be after 2 minutes
- In case of Historical Reports it will be after 15 minutes
- In case of RCM Reports it will be after 1 hour

Time To Implement/System Impact

Low - up to 5min for ATR. No service downtime or loss of functionality.

Software Parts Required

N/A

Hardware Parts Required

N/A

Additional Information

N/A

Reference The Following Documents/Processes For Installation Procedures

N/A

Labor Allowance

This is an informational bulletin. No labor warranty is implied, intended, or authorized.

For assistance with this bulletin please contact your MSI Technical Support Centre at https://motorolasolutions.com/support

MOTOROLA SOLUTIONS TECHNICAL NOTIFICATION

ANY USE NOT APPROVED BY MOTOROLA SOLUTIONS IS PROHIBITED. This Motorola Technical Notification (MTN) is issued pursuant to Motorola's ongoing review of the quality, effectiveness, and performance of its products. The information provided in this bulletin is intended for use by trained, professional technicians only, who have the expertise to perform the service described in the MTN. Motorola disclaims any and all liability for product quality or performance if the recommendations in this MTN are not implemented, or not implemented in compliance with the instructions provided here. Implementation of these recommendations may be necessary for the product to remain compliant with applicable laws or regulations. Please be advised that failure to implement these recommendations in the manner instructed may also invalidate applicable warranties, or otherwise impact any potential contractual rights or obligations. MOTOROLA, MOTO, MOTOROLA SOLUTIONS, and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. © 2023 Motorola Solutions, Inc. All rights reserved.