

DOCUMENT NUMBER: **MTN-0043-25**ISSUE DATE: **2025-03**

MOTOROLA SOLUTIONS TECHNICAL NOTIFICATION (MTN)

Title

When analog headset is set as the output device in Enhanced Instant Recall Recorder (EIRR) application on MCC7500E console, recordings cannot be played back

Technology

ASTRO® 25

Severity Recommendation

High/Safety - Perform Immediately

Symptoms

Recordings fail to play in the Enhanced Instant Recall Recorder (EIRR) application when an analog headset is selected as the output device. The IRR playback functionality is lost for analog headsets, and clicking the Play button has no effect. This issue is specific to analog headsets and does not occur with desktop speakers or USB headsets. Issue is consistently reproducible for an analog headset used for playback recordings functionality on EIRR application.

Models / System Releases / Kits / Datecodes Affected

System Release	Name / SW version
A2022.1, A2022.HS, AN 2024.1, AN 2024.HS	MCC7500E Dispatch Position software version 25.1.157

When To Apply

After failure X

During maintenance X

Immediately X

Resolution And Repair Procedure

Upgrade to the appropriate version as listed in the "Software/Hardware Parts Required" section below, based on the model.

To obtain software:

1. Initiate a software request case through Motorola Solutions, Inc. Centralized Managed Support Operations (CMSO) - see contact numbers at <https://motorolasolutions.com/support> (for NA call directly: 800-MSI-HELP (800-674-4357) or 302-444-9800)

MOTOROLA SOLUTIONS TECHNICAL NOTIFICATION

ANY USE NOT APPROVED BY MOTOROLA SOLUTIONS IS PROHIBITED. This Motorola Technical Notification (MTN) is issued pursuant to Motorola's ongoing review of the quality, effectiveness, and performance of its products. The information provided in this bulletin is intended for use by trained, professional technicians only, who have the expertise to perform the service described in the MTN. Motorola disclaims any and all liability for product quality or performance if the recommendations in this MTN are not implemented, or not implemented in compliance with the instructions provided here. Implementation of these recommendations may be necessary for the product to remain compliant with applicable laws or regulations. Please be advised that failure to implement these recommendations in the manner instructed may also invalidate applicable warranties, or otherwise impact any potential contractual rights or obligations. MOTOROLA, MOTO, MOTOROLA SOLUTIONS, and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. © 2023 Motorola Solutions, Inc. All rights reserved.

DOCUMENT NUMBER:	MTN-0043-25
ISSUE DATE:	2025-03

2. Await confirmation email from Motorola Solutions Software Factory (MSSF) with instructions
3. Complete the Motorola Solutions Software Factory Software Order Form:
 - Reference MTN-0043-25 in the 'Reason for Software/Hardware Change' section of the software order form.
 - List the part number (KC # as listed under "Software Parts Required" below) in the 'Part # or Version #' section of the software order form.
4. Email completed Software Order Form to MSSF for processing>

Time To Implement/System Impact

Estimated time to implement - per operator position - 15-20 min

High - Loss of functionalities/audio/downtime - Operator position will be unavailable for 20 minutes (during the software installation).

Software Parts Require

System Release	Name / SW version	
A2022.1 / A2022.HS / AN2024.1 / AN2024.HS	MCC7500E Dispatch Position software version 25.1.164 and later	KC443V00E000250001

Reference The Following Documents/Processes For Installation Procedures

A2022.1/AN2024.1 MCC 7500E Dispatch Console Use Guide - MN009830A01-L

Chapter 2.7: Installing the Dispatch Console Software Inside the RNI

Chapter 3.2: Installing the Dispatch Console Software Outside the RNI

Labor Allowance

For assistance with this bulletin please contact your MSI Technical Support Centre at <https://motorolasolutions.com/support>

MOTOROLA SOLUTIONS TECHNICAL NOTIFICATION

ANY USE NOT APPROVED BY MOTOROLA SOLUTIONS IS PROHIBITED. This Motorola Technical Notification (MTN) is issued pursuant to Motorola's ongoing review of the quality, effectiveness, and performance of its products. The information provided in this bulletin is intended for use by trained, professional technicians only, who have the expertise to perform the service described in the MTN. Motorola disclaims any and all liability for product quality or performance if the recommendations in this MTN are not implemented, or not implemented in compliance with the instructions provided here. Implementation of these recommendations may be necessary for the product to remain compliant with applicable laws or regulations. Please be advised that failure to implement these recommendations in the manner instructed may also invalidate applicable warranties, or otherwise impact any potential contractual rights or obligations. MOTOROLA, MOTO, MOTOROLA SOLUTIONS, and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. © 2023 Motorola Solutions, Inc. All rights reserved.