

DOCUMENT NUMBER:	MTN-0173-24
ISSUE DATE:	2024-12

MOTOROLA SOLUTIONS TECHNICAL NOTIFICATION (MTN)

Title

Rarely, dispatchers may be logged off the AXS console software when the ZDS service is shut down.

Technology

ASTRO® 25 - AXS Console

Severity Recommendation

Medium/Operational - Schedule to implement

Symptoms

In the event the ZDS server becomes unavailable (i.e. system updates, DSR zone switching, and random ZDS resets), console operators may be logged out of the AXS application. This condition is rare and difficult to predict. This could potentially impact multiple console operators simultaneously.

Models / System Releases / Kits / Datecodes Affected

	System Release	Name / SW version
1	A2021.1, A2022.1, A2022.HS, AN 2024.1, AN 2024.HS	CommandCentral AXS Dispatch Position software version 3.3.96 and prior

When To Apply

MSI recommends scheduling an update for your AXS consoles at the earliest opportunity. This upgrade will include enhancements eliminating the risk of unintentional logouts.

It is important to upgrade your AXS consoles before proceeding with any upgrades to the Core system, particularly the ZDS server.

Workaround/Recovery

There is no workaround available.

If a problem occurs, the dispatcher must log in to the AXS console.

Resolution And Repair Procedure

Upgrade to the appropriate version as listed in the <u>"Software/Hardware Parts Required"</u> section below, based on the model. To obtain software:

MOTOROLA SOLUTIONS TECHNICAL NOTIFICATION

ANY USE NOT APPROVED BY MOTOROLA SOLUTIONS IS PROHIBITED. This Motorola Technical Notification (MTN) is issued pursuant to Motorola's ongoing review of the quality, effectiveness, and performance of its products. The information provided in this bulletin is intended for use by trained, professional technicians only, who have the expertise to perform the service described in the MTN. Motorola disclaims any and all liability for product quality or performance if the recommendations in this MTN are not implemented, or not implemented in compliance with the instructions provided here. Implementation of these recommendations may be necessary for the product to remain compliant with applicable laws or regulations. Please be advised that failure to implement these recommendations in the manner instructed may also invalidate applicable warranties, or otherwise impact any potential contractual rights or obligations. MOTOROLA, MOTO, MOTOROLA SOLUTIONS, and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. © 2023 Motorola Solutions, Inc. All rights reserved.



DOCUMENT NUMBER:	MTN-0173-24
ISSUE DATE:	2024-12

- Initiate a software request case through Motorola Solutions, Inc. Centralized Managed Support Operations (CMSO) see contact numbers at https://motorolasolutions.com/support (for NA call directly: 800-MSI-HELP (800-674-4357) or 302-444-9800)
- 2. Await confirmation email from Motorola Solutions Software Factory (MSSF) with instructions
- 3. Complete the Motorola Solutions Software Factory Software Order Form:
 - Reference MTN-0173-24 in the 'Reason for Software/Hardware Change' section of the software order form.
 - List the part number (KC # as listed under <u>"Software Parts Required"</u> below) in the 'Part # or Version #' section of the software order form.
- 4. Email completed Software Order Form to MSSF for processing

Time To Implement/System Impact

Estimated time to implement - per machine - 15 minutes High - console operator position will not be available during upgrade time

Software Parts Required

System Release	Name / SW version /	Details / Part Number
A2021.1, A2022.1, A2022.HS, AN 2024.1, AN 2024.HS	CommandCentral AXS Dispatch Position software version 3.4.154 or later	KC504V00E000240003 or later

Reference The Following Documents/Processes For Installation Procedures

AXS Dispatch Console Installation Guide https://learning.motorolasolutions.com/installation-guide/86086enus

Labor Allowance

This is an informational bulletin. No labor warranty is implied, intended, or authorized

For assistance with this bulletin please contact your MSI Technical Support Centre at https://motorolasolutions.com/support

MOTOROLA SOLUTIONS TECHNICAL NOTIFICATION

ANY USE NOT APPROVED BY MOTOROLA SOLUTIONS IS PROHIBITED. This Motorola Technical Notification (MTN) is issued pursuant to Motorola's ongoing review of the quality, effectiveness, and performance of its products. The information provided in this bulletin is intended for use by trained, professional technicians only, who have the expertise to perform the service described in the MTN. Motorola disclaims any and all liability for product quality or performance if the recommendations in this MTN are not implemented, or not implemented in compliance with the instructions provided here. Implementation of these recommendations may be necessary for the product to remain compliant with applicable laws or regulations. Please be advised that failure to implement these recommendations in the manner instructed may also invalidate applicable warranties, or otherwise impact any potential contractual rights or obligations. MOTOROLA, MOTO, MOTOROLA SOLUTIONS, and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. © 2023 Motorola Solutions, Inc. All rights reserved.