

DOCUMENT NUMBER: MTN-0038-18-NA

APC: 481, 536, 562, 579, 581
470, 655, 755, 756, 837
426, 466, 471, 527, 570
305, 652, 656, 757, 761

ISSUE DATE: 05-2018

EXPIRATION DATE: 31-05-2019

Bulletin Type: Informational Only

Motorola Solutions Technical Notification (MTN)

TITLE: APX Radio Management – Firmware upgrades performed using RM 2.10.8 (R17.00.01) to firmware version R17.00.00 or later will result in missing or unexpected functionality.

TECHNOLOGY: APX Radio Management

SYMPTOMS:

After performing a radio firmware upgrade using Radio Management version 2.10.8 (R17.00.01) to firmware version R17.00.00 or later, the template in the Radio Management database is not updated correctly, and some field values will be incorrectly set and not modifiable.

MODELS / SYSTEM RELEASES / KITS / DATECODES AFFECTED:

All templates for APX radios upgraded with RM 2.10.8 (R17.00.01). When performing firmware upgrade with standalone CPS, this issue does not occur.

SEVERITY RECOMMENDATION:

Low / Maintenance - Perform if system exhibits above symptoms

ROOT CAUSE / DEFINITIVE TEST:

SW Defect

WORKAROUNDS AND CORRECTIVE ACTIONS:

Choose one of the following two methods:

1. Using CPS R17.00.01:
 - Upgrade to the R17 firmware using the R17.00.01 **CPS** (as opposed to upgrading from RM), and then read the radio again in RM.
2. Using RM 2.10.13 (R17.01.01):
 - If radios have not been upgraded with RM 2.10.8 (R17.00.01), please use RM 2.10.13 (R17.01.01) to avoid this issue.
 - If radios have already been upgraded using RM 2.10.8, use RM version 2.10.13 (R17.01.01) or higher and perform a firmware upgrade.

RESOLUTIONS AND REPAIR PROCEDURES:

A software fix for this issue will be available with APX CPS/RM R17.01.01 (2.10.13) (May 2018).

Use one of the corrective actions listed above to repair this issue.

When released, the Software will be available on Motorola On-Line web page which is located at:

<https://businessonline.motorolasolutions.com/Member/ContentManagement/resourcecenter.asp>

Select the following path from the items on the left side of the page,

- o Software -> Two-Way -> APX Family Portables and Mobiles

ANY USE NOT APPROVED BY MOTOROLA SOLUTIONS IS PROHIBITED. This Motorola Technical Notification (MTN) is issued pursuant to Motorola's ongoing review of the quality, effectiveness, and performance of its products. The information provided in this bulletin is intended for use by trained, professional technicians only, who have the expertise to perform the service described in the MTN. Motorola disclaims any and all liability for product quality or performance if the recommendations in this MTN are not implemented, or not implemented in compliance with the instructions provided here. Implementation of these recommendations may be necessary for the product to remain compliant with applicable laws or regulations. Please be advised, that failure to implement these recommendations in the manner instructed may also invalidate applicable warranties, or otherwise impact any potential contractual rights or obligations. MOTOROLA, MOTO, MOTOROLA SOLUTIONS, and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. ©2016 Motorola Solutions, Inc. All rights reserved."

PARTS REQUIRED (HARDWARE/SOFTWARE):

NA

ADDITIONAL INFORMATION:

NA

REFERENCE THE FOLLOWING DOCUMENTS/PROCESSES FOR INSTALLATION PROCEDURES:

NA

WHEN TO APPLY RESOLUTION:

After reboot ___

After (re)installation ___

After upgrade ___

After power cycle ___

After database restoration ___

After failure ___

On FRU replacement ___

During maintenance ___

Immediately ___

As instructed _X_

Information only ___

LABOR ALLOWANCE:

This is an informational bulletin. No labor warranty is implied, intended or authorized for U.S. Domestic Partners/Customers. Other regions should follow their own standard procedures.

For assistance with this bulletin please contact your MSI Technical support centre

https://www.motorolasolutions.com/en_us/support.html