



Lucent Gateway Platform Release Notes

255-400-006R5.1.0.3.SP.15

Issue 1

5 June 2006

Lucent Technologies
Bell Labs Innovations





Copyright © 2005 by Lucent Technologies. All Rights Reserved.

This material is protected by the copyright and trade secret laws of the United States and other countries. It may not be reproduced, distributed, or altered in any fashion by any entity (either internal or external to Lucent Technologies), except in accordance with applicable agreements, contracts or licensing, without the express written consent of the Lucent Session Manager (Lucent SM) Product Management Team and the business management owner of the material.

About Lucent Technologies

Lucent Technologies, headquartered in Murray Hill, N.J., USA, designs and delivers networks for the world's largest communications service providers. Backed by Bell Labs research and development, Lucent relies on its strengths in mobility, optical, data and voice networking technologies as well as software and services to develop next-generation networks. The company's systems, services and software are designed to help customers quickly deploy and better manage their networks and create new revenue-generating services that help businesses and consumers. For more information on Lucent Technologies, visit its web site at <http://www.lucent.com>.

Notice

At the time of publication, this document reflects the latest information on Lucent Session Manager offering. However, as we are continually enhancing our products and solutions, we recommend that 6 months after the date of publication you obtain the latest version of this document from your Lucent representative.

Trademarks

Not applicable.



CONTENTS

1	OVERVIEW	4
1.1	INTRODUCTION	4
2	UPGRADE FILES	4
3	UPGRADE NOTES	5
3.1	IN-SERVICE UPGRADE	5
3.2	IN-SERVICE DOWNGRADE	6
3.3	EMS/BILLING/TRAFFIC SERVER REQUIREMENTS	6
3.4	SYSTEM CAPACITY, MONITORING, AND ENGINEERING (SCME) INFORMATION	6
4	RESOLVED/UNRESOLVED ERROR DEFECTS.....	9
4.1	RESOLVED ERROR DEFECTS.....	9
4.2	UNRESOLVED ERROR DEFECTS	19
5	HARDWARE INSTALLATION AND PROVISIONING CONSIDERATIONS	19
6	SOFTWARE INSTALLATION AND PROVISIONING CONSIDERATIONS	21
6.1	EQUIPMENT MANAGEMENT ISSUES	21
6.2	SS7 AND ISDN SIGNALING.....	24
6.3	CAS SIGNALING.....	25
6.4	ISUP AND SIP-T INTERWORKING.....	25
6.5	CALL PROCESSING	25
6.6	BILLING/STATISTICS.....	25
6.7	SESSION INITIATION PROTOCOL	26
6.8	INTEGRATED VOIP.....	26
6.9	SYSTEM SOFTWARE	28
6.10	SS7 MTP-2 PERFORMANCE	28
6.11	SQA AND NLT	29
7	TL1 RESTRICTIONS AND SECURITY ERRATA	29
7.1	TL1 RESTRICTIONS	29
7.2	IP SECURITY CONSIDERATIONS	30
8	APPENDIX A: EXCEPTIONS AND WORKAROUNDS	31



1 OVERVIEW

1.1 Introduction

Overview

This document provides information regarding the Lucent Gateway Platform (Signaling Gateway, Network Gateway and Network Controller) system software version 5.1.0.3.SP.15 patch release for the System Processor (SP) and Input/Output Modules (IOMs). Topics covered are:

- Upgrade files
- Upgrade notes
- New features and product improvements
- TL1 Commands
- Resolved/unresolved error defects
- Hardware installation and provisioning considerations
- Software installation and provisioning considerations
- TL1 restrictions and security errata

Detailed descriptions of all hardware supported by release 5.1.0.3 is available by CLEI code and part number in the Part Information section in the *Lucent Gateway Platform Planning and Engineering Guide*.

Release Notes Issue

Version Information

Issue	Date	Purpose
1.0	5-June-2006	Release Notes for the official delivery of Release 5.1.0.3.SP.15.

2 UPGRADE FILES

The following file is required to upgrade to version 5.1.0.3.SP.15.

5.1.0.3.SP.15_cpu.tar.gz



3 UPGRADE NOTES

3.1 In-Service Upgrade

The following in-service processor upgrades are supported for this release:

- 5.1.0.3.SP.3 → 5.1.0.3.SP.15
- 5.1.0.3.SP.4 → 5.1.0.3.SP.15
- 5.1.0.3.SP.5 → 5.1.0.3.SP.15
- 5.1.0.3.SP.6 → 5.1.0.3.SP.15
- 5.1.0.3.SP.7 → 5.1.0.3.SP.15
- 5.1.0.3.SP.8 → 5.1.0.3.SP.15
- 5.1.0.3.SP.9 → 5.1.0.3.SP.15
- 5.1.0.3.SP.10 → 5.1.0.3.SP.15
- 5.1.0.3.SP.10.1 → 5.1.0.3.SP.15
- 5.1.0.3.SP.11 → 5.1.0.3.SP.15
- 5.1.0.3.SP.12 → 5.1.0.3.SP.15
- 5.1.0.3.SP.13 → 5.1.0.3.SP.15
- 5.1.0.3.SP.14 → 5.1.0.3.SP.15

If the rc.local files were used in a previous release to set the signaling transmission mode and speed for the Ethernet interfaces, the rc.local files should be updated before upgrading.

Important: After upgrading the system processor, you should check the versions of the IOMs and upgrade, if necessary. For instructions on performing an in-service IOM upgrade, contact LWS. An LWS representative will refer you to Lucent Gateway Platform Release 5.X Switch Software Change Procedures document (255-400-013R5.X) that contains specific steps for completing the upgrade.

Supported IOM Type	Part Number	Commcode	Minimum Version
Ethernet Network Access Module	89-0390-B	300746906	5.1.0.3.P1
Ethernet Network Access 2 Module	89-0432-A	300783925	5.1.0.3.P1
Compute Module Front	89-0419-B	300763885	5.1.0.3
Voice Server Module 2688 Channel	89-0395-B	300730157	5.1.0.3.P1
Triple DS3 STS-1 I/O with Tone Detect	89-0410-A	300730215	5.1.0.3.P1
Octal DS3 STS-1 I/O with Tone Detect	89-0411-A	300730223	5.1.0.3.P2



Supported IOM Type	Part Number	Commcode	Minimum Version
DS1/E1/J1 I/O Termination Module	89-0414-A	300746922	5.1.0.3.P1
Triple DS3 I/O Module With Tone Detect	89-0424-A	300730264	5.1.0.3.P1
Octal DS3 I/O Module With Tone Detect	89-0425-A	300730272	5.1.0.3.P2

3.2 In-Service Downgrade

An in-service downgrade from version 5.1.0.3.SP.15 is supported to 5.1.0.3.SP.3, 5.1.0.3.SP.4, 5.1.0.3.SP.5, 5.1.0.3.SP.6, and 5.1.0.3.SP.8.

3.3 EMS/Billing/Traffic Server Requirements

- Element Management System (EMS) version 9.8.0.0 or higher is required for 5.1.0.3.
- Billing and Traffic System (BTS) version 5.1.2.0.12 or higher is required for 5.1.0.3.
- Traffic Collection Application (TCA) version 2.0.0.98 or higher is required for 5.1.0.3.

3.4 System Capacity, Monitoring, and Engineering (SCME) Information

To plan hardware requirements, monitor performance, and plan for growth by identifying, measuring, and engineering key system resources, use the information in this section along with the *Lucent Gateway Platform System Capacity, Monitoring, and Engineering (SCME) Guidelines* document (255-400-005R5.1.0.1).



**Determine
the Number
of Time-
Division
Multiplexing
IOMs**

Name	Description	Value: Release 5.1	
		410/411	414/424/425
Facility and Operating System (OS)	Percentage of CPU used for IOM port monitoring and by the OS for timers, counters and such	22%	22%
%CPU_per_crs_per_sec	Percentage of CPU used to set up the FPGA resources for a TDM cross connect in one second.	Negligible	Negligible
%CPU_per_CAScall_per_sec	Percentage of CPU used per CAS call per second. This is a function of message processing required for call setup and teardown. Currently CAS and LAPD require approximately the same amount of CPU capacity per call, so this parameter is used to calculate call processing capability for either.	2%, assuming 4 messages	2%, assuming 4 messages
%CPU_per_T1_for_CAS	Percentage of CPU time used by each T1 configured for Robbed-Bit Signaling	5.3%	6.5%
%CPU_per_tone_per_sec	Percentage of CPU time used per tone per second. Usually this is used to calculate the CPU load for performing the ISUP Continuity Test for one out of eight call attempts	1% per 2 messages	1% per 2 messages
%CPU_per_SS7msg_per_sec	Percentage of CPU required to process an SS7 message in one second	TBD	TBD



Configure the Lucent Network Controller (LNC)

Call Type	Maximum Contexts/Second per Processor: Release 5.1
ISUP-ISUP (on one Media Gateway)	110
ISUP-ISUP (between Media Gateways)	90
ISUP-SIP	62
SIP-SIP	49
CAS-CAS (1 Media Gateway)	62
CAS-CAS (2 Media Gateways)	58
CAS-SIP	47
ISUP-CAS (1 Media Gateway)	88
ISUP-CAS (2 Media Gateways)	72

Other Lucent Network Controller Parameters:

Parameter	Value
LNP Impact	25%
TCAP Impact	29%
# of NG's per processor	4
# of Compute Modules (not including Common Channel Signaling)	4

Determine the Voice Server Module (VSM) Capacity

CODEC	VSM2 Capacity (per VSM)
g.711	2688
g.726	2688
g.729ab (32ms tail)	816
g.729ab (greater than 32ms tail)	768
g.723.1	672



Calculate the Number of Links and IOMs

Number of links per IOM	4
Msg/Sec per IOM	960 msg/sec for 89-0424/425/414 680 msg/s for 89-0410/411
Msg/Sec per Chassis	9600 msg/sec

4 RESOLVED/UNRESOLVED ERROR DEFECTS

4.1 Resolved Error Defects

Listed below are the resolved error defects in this version.

Tracking Number	Symptom	Comments
37297	The JIP is not generated in case of a ported-in subscriber forwarding the call. The JIP needs to be replaced in all cases that a call is forwarded.	Fixed in SP.1
39093	Release cause not populated on CDR module code 623.	Fixed in SP.1
39258	Security scan, with IP Filtering enabled, causes the slave processor to fail.	Fixed in SP.1
39413	Target Type printed out in CALEA M-Log may be incorrect.	Fixed in SP.1
39426	SSH does not work.	Fixed in SP.1
39532	Non WLNP calls are populating the 720 module in the CDRs.	Fixed in SP.1
39544	WLNP CDR fields are not being populated correctly.	Fixed in SP.1
39708, 39741	Issuing the SW-TOPROTN-EQPT command on the SP resulted in all the CICs going OOS.	Fixed in SP.1
39805	WLNP query on TLDN needs to be allowed in order to support number pooling of TLDN ranges.	Fixed in SP.1
39806	CM switch over IOM-4 to IOM-3 causes channel goes OOS	Fixed in SP.1
39815	ISUP - congestion threshold 1 exceeded.	Fixed in SP.1
39830	MGC-to-MG MEGACO connection dropped during load testing causing calls to fail.	Fixed in SP.1
39902	Unable to Modify ROUTE-DIGITS.	Fixed in SP.1
39952	Need a mechanism to capture GENDGTS entries in the billing CDR.	Fixed in SP.1



Tracking Number	Symptom	Comments
40066	SS7 calls fail when the IAM "segmentation and ISDN UserPart All the way" fields are set to 1.	Fixed in SP.1
40090	Additional SNMP Trap destinations are required to support loss of BTS Heartbeat.	Fixed in SP.1
40134	REG is not being accepted at RTKEYLIST in TRANS-PLAN.	Fixed in SP.1
40281, 39708	SP failover on the MGC results in calls failing and Trunk Group 75% OOS alarms.	Fixed in SP.1
40289	CM failover caused calls to failover from IOM-3 to IOM-4.	Fixed in SP.1
40296	CAS FGD calls are not receiving RINGBACK signal.	Fixed in SP.1
40301	SIP-T calls do not release after CM switch to protection.	Fixed in SP.1
40304	Enhancement to failover the active VSM based on "outgoing cell drop" level to prevent one-way audio path.	Fixed in SP.1
40436	CALL PROCESSING FAILURE OCCURRED UPON MEDIA SHUFFLING ON CALLS THAT TRANSIT BOTH MEDIA GATEWAYS.	Fixed in SP.1
40464	Charge Number is not being populated when is applied at ROUTE-DIGITS level.	Fixed in SP.1
40511, 40427	IS41 query with invalid presentation Indicator in CGPN (*67 issue).	Fixed in SP.1
40561	Re-configuring IP management and signaling ports from "Auto" to "Full Duplex/100" causes intermittent call failures.	Fixed in SP.1
40563	Security Scan causes call failures.	Fixed in SP.1
40607	Protection IOM failure occurred after active IOM failed.	Fixed in SP.1
40646	CDRSEARCH fails if no modules are appended to main structure code.	Fixed in SP.1
40653	RTRV-PM-RC does not contain any data.	Fixed in SP.1
40666	Delay in bringing CICs IS after provisioning.	Fixed in SP.1
40720	Standby CM continuously fails when the incoming COT procedure fails.	Fixed in SP.1
40728	Active SP failed over.	Fixed in SP.1
40746	Timer value of TCCR is not set to the correct value.	Fixed in SP.1
40762	MGC is not handling reINVITE with no SDP properly.	Fixed in SP.1
40765	Call release is being delayed by 90 seconds.	Fixed in SP.1
40770	An extra MODIFY request is sent by the originating MGC.	Fixed in SP.1
39265	The RTRV-PM-SLK does not return all of the proper parameters.	Fixed in SP.2



Tracking Number	Symptom	Comments
40682	Changing the session timer from a high value to a low value using ED-SIP-SYS causes SIP-T calls to fail.	Fixed in SP.2
40772	System process failure occurred during COT testing.	Fixed in SP.2
40846	System process error event observed in TL1 while provisioning CALEA target DN in LTDU.	Fixed in SP.2
40967	ISUP-to-SIP with direct 200 OK (no 183/180) results in one way RTP problem.	Fixed in SP.2
41213	SSH prevents EMS from Accessing Switch DB	Fixed in SP.3
41323	Switch Shows Standing Calls When No Calls Are Being Made	Fixed in SP.3
40446	When a PSTN private call is made, the switch sends an INVITE in which the From header's Display-name field is "Unavailable" rather than "Anonymous". As a consequence, the call is delivered to a Voice On the Net (VoN) user whose Anonymous Call Rejection feature is on.	Fixed in SP.4
40846	When attempting to provision a CALEA mobile call in the LTDU, errors are seen and the LTDU also returns an incorrect point code.	Fixed in SP.4
40989	Privacy is not maintained for calls from VoN to PSTN.	Fixed in SP.4
41278	When deleting TNS using the DIGITMOD-TNS command, the CIP is also deleted.	Fixed in SP.4
41715	ENT-TREATMENT fails in a distributed environment.	Fixed in SP.5
40296	Occasionally call progression tones will not be switched through on CAS trunks.	Fixed in SP.5
41878	A one-way voice path is set up for SS7-to-SIP-T calls when 180 ringing is received as the first response to the invite.	Fixed in SP.5
42078	Support added for SIP p-asserted-ID.	Fixed in SP.5
41952	Calls may fail in a scenario where a SIP-to-SIP call processes multiple media transfers (media shuffle).	Fixed in SP.5
41014	Incoming IAM COT failure followed by success causes the circuit to be blocked.	Fixed in SP.5
39071	EMS does not clear MGC-SG M3UA Down alarms.	Fixed in SP.5
41812	Calls involving AIN triggers can cause a circuit to remain blocked for 15 seconds after the call is released.	Fixed in SP.5
41812	Calls involving AIN triggers can cause a circuit to remain blocked for 15 seconds after the call is released.	Fixed in SP.5
42214	Incorrect tone played for Milliwatt tone test.	Fixed in SP.5
42196	Deleting all CICs on a T1 may cause a provisioning inconsistency. A CM failover is required to recover.	Fixed in SP.5



Tracking Number	Symptom	Comments
40846	The CALEA target DN provisioned using the GMSC-LAESDN command is not persistent. The data is lost when a CM module is rebooted in a distributed system or an SP is rebooted in an integrated system. The target DN must be deleted and entered again after the CM or SP module has been rebooted. A target reset on the LTDU will repopulate all target CALEA DNs.	Fixed in SP.6
41933	SP's cyclic reboot	Fixed in SP.7
42782	MORE THEN 4000 ROUTE DIGITS (RT-DIGITS) ENTRIES ARE NOT SUPPORT.	Fixed in SP.7
42787	RECEIVING AN UNSOLICITED TCAP QUERY WILL CAUSE MEMORY TO BE CONSUMED AND NOT RELEASED.	Fixed in SP.7
42820	DELETING A CIC WITH AN ACTIVE CALL CAUSES THE TL1 AGENT TO REJECT FUTURE CIC PROVISIONING UNTIL A SP FAILOVER IS PERFORMED.	Fixed in SP.7
42823	ISUP congestion introduced by M3UA/SCTP congestion does not clear.	Fixed in SP.7
42924	Over a period of time the CM card may fail when CNAM = Y is configured in the SIP trunk and TCAP is not configured to a SCP for the Calling name query.	Fixed in SP.7
42782	MORE THEN 4000 ROUTE DIGITS (RT-DIGITS) ENTRIES ARE NOT SUPPORT.	Fixed in SP.8
42787	RECEIVING AN UNSOLICITED TCAP QUERY WILL CAUSE MEMORY TO BE CONSUMED AND NOT RELEASED.	Fixed in SP.8
42820	DELETING A CIC WITH AN ACTIVE CALL CAUSES THE TL1 AGENT TO REJECT FUTURE CIC PROVISIONING UNTIL A SP FAILOVER IS PERFORMED.	Fixed in SP.8
42823	ISUP congestion introduced by M3UA/SCTP congestion does not clear.	Fixed in SP.8
42924	Over a period of time the CM card may fail when CNAM = Y is configured in the SIP trunk and TCAP is not configured to a SCP for the Calling name query.	Fixed in SP.8
38693	THE COREPORTMODE (SIGNALING) AND EMPORTRMODE (MANAGEMENT) FIELDS IN THE ED-CHASSIS-EQPT DID NOT HAVE ANY AFFECT ON THE ETHERNET INTERFACES. THE FIELDS IDENTIFIES THE TRANSMISSION MODE AND SPEED FOR THE SIGNALING AND MANAGEMENT ETHERNET INTERFACES ON THE SYSTEM PROCESSOR MODULE.	Fixed in SP.9
41123	BOOT UP OF CM CARD OCCASIONALLY FAILS (ONE IN THOUSANDS OF BOOT CYCLES).	Fixed in SP.9



Tracking Number	Symptom	Comments
42897	INTERNAL GLARE CAUSED BY A CALL BEING RELEASED AT THE SAME TIME ON TERMINATING AND ORIGINATING SIDE CAN CAUSE SIP CALL RESOURCES TO REMAIN IN USE AFTER THE CALL IS RELEASED. RTRV-PM-SIPMSG WILL SHOW STANDING CALLS WHEN NONE EXIST.	Fixed in SP.9
43005	A MEMORY LEAK OCCURS WHEN THE TERMINATING SWITCH DOES NOT RESPOND TO BOTH THE INVITE AND CANCEL SIP MESSAGES.	Fixed in SP.9
43010	WHEN RUNNING THE SYSTEM IN EXCESS OF 100% OF THE CM CPU FOR AN EXTENDED PERIOD OF TIME, THE CM WILL EXHAUST ALL MEMORY AND FAILOVER TO THE PROTECTION MODULE.	Fixed in SP.9
43070	CORRUPTED IP PACKETS MAY CAUSE THE GIG-E INTERFACE TO LOSE IP CONNECTIVITY.	Fixed in SP.9
43392	SS7 TRUNKS DO NOT REMAIN MANUALLY OUT OF SERVICE WHEN THE CORRESPONDING FACILITY TRANSITIONS FROM OUT OF SERVICE TO IN SERVICE.	Fixed in SP.9
43415	THE ACTIVE CM CARD MAY CONSUME 100% OF THE CPU AS OF RESULT OF SYNCHRONIZING THE SIP PROCESS ON THE STANDBY CM. THE ACTIVE CM REMAINS IN THIS STATE CAUSING SIP CALLS TO FAIL.	Fixed in SP.9
43583	BOOT UP OF TDM IOM CARDS OCCASIONALLY FAILS (ONE IN THOUSANDS OF BOOT CYCLES).	Fixed in SP.9
43687	THE DLT-SS7-TRK INCORRECTLY RETURNS "COMPLETED" BUT SHOULD HAVE RETURNED "INVALID STATE" WHEN A CIC IN THE DELETED RANGES HAS A STANDING CALL.	Fixed in SP.9
39415	IP LINK CONNECTIVITY NOT VERFIED FOR IOM 8	Fixed in SP.10
39706	DLP-512 IS INCORRECT FOR REPLACING SP PROCESSORS	Fixed in SP.10
39732	SP-3 UPGRADE ON 7288 AND EM IS NOT SHOWING NEW CLEI	Fixed in SP.10
42628	NEW CONFIGURATIONS NOT BEING SENT TO VSM	Fixed in SP.10
42989, 42727	EMS WITH ISUP TRKGRP ID NAMED IN WRONG IOM CARD DISPLAY.	Fixed in SP.10
43896	WHEN MG IS REBOOTED, ISDN LINKS MAY NOT AUTOMATICALLY COME BACK INTO SERVICE.	Fixed in SP.10
44114	SP CAN BE MANUALLY FAILED-OVER WHEN NO CARRIER ON	Fixed in SP.10
44076	IOM-FAIL: Module in slot 3 faulted - MODULE_ERR_APP_CORE(79)	Fixed in SP.10
44255	Documentation Issues with SP 10	Fixed in SP.10
44600	Stable Calls Fail with IOM Switchover	Fixed in SP.10
43323	Initiating an ENA failover then followed immediately by an SP failover, caused both the primary ENA and standby ENA to remain Out-of-Service "OOS".	Fixed in SP.10.1



Tracking Number	Symptom	Comments
43572	Certain routers being used as an NTP server have an issue with responding to LGP NTP request when the LGP was configured as an NTP peer. The LGP was modified to only send NTP request as a "Server" to work around the issue with router not responding.	Fixed in SP.10.1
44380	PSTN to Mobile CFDN does not forward to Voice Mail when the "Vendor Identifier" is set to NORTEL in the IS41 Redirection Request message	Fixed in SP.10.1
44845	Intermittent 3 Way Call Failure occurs when the 2nd mobile drops after which the originator and the 3rd mobile conferenced in drops from the call. The second invite (refresh) can not be received by the LCS system within 1 second of the ACK with the same SDP.	Fixed in SP.10.1
37851	Customers use SIP-based prepaid platforms. Charges for calls from payphone and other non-residential lines are not being debited properly because the ISUP-OLI parameter is missing in SIP Invites. This results in the user being undercharged.	Fixed in SP.11
40722	Add Rate Center: Switch doesn't accept names longer than 10 characters.	Fixed in SP.11
41129	Blocking the deletion of the default SCP-TNS route was not implemented.	Fixed in SP.11
41716	TRD media gateway fails to generate an alarm that the media gateway controller association is down.	Fixed in SP.11
41857	Common channel signaling cored when all outgoing trunks were reset via the ed-ss7-trk command during the call load.	Fixed in SP.11
42531	Security message of the day gets truncated on switchover of SPs. Only one line of the security warning gets printed after the switchover.	Fixed in SP.11
43412	MGC dlt/ent-ss7-trk command goes to TRANS state.	Fixed in SP.11
43595	The integrated services digital network interface failed to come up on its own. - Administration action OOS/IS required	Fixed in SP.11
43738	Send in an initial address message with NCI indicating continuity test message required. Then send in a continuity test message (failure) message. Then send in a REL message. The standby SP card crashes.	Fixed in SP.11
44380	Public switched telephone network to Mobile CFDN does not forward to voice mail when the vendor identifier is set to "NORTE" in the IS41 redirection request message.	Fixed in SP.11



Tracking Number	Symptom	Comments
44502	Link congestion alarm is broken. The system does not observe the link congestion alarm on TL1 even though protocol is sending it. PLM is missing code to handle congestion.	Fixed in SP.11
44557	Values in DBPTABLELIMIT table are not populated.	Fixed in SP.11
44580	The common channel signaling crashed during the continuity test message load.	Fixed in SP.11
44588	VOIPNETWORKCONN shows OOS and has zero resources available.	Fixed in SP.11
44712	SIP session does not send "200 OK" in response to invite, just 100 and 180. Only alerting is received on ISDN1. T301 timer is set to 1 and expires which causes the CM to fault.	Fixed in SP.11
44791	Running call load, with some calls being rerouted. TL1 user deletes an empty trunk group causes the CM to fault.	Fixed in SP.11
44805	Automatic call gapping is a mechanism that could be used by an SCP during congestion to throttle a switch's queries/messages of services like CNAM, Toll-free, local number portability, etc. This causes the switch to stop processing calls.	Fixed in SP.11
44808	During multiple reboots of the standby processor the DCL system manger state machine hits an invalid state causing the SP to fault.	Fixed in SP.11
44818	During 3-way conference call, RTP stream drops after hold.	Fixed in SP.11
44845	3-way call failure occurs (intermittently). This happens when a 3-way call is created by caller A (originator of the call) calling caller B and then caller B conferencing in caller C. When caller B drops from the call, instead of the caller A-caller B connection staying up, it drops.	Fixed in SP.11
44919	CM fails while processing a freed buffer when segmentation timer timed out for incoming IAM message with segmentation bit set.	Fixed in SP.11
44936	The continuity check fails if performed on an outgoing-only trunk.	Fixed in SP.11
45097	CM faulted due to operator continuity.	Fixed in SP.11
40569	Service processor faults with a session initiation protocol application core. In certain scenarios (negative behavior), the session description protocol length was too large causing ips corruption in the session description protocol address.	Fixed in SP.12
41097	New feature: Add a fault detector and alarm for signaling interface & management interface routers.	Fixed in SP.12



Tracking Number	Symptom	Comments
41516	The LCS media gateway association in the media gateway controller is out of service if the media gateway gets assigned to CM1_CPU1_INST1. This happens when the fourth media gateway is added to the media gateway controller.	Fixed in SP.12
43323	When doing an ethernet network adapter failover followed immediately by a service processor failover causes both the primary ethernet network adapter and the standby ethernet network adapter to remain out of service.	Fixed in SP.12
43571	Entering the ENT(ED)-TREATMENT command with a certain announcement ID in quick succession causes a race condition. This causes the service processor to fault.	Fixed in SP.12
43572	Certain routers being used at an NTP server had an issue with responding to a Lucent Gateway Platform NTP request when the Lucent Gateway Platform was configured as an NTP peer. The Lucent Gateway Platform was modified to only send NTP request as a "Server" to work around the issue with router not responding.	Fixed in SP.12
44890	The LCS leaves out P-Asserted Identity header from redirected INVITE message. The P-Asserted Identity header is needed in specific call scenarios because it carries the calling party number. Without the calling party number, the VoN feature server will not find a match to a specific selective call rejection entry and fail to block the call.	Fixed in SP.12
44962	During weekend test, the service processor faulted under a large call load (SS7<-->SS7).	Fixed in SP.12
45122	Standby service processor fails to sync due to a large number of trunk groups configured with over 10,000 circuit identification codes. This is due to multiple log messages being printed by a specific application.	Fixed in SP.12
45167	The compute module will fault if an integrated services digital network user part call with the M-bit set (Ported call) is routed in a distributed LCS system and out an integrated services digital network interface.	Fixed in SP.12
45198	If a RE-INVITE with no session description protocol (query) is received within 1 second of sending a 200 OK response to a previous RE-INVITE with no session description protocol (query), the call will fail.	Fixed in SP.12



Tracking Number	Symptom	Comments
45200	When a call comes in from session initiation protocol, the session initiation protocol to channel associated signaling interworking function does not send out the calling party number over the channel associated signaling trunks.	Fixed in SP.12
45207	Incoming calls over channel associated signaling trunks do not complete because the called party number is not received.	Fixed in SP.12
45275	When a circuit reservation message is received, the active compute module faults. A circuit reservation message is a very uncommon message. It is sent by an access tandem only when an incoming channel associated signaling feature group D call is terminating on an SS7.	Fixed in SP.12
45370	The service processor faults due to multiple SS7 links being configured.	Fixed in SP.12
37521	The 4-wire continuity test message should loop back the circuit and not generate a tone.	Fixed in SP.13
40318	Incorrect M3UA and media gateway controller state in the rtrv-status-mgcproc command are displayed wrong.	Fixed in SP.13
41097	New Feature: Added a fault detector and an alarm for the Signaling and Management routers.	Fixed in SP.13
43856	After a host failover, the standby service processor failed to restore because the session initiation protocol did not send the STANBY READY EVENT message to CLAM.	Fixed in SP.13
44355	The rtrv-status-mgcproc command shows M3UASTATE=OOS while the M3UA is in service	Fixed in SP.13
45186	Deleting a T1 on the media gateway causes the Edit and RTRV T0 commands to fail for all T0s associated with the corresponding T3. Deleting and entering the provisioned T1s in the T3 will correct the issue.	Fixed in SP.13
45289	Active compute module faulted with the "MODULE_ERR_APP_CORE(79)" message.	Fixed in SP.13
45399	The Megaa's alarms and the notification to MGI are inconsistent which caused the call to fail.	Fixed in SP.13
45465	On the active service processor, a memory leak occurs on the slave processor because uBuf is out of control for both the integrated services digital network user part and the generic call control.	Fixed in SP.13
45511	The redirection directory number and the original called party number are present in the egress initial address message for wireless intelligent network bypass calls.	Fixed in SP.13



Tracking Number	Symptom	Comments
45558	MEGAA cored during silly-savvy	Fixed in SP.13
43463	The media gateway controller cored on the common channel signaling while running a channel associated with signaling calls	Fixed in SP.14
45433	"KP and ST" are not being spilled for profile 41.	Fixed in SP.14
45648	The ent-route-digits ISDN IF value limit is incorrect.	Fixed in SP.14
43888	The circuit group unblock (unblocked message) cannot unblock the circuit identification code's hardware block status for the american national standards institute variants	Fixed in SP.15
45016	The common channel signaling cored while doing continuity test message load tests.	Fixed in SP.15
45103	Received the following message: 404 Status-Code cannot play announcement	Fixed in SP.15
45297	The system processor reboots on first call after hop count is calculated to be "0".	Fixed in SP.15
45937	The dual system processor fault occurred because the fcUtilAcgSetTime calls are incorrectly freed.	Fixed in SP.15
45975	The severities of the Ethernet and IP connectivity alarms are not consistent.	Fixed in SP.15
45979	The session initiation protocol application crashed because the free memory was being consumed by sessions/calls that were in the "hang up" state.	Fixed in SP.15
46086	Cannot edit trunk with ACTNTERMATTMPT=DIG-MOD.	Fixed in SP.15
46121	The internal session initiation protocol audit is not releasing hung calls.	Fixed in SP.15
46240	The active compute module fails on the gateway mobile switching center when a call sent to a serving mobile switching center is forwarded (busy, no answer) to a number requiring a local number portability query. The initial address message must also have the jurisdiction information parameter present. This same call flow must have been run several times before the fault occurs.	Fixed in SP.15
46446	Provisioning failed for ROUTER with the following message: Error 19 TableId 446	Fixed in SP.15
46535	The standby service processor rebooted when a T1 port that was not successfully deleted was edited to "IS".	Fixed in SP.15
46595	The session initiation protocol leaks memory if the LCS receives a 4xx response from the transmitted re-invite.	Fixed in SP.15



Tracking Number	Symptom	Comments
46828	Once a digit modification has been applied to a route digit entry, the entry cannot be modified.	Fixed in SP.15
47048	For an incoming initial address message, if the set FCI M bit is "1" and the assigned digit modification is changed to "0", the value of M bit is not changed in the outgoing initial address message.	Fixed in SP.15
47151	The ent-digitmod-param does not work for FCI M bit.	Fixed in SP.15

4.2 Unresolved Error Defects

Listed below are the unresolved error defects in this version.

Tracking Number	Symptom
42225	The Edit LRN command is not supported. LRN must be deleted and entered again to change a parameter.
39548	CM failed to upgrade.
40177, 40017	ISUP congestion observed during SG-MGC upgrade.
41489	Once SIP heartbeat is enabled, SIP OPTION messages of the Lucent Gateway Platform switch are sent out for every configured instance of the CMs.
42421	Unable to configure IUA and channel associated signaling on the same input/output module.
43571	ED-TREATMENT fails in a distributed environment.
43576	The Ethernet interface can fail when configured in a mode that does not match the router/switch/hub that it is connected to.
44966	Announcement ID with a newly created message that has the message id of an old deleted message still plays the old message. Note: There is a workaround for this defect.

5 HARDWARE INSTALLATION AND PROVISIONING CONSIDERATIONS

- A front SP-3 module, 89-406, requires a rear SP-3 module, 89-0417, front switch fabric card (89-0363-D), and Midplane III (chassis 85-3007 or 85-3008).
Note: The OS port is above the SIGA port on the rear SP-3 module, whereas the OS port is below the SIG port on the rear SP module.



- Front and rear CM modules, 89-419 and 89-420 respectively, require SP-3 modules, and Midplane III (chassis 85-3008 ONLY). Slot I/O-9 cannot be used for a CM. Up to 8 protected CM pairs are allowed in a single chassis. A MGC chassis that is fully loaded with CMs has a power dissipation of 1800 Watts.
- The Triple and Octal DS-3 Front IOMs, 89-0424 and 89-0425, require a Rear Octal DS-3 module, 89-0383, and a rear Octal Protection module, 89-0386. They are only supported in a chassis with Midplane II (85-3004) and Midplane III (85-3007 and 85-3008).
- The Triple and Octal DS-3 Front IOMs, 89-0424 and 89-0425 can be protected by corresponding 89-0424/0425 IOMs as well as by 89-0410/0411 IOMs.
Note: ISDN, MTP2, CAS and GR-303 peak signaling rates must be taken into account when using a 89-0410/0411 to protect a 89-0424/0425, since they support higher signaling rates than the 89-0410/0411 IOMs (25%, or greater, depending on the signaling).
Note: They cannot be used to protect corresponding Triple and Octal DS-3/STS-1 IOMs, part numbers 89-0397/ 0398/ 0410/0411, since they do not support STS-1.
Note: They cannot be used to replace previously provisioned Triple and Octal DS-3/STS-1 IOMs, part numbers 89-0397/ 0398/ 0410/ 0411, since they do not support STS-1.
- A VSM can be provisioned in any I/O slot, but it will only fail over to I/O slot 9. Version 5.0.0.47 is the minimum version that is required to support VSM protection in I/O slot 9. **Note:** In versions 3.X and earlier versions of 5.0, the VSM would only failover to slot I/O 17.
- ENA IOMs can only be provisioned in slot 8 and will only fail over to slot 10.
- A OC-3 module, 89-0400-A, requires a Midplane III (chassis 85-3007 or 85-3008). It also requires a OC-3 rear module (89-0492-A). The rear module can terminate four OC-3 lines. Only the first eight STS-1 can be provisioned. STS-1 through STS-6 can be bulk provisioned. STS-7 and STS-8 cannot be bulk provisioned. They must be provisioned individually. A maximum of four protected pairs of Channelized OC-3 modules are supported. A Channelized OC-3 module cannot be provisioned if there is a card in its mated pair I/O slot that is other than a Channelized OC-3 module. The protected pairs can be installed in:
 - I/O-1 and I/O-2
 - I/O-3 and I/O-4
 - I/O-5 and I/O-6
 - I/O-7 and I/O-8
- A Midplane III (85-3007 and 85-3008) chassis requires an Octal rear-protection IOM on DS3 IOMs regardless of whether the front IOMs are Octal or Triple DS3 IOMs (rear-working IOMs can be Triples, but the protection IOM must always be Octal).



- An Octal rev. A can be backed up with either an Octal rev. A or an Octal rev. B; however, an Octal rev. B can only be backed up with an Octal rev. B. IOM failover won't work if Octal rev. B tries to fail over to an Octal rev. A.
- A Switch Fabric (SF) module must be inserted before its associated SP module.
- SP and SF Rev. B or later are required for operation with Octal DS3 IOMs.
- Chassis Part Number 85-3000, CLEI Code BAM9LJ0GRA, does not support Octal IOMs.
- CAS is supported on Octal, part number 89-0398 and higher and triple DS3, part number 89-0397 and higher.
- When using the ENT-EQPT command, redundancy can be set equal to SEC (redundancy=sec) only if the IOM AID specified is in a protection slot. Attempting to provision an unsupported slot as a SEC redundancy returns a DENY message.
- You cannot provision slot 11 (IOM slot 9) if the ENA port 4 is provisioned, nor can you provision the ENA port 4 if slot 11 (IOM slot 9) contains a provisioned card. This is because there is a bandwidth limitation on the SF card.
- If an SP module is manually removed and then reinserted, it will not automatically be restored to service. You must enter the TL1 command, `RST-EQPT::SP-{A|B}`, to initialize and synchronize the previously removed SP.

6 SOFTWARE INSTALLATION AND PROVISIONING CONSIDERATIONS

6.1 Equipment Management Issues

- A Compute Module can support up to eight media gateways (subject to Compute Module CPU capacity).
- Additional logic has been implemented regarding the execution of the RMV-EQPT command (or EMS equivalent) on a working 1:1 protected IOM (CM, ANA, ENA) to allow the operator to take a working/standalone IOM OOS for emergency operations.
 - If the standby IOM is provisioned to be OOS, then the RMV-EQPT command will be accepted for the active IOM to allow the operator to take a protected/standalone IOM OOS for emergency operations.
 - If an attempt is made to remove the active I/O IOM before first provisioning the stand-by IOM to be OOS, the system will respond with a "DENY card not in a valid state" error



- message. You must first use the RMV-EQPT command against the stand-by IOM to place it into an OOS state and then re-issue the RMV-EQPT command for the active IOM.
- If an attempt is made to remove an active IOM using the EMS, it will respond with "are you sure" and if the user selects "yes" the system will respond with "The card is not in a valid state." You should then use the appropriate EMS procedure to place the standby IOM OOS and then remove the active IOM using the appropriate EMS procedure.
 - The TEST-TRANS command has the following limitations:
 - No SCP interactions (tollfree, LNP, other general AIN triggers) are validated. They would not even be detected in this case.
 - The announcement ID associated with a treatment will be captured. However, individual arguments (spoken announcement variables) that are used in an announcement may or may not be captured.
 - The absence of carrier on the signaling or management ports on the protection SP will not prevent the manually executed SW-TOPROTN-EQPT::SP-x TL1 command from being executed. It will result in an SP failover, even if the signaling or management ports do not have carrier (an Ethernet cable has been pulled). Note: It is recommended that you check for alarms before issuing any equipment commands that force failovers.
 - The associated Connection Control and Signaling (CCS) process must be rebooted when a TL1 DLT-MGC-MGASSOC command is issued.
 - When an IOM or CM is manually put into an OOS state using the TL1 SW-TOPROTN-EQPT command or by selecting `Switch to Protection` within the EMS, it must be manually put back IS using the TL1 RST-EQPT command or by setting the card's state to IS with the EMS `Modify Card` screen prior to issuing a TL1 SW-TOWORK-EQPT command or EMS `Switch to Working` screen.
 - If a CM needs to be moved from one slot to another, the corresponding MGs must be deleted prior to removing the CM. The corresponding MGs must then be re-entered after the CM has been installed in the new slot.
 - Support for the following software features is not available in this software version but is on the roadmap for a future 5.X release: H248.2 (Text Conversation and FAX) – MG and MGC.
 - The IP addresses must be correct and unique on both SPs before bringing the switches into service.
 - IP addresses for OS, signaling and craft Ethernet ports should not be on the same subnet. If it is desired that they be on the same subnet, contact Lucent Worldwide Services at 1-866-582-3688 for provisioning assistance.
 - If the signaling interfaces are not configured with IP addresses, an alarm from each SP, stating "lost link on signaling Ethernet," will be generated.



- When switching from SS7 to ISDN signaling or vice-versa, the signaling link and interface must be deleted and the Octal DS3/DS1/DS3 IOMs must be rebooted before provisioning can occur.
- If you pull an SP, thus taking it out of service, you must wait 10 seconds before reinserting the SP.
- Using the ED-DATE TL1 command to change the time is not required or recommended when the NTP is provisioned. If the new date differs by more than 1000 seconds, then the NTP daemon may shut down. If this happens, you should reset the NTP server to 0.0.0.0 then back to the correct server IP address.
- A single IOM cannot support signaling links of both 56K and 64K. The link speed must be the same for all links on a single IOM. This restriction does not apply to Triple DS3 IOMs, part numbers 89-0397 and higher, and Octal DS3 IOMs, part numbers 89-0398 and higher, as a mix in the link speed creates no problems.
- Midplane II (85-3004 chassis) and Midplane III (85-3007 and 85-3008 chassis) use slot pairs for provisioning line timing. Therefore, you cannot have just one IOM in a paired slot. Slots 1 and 2 are paired, as are slots 8 and 10. To use line timing, any Triple DS3 IOMs must be in place in a given slot pair or any Octal DS3 IOMs.
- The default value for the Signaling loss of carrier timer has been changed to 3 seconds from 30 seconds.
- The CorePortMode (signaling) and emPortMode (management) fields in the ED-CHASSIS-EQPT are now functional.

DS3 IOMs

- Operating a FEND loopback on a channel already in a near-end (NEND) loopback cannot be done because of DS3 interface chip limitations. If a NEND loopback command was followed by a FEND loopback command, the DS3 interface chip will only execute the NEND loopback, but will remember the FEND request. If the NEND loopback is released, the FEND request is remembered but will not execute. Issuing a FEND loopback will not work because the DS3 interface chip thinks a loopback is in progress. The FEND must also be released. To insure a T3 is put into a FEND loopback, first send a RLS-LPBK-T3:::::FEND command followed by a OPR-LPBK-T3:::::FEND.
Note: This limitation is still in effect from a TL1 command standpoint and will remain in the release notes until it is documented in DLP-532 (Perform Loopbacks). However, you cannot issue a NEND loopback followed by a FEND loopback from the EMS without issuing a RLS in between.



STS-1 IOMs

- GR-253 (R6-372) states that there must be a method provided to detect and report the actual contents of the Received STS Path Trace message. The RTRV-STSI command presently only supports the expected Rx Trace message and the Tx Trace message.
- The system reports an STS Trace ID Mismatch when the J1 byte is inaccessible. GR-253 (R6-382) states that STS Path Trace monitoring should be suspended if the J1 byte in the Path Overhead cannot be accessed (e.g., LOS, LOF, LOP-P and AIS-P). This means that the system should not report an STS Trace ID Mismatch just before it declares any of the above mentioned alarm conditions, or after they clear.
- STS reports Trace ID Mismatch events.

Voice Server Modules

- When the precedence of RTP packets is changed with ED-VOIP-SYS, the voice server module needs to be rebooted for the settings to take effect. This can be done with an IOM failover to the protection voice server module followed by an IOM revert of the voice server module.

Primary Rate ISDN Line

- As indicated by the ED/ENT-ISDN-IF command responses, the 4ESS ISDN PRI variant is currently not supported in this version.
- Two-way Primary Rate ISDN lines on the LCS should be provisioned as National ISDN-2 or DMS-100.
- The LCS supports National ISDN-2, 4ESS, 5ESS, and DMS-100 variants for one-way calls leaving the LCS.

6.2 SS7 and ISDN Signaling

- The capturing of SS7 MTP3 signaling messages via SigTrace is supported in this version. The capture of ISDN Q.931 or CAS signaling messages is not supported in this version.
- When editing a T1 out-of-service the mode (OMODE) must be set to AIS in order to bring MTP2 and LAPD down.
- Currently, the signaling point code restart procedure is not supported.
- Alarms for ISUP timer expiry are disabled.
- Alarms are not generated if the initial condition for a remote Point Code is down.
- A maximum of 1250 destination point codes can be configured.
- A signaling link set must contain at least one signaling link with a link priority set to 0. Any additional links, in the link set, must have contiguous priorities.



- The LCS currently does not support T-321 timers.
- Trunk Group IDs must be unique in the system.
- There can be no more than 100,000 interfaces formed by TRKGRPS+ISDNIF+CASIF in the router. The breakdown of each consists of the following: a maximum of 3808 configurable ISDN interfaces and TRKGRPS each; and a maximum of 91392 CAS-IF interfaces (currently, however, it is recommended that you not configure more than 64,000 CAS-IFs).
- SS7 Trunks cannot be assigned the CIC value 0.

6.3 CAS Signaling

- The CAS profileID for an existing CAS trunk group cannot be edited. In order to change the CAS profileID, all of the trunks in the trunk group must be deleted, the trunk group must be then be deleted and subsequently re-added with the new CAS profile.
- The maximum CAS ports (T1s) that can be provisioned for one Octal (89-0398, 89-0411, 89-0425) is 150 T1 ports (3600 T0s).
- Parameters in the CAS-IF command cannot be edited after changing the ALLOC parameter equal to CIRCULAR for one CAS-IF entry.

6.4 ISUP and SIP-T Interworking

- All unrecognized parameters received in SIP-T messages are not passed to ISUP. Correspondingly, all unrecognized parameters received in ISUP messages will be discarded in SIP-T.

6.5 Call Processing

- The CALL TRACE and CALL CAPTURE TL1 commands are not supported in this version.
- The signaling trace utility (sigtrace) should not be relied on for debugging with high CPU utilization (greater than 85-90%).
- The SS7 signaling links are not protected during an IOM hardware failover.
- When an IOM is in protection mode, attempting to add, modify or delete ISDN or signaling links from the protected IOM will return DENY messages.

6.6 Billing/Statistics

- The ISDN PRI Traffic CCS report does not currently update the available circuit (AVLCIRC) field to reflect ISDN channels that are OOS.
- Because Feature Group D functionality is fully supported from an Access Tandem and Inter-Exchange Carrier standpoint for CAS and ISUP in release 3.8 and above, originating carrier information (such as connect date, connect time, and elapsed time) is only valid for Feature Group D



trunks. Note: End Office Feature Group D functionality is not fully supported. For terminating carrier access calls, the carrier timing information is populated even if the incoming trunk group is not Feature Group D.

6.7 Session Initiation Protocol

- Enabling the SIP session timer can cause some performance degradation at high call rates if a large number of session refresh messages are sent at the same time. The recommended value for this timer when enabled is 1800 (30 minutes) - that way, session refresh messages will not occur in most cases.
- A SIP trunk group should not be deleted if it has standing calls (#37577/31033)
- In release 3.10, the default NPI for CPN for SIP initiated calls was UNKNOWN. Starting with this release, the default NPI value is ISDN. Customers that were previously assuming that the default value was UNKNOWN or were using digitmods to change the NPI value, need to make appropriate configuration changes (add/remove the digitmods).
- Changing media streams in SIP 18x responses and subsequent 200 OK responses is not supported since it is contrary to RFC 3261.
- A SIP CANCEL message is not sent out after Invite Timer (T1) expiry which is consistent with RFC 3261 but inconsistent with RFC 3398.
- The npdi parameter in SIP has been updated from "npdi=yes" to "npdi" and will now appear in the SIP-URI user part.
- Session Timer for SIP-T should be configured at the same time on both LNC switches. Otherwise SIP-T traffic will fail in one direction since Session timer negotiation is not supported. Session timer value should be same or smaller than the value of the other LNC switch Session timer value.

6.8 Integrated VoIP

- If you change the VSM `aal5enc` encoding parameter (VCMUX, LLC SNAP), a VSM reboot is required for the change to take effect.
- If you change the ENA `format` parameter (802.3, DIX II), an ENA reboot is required for the change to take effect.
- Tone Relay support is limited to DTMF Events per RFC2833, Section 3.10, Table 1. Other types of tones are not supported.
- Additional logic has been implemented regarding the execution of the remove command on an active module. The system now denies RMV commands for working 1:1 modules (CM, ANA, ENA) when the protection card is provisioned to be IS.
 - If the protection card is provisioned to be OOS, then the RMV card will be accepted - this is to allow the operator to take a working/standalone card OOS for emergency operations.



- If an attempt is made to remove an active IOM before first removing the stand-by card the system will respond with a DENY card not in a valid state. The operator should then follow the proper procedure of first removing the stand-by module.
- If an attempt is made to remove an active IOM using the EMS, it will respond with "our your sure" and if the user selects "yes" the system will respond with "The card is not in a valid state."
- If an attempt is made to remove an active IOM before first removing the stand-by card the system will respond with a DENY card not in a valid state. The operator should then follow the proper procedure of first removing the stand-by module.

Note: This is fixed in 2 ways in R6.0 and beyond. The ENA cards are not auto revertive and they are true one to one protection, so when the standby takes over after a failover it 'becomes' the active.

- Fax/modem support between the LCS and some third-party equipment (such as gateways, IADs) is only available on G711 calls. For calls using compressed codecs (using G.729 protocol), fax/modem calls won't work with these vendors if they use proprietary signaling protocols.
- The LCS supports G.711, G.726, G.729, G.723.1, CLEARMODE, X-CCD, CISCO-CLEAR-CHANNEL codecs, each with 10, 20, 30 and 40ms sampling, except for G.723.1, which supports 30 and 60ms sampling
- If you want to modify the endptvoip IP address on a GigE port, you must edit the ENET port Out of Service (OOS) and then use the RMV-EQPT command on the VSM. There is no way to dynamically update the IP addresses without dropping all calls associated with a VSM. For example, information would be entered as such:

```
ED-ENET::IOM-8-ENET-1::::OOS; (GigE port)
RMV-EQPT::IOM-11; (VSM)
DLT-ENET-ENDPTVOIP::IOM-8-ENET-1;(Delete Endpoint)
ENT-ENET-ENDPTVOIP::IOM-8-ENET-:::IPADDR=10.18.140.211,
MATEIPADDR=10.18.140.212,SUBNETMASK=255.255.255.0,
DEFAULTGATEWAY=10.18.140.1:IS;
(Enter new IP address to the endpoint)
ED-ENET::IOM-8-ENET-1::::IS;
RST-EQPT::IOM-11;
```
- When the SDP profile contains multiple deep compression CODECs (G.729, G.723.1 or G.726), only the first available deep compression CODEC in the preference list will be included in the originating offer from the LCS, e.g., G.729, G.711, G.726. This results in G.711 and G.729 being the offered CODECs in the originating offer (provided G.729 is available; otherwise, G.726 or G.711 would be offered). This limitation applies to CODEC negotiation across SIP.



- MF Tone detection is not supported on the VSM in this release. In order to support MF Tone detection, 89-0410/0411/0424/0425 IOMs, which have on-board DSPs to perform MF tone detection, must be used.
- The LCS only supports Payload Type 13 comfort noise for G.711 and G.726.
- RTCP reports sent for T.38 calls are invalid and should be ignored.

6.9 System Software

- UNIX system security does not support password aging or security logging for FTP and remote login access.
- The date/time should be set before configuring the system and adding the IOM. Please contact Lucent Worldwide Services at 1-866-582-3688 for instructions on how to provision the switch clock for time zone.
- If an IOM protection switch occurs, the monitoring function stops. Once an IOM revert occurs, the cross-connect to the test port has to be put out of service (OOS) and restored.
- Currently, there is no way to retrieve the status of a nailed up DS0 connection unless you know the exact DS0 of one of the connections. RTRV-CRS-T0 without an AID should return the status of test port settings.
- The ED-SERVICE-ACCESSCODE must put the VMS in-service to support voice mail. The command would appear as: ED-SERVICE-ACCESSCODE::VMS:::IS;

6.10 SS7 MTP-2 Performance

- Listed below are the number of SS7 MTP-2 messages per second that can be supported by various IOMs at different IOM CPU utilization rates, assuming that the IOM is ONLY handling SS7 signaling and IMTs. The table does not indicate the calls per second for SS7 links since these performance numbers are a function of TCAP transactions as well as ISUP (or BICC) usage. Please contact your Lucent Sales Engineer, for assistance in determining the numbers of calls per second that can be supported for your particular application(s).

Note: The total number of messages per second per chassis is 8,500 messages/sec (at 85% utilization).

Description	Part Number	MTP-2 Msgs/sec (80%)	MTP-2 Msgs/sec (40%)
3 DS-3/STS-1	89-0397	544	272
8 DS-3/STS-1	89-0398	544	272
3 DS-3/STS-1 w digit collect	89-0410	544	272
8 DS-3/STS-1 w digit collect	89-0411	544	272
28 T1/E1/J1	89-0414	768	384
3 DS-3 w digit collect	89-0424	768	384



Description	Part Number	MTP-2 Msgs/sec (80%)	MTP-2 Msgs/sec (40%)
8 DS-3 w digit collect	89-0425	768	384

6.11 SQA and NLT

- Only an INVITE with a "session-expires" value equal to or greater than the value that the session timer is configured to on the receiving switch is acceptable. The change has to be done at the same time on both MGC switches.

7 TL1 RESTRICTIONS AND SECURITY ERRATA

7.1 TL1 Restrictions

- The EXEC-BULK-DOWNLOAD command is not supported in this version.
- The following parameters in the ED-MGC-SYS command cannot be edited in this version and should be left:
 - cdr
 - iua
 - m3ua
 - megaco
 - mgcp
 - sipStaPortRange
- The *sipCgpMap* parameter for SIP and SIP-T trunk groups in the ENT/ED/RTRV-TRKGRP command is not implemented; leave it blank.
- ED/ENT-TRKGRP incorrectly allows you to set the BEARERCAP parameter to RESDIGITAL or UN UNRESDIGITAL in the ITU-T stack. These are ANSI only values.
- The minDgt2Seize parameter in the DLT/ED/ENT/RTRV-PC is not supported in this version, even though TL1 incorrectly lets you provision this un-supported parameter.
- RTRV-PM-T3::IOM-1-T3-1-PORT-1; :: [<montype>], [<monlev>] should not be executed with *montype* parameter equal to *all* since the large amount of data returned will lead to a failure in writing the data on the TL1 -port and subsequently result in the TL1 session being closed.
- The number of TL1 retrieve (RTRV) commands is limited to five results per second.
- Signaling TL1 commands respond "All Resources Busy" while standby SP is synchronizing.



- Logging into the TL1 agent cannot be done during part of SP sync on the standby side.
- When using the INIT-SYS, ED-BILLSYS, and EXEC-RESTORE-PLEXUS commands, the target identifier (TID) must always be used. Therefore, the form of the command must be, as an example, INIT-SYS:TID::::10; or ED-BILLSYS:TID::::10; or EXEC-RESTORE-PLEXUS:TID::::10;
- Before restoring a backed up database using the EXEC-RESTORE-PLEXUS command, contact Lucent Worldwide Services at 1-866-582-3688 for assistance to ensure a successful database restoration.
- The *T3 Idle* and *T3 Map* parameters in the ENT/ED/RTRV-T3 command are not supported.
- For the commands INIT-REG-T1/T3/E1/OC3/STS1, NULL is the only accepted value in the *mondat* and *montm* parameters. *ALL* is the only *montype* that will clear the registers.
- The “state” information on the SIP-IPADDR command is not persistent. If the primary IP address has failed over to the secondary IP address, and then you fail over the SP, your first SIP call after the SP failover will initially attempt the call on the wrong IP address. The call will complete on the secondary IP address once the SP determines the primary is down. The secondary IP address will then be made “active” and all subsequent calls will be made using the “active” IP Address.
- For the DLT/ED/ENT/RTRV-SS7-TRK command, ITU TRKGRP CICs are restricted to 0-4095. This command has been modified to allow for ED/DLT of non-contiguous ranges. RTRV returns a status of no more than 4,000 CICs at a time; re-invoke the command to return information for successive groups of 4,000.
- The RTRV-CAS-TRK command returns a status of no more than 4,000 CICs at a time; re-invoke the command to return information for successive groups of 4,000.

7.2 IP Security Considerations

An IP packet filtering application that runs on the SP is available in this build. It is important to note that IP packet filtering is only a subset of full firewall/Session Border Controller functionality (e.g., packet filtering, bandwidth management, user authentication, network access rules, network address translation, and back-to-back user-agent). Because IP filtering and processing filtering rules is a CPU-intensive task that can degrade overall switch performance, the use of an external network firewall is highly desirable and recommended.

However, in the absence of a firewall, IP filtering can protect the switch from unsophisticated attacks or accidental misuse.

IP Filtering **is not enabled** upon initial boot up. Should IP filtering be required, contact Lucent Worldwide Services at 1-866-582-3688 (Option 5) for assistance. An LWS representative will refer you to DLP-570, which contains specific steps for



activating/de-activating and editing security settings. DLP-570 can be obtained from your LWS representative.

It is recommended that security be enabled **during the switch maintenance window** in order to minimize any potential impact to call completion during initial activation.

8 APPENDIX A: EXCEPTIONS AND WORKAROUNDS

Currently there are no exceptions and/or workarounds.

