

**TELEVISION**  
**VIDEO TAPE SIGNAL ANALYSIS**

- 1.01** This section is issued to make available to the Bell System, Report No. 2 of the Network Transmission Committee. The Report deals with signal impairments which are peculiar to the video tape recording-playback process. It also presents a glossary of terms and a brief description of impairments that may occur in signals from both monochrome and color video tape machines.
- 1.02** The Network Transmission Committee is the subcommittee of the Video Transmission Engineering Advisory Committee. Representation consists of the following:

American Broadcasting Company  
Columbia Broadcasting System  
National Broadcasting Company  
The Bell System

**ENGINEERING REPORT No. 2**

**VIDEO TAPE SIGNAL ANALYSIS**

**MARCH, 1959**

**NETWORK TRANSMISSION COMMITTEE**

**of the**

**VIDEO TRANSMISSION ENGINEERING ADVISORY COMMITTEE**

**(Joint Committee of the Television Network Broadcasters and the Bell Telephone System)**



**TELEVISION  
NETWORK TRANSMISSION COMMITTEE  
ENGINEERING REPORT No. 2**

**VIDEO TAPE SIGNAL ANALYSIS**

**JOINT COMMITTEE**

**REPRESENTING  
THE NETWORK BROADCASTERS**

H. C. Gronberg ..... NBC  
J. Serafin ..... ABC  
W. B. Whalley ..... CBS

**Consultants:**

C. A. Younger ..... ABC  
L. Weiland ..... NBC

**REPRESENTING  
THE BELL SYSTEM**

J. Thorpe ..... AT&T - Long Lines  
A. G. Coffin ..... AT&T - Long Lines  
L. B. Davis ..... AT&T Company  
F. L. Freiberger .... Pac. Tel. & Tel. Co.  
R. W. Gast ..... N. Y. Tel. Co.

**OUTLINE OF REPORT**

**1. INTRODUCTION**

**2. THE VIDEO TAPE SYSTEM**

**2.1 The Tape**

**2.2 The Tape Machine**

**2.3 Interconnecting Facilities**

**3. GLOSSARY OF IMPAIRMENTS**

# VIDEO TAPE SIGNAL ANALYSIS

## 1. INTRODUCTION

The increasing use of video tape recording by the network broadcasters has made it important that both Broadcasting and Telephone Company operating people be able to recognize and compare certain signal impairments which are peculiar to the video tape recording-playback process. This report supplements the booklet "Television Signal Analysis" originally published by the American Telephone and Telegraph Company in 1955. It presents a glossary of terms and brief descriptive information covering impairments which can occur in signals from both monochrome and color video tape machines. Certain background information is included for completeness.

This report does not purport to set up standard terms for industry use. However, it is hoped that the terms defined will enable more efficient exchange of information in handling network operational problems.

## 2. THE VIDEO TAPE SYSTEM

All three major television networks are using Video Tape Recording (VTR) equipment. Figures 1 and 2 show the appearance of typical VTR equipment.

What appear to be transmission impairments of signals from this equipment may be caused by:—

- (a) the tape
- (b) the tape machine
- (c) the interconnecting facilities

### 2.1 *The Tape*

#### *Signal-to-Noise Ratio*

The chief factors determining the signal-to-noise ratio in the tape are the smoothness of the tape surface and the ability to magnetize the tape to optimum flux density. In the final analysis, it is necessary to choose the best compromise between signal-to-noise ratio and available modulation bandwidth.

### 2.2 *The Tape Machine*

The most serious impairments caused by the tape mechanism are "head-hunting," "mistracking" and "banding."

#### *Head-Hunting*

Because the magnetic head assembly in current VTR equipment is a rotating device controlled by a servo system, it is subject to hunting.

#### *Mistracking*

The tape is moved longitudinally past the head by a servo controlled transport mechanism. Variations in playback speed with respect to recording speed cause mistracking of the head.

#### *Banding*


There are four video heads in each rotating head assembly. Each head records sequentially approximately 16 picture lines in each field. Because of interlace the band appears as 32 lines on a monitor. Many impairments, therefore, show as distinct horizontal bands in the reproduced picture.

### 2.3 *Interconnecting Facilities*

Problems generally associated with interconnecting facilities are discussed in the prior booklet "Television Signal Analysis." In this connection, a word of caution: Beware that legitimate network transmission troubles are not neglected or overlooked just because they may be similar to, and therefore, assumed to be video tape impairments. On the other hand, when a tape machine is running at high speed (as during rewind) or is stopped, the output signal may resemble a "microwave open circuit."




**Fig. 1 - Monochrome Video Tape Recording Equipment**



**Fig. 2 - Color Video Tape Recording Equipment**


### 3. GLOSSARY OF IMPAIRMENTS



#### BANDING


##### *Delay Banding*

Banding made visible by differences in head geometry (quadrature), and/or by differences in electrical delay between the head channels.




##### *Head Displacement*

A recurring displacement of every 16 lines in each reproduced field, caused by a slight horizontal displacement of a head or misadjustment of the switching system.




##### *Noise Banding*

Banding made visible by differences in signal-to-noise ratios between head channels.




##### *R.F. Banding*

Banding made visible by undesirable radio frequency patterns.




***Scalloping***

A rounding of the edge of each band of lines caused by incorrect vertical positioning of the tape.



***Venetian Blind (Not to be confused with co-channel interference)***

A linear displacement of lines within each band, giving a sawtooth vertical picture edge. It is caused by incorrect pressure between head and tape.




**BRUSH NOISE**

Repetitive noise which is similar in appearance to ignition noise, caused by faulty slip-ring contact.

**CHROMA FLUTTER**


A random change in color saturation in portions of the picture.

## COLOR BANDING




### *Color Phase Shift Banding*

Banding made visible by differences in color phase between head channels.




### *Hue Shift Banding*

Banding made visible by hue shifts within a band.




### *First Line Hue Shift*

Banding made visible by a difference in hue of the first line of each band.




### *Saturation Banding*

Banding made visible by differences in saturation between head channels.




#### **DROPOUTS**

Random noise flashes directly associated with imperfections in the magnetic coating of the tape.




#### **EDGE BEAT**

An irregular beat at edges of sharp luminance transitions. This is caused by intermodulation between the various component signals.




#### **HEAD HUNTING**

A horizontal shifting back and forth of the reproduced picture, caused by undesirable fluctuations in speed of the head.




#### **HEAD SWITCHING TRANSIENTS**

White or black transients which occur regularly in bands, resulting from improper operation of the head switching system.




### **HIGH-LIGHT TEARING**

Polarity changes of high-light picture areas, caused by overdeviation in the modulation process.




### **MISTRACKING**

Deterioration in picture quality, caused by errors in positioning of the tape with respect to the head. The degree of impairment may vary from a reduced signal-to-noise ratio through heavy moiré to complete loss of picture.



### **ROTATIONAL "S" DISTORTION**

A horizontal shift of picture lines in time with a rotation of the head, (repeating every 4 heads).



### **SCRATCHES**

Noise flashes forming a geometrical pattern, usually diagonal, and caused by physical scratches in the magnetic material.

### **WATERFALL**

A shimmering effect over the entire picture, which may be caused by defective or worn bearings.