




Boss Chromatic Tuner TU-2 Fix battery connection

My boss Chromatic Tuner TU-2 was working fine when connected to the 9V DC input, but not working on batteries. Here's how I've debugged and fixed the issue.

Written By: palako




This document was generated on 2020-04-05 08:47:07 PM (MST).

INTRODUCTION

My boss Chromatic Tuner TU-2 was working fine when connected to the 9V DC input, but not working on batteries. Here's how I've debugged and fixed the issue.

The guide is marked as difficult because it requires soldering, but it's just a simple soldering job, other than that assembling and disassembling is easy and straightforward.

Step 1 — Reproducing the problem





- With the 9V DC input connected, the unit switches on correctly
- When on batteries, the pedal will not work unless a jack is plugged into the input (for battery saving). However, in this case the unit won't work.
- Note that instead of a 9V battery I'm using alligator clips to connect the battery connector to my DC power source at 9V, which does the same.

Step 2 — Opening the pedal





- Turn the pedal upside down and remove the 4 screws in the corners with a regular Phillips screwdriver

Step 3 — Access the PCB




- Remove the plastic lid and lift the circuit board. There are no delicate connections but there are cables connecting it to the other PCB, so don't pull too hard and don't separate them completely.

Step 4 — Test the cable connections




- From the battery connection, test continuity with a multimeter to where the cable is soldered to the PCB, input connector, etc...
- For me, all of these connections worked fine

Step 5 — Test the PCB traces



- Starting where the cable is soldered to the PCB, follow the traces checking for continuity.
- In my case I found one that was not connected, I cleaned it with a bit of isopropyl alcohol, and looked with a magnifying glass to reveal what looks like a crack on the trace.

Step 6 — Short the contact pads




- Solder a thin piece of solid wire between the two contact pads that should be in touch by the trace

Step 7 — Check the soldering



- Test for continuity between the two pads that have been joined
- Make sure no other contacts have been affected by the soldering

Step 8 — Test the battery connection



- Insert a battery (I'm still using my DC power source) and check that the unit powers up
- Don't forget to add a jack to the input or the unit won't power up on batteries

To reassemble your device, follow these instructions in reverse order.