

HPE 3PAR OS 3.2.2 MU1 Patch 16 Release Notes

This release notes document is for Patch 16 and intended for HPE 3PAR Operating System Software 3.2.2.326 (MU1).

Part Number: QL226-99132 Published: March 2016

Edition: 1

© Copyright 2016 Hewlett Packard Enterprise Development LP

The information contained herein is subject to change without notice. The only warranties for Hewlett Packard Enterprise products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. Hewlett Packard Enterprise shall not be liable for technical or editorial errors or omissions contained herein.

Confidential computer software. Valid license from Hewlett Packard Enterprise required for possession, use, or copying. Consistent with FAR 12.211 and 12.212, Commercial Computer Software, Computer Software Documentation, and Technical Data for Commercial Items are licensed to the U.S. Government under vendor's standard commercial license.

Acknowledgments

Intel®, Itanium®, Pentium®, Intel Inside®, and the Intel Inside logo are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Microsoft® and Windows® are trademarks of the Microsoft group of companies.

Adobe® and Acrobat® are trademarks of Adobe Systems Incorporated.

Java and Oracle are registered trademarks of Oracle and/or its affiliates.

UNIX® is a registered trademark of The Open Group.

Documentation

For the latest version of this document, go to www.hpe.com/info/enterprise/docs.

Contents

1	Purpose	.4
	Guidance	
	Prerequisites	
	Details	
	Warnings, cautions and notes	4
	Related documentation	4
	Affected components	
	Modifications	5
	Verification	5

1 Purpose

HPE 3PAR OS 3.2.2 MU1 P16 prevents an unexpected array restart where RC was ever configured.

Guidance

This patch applies to 3PAR OS 3.2.2 MU1. This is a recommended patch. The Patch 16 install will fail if 3PAR 3.2.2 MU1 Patch 02 is already installed. Patch 16 should not be applied if the system is running Asynchronous Streaming Remote Copy.

Prerequisites

• **SP**: 4.4.0.GA-22 plus the latest SP patch (if any)

• **OS**: OS-3.2.2.326-MU1

Details

Affected packages: tpd-kernelpatch, tpd-prerevert

Obsoletes: OS-3.2.2.326-P12

Build version: 3.2.2.398

Revertible: Yes

Warnings, cautions and notes

MARNING!

- Patch 16 should not be applied if the system is running Asynchronous Streaming Remote Copy.
- The Patch 16 install will fail if 3PAR 3.2.2 MU1 Patch 02 is already installed.

△ CAUTION: Patch 16 must be installed prior to upgrading from 3PAR 3.2.2 MU1 to a later version.

NOTE:

- A post-installation procedure to reset 8 GB Fibre Channel (FC) ports is required for Patch 16. Refer to the HPE 3PAR OS 3.2.2 MU1 Patch 12 Release Notes for the steps to complete this procedure. This procedure is not required if Patch 12 was previously installed and the post-installation steps were performed.
- Applying this patch to the 3PAR OS might restart the affected OS components. With these
 restarts, events and alerts might be generated and this is an expected behavior. The system
 continues to serve data, but existing CLI or SSMC sessions might be interrupted.
- Hewlett Packard Enterprise recommends installing patches in the same sequence as they are released, unless instructed otherwise.
- When displaying the showversion command output from the SP, the CLI Client version is fixed in the SP code, and might differ from the output displayed from any other system.

Related documentation

For information about supported browsers for SP, see the Single Point of Connectivity Knowledge (SPOCK) website: http://www.hpe.com/storage/spock

Affected components

Component	Version
TPD Kernel Patch	3.2.2.398 (P16)

Modifications

This patch includes the following modifications to 3PAR OS 3.2.2 MU1:

 Prevents an unexpected array restart due to a single controller node restart such as, but not limited to, maintenance activities or online upgrades on systems running 3PAR 3.2.2 MU1. This unexpected array restart affects systems on which Remote Copy was ever configured.

Verification

The installation of Patch 16 can be verified from an interactive CLI session. Issue the CLI command showversion -a -b to verify that Patch 16 is listed.

```
cli% showversion -a -b
Release version 3.2.2.326 (MU1)
Patches: P16
Component Name
                             Version
CLI Server
                             3.2.2 (MU1)
CLI Client
                              3.2.2
System Manager
                             3.2.2 (MU1)
                             3.2.2 (MU1)
Kernel
TPD Kernel Code
TPD Kernel Patch
                             3.2.2 (MU1)
                         3.2.2 (P16)
```