

| | |
|-------------|---------------|
| 产品名称 | 密级 |
| E5885Ls-93a | 内部公开 |
| 产品版本 | Total 3 pages |
| V200R001 | |

HUAWEI E5885Ls-93aTCPU-V200R001B170D99SP03C00

烧片软件版本说明书

| | | | |
|-------------|---------------------|------|----------|
| Prepared by | E5885ls-93a Team | Date | 2017/3/1 |
| Reviewed by | | Date | |
| Approved by | | Date | |



Huawei Technologies Co., Ltd.

All rights reserve

目录

目录

- 1 缩略语3
- 2 硬件信息3
- 2.1 版本描述3
- 3 烧片软件3
- 3.1 版本描述3
 - 3.1.1 E5885Ls-93aTCPU-V200R001B170D99SP00C00.....3
 - 3.1.2 E5885Ls-93aTCPU-V200R001B170D99SP01C00.....3
 - 3.1.3 E5885Ls-93aTCPU-V200R001B170D99SP02C00.....3
 - 3.1.4 E5885Ls-93aTCPU-V200R001B170D99SP03C00.....3

1 缩略语

| 缩略语 | 描述说明 |
|-----|------|
| E5 | |

2 硬件信息

2.1 版本描述

| | |
|---------------------|--------------------------------------|
| Hardware Version: | CL1E5885SM |
| Platform & Chipset: | Balong Hi6932+Hi6362 V7R22 Hi1151 |

3 烧片软件

3.1 版本描述

| | |
|------------------------|----------------------|
| Firmware Version : | 21.170.99.03.00 |
| Baseline information: | Balong V7R22 C30B170 |
| ProductLine WinDriver: | 2.78.11.00 |

3.1.1 E5885Ls-93aTCPU-V200R001B170D99SP00C00

| Index | Case ID | Issue Description |
|-------|--------------|-------------------|
| 1 | New Features | E5885Ls-93a 烧片. |

3.1.2 E5885Ls-93aTCPU-V200R001B170D99SP01C00

| Index | Case ID | Issue Description |
|-------|--------------|---------------------|
| 1 | New Features | RD工位中断验证方案，其余为BUG修复 |

3.1.3 E5885Ls-93aTCPU-V200R001B170D99SP02C00

| Index | Case ID | Issue Description |
|-------|--------------|-------------------|
| 1 | New Features | 无新特性，全部是BUG修复 |

3.1.4 E5885Ls-93aTCPU-V200R001B170D99SP03C00

| Index | Case ID | Issue Description |
|-------|--------------|-------------------|
| 1 | New Features | 无新特性，全部是BUG修复 |

