

Prepared (Subject resp) XNATTOL Nataliya TolokontsevaXNATTOL Nataliya		No. 15/1543-ANA 901 37 Uen		
Approved (Document resp) BICPAGCB [Hans Fernqvist]	Checked	Date 2016-11-23	Rev B	Reference

SS7 CAF Route Set Failure

Contents

1	Overview	2
1.1	Description	2
2	Procedure	2

Prepared (Subject resp) XNATTOL Nataliya Tolokontseva		No. 15/1543-ANA 901 37 Uen		
Approved (Document resp) BICPAGCB [Hans Fernqvist]	Checked	Date 2016-11-23	Rev B	Reference

1 Overview

1.1 Description

The alarm is issued when an unsuccessful forced rerouting was performed due to which a route set has become inaccessible.

Major type	193
Minor type	1586562671
MO Class	N/A
Specific Problem	SS7 CAF Route Set Failure
Severity	SEVERITY_WARNING
Additional Text	Route Set Failure

The possible causes are as follows:

- No alternative routes exist towards the concerned DPC. All forced rerouting failed.

Note: If links that could carry traffic to the destination are inhibited, an automated procedure to uninhibit them will begin. If the uninhibit is successful a controlled rerouting will be performed. All unavailable signaling links are repeatedly restarted in an attempt to realign. If a link realigns successfully a route concerned with the link will become available.

2 Procedure

If the alarm is persistent contact the next level of maintenance support, see SS7 CAF Troubleshooting Guide for details.