

DOCUMENT NUMBER: MTN-0013-17-NA

APC: 466, 471, 527, 570,  
652, 656, 757, 761

ISSUE DATE: 01-2017

EXPIRATION DATE: 31-01-2018

Bulletin Type: Informational Only

## **Motorola Solutions Technical Notification (MTN)**

**TITLE:** Cannot write Power Detection Calibration values to the radio using the APX Tuner R15.00.02

**TECHNOLOGY:** APX Tuner

**SYMPTOMS:**

A communications error is displayed when attempting to write Power Detection Calibration values into the APX mobile radios using the R15.00.02 APX Tuner

**MODELS / SYSTEM RELEASES / KITS / DATECODES AFFECTED:**

All APX mobile radios

**SEVERITY RECOMMENDATION:**

**Low / Maintenance** - Perform if system exhibits above symptoms

**ROOT CAUSE / DEFINITIVE TEST:** Code defect

**WORKAROUNDS AND CORRECTIVE ACTIONS:**

Use R14.01.03 APX Tuner

**RESOLUTIONS AND REPAIR PROCEDURES:**

The fix for this issue is included in Tuner Version **R15.00.03** which is available on Motorola-On-Line (Resource Center > Software > Two-Way > APX Family Portables and Mobiles)

**PARTS REQUIRED (HARDWARE/SOFTWARE):**

RVN5224AH (APX Portable and Mobile) Tuner version R15.00.03 \*\*

**APX Tuner \*\* can be obtained by downloading from Motorola-On-Line at the following location:**

Resource Center > Software > Two-Way > APX Family Portables and Mobiles.

**\*\*Requires a current license subscription.**

**ADDITIONAL INFORMATION:**

NA

**REFERENCE THE FOLLOWING DOCUMENTS/PROCESSES FOR INSTALLATION PROCEDURES:**

NA

ANY USE NOT APPROVED BY MOTOROLA SOLUTIONS IS PROHIBITED. This Motorola Technical Notification (MTN) is issued pursuant to Motorola's ongoing review of the quality, effectiveness, and performance of its products. The information provided in this bulletin is intended for use by trained, professional technicians only, who have the expertise to perform the service described in the MTN. Motorola disclaims any and all liability for product quality or performance if the recommendations in this MTN are not implemented, or not implemented in compliance with the instructions provided here. Implementation of these recommendations may be necessary for the product to remain compliant with applicable laws or regulations. Please be advised, that failure to implement these recommendations in the manner instructed may also invalidate applicable warranties, or otherwise impact any potential contractual rights or obligations. MOTOROLA, MOTO, MOTOROLA SOLUTIONS, and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. ©2016 Motorola Solutions, Inc. All rights reserved."

**WHEN TO APPLY RESOLUTION:**

After reboot \_\_\_  
After (re)installation \_\_\_  
After upgrade \_\_\_  
After power cycle \_\_\_  
After database restoration \_\_\_  
After failure \_\_\_  
On FRU replacement \_\_\_  
During maintenance \_\_\_  
Immediately \_\_\_  
As instructed \_X\_  
Information only \_\_\_

**LABOR ALLOWANCE:**

This is an informational bulletin. No labor warranty is implied, intended or authorized.

For assistance with this bulletin please contact your MSI Technical support centre  
[https://www.motorolasolutions.com/en\\_us/support.html](https://www.motorolasolutions.com/en_us/support.html)