

NA Firmware R01.04.00

Release Notes
November 27th 2023

| Fixes / Enhancements: | <p>New main Features:</p> <p>1. Full Cloning:</p> <p>Over the Air (OTA) Full Cloning feature allows you to add all the channels from another radio wirelessly without connecting the radios by cable. OTA Full Cloning feature is enabled through Customer Programming Software (CPS) configuration. To acquire the channels, all the contacts in the source radio replace the contacts in the target radio. The target radio contact can be either private or private group only.</p> <p>This feature will first do the the existing Contact All Cloning feature then only it will clone the channel. It enables users to clone all contact lists and channels within Primary radio to the Receiving radio/s via OTA. The items that will be cloned for the channel are:</p> <ul style="list-style-type: none">1. Channel Name,2. Disabled Channel,3. Mode (contact type), and4. Channel Mapping (ID) <p>The need to clone all contacts first is because radio channels have very high dependency on the contacts.</p> <p>2. DTR Lockup Fix</p> <p>This firmware fixes the hang screen and power cycle during switching the channel.</p> | | | | | | | | |
|-----------------------|--|--------------|-------------|-------------|-----------|----------------------------|--------------|--------------|------------------------|
| | <p>Applicable Models:</p> <table><tr><th>S/Tanapa</th><th>Description</th><th>Sales Model</th></tr><tr><td>PMUF1952A</td><td>S/T DTR600 1W 900 MHZ 30CH</td><td>DTS130NBDLAA</td></tr><tr><td>PMUF1954A/AD</td><td>DTR700 1W 900 MHZ 50CH</td><td>DTS150NBDLAA</td></tr></table> | S/Tanapa | Description | Sales Model | PMUF1952A | S/T DTR600 1W 900 MHZ 30CH | DTS130NBDLAA | PMUF1954A/AD | DTR700 1W 900 MHZ 50CH |
| S/Tanapa | Description | Sales Model | | | | | | | |
| PMUF1952A | S/T DTR600 1W 900 MHZ 30CH | DTS130NBDLAA | | | | | | | |
| PMUF1954A/AD | DTR700 1W 900 MHZ 50CH | DTS150NBDLAA | | | | | | | |

| | | | | | | | | | | |
|----------------------------|---|--|------------------------|--------------|------------------|------------------|-------------|---------------|-------------|---------------|
| | PMUF1954B/BD | | DTR700 1W 900 MHZ 50CH | DTS150NBDLAA | | | | | | |
| SOFTWARE | DTR Full Cloning (R01.04) <table><tr><td>Firmware Version</td><td>R01.04.00</td></tr><tr><td>CPS Version</td><td>R09.08</td></tr><tr><td>Update Tool</td><td>R01.05</td></tr></table> | | | | Firmware Version | R01.04.00 | CPS Version | R09.08 | Update Tool | R01.05 |
| Firmware Version | R01.04.00 | | | | | | | | | |
| CPS Version | R09.08 | | | | | | | | | |
| Update Tool | R01.05 | | | | | | | | | |
| USER GUIDE | MN004869A01-AE https://learning.motorolasolutions.com/user-guide/51387enus | | | | | | | | | |
| MANUFACTURING CUTOVER DATE | | | | | | | | | | |