



TELEX

Radio Dispatch

Radio Dispatch Engineering Group

System Manager 1.500 Engineering Release Notes

Notice:

The content in this document represents the current view of Bosch Security Systems as of the date of publication. Because Bosch Security Systems responds continually to changing market conditions, this document should not be interpreted as a commitment on the part of Bosch Security Systems. Bosch Security Systems cannot guarantee the accuracy of any information presented after the date of publication.

Bosch Security Systems. All rights reserved

Revision E

June 8, 2012

Table of Contents

1. Revision History	1
2. Overview.....	1
3. New Features	1
4. Improved Features and Fixed Issues	1
5. Known Issues.....	4
6. Compatibility.....	4
7. Installation and Upgrade.....	4

1. Revision History

Revision	Date	Author	Description
A	7/30/2008	Radio Dispatch Engineering	Initial draft System Manager Version 1.100
B	08/03/2009	Radio Dispatch Engineering	Updated System Manager Version 1.200
C	03/30/2010	Radio Dispatch Engineering	Updated System Manager Version 1.300
D	10/18/2010	Radio Dispatch Engineering	Updated System Manager Version 1.400
E	06/08/2012	Radio Dispatch Engineering	Updated System Manager Version 1.500

2. Overview

This is the release notes for Telex System Manager firmware/software. This release contains new features, improved features, and fixed issues. The release notes include all of the changes and fixes since official release Version 1.500.

3. New Features

Version 1.500

- Added support for IP-224. Supports reading, writing, modifying, and copying IP-224 device parameters.
- IP packet TTL value, Device Detection timeout, Configuration Update timeout, and Firmware Update timeout are now user configurable parameters. These fields are located in Tools -> Options.
- System Manager now displays an LED icon in the Device List to indicate if a device is running a firmware version compatible with the version of System Manager. The LED colors mean the following:
 - Green – Device is running firmware compatible with this version of System Manager. System Manager can read and write parameters to this device
 - Red – Device is running firmware incompatible with this version of System Manager. The device's firmware must be upgraded to a supported firmware version before device parameters can be read or written.
 - Blue – System Manager detects this device on the network but does not support reading or writing device parameters for this device type.

4. Improved Features and Fixed Issues

Version 1.500

- General
 - Delete key is now recognized in the login username and password fields.
 - The firmware version for configuration files read from a file is now displayed in the device list's tool tip.
 - Improved exception handling if System Manager is unable to open a Telnet window.
 - Resolved issue which caused System Manager to become unresponsive if the Network Device list was being refreshed while System Manager was closing.
- ADHB-4 Configuration
 - Changed "Console Name" field to "Position Name".
 - Deck Mic Connector Setup field is now being read correctly from the ADHB-4.
 - Microphone Input Noise Threshold settings were not being copied when copying configurations between ADHB-4s.



- Resolved issues where certain device firmware checksum values would cause System Manager to crash.
- The Console Name and IP Address fields were being recorded to an ADHB-4 even if the Record Name & IP Address checkbox was unchecked.
- The following fields were not being saved correctly:
 - Console Generated PTT
 - Footswitch PTT
 - NENA PTT
 - PTT Priority
- IP-1616 Configuration
 - Account Setup checkboxes now matches the IP-1616's webpage Account Setup.
 - Added Gain setup as a configurable setting in Account Setup.
 - Added logic to disable the TX All Enable Key field if TX Blocks were configured for any of the lines.
 - Added support for up to 15 Local Console IP Addresses.
 - Can now read and write to the System Manager Enabled and TTL fields on Multicast tab.
 - Changed label for RX Block field from seconds to milliseconds.
 - Combined Paging and ID Directory fields in Account Setup.
 - Disabled the Record Name and IP Configuration checkbox when recording the IP-1616's configuration. Version 4.100 of the IP-1616 does not support changing the Console Name or Base IP Setup parameters via System Manager.
 - Entries in ID Directory can now be deleted via the 'X' delete button.
 - Fixed issue with reading the ID Directory parameters in version 4.100 of IP-1616.
 - Handset Speaker Gain drop menu no longer displays duplicate values if the configuration is re-downloaded from the device.
 - Removed the following fields:
 - DNS 3 field from the Network Setup tab.
 - The Aux Relay Button field under System Setup in Copy Configuration. Settings can be copied using the NEO10 Aux Relay Button field under Multicast Setup.
 - Renamed the following fields to match the IP-1616 webpage:
 - "RX Only" to "TX Inhibit" on the ID Directory tab.
 - "Custom Accounts" to Created Accounts in Account Setup tab.
 - "TX/RX Block" to "RX/TX Block" on RX/TX Block tab.
 - "Nextel Phone" to "iDEN Phone" on Per Line Setup tab.
 - The following fields were not being copied correctly
 - Line Type in Multicast setup
 - Base IP in Multicast setup
 - Multicast IP in Multicast setup
 - TX Port in Multicast setup
 - The following fields were not being saved correctly:
 - Disable Call List in System setup
 - Enable ID Lookup parameter in ID Directory
 - Handset to Speaker in System setup
 - Multicast settings except for first two lines
 - Page String and Page Format in Paging
 - Pair Mode configuration in Per Line setup
 - SNTP Local Time Offset in Network setup
 - Tape Mix settings in System setup

- IP-2002 Configuration
 - Account Setup checkboxes now matches the IP-2002's webpage Account Setup.
 - Added Gain setup as a configurable setting in Account Setup
 - Added support for up to 15 Local Console IP Addresses.
 - Combined Paging and ID Directory fields in Account Setup
 - Disabled the Record Name and IP Configuration checkbox when recording the IP-2002's configuration. Version 4.100 of the IP-2002 does not support changing the Console Name or Base IP Setup parameters via System Manager.
 - Fixed issue where the TX Block field for line 1 was disabled when configuring line 2.
 - Fixed RX Block Time field so the field is displayed and saved in milliseconds. In previous versions this field was displayed and saved in seconds.
 - Handset Speaker Gain drop menu no longer displays duplicate values if the configuration is re-downloaded from the device.
 - Removed DNS 3 field from the Network Setup tab.
 - Renamed the following fields:
 - "Custom Accounts" to "Created Accounts" in Account Setup tab
 - "RX Only" to "TX Inhibit" in the ID Directory tab
 - "TX/RX Block" to "RX/TX Block" on RX/TX Block tab.
 - The following fields were not being copied correctly:
 - Per Line Radio settings when copying only the Radio settings
 - Select Call settings in Per Line setup.
 - The following fields were not being saved correctly:
 - Enable ID Lookup parameter in ID Directory
 - Pair Mode configuration in Per Line setup
 - System Manager and TTL fields in Multicast setup
 - RX/TX Block parameters in Per Line setup
 - Select Call settings in Per Line setup
 - Page String and Page Format fields in Paging
 - SNTP Local Time Offset in Network setup
- IP-223 Configuration
 - Added additional validation to ensure the Crosspatch PIN field is four digits.
 - Added additional validation to ensure the Crosspatch Drop All field contains the same number of digits as specified by the Dialing Digits field.
 - Fixed issue where iDEN Direct Connect and Group fields were being populated with data from the previous page.
 - Fixed data validation logic for the Relay Group field in Function Tone setup when importing via .csv file.
 - Function Tone – CTCSS data can now be imported via a .cvs file.
 - Modifying LAM Time or Busy Channel Lockout field on one line caused the parameter to be updated on both lines.
 - Renamed "Custom Accounts" to Created Accounts in Account Setup tab.
 - System and Channel fields in Function Tone-CTCSS setup can no longer be set to 0.
 - The following fields were not being copied correctly:
 - MSK Tone Gain fields
 - Ethernet Setup when copying only the Ethernet Setup or child parameters of Ethernet Setup
 - The following fields were not being saved correctly:
 - Crosspatch Drop All field in Crosspatch setup
 - Crosspatch RCP DTMF Decode field in Crosspatch setup
 - DNS 3 field in Network setup



- Serial Over IP fields would save only if another field was clicked before recording the configuration to the IP223.
- Serial Over IP TCP Client in Serial Over IP setup

5. Known Issues

- IP-1616 v4.100 does not support changing the Console Name or Base IP Setup parameters via System Manager.
- IP-2002 v4.100 does not support changing the Console Name or Base IP Setup parameters via System Manager.

6. Compatibility

- System Manager v1.500 supports the following device firmware versions:

Device	Minimum Firmware Version
ADHB-4	v1.202
IP-1616	v4.100
IP-2002	v4.100
IP-223	v4.500
IP-224	v0.042

7. Installation and Upgrade

- To install Telex System Manager 1.500
 - If the .NET 2.0 framework or greater is not installed, first install using either through the Microsoft update.
 - Run setup.exe and follow the prompts.