

## CENTRALIZED AUTOMATIC REPORTING ON TRUNKS (CAROT)

### CAROT 1

### CAROT CENTER OPERATION AND ADMINISTRATION

### SUMMARIZATION OF TEST RESULTS

#### 1. GENERAL

1.001 This addendum supplements Section 010-410-315, Issue 2. Place this pink sheet ahead of Page 1 of the section.

1.002 This addendum is issued:

- (a) to correct a trouble indication for trunks failing operational tests
- (b) to revise information and figures for the Trunk Transmission Maintenance Index (TTMI).

#### 2. CHANGES TO SECTION

2.001 On Page 5, in paragraph 3.14, change the indication for a timing disconnect failure (SXS ROTL only) from O to D.

2.002 On Page 8, at the end of paragraph 4.17, add the following sentence: For companies using a mechanized summary procedure, Form E-6501 should be prepared in accordance with Section 660-403-011.

2.003 On Page 23/24, in Fig. 10, make the following changes:

- (a) Change the form date from 4/74 to 3/75.
- (b) Delete the legend on the TTMI from the lower right-hand corner and add the following:

**\*% Measurements Made**

Type	FAC	Freq.	Formula
8	05	30	$(F \div 3A) \times 100$
8	05	10	
8	05	20	
9	06	30	$(F \div 6A) \times 100$
9	10	30	
9	06	10	
9	06	20	
9	10	10	$(F \div 12A) \times 100$
9	10	20	

Greater than 100% = 100%  
BSP 301-121-500  
301-122-500

2.004 On Page 25, in Fig. 11, make the following changes:

- (a) Under the column headed RDCYCA0136C, change the 05 in 9 05 20 and 9 05 30 to 06.
- (b) In the legend, after 05—E-TYPE REPEATER OR NON-GAIN, add the following: 06—E-TYPE REPEATER OR NON-GAIN + HYB.

#### NOTICE

Not for use or disclosure outside the  
Bell System except under written agreement