

KS-SPECIFICATION TIMERS

GENERAL REPLACEMENT INFORMATION

1. GENERAL

1.01 This section covers information relative to the replacement of those KS-type timers not specifically covered by other Bell System Practices.

1.02 This section is reissued to:

- Add the KS-21142 timer
- Cover the disposition of the KS-16663, KS-19931, and KS-20323 timers under 2.01 instead of 2.02
- Add 2.04 which concerns failure reports
- Delete KS-13585 timer which has been rated Manufacture Discontinued.

2. TIMERS

2.01 When one of the following timers malfunctions, it is to be discarded and replaced with a new one of the same code:

KS-14799	KS-19145
KS-16100	KS-19248
KS-16446	KS-19408
KS-16594	KS-19812

KS-16625

▶KS-19931◀

KS-16643

KS-19940

KS-16663

▶KS-20323◀

KS-16755

KS-20369

KS-16924

▶KS-21142◀

2.02 The following KS-timers are to be replaced with a new or repaired timer when defective and returned to the supplier or Western Electric for repair:

KS-8561

KS-16585

KS-19999

2.03 The KS-20394 timer is a solid-state plug-in device which requires no maintenance. When one of these timers becomes defective, it is to be replaced and the old one discarded.

2.04 ▶Failure reports of any of the above timers should be sent to Engineering Control, Purchased Products Engineering, Springfield, New Jersey, 07081.◀