

GFELLER LINE CONCENTRATORS  
49-9-2, 49-11+1-2, 49-12-2  
INITIAL PREPARATION, LINE-UP, AND CUTOVER

1. GENERAL

(a) Test F, Step 13 - revised

1.001 This addendum supplements Section  
067-201-201.

F. Test of M and N Relays

1.002 It is issued to correct a typographical  
error in Test F, Step 13.

13 Using the W3M cord -  
Insert plug in BAT G jack and  
connect tip (white conductor) to  
battery and sleeve (red conductor)  
to ground.

4. METHOD

The following change applies to Part 4  
of the section: