



**MOTOR-DRIVEN GENERATORS**  
**RINGING AND COIN CONTROL**  
**KS-15816**

**REPLACEMENT PARTS AND PROCEDURES**

**1. GENERAL**

**1.01** This addendum supplements Section 155-425-801, Issue 1. Place this pink sheet ahead of Page 1 of the section.

**1.02** This addendum is issued to include information on the rubberized link and collar (not shown in illustrations) that fits on the shaft between the tone alternator and the interrupter.

In Part 3 after 3.20, add:

**3.21 *Rubberized Link and Collar:*** To replace the rubberized link and collar that fits on the shaft between the tone alternator and interrupter, remove the interrupter from the shaft, remove and replace the link and collar, and reinstall the interrupter.