

**50-KILOBIT WIDEBAND LOOP
1 THROUGH 50 KHZ
WLR-5 REPEATER
INSTALLATION AND CONNECTION**

1. GENERAL

1.001 This addendum supplements Section 314-643-200, Issue 3. Attach this pink sheet in front of Page 1.

1.002 This addendum is reissued for the following reasons:

- (a) To add information concerning tip and ring continuity
- (b) To update lineup and test references.

2. CHANGES TO SECTION


2.001 On Page 3, paragraph 3.03, add the following: The installer must strap certain connector pins located at the rear of a terminal and customer repeater. See Fig. 6.

2.002 On Page 6, paragraph 4.01, change from "Perform the polarity check, preliminary inspection and adjustments, energizing, equalization, and pilot alarm test per Section 314-643-500" to "Perform the repeater preparation and loop lineup procedure per Section 314-643-500."

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement


TERMINAL REPEATER



NOTE: INTERMEDIATE REPEATER DOES NOT REQUIRE TIP AND RING CONTINUITY STRAPPING BY INSTALLER.

STRAPS TO BE MADE BY INSTALLER

CUSTOMER REPEATER



STRAPS TO BE MADE BY INSTALLER

Fig. 6—Tip and Ring Continuity Strapping