

NOTICE

Certain voice (protective) connecting arrangements briefly described in this publication are no longer available for new connections of customer-provided equipment to the facilities of the Telephone Company. Technical References involved are:

PUB 42101	PUB 42301
PUB 42102	PUB 42305
PUB 42104	PUB 42307
PUB 42108	PUB 42701
PUB 42109	PUB 42702
PUB 42211	PUB 42703