

**ADJUSTMENT
AECO DIAL SPEED**

1. GENERAL

1.01 This Addendum is issued to add information pertaining to the limitations and scope of field adjustments of dial speed in Part 1, and also to change the text and the dial pliers in Part 2 of GSP 473-822-700, Issue 2. In ink or red pencil, make the changes as indicated in Part 2. This addendum should then be filed in front of GSP 473-822-700, Issue 2.

2. CHANGES AND ADDITIONS

2.01 In the margin, next to Part 1. GENERAL and Part 2. TOOLS write "See Addendum".

2.02 To Part 1. GENERAL add the following paragraphs:

1.05 Dials requiring adjustment should be replaced and the defective dial properly packaged and identified before being

sent to the repair shop. A tag explaining the dial faults should be affixed to the dial.

1.06 Field adjustment of dials is not recommended. If, however, it becomes absolutely essential that the dial be adjusted in the field, the work should be done by qualified personnel having the proper tools and having supervisory authorization.

2.03 Change paragraph 2.01 to read: When field adjustment of the dial is required one of the following governor adjusting tools should be issued in addition to the basic station installation maintenance tools as prescribed in paragraph 3.01 of GSP 080-020-080.

(a) Dial Pliers (Material Code No. 586205).

(b) Spring Bender (Material Code No. 580050).