

KS-19442 TELEPHONE BOOTH

IDENTIFICATION AND INSTALLATION

1. GENERAL

1.001 This addendum supplements Section 508-231-100, Issue 3.

1.002 This addendum is issued to:

- Add information explaining why no directory racks are used.
- Delete information pertaining to the unfinished bronze trim.
- Delete list number from KS-19094 anti-seize compound.
- Revise information on vacuum cup glass lifters.
- Add information on the 127A cover assembly.
- Add note to Fig. 13.
- Add note pertaining to seat installation.

1. GENERAL

The following supplemental information applies to Part 1 of the section.

(a) 1.08 — added

1.08 This booth was not designed to include an interior directory. It is intended that this all glass deluxe booth be placed in locations that have a directory shelf or table.

2. IDENTIFICATION

Delete the following information from Table B of the section.

LIST NO.	DESCRIPTION
84	Trim and Accessory Finish — Unfinished Bronze

3. SPECIAL TOOLS

The following supplemental information applies to Part 3 of the section:

- (a) Tool listing — revised
- (1) L1 should not be specified with KS-19094 antiseize compound.
 - (2) Red Devil should not be specified with vacuum cup glass lifters.
Revise to read as follows:
Glass lifter, Vacuum Cup, (capable of lifting 50 pounds — 2 required)

4. INSTALLATION — SINGLE BOOTH

The following supplemental information applies to Part 4 of the section.

- (a) 4.10 (i) — added
- (i) If a 235G coin telephone is used, a 127A cover should be installed over the telephone. This cover must be ordered separately since it is not a part of the booth or telephone.

5. INSTALLATION — SIDE-BY-SIDE MULTIPLE ARRANGEMENT

The following supplemental information applies to Part 5 of the section.

- (a) Fig. 13 — added note
- (b) 5.06 (ar) — added note

Fig.13 — *Note:* Earlier models of the booth were equipped with a B-562315 guide assembly and a B-562318 door stop. In current models, these two items are combined into one assembly as shown (B-650993 door stop assembly). If either of the two early items becomes damaged, they should be replaced with the B-650993 door stop assembly.

5.06 (ar) (Add at end of this paragraph)

Note: Ensure that all interlocking parts are properly engaged and all screws are tight.