

## TP193987 TAPE GUIDE BRACKET

*APPARATUS AFFECTED:* 28A, 28B, 28B-1, 28C, 28D, 28E, 28E-1, 28F, 28G, 28G-1, 28H, 28J, 28J-1, 28K, 28L Perforator-Transmitter-Bases; TP194076 Modification Kit; TP193987 Tape Guide Bracket.

*OBJECT:* To prevent a loop of tape from forming which can result in an interference with the print hammer on the typing unit when mounted in an ASR Set.

*CHANGE:* The TP193987 tape guide bracket is modified to add an "L" shaped arm.

The TP193987 tape guide bracket is shown in Specification 50,260S covering the TP194076 modification kit to provide rigid tape path.

*IDENTIFICATION:* See "CHANGE".

*INTERCHANGEABILITY:* New and old style brackets are interchangeable.

*CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE:* This change is now in effect.

*W.E.CO. STOCK OF OLD STYLE PARTS:* Should not be furnished after new style parts become available.

*APPLICATION TO APPARATUS IN THE FIELD:* Should be incorporated in all apparatus.

*APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS:* All units and modification kits shall be equipped with new style parts as soon as new style parts can be obtained from Teletype.