

**TP182867 thru TP182872, TP182874, TP182875 and
TP182929 SELECTOR LEVERS**

APPARATUS AFFECTED: 33C, 33C-1, 33C-2, 33C-3, 33C-4, 33F, 33F-1, 33F-2, 33F-3, 33F-4 Teletypewriter-Sets.

OBJECT: To reduce the possibility of accidentally dislodging the TP182909 spring.

CHANGE: The anchor for the tape punch selector lever spring is being modified.

The TP182867, TP182868, TP182869, TP182870, TP182871, TP182872, TP182874, TP182875 and TP182929 selector levers are shown in Teletype Bulletin 1184B, page 5-4, change 3.

IDENTIFICATION: New style selector levers have the open end of the spring anchor facing the pivot hole; old style selector levers have the open end of the spring anchor facing away from the pivot hole.

INTERCHANGEABILITY: New and old style selector levers are interchangeable.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change is now in effect for the TP182867 selector levers only. It will be in effect for the remainder of the selector levers by April 1964.

W.E.CO. STOCK OF OLD STYLE PARTS: Should not be furnished after new style parts become available.

APPLICATION TO APPARATUS IN THE FIELD: Old style parts giving satisfactory service need not be replaced.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: All units shall be equipped with new style parts if parts are disassembled for other reasons.