

TP7002 FLAT WASHER

APPARATUS AFFECTED: 33A, 33A-1, 33A-2, 33A-3, 33A-4, 33B, 33C, 33C-1, 33C-2, 33C-3, 33C-4, 33D, 33D-4, 33E, 33F-1, 33F-2, 33F-3, 33F-4 Teletypewriter Sets.

OBJECT: To prevent a possible interference between the TP180489 power lever and the TP180500 carriage frame.

CHANGE: A TP7002 flat washer is being added to the TP180547 eccentric stud between the TP180489 power lever and TP180500 carriage frame.

The TP180547 eccentric stud, TP180489 power lever and TP180500 carriage frame are shown in Teletype Bulletin 1184B, page 2-4, change 3.

IDENTIFICATION: Not involved.

INTERCHANGEABILITY: Not affected.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change is now in effect.

W.E.CO. STOCK OF OLD STYLE PARTS: Not affected.

APPLICATION TO APPARATUS IN THE FIELD: Should be incorporated in all apparatus where required for proper operation.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: All units shall be equipped with the additional TP7002 flat washer if parts are disassembled.

AVAILABILITY: Now available.