

TAPE ROLL AND TAPE SPOOL ASSEMBLY

APPARATUS AFFECTED: 33C, 33C-1, 33C-2, 33C-3, 33C-4, 33F, 33F-1, 33F-2, 33F-3, and 33F-4 Teletypewriter-Sets.

OBJECT: To correct the figure illustrating the tape leadout from the tape reel cover.

CHANGE: Figure 2-12 shown in Bulletin 273B issue of February, 1963 and in Figure 4 of Section 574-100-201 issue of March, 1963 is being changed to illustrate the tape leading from the top of the tape reel cover rather than from the bottom of the tape reel cover.

IDENTIFICATION: Not involved.

INTERCHANGEABILITY: Not involved.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: Not involved.

W.E.CO. STOCK OF OLD STYLE PARTS: Not involved.

APPLICATION TO APPARATUS IN THE FIELD: The new illustration should be used.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: The new illustration shall be used.