

## **TP180075 AND TP180090 TERMINALS**

*APPARATUS AFFECTED:* 33A, 33A-1, 33A-2, 33A-3, 33A-4, 33C, 33C-1, 33C-2, 33C-3, 33C-4, 33D, 33D-1, 33D-2, 33D-3, 33D-4, 33F, 33F-1, 33F-2, 33F-3 and 33F-4 Teletypewriter Sets.

*OBJECT:* (a) To eliminate possible interference between the insulating tubing on adjacent terminals of the keyboard contact block.

(b) To facilitate manufacture.

*CHANGE:* (a) The projection on the TP180075(2) and TP180090 terminals located 0.117 inch from the bottom of the terminal has been relocated to be 0.055 inch from the bottom of the terminal.

(b) The projection on the TP180090 terminal has been bent to an angle of approximately 30 degrees. A 0.045 inch diameter hole has been added to the projection on the TP180075(2) and TP180090 terminals.

The parts are shown in Bulletin 1184B, page 4-2, change 3.

*IDENTIFICATION:* See "CHANGE".

*INTERCHANGEABILITY:* New and old style terminal strips are interchangeable.

*CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE:* This change shall be incorporated as soon as manufacturing conditions permit. This is expected to be about March, 1964.

*W.E.CO. STOCK OF OLD STYLE PARTS:* Shall not be used after new style parts become available.

*APPLICATION TO APPARATUS IN THE FIELD:* Parts giving satisfactory service need not be replaced.

*APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS:* Units may be equipped with new or old style parts. If parts involved require replacement, the new style parts shall be used.

*AVAILABILITY:* About March, 1964.