

## **TP117176 FUSE**

*APPARATUS AFFECTED:* 33A-1 to 33A-5, 33B-5, 33C-1 to 33C-5, 33D-1 to 33D-5, 33E-5, and 33F-1 to 33F-5 Teletypewriter-Sets—TP182081 and TP182083 Call Control Assemblies.

*OBJECT:* To minimize blowing of the 1/2 ampere fuse in the call control assembly.

*REASON FOR REISSUE:* To revise information under "APPARATUS AFFECTED".

*CHANGE:* The TP126296 1/2 ampere fuse has been replaced by a TP117176 1/2 ampere delayed action type fuse.

The TP126296 fuse is shown in Bulletin 1184B, pages 3-6 and 3-8, change 3.

*IDENTIFICATION:* See "CHANGE".

*INTERCHANGEABILITY:* New and old style fuses are interchangeable.

*CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE:* This change is now in effect.

*W.E.CO. STOCK OF OLD STYLE PARTS:* May be used for other applications.

*APPLICATION TO APPARATUS IN THE FIELD:* Old style fuses giving satisfactory service need not be replaced.

*APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS:* All units shall be equipped with the new style fuse.