

TP183474 RIBBON CARRIER MODIFICATION KIT

APPARATUS AFFECTED: 33A-1 to 33A-5, 33B-5, 33C-1 to 33C-5, 33D-1 to 33D-5, 33E-5, 33F-1 to 33F-5 Teletypewriter-Sets.

OBJECT: To improve ribbon routing.

CHANGE: A TP183474 ribbon carrier modification kit replaces the following old style parts in the ribbon feed mechanism:

<i>TP183474 Modification Kit</i>	<i>Old Parts</i>
(1) TP183324 Reverse Arm	TP181116 Arm
(1) TP183326 Ribbon Guide Bracket	TP180568 Ribbon Guide Bracket
(2) TP183330 Guide	TP181124 Post

The TP181116 arm and TP181124 post are shown in Bulletin 1184B, page 2-4, change 3. The TP180568 ribbon guide bracket is shown on page 2-5, change 3.

IDENTIFICATION: The slot in the ribbon guide of the new style TP183324 reverse arm is about 5/8 inch high.

The slot in the ribbon guide of the old style TP181116 arm is about 23/32 inch high.

The span of the opening between the guides on new style TP183326 ribbon guide bracket is about 17/32 inch wide.

The span of the opening between the guides on old style TP180568 ribbon guide bracket is about 5/8 inch wide.

New style TP183330 guides are fixed tapered posts with hexagon-shaped lower flange and have a black oxide finish.

Old style TP181124 post has an aluminum rotating roller and the roller mounting post is nickel-plated.

INTERCHANGEABILITY: New and old style parts are not individually interchangeable.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change is now in effect.

W.E.CO. STOCK OF OLD STYLE PARTS: May be used.

APPLICATION TO APPARATUS IN THE FIELD: Where desired, the new style parts may be incorporated.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: Units may be equipped with new or old style parts. If parts are disassembled for other reasons, the modification kit shall be used.