

## **TP159995 LIFTER ARM**

*APPARATUS AFFECTED:* 28A, 28B, 28C, 28D, 28E, 28F, 28G, 28J, 28J-1, 28K, 28L, 28M Typing Reperforator Units; 28LA, 28LA-1 Tape Typing Units; 28D, 28E, 28G-1, 28K Perforator-Transmitter-Bases; 28A, 28D, 28D-1, 28D-2, 28D-3, 28D-4, 28D-6, 28E, 28F, 28F-1, 28F-2 Reperforator-Transmitter Units; 35A, 35B Tape Typing Units; 35A Typing Reperforator Unit; 35B, 35D Perforator-Transmitter-Bases; TP159995 Lifter Arm.

*OBJECT:* To improve the alignment between the roller on the TP159995 lifter arm and the cam on the TP162350 rocker bail.

*CHANGE:* The TP159995 lifter arm is modified by removing the 0.031 inch offset.

The TP159995 lifter arm is shown in Teletype Bulletins 1167B, page 2-18, change 6; 1169B, page 3-28, change 6; 1188B, page 2-19, original.

*IDENTIFICATION:* New style lifter arms have a straight section adjacent to the stud; old style lifter arms have an offset section adjacent to the stud.

*INTERCHANGEABILITY:* New and old style parts are interchangeable.

*CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE:* This change will be put into effect as soon as manufacturing conditions permit which is expected to be by November, 1964.

*W.E.CO. STOCK OF OLD STYLE PARTS:* May be furnished.

*APPLICATION TO APPARATUS IN THE FIELD:* Old style parts giving satisfactory service need not be replaced.

*APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS:* Units may be equipped with new or old style parts.