

## DATA SET 203-TYPE REFERENCE GUIDE

### 1. GENERAL

**1.001** This addendum supplements Section 590-002-107, Issue 1.

**1.002** This addendum is issued to correct a USOC error and add a clarifying procedure.

### 4. SERVICE ORDER INFORMATION

The following changes apply to Part 4 of the section:

- (a) Table D-7—revised
- (b) Table E-3—revised.

**4.001** On Page 15, Table D-7, second USOC Code entry, change DEL++ to read DFL++.

**4.002** On Page 17, Table E-3, Option 3, expand statement in parentheses to read as follows: "[Decision E9 is required (Note 2)]." Change "(Note 2)" after both Options 5 and 7 to read "(Note 3)."

**4.003** On Page 17, below Table E-3, change "**Note 2:**" to read "**Note 3:**" and add the following where space permits:

**Note 2:** Requirement for a M23A-51 cord should be specified in the Remarks column of the Service Order (see 4.24).